

# List of Monuments and Structures at Risk



*Image: Detail of the Prior's House, Remains of Beauvale Priory (Greasley);  
image opposite: Gatepiers at Gatehouse Lodges (Drakeholes, Wiseton).*



Clarborough	1A	Pair of Chest Tombs at the Church of St John the Baptist	Mid 19th century ashlar chest tombs enclosed by iron railings, with decorated traceried panels.	Overgrown; the railings are collapsing.
Cottam	3A	Font beside the South Porch of the Church of Holy Trinity	Octagonal 14th century ashlar font bowl carried on an octagonal stem.	Removed from its base. Becoming green.
Cuckney	3A	Walls, Railings and Sluice Gates at Cuckney Mill	18th century dam of ashlar and coursed rubble with iron railings and sluices.	Ironwork is corroding. Vegetation growth around the sluices.
Darlton	3A	Chest Tomb 1842 to Thomas Newstead, Church of St Giles	One of three ashlar chest tombs enclosed in a rectangular iron compound.	Railings are split and generally in bad repair. The tomb is covered in ivy.
Darlton	3A	Chest Tomb of 1845 to Mary Ann Newstead, Church of St Giles	One of three ashlar chest tombs enclosed in a rectangular iron compound.	Railings are split and generally in bad repair. The tomb is covered in ivy.
Darlton	3A	Chest Tomb 1818 to Mary (?), Church of St Giles	One of three ashlar chest tombs enclosed in a rectangular iron compound.	Railings are split and in generally bad repair. The tomb is covered in ivy.
Drakeholes	3A	Gatepiers at Gatehouse Lodges	Four round stone gatepiers with incised decoration and gadrooned caps.	Overgrown at time of survey.
Drakeholes	1A	Icehouse at the Gatehouse Lodges	An icehouse dating to the early 19th century in the grounds of the Gatehouse Lodges to Wiseton Hall.	Unused; the site is overgrown to an extent that the structure is no longer accessible.
Dunham	3A	Headstone 1731 to Mary Bacon, Church of St Oswald	One of a group of three 18 <sup>th</sup> century ashlar headstones.	Very eroded and difficult to read.
Dunham	3A	Headstone 1738 to Robert Wills, Church of St Oswald	One of a group of three 18 <sup>th</sup> century ashlar headstones.	Very eroded, inscription is becoming illegible.
Dunham	3A	Headstone 1729 to Mary Bo....ll, Church of St Oswald	One of a group of three 18 <sup>th</sup> century ashlar headstones.	Very eroded, inscription is becoming illegible. High amount of lichen cover may be speeding up erosion.
East Retford	1A	Gateposts to South at Bolham Hall	Set of 18 <sup>th</sup> century gateposts with pineapple finials.	Replaced – state and location of the originals are unknown.
East Retford	3A	Gateposts to North at Bolham Hall	Set of 18 <sup>th</sup> century gateposts with pineapple finials.	Poor condition.
Haughton	3A	Church of St James	Ruined church dating to the early 12 <sup>th</sup> century,	Problems with vegetation growth. The corner of the

			built of ashlar, dressed rubble and coursed rubble. Remains include that of the nave, chancel and north chantry.	west wall is collapsing and needs re-mortaring in position.
Misson	3A	Boundary Wall 25m long at Northfield House	19 <sup>th</sup> century cast iron spearhead railings on a dwarf wall.	Damage to sections of the railings; some repointing required to wall.
Misson	3A	Boundary Wall 75m long at Holly House	19 <sup>th</sup> century brick boundary wall with stone coping.	Poor pointing and eroding brickwork.
Misterton	3A	Access Bridge at Pumping Engine Houses	Access bridge dated 1803 and built of brick with stone coping.	The structure is covered in vegetation and the water channel entrance is barely visible.
Rampton	3A	Gateway and Walls from Manor Farm to Church of All Saints	Heavily decorated gateway and walls dating to the mid 16 <sup>th</sup> century. Built of red brick, ashlar and terracotta.	Very bad condition of masonry; there is collapsing with clear gaps right through, and vegetation growth from the gateway. Overall condition is between poor and very bad.
Rockley	3A	Icehouse at Rockley House Cottage	Icehouse with a late 18 <sup>th</sup> century interior and a 19 <sup>th</sup> century exterior, built in red brick with a pantile roof.	(no update since 1991; highlighted in previous survey as being in poor condition)
Serlby	3A	Arch at Serlby Park	Early 18 <sup>th</sup> century archway of dressed coursed rubble and brick.	Mass of climbing vegetation.
Serlby	1A	Garden Seat in Serlby Park	Late 18 <sup>th</sup> century garden seat of red brick, ashlar and stucco, with a pantile roof and coped parapet.	Collapse of north pier; cracks at south pier indicate that it is close to collapse too. This may be affected by subsidence due to the Harworth colliery.
Shireoaks	3A	Ha-Ha at Shireoaks Hall	Early 18 <sup>th</sup> century Ha-Ha of coursed squared rubble with ashlar coping.	Heavy vegetation cover and collapse of stonework.
South Wheatley	1A	Church of St Helen Remains	Remains of parish church dating to the 12 <sup>th</sup> and 15 <sup>th</sup> century. Built of ashlar and coursed rubble the tower and chancel arch remain.	Vegetation growth has taken over the structure. There are trees growing close to the base of the tower, and there is evidence of recently fallen masonry.
Sutton	3A	Gate Piers and Gates to Sutton Manor Grounds	Late 18 <sup>th</sup> century gate piers and gates of ashlar and wood.	Some spalling stonework and poor pointing.
Wallingwells	3A	Walled Garden at Wallingwells Hall	Walled garden of coursed rubble with quoins and ashlar coping.	Poor condition.

Wallingwells	1A	Walls and Pavilions at Wallingwells Castle Garden	Mid 18 <sup>th</sup> century quadrangular garden walls with four pavilions at the angles, designed in a style of a castle. Built of coursed rubble with ashlar dressings.	Overall in a poor condition.
Welbeck Abbey	3A	Grotto	Double roomed grotto of rough hewn rock, dating to the mid 19 <sup>th</sup> century.	Very overgrown and fenced off (for Health&Safety reasons?) Some of the iron structure is rusting at the base of steps.
Welbeck Abbey	3A	Wall and Gateway to North of the Abbey	Mid 19 <sup>th</sup> century wall and gateway of ashlar and iron.	Damage and loss of coping to wall as well as some eroded stonework. There are damp issue on the house side of the wall.
Wiseton	3A	Lady's Bridge, Chesterfield Canal	Late 18 <sup>th</sup> century ornamental canal bridge. Rendered brick with ashlar dressings and 19 <sup>th</sup> century, cast iron railings.	Corroding railings, excessive ivy growth and loss of render. One pier has collapsed.
Wiseton	1A	Icehouse at Wiseton Hall	An ice house dating to about 1800. Built in brick, partly rendered. The interior has a circular, saucer domed ice chamber.	Unused and neglected. The icehouse has trees growing out of the roof splitting the structure and the brickwork has partially collapsed.
Worksop	3A	Chimney at Bracebridge Pumping Station	A tall Romanesque style chimney of three stages, of brick and ashlar.	Poor pointing and vegetation growth.
Worksop	3A	Cloister Wall at Church of SS Cuthbert and Mary	Remains of 12th century cloister wall with round headed and four centred arched doorways.	Lots of vegetation is growing out of the ruin and there are trees growing very close to base. Some signs of recent stone fall.
Worksop		Icehouse to Rear of Gateford Farmhouse	Icehouse of the late 18th century built of coursed squared rubble and brick with ashlar dressings.	Unused and neglected. There are saplings growing out of the mount affecting the masonry.
Worksop	3A	Drive Walls and Gate Piers at Worksop Manor	Two 18th century rubble and ashlar boundary walls flanking the driveway with rusticated gatepiers.	Large sections are in a poor condition and there has been some substantial collapse along the drive walls.





















