

Effective: 09/01/2017 to 09/01/2018  
Street: Micklebarrow Hill (26822253)

Display Action Officer: No

Street: Micklebarrow Hill (26822253)

Locality: Averham, Nottinghamshire

Area: Newark

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 1,000.00	<b>Feature Id - Locn.:</b> 3226C - Spring Wood Bridge Upton/Averham Parish Boundary			<b>Feature Type:</b> Culvert (Spans 1m to 3m)			<b>Area:</b> Newark	
<b>Batch:</b> 105047 - Inspection Batch				<b>Route:</b> 2016 Newark Culverts				<b>Date:</b> 18/07/2017
	No actionable defects found							
<b>Feat No.:</b> 1,000.01	<b>Feature Id - Locn.:</b> 3226C/1/1 - Spring Wood Bridge Upton/Averham Parish Boundary			<b>Feature Type:</b> Spans			<b>Area:</b> Newark	
<b>Batch:</b> 105048 - Inspection Batch				<b>Route:</b> 2016 Newark Culverts				<b>Date:</b> 18/07/2017
	No actionable defects found							
<b>Feat No.:</b> 1,000.02	<b>Feature Id - Locn.:</b> 3226C/1/2 - Spring Wood Bridge Upton/Averham Parish Boundary			<b>Feature Type:</b> Spans			<b>Area:</b> Newark	
<b>Batch:</b> 105049 - Inspection Batch				<b>Route:</b> 2016 Newark Culverts				<b>Date:</b> 18/07/2017
	No actionable defects found							
<b>Feat No.:</b> 1,000.03	<b>Feature Id - Locn.:</b> 3226C/1/3 - Spring Wood Bridge Upton/Averham Parish Boundary			<b>Feature Type:</b> Spans			<b>Area:</b> Newark	
<b>Batch:</b> 105050 - Inspection Batch				<b>Route:</b> 2016 Newark Culverts				<b>Date:</b> 18/07/2017
	No actionable defects found							
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> A617 - Hockerton Road Junction To Main Road (A612) Junction			<b>Feature Type:</b> Street Section			<b>Area:</b> Newark	
<b>Batch:</b> 20261753 - Inspection Batch				<b>Route:</b> Newark Area 2 Jan Saf CW				<b>Date:</b> 08/01/2018
3563218 potholes		08/01/2018	on bend near broadgate ln marked	CW Repairs-Bituminous	Internal		Committed	2666115
3563219 potholes		08/01/2018	on hill next to road narowe sign marked	CW Repairs-Bituminous	Internal		Committed	2666114
<b>Batch:</b> 20261748 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 08/01/2018
3563212 pothole		08/01/2018	400m befor hockerton rd filled when found	CW Repairs-Bituminous	Internal		Uncommitt	2666108
<b>Batch:</b> 20260344 - Inspection Batch				<b>Route:</b> Newark Area 2 Dec Saf CW				<b>Date:</b> 27/12/2017
	No actionable defects found							
<b>Batch:</b> 20254181 - Inspection Batch				<b>Route:</b> Newark Area 2 Nov Saf CW				<b>Date:</b> 09/11/2017
	No actionable defects found							
<b>Batch:</b> 20248790 - Inspection Batch				<b>Route:</b> Newark Area 2 Oct Saf CW				<b>Date:</b> 05/10/2017
	No actionable defects found							
<b>Batch:</b> 20246166 - Inspection Batch				<b>Route:</b> Newark Area 2 Sep Saf CW				<b>Date:</b> 18/09/2017
3555395 pothole		18/09/2017	opps spring wood side house marked	CW Repairs-Bituminous	Internal		Committed	2657910
3555394 pothole		18/09/2017	in entrance to springwood sid house marked	CW Repairs-Bituminous	Internal		Committed	2657911
<b>Batch:</b> 20241680 - Inspection Batch				<b>Route:</b> Newark Area 2 Aug Saf CW				<b>Date:</b> 15/08/2017
	No actionable defects found							
<b>Batch:</b> 20239149 - Inspection Batch				<b>Route:</b> Newark Area 2 Jul Saf CW				<b>Date:</b> 24/07/2017
	No actionable defects found							
<b>Batch:</b> 20233817 - Inspection Batch				<b>Route:</b> Newark Area 2 Jun Saf CW				<b>Date:</b> 13/06/2017
	No actionable defects found							
<b>Batch:</b> 20231867 - Inspection Batch				<b>Route:</b> Newark Area 2 May Enh CW/FW				<b>Date:</b> 31/05/2017
	No actionable defects found							

Effective: 09/01/2017 to 09/01/2018  
Street: Micklebarrow Hill (26822253)

Display Action Officer: No

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> A617 - Hockerton Road Junction To Main Road (A612) Junction			<b>Feature Type:</b> Street Section			<b>Area:</b> Newark	
<b>Batch:</b> 20225913 - Inspection Batch				<b>Route:</b> Newark Area 2 Apr Saf CW				<b>Date:</b> 20/04/2017
3546859	pothole	20/04/2017	on bend nr averham park	CW Repairs-Bituminous	Internal		Committed	2648691
<b>Batch:</b> 20219578 - Inspection Batch				<b>Route:</b> Newark Area 2 Mar Saf CW				<b>Date:</b> 03/03/2017
	No actionable defects found							
<b>Batch:</b> 20216004 - Inspection Batch				<b>Route:</b> Newark Area 2 Feb Saf CW				<b>Date:</b> 09/02/2017
3542060	pothole	09/02/2017	start of red high friction aprox 100 yards before right turn for averham park marked	CW Repairs-Bituminous	Internal		Committed	2643780
<b>Batch:</b> 20211422 - Inspection Batch				<b>Route:</b> Newark Area 2 Jan Saf CW				<b>Date:</b> 09/01/2017
	No actionable defects found							
<b>Feat No.:</b> 3,500.00	<b>Feature Id - Locn.:</b> chevron			<b>Feature Type:</b> Non-Illum Sign - 1 Post			<b>Area:</b> Newark	
<b>Batch:</b> 20659908 - Inspection Batch				<b>Route:</b> Ad Hoc SL Countywide				<b>Date:</b> 23/10/2017
	No actionable defects found							
<b>Feat No.:</b> 3,501.00	<b>Feature Id - Locn.:</b> chevron			<b>Feature Type:</b> Non-Illum Sign - 1 Post			<b>Area:</b> Newark	
<b>Batch:</b> 20659912 - Inspection Batch				<b>Route:</b> Ad Hoc SL Countywide				<b>Date:</b> 23/10/2017
	No actionable defects found							
<b>Feat No.:</b> 8,000.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection				<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
	No actionable defects found							
<b>Feat No.:</b> 8,001.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection				<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
	No actionable defects found							
<b>Feat No.:</b> 8,002.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection				<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
	No actionable defects found							
<b>Feat No.:</b> 8,003.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection				<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
	No actionable defects found							
<b>Feat No.:</b> 8,004.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection				<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
	No actionable defects found							
<b>Feat No.:</b> 8,005.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection				<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 25/08/2017
	No actionable defects found							
<b>Feat No.:</b> 8,006.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection				<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
	No actionable defects found							

Effective: 09/01/2017 to 09/01/2018  
 Street: Micklebarrow Hill (26822253)

Display Action Officer: No

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 8,007.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,008.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,009.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,010.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,011.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,012.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,013.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,014.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/08/2017
<b>Feat No.:</b> 8,015.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,016.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,017.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,018.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017

Effective: 09/01/2017 to 09/01/2018  
 Street: Micklebarrow Hill (26822253)

Display Action Officer: No

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 8,019.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,020.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,021.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,022.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,023.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,024.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,025.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,026.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,027.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,028.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,029.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,030.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017

Effective: 09/01/2017 to 09/01/2018  
 Street: Micklebarrow Hill (26822253)

Display Action Officer: No

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 8,031.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,032.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,033.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,034.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,035.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,036.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,037.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 25/08/2017
<b>Feat No.:</b> 8,038.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 25/08/2017
<b>Feat No.:</b> 8,040.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/08/2017
<b>Feat No.:</b> 8,041.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,042.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,043.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017

Effective: 09/01/2017 to 09/01/2018  
 Street: Micklebarrow Hill (26822253)

Display Action Officer: No

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 8,044.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,045.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/08/2017
<b>Feat No.:</b> 8,046.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/08/2017
<b>Feat No.:</b> 8,048.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,053.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,054.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,055.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,056.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,057.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,058.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017
<b>Feat No.:</b> 8,059.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 22/08/2017

Effective: 09/01/2017 to 09/01/2018  
Street: Micklebarrow Hill (26822253)

Display Action Officer: No

### Customer Services

<b>Enquiry No.:</b> 6075503	<b>Logged by:</b> External to Confirm	<b>on:</b> 08/01/2018 16:12	
<b>Service:</b> Claims	<b>Subject:</b> Highway Insurance Claim	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS65313643
<b>Desc.:</b> Insurance claim - related to Confirm defect reference: 6075502 Date/Time: 07/01/2018 18:00:00 Direction of travel: Westbound along the A617 before the junction with Hockerton Road Account of what happened: The customer was travelling along the road when she passed over the pothole, both passenger side alloy wheels have been cracked. She had to have her car recovered and driven to a garage.			
<b>Location:</b> Road name should be MICKLEBARROW HILL, AVERHAM. Heading towards Mansfield, just before junction of Hockerton Road.		<b>Contact:</b>	
<b>Plot Number:</b> 2,000.00	<b>Feature Id - Location:</b> A617 - Hockerton Road Junction To Main Road (A612) Junction	<b>Feature Type:</b> Street Section	
<b>Enquiry No.:</b> 6075502	<b>Logged by:</b> External to Confirm	<b>on:</b> 08/01/2018 16:09	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Carriageway Pothole	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-65313643
<b>Desc.:</b> Insurance claim form requested - Road Pothole - On the westbound carriage of the A617 just before the junction with Hockerton Road there is a large pothole that has damaged the customer's car. As it was dark and on a fast road she is not exactly sure of the diameters but both wheels on the passenger side have been damaged (cracked alloys). . Submitted by Advisor: TP			
<b>Location:</b> See map coordinates and description details		<b>Contact:</b>	
<b>Plot Number:</b> 2,000.00	<b>Feature Id - Location:</b> A617 - Hockerton Road Junction To Main Road (A612) Junction	<b>Feature Type:</b> Street Section	
<b>Job Number:</b> 2666108	<b>Defect Number:</b> 3563212		
<b>Enquiry No.:</b> 6075422	<b>Logged by:</b> External to Confirm	<b>on:</b> 08/01/2018 12:45	
<b>Service:</b> Claims	<b>Subject:</b> Highway Insurance Claim	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-65283979
<b>Desc.:</b> Road Pothole - On the A617 heading west. Large pothole is on the hill (think it is called Wheatgrass Hill) towards Brooklyn care home. I went over this pothole at 7.30 on 8/1/18 and it punctured my tyre. I managed to get to the Brooklyn care home where they helped me try and repair the tyre. It didn't work as too badly damaged, a breakdown truck then took me to Newark to get tyre replaced. I then went to work at TP 4 hrs late. How do i go about claiming compensation for new tyre and inconvenience caused? . Online report			
<b>Location:</b> See map coordinates and description details		<b>Contact:</b>	
<b>Plot Number:</b> 2,000.00	<b>Feature Id - Location:</b> A617 - Hockerton Road Junction To Main Road (A612) Junction	<b>Feature Type:</b> Street Section	
<b>Job Number:</b> 2666108	<b>Defect Number:</b> 3563212		
<b>Enquiry No.:</b> 6075292	<b>Logged by:</b> External to Confirm	<b>on:</b> 08/01/2018 10:55	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Carriageway Pothole	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-65212802
<b>Desc.:</b> Road Pothole - Huge pothole which we had to go through and couldn't avoid due to oncoming traffic, surprised we didn't have an accident, pothole so big! Will have to check car for damage when we reach destination! . Online report			
<b>Location:</b> See map coordinates and description details		<b>Contact:</b>	
<b>Plot Number:</b> 2,000.00	<b>Feature Id - Location:</b> A617 - Hockerton Road Junction To Main Road (A612) Junction	<b>Feature Type:</b> Street Section	
<b>Job Number:</b> 2666108	<b>Defect Number:</b> 3563212		
<b>Enquiry No.:</b> 6075283	<b>Logged by:</b> External to Confirm	<b>on:</b> 08/01/2018 10:55	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Carriageway Pothole	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-65210010
<b>Desc.:</b> Road Pothole - Very deep pothole, roughly 4 to 5 inches deep, reporting this to the council as it has cracked my alloy wheel. . Online report			
<b>Location:</b> See map coordinates and description details		<b>Contact:</b>	
<b>Plot Number:</b> 2,000.00	<b>Feature Id - Location:</b> A617 - Hockerton Road Junction To Main Road (A612) Junction	<b>Feature Type:</b> Street Section	
<b>Job Number:</b> 2666108	<b>Defect Number:</b> 3563212		
<b>Enquiry No.:</b> 6075281	<b>Logged by:</b> External to Confirm	<b>on:</b> 08/01/2018 10:55	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Carriageway Pothole	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-65197995
<b>Desc.:</b> Road Pothole - Very large pothole close to edge of road in westerly direction, just after the right hand bend. Has cracked alloy wheel . Online report			
<b>Location:</b> See map coordinates and description details		<b>Contact:</b>	
<b>Plot Number:</b> 2,000.00	<b>Feature Id - Location:</b> A617 - Hockerton Road Junction To Main Road (A612) Junction	<b>Feature Type:</b> Street Section	
<b>Job Number:</b> 2666108	<b>Defect Number:</b> 3563212		

Effective: 09/01/2017 to 09/01/2018  
Street: Micklebarrow Hill (26822253)

Display Action Officer: No

### Customer Services

<b>Enquiry No.:</b> 6075254	<b>Logged by:</b> External to Confirm	<b>on:</b> 08/01/2018 09:24	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Carriageway Pothole	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-65254076
<b>Desc.:</b> Road Pothole - Police reporting a pothole which has caused an incident they are currently dealing with. outside spring wood farm on the A617 Wheatgrass Hill NG23 5TH. The pothole is on a lot of the road and the police are having to remain there at the moment to advise drivers that this is there. reference number TP of 08/01/2018 . Submitted by Advisor: TP			
<b>Location:</b> See map coordinates and description details		<b>Contact:</b>	
<b>Plot Number:</b> 2,000.00	<b>Feature Id - Location:</b> A617 - Hockerton Road Junction To Main Road (A612) Junction	<b>Feature Type:</b> Street Section	
<b>Job Number:</b> 2666108	<b>Defect Number:</b> 3563212		
<b>Enquiry No.:</b> 6075252	<b>Logged by:</b> External to Confirm	<b>on:</b> 06/01/2018 09:57	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Carriageway Pothole	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-65176894
<b>Desc.:</b> Road Pothole - This hole in the road has caused a puncture in my tyre it is as you come round the bend so it's disgusting that it has got this bad . Online report			
<b>Location:</b> See map coordinates and description details		<b>Contact:</b>	
<b>Plot Number:</b> 2,000.00	<b>Feature Id - Location:</b> A617 - Hockerton Road Junction To Main Road (A612) Junction	<b>Feature Type:</b> Street Section	
<b>Job Number:</b> 2666108	<b>Defect Number:</b> 3563212		
<b>Enquiry No.:</b> 6070822	<b>Logged by:</b> External to Confirm	<b>on:</b> 20/11/2017 16:15	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Temporary Traffic Lights	<b>Classification:</b> Service Request	<b>Enquiry Ref:</b> FS-CASE-62388273
<b>Desc.:</b> Temporary Traffic lights (roadworks) issue - Customer has called to report that temporary traffic have been placed on the A617 in Hockerton. These have been up for 3 weeks and the customer states that there are no roadworks currently taking place.			
These are causing massive tailbacks and can be a real nightmare to get through. Please could this be looked into.			
NG23 5TG . Submitted by Advisor TP			
<b>Location:</b> See map coordinates and description details		<b>Contact:</b>	
<b>Enquiry No.:</b> 6059951	<b>Logged by:</b> External to Confirm	<b>on:</b> 31/07/2017 13:14	
<b>Service:</b> Trees/Verges	<b>Subject:</b> Grass Cutting	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-56690232
<b>Desc.:</b> Overgrown grass and verges - TP has previously called about an ongoing issue with some thistles that are growing on the grass verges that are connected to TP The issue has arose since we cut down the trees on the lay by last year, and due to this is has just opened up the space for weeds and thistles and because of the temperamental weather the seeds are blowing off of the thistles on to the farm land. Which in turn the thistles are going to start growing in the farmland. This needs to be seen to immediately before it worsens and puts a halt to on going works within the farm. These need to be cut back to eradicate the issue completely. The issue is lies from all across the A612 through the A617, TP If you could also get in touch with TP to let him know of any works that are happening. . Submitted by Advisor: TP			
<b>Location:</b> See map coordinates and description details		<b>Contact:</b>	
<b>Enquiry No.:</b> 6049270	<b>Logged by:</b> External to Confirm	<b>on:</b> 04/04/2017 21:19	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> St Furn/Non Illum Sign Damage	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-50687317
<b>Desc.:</b> Dirty / obscured signs			
<b>Location:</b> See map coordinates and description details		<b>Contact:</b>	
<b>Enquiry No.:</b> 6039950	<b>Logged by:</b> External to Confirm	<b>on:</b> 21/01/2017 13:46	
<b>Service:</b> Trees/Verges	<b>Subject:</b> Overhanging Vegetation/Trees	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-12054322
<b>Desc.:</b> Overhanging trees - This section of road which is has overgrown hedges forcing hgvs to cross the white line and collide mirrors needs all the hedges cutting back.. The road road is very narrow and dangerous and needs cutting nack on both sides... . Online report			
<b>Location:</b> 'See map coordinates and description details'		<b>Contact:</b>	



Effective: 09/01/2017 to 09/01/2018  
Street: Micklebarrow Hill (26822253)

Display Action Officer: No

### Customer Services

Enquiry No.: 65778

Logged by: TP

on: 05/09/2017 10:05

Service: Road Works

Subject: Utility Works

Classification: Report or Observation

Desc.: Permission to site BT Broadband Cabinet PCP092

Location: Outside Flash Farm

Contact:

Plot Number: 2,000.00

Feature Id - Location: A617 - Hockerton Road Junction To Main Road (A612) Junction

Feature Type: Street Section

### Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Feat No.:</b>	2,000.00	<b>Feature Id - Locn.:</b> A617 - Hockerton Road Junction To Main Road (A612) Junction		<b>Feature Type:</b> Street Section		<b>Area:</b> Newark	
2643780	pothole (CW Repairs-Bituminous)	start of red high friction aprox 100 yards before right turn for averham park marked	Category 2 (High)	Job Completed	09/02/2017	10/02/2017	Act. NEW-AS/5502357
2648691	pothole (CW Repairs-Bituminous)	on bend nr averham park	Category 2 (High)	Job Completed	20/04/2017	24/04/2017	Act. NEW-AS/5502935
2657910	pothole (CW Repairs-Bituminous)	opps spring wood side house marked	Category 2 (High)	Job Completed	18/09/2017	25/09/2017	Act. NEW-AS/5503803
2657911	pothole (CW Repairs-Bituminous)	in entrance to springwood sid house marked	Category 2 (High)	Job Completed	18/09/2017	25/09/2017	Act. NEW-AS/5503802
2666108	pothole (CW Repairs-Bituminous)	400m befor hockerton rd filled when found	Filled when found (Cat 1)	Job Completed	08/01/2018	08/01/2018	Act.
2666114	potholes (CW Repairs-Bituminous)	on hill next to road narowe sign marked	Category 2 (High)	Job Completed	08/01/2018	09/01/2018	Act. NEW-AS/5504436
2666115	potholes (CW Repairs-Bituminous)	on bend near broadgate ln marked	Category 2 (High)	Job Completed	08/01/2018	09/01/2018	Act. NEW-AS/5504437
<b>Feat No.:</b>	3,512.00	<b>Feature Id - Locn.:</b>		<b>Feature Type:</b> Non-Illum Sign - 1 Post		<b>Area:</b> Newark	
3627430	Clean ALL chevrons on this bend and cut branches where required to make visible. thanks		SL- 30 Days	Job Completed	30/10/2017	01/11/2017	Act. SLNE/12004952