10/07/2018

Street History Report

Effective: 01/04/2017 to 01/04/2018 Display Action Officer: No	8 Feature No.: 2000.00 to 2005.00 Street: Tollerton Lane (33002303)					
Street: Tollerton Lane (33002303)		Locality: Tollerton, Nottinghamshire Area: Rushcliffe				
Condition Survey						
Defect No: Description	Log Date	Location	Defect Type	Class.	Organisation Status	Job No.
Feat No.: 2,000.00 Feature Id - Locn.:	-		Feature Type: Street S	ection	Area: Rushcliff	e
Batch: 20274122 - Inspection Batch		Route: Rush A	Area 2 Mar Saf CW			Date: 22/03/2018
No actionable defects found						
Batch: 20272405 - Inspection Batch		Route: Adhoc	Inspection			Date: 14/03/2018
3570962 Three areas of wearing course erosion marked up to be overlay - viafix has been used to reduce the depth(Enquiry 6085926)	14/03/2018	Outside house number 89 (just before L / C 19) and opposite L / C 20 near Medina Drive .	CW Repairs-Bituminous	Internal	Committed	2673950
Batch: 20272350 - Inspection Batch		Route: Adhoc	Inspection			Date: 14/03/2018
3570923 Carriageway defect has now been made safe.	14/03/2018	The pothole is just off the center of the carriageway opposite manor farm.	CW Repairs-Bituminous	Internal	Uncommitte	2673911
Batch: 20269218 - Inspection Batch		Route: Adhoc	Inspection			Date: 21/02/2018
kerbs . Standing water problem. The kerb has dropped outside of the house and the road dips towards where dropped stone meets the tarmac. There is a bowl shape in the tarmac and water collects at this point. Can we fill the dip or prevent water from collecting . Submitted by Advisor: Claire Shockledge (Enquiry 6082579)		marked in yellow				
Batch: 20269217 - Inspection Batch		Route: Adhoc	Inspection			Date: 21/02/2018
3568815 Replace and relay 3 new 6x5 kerbs then reinstate . Standing water problem - The kerb has dropped outside of the house and the road dips towards where dropped stone meets the tarmac. There is a bowl shape in the tarmac and water collects at this point. Can we fill the dip or prevent water from collecting . Submitted by Advisor: Claire Shockledge (Enquiry 6082579)	21/02/2018	Outside of number 42 marked in yellow	CW Repairs-Bituminous	Internal	Committed	2671777
Batch: 20268795 - Inspection Batch		Route: Adhoc	Inspection			Date: 19/02/2018
3568353 Carriageway Damage - Road Damage - Multiple potholes . Online report (Enquiry 6082031)	19/02/2018	Tollerton Lane at junction with Medina Dri Tollerton	v CW Repairs-Bituminous	Internal	Uncommitte	2671310
Batch: 20267751 - Inspection Batch		Route: Rush A	Area 2 Feb Enh CW/FW			Date: 09/02/2018
No actionable defects found						
Batch: 20265318 - Inspection Batch		Route: Adhoc	Inspection			Date: 29/01/2018
3565937 Carriageway defects have been made safe .	29/01/2018	Opposite L / C 23	CW Repairs-Bituminous	Internal	Uncommitte	2668878

Effective: 01/04/2017 to 01/04/2018 Display Action Officer: No

Feature No.: 2000.00 to 2005.00 Street: Tollerton Lane (33002303)

Condition Survey

fect No: Description	Log Date	Location	Defect Type	Class. Organisation	Status	Job No.
Feat No.:2,000.00Feature Id - Locn.:			Feature Type: Street S	Section	Area: Rushcliffe	9
Batch: 20264320 - Inspection Batch		R	oute: Rush Area 2 Jan Saf CW			Date: 24/01/2018
No actionable defects found						
Batch: 20264253 - Inspection Batch		R	oute: Adhoc Inspection			Date: 23/01/2018
3565212 CW overlay - Carriageway erosion at given location has had the depth reduced with viafix and requires overlay patching. (Enquiry 6077736)	23/01/2018	Approx 10 meters from the 40 nearest house number 226, I adjacent with field entrance, C 45 in the direction of Gams	eft hand side opposite L /	Internal	Committed	2668137
Batch: 20262154 - Inspection Batch		R	oute: Adhoc Inspection			Date: 10/01/2018
3563519 Carriageway defect has been made safe.	10/01/2018	Near L / C 14	CW Repairs-Bituminous	Internal	Uncommitte	2666416
Batch: 20261699 - Inspection Batch		R	oute: Adhoc Inspection			Date: 08/01/2018
3563168 Defect made safe .	08/01/2018	Outside house number 80	CW Repairs-Bituminous	Internal	Uncommitte	2666064
Batch: 20258962 - Inspection Batch		R	oute: Adhoc Inspection			Date: 12/12/201
3561711 HWIA - Section of Carriageway is to be resurfaced at some stage but until this takes place defects are marked up within the section that require marking safe . Online report (Enquiry 6073036)	12/12/2017	Directly outside Oak Tree Ho with the Medina Drive Junctio	use adjacent CW Repairs-Bituminous n	Internal	Committed	2664564
Batch: 20258745 - Inspection Batch		R	oute: Rush Area 2 Dec Saf CW			Date: 11/12/2017
3561646	11/12/2017	Outside Manor Farm Cattery with the speed signs leaving the direction of Bassingfield	and adjacent CW Repairs-Bituminous he Village in	Internal	Uncommitte	2664493
Batch: 20255554 - Inspection Batch		R	oute: Rush Area 2 Nov Saf CW			Date: 20/11/2017
3560135 Defect made safe	20/11/2017	Outside house number 161	CW Repairs-Bituminous	Internal	Uncommitte	2662918
Batch: 20254545 - Inspection Batch		R	oute: Adhoc Inspection			Date: 13/11/2017
3559498 Carriageway defect has been made safe.	13/11/2017	Outside Oak Tree House	CW Repairs-Bituminous	Internal	Uncommitte	2662260
Batch: 20250721 - Inspection Batch		R	oute: Rush Area 2 Oct Saf CW			Date: 19/10/201
No actionable defects found						
Batch: 20246344 - Inspection Batch		R	oute: Rush Area 2 Sep Saf CW			Date: 19/09/201
No actionable defects found						
Batch: 20244451 - Ad Hoc Inspection Batch		R	oute: Adhoc Inspection			Date: 05/09/201
3554441 Manholes/Gullies - Blocked gullies - The gully that runs under the pavement outside 89 Tollerton Lane is blocked with silt and causing flooding up the drive way and in the middle of the road. SPEAK WITH ANDY CLIFFORD, WHO KNOWS WHAT REPAIRS ARE	05/09/2017	Outside no 89.	Drainage	Internal	Committed	2656914
REQUIRED. BOOK REPAIRS DOWN TO O P 170036.						

Report generated by : Andrzej Lukaszczyk

Effective: 01/04/2017 to 01/04/2018 Display Action Officer: No

Feature No.: 2000.00 to 2005.00 Street: Tollerton Lane (33002303)

Condition Survey

Defect No: Desc	cription		Log Date	Location		Defect Type	Clas	ss. Organi	sation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:				Feature Ty	ype: Street Section		А	rea: Rushcliffe	
Batch: 20)243114 - Inspe	ection Batch		R	oute: Rush	Area 2 Aug Saf CW					Date: 25/08/2017
No a	ctionable defec	cts found									
Batch: 20)241660 - Inspe	ection Batch		R	oute: Adho	c Inspection					Date: 15/08/2017
3553381 HWI	A - defects mai	rked up for repair .	15/08/2017	On the T junction side of the Restaurant / Garage	Charde	CW Repairs-Bitum	ninous Inte	rnal		Committed	2655820
Batch: 20)238723 - Inspe	ection Batch		R	oute: Rush	Area 2 Jul Saf CW					Date: 19/07/2017
No a	ctionable defec	cts found									
Batch: 20)238722 - Inspe	ection Batch		R	oute: Adho	c Inspection					Date: 19/07/2017
erosi		has wearing course s overlaying - location 6058553)	19/07/2017	Outside house number 12		FW Repairs-Bitum	ninous Inte	rnal		Committed	2654419
Batch: 20)236469 - Inspe	ection Batch		R	oute: Rush	Area 2 Jun Saf CW					Date: 03/07/2017
No a	ctionable defec	cts found									
Batch: 20)236121 - Inspe	ection Batch		R	oute: Adho	c Inspection					Date: 29/06/2017
3551206 Defe	ct been made s	safe	29/06/2017	On the T junction with Medina	a Drive	CW Repairs-Bitum	ninous Inte	rnal		Uncommitte	2653360
Batch: 20)231028 - Inspe	ection Batch		R	oute: Rush	Area 2 May Saf CW					Date: 23/05/2017
No a	ctionable defea	cts found									
Batch: 20)229725 - Inspe	ection Batch		R	oute: Adho	c Inspection					Date: 12/05/2017
erosi and r	on and require	n has large scale s planing out 3M x 24M rse / wearing course to ked up	12/05/2017 	Outside house called Oak Tre house number 99 adjacent wi Medina Drive junction		CW Repairs-Bitum	ninous Inte	rnal		Uncommitte	2650322
Batch: 20)229724 - Inspe	ection Batch		R	oute: Adho	c Inspection					Date: 12/05/2017
3548403 Defe	ct made safe		12/05/2017	Entrance to Oak Tree House		CW Repairs-Bitum	ninous Inte	rnal		Uncommitte	2650321
Batch: 20)228039 - Inspe	ection Batch		R	oute: Adho	c Inspection					Date: 03/05/2017
	ageway defect	s made safe during	03/05/2017	On the T junction with Cotgra	ave Lane	CW Repairs-Bitur	ninous Inte	rnal		Uncommitte	2649545
Batch: 20)226943 - Inspe	ection Batch		R	oute: Rush	Area 2 Apr Saf CW					Date: 26/04/2017
No a	ctionable defeo	cts found									
Maintenance	Manageme	ent									
Job No. Descr	iption	Location			Pri	ority	Job Status	Er	tered	Completion	Works Order
Feat No.	: 2,000.00	Feature Id - Loc	n.:			Feature	e Type: Street Section	on		Area: Rushcl	iffe
during Repair	inspection. (C rs-Bituminous)		-	-	2H)		Job Completed			03/05/2017	
2650321 Defect Repair	t made safe (C rs-Bituminous)		to Oak Tree H	louse	Fille 2H)	ed when found (Cat	Job Completed	12	/05/2017	12/05/2017	Act.

Effective: 01/04/2017 to 01/04/2018 Display Action Officer: No Feature No.: 2000.00 to 2005.00 Street: Tollerton Lane (33002303)

ce Management	Maintenance
---------------	-------------

Job No. Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 2,000.00 Featu	re ld - Locn.:	Feature	• Type: Street Section		Area: Rushcliffe	
2650322 Carriageway section has large scale erosion and requires planing out 3M x 24M and relay base course / wearing course to existing level - marked up (CW Repairs-Bituminous)		Category 2 (Low)	Job Closed	12/05/2017	17/10/2017 Act.	RUSH/3702361
2653360 Defect been made safe (CW Repairs-Bituminous)	On the T junction with Medina Drive	Filled when found (Cat 2H)	Job Completed	29/06/2017	29/06/2017 Act.	
2654419 Section of footpath has wearing course erosion and requires overlaying - location marked up (Enquiry 6058553) (FW Repairs-Bituminous)	Outside house number 12	Category 2 (High)	Job Completed	19/07/2017	21/07/2017 Act.	RUSH/3702549
2655820 HWIA - defects marked up for repair . (CW Repairs-Bituminous	On the T junction side of the) Charde Restaurant / Garage	Category 2 (High)	Job Completed	15/08/2017	26/09/2017 Act.	RUS-AS/5600749
2656914 Manholes/Gullies - Blocked gullies - The gully that runs unde the pavement outside 89 Tollerton Lane is blocked with sil and causing flooding up the drive way and in the middle of the road SPEAK WITH ANDY CLIFFORD, WHO KNOWS WHAT REPAIRS ARE REQUIRED. BOOK REPAIRS DOWN TO O F 170036. (Drainage)	Outside no 89. er t e d.	Category 2 (Low)	Job Closed	05/09/2017	21/09/2017 Act.	RUSH/3702647
2662260 Carriageway defect has been made safe . (CW Repairs-Bituminous)	Outside Oak Tree House	Filled when found (Cat 2H)	Job Completed	13/11/2017	13/11/2017 Act.	
2662918 Defect made safe (CW Repairs-Bituminous)	Outside house number 161	Filled when found (Cat 2H)	Job Completed	20/11/2017	20/11/2017 Act.	
2664493 CW Repairs-Bituminous	Outside Manor Farm Cattery and adjacent with the speed signs leaving the Village in the direction of Bassingfield	Filled when found (Cat 2H)	Job Completed	11/12/2017	11/12/2017 Act.	
2664564 HWIA - Section of Carriageway is to be resurfaced at some stage but until this takes place defects are marked up within the section that require marking safe . Online report (Enquiry 6073036 (CW Repairs-Bituminous)	e 5)	Category 2 (High)	Job Completed			RUS-AS/5600872
2666064 Defect made safe . (CW Repairs-Bituminous)	Outside house number 80	Filled when found (Cat 2H)	Job Completed	08/01/2018	08/01/2018 Act.	

Effective: 01/04/2017 to 01/04/2018 Display Action Officer: No Feature No.: 2000.00 to 2005.00 Street: Tollerton Lane (33002303)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
F	eat No.: 2,000.00 Featur	re Id - Locn.:	Feature	Type: Street Section		Area: Rushcliffe	
266641	6 Carriageway defect has been made safe . (CW Repairs-Bituminous)	Near L / C 14	Filled when found (Cat 2H)	Job Completed	10/01/2018	10/01/2018 Act.	
266813	7 CW overlay - Carriageway erosion at given location has had the depth reduced with viafix and requires overlay patching. (Enquiry 6077736) (CW Repairs-Bituminous)		Category 2 (High)	Job Completed	24/01/2018	08/02/2018 Act.	RUSH/3703026
266887	8 Carriageway defects have been made safe . (CW Repairs-Bituminous)	Opposite L / C 23	Filled when found (Cat 1)	Job Completed	29/01/2018	29/01/2018 Act.	
267131	0 Carriageway Damage - Road Damage - Multiple potholes . Online report (Enquiry 6082031) (CW Repairs-Bituminous)	Tollerton Lane at junction with Medina Drive Tollerton	Filled when found (Cat 2H)	Job Completed	19/02/2018	19/02/2018 Act.	
	7 Replace and relay 3 new 6x5 kerbs then reinstate . Standing water problem - The kerb has dropped outside of the house and the road dips towards where dropped stone meets the tarmac. There is a bowl shape in the tarmac and water collects at this point. Can we fill the dip or prevent water from collecting . Submitted by Advisor: Claire Shockledge (Enquiry 6082579) (CW Repairs-Bituminous)		Category 2 (Low)	Works Order Printed		21/03/2018 Est.	
	8 Take up and replace and reline 3 6x5 kerbs . Standing water problem. The kerb has dropped outside of the house and the road dips towards where dropped stone meets the tarmac. There is a bowl shape in the tarmac and water collects at this point. Can we fill the dip or prevent water from collecting . Submitted by Advisor: Claire Shockledge (Enquiry 6082579) (Kerbing/Edging)		Category 2 (Low)	Job Completed		03/05/2018 Act.	RUSH/3703161
267391	1 Carriageway defect has now been made safe. (CW Repairs-Bituminous)	The pothole is just off the center of the carriageway opposite manor farm.	Filled when found (Cat 2H)	Job Completed	14/03/2018	14/03/2018 Act.	

10/07/2018

Effective: 01/04/2017 to 01/04/2018 Display Action Officer: No

Feature No.: 2000.00 to 2005.00 Street: Tollerton Lane (33002303)

Maintenance Management

Job No. Description	Location	Priority	Job Status	Entered	Completion	Works Order	
Feat No.: 2,000.00	Feature Id - Locn.:	Feature Type: Street Section			Area: Rushcliffe		
erosion marked up to be o	,	Category 2 (High)	Job Completed	14/03/2018	17/03/2018 Act	. RUSH/3703226	