

Effective: 01/01/2018 to 09/01/2019  
Street: Clifford Avenue (4907963)

Display Action Officer: Yes

Street: Clifford Avenue (4907963)

Locality: Beeston, Nottinghamshire

Area: Broxtowe

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Street Section			<b>Area:</b> Broxtowe	
<b>Batch:</b> 20302175 - Inspection Batch	No actionable defects found			<b>Route:</b> Broxtowe South Sep Enh CW/FW	<b>Officer:</b> #2			<b>Date:</b> 12/09/2018
<b>Batch:</b> 20291210 - Inspection Batch	No actionable defects found			<b>Route:</b> Broxtowe South Jun Saf CW	<b>Officer:</b> #2			<b>Date:</b> 29/06/2018
<b>Batch:</b> 20271491 - Inspection Batch				<b>Route:</b> Broxtowe South Mar Saf CW/FW	<b>Officer:</b> #2			<b>Date:</b> 07/03/2018
3570111	Tree root uplift 12 m	07/03/2018	#2	FW Repairs-Bituminous	Internal		Committed	2673094
<b>Feat No.:</b> 4,003.00	<b>Feature Id - Locn.:</b> 4 - O/S No 23			<b>Feature Type:</b> Column			<b>Area:</b> Broxtowe	
<b>Batch:</b> 20685500 - Ad Hoc Inspection Batch				<b>Route:</b> Ad Hoc SL Countywide	<b>Officer:</b> #2			<b>Date:</b> 12/12/2018
20639969	Street Light Fault - Light out - Completely out. Submitted by Advisor: #2 Customer title is #2 (Enquiry 6114377)	12/12/2018	lamp outside 23/25 Clifford Avenue	SL- Street Light out	Internal		Uncommitt	3644600
<b>Feat No.:</b> 6,000.00	<b>Feature Id - Locn.:</b> BROX-02466			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405614 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,001.00	<b>Feature Id - Locn.:</b> BROX-02467			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405613 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,002.00	<b>Feature Id - Locn.:</b> BROX-02468 - OPPOSITE 84			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405615 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,003.00	<b>Feature Id - Locn.:</b> BROX-02469 - FRONT OF 84			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405612 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,004.00	<b>Feature Id - Locn.:</b> BROX-02470 - FRONT OF 65			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405616 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,005.00	<b>Feature Id - Locn.:</b> BROX-02471 - FRONT OF 76			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405611 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,006.00	<b>Feature Id - Locn.:</b> BROX-02472 - FRONT OF 61			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405617 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,007.00	<b>Feature Id - Locn.:</b> BROX-02473 - FRONT OF 68			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405610 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018

Effective: 01/01/2018 to 09/01/2019  
Street: Clifford Avenue (4907963)

Display Action Officer: Yes

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 6,008.00	<b>Feature Id - Locn.:</b> BROX-02474 - FRONT OF 57			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405618 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,009.00	<b>Feature Id - Locn.:</b> BROX-02476			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405607 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,010.00	<b>Feature Id - Locn.:</b> BROX-02477			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405608 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,011.00	<b>Feature Id - Locn.:</b> BROX-02478 - FRONT OF 33			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405606 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,012.00	<b>Feature Id - Locn.:</b> BROX-02479 - FRONT OF 40			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405605 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,013.00	<b>Feature Id - Locn.:</b> BROX-02480 - FRONT OF 22			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405604 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,014.00	<b>Feature Id - Locn.:</b> BROX-02481 - FRONT OF 13			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405597 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,015.00	<b>Feature Id - Locn.:</b> BROX-02482 - FRONT OF 12			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405603 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,016.00	<b>Feature Id - Locn.:</b> BROX-02483 - FRONT OF 7			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405598 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,017.00	<b>Feature Id - Locn.:</b> BROX-02484 - FRONT OF 8			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405602 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,018.00	<b>Feature Id - Locn.:</b> BROX-02485 - FRONT OF 1			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405599 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,019.00	<b>Feature Id - Locn.:</b> BROX-02486 - FRONT OF 2			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405601 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North	<b>Officer:</b> #2			<b>Date:</b> 18/09/2018

Effective: 01/01/2018 to 09/01/2019  
Street: Clifford Avenue (4907963)

Display Action Officer: Yes

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 6,020.00	<b>Feature Id - Locn.:</b> BROX-02487			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405600 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North		<b>Officer:</b> #2		<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 6,021.00	<b>Feature Id - Locn.:</b> BROX-06182 - FRONT OF 58			<b>Feature Type:</b> Platanus x hispanica			<b>Area:</b> Broxtowe	
<b>Batch:</b> 3405609 - Inspection Batch	No actionable defects found			<b>Route:</b> Beeston - North		<b>Officer:</b> #2		<b>Date:</b> 18/09/2018
<b>Feat No.:</b> 8,000.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Broxtowe	
<b>Batch:</b> 10000416 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection		<b>Officer:</b> Tarmac		<b>Date:</b> 06/03/2018
<b>Feat No.:</b> 8,001.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Broxtowe	
<b>Batch:</b> 10000416 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection		<b>Officer:</b> Tarmac		<b>Date:</b> 06/03/2018
<b>Feat No.:</b> 8,002.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Broxtowe	
<b>Batch:</b> 10000416 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection		<b>Officer:</b> Tarmac		<b>Date:</b> 06/03/2018
<b>Feat No.:</b> 8,003.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Broxtowe	
<b>Batch:</b> 10000416 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection		<b>Officer:</b> Tarmac		<b>Date:</b> 06/03/2018
<b>Feat No.:</b> 8,004.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Broxtowe	
<b>Batch:</b> 10000416 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection		<b>Officer:</b> Tarmac		<b>Date:</b> 06/03/2018
<b>Feat No.:</b> 8,005.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Broxtowe	
<b>Batch:</b> 10000416 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection		<b>Officer:</b> Tarmac		<b>Date:</b> 06/03/2018
<b>Feat No.:</b> 8,006.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Broxtowe	
<b>Batch:</b> 10000416 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection		<b>Officer:</b> Tarmac		<b>Date:</b> 06/03/2018
<b>Feat No.:</b> 8,007.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Broxtowe	
<b>Batch:</b> 10000416 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection		<b>Officer:</b> Tarmac		<b>Date:</b> 06/03/2018
<b>Feat No.:</b> 8,008.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Broxtowe	
<b>Batch:</b> 10000416 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection		<b>Officer:</b> Tarmac		<b>Date:</b> 06/03/2018
<b>Feat No.:</b> 8,009.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Broxtowe	
<b>Batch:</b> 10000416 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection		<b>Officer:</b> Tarmac		<b>Date:</b> 06/03/2018

Effective: 01/01/2018 to 09/01/2019  
Street: Clifford Avenue (4907963)

Display Action Officer: Yes

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	8,010.00	Feature Id - Locn.:		Feature Type: Gully			Area: Broxtowe	
Batch:	10000416 - Ad Hoc Inspection			Route: Ad Hoc Inspection	Officer:	Tarmac		Date: 06/03/2018
	No actionable defects found							
Feat No.:	8,011.00	Feature Id - Locn.:		Feature Type: Gully			Area: Broxtowe	
Batch:	10000416 - Ad Hoc Inspection			Route: Ad Hoc Inspection	Officer:	Tarmac		Date: 06/03/2018
	No actionable defects found							
Feat No.:	8,012.00	Feature Id - Locn.:		Feature Type: Gully			Area: Broxtowe	
Batch:	10000416 - Ad Hoc Inspection			Route: Ad Hoc Inspection	Officer:	Tarmac		Date: 06/03/2018
	No actionable defects found							
Feat No.:	8,013.00	Feature Id - Locn.:		Feature Type: Gully			Area: Broxtowe	
Batch:	10000416 - Ad Hoc Inspection			Route: Ad Hoc Inspection	Officer:	Tarmac		Date: 06/03/2018
	No actionable defects found							
Feat No.:	8,014.00	Feature Id - Locn.:		Feature Type: Gully			Area: Broxtowe	
Batch:	10000416 - Ad Hoc Inspection			Route: Ad Hoc Inspection	Officer:	Tarmac		Date: 06/03/2018
	No actionable defects found							
Feat No.:	8,015.00	Feature Id - Locn.:		Feature Type: Gully			Area: Broxtowe	
Batch:	10000416 - Ad Hoc Inspection			Route: Ad Hoc Inspection	Officer:	Tarmac		Date: 06/03/2018
	No actionable defects found							
Feat No.:	8,016.00	Feature Id - Locn.:		Feature Type: Gully			Area: Broxtowe	
Batch:	10000416 - Ad Hoc Inspection			Route: Ad Hoc Inspection	Officer:	Tarmac		Date: 06/03/2018
	No actionable defects found							
Feat No.:	8,017.00	Feature Id - Locn.:		Feature Type: Gully			Area: Broxtowe	
Batch:	10000416 - Ad Hoc Inspection			Route: Ad Hoc Inspection	Officer:	Tarmac		Date: 06/03/2018
	No actionable defects found							

**Customer Services**

Enquiry No.:	6114377	Logged by:	External to Confirm	on:	11/12/2018 16:39	Officer:	#2
Service:	Lighting	Subject:	Street Light Fault	Classification:	Report or Observation	Enquiry Ref:	FS-CASE#2
Desc.:	Light out - Completely out . Submitted by Advisor: #2						
Location:	lamp outside 23/25 Clifford Avenue						
Plot Number:	4,003.00	Feature Id - Location:	4 - O/S No 23	Feature Type:	Column		
Job Number:	3644600	Defect Number:	20639969				
Enquiry No.:	6110958	Logged by:	External to Confirm	on:	03/11/2018 09:03	Officer:	#2
Service:	Traffic Management	Subject:	Parking General	Classification:	Report or Observation	Enquiry Ref:	F#2
Desc.:	Parking issues - owners of property continue to drive car over the pavement with no dropped kerbs , they was served with enforcement action using a plank of wood and then served another one to cease driving over the pavement, but nothing has been done by Via , this needs action taking to cease this action , closing this to keep kpi figures high isn't acceptable , other properties along the ref are the same but the inspector must walk round with blinkers on as they care seem to see cars thats in drives with no dropped kerbs, Maybe a crane moves them into position over night and removes them in the morning ?? . Online report Customer title is Mr.						
Location:	# Clifford Avenue						
Contact:							

Effective: 01/01/2018 to 09/01/2019  
Street: Clifford Avenue (4907963)

Display Action Officer: Yes

**Customer Services**

<b>Enquiry No.:</b> 6108787	<b>Logged by:</b> External to Confirm	<b>on:</b> 10/10/2018 18:21	<b>Officer:</b> #2
<b>Service:</b> Traffic Management	<b>Subject:</b> Parking General	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-91380969
<b>Desc.:</b> Parking issues - Numerous properties on both side of the street have no dropped kerbs and vehicles have mounted the pavement and are on drives , your inspector can't see these cars though , . Online report Customer title is Mr.			
<b>Location:</b> Clifford avenue	<b>Contact:</b>		
<b>Enquiry No.:</b> 6106448	<b>Logged by:</b> External to Confirm	<b>on:</b> 16/09/2018 21:18	<b>Officer:</b> Dropped Kerb Requests
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Dropped Kerb (Vehicle) Request	<b>Classification:</b> Service Request	<b>Enquiry Ref:</b> #2
<b>Desc.:</b> Dropped kerb - Cars & other vehicles - The plan is to get the curb dropped in the middle of the drive way. The width of the pavement is under two meters from the drive way. . Online report - Quote NOT required 3 whole kerb(s) and 2 tapered kerb(s) to be dropped Position of kerb - The drop curb will be put in the middle of the drive way. Customer title is Mr.			
<b>Location:</b> The drop kerb will be outside the property of # Clifford Avenue. The is no drop curb opposite the drive way . There is a tree located about 10 meters away from the start of the drive way.	<b>Contact:</b>		
<b>Enquiry No.:</b> 6104599	<b>Logged by:</b> External to Confirm	<b>on:</b> 21/08/2018 17:42	<b>Officer:</b> #2
<b>Service:</b> Traffic Management	<b>Subject:</b> Parking General	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> #2
<b>Desc.:</b> Parking issues - Properties on the above mentioned streets have no dropped kerbs enforcement action was served on these properties and no action has been taken , this will be reported daily until this is dealt with , it's an offence under section 72 of highways act to drive a vehicle across the pavement with no dropped kerb . Online report Customer title is Mr.			
<b>Location:</b> Numerous properties on central ave , dennis ave , wallet ave , Clifford ave	<b>Contact:</b>		
<b>Enquiry No.:</b> 6104335	<b>Logged by:</b> External to Confirm	<b>on:</b> 19/08/2018 08:12	<b>Officer:</b> #2
<b>Service:</b> Traffic Management	<b>Subject:</b> Parking General	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> #2
<b>Desc.:</b> Parking issues - home owners are breaching the enforcement against them for mounting the pavement to access there drive, without a drop kerb , this has been reported before numerous times , but you can't be bothered to deal with the problem you just close the case , . Online report Customer title is			
<b>Location:</b> Clifford avenue	<b>Contact:</b>		
<b>Enquiry No.:</b> 6103062	<b>Logged by:</b> External to Confirm	<b>on:</b> 04/08/2018 13:23	<b>Officer:</b> #2
<b>Service:</b> Traffic Management	<b>Subject:</b> Parking General	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> #2
<b>Desc.:</b> Parking issues - home owner is still hunting the pavement to put his cars onto the drive , this was supposed to be enforced to stop people with out dropped kerbs mourning the pavement and cross there footway with out a dropped kerb , this is an offence under section 72 of highways act to which you are aiding too . Online report Customer title is Mr.			
<b>Location:</b> # Clifford avenue	<b>Contact:</b>		
<b>Enquiry No.:</b> 6088453	<b>Logged by:</b> External to Confirm	<b>on:</b> 28/03/2018 08:45	<b>Officer:</b> Laura Trusler
<b>Service:</b> Road Works	<b>Subject:</b> Road Works Report	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-71467059
<b>Desc.:</b> Road work issue - Customer has called regarding the state of the road and pavement that has been left after gas works has taken place on the street. Customer believes it was Cadent that has been doing the work. #2 explains that there is dirt and mud all over from where the work had taken place and it is constantly walked into the property. They have not cleared up the mess they made when the work was carried out a few weeks ago. . Submitted by Advisor: #2			
<b>Location:</b> Clifford Avenue, full length	<b>Contact:</b>		
<b>Enquiry No.:</b> 6083151	<b>Logged by:</b> External to Confirm	<b>on:</b> 23/02/2018 19:42	<b>Officer:</b> Sharon Kirk
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Carriageway Obstruction	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-68824018
<b>Desc.:</b> Parking issues - property owner has placed a large piece of wood in the road as he has no dropped kerb but a blocked paved drive , he uses the wood to mount the pavement to get onto his drive . Online report			
<b>Location:</b> # clifford avenue , beeston Nottingham	<b>Contact:</b>		
<b>Enquiry No.:</b> 74114	<b>Logged by:</b> #2	<b>on:</b> 29/08/2018 09:21	<b>Officer:</b> #2
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Dropped Kerb (Vehicle) Request	<b>Classification:</b> Service Request	
<b>Desc.:</b> Illegal VA			
<b>Location:</b> No #	<b>Contact:</b>		

Effective: 01/01/2018 to 09/01/2019  
 Street: Clifford Avenue (4907963)

Display Action Officer: Yes

**Customer Services**

Enquiry No.: 70441      Logged by: #2      on: 27/03/2018 13:23      Officer: #2  
 Service: Carriageway/Footway      Subject: Dropped Kerb (Vehicle) Request      Classification: Service Request  
 Desc.: Get Outlook for Android

Location: #2 clifford av, beeston, notts ng9 2qn Ref no hams 70158...estimate please to lower the highway kerb at the address shown so i can drive my mechanically propelled vehicle on to my drive.  
 Contact:

Enquiry No.: 70128      Logged by: #2      on: 16/03/2018 11:32      Officer: #2  
 Service: Carriageway/Footway      Subject: Carriageway Obstruction      Classification: Report or Observation  
 Desc.: From: #2  
 Sent: 13 March 2018 18:16  
 To: #2  
 Subject: highways

Dear Sir,

I have recently contacted Broxtowe borough council about problems with car owners who haven't dropped kerbs and place pieces of wood in the highway so they can mount the pavement so they can park on their drive or in there garages , Broxtowe council response is that is ok and they have done that to prevent damage to there car tyres , not only is it an offence to mount the pavement or place any object on the highway it is also damages the kerbs and pavement , this is a common practice which the council ignore and s damaged slabs and tarmacked roads around the following roads

- Clifford avenue beeston
- Fairfield Avenue beeston
- Anderson crescent beeston
- wallet avenue beeston
- central avenue beeston
- Dennis avenue beeston

could you please send a highway's officer to remove the pieces of wood from the above roads and enforce any offences

#2

Location: Clifford Avenue      Contact:

**Maintenance Management**

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b>				<b>Feature Type:</b> Street Section		<b>Area:</b> Broxtowe	
2673094	Tree root uplift 12 m (FW Repairs-Bituminous)	Outside 8	#2 (Ash Inspector Category 3)		Job Completed	07/03/2018	20/03/2018 Act.	BROX/3304665
<b>Feat No.:</b> 4,003.00	<b>Feature Id - Locn.:</b> 4 - O/S No 23				<b>Feature Type:</b> Column		<b>Area:</b> Broxtowe	
3644600	Street Light Fault - Light out - Completely out . Submitted by Advisor: #2 title is Mrs. (#2) (SL- Street Light out)	lamp outside #2 Clifford Avenue	#2	SL - 7 Days	Job Completed	12/12/2018	12/12/2018 Act.	

Effective: 01/01/2018 to 09/01/2019  
 Street: Clifford Avenue (4907963)

Display Action Officer: Yes

**Maintenance Management**

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
	<b>Feat No.:</b> 4,012.00	<b>Feature Id - Locn.:</b> 13 - Opp No 69			<b>Feature Type:</b> Column		<b>Area:</b> Broxtowe	
1651367	Street Light Fault - Light not working #2 clifford ave (Enquiry 3190288) (SL- Supply fault (SL10))	Opp No 69	#2	SL- 30 Days	Job Closed	09/11/2015	22/06/2018	Act. EONBRB/35

**Street Works Inspections**

Organisation: NRSWA - Cadent Gas - East Midlands (0010001) (Street Works Admin Team NG Gas)

Works Ref: 1000648309

<b>Group No:</b> 2	<b>Site No:</b> 3	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 25/04/2018 14:15:10
<b>Category:</b> Defect Follow Up		<b>Outcome:</b> Passed	<b>Sampled:</b> No
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> 11300937	<b>Site Informed:</b> Yes
<b>Officer:</b> #2		<b>Tel:</b> 07557895771	<b>Site Location:</b> 35
<b>Insp. Notes:</b>			<b>Position:</b> Footway
<b>Defect Notes:</b>			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Sampled Site No:</b>
			<b>Site Post Code:</b>
<b>Group No:</b> 1	<b>Site No:</b> 3	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 09/04/2018 10:21:32
<b>Category:</b> Third Party Report		<b>Outcome:</b> Failed (Lower Risk/Non Dangerous)	<b>Sampled:</b> No
<b>Defect Notif. No:</b> 11300937		<b>Defect No:</b> 11300937	<b>Site Informed:</b> Yes
<b>Officer:</b> #2		<b>Tel:</b> 07557895771	<b>Site Location:</b> 35
<b>Insp. Notes:</b> c	oth sides of the junction with Central Ave photos available thank you lc		<b>Position:</b> Footway
<b>Defect Notes:</b> clearance needed on both sides of the junction with Central Ave photos available thank you lc			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Sampled Site No:</b>
			<b>Site Post Code:</b>

**Street Works Notices**

Organisation: NRSWA - Cadent Gas - East Midlands (0010001) (Street Works Admin Team NG Gas)

**Works Ref:** 1000648309  
**Notice Type:** Registration of Reinstatement - Full  
**Work Status:** Works Stopped  
**Work Type:** ETon 4: Major

**Version:** 7  
**Start:** 12/02/2018 00:00:00  
**Issued:** 13/03/2018 09:55:13  
**Est. End:** 09/03/2018

**Work Desc:** Gas mains renewal works abandon 422 meters of 4" SI main and replace with 422 meters of 90mm PE using insertion techniques approx 85 transfers and 32 relays EMGA192069  
**Completion:** 09/03/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	#	Footway	Up to 1.5 Metres of Cover	1.60	1.10	A Permanent Reinstatement	09/03/2018		09/03/2018	02/03/2018
2	#	Carriageway	Up to 1.5 Metres of Cover	0.70	0.40	A Permanent Reinstatement	09/03/2018		09/03/2018	
3	##	Footway	Up to 1.5 Metres of Cover	1.50	1.20	A Permanent Reinstatement	09/03/2018		09/03/2018	
4	#	Footway	Up to 1.5 Metres of Cover	1.00	0.70	A Permanent Reinstatement	09/03/2018		09/03/2018	
5	#2	Footway	Up to 1.5 Metres of Cover	0.80	0.70	A Permanent Reinstatement	09/03/2018		09/03/2018	
6	#	Footway	Up to 1.5 Metres of Cover	0.80	0.80	A Permanent Reinstatement	09/03/2018		09/03/2018	
7	#	Footway	Up to 1.5 Metres of Cover	0.90	0.70	A Permanent Reinstatement	09/03/2018		09/03/2018	



Effective: 01/01/2018 to 09/01/2019  
Street: Clifford Avenue (4907963)

Display Action Officer: Yes

### Street Works Notices

Organisation: NRSWA - Cadent Gas - East Midlands (0010001) (Street Works Admin Team NG Gas)

**Works Ref:** 1000648309      **Version:** 7      **Work Desc:** Gas mains renewal works abandon 422 meters of 4" SI main and replace with 422 meters of 90mm PE using insertion techniques approx 85 transfers and 32 relays EMGA192069  
**Notice Type:** Registration of Reinstatement - Full      **Start:** 12/02/2018 00:00:00  
**Work Status:** Works Stopped      **Issued:** 13/03/2018 09:55:13  
**Work Type:** EToN 4: Major      **Est. End:** 09/03/2018      **Completion:** 09/03/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
8	#	Footway	Up to 1.5 Metres of Cover	1.60	1.30	A Permanent Reinstatement	09/03/2018		09/03/2018	
9	#	Footway	Up to 1.5 Metres of Cover	1.90	1.10	A Permanent Reinstatement	09/03/2018		09/03/2018	
10	#	Footway	Up to 1.5 Metres of Cover	0.80	0.60	A Permanent Reinstatement	09/03/2018		09/03/2018	
11	#	Footway	Up to 1.5 Metres of Cover	1.10	1.00	A Permanent Reinstatement	09/03/2018		09/03/2018	
12	#	Footway	Up to 1.5 Metres of Cover	1.00	1.00	A Permanent Reinstatement	09/03/2018		09/03/2018	
13	#	Carriageway	Up to 1.5 Metres of Cover	1.00	1.00	A Permanent Reinstatement	09/03/2018		09/03/2018	
14	#	Footway	Up to 1.5 Metres of Cover	1.00	1.00	A Permanent Reinstatement	09/03/2018		09/03/2018	
15	#	Footway	Up to 1.5 Metres of Cover	1.10	0.80	A Permanent Reinstatement	09/03/2018		09/03/2018	
16	#	Footway	Up to 1.5 Metres of Cover	1.20	1.20	A Permanent Reinstatement	09/03/2018		09/03/2018	
#	Clifford avenue	Carriageway	Up to 1.5 Metres of Cover	0.80	0.80	A Permanent Reinstatement	09/03/2018		09/03/2018	
18	#	Footway	Up to 1.5 Metres of Cover	0.90	0.90	A Permanent Reinstatement	09/03/2018		09/03/2018	
#	Clifford avenue	Footway	Up to 1.5 Metres of Cover	1.00	0.80	A Permanent Reinstatement	09/03/2018		09/03/2018	
20	#	Footway	Up to 1.5 Metres of Cover	1.40	0.90	A Permanent Reinstatement	09/03/2018		09/03/2018	
21	#	Footway	Up to 1.5 Metres of Cover	1.00	1.00	A Permanent Reinstatement	09/03/2018		09/03/2018	
#	Clifford avenue	Footway	Up to 1.5 Metres of Cover	1.20	0.80	A Permanent Reinstatement	09/03/2018		09/03/2018	
#	jct of wollaton	Footway	Up to 1.5 Metres of Cover	1.00	0.80	A Permanent Reinstatement	09/03/2018		09/03/2018	
#	Side of # central avenue	Footway	Up to 1.5 Metres of Cover	1.20	1.60	A Permanent Reinstatement	09/03/2018		09/03/2018	
#	Side of # central avenue	Footway	Up to 1.5 Metres of Cover	4.80	1.00	A Permanent Reinstatement	09/03/2018		09/03/2018	
#	Side of #	Footway	Up to 1.5 Metres of Cover	1.20	1.40	A Permanent Reinstatement	09/03/2018		09/03/2018	
#	J/o central ave	Carriageway	Up to 1.5 Metres of Cover	1.50	2.10	A Permanent Reinstatement	09/03/2018		09/03/2018	
#	J/o central ave	Footway	Up to 1.5 Metres of Cover	0.60	0.60	A Permanent Reinstatement	09/03/2018		09/03/2018	



Effective: 01/01/2018 to 09/01/2019  
Street: Clifford Avenue (4907963)

Display Action Officer: Yes

### Street Works Notices

Organisation: NRSWA - Cadent Gas - East Midlands (0010001) (Street Works Admin Team NG Gas)

Works Ref: 1000648309

Version: 7

Work Desc: Gas mains renewal works abandon 422 meters of 4" SI main and replace with 422 meters of 90mm PE using insertion techniques approx 85 transfers and 32 relays EMGA192069

Notice Type: Registration of Reinstatement - Full

Start: 12/02/2018 00:00:00

Work Status: Works Stopped

Issued: 13/03/2018 09:55:13

Work Type: EToN 4: Major

Est. End: 09/03/2018

Completion: 09/03/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
#	Clifford avenue	Footway	Up to 1.5 Metres of Cover	1.00	0.70	A Permanent Reinstatement	09/03/2018		09/03/2018	
#	Clifford avenue	Footway	Up to 1.5 Metres of Cover	0.80	0.90	A Permanent Reinstatement	09/03/2018		09/03/2018	
#	Clifford avenue	Footway	Up to 1.5 Metres of Cover	1.00	0.90	A Permanent Reinstatement	09/03/2018		09/03/2018	
#	جت of wollaton	Footway	Up to 1.5 Metres of Cover	5.60	1.20	A Permanent Reinstatement	09/03/2018		09/03/2018	