

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Street: Vale Road (24610395)

Locality: Mansfield Woodhouse, Nottinghamshire

Area: Mansfield

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:	Feature Type: Street Section			Area: Mansfield		
Batch: 20383392 - Inspection Batch		Route: Mansfield West Mar Enh CW/FW		Officer:	Personal Information	Date: 17/03/2020		
3636896		17/03/2020	opp lamp 9(1) rd hump lamp 2(1)	CW Repairs-Bituminous	Inte		Uncommitted	2740666
Batch: 20376141 - Inspection Batch		Route: Adhoc Inspection		Officer:		Date: 04/02/2020		
3632574		04/02/2020	jct brown avenue (6) 180(1) 174(1)	CW Repairs-Bituminous	Inte		Uncommitted	2736317
Batch: 20371408 - Inspection Batch		Route: Adhoc Inspection		Officer:		Date: 07/01/2020		
3629531		07/01/2020	122	CW Repairs-Bituminous	Inte		Uncommitted	2733269
Batch: 20367541 - Inspection Batch		Route: Mansfield West Dec Saf CW		Officer:		Date: 09/12/2019		
3627066		09/12/2019	lamp 2	CW Repairs-Bituminous	Inte		Uncommitted	2730795
Batch: 20366448 - Inspection Batch		Route: Adhoc Inspection		Officer:		Date: 03/12/2019		
3626453	9 number infill areas	03/12/2019	between 69 - 73	CW Repairs-Bituminous	Inte		Uncommitted	2730179
Batch: 20360682 - Inspection Batch		Route: Adhoc Inspection		Officer:		Date: 28/10/2019		
3623356	stop & go	28/10/2019	opp lamp 3 fronting speed hump.	CW Repairs-Bituminous	Inte		Committed	2727076
Batch: 20356462 - Inspection Batch		Route: Mansfield West Sep Saf CW/FW		Officer:		Date: 25/09/2019		
3620961		25/09/2019	73	FW Repairs-Bituminous	Internal		Committed	2724668
3620965		25/09/2019	130(2) vale paint (2) lamp 4(1) opp 64(1)	FW Repairs-Bituminous	Internal		Uncommitted	2724666
3620960		25/09/2019	122(2) 152(1)	CW Repairs-Bituminous	Internal		Uncommitted	2724667
3620963	plastic bollard knocked out of ground made safe with cone by inspector.	25/09/2019	opp 68	Other	Internal		Uncommitted	2724670
3620964	pick up bollard out of vale road depot reset in position with in traffic calming kerbs	25/09/2019	opp 68	Bollard Repairs	Internal		Uncommitted	2724671
3620962		25/09/2019	154	Kerbing/Edging	Internal		Committed	2724669
Batch: 20342222 - Inspection Batch		Route: Mansfield West Jun Saf CW		Officer:	Personal Information	nspector)	Date: 19/06/2019	
3613583		19/06/2019	71(4) 73(1) 128(3)	CW Repairs-Bituminous	Inter		Committed	2717254
Batch: 20337053 - Inspection Batch		Route: Adhoc Inspection		Officer:		nspector)	Date: 22/05/2019	
3610849		22/05/2019	jct Brown Ave	CW Repairs-Bituminous	Inter		Committed	2714509
Batch: 20336130 - Inspection Batch		Route: Adhoc Inspection		Officer:		nspector)	Date: 15/05/2019	
3610170		15/05/2019	junction Brown Ave	CW Repairs-Bituminous	Inter		Committed	2713828
Batch: 20330531 - Inspection Batch		Route: Adhoc Inspection		Officer:		nspector)	Date: 08/04/2019	
3606277		08/04/2019	156(1) 67(3) jct manor road (4)	CW Repairs-Bituminous	Inter		Committed	2709910
Batch: 20327543 - Inspection Batch		Route: Mansfield West Mar Enh CW/FW		Officer:		nspector)	Date: 18/03/2019	
3604449		18/03/2019	81(1) 103(2) 105(1) jct brown ave (4)	CW Repairs-Bituminous	Internal		Committed	2708066
3604450	M90 to chip top of kerb	18/03/2019	opp 90	Other	Internal		Committed	2708067
3604451		18/03/2019	lamp 16(1) opp 65(6) 71(6) 73(3) 75(2) 77(2)	CW Repairs-Bituminous	Internal		Committed	2708065
Batch: 20327542 - Inspection Batch		Route: Adhoc Inspection		Officer:	Nigel Freezer (Inspector)	Date: 18/03/2019		
3604448		18/03/2019	77	CW Repairs-Bituminous	Internal		Committed	2708064

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.:			Feature Type: Street Section			Area: Mansfield	
Batch: 20327541 - Inspection Batch				Route: Adhoc Inspection	Officer:	Personal Information	Inspector)	Date: 18/03/2019
3604447		18/03/2019	jct station street	CW Repairs-Bituminous	Inter		Committed	2708063
Batch: 20321090 - Inspection Batch				Route: Adhoc Inspection	Officer:		Inspector)	Date: 31/01/2019
3599932	inspectors reset bollard	31/01/2019	low side lamp 3	Bollard Repairs	Inter		Uncommitted	2703468
Batch: 20314189 - Inspection Batch				Route: Mansfield West Dec Saf CW	Officer:		Inspector)	Date: 05/12/2018
	No actionable defects found							
Batch: 20302919 - Inspection Batch				Route: Mansfield West Sep Saf CW	Officer:		Inspector)	Date: 19/09/2018
3589321	build up no stats, replace existing with plastic bollards	19/09/2018	opp 75	Bollard Repairs	Inter		Committed	2692646
Batch: 20290956 - Inspection Batch				Route: Mansfield West Jun Saf CW	Officer:		Inspector)	Date: 27/06/2018
	No actionable defects found							
Batch: 20278456 - Inspection Batch				Route: Mansfield West Mar Enh CW/FW	Officer:		Inspector)	Date: 18/04/2018
3575316		18/04/2018	opp lamp 9(1) 81(1)	FW Repairs-Bituminous	Internal		Committed	2678388
3575315		18/04/2018	lamp 2(2)178(1) junction brown ave (1)	CW Repairs-Bituminous	Internal		Committed	2678387
3575317	sop and go	18/04/2018	lamp 23	CW Repairs-Bituminous	Internal		Committed	2678386
Batch: 20271639 - Inspection Batch				Route: Adhoc Inspection	Officer:	Personal Information	Inspector)	Date: 07/03/2018
3570238	seal patch 23 fretting areas/potholes	07/03/2018	65(3) 63(1) 69(5) 73(5) 77(2) 79(2) lamp 20 round manhole (1) 87(3) 93(1)	CW Repairs-Bituminous	Inter		Committed	2673222
Batch: 20271635 - Inspection Batch				Route: Adhoc Inspection	Officer:		Inspector)	Date: 07/03/2018
3570232		07/03/2018	road hump vale road chippy	CW Repairs-Bituminous	Inter		Committed	2673216
Batch: 20259690 - Inspection Batch				Route: Mansfield West Dec Saf CW	Officer:			Date: 19/12/2017
3562148	18 number infill areas	19/12/2017	outside 67 (1),outside 69 (10),outside 75 (3),outside 79 (4)	CW Repairs-Bituminous	Inter		Committed	2665020
Batch: 20259173 - Inspection Batch				Route: Adhoc Inspection	Officer:		Inspector)	Date: 14/12/2017
3561862	existing cast iron bollard in depot requires metal sleeve welding in place, then relay back on site. stats required	14/12/2017	junction station street	Bollard Repairs	Inter		Committed	2664725
Batch: 20247670 - Inspection Batch				Route: Mansfield West Sep Saf CW	Officer:		Inspector)	Date: 27/09/2017
3556165		27/09/2017	junction brown avenue	CW Repairs-Bituminous	Inter		Committed	2658687
Batch: 20234822 - Inspection Batch				Route: Mansfield West Jun Saf CW	Officer:		Inspector)	Date: 20/06/2017
3550678		20/06/2017	69	CW Repairs-Bituminous	Inter		Committed	2652777
Batch: 20231695 - Inspection Batch				Route: Adhoc Inspection	Officer:		Inspector)	Date: 30/05/2017
3549244		30/05/2017	70	CW Repairs-Bituminous	Inter		Committed	2651230
Batch: 20224531 - Inspection Batch				Route: Adhoc Inspection	Officer:		Inspector)	Date: 07/04/2017
3546254	work undertaken 6/4/17	07/04/2017	topside vale road chip shop	Bollard Repairs	Internal		Uncommitted	2648069

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 4,001.00	Feature Id - Locn.: 2 - O/S Vale Court			Feature Type: Column			Area: Mansfield	
Batch: 20660195 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide	Officer:	Personal Information	L MANS)	Date: 25/10/2017
20624717	Lamp out as told by resident when repairing 1/c 5 ticket 3626239	25/10/2017		SL- Street Light out	Inter		Committed	3627231
Feat No.: 4,002.00	Feature Id - Locn.: 3 - O/S Vale Ct junct Park Road			Feature Type: Column			Area: Mansfield	
Batch: 20671806 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide	Officer:	Personal Information	L MANS)	Date: 14/05/2018
20632513	Street Light Fault - Light out - Light not working . Online report (Enquiry 6094861)	14/05/2018	LC3	SL- Street Light out	Inter		Committed	3635928
Feat No.: 4,004.00	Feature Id - Locn.: 5 - O/S 22/24 Opp 17			Feature Type: Column			Area: Mansfield	
Batch: 20671160 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide	Officer:	Personal Information	L MANS)	Date: 30/04/2018
20632061	Street Light Fault - Light out - Streetlight out. . Submitted by Advisor: (Enquiry 6093365)	30/04/2018	Streetlight 5 outside 22/24 Vale Road	SL- Street Light out	Inter		Committed	3635386
Batch: 20666332 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide	Officer:	Personal Information	L MANS)	Date: 26/01/2018
20628859	Street Light Fault - Light out - Number 5 streetlight on Vale Road is out, it has been out for a couple of months now and is showing no signs of coming back on. Can someone have a look at this please to see what the issue is? . Submitted by Advisor: (Enquiry 6078537)	26/01/2018		SL- Street Light out	Inter		Committed	3631762
Batch: 20663506 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide	Officer:	Personal Information	L MANS)	Date: 11/12/2017
20626940	Street Light Fault - Light out - Streetlight 5 selected Outside 22/24 Opposite 17 Vale Road is not working. . Submitted by Advisor: (Enquiry 6072849)	11/12/2017		SL- Street Light out	Inter		Committed	3629657
Batch: 20658776 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide	Officer:	Personal Information	L MANS)	Date: 09/10/2017
20623820	Street Light Fault - Light out - Customer is reporting that street light 5 on vale road in mansfield woodhouse is not working. Please can this be looked into. . Submitted by Advisor: (Enquiry 6066635)	09/10/2017		SL- Street Light out	Inter		Committed	3626239
Feat No.: 4,005.00	Feature Id - Locn.: 6 - O/S 27/29 Opp 34			Feature Type: Column			Area: Mansfield	
Batch: 20671159 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide	Officer:	Personal Information	L MANS)	Date: 30/04/2018
20632060	Street Light Fault - Lit during the day - Light is on all the time. . Submitted by Advisor: (Enquiry 6093366)	30/04/2018	Streetlight 6 selected. (Outside 27/29 Opposite 34)	SL- Street Light out	Internal		Committed	3635385

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes


Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	4,005.00	Feature Id - Locn.:	6 - O/S 27/29	Opp 34	Feature Type: Column		Area: Mansfield	
Batch: 20666081 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide	Officer:	Personal Information (SL MANS)	Date: 23/01/2018	
20628701	Street Light Fault - Other streetlight fault - Good morning,	23/01/2018		SL- Street Light out	Internal		Committed	3631578

Column 6 is strobing. Can this be looked into please.

Many thanks

Personal Information



. Online report (Enquiry 6077687)

Batch: 20663504 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide	Officer:	Personal Information (SL MANS)	Date: 11/12/2017	
20626938	Street Light Fault - Lit during the day - Streetlight 6 selected Outside 27/29 Opposite 3 Vale Road is on all the time. Submitted by Advisor: Personal Information (Enquiry 6072853)	11/12/2017		SL- Street Light out	Internal		Committed	3629655
Feat No.:	4,008.00	Feature Id - Locn.:	9 - O/S 50-62	Opp Mdc Depot	Feature Type: Column		Area: Mansfield	
Batch: 20652984 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide	Officer:	Personal Information (MANS)	Date: 17/07/2017	
20620546	Lamp cycling on and off	17/07/2017		SL- (Night Patrol) Column Out	Inter		Committed	3622595
Feat No.:	4,021.00	Feature Id - Locn.:	22 - O/S 156	Opp 87/89	Feature Type: Column		Area: Mansfield	
Batch: 20652983 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide	Officer:	Personal Information (MANS)	Date: 17/07/2017	
20620545	Lamp out	17/07/2017		SL- (Night Patrol) Column Out	Inter		Committed	3622594
Feat No.:	4,021.10	Feature Id - Locn.:	22 - O/S 156	Opp 87/89	Feature Type: Column		Area: Mansfield	
Batch: 20709262 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide	Officer:	Personal Information (MANS)	Date: 29/11/2019	
20651369	lit during the day	29/11/2019		SL- Day burning	Inter		Committed	3658184
Feat No.:	4,027.00	Feature Id - Locn.:	28 - O/S 182	Opp Mayhall Ave	Feature Type: Column		Area: Mansfield	
Batch: 20652981 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide	Officer:	Personal Information (MANS)	Date: 17/07/2017	
20620543	Lamp out	17/07/2017		SL- (Night Patrol) Column Out	Inter		Committed	3622592

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	4,028.00	Feature Id - Locn.:	29 - O/S 109	Opp Brown Ave	Feature Type:	Column	Area: Mansfield	
Batch:	20657914 - Ad Hoc Inspection Batch			Route:	Ad Hoc SL Countywide	Officer:	Personal Information (SL MANS)	Date: 26/09/2017
20623345	Street Light Fault - Other streetlight fault - The streetlight outside 109 Vale Rd near the junction with Brown Ave Mansfield Woodhouse is faulty.It will come on for about 20 mins then turn itself off for about 30 mins then come back on again for another 20mins and it does this all through the night.It started doing this in January 2017. . Submitted by Advisor: Personal Informa Enquiry 6065309)	26/09/2017		SL- Street Light out	Internal		Committed	3625706
Feat No.:	8,000.00	Feature Id - Locn.:		Feature Type:	Gully	Area: Mansfield		
Batch:	10000533 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 07/03/2019
	No actionable defects found							
Batch:	10000353 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 23/10/2017
	No actionable defects found							
Feat No.:	8,002.00	Feature Id - Locn.:		Feature Type:	Gully	Area: Mansfield		
Batch:	10000533 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 07/03/2019
	No actionable defects found							
Batch:	10000353 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 23/10/2017
	No actionable defects found							
Feat No.:	8,003.00	Feature Id - Locn.:		Feature Type:	Gully	Area: Mansfield		
Batch:	10000533 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 07/03/2019
	No actionable defects found							
Batch:	10000353 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 23/10/2017
	No actionable defects found							
Feat No.:	8,004.00	Feature Id - Locn.:		Feature Type:	Gully	Area: Mansfield		
Batch:	10000533 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 07/03/2019
	No actionable defects found							
Batch:	10000353 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 23/10/2017
	No actionable defects found							
Feat No.:	8,005.00	Feature Id - Locn.:		Feature Type:	Gully	Area: Mansfield		
Batch:	10000533 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 07/03/2019
	No actionable defects found							
Batch:	10000353 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 23/10/2017
	No actionable defects found							
Feat No.:	8,006.00	Feature Id - Locn.:		Feature Type:	Gully	Area: Mansfield		
Batch:	10000533 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 07/03/2019
	No actionable defects found							

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,006.00	Feature Id - Locn.:			Feature Type: Gully			Area: Mansfield	
Batch: 10000353 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 23/10/2017
Feat No.: 8,007.00	Feature Id - Locn.:			Feature Type: Gully			Area: Mansfield	
Batch: 10000533 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 07/03/2019
Batch: 10000353 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 23/10/2017
Feat No.: 8,008.00	Feature Id - Locn.:			Feature Type: Gully			Area: Mansfield	
Batch: 10000533 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 07/03/2019
Batch: 10000353 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 23/10/2017
Feat No.: 8,009.00	Feature Id - Locn.:			Feature Type: Gully			Area: Mansfield	
Batch: 10000533 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 07/03/2019
Batch: 10000353 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 23/10/2017
Feat No.: 8,010.00	Feature Id - Locn.:			Feature Type: Gully			Area: Mansfield	
Batch: 10000533 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 07/03/2019
Batch: 10000353 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 23/10/2017
Feat No.: 8,011.00	Feature Id - Locn.:			Feature Type: Gully			Area: Mansfield	
Batch: 10000533 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 07/03/2019
Batch: 10000353 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 23/10/2017
Feat No.: 8,012.00	Feature Id - Locn.:			Feature Type: Gully			Area: Mansfield	
Batch: 10000533 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 07/03/2019
Batch: 10000353 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 23/10/2017
Feat No.: 8,013.00	Feature Id - Locn.:			Feature Type: Gully			Area: Mansfield	
Batch: 10000533 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 07/03/2019

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,013.00	Feature Id - Locn.:			Feature Type: Gully			Area: Mansfield	
Batch: 10000353 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 23/10/2017
Feat No.: 8,014.00	Feature Id - Locn.:			Feature Type: Gully			Area: Mansfield	
Batch: 10000533 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 07/03/2019
Batch: 10000353 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 23/10/2017
Feat No.: 8,015.00	Feature Id - Locn.:			Feature Type: Gully			Area: Mansfield	
Batch: 10000533 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 07/03/2019
Batch: 10000353 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 23/10/2017
Feat No.: 8,016.00	Feature Id - Locn.:			Feature Type: Gully			Area: Mansfield	
Batch: 10000533 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 07/03/2019
Batch: 10000353 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 23/10/2017
Feat No.: 8,017.00	Feature Id - Locn.:			Feature Type: Gully			Area: Mansfield	
Batch: 10000533 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 07/03/2019
Batch: 10000353 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 23/10/2017
Feat No.: 8,018.00	Feature Id - Locn.:			Feature Type: Gully			Area: Mansfield	
Batch: 10000533 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 07/03/2019
Batch: 10000353 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 23/10/2017
Feat No.: 8,019.00	Feature Id - Locn.:			Feature Type: Gully			Area: Mansfield	
Batch: 10000533 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 07/03/2019
Batch: 10000353 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 23/10/2017
Feat No.: 8,020.00	Feature Id - Locn.:			Feature Type: Gully			Area: Mansfield	
Batch: 10000533 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 07/03/2019

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	8,020.00	Feature Id - Locn.:		Feature Type: Gully			Area: Mansfield	
Batch:	10000353 - Ad Hoc Inspection			Route: Ad Hoc Inspection	Officer:	Tarmac		Date: 23/10/2017
	No actionable defects found							
Feat No.:	8,021.00	Feature Id - Locn.:		Feature Type: Gully			Area: Mansfield	
Batch:	10000533 - Ad Hoc Inspection			Route: Ad Hoc Inspection	Officer:	Tarmac		Date: 07/03/2019
	No actionable defects found							
Batch:	10000353 - Ad Hoc Inspection			Route: Ad Hoc Inspection	Officer:	Tarmac		Date: 23/10/2017
	No actionable defects found							

Customer Services

Enquiry No.: 6163933 Logged by: External to Confirm on: 10/03/2020 11:18 Officer: Personal Information
 Service: Road Works Subject: Road Works Report Classification: Report or Observation Enquiry Ref: FS-CASE-182205744
 Desc.: Road work issue - The resurfacing job is disgraceful. The pot holes are showing through already. All the surface is loose. You wouldn't be able to put white lines on it, too loose, no tar in it. Needs doing again. When will be doing under the railway bridge as well. . Submitted by Advisor: Robert Warburton Customer title is Mr.
 Location: The common lane end of vale road. Contact:

Enquiry No.: 6163701 Logged by: External to Confirm on: 09/03/2020 11:09 Officer: Personal Information
 Service: Carriageway/Footway Subject: Line Marking/Stud Renewal Classification: Report or Observation Enquiry Ref: FS-CASE-181826370
 Desc.: Road marking renewal - before the resurfacing, customer has a H bar outside her dropped kerb. she would like this to be renewed now the road has been resurfaced. . Submitted by Advisor: Personal Information
Personal Information
Personal Information
Personal Information
Personal Information
 Contact:

Enquiry No.: 6157218 Logged by: External to Confirm on: 05/02/2020 15:15 Officer: Personal Information
 Service: Carriageway/Footway Subject: Spillage/Debris on Carriageway Classification: Report or Observation Enquiry Ref: FS-CASE-172665910
 Desc.: Spillage/debris in road - Mud and dirt from tip is pouring out on to the road surface, road has been swept but this is just spreading the dirt around. Customer would like this road surface power washed as the dirt is making the road surface slippery and is covering residents vehicles and property in dirt. . Submitted by Advisor: Personal Information Customer title is Person
 Location: Vale Road entire length. Contact:

Enquiry No.: 6156424 Logged by: External to Confirm on: 30/01/2020 16:48 Officer: Personal Information
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation Enquiry Ref: FS-CASE-171356926
 Desc.: Road Pothole - Gaping Pothole getting worse as the lorries from the quarry keep going over it . Online report Customer title is Person
 Location: At the entrance to Vale Road from Station Street Contact:

Plot Number: 2,000.00 Feature Id - Location: Feature Type: Street Section
 Job Number: 2736317 Defect Number: 3632574

Enquiry No.: 6152529 Logged by: External to Confirm on: 06/01/2020 07:27 Officer: Personal Information
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation Enquiry Ref: FS-CASE-165647778
 Desc.: Road Pothole - Pothole on edge of speed hump in middle of road . Online report Customer title is Person
 Location: on the speed humps just before Shelley Ave Contact:

Plot Number: 2,000.00 Feature Id - Location: Feature Type: Street Section
 Job Number: 2733269 Defect Number: 3629531

Effective: 02/04/2017 to 02/04/2020

Display Action Officer: Yes

Street: Vale Road (24610395)

Customer Services

Enquiry No.: 6142922	Logged by: External to Confirm	on: 21/10/2019 18:48	Officer: Personal Information
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-151863923
Desc.: Road Damage - Road around the speed hump as sunk and is causing cars to scrape the speed hump mine included. . Online report Customer title is Person			
Location: Vale road Mansfield woodhouse road around first speed hump		Contact:	
Plot Number: 2,000.00	Feature Id - Location:	Feature Type: Street Section	
Job Number: 2727076	Defect Number: 3623356		
Enquiry No.: 6127461	Logged by: External to Confirm	on: 10/05/2019 18:57	Officer: Personal Information (Inspector)
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-118255105
Desc.: Road Pothole - Pothole come back after the rain . Online report Customer title is			
Location: Top of Vale road		Contact:	
Plot Number: 2,000.00	Feature Id - Location:	Feature Type: Street Section	
Job Number: 2713828	Defect Number: 3610170		
Enquiry No.: 6124885	Logged by: External to Confirm	on: 05/04/2019 09:06	Officer: Personal Information (Inspector)
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-112659582
Desc.: Road Damage - Numerous potholes, road desperately needs resurfacing . Online report Customer title is Person			
Location: Vale road Mansfield woodhouse		Contact:	
Plot Number: 2,000.00	Feature Id - Location:	Feature Type: Street Section	
Job Number: 2709910	Defect Number: 3606277		
Enquiry No.: 6122533	Logged by: External to Confirm	on: 13/03/2019 10:33	Officer: Personal Information (Inspector)
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-109272821
Desc.: Road Pothole - As above . Online report Customer title is Person			
Location: Deep pothole between road humps by Focus Point/ 73 -77 Vale Rd plus numerous smaller potholes in area towards junction with Ferguson Ave		Contact:	
Plot Number: 2,000.00	Feature Id - Location:	Feature Type: Street Section	
Job Number: 2708064	Defect Number: 3604448		
Enquiry No.: 6122529	Logged by: External to Confirm	on: 13/03/2019 10:21	Officer: Personal Information (Inspector)
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-109267123
Desc.: Road Pothole - A reasonably deep pothole and unavoidable . Online report Customer title is Person			
Location: As you turn left into Vale Rd from Station St you hit the pothole in center of road		Contact:	
Plot Number: 2,000.00	Feature Id - Location:	Feature Type: Street Section	
Job Number: 2708063	Defect Number: 3604447		
Enquiry No.: 6119283	Logged by: External to Confirm	on: 07/02/2019 14:23	Officer: Personal Information Personal Info
Service: Carriageway/Footway	Subject: Spillage/Debris on Carriageway	Classification: Report or Observation	Enquiry Ref: FS-CASE-105034395
Desc.: Spillage/debris in road - Dirt and mud on the road from the trucks from the quarry, it is also transferring onto resident's cars and driveway. Customer is very unhappy about this, he states that it is dangerous especially when frosty. He said there is a road sweeper that comes along but that it doesn't work as it just disperses the mud. He wishes for it to be cleaned/jet washed. He has asked someone contact him by phone once it has been inspected to inform him of any updates. . Submitted by Advisor: Personal Information Customer title is Person			
Location: Vale Road Mansfield Woodhouse		Contact:	

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Customer Services

Enquiry No.: 6114719 **Logged by:** External to Confirm **on:** 15/12/2018 19:39 **Officer:** Personal Information (Inspector)
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-99766883
Desc.: Road Pothole - Pothole is forming again where it has been repaired once, getting quite deep. Also the road is getting pot holes when you enter the bridge on to common lane. . Online report Customer title is
Location: Pothole is forming again where it has been repaired once, getting quite deep top of Vale road heading towards common lane. Also the road is getting pot holes when you enter the bridge on to common lane. **Contact:**

Enquiry No.: 6114270 **Logged by:** External to Confirm **on:** 10/12/2018 22:09 **Officer:** Personal Information
Service: Licences/Permits **Subject:** Res Park Permit Request (new) **Classification:** Service Request **Enquiry Ref:** FS-CASE-99231148
Desc.: Residents parking scheme proposal - The area in question is between Numbers 16 and 42 Vale Road. The parking here is very limited and no house has a driveway, garage or any form of private parking.

Over the last year parking has become increasingly congested and contested. Parking disputes have ensued between a number of neighbours some of which are getting heated and aggressive. Some residents believe they have a 'right' to park directly outside there property, others have 2-3 vehicles and take up an ezcessive amount of the limited space.

Recently a neighbor has erected a 'no parking' sign despite having 3 cars and has been harassing neighbors who park directly outside there property.

A neighbor has informed me she is considering moving house due to the stress of the parking situation and complaints from her neighbours, despite the fact she is parking perfectly legally as there is no assigned parking. As stated those causing much of the problem are those with multiple (2 or more) vehicles taking up unecessary amounts of space.

Often on busy days, such as Saturdays and Sundays the problem becomes worse with visitors. Residents are often left to park on the surround streets (e.g Park road, park Street and limestone terrace) which can be frustrating if they have young children or a large amount of baggage (shopping etc).

My worry is that if things continue as they are the frustration and anger will escalate perhaps leading to more harrasment or criminal damage.

I would suggest making this section of the road limited to permit parking, with one visitor permit and one residents permit per household. This will therefore ease congestion caused by visitors of those with multiple vehicles. . Online report - Customer title is Person

Location: Between numbers 16 and 42 Vale Road (RHS) Mansfield Woodhouse **Contact:**

Enquiry No.: 6097803 **Logged by:** External to Confirm **on:** 07/06/2018 14:21 **Officer:** Personal Information
Service: Traffic Management **Subject:** Traffic Issues **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-78035050
Desc.: Traffic issues - Is there a possibility of putting yellow lines outside the Housing Repairs office. Problems are created with vehicles parking outside the entrance gates both ends and there is limited vision when coming out the depot. Vale Road is a busy road and there are a lot of lorries back and forward to the quarry. We have a busy depot and approximately 80 vans are in and out at various times of the day. We have also delivery lorries. . Online report - Customer title is Person
Location: Outside Mansfield District Council, Vale Road Housing Repairs **Contact:**

Enquiry No.: 6095775 **Logged by:** External to Confirm **on:** 21/05/2018 15:42 **Officer:** Highway Authorisations
Service: Carriageway/Footway **Subject:** Dropped Kerb (Vehicle) Request **Classification:** Service Request **Enquiry Ref:** FS-CASE-76200975
Desc.: Dropped kerb - Cars & other vehicles - wanting to have a dropped kerb for his driveway . Submitted by Advisor: Personal Information - Quote required - 8 kerb(s) to be dropped - Position of kerb - directly outside the house Customer title is Person
Location: Person Vale Road,
Mansfield Woodhouse,
NG198DW **Contact:**

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Customer Services

Enquiry No.: 6094861	Logged by: External to Confirm	on: 11/05/2018 17:03	Officer: Personal Information (SL MANS)
Service: Lighting	Subject: Street Light Fault	Classification: Report or Observation	Enquiry Ref: FS-CASE-75379172
Desc.: Light out - Light not working . Online report			
Location: LC3	Contact:		
Plot Number: 4,002.00	Feature Id - Location: 3 - O/S Vale Ct junct Park Road	Feature Type: Column	
Job Number: 3635928	Defect Number: 20632513		
Enquiry No.: 6094664	Logged by: External to Confirm	on: 10/05/2018 13:45	Officer: Personal Information
Service: Traffic Management	Subject: Parking General	Classification: Report or Observation	Enquiry Ref: FS-CASE-75230852
Desc.: Parking issues - Customer is advising that the parking along vale road is very full- cars are also parking very close to dropped kerb making it difficult to enter and exit the drive way. Customer has advised the neighbors own over 5 mini buses and continuously park on the roadside causing difficulty for public to access driveways or park near home. . Submitted by Advisor: Personal Information			
Location: Along the street of Vale Road, MANSFIELD WOODHOUSE, Mansfield Woodhouse, Nottinghamshire, NG19 8DW	Contact:		
Enquiry No.: 6094663	Logged by: External to Confirm	on: 10/05/2018 13:39	Officer: Personal Information
Service: Carriageway/Footway	Subject: Dropped Kerb (Vehicle) Request	Classification: Service Request	Enquiry Ref: FS-CASE-75229598
Desc.: Dropped kerb - Cars & other vehicles - Customer has had a dropped kerb put into place over 15 years and have advised that it has always been quite high for a dropped kerb. Customer has now noticed that when pulling on and off the driveway with caravan it is causing a scraping to the bottom and leaving marks on the pavement. Customer advised the kerb also catches the front of the car when reversing off the drive. . Submitted by Advisor: Baily De Ville - Quote required - 6 kerb(s) to be dropped - Position of kerb - Out the front of Personal Information ANSFIELD WOODHOUSE, Mansfield Woodhouse, Nottinghamshire, Personal Information Customer title is Personal Information			
Location: On Vale Road- outside number Personal Information MANSFIELD WOODHOUSE, Mansfield Woodhouse, Nottinghamshire, NG19 8DW	Contact:		
Enquiry No.: 6093366	Logged by: External to Confirm	on: 27/04/2018 14:47	Officer: Personal Information (SL MANS)
Service: Lighting	Subject: Street Light Fault	Classification: Report or Observation	Enquiry Ref: FS-CASE-74067856
Desc.: Lit during the day - Light is on all the time. . Submitted by Advisor: Personal Information			
Location: Streetlight 6 selected. (Outside 27/29 Opposite 34)	Contact:		
Plot Number: 4,005.00	Feature Id - Location: 6 - O/S 27/29 Opp 34	Feature Type: Column	
Job Number: 3635385	Defect Number: 20632060		
Enquiry No.: 6093365	Logged by: External to Confirm	on: 27/04/2018 14:45	Officer: Personal Information (SL MANS)
Service: Lighting	Subject: Street Light Fault	Classification: Report or Observation	Enquiry Ref: FS-CASE-74066898
Desc.: Light out - Streetlight out. . Submitted by Advisor: Personal Information			
Location: Streetlight 5 outside 22/24 Vale Road	Contact:		
Plot Number: 4,004.00	Feature Id - Location: 5 - O/S 22/24 Opp 17	Feature Type: Column	
Job Number: 3635386	Defect Number: 20632061		
Enquiry No.: 6093337	Logged by: External to Confirm	on: 27/04/2018 11:57	Officer: Personal Information
Service: Carriageway/Footway	Subject: Request new line marking/studs	Classification: Report or Observation	Enquiry Ref: FS-CASE-74042398
Desc.: New road marking - The customer has had a gate installed on his drive and now people are parking across the driveway and close which is stopping access for him. During the day he cannot get in or out as even though the vans do leave some space it's difficult for visibility. Can a H-bar or something of the like be installed so that the customer can have access to his drive. . Submitted by Advisor: Personal Information - - Customer title is Personal Information .			
Location: Directly at the bottom of the customer's drive.	Contact:		

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Customer Services

Enquiry No.: 6090510	Logged by: External to Confirm	on: 09/04/2018 10:42	Officer: Personal Information (Inspector)
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-72366851
Desc.: Road Pothole - Series of deep pot holes requiring urgent attention in this area. . Online report			
Location: Vale Road	Contact:		
Plot Number: 2,000.00	Feature Id - Location:	Feature Type: Street Section	
Job Number: 2678387			
Enquiry No.: 6085806	Logged by: External to Confirm	on: 13/03/2018 13:21	Officer: Personal Information (Inspector)
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-70198900
Desc.: Road Damage - Badly damaged road surface including pot holes . Online report			
Location: On Vale Road outside the Community Centre, affecting both sides of the road	Contact:		
Plot Number: 2,000.00	Feature Id - Location:	Feature Type: Street Section	
Job Number: 2673222			
Enquiry No.: 6085351	Logged by: External to Confirm	on: 12/03/2018 10:38	Officer: Personal Information
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-70054715
Desc.: Road Pothole - Thank you for your information regarding FS68117584, what I would also like to know is why you repaired a section of Vale Road last month by totally re-surfacing the road, which was no where near as bad as the section of road you have now looked at? . Submitted by Advisor: Personal Information			
Location: Vale Road, Mansfield Woodhouse, NG19 8SG	Contact:		
Enquiry No.: 6084850	Logged by: External to Confirm	on: 08/03/2018 08:30	Officer: Personal Information (Inspector)
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-69778352
Desc.: Road Pothole - the pot hole has been getting worse over the last few weeks. the road got replaced from the crossing to just the other side of the council offices but the road wasn't repaired where it needs doing. I drove into the hole the other day as it isn't easy to get pass without hitting one of the potholes in this area. I am not sure if this has caused any damage to my vehicle. But it is pulling to onside (passenger) now . Online report			
Location: on the brow of the hill outside the community centre just after the road hump heading down vale rd towards council offices	Contact:		
Plot Number: 2,000.00	Feature Id - Location:	Feature Type: Street Section	
Job Number: 2673222			
Enquiry No.: 6084741	Logged by: External to Confirm	on: 07/03/2018 13:18	Officer: Personal Information (Inspector)
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-69714708
Desc.: Road Pothole - first speed bump on Vale Road from High Street . Online report			
Location: Large pot hole directly behind speed bump	Contact:		
Plot Number: 2,000.00	Feature Id - Location:	Feature Type: Street Section	
Job Number: 2673222			
Enquiry No.: 6084297	Logged by: External to Confirm	on: 05/03/2018 09:39	Officer: Personal Information (Inspector)
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-69444083
Desc.: Road Pothole - Large potholes . Online report			
Location: Worst potholes between Ferguson Avenue and Greenwood Avenue however all of Vale Road requires inspection due to numerous more minor potholes.	Contact:		
Plot Number: 2,000.00	Feature Id - Location:	Feature Type: Street Section	
Job Number: 2673222	Defect Number: 3570238		

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Customer Services

Enquiry No.: 6084221 Logged by: External to Confirm on: 03/03/2018 15:48 Officer: Personal Information (Inspector)
Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation Enquiry Ref: FS-CASE-69379922
Desc.: Road Pothole - Lots of potholes down vale road outside and just past Vale Road Focus point (community centre) some are very deep. . Online report
Location: Lots of potholes down vale road outside and just past Vale Road Focus point (community centre) some are very deep. Contact:

Plot Number: 2,000.00 Feature Id - Location: Feature Type: Street Section
Job Number: 2673222

Enquiry No.: 6084181 Logged by: External to Confirm on: 02/03/2018 17:27 Officer: Personal Information (Inspector)
Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation Enquiry Ref: FS-CASE-69347310
Desc.: Road Pothole - Large pothole on exit to road hump . Online report
Location: Vale Rd half way between High Street and Park Road. Immediately on exit to road hump. Contact:

Plot Number: 2,000.00 Feature Id - Location: Feature Type: Street Section
Job Number: 2673216 Defect Number: 3570232

Enquiry No.: 6083002 Logged by: External to Confirm on: 22/02/2018 19:45 Officer: Personal Information (Inspector)
Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation Enquiry Ref: FS-CASE-68734915
Desc.: Road Pothole - Pot hole by the speed bump at the bottom of vale road . Online report
Location: Just below the new tarmac by the speed bump Contact:

Plot Number: 2,000.00 Feature Id - Location: Feature Type: Street Section
Job Number: 2673216

Enquiry No.: 6081812 Logged by: External to Confirm on: 15/02/2018 13:54 Officer: Personal Information
Service: Road Works Subject: Road Works Report Classification: Report or Observation Enquiry Ref: FS-CASE-68157954
Desc.: Road work issue - When resurfacing works were going on this street, customer's car which was parked on his drive has been splattered with overspray from the works. . Submitted by Advisor: Personal Information
Location: Customer's property, Personal Information Vale Road Contact:

Enquiry No.: 6081725 Logged by: External to Confirm on: 15/02/2018 09:42 Officer: Personal Information (Inspector)
Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation Enquiry Ref: FS-CASE-68117584
Desc.: Road Damage - At least 50 deep potholes along northern end of Vale Road, the southern end of Vale Road has just been resurfaced and it wasn't anywhere near as bad. Can we let customer know if and when there are any plans to resurface. . Submitted by Advisor: Personal Information
Location: Vale Road, northern end near Manor Road and Ferguson Avenue turnings, Mansfield Woodhouse. Contact:

Plot Number: 2,000.00 Feature Id - Location: Feature Type: Street Section
Job Number: 2673222

Enquiry No.: 6080551 Logged by: External to Confirm on: 07/02/2018 10:12 Officer: Personal Information
Service: Road Works Subject: Road Works Report Classification: Report or Observation Enquiry Ref: FS-CASE-67511668
Desc.: Road work issue - there has been warnings that this road is going to be closed for about a week for resurfacing however, Personal Information i have just been woken up by a very angry man telling me if i don't move my car he will move it for me and get it lifted. I haven't had a letter regarding the removal of my vehicle or i would have done so and none of my neighbors on this street have either Personal Information

I'm not too happy that i wasn't told about this to remove my vehicle or i would have done this. I just want you to learn by your mistakes. and getting this right next time with the general admin. .
Submitted by Advisor: Personal Information

Location: Outside customers address Personal Information Vale Road, MANSFIELD WOODHOUSE, Mansfield Contact:
Woodhouse, Nottinghamshire , NG19 8EA.

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Customer Services

Enquiry No.: 6078537 **Logged by:** External to Confirm **on:** 26/01/2018 11:54 **Officer:** Personal Information (SL MANS)
Service: Lighting **Subject:** Street Light Fault **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-66697254
Desc.: Light out - Number 5 streetlight on Vale Road is out, it has been out for a couple of months now and is showing no signs of coming back on. Can someone have a look at this please to see what the issue is? . Submitted by Advisor: Personal Information

Location: **Contact:**

Plot Number: 4,004.00 **Feature Id - Location:** 5 - O/S 22/24 Opp 17 **Feature Type:** Column
Job Number: 3631762 **Defect Number:** 20628859

Enquiry No.: 6077687 **Logged by:** External to Confirm **on:** 23/01/2018 08:47 **Officer:** Personal Information (SL MANS)
Service: Lighting **Subject:** Street Light Fault **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-66423944
Desc.: Other streetlight fault - Good morning,

Column 6 is strobing. Can this be looked into please.

Many thanks

Personal Information MIET, MInstLM
Supervisor (Electrical)

Housing Repairs Services
Mansfield District Council
Vale Road
Mansfield Woodhouse
Mansfield
Nottinghamshire
NG198EB

Tel:- Personal Information
Email:- Personal Information
Web:- www.mansfield.gov.uk
. Online report

Location: **Contact:**

Plot Number: 4,005.00 **Feature Id - Location:** 6 - O/S 27/29 Opp 34 **Feature Type:** Column
Job Number: 3631578 **Defect Number:** 20628701

Enquiry No.: 6077686 **Logged by:** External to Confirm **on:** 23/01/2018 08:47 **Officer:** Personal Information
Service: Traffic Management **Subject:** Parking General **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-66423660
Desc.: Parking issues - Customer is reporting a parking issue on behalf of his nan who lives at Personal Information Vale Road. Parking is already limited in this area, but it is made a lot worse because of a company called Adventure Services who have cars and minibuses, that are parking on his nan's side of the road, rather than on their own side where the business is. An Ambulance came a couple weeks ago, and the ambulance was unable to park outside his nan's address and had to park 4 doors down before helping her for an emergency. The neighbours are also having parking issues due to adventure services vehicles taking up the pavement. The customer has tried talking to them, but no improvement has happened, so he and his nan need your help sorting this. . Submitted by Advisor: Personal Information

Location: No 156 **Contact:**

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Customer Services

Enquiry No.: 6074054	Logged by: External to Confirm	on: 20/12/2017 16:23	Officer: Personal Information
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS64256147
Desc.: Insurance claim - related to Confirm defect reference: 6074053			
Date/Time: 20/12/2017 16:05:00			
Direction of travel: Hilltop Northfield Avenue, PLEASLEY VALE, Pleasley Vale, Nottinghamshire, NG19 8SG			
Going to Common Lane			
Account of what happened: Customer was travelling down Vale road which then turns into Common Lane, as customer was travelling under the bridge she struck a vary large and deep pot hole which has shredded some of the customer tyres. Customer is ok but very distressed.			
Customer could not give an exact size of the pot hole but said it was large and deep enough to cause significant damage.			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6072853	Logged by: External to Confirm	on: 11/12/2017 11:27	Officer: Personal Information (SL MANS)
Service: Lighting	Subject: Street Light Fault	Classification: Report or Observation	Enquiry Ref: FS-CASE-63680450
Desc.: Lit during the day - Streetlight 6 selected Outside 27/29 Opposite 3 Vale Road is on all the time. . Submitted by Advisor: Personal Information			
Location:		Contact:	
Plot Number: 4,005.00	Feature Id - Location: 6 - O/S 27/29 Opp 34	Feature Type: Column	
Job Number: 3629655	Defect Number: 20626938		
Enquiry No.: 6072849	Logged by: External to Confirm	on: 11/12/2017 11:27	Officer: Personal Information (SL MANS)
Service: Lighting	Subject: Street Light Fault	Classification: Report or Observation	Enquiry Ref: FS-CASE-63680002
Desc.: Light out - Streetlight 5 selected Outside 22/24 Opposite 17 Vale Road is not working. . Submitted by Advisor: Personal Information			
Location:		Contact:	
Plot Number: 4,004.00	Feature Id - Location: 5 - O/S 22/24 Opp 17	Feature Type: Column	
Job Number: 3629657	Defect Number: 20626940		
Enquiry No.: 6067859	Logged by: External to Confirm	on: 20/10/2017 13:29	Officer: Personal Information (Inspector)
Service: Carriageway/Footway	Subject: Footway Obstruction	Classification: Report or Observation	Enquiry Ref: FS-CASE-60569508
Desc.: Pavement obstructions - There are 4 metal black and gold posts on the corner of Station Street and Vale road. 1 has been knocked out and is lying on the pavement. . Submitted by Advisor: Personal Information			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6067808	Logged by: External to Confirm	on: 20/10/2017 08:29	Officer: Personal Information
Service: Traffic Management	Subject: Parking General	Classification: Report or Observation	Enquiry Ref: FS-CASE-60544267
Desc.: Parking issues - A caravan is parked on the pavement outside 22 Elm Tree Avenue, it has been there for a considerable amount of time, many months, it has no registration plate. . Online report			
Location: See map coordinates and description details		Contact:	
Plot Number: 2,000.00	Feature Id - Location:	Feature Type: Street Section	
Job Number: 2664049			

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Customer Services

Enquiry No.: 6066635 Service: Lighting Desc.: Light out - Customer is reporting that street light 5 on vale road in mansfield woodhouse is not working. Please can this be looked into. . Submitted by Advisor: [Personal Information] Location:	Logged by: External to Confirm Subject: Street Light Fault	on: 09/10/2017 12:17 Classification: Report or Observation	Officer: [Personal Information] (SL MANS) Enquiry Ref: FS-CASE-59896380
Plot Number: 4,004.00 Job Number: 3626239	Feature Id - Location: 5 - O/S 22/24 Opp 17 Defect Number: 20623820		Feature Type: Column
Enquiry No.: 6065309 Service: Lighting Desc.: Other streetlight fault - The streetlight outside 109 Vale Rd near the junction with Brown Ave Mansfield Woodhouse is faulty.It will come on for about 20 mins then turn itself off for about 30 mins then come back on again for another 20mins and it does this all through the night.It started doing this in January 2017. . Submitted by Advisor: [Personal Information] Location:	Logged by: External to Confirm Subject: Street Light Fault	on: 26/09/2017 11:32 Classification: Report or Observation	Officer: [Personal Information] (SL MANS) Enquiry Ref: FS-CASE-59274325
Plot Number: 4,028.00 Job Number: 3625706	Feature Id - Location: 29 - O/S 109 Opp Brown Ave Defect Number: 20623345		Feature Type: Column
Enquiry No.: 6058824 Service: Carriageway/Footway Desc.: Dropped kerb - Cars & other vehicles - Dropped Kerb request outside [Personal Information] Vale Road. The caller is looking to put a drive in place. . Submitted by Advisor: [Personal Information] - Quote required Location: Outside [Personal Information] Vale Road. Mansfield Woodhouse	Logged by: External to Confirm Subject: Dropped Kerb (Vehicle) Request	on: 19/07/2017 15:23 Classification: Service Request	Officer: [Personal Information] Enquiry Ref: FS-CASE-56198945
Enquiry No.: 6053867 Service: Carriageway/Footway Desc.: Road Pothole - Deep pothole between speed humps outside MDC depot not helped with cars parked either side of road . Online report Location: See map coordinates and description details	Logged by: External to Confirm Subject: Carriageway Pothole	on: 27/05/2017 11:17 Classification: Report or Observation	Officer: [Personal Information] (Inspector) Enquiry Ref: FS-CASE-53430791
Plot Number: 2,000.00 Job Number: 2651230	Feature Id - Location: Defect Number: 3549244		Feature Type: Street Section
Enquiry No.: 2507179 Service: Carriageway/Footway Desc.: cllr bosnjak is not happy with the resurfacing work which has recently been undertaken on vale road and wants to know what is happening Location: vale road	Logged by: [Personal Information] Subject: Surface Dressing	on: 11/03/2020 14:23 Classification: Report or Observation	Officer: [Personal Information]
Enquiry No.: 84221 Service: Carriageway/Footway Desc.: Half a dozen potholes Location: focus point	Logged by: [Personal Information] Subject: Carriageway Damage	on: 29/11/2019 10:49 Classification: Report or Observation	Officer: [Personal Information]
Plot Number: 2,000.00 Job Number: 2730179	Feature Id - Location: Defect Number: 3626453		Feature Type: Street Section
Enquiry No.: 77610 Service: Carriageway/Footway Desc.: a calming post is damaged Location: on Vale Rd 50 yard from chippy - probably here https://goo.gl/maps/wURuCLmd4Fm	Logged by: [Personal Information] Subject: Carriageway Damage	on: 30/01/2019 16:35 Classification: Report or Observation	Officer: [Personal Information] (Inspector)
Plot Number: 2,000.00 Job Number: 2703468	Feature Id - Location: Defect Number: 3599932		Feature Type: Street Section

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Customer Services

Enquiry No.: 75822	Logged by: Personal Information	on: 02/11/2018 11:48	Officer: Personal Information
Service: Lighting	Subject: Requests for Street Lighting	Classification: Service Request	
Desc.: Can any of you resolve this please as a matter of some urgency as lighting engineers are on site. I have had 2 irate Vale Road residents contact me regarding a new street light being installed. Where it is to go would shine directly into their bedrooms and would prevent a proposed driveway being built. I have had no request for additional lighting and the area looks to be adequately light.			
Location: No 59	Contact:		
Enquiry No.: 70900	Logged by: Personal Information	on: 12/04/2018 11:48	Officer: Personal Information
Service: Traffic Management	Subject: Speed Limits/Issues	Classification: Report or Observation	
Desc.:			
Location: end of Vale Road nearest railway line	Contact:		
Enquiry No.: 70027	Logged by: Personal Information	on: 14/03/2018 10:55	Officer: Personal Information
Service: Claims	Subject: Via Operations Insurance Claim	Classification: Report or Observation	
Desc.: Recently we had some workmen come and resurface part of our road, however on completion of the work myself and a few of my fellow residents have noticed the fronts of our houses are covered with speckles of tar which will not come off! My car was parked at least 12ft from the kerb and the tar has managed to cover the back, the front and the front of my house!			
Location: Near No 64	Contact:		
Enquiry No.: 69943	Logged by: Personal Information	on: 13/03/2018 11:59	Officer: Personal Information
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: that a portion of the road has recently been resurfaced from the junction of Station Street to Shelley Avenue, however the remainder of Vale Road, leading to Brown Avenue is still in a very poor state of repair - are there any immediate plans to complete this road?			
Location: Shelley Ave to Brown Ave	Contact:		
Enquiry No.: 67850	Logged by: Personal Information	on: 06/12/2017 14:43	Officer: Personal Information (SL MANS)
Service: Lighting	Subject: Street Light Fault	Classification: Report or Observation	
Desc.: Reported and fixed previously on HAMS 6066635, but its faulty again now and switching on and off/flickering			
Location: L/C No 5 near play area/Focus Point	Contact:		
Plot Number: 4,004.00	Feature Id - Location: 5 - O/S 22/24	Opp 17	Feature Type: Column
Job Number: 3635386	Defect Number: 20632061		
Enquiry No.: 64604	Logged by: Personal Information	on: 11/07/2017 13:58	Officer: Personal Information
Service: Traffic Management	Subject: Parking General	Classification: Report or Observation	
Desc.: Mr Parke would like a disabled bay outside his house.			
Location: Vale Road	Contact:		

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 2,000.00	Feature Id - Locn.:			Feature Type: Street Section	Area: Mansfield			
2648069	work undertaken 6/4/17 (Bollard Repairs)	topside vale road chip shop	Personal Information Inspector)	Category 1	Job Completed	07/04/2017	06/04/2017	Act.
2651230	CW Repairs-Bituminous	70	Personal Information Inspector)	Category 1	Job Completed	30/05/2017	31/05/2017	Act. MAN-AS/5403105
2652777	CW Repairs-Bituminous	69	Personal Information Inspector)	Category 2	Job Completed	20/06/2017	27/06/2017	Act. MAN-AS/5403219
2658687	CW Repairs-Bituminous	junction brown avenue	Personal Information Inspector)	Category 2	Job Completed	27/09/2017	29/09/2017	Act. MAN-AS/5403593

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:			Feature Type: Street Section		Area: Mansfield	
2664049	Parking General - Parking issues - A caravan is parked on the pavement outside 22 Elm Tree Avenue, it has been there for a considerable amount of time, many months, it has no registration plate. . Online report (Enquiry 6067808)	See map coordinates and description details	Personal Information	Category 2	Job Cancelled	04/12/2017	11/12/2017	Est.
2664725	existing cast iron bollard in depot requires metal sleeve welding in place, then relay back on site. stats required (Bollard Repairs)	junction station street: STATS 453918 - 363359	Personal Information	Category 3	Job Completed	14/12/2017	03/08/2018	Act. MAN/3504144
2665020	18 number infill areas (CW Repairs-Bituminous)	outside 67 (1),outside 69 (10),outside 75 (3),outside 79 (4)		Category 3	Job Completed	19/12/2017	22/12/2017	Act. MAN-AS/5404057
2673216	CW Repairs-Bituminous	road hump vale road chippy		Category 2	Job Completed	07/03/2018	12/03/2018	Act. MAN-AS/5404543
2673222	seal patch 23 fretting areas/potholes (CW Repairs-Bituminous)	65(3) 63(1) 69(5) 73(5) 77(2) 79(2) lamp 20 round manhole (1) 87(3) 93(1)		Category 2	Job Completed	07/03/2018	20/03/2018	Act. MAN/3504569
2678386	sop and go (CW Repairs-Bituminous)	lamp 23		Category 3	Job Completed	18/04/2018	08/06/2018	Act. MAN/3504777
2678387	CW Repairs-Bituminous	lamp 2(2)178(1) junction brown ave (1)		Category 2	Job Completed	18/04/2018	23/04/2018	Act. MAN-AS/5404810
2678388	FW Repairs-Bituminous	opp lamp 9(1) 81(1)		Category 2	Job Completed	18/04/2018	23/04/2018	Act. MAN-AS/5404811
2692646	build up no stats, replace existing with plastic bollards (Bollard Repairs)	opp 75		Category 2	Job Completed	20/09/2018	27/09/2018	Act. MAN/3505534
2703468	inspectors reset bollard (Bollard Repairs)	low side lamp 3		Filled when found (Cat 1)	Job Completed	31/01/2019	31/01/2019	Act.
2708063	CW Repairs-Bituminous	jct station street		Category 2	Job Completed	18/03/2019	20/03/2019	Act. MAN-AS/5407048
2708064	CW Repairs-Bituminous	77		Category 3	Job Completed	18/03/2019	13/05/2019	Act. MAN/3506513
2708065	CW Repairs-Bituminous	lamp 16(1) opp 65(6) 71(6) 73(3) 75(2) 77(2)		Category 2	Job Completed	18/03/2019	20/03/2019	Act. MAN-AS/5407049
2708066	CW Repairs-Bituminous	81(1) 103(2) 105(1) jct brown ave (4)		Category 2	Job Completed	18/03/2019	20/03/2019	Act. MAN-AS/5407050
2708067	M90 to chip top of kerb (Other)	opp 90		Category 2	Job Completed	18/03/2019	20/03/2019	Act. MAN-AS/5407051
2709910	CW Repairs-Bituminous	156(1) 67(3) jct manor road (4)		Category 2	Job Completed	08/04/2019	09/04/2019	Act. MAN-AS/5407199
2713828	CW Repairs-Bituminous	junction Brown Ave		Category 2	Job Cancelled	15/05/2019	12/06/2019	Est. MAN/3506789
2714509	CW Repairs-Bituminous	jct Brown Ave		Category 2	Job Completed	22/05/2019	24/05/2019	Act. MAN-AS/5407543
2717254	CW Repairs-Bituminous	71(4) 73(1) 128(3)		Category 2	Job Completed	19/06/2019	25/06/2019	Act. MAN-AS/5407739
2724666	FW Repairs-Bituminous	130(2) vale paint (2) lamp 4(1) opp 64(1)		Category 2	Repair Completed	25/09/2019	26/09/2019	Act.
2724667	CW Repairs-Bituminous	122(2) 152(1)		Category 2	Repair Completed	25/09/2019	26/09/2019	Act.
2724668	FW Repairs-Bituminous	73		Category 3	Job Completed	25/09/2019	24/10/2019	Act. MAN/3507421
2724669	Kerbing/Edging	154		Category 3	Job Completed	25/09/2019	30/10/2019	Act. MAN/3507420

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:			Feature Type: Street Section		Area: Mansfield	
2724670	plastic bollard knocked out of ground made safe with cone by inspector. (Other)	opp 68	Personal Information	Made Safe (Cat 1)	Job Completed	25/09/2019	25/09/2019	Act.
2724671	pick up bollard out of vale road depot reset in position with in traffic calming kerbs (Bollard Repairs)	opp 68		Category 2	Repair Completed	25/09/2019	26/09/2019	Act.
2727076	stop & go (CW Repairs-Bituminous)	opp lamp 3 fronting speed hump.		Category 3	Job Completed	28/10/2019	04/11/2019	Act. MAN/3507603
2730179	9 number infill areas (CW Repairs-Bituminous)	between 69 - 73		Category 2	Repair Completed	03/12/2019	05/12/2019	Act.
2730795	CW Repairs-Bituminous	lamp 2		Category 2	Repair Completed	09/12/2019	13/12/2019	Act.
2733269	CW Repairs-Bituminous	122		Category 2	Repair Completed	07/01/2020	15/01/2020	Act.
2736317	CW Repairs-Bituminous	jct brown avenue (6) 180(1) 174(1)		Category 2	Repair Completed	04/02/2020	05/02/2020	Act.
2740666	CW Repairs-Bituminous	opp lamp 9(1) rd hump lamp 2(1)		Category 2	Job Sent to Operatives Device	18/03/2020	14/04/2020	Est.
Feat No.:	4,000.00	Feature Id - Locn.: 1 - S/O Dentist opp chippie			Feature Type: Column		Area: Mansfield	
3620454	Please fit a new purple V max LED onto existing column, fit a DPI if required, test, and renumber as original		Personal Information	MANS) SL - 7 Days	Job Completed	09/05/2017	16/05/2017	Act. SLMA/11002872
Feat No.:	4,001.00	Feature Id - Locn.: 2 - O/S Vale Court			Feature Type: Column		Area: Mansfield	
3627231	Lamp out as told by resident when repairing l/c 5 ticket 3626239 (SL- Street Light out)			MANS) SL - 7 Days	Job Completed	25/10/2017	25/10/2017	Act. SLMA/11004053
Feat No.:	4,002.00	Feature Id - Locn.: 3 - O/S Vale Ct junct			Feature Type: Column		Area: Mansfield	
3635928	Street Light Fault - Light out - Light not working . Online report (Enquiry 6094861) (SL- Street Light out)	LC3		MANS) SL - 7 Days	Job Completed	14/05/2018	18/05/2018	Act. SLMA/11005605
Feat No.:	4,004.00	Feature Id - Locn.: 5 - O/S 22/24 Opp			Feature Type: Column		Area: Mansfield	
3626239	Street Light Fault - Light out - Customer is reporting that street light 5 on vale road in mansfield woodhouse is not working. Please can this be looked into. . Submitted by Advisor: (Enquiry 6066635) (SL- Street Light out)			MANS) SL - 7 Days	Job Completed	09/10/2017	24/10/2017	Act. SLMA/11003851

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	4,004.00	Feature Id - Locn.: 5 - O/S 22/24	Opp 17		Feature Type: Column		Area: Mansfield	
3629657	Street Light Fault - Light out - Streetlight 5 selected Outside 22/24 Opposite 17 Vale Road is not working. . Submitted by Advisor: Personal Information (Enquiry 6072849) (SL- Street Light out)		Personal Information (SL MANS)	SL - 7 Days	Job Completed	11/12/2017	17/12/2017	Act. SLMA/11004505
3631762	Street Light Fault - Light out - Number 5 streetlight on Vale Road is out, it has been out for a couple of months now and is showing no signs of coming back on. Can someone have a look at this please to see what the issue is? . Submitted by Advisor: Personal Information (Enquiry 6078537) (SL- Street Light out)		Personal Information (SL MANS)	SL - 7 Days	Job Completed	26/01/2018	07/02/2018	Act. SLMA/11004875
3635386	Street Light Fault - Light out - Streetlight out. . Submitted by Advisor: Personal Information (Enquiry 6093365) (SL- Street Light out)	Streetlight 5 outside 22/24 Vale Road	Personal Information (SL MANS)	SL - 7 Days	Job Completed	30/04/2018	03/05/2018	Act. SLMA/11005536
Feat No.:	4,005.00	Feature Id - Locn.: 6 - O/S 27/29	Opp 34		Feature Type: Column		Area: Mansfield	
3629655	Street Light Fault - Lit during the day - Streetlight 6 selected Outside 27/29 Opposite 3 Vale Road is on all the time. . Submitted by Advisor: Personal Information (Enquiry 6072853) (SL- Street Light out)		Personal Information (SL MANS)	SL - 7 Days	Job Completed	11/12/2017	17/12/2017	Act. SLMA/11004504

Effective: 02/04/2017 to 02/04/2020

Display Action Officer: Yes

Street: Vale Road (24610395)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 4,005.00	Feature Id - Locn.: 6 - O/S 27/29	Opp 34			Feature Type: Column		Area: Mansfield	
3631578	Street Light Fault - Other streetlight fault - Good morning, Column 6 is strobing. Can this be looked into please. Many thanks		Personal Information (SL MANS)	SL - 7 Days	Job Completed	23/01/2018	07/02/2018	Act. SLMA/11004837
	Personal Information MIET, MInstLM Supervisor (Electrical) Housing Repairs Services Mansfield District Council Vale Road Mansfield Woodhouse Mansfield Nottinghamshire NG198EB Tel:- Personal Information Email:- Personal Information Web:- www.mansfield.gov.uk . Online report (Enquiry 6077687) (SL- Street Light out)							
3635385	Street Light Fault - Lit during the day - Light is on all the time. . Submitted by Advisor: Personal Information (Enquiry 6093366) (SL- Street Light out)	Streetlight 6 selected. (Outside 27/29 Opposite 34)	Personal Information (SL MANS)	SL - 3 Months	Job Completed	30/04/2018	01/05/2018	Act. SLMA/11005535
Feat No.: 4,008.00	Feature Id - Locn.: 9 - O/S 50-62	Opp Mdc Depot			Feature Type: Column		Area: Mansfield	
3622595	Lamp cycling on and off (SL- (Night Patrol) Column Out)		Personal Information (SL MANS)	SL - 7 Days	Job Completed	17/07/2017	19/07/2017	Act. SLMA/11003253
Feat No.: 4,011.00	Feature Id - Locn.: 12 - O/S 98/100	Opp 51			Feature Type: Column		Area: Mansfield	
3636388	Please install a new 8 mtr column in original position, fit a Purple V Max LED, fit a DPI, test, re number as original and re instate footpath.		Personal Information (MANS)	SL - 30 Days	Job Completed	29/05/2018	01/06/2018	Act. SLMA/11005671
Feat No.: 4,021.00	Feature Id - Locn.: 22 - O/S 156	Opp 87/89			Feature Type: Column		Area: Mansfield	
3622594	Lamp out (SL- (Night Patrol) Column Out)		Personal Information (SL MANS)	SL - 7 Days	Job Completed	17/07/2017	19/07/2017	Act. SLMA/11003252
Feat No.: 4,021.10	Feature Id - Locn.: 22 - O/S 156	Opp 87/89			Feature Type: Column		Area: Mansfield	
3658184	lit during the day (SL- Day burning)		Personal Information	SL - 3 Months	Job Completed	29/11/2019	02/12/2019	Act. SLMA/11008835

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 4,027.00	Feature Id - Locn.: 28 - O/S 182	Opp Mayhall Ave	Feature Type: Column				Area: Mansfield	
3622592	Lamp out (SL- (Night Patrol) Column Out)		Personal Information (SL MANS)	SL - 7 Days	Job Completed	17/07/2017	19/07/2017	Act. SLMA/11003251
Feat No.: 4,028.00	Feature Id - Locn.: 29 - O/S 109	Opp Brown Ave	Feature Type: Column				Area: Mansfield	
3625706	Street Light Fault - Other streetlight fault - The streetlight outside 109 Vale Rd near the junction with Brown Ave Mansfield Woodhouse is faulty.It will come on for about 20 mins then turn itself off for about 30 mins then come back on again for another 20mins and it does this all through the night.It started doing this in January 2017. . Submitted by Advisor: Personal Info (Enquiry 6065309) (SL- Street Light out)		Personal Information (SL MANS)	SL - 7 Days	Job Completed	26/09/2017	29/09/2017	Act. SLMA/11003753

Street Works Inspections

Organisation: BT (0030006)								
Works Ref: T1001MW500263790700								
Group No: 1	Site No: 1	Street Authority: Nottinghamshire			Inspected: 12/06/2018 10:49:16		Sampled Site No: 1	
Category: Category A		Outcome: Abortive			Sampled: Yes		Sign./Light./Guard. Inadequacy: No	
Defect Notif. No: N/A		Defect No: N/A			Site Informed: Yes			
Officer: Personal Information (NRSWA)		Personal Information			Site Location: ADJ 6 , VALE ROAD			
Insp. Notes:					Position: Footway		Site Post Code:	
Defect Notes:								
Works Ref: T1003MW500281916500								
Group No: 1	Site No: 1	Street Authority: Nottinghamshire			Inspected: 12/12/2019 14:50:54		Sampled Site No: 1	
Category: Category B		Outcome: Passed			Sampled: Yes		Sign./Light./Guard. Inadequacy: No	
Defect Notif. No: N/A		Defect No: N/A			Site Informed: Yes			
Officer: Personal Information		Tel: Personal Information			Site Location: ADJ 62 , VALE ROAD			
Insp. Notes:					Position: Footway		Site Post Code:	
Defect Notes:								

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Street Works Inspections

Organisation: Cadent Gas EM (0010001) (Street Works Admin Team NG Gas)

Works Ref: 1000541370

Group No: 1	Site No: 1	Street Authority: NCC - MANSFIELD	Inspected: 12/09/2018 15:01:04
Category: Category C		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: Personal Information (Inspector)		Tel: Personal Information	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: S/O 14-16 STATION STREET
Defect Notes:			Position: Footway
			Sampled Site No: 1
			Site Post Code:

Organisation: Severn Trent Waste (9103902)

Works Ref: 2103/000012185454

Group No: 1	Site No: 1	Street Authority: NCC - MANSFIELD	Inspected: 19/06/2019 14:48:16
Category: Category A		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: No
Officer: Personal Information (Inspector)		Tel: Personal Information	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: FW OS 62 VALE ROAD
Defect Notes:			Position: Footway
			Sampled Site No: 1
			Site Post Code:

Organisation: Severn Trent Water East (9103908)

Works Ref: 1101/000011872281

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 26/04/2018 12:27:58
Category: Category A		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: Personal Information (NRSWA)		Tel: Personal Information	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: 91
Defect Notes:			Position: Carriageway
			Sampled Site No: 1
			Site Post Code:

Works Ref: 1101/000060173509

Group No: 1	Site No: 1	Street Authority: NCC - MANSFIELD	Inspected: 03/11/2017 15:18:05
Category: Category C		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: Personal Information (Inspector)		Tel: Personal Information	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: council depot vale rd
Defect Notes:			Position: Footway
			Sampled Site No: 1
			Site Post Code:

Works Ref: 1101/000060173600

Group No: 1	Site No: 1	Street Authority: NCC - MANSFIELD	Inspected: 03/11/2017 15:17:32
Category: Category C		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: Personal Information (Inspector)		Tel: Personal Information	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: 51, VALE ROAD, NG19 8EB
Defect Notes:			Position: Footway
			Sampled Site No: 1
			Site Post Code:

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Street Works Inspections

Organisation: WPD 5134 Mansfield (7011534)

Works Ref: M51340456655

Group No: 1 Site No: 1 Street Authority: Nottinghamshire
Category: Category A Outcome: Passed
Defect Notif. No: N/A Defect No: N/A
Officer: Personal Information (NRSWA) Tel: Personal Information
Insp. Notes:
Defect Notes:

Inspected: 04/12/2019 12:15:03
Sampled: Yes Sampled Site No: 1
Site Informed: Yes Sign./Light./Guard. Inadequacy: No
Site Location: Outside 23
Position: Footway Site Post Code:

Street Works Notices

Organisation: BT (0030005)

Works Ref: OP1W00000IBTPR4AP01 Version: 4 Work Desc: excavation to install 8 meters of new telecoms duct in the footway
Notice Type: Registration of Reinstatement - Full Start: 09/04/2018 00:00:00
Work Status: Works Stopped Issued: 11/04/2018 14:35:59
Work Type: EToN 4: Minor Est. End: 11/04/2018 Completion: 10/04/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	O/S 6 VALE ROAD NG19 8AF NG19 8AF	Footway	Up to 1.5 Metres of Cover	8.00	0.40 A Permanent Reinstatement	10/04/2018		10/04/2018	11/04/2018

Organisation: BT (0030006)

Works Ref: CT003MW500248226300 Version: 4 Work Desc: Recover 1 existing pole
Notice Type: Registration of Reinstatement - Full Start: 04/10/2017 00:00:00
Work Status: Works Stopped Issued: 05/10/2017 10:08:25
Work Type: EToN 4: Minor Est. End: 06/10/2017 Completion: 04/10/2017

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	EMXFQ214, OPP NO 6., VALE ROAD	Verge	Up to 1.5 Metres of Cover	0.50	0.50 A Permanent Reinstatement	04/10/2017		04/10/2017	06/10/2017

Works Ref: TI001MW500263790700 Version: 4 Work Desc: Install 8m of 1 way poly duct in Footway,Provide 1 core drill(s) into jointbox or building
Notice Type: Registration of Reinstatement - Full Start: 08/06/2018 00:00:00
Work Status: Works Stopped Issued: 22/06/2018 10:05:38
Work Type: EToN 4: Minor Est. End: 12/06/2018 Completion: 12/06/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	ADJ 6 , VALE ROAD	Footway	Up to 1.5 Metres of Cover	8.00	0.30 A Permanent Reinstatement	12/06/2018		12/06/2018	12/06/2018

Works Ref: TI003MW500281916500 Version: 4 Work Desc: Recover 1 existing pole
Notice Type: Registration of Reinstatement - Full Start: 16/06/2019 00:00:00
Work Status: Works Stopped Issued: 17/06/2019 09:01:44
Work Type: EToN 4: Minor Est. End: 19/06/2019 Completion: 16/06/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	ADJ 62 , VALE ROAD	Footway	Up to 1.5 Metres of Cover	0.50	0.50 A Permanent Reinstatement	16/06/2019		16/06/2019	19/06/2019

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Street Works Notices

Organisation: Cadent Gas EM (0010001) (Street Works Admin Team NG Gas)

Works Ref: 1000871997

Version: 2

Work Desc: LAY A NEW GAS SERVICE 6 METERS FROM THE MAIN LOCATED IN THE NEARSIDEFOOTPATH

Notice Type: Cancellation

Start: 10/10/2019 00:00:00

Work Status: Abandoned Works

Issued: 11/10/2019 08:42:07

Work Type: EToN 4: Standard

Est. End: 16/10/2019

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	MAIN LOCATED IN THE NEARSIDE FOOTPATH OUTSIDE NUMBER 172 VALE ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	10/10/2019			16/10/2019

Organisation: NCC - MANSFIELD (3055003) (VIA Bilsthorpe)

Works Ref: 30502436

Version: 3

Work Desc: installation of a new bus shelter

Notice Type: Works Stop

Start: 04/03/2019 00:00:00

Work Status: Works Stopped

Issued: 06/03/2019 11:41:24

Work Type: EToN 4: Minor

Est. End: 05/03/2019

Completion: 05/03/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Near house no. 107	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	05/03/2019			05/03/2019

Works Ref: SM687

Version: 1

Work Desc: Relocation of bus stop pole

Notice Type: 3 Day Initial Notice

Start: 20/09/2019 00:00:00

Work Status: Proposed Works

Issued: 04/09/2019 10:34:11

Work Type: EToN 4: Minor

Est. End: 20/09/2019

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Adj Mayhall Avenue	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	20/09/2019			20/09/2019

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: /HW30538

Version: 2

Work Desc: Micro asphalt

Notice Type: 3 Month Initial Notice

Start: 07/03/2020 00:00:00

Work Status: Proposed Works

Issued: 17/02/2020 08:36:51

Work Type: EToN 4: Major

Est. End: 07/03/2020

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	from o/s No122 to jct with Mayhill Avenue	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	07/03/2020			07/03/2020

Works Ref: /VALE040719

Version: 1

Work Desc: Coring

Notice Type: 10 Day Initial Notice

Start: 15/07/2019 00:00:00

Work Status: Proposed Works

Issued: 04/07/2019 08:25:51

Work Type: EToN 4: Standard

Est. End: 19/07/2019

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Entire Length	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	15/07/2019			19/07/2019

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Street Works Notices

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: /VALE270219

Version: 1

Work Desc: Parking Enforcement Refresh Work at night

Notice Type: 10 Day Initial Notice

Start: 04/03/2019 00:00:00

Work Status: Proposed Works

Issued: 27/02/2019 11:36:47

Work Type: EToN 4: Standard

Est. End: 09/03/2019

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Entire Length	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	04/03/2019			09/03/2019

Works Ref: 154VALEROADCLW

Version: 1

Work Desc: Kerbing/edging

Notice Type: 3 Day Initial Notice

Start: 24/10/2019 00:00:00

Work Status: Proposed Works

Issued: 23/10/2019 09:44:36

Work Type: EToN 4: Minor

Est. End: 25/10/2019

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	154 Vale Road, Mansfield Woodhouse	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	24/10/2019		25/10/2019	25/10/2019

Works Ref: 40809011

Version: 1

Work Desc: Resurfacing Works

Notice Type: 3 Month Initial Notice

Start: 06/02/2018 00:00:00

Work Status: Proposed Works

Issued: 29/01/2018 11:16:39

Work Type: EToN 4: Major

Est. End: 10/02/2018

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Vale Road and Castle Street Mansfield Woodhouse	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	06/02/2018			10/02/2018

Works Ref: 40809076

Version: 1

Work Desc: Resurface Works

Notice Type: 3 Day Initial Notice

Start: 07/02/2018 00:00:00

Work Status: Proposed Works

Issued: 31/01/2018 09:29:34

Work Type: EToN 4: Minor

Est. End: 10/02/2018

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Vale Road, Mansfield Woodhouse from its junction of Greenwood Avenue to its junction with the High Street.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	07/02/2018			10/02/2018

Works Ref: 40813076

Version: 1

Work Desc: INstalling Light Columns

Notice Type: 3 Month Initial Notice

Start: 05/11/2018 00:00:00

Work Status: Proposed Works

Issued: 25/10/2018 10:27:12

Work Type: EToN 4: Major

Est. End: 21/12/2018

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Various locations along Vale Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	05/11/2018			21/12/2018

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Street Works Notices

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: VALEROADTA

Version: 3

Work Desc: FW repairs

Notice Type: Works Stop

Start: 24/10/2019 00:00:00

Work Status: Works Stopped

Issued: 25/10/2019 08:39:40

Work Type: EToN 4: Minor

Est. End: 25/10/2019

Completion: 24/10/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	73 Vale Road Mansfield	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	24/10/2019			25/10/2019

Organisation: Severn Trent Waste (9103902)

Works Ref: 0000/000011606446

Version: 3

Work Desc: DIG ONTO COLLAPSED SEWER PIPE TO CARRY OUT REPAIR

Notice Type: Works Stop

Start: 04/05/2017 00:00:00

Work Status: Works Stopped

Issued: 08/05/2017 10:30:52

Work Type: EToN 4: Standard

Est. End: 17/05/2017

Completion: 05/05/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	S/O 14 STATION STREET VALE ROAD MANSFIELD WOODHOUSE NOTTINGHAMSHIRE	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	05/05/2017			17/05/2017

Works Ref: 0000/000011680928

Version: 2

Work Desc: DIG TO REPAIR FOUL SEWER IN FOOTPATH

Notice Type: Cancellation

Start: 04/09/2017 00:00:00

Work Status: Abandoned Works

Issued: 17/08/2017 12:11:43

Work Type: EToN 4: Standard

Est. End: 15/09/2017

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	O/S 20 VALE ROAD MANSFIELD WOODHOUSE NOTTINGHAMSHIRE	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	04/09/2017			15/09/2017

Works Ref: 2103/000012076371

Version: 5

Work Desc: Rep/reset MH 6701 In H'way to 675mmsq WORKS NEEDED TO REPAIR FRAME AND COVER. Job in Carriageway (10mm StoneMastic Asphalt)

Notice Type: Registration of Reinstatement - Full

Start: 11/02/2019 00:00:00

Work Status: Works Stopped

Issued: 11/02/2019 15:43:00

Work Type: EToN 4: Minor

Est. End: 11/02/2019

Completion: 11/02/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	C/W O/S 144 VALE ROAD	Carriageway	Up to 1.5 Metres of Cover	1.20	1.60	A Permanent Reinstatement	11/02/2019		11/02/2019	11/02/2019

Works Ref: 2103/000012185454

Version: 3

Work Desc: StdSewRep225mm3.0m PROG 18/06 EN Excavation required on suspected collapsed sewer Job in Footway (6mm Bitmac (Tarmac))

Notice Type: Registration of Reinstatement - Full

Start: 17/06/2019 14:15:00

Work Status: Works Stopped

Issued: 24/06/2019 14:15:06

Work Type: EToN 4: Immediate - Emergency

Est. End: 28/06/2019

Completion: 24/06/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FW OS 62 VALE ROAD	Footway	Up to 1.5 Metres of Cover	1.40	1.00	A Permanent Reinstatement	24/06/2019		24/06/2019	28/06/2019

Effective: 02/04/2017 to 02/04/2020
Street: Vale Road (24610395)

Display Action Officer: Yes

Street Works Notices

Organisation: Severn Trent Waste (9103902)

Works Ref: 2103/000012196233

Notice Type: Registration of Reinstatement - Full

Work Status: Works Stopped

Work Type: EToN 4: Standard

Version: 4

Start: 08/07/2019 00:00:00

Issued: 15/07/2019 11:05:20

Est. End: 12/07/2019

Work Desc: TransStdSewRep225mm3.0 PRINTS REQ Excavation required to repair defect within the foul pipeline Job in Footway (6mm Bitmac (Tarmac))

Completion: 12/07/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	FW OS 62 VALE ROAD	Footway	Up to 1.5 Metres of Cover	1.40	1.00 A Permanent Reinstatement	12/07/2019		12/07/2019	12/07/2019

Works Ref: 2103/000012230116

Notice Type: Works Stop

Work Status: Works Stopped

Work Type: EToN 4: Minor

Version: 3

Start: 29/08/2019 00:00:00

Issued: 30/08/2019 08:51:47

Est. End: 29/09/2019

Work Desc: MH cover In H'way - PROGRAMMED WORKS NEEDED TO REPAIR DAMAGED FRAME AND COVER. Job in Carriageway (10mm Bitmac (Tarmac))

Completion: 29/08/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	WORKS ON VALE ROAD NEXT TO ENTRANCE OF PARK ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	29/08/2019			29/09/2019

Organisation: Severn Trent Water East (9103908)

Works Ref: 1101/000011871915

Notice Type: Works Stop

Work Status: Works Stopped

Work Type: EToN 4: Immediate - Urgent

Version: 4

Start: 24/04/2018 14:20:00

Issued: 01/05/2018 11:10:36

Est. End: 26/04/2018

Work Desc: Long Comm Pipe Repair 25mm Job in Carriageway (14mm StoneMastic Asphalt)

Completion: 24/04/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	91	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	24/04/2018		24/04/2018	26/04/2018

Works Ref: 1101/000011871915A

Notice Type: Works Stop

Work Status: Works Stopped

Work Type: EToN 4: Minor

Version: 3

Start: 20/05/2018 00:00:00

Issued: 22/05/2018 11:02:06

Est. End: 23/05/2018

Work Desc: Long Comm Pipe Repair 25mm 1/2 Job in Carriageway (Stone Mastic Asphalt)

Completion: 20/05/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	91	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	20/05/2018			23/05/2018

Works Ref: 1101/000011872281

Notice Type: Cancellation

Work Status: Abandoned Works

Work Type: EToN 4: Immediate - Urgent

Version: 2

Start: 25/04/2018 10:12:00

Issued: 26/04/2018 11:55:07

Est. End: 27/04/2018

Work Desc: Stop tap Renew 25mm Job in Carriageway (14mm StoneMastic Asphalt)

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	91	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	25/04/2018 10:12:00			27/04/2018