

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Street: Melton Road (33019457)

Locality: Stanton on the Wolds, Nottinghamshire

Area: Rushcliffe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:		Feature Type: Street Section			Area: Rushcliffe	
Batch: 20224223	- Inspection Batch No actionable defects found			Route: Rush Area 1 Apr Enh CW/FW	Officer: John Buxton (Inspector)		Date: 06/04/2017	
Batch: 20223282	- Inspection Batch No actionable defects found			Route: Rush Area 1 Mar Saf CW	Officer: John Buxton (Inspector)		Date: 03/04/2017	
Batch: 20217795	- Inspection Batch No actionable defects found			Route: Rush Area 1 Feb Saf CW	Officer: John Buxton (Inspector)		Date: 22/02/2017	
Batch: 20213572	- Inspection Batch No actionable defects found			Route: Rush Area 1 Jan Saf CW	Officer: John Buxton (Inspector)		Date: 24/01/2017	
Batch: 20207989	- Inspection Batch No actionable defects found			Route: Rush Area 1 Dec Saf CW	Officer: John Buxton (Inspector)		Date: 07/12/2016	
Batch: 20206134	- Inspection Batch No actionable defects found			Route: Rush Area 1 Nov Saf CW	Officer: John Buxton (Inspector)		Date: 24/11/2016	
Batch: 20200746	- Inspection Batch No actionable defects found			Route: Rush Area 1 Oct Saf CW	Officer: John Buxton (Inspector)		Date: 14/10/2016	
Batch: 20198353	- Inspection Batch No actionable defects found			Route: Rush Area 1 Sep Saf CW	Officer: John Buxton (Inspector)		Date: 28/09/2016	
Batch: 20198248	- Inspection Batch			Route: Adhoc Inspection	Officer: John Buxton (Inspector)		Date: 27/09/2016	
3535272	Fw pothole complaint by resident.	27/09/2016	Access to 200 Melton Road, Nottingham, United Kingdom, NG12 5BP	FW Repairs-Bituminous	Internal		Committed	2636659
Batch: 20192202	- Inspection Batch No actionable defects found			Route: Rush Area 1 Aug Saf CW	Officer: John Buxton (Inspector)		Date: 05/08/2016	
Batch: 20189455	- Inspection Batch No actionable defects found			Route: Rush Area 1 Jul Saf CW	Officer: John Buxton (Inspector)		Date: 19/07/2016	
Batch: 20187796	- Inspection Batch No actionable defects found			Route: Rush Area 1 Jun Saf CW	Officer: John Buxton (Inspector)		Date: 05/07/2016	
Batch: 20182231	- Inspection Batch No actionable defects found			Route: Rush Area 1 May Saf CW	Officer: John Buxton (Inspector)		Date: 27/05/2016	
Batch: 20181294	- Inspection Batch			Route: Adhoc Inspection	Officer: John Buxton (Inspector)		Date: 23/05/2016	
3529592	Customer complaint regarding Cw surface.	23/05/2016	Heading in to Stanton from Tollerton direction. Just before the 40mph signs. Poor section of Cw all in the same lane , all potholes within an area marked in White	CW Repairs-Bituminous	Internal		Committed	2630581
Batch: 20173643	- Inspection Batch No actionable defects found			Route: Rush Area 1 Apr Enh CW/FW	Officer: John Buxton (Inspector)		Date: 01/04/2016	
Batch: 20170226	- Inspection Batch No actionable defects found			Route: Rush Area 1 Mar Saf CW	Officer: John Buxton (Inspector)		Date: 05/03/2016	

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.:			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20168590 - Inspection Batch	No actionable defects found			Route: Rush Area 1 Feb Saf CW		Officer: John Buxton (Inspector)		Date: 25/02/2016
Batch: 20162490 - Inspection Batch	No actionable defects found			Route: Rush Area 1 Jan Saf CW		Officer: John Buxton (Inspector)		Date: 20/01/2016
Batch: 20160964 - Inspection Batch				Route: Adhoc Inspection		Officer: John Buxton (Inspector)		Date: 09/01/2016
3520963	Cw deterioration	09/01/2016	Various locations just before the 40 MPH sign heading in to Stanton from Plumtree direction Melton Road A606	HW CW Pothole Z1	Internal		Uncommitt	2621802
Batch: 20158656 - Inspection Batch	No actionable defects found			Route: Rush Area 1 Dec Saf CW		Officer: John Buxton (Inspector)		Date: 16/12/2015
Batch: 20154260 - Inspection Batch	No actionable defects found			Route: Rush Area 1 Nov Saf CW		Officer: John Buxton (Inspector)		Date: 17/11/2015
Batch: 20149968 - Ad Hoc Inspection Batch				Route: Adhoc Inspection		Officer: Pete Moncaster (Rushcliffe)		Date: 20/10/2015
3517127	Please jet through culvert under the A606, there could be a possible blockage, farmer has excavated out his road side ditches, but water is not free flowing through culvert. Will require t/m.	20/10/2015	On A606, between Browns Lane jnc and layby on l/h/s.	HW DR Standing water Z3	Internal		Committed	2617831
Batch: 20149850 - Inspection Batch	No actionable defects found			Route: Rush Area 1 Oct Saf CW		Officer: John Buxton (Inspector)		Date: 19/10/2015
Batch: 20146498 - Inspection Batch	No actionable defects found			Route: Rush Area 1 Sep Saf CW		Officer: John Buxton (Inspector)		Date: 28/09/2015
Batch: 20142177 - Inspection Batch	No actionable defects found			Route: Rush Area 1 Aug Saf CW		Officer: John Buxton (Inspector)		Date: 24/08/2015
Batch: 20137267 - Inspection Batch	No actionable defects found			Route: Rush Area 1 Jul Saf CW		Officer: John Buxton (Inspector)		Date: 18/07/2015
Batch: 20133674 - Inspection Batch	No actionable defects found			Route: Rush Area 1 Jun Saf CW		Officer: John Buxton (Inspector)		Date: 23/06/2015
Batch: 20129703 - Inspection Batch	No actionable defects found			Route: Rush Area 1 May Saf CW		Officer: John Buxton (Inspector)		Date: 28/05/2015
Feat No.: 2,020.00	Feature Id - Locn.:			Feature Type: Layby - Integrated			Area: Rushcliffe	
Batch: 20224220 - Inspection Batch	No actionable defects found			Route: Rush Area 1 Apr Enh CW/FW		Officer: John Buxton (Inspector)		Date: 06/04/2017
Batch: 20223283 - Inspection Batch	No actionable defects found			Route: Rush Area 1 Mar Saf CW		Officer: John Buxton (Inspector)		Date: 03/04/2017
Batch: 20217796 - Inspection Batch	No actionable defects found			Route: Rush Area 1 Feb Saf CW		Officer: John Buxton (Inspector)		Date: 22/02/2017

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,020.00	Feature Id - Locn.:			Feature Type: Layby - Integrated			Area: Rushcliffe	
Batch: 20213571 - Inspection Batch	No actionable defects found			Route: Rush Area 1 Jan Saf CW	Officer: John Buxton (Inspector)			Date: 24/01/2017
Batch: 20210069 - Inspection Batch	No actionable defects found			Route: Rush Area 1 Dec Saf CW	Officer: John Buxton (Inspector)			Date: 21/12/2016
Feat No.: 8,000.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,001.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,002.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,003.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,004.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,005.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,006.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,007.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016

Effective: 19/04/2015 to 19/04/2017
Street: Melton Road (33019457)

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,008.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,009.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,010.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,011.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,012.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,013.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,014.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,015.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016

Effective: 19/04/2015 to 19/04/2017
 Street: Melton Road (33019457)

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,016.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,017.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,018.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,019.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,020.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,021.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,022.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,023.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,024.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,025.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,026.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,027.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,028.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,029.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,030.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,031.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,032.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,033.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,034.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,034.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000218 - Ad Hoc Inspection				Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
No actionable defects found								
Feat No.: 8,035.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection				Route: Ad Hoc Inspection	Officer: Tarmac			Date: 26/07/2016
No actionable defects found								
Batch: 10000218 - Ad Hoc Inspection				Route: Ad Hoc Inspection	Officer: Tarmac			Date: 26/07/2016
No actionable defects found								
Feat No.: 8,036.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection				Route: Ad Hoc Inspection	Officer: Tarmac			Date: 26/07/2016
No actionable defects found								
Batch: 10000218 - Ad Hoc Inspection				Route: Ad Hoc Inspection	Officer: Tarmac			Date: 26/07/2016
No actionable defects found								
Feat No.: 8,037.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection				Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
No actionable defects found								
Batch: 10000219 - Ad Hoc Inspection				Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
No actionable defects found								
Batch: 10000218 - Ad Hoc Inspection				Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
No actionable defects found								
Feat No.: 8,038.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection				Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
No actionable defects found								
Batch: 10000218 - Ad Hoc Inspection				Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
No actionable defects found								
Feat No.: 8,039.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection				Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
No actionable defects found								
Batch: 10000218 - Ad Hoc Inspection				Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
No actionable defects found								
Feat No.: 8,041.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection				Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
No actionable defects found								
Batch: 10000218 - Ad Hoc Inspection				Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
No actionable defects found								

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	8,042.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Feat No.:	8,044.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Feat No.:	8,045.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Feat No.:	8,046.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Feat No.:	8,047.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Feat No.:	8,048.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Feat No.:	8,049.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							

Effective: 19/04/2015 to 19/04/2017
Street: Melton Road (33019457)

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,050.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,051.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,052.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,053.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,054.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,055.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,056.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016

Effective: 19/04/2015 to 19/04/2017
Street: Melton Road (33019457)

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,057.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,058.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,059.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,060.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,061.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,062.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,063.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	8,064.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Feat No.:	8,065.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Feat No.:	8,066.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 25/07/2016
	No actionable defects found							
Feat No.:	8,067.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Feat No.:	8,068.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Feat No.:	8,069.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Feat No.:	8,070.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							

Effective: 19/04/2015 to 19/04/2017
Street: Melton Road (33019457)

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,072.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 26/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 26/07/2016
Feat No.: 8,073.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 26/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 26/07/2016
Feat No.: 8,074.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 26/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 26/07/2016
Feat No.: 8,075.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 26/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 26/07/2016
Feat No.: 8,076.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 26/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 26/07/2016
Feat No.: 8,077.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,077.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 26/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 26/07/2016
Feat No.: 8,078.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,079.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,080.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,081.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,082.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016

Effective: 19/04/2015 to 19/04/2017
Street: Melton Road (33019457)

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,082.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,083.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,084.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,085.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,086.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,087.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,088.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017

Effective: 19/04/2015 to 19/04/2017
Street: Melton Road (33019457)

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,088.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,089.00	Feature Id - Locn.:			Feature Type: Gully			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 18/04/2017
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,090.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,091.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,092.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,093.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Feat No.: 8,094.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	8,095.00	Feature Id - Locn.:		Feature Type:	Offlet		Area:	Rushcliffe
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 25/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 25/07/2016
	No actionable defects found							
Feat No.:	8,096.00	Feature Id - Locn.:		Feature Type:	Offlet		Area:	Rushcliffe
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 25/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 25/07/2016
	No actionable defects found							
Feat No.:	8,097.00	Feature Id - Locn.:		Feature Type:	Offlet		Area:	Rushcliffe
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 25/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 25/07/2016
	No actionable defects found							
Feat No.:	8,098.00	Feature Id - Locn.:		Feature Type:	Gully		Area:	Rushcliffe
Batch:	10000297 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 18/04/2017
	No actionable defects found							
Batch:	10000217 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 21/07/2016
	No actionable defects found							
Feat No.:	8,099.00	Feature Id - Locn.:		Feature Type:	Gully		Area:	Rushcliffe
Batch:	10000297 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 18/04/2017
	No actionable defects found							
Batch:	10000217 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 21/07/2016
	No actionable defects found							
Feat No.:	8,101.00	Feature Id - Locn.:		Feature Type:	Offlet		Area:	Rushcliffe
Batch:	10000217 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 22/07/2016
	No actionable defects found							
Feat No.:	8,102.00	Feature Id - Locn.:		Feature Type:	Offlet		Area:	Rushcliffe
Batch:	10000217 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 22/07/2016
	No actionable defects found							
Feat No.:	8,103.00	Feature Id - Locn.:		Feature Type:	Offlet		Area:	Rushcliffe
Batch:	10000217 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 22/07/2016
	No actionable defects found							
Feat No.:	8,104.00	Feature Id - Locn.:		Feature Type:	Offlet		Area:	Rushcliffe
Batch:	10000217 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer:	Tarmac	Date: 22/07/2016
	No actionable defects found							

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,105.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,106.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,107.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,108.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,109.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,110.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,111.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,112.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,113.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,114.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 22/07/2016
Feat No.: 8,115.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection	Officer: Tarmac			Date: 25/07/2016

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,115.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 25/07/2016
Feat No.: 8,116.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 25/07/2016
Feat No.: 8,117.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 22/07/2016
Feat No.: 8,118.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 22/07/2016
Feat No.: 8,119.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000297 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 18/04/2017
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 22/07/2016
Feat No.: 8,120.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 22/07/2016
Feat No.: 8,121.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 22/07/2016
Feat No.: 8,122.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 22/07/2016
Feat No.: 8,123.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 22/07/2016
Feat No.: 8,124.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 26/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 26/07/2016

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	8,125.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Feat No.:	8,126.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Feat No.:	8,127.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Feat No.:	8,128.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Feat No.:	8,129.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Feat No.:	8,130.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Feat No.:	8,131.00	Feature Id - Locn.:		Feature Type:	Offlet		Area: Rushcliffe	
Batch:	10000219 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							
Batch:	10000218 - Ad Hoc Inspection			Route:	Ad Hoc Inspection	Officer: Tarmac		Date: 26/07/2016
	No actionable defects found							

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,132.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 25/07/2016
Feat No.: 8,133.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 22/07/2016
Feat No.: 8,134.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000217 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 22/07/2016
Feat No.: 8,135.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 25/07/2016
Feat No.: 8,136.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 25/07/2016
Feat No.: 8,137.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Rushcliffe	
Batch: 10000219 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 25/07/2016
Batch: 10000218 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection		Officer: Tarmac		Date: 25/07/2016

Customer Services

Enquiry No.: 6046716	Logged by: External to Confirm	on: 14/03/2017 09:38	Officer: South Highways Management
Service: Trees/Verges	Subject: Fallen Tree	Classification: Report or Observation	Enquiry Ref: FS-CASE-14048168
Desc.: Damaged/dangerous/fallen tree - Customer rang from PersonA Melton road as the public footpath that runs at the other side of PersonB boundary has fallen down and is making the footpath not passable, it is top of power line and is resting on another tree at the moment . . Submitted by Advisor: Rachel Jones			
Location: See map coordinates and description details	Contact:		
Enquiry No.: 6046631	Logged by: External to Confirm	on: 13/03/2017 14:59	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Spillage/Debris on Carriageway	Classification: Report or Observation	Enquiry Ref: FS-CASE-14019607
Desc.: Spillage/debris in road - There is a concrete bollard similar to a breeze block about 3 foot long in the road on the A606. It is near to the centre of the carriageway and have to swerve to get round it . Submitted by Advisor: Claire Shockledge			
Location: See map coordinates and description details	Contact:		

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Customer Services

Enquiry No.: 6038007	Logged by: External to Confirm	on: 03/01/2017 14:53	Officer: Laura Trusler
Service: Traffic Management	Subject: Traffic Calming	Classification: Report or Observation	Enquiry Ref: FS-CASE-11182980
Desc.: Traffic calming requests - I, along with many other residents on this street, often cross from one side of Melton Road to the other to use the public footpaths which straddle the road. Unfortunately, there have been MANY occasions when we have crossed the road, thinking there are no Cars coming, when suddenly one appears. Crossing from the public footpath/bridalway over to laming gap lane is particularly dangerous because the road bends creating a blind spot (see photo attached) for the pedestrian. Furthermore, cars are often travelling much faster than the designated speed limit of 50 mph and it is inevitable that there will be a serious accident between car and person in the near future. We often see people on horses trying to cross at this point and there have been some near misses. We strongly request you create a pedestrian crossing somewhere close to Laming Gap Lane to help residents cross safely and be able to use surrounding footpaths without fearing they will get knocked down by a speeding car. . Online report			
Location: The pin has been placed near 3 Melton Road, Nottingham, United Kingdom, NG12 5PH	Contact:		
Enquiry No.: 6028743	Logged by: External to Confirm	on: 27/09/2016 09:39	Officer: John Buxton (Inspector)
Service: Carriageway/Footway	Subject: Footway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-7330855
Desc.: Pavement Damage (e.g. damaged dropped kerb) - Caller reports the tarmac on the pavement/access onto the road has deteriorated to the point where cars exiting onto Melton Road, which is a fast road, are wheelspinning and so getting no traction. . 200, Melton Road, KEYWORTH, Stanton On The Wolds, NG12 5BP. Submitted by Advisor: dawn smith			
Location: The pin has been placed near 200 Melton Road, Nottingham, United Kingdom, NG12 5BP	Contact:		
Plot Number: 2,000.00	Feature Id - Location:	Feature Type: Street Section	
Job Number: 2636659	Defect Number: 3535272		
Enquiry No.: 6020294	Logged by: External to Confirm	on: 01/07/2016 13:51	Officer: Sharon Kirk
Service: Carriageway/Footway	Subject: Manholes/Gullies	Classification: Report or Observation	Enquiry Ref: FS4325497
Desc.: Issue with public footpath or bridleway Personal Information has advised that a BT cover is broken directly outside Personal Information property Personal Information As this is BT's Cover they have been notified however no action has been taken, can we poss ble get in touch with BT to explain that this is a hazard and require covering ASAP, cones have been place outside however this does not seem suitable. . Personal Information Submitted by Advisor: Nicholas Wing			
Location: The pin has been placed near 122 Melton Road, Nottingham, United Kingdom, NG12 5BQ	Contact:		
Enquiry No.: 6018102	Logged by: External to Confirm	on: 14/06/2016 17:00	Officer: Paula Johnson
Service: Trees/Verges	Subject: Grass Cutting	Classification: Report or Observation	Enquiry Ref: FS3557383
Desc.: Overgrown grass and verges - Customer ringing to report grass is overgrown. Needs cutting back as road users can't see oncoming traffic on a 50mph road. On Melton Road A606 at the junction near Wolds Kitchens & Interiors. . Submitted by Advisor: Oliver Hearn			
Location: The pin has been placed near 122 Melton Road, Nottingham, United Kingdom, NG12 5BQ	Contact:		
Enquiry No.: 6017803	Logged by: External to Confirm	on: 10/06/2016 17:15	Officer: Gary Cain
Service: Carriageway/Footway	Subject: Stray Animal	Classification: Report or Observation	Enquiry Ref: FS3502147
Desc.: Live/dead animal in road - several dead animals along this stretch of Melton road . Submitted by Advisor: Debbie Woolley			
Location: The pin has been placed near 138 Melton Road, Nottingham, United Kingdom, NG12 5BQ	Contact:		
Enquiry No.: 6017264	Logged by: External to Confirm	on: 07/06/2016 13:26	Officer: Laura Trusler
Service: Trees/Verges	Subject: Grass Cutting	Classification: Report or Observation	Enquiry Ref: FS3430871
Desc.: Overgrown grass and verges - Customer is calling Personal Information advised when vehicles pull out of the property their sight is obstructed by the grass. It really needs cutting. Its along Melton road the verge. Needs cutting back around the bus stops too. . Submitted by Advisor: Amy Burrekers			
Location: The pin has been placed near 122 Melton Road, Nottingham, United Kingdom, NG12 5BQ	Contact:		

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Customer Services

Enquiry No.: 6015809	Logged by: External to Confirm	on: 23/05/2016 07:35	Officer: John Buxton (Inspector)
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: 103895449
Desc.: Road heading past houses at the bottom of the hill on towards the houses at the top of the hill. Multiple pot holes, surface damage and worn out road surface. ** Customer Requested Auto Updates **			
Location: 225 meters from Melton Road		Contact:	
Plot Number: 2,000.00	Feature Id - Location:	Feature Type: Street Section	
Job Number: 2630581	Defect Number: 3529592		
Enquiry No.: 6013331	Logged by: External to Confirm	on: 24/04/2016 14:06	Officer: Paula Johnson
Service: Traffic Management	Subject: Traffic Calming	Classification: Report or Observation	Enquiry Ref: 103892798
Desc.: A606 entering 40 mph zone travelling north west from A46. Brand new speed limit illuminated sign which asks you to slow down if over the limit and thanks you if under the limit. BUT the sign has been set at 30 mph rather than 40 mph so if you are driving at say, 35 mph the sign still asks for you to slow down. If you are driving at 29 mph you are thanked. ** Customer Requested Auto Updates **			
Location: 31 meters from Melton Road		Contact:	
Enquiry No.: 6001595	Logged by: External to Confirm	on: 17/01/2016 16:38	Officer: Lester French (SL Rush-Brox S)
Service: Carriageway/Footway	Subject: St Furn/Non Illum Sign Damage	Classification: Report or Observation	Enquiry Ref: 103848756
Desc.: cross roads junction sign damaged			
Location: 93 meters from Melton Road		Contact:	
Enquiry No.: 6001434	Logged by: External to Confirm	on: 15/01/2016 11:52	Officer: Jennifer Smith
Service: Carriageway/Footway	Subject: Dropped Kerb (Vehicle) Request	Classification: Service Request	Enquiry Ref: 103847666
Desc.: Customer wants a dropped kerb request quote. Personal Information			
Dropped kerb is to be on the left of the property where a new drive has just been installed. Logged by CSC operator: Theo Stratton			
Location: Near Melton Road		Contact:	
Enquiry No.: 6000078	Logged by: External to Confirm	on: 08/01/2016 10:42	Officer: Jim Freeman
Service: Carriageway/Footway	Subject: Blocked Drain	Classification: Report or Observation	Enquiry Ref: 103837519
Desc.: Customer is reporting a blocked drain. Seven trent have been out to the site which is flooded who have notified customer that it is the drain thats blocked and is out responsibility. The water is running towards customers property Personal Information he drain is located next to a phone box which is directly outside Personal Information Could someone take a look please. Logged by CSC operator: Kelly Magill			
Location: 33 meters from Melton Road		Contact:	
Plot Number: 2,000.00	Feature Id - Location:	Feature Type: Street Section	
Job Number: 2621802	Defect Number: 3520963		
Enquiry No.: 3194943	Logged by: External to Confirm	on: 24/11/2015 15:34	Officer: Monty Haw
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	Enquiry Ref: 103796418
Desc.: There is a plum tree outside property 122 Melton Road, the tree has now been blown over by the wind and is leaning onto the property over a fence that goes between the property and the footpath. Logged by CSC operator: Zahra Alam			
Location: 38 meters from Melton Road		Contact:	

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Customer Services

Enquiry No.: 3184536	Logged by: External to Confirm	on: 10/09/2015 11:54	Officer: Claire Wilkinson
Service: Other	Subject: Other Enquiry (Highways)	Classification: Report or Observation	Enquiry Ref: 103707567
Desc.: Just past bank farm across from blue star garage - there is culvit under the melton road, Customer has been told that this would need to be done on a Sunday by NCC highways. customer is happy with this and has spoken with a contractor about this. customers query is regarding temporary traffic lights and what person needs to do regarding this. Can you give customer a ring so person an meet inspector to discuss this.			
Logged by CSC operator: Candy Cooper			
Location: 1029 meters from Melton Road	Contact:		
Enquiry No.: 3181512	Logged by: External to Confirm	on: 14/08/2015 08:09	Officer: Lynn Connelly (NRSWA)
Service: Trees/Verges	Subject: Grass Cutting	Classification: Report or Observation	Enquiry Ref: 103675454
Desc.: The pavement on the field side of the road from the topp of the hill at Stanton on the Wolds to the first house at the bottom of the hill is overgrown with grass. Over half of the pavement width is now grassed making it difficulty to walk safely along the path. Given the high speed of vechile traveling down the road it is make any resultant fall due to grass / vegetation overgrowth potentially very dangous.			
Can the council remove the grass ingress (not just cutt it back) to expose the pavement full width again please			
** Customer Requested Auto Updates **			
Location: 236 meters from Melton Road	Contact:		
Enquiry No.: 3177588	Logged by: External to Confirm	on: 09/07/2015 13:02	Officer: Lynn Connelly (NRSWA)
Service: Other	Subject: Other Enquiry (Escalated)	Classification: Report or Observation	Enquiry Ref: 103636166
Desc.: Customer is worried because only a strip of the grass has been cut and the rest is about 2 foot high and it is a problem pulling out of hillcrest works because of visibility. customer feels that there will be an accident because of this and she has previously rung twice.			
Closed Enquiry Number: 3176846			
Logged by CSC operator: Candy Cooper			
Location: 793 meters from Melton Road	Contact:		
Enquiry No.: 3176846	Logged by: External to Confirm	on: 02/07/2015 12:15	Officer: Paula Johnson
Service: Other	Subject: Other Enquiry (Escalated)	Classification: Report or Observation	Enquiry Ref: 103627927
Desc.: Customer phoned stating there is a strip which has been cut, but nearest to the kerb it hasn't, so you still cant see.			
Closed Enquiry Number: 3176445			
Logged by CSC operator: Josh Thacker			
Location: 793 meters from Melton Road	Contact:		
Enquiry No.: 3176445	Logged by: External to Confirm	on: 29/06/2015 11:30	Officer: Paula Johnson
Service: Trees/Verges	Subject: Grass Cutting	Classification: Report or Observation	Enquiry Ref: 103622859
Desc.: Customer is concerned about the grass as you turn out of Hillcrest onto A606. The grass is very overgrown and is obscuring the view for motorists pulling out, although is 40mph most people travelling on the road are doing so at 50mph plus. Is very dangerous.			
Logged by CSC operator: Claire Shockledge			
Location: 793 meters from Melton Road	Contact:		
Enquiry No.: 3170295	Logged by: External to Confirm	on: 05/05/2015 08:29	Officer: Lynn Connelly (NRSWA)
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: 103559918
Desc.: Road markings wearing. Please re-do. Cars are overtaking on the works "No overtaking" road markings.			
This was previously put onto this system and reported as complete. No re-doing of the road markings has happened though.			
Location:	Contact:		
Enquiry No.: 3170294	Logged by: External to Confirm	on: 05/05/2015 08:27	Officer: Lynn Connelly (NRSWA)
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: 103559913
Desc.: Pot holes in the road surface. Please repair. Previously reported on this system with the report being closed off without any works happening to the road.			
** Customer Requested Auto Updates **			
Location:	Contact:		

Effective: 19/04/2015 to 19/04/2017
Street: Melton Road (33019457)

Display Action Officer: Yes

Customer Services

Enquiry No.: 3169658	Logged by: External to Confirm	on: 27/04/2015 13:33	Officer: Lynn Connelly (NRSWA)
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: 103552251
Desc.: Road marking worn and faded. Road Chevrons for no overtaking visually poor due to wear.			
Location: 333 meters from Melton Road		Contact:	
Enquiry No.: 3169656	Logged by: External to Confirm	on: 27/04/2015 13:32	Officer: Lynn Connelly (NRSWA)
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: 103552244
Desc.: Pot holes and poor road service from Laming gap turning till the botton of hill at Stanton on the Wolds. ** Customer Requested Auto Updates **			
Location:		Contact:	
Enquiry No.: 3168976	Logged by: External to Confirm	on: 20/04/2015 16:25	Officer: Lynn Connelly (NRSWA)
Service: Other	Subject: Other Request (Highways)	Classification: Service Request	Enquiry Ref: 103544525
Desc.: Personal Information highways people have left all rubbish and all the railings down near Person property after doing some work on the road and he would			
Logged by CSC operator: Eilidh Adams			
Location: 444 meters from Melton Road		Contact:	
Enquiry No.: 62363	Logged by: Kendra Hourd	on: 19/04/2017 11:13	Officer: Kendra Hourd
Service: Carriageway/Footway	Subject: Manholes/Gullies	Classification: Report or Observation	
Desc.: Collapsed gullies			
Location: Opp the 8 houses in this length		Contact:	
Enquiry No.: 62188	Logged by: Kendra Hourd	on: 11/04/2017 15:01	Officer: Garry Kemp
Service: Road Works	Subject: Information Request	Classification: Service Request	
Desc.: Road closure queries about access and timings			
Location: residents/correspondents who live on the A606 at Stanton on the Wolds, and Laming Gap Lane – which is accessed from the A606.		Contact:	
Enquiry No.: 60754	Logged by: Kendra Hourd	on: 08/03/2017 14:32	Officer: Joanne Wilkinson
Service: Road Works	Subject: Road Works Report	Classification: Report or Observation	
Desc.: Temp signals not working twice in peak on 6/3/17. Also, only letting 10 cars through at a time and causing bad congestion. Can this be improved and managed better by the contractors ?			
Location: Not specific other than where signals are		Contact:	
Enquiry No.: 50427	Logged by: Jackie Turner	on: 15/06/2016 14:36	Officer: Katie Oakley
Service: Carriageway/Footway	Subject: Emergency Service Request	Classification: Report or Observation	
Desc.: RWO			
Location:		Contact:	
Enquiry No.: 50299	Logged by: Jim Freeman	on: 13/06/2016 14:02	Officer: Jim Freeman
Service: Other	Subject: Other Enquiry (Highways)	Classification: Report or Observation	
Desc.: Toursim Sign request			
Location: Browns Lane		Contact:	

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Customer Services

Enquiry No.: 50001	Logged by: Laura Trusler	on: 07/06/2016 10:50	Officer: Laura Trusler
Service: Trees/Verges	Subject: Overhanging Vegetation/Trees	Classification: Report or Observation	
Desc.: I have received a comment from a resident in regard to the recently installed flashing speed sign on the main road at SoWolds Personal is concerned that the sign is partially hidden by the overhanging branches of the oak tree which stands in front of the sign Personal maintains that 50% of the vehicles that pass Personal house are still travelling above the speed limit and that if the sign was in full view it would be more effective. Personal is asking for action to trim the tree.			
Location: O/S No 204	Contact:		
Enquiry No.: 48094	Logged by: Aaron Potival	on: 20/04/2016 13:08	Officer: Katie Oakley
Service: Carriageway/Footway	Subject: Emergency Service Request	Classification: Report or Observation	
Desc.: RWO			
Location: Melton Road, Stanton on Wolds	Contact:		
Enquiry No.: 47335	Logged by: Paula Johnson	on: 01/04/2016 14:42	Officer: Paula Johnson
Service: Other	Subject: Other Enquiry (Highways)	Classification: Report or Observation	
Desc.: An ISS was promised last year, Paul Hillier seem to think it should be in as was in 15/16 programme. Awaiting update from Chris Ashton.			
Location: A606 Melton Road	Contact:		
Enquiry No.: 46965	Logged by: Katie Oakley	on: 22/03/2016 11:28	Officer: Katie Oakley
Service: Carriageway/Footway	Subject: Emergency Service Request	Classification: Report or Observation	
Desc.: RWO - Via insurers as serious injuries to debtor			
Location:			
Enquiry No.: 43991	Logged by: Jim Freeman	on: 08/01/2016 11:05	Officer: Jim Freeman
Service: Other	Subject: Other Enquiry (Highways)	Classification: Report or Observation	
Desc.: adverts for Belvoir Vale Rest Home			
Location: on lighting columns 1. nr junction with Old Melton Road 2. at A46 island			
Enquiry No.: 43487	Logged by: Kendra Hourd	on: 15/12/2015 14:45	Officer: Kendra Hourd
Service: Traffic Management	Subject: Speed Limits/Issues	Classification: Report or Observation	
Desc.: Permanent interactive speed sign position			
Location: South of Browns Ln outside No 202	Contact:		
Enquiry No.: 39248	Logged by: Kendra Hourd	on: 04/09/2015 11:51	Officer: Paula Johnson
Service: Carriageway/Footway	Subject: Footway Obstruction	Classification: Report or Observation	
Desc.: There is a redundant sign post. Can this be removed?			
Location: on the A606, at the junction opposite Browns Lane (near the bus stop)	Contact:		
Enquiry No.: 39247	Logged by: Kendra Hourd	on: 04/09/2015 11:49	Officer: South Highways Management
Service: Trees/Verges	Subject: Overhanging Vegetation/Trees	Classification: Report or Observation	
Desc.: Vegetation is over-hanging the 'Stanton on the Wolds' village sign at the very northern end of the village, adjacent to Laming Gap. Can this vegetation be removed / landowner instructed to remove.			
Location: the 'Stanton on the Wolds' village sign at the very northern end of the village, adjacent to Laming Gap	Contact:		

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Customer Services

Enquiry No.: 39246	Logged by: Kendra Hourd	on: 04/09/2015 11:48	Officer: Sharon Kirk
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: my concern regarding the road surface was also motivated by the noise produced as much as by the uneven ride. I would point out that on the sharp RH bend north bound after Pinewood Lodge (approx 0.5 miles north of the A46 roundabout) there is significant frost damage on the nearside apex which as a motorcyclist I have found it imperative to avoid			
Location: Northern part of the village where the 40mph limit starts	Contact:		
Enquiry No.: 39228	Logged by: Kendra Hourd	on: 03/09/2015 17:00	Officer: Jim Freeman
Service: Carriageway/Footway	Subject: Footway Obstruction	Classification: Report or Observation	
Desc.: Request for footway width to be reclaimed/widened			
Location: On the west side from Laming Gap Lane southward to the existing 40mph signs	Contact:		
Enquiry No.: 38466	Logged by: Kendra Hourd	on: 12/08/2015 11:22	Officer: Kendra Hourd
Service: Traffic Management	Subject: Speed Limits/Issues	Classification: Report or Observation	
Desc.: Complaint that speed limit reduction consultation has not included [redacted] and wants additional speed reduction measures			
Location: Tollerton Ln to A46T	Contact:		
Enquiry No.: 35827	Logged by: Kendra Hourd	on: 22/05/2015 11:07	Officer: Kendra Hourd
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: Request for resurfacing, not Surface Dressing			
Location: 500m length outside houses near Browns Ln	Contact:		
Enquiry No.: 35741	Logged by: Kendra Hourd	on: 19/05/2015 16:40	Officer: Kendra Hourd
Service: Traffic Management	Subject: Traffic Issues	Classification: Report or Observation	
Desc.: Stanton/Keyworth direction sign is rusted and also blocks visibility for horseriders coming out of bridleway and trying to cross the A606. Can this be repositioned & replaced ?			
Location: Bridleway opposite Browns Ln jcn	Contact:		

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:	Feature Type: Street Section			Area: Rushcliffe		
2617831	Please jet through culvert under the A606, there could be a possible blockage, farmer has excavated out his road side ditches, but water is not free flowing through culvert. Will require t/m. (HW DR Standing water Z3)	On A606, between Browns Lane jnc and layby on l/h/s.	Pete Moncaster (Rushcliffe Category 2 (Low)		Job Completed	20/10/2015	20/11/2015	Act. RUSH/3701337
2621802	Cw deterioration (HW CW Pothole Z1)	Various locations just before the 40 MPH sign heading in to Stanton from Plumtree direction Melton Road A606	John Buxton (Inspector)	Filled when found (Cat 2H)	Job Completed	09/01/2016	09/01/2016	Act.
2630581	Customer complaint regarding Cw surface. (CW Repairs-Bituminous)	Heading in to Stanton from Tollerton direction. Just before the 40mph signs. Poor section of Cw all in the same lane , all potholes within an area marked in White	John Buxton (Inspector)	Category 2 (Low)	Job Completed	23/05/2016	05/07/2016	Act. RUS-AS/5600328

Effective: 19/04/2015 to 19/04/2017
Street: Melton Road (33019457)

Display Action Officer: Yes

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.:			Feature Type: Street Section		Area: Rushcliffe	
2636659	Fw pothole complaint by resident. - PLEASE C/W EDGE CHANNEL OF LOOSE DEBRIS / GRIT - (FW Repairs-Bituminous)	Access to 200 Melton Road, Nottingham, United Kingdom, NG12 5BP	John Buxton (Inspector)	Category 2 (Low)	Job Completed	27/09/2016	03/10/2016	Act. RUS-AS/5600446

Street Works Notices

Organisation: BT (0030005)

Works Ref: CR4W00000LUXCV6674B

Notice Type: Works Stop

Work Status: Works Stopped

Work Type: EToN 4: Major

Version: 4

Start: 04/05/2015 00:00:00

Issued: 06/05/2015 08:42:37

Est. End: 29/05/2015

Work Desc: MULTIWAY LIGHTS REQUIRED FOR 20 DAYS MON-FRI 0930-1530HRS TO ENABLE SAFE ACCESS TO BT CHAMBERS FOR BDUK FIBRE ROLLOUT PROJECT. LIGHTS WILL BE MANNED AT ALL TIMES***NO EXCAVATION****

Completion: 06/05/2015

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	MELTON ROAD FROM NEAR ENTRANCE TO BLACK PLANTATION TO JUNC LAMING GAP LANE CLIPSTON WOLDS NOTTINGHAMSHIRE	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	06/05/2015			29/05/2015

Works Ref: WP00100500216074200

Notice Type: Registration of Reinstatement - Full

Work Status: Works Stopped

Work Type: EToN 4: Immediate - Emergency

Version: 3

Start: 19/07/2016 15:54:00

Issued: 28/07/2016 14:40:59

Est. End: 21/07/2016

Work Desc: 1 ,Replace 1 jointbox frame and cover(s) (625mm x 625mm) in Footway

Completion: 21/07/2016

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	HAZARDOUS SITE. between 126 and 130, MELTON ROAD	Footway	Up to 1.5 Metres of Cover	1.00	1.00	A Permanent Reinstatement	21/07/2016		21/07/2016	21/07/2016

Works Ref: WP00100500238794800

Notice Type: Registration of Reinstatement - Full

Work Status: Works Stopped

Work Type: EToN 4: Immediate - Emergency

Version: 3

Start: 19/04/2017 19:00:00

Issued: 26/04/2017 10:55:39

Est. End: 21/04/2017

Work Desc: Replace 1 jointbox frame and cover(s) (1220mm x 680mm) in Carriageway

Completion: 21/04/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	420M NORTH OF CORNER OF BROOK LANE AND MELTON ROADWOLDS NG12 5PH, MELTON ROAD	Carriageway	Up to 1.5 Metres of Cover	2.10	1.40	A Permanent Reinstatement	21/04/2017		21/04/2017	21/04/2017

Works Ref: WP00400500232295600

Notice Type: Registration of Reinstatement - Full

Work Status: Works Stopped

Work Type: EToN 4: Minor

Version: 4

Start: 27/02/2017 00:00:00

Issued: 01/03/2017 10:27:45

Est. End: 01/03/2017

Work Desc: Locate and excavate 1 blockage in existing duct

Completion: 01/03/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN F/W O/S 138, MELTON ROAD	Footway	Up to 1.5 Metres of Cover	0.50	0.40	A Permanent Reinstatement	01/03/2017		01/03/2017	01/03/2017

Effective: 19/04/2015 to 19/04/2017
Street: Melton Road (33019457)

Display Action Officer: Yes

Street Works Notices

Organisation: BT (0030005)

Works Ref: WP00400500232320200
Notice Type: Registration of Reinstatement - Full
Work Status: Works Stopped
Work Type: EToN 4: Minor

Version: 4
Start: 27/02/2017 00:00:00
Issued: 01/03/2017 09:15:00
Est. End: 01/03/2017

Work Desc: Locate and excavate 1 blockage in existing duct
Completion: 01/03/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN SOFT O/S 174, MELTON ROAD	Verge	Up to 1.5 Metres of Cover	0.40	0.40	A Permanent Reinstatement	01/03/2017		01/03/2017	01/03/2017

Works Ref: WP00400500232333100
Notice Type: Registration of Reinstatement - Full
Work Status: Works Stopped
Work Type: EToN 4: Minor

Version: 4
Start: 27/02/2017 00:00:00
Issued: 01/03/2017 10:54:23
Est. End: 01/03/2017

Work Desc: Locate and excavate 1 blockage in existing duct
Completion: 01/03/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN SOFT O/S 186 , MELTON ROAD	Footway	Up to 1.5 Metres of Cover	0.30	0.25	A Permanent Reinstatement	01/03/2017		01/03/2017	01/03/2017
2	IN SOFT O/S 186 , MELTON ROAD	Verge	Up to 1.5 Metres of Cover	0.30	0.25	A Permanent Reinstatement	01/03/2017		01/03/2017	

Works Ref: WP00400500232446501
Notice Type: Registration of Reinstatement - Full
Work Status: Works Stopped
Work Type: EToN 4: Minor

Version: 4
Start: 01/03/2017 00:00:00
Issued: 17/03/2017 17:06:22
Est. End: 03/03/2017

Work Desc: locate and excavate 1 subsequent blockage in existing duct
Completion: 03/03/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	O/S 200, MELTON ROAD	Verge	Up to 1.5 Metres of Cover	0.50	0.70	A Permanent Reinstatement	17/03/2017		17/03/2017	02/03/2017

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: /A6062
Notice Type: Cancellation
Work Status: Abandoned Works
Work Type: EToN 4: Major

Version: 2
Start: 31/10/2016 00:00:00
Issued: 02/11/2016 08:27:51
Est. End: 04/11/2016

Work Desc: Carriageway resurfacing
Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Melton Road Stanton	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	31/10/2016			04/11/2016

Works Ref: /ACLA606C
Notice Type: Cancellation
Work Status: Abandoned Works
Work Type: EToN 4: Minor

Version: 2
Start: 20/07/2016 00:00:00
Issued: 28/07/2016 15:33:22
Est. End: 22/07/2016

Work Desc: Gully cleansing works.
Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Between A46 junction and Normanton on the Wolds.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	20/07/2016			22/07/2016

Effective: 19/04/2015 to 19/04/2017

Display Action Officer: Yes

Street: Melton Road (33019457)

Street Works Notices**Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** /MELTONRD1**Version:** 2**Work Desc:** Carriageway resurfacing**Notice Type:** Cancellation**Start:** 31/10/2016 00:00:00**Work Status:** Abandoned Works**Issued:** 02/11/2016 08:36:10**Work Type:** EToN 4: Major**Est. End:** 04/11/2016**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Melton Road Stanton	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	31/10/2016			04/11/2016

Works Ref: 40803997**Version:** 1**Work Desc:** Signing**Notice Type:** 3 Month Initial Notice**Start:** 11/01/2016 00:00:00**Work Status:** Proposed Works**Issued:** 06/01/2016 17:19:54**Work Type:** EToN 4: Major**Est. End:** 29/01/2016**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Eastbound - From Start of Stanton on the Wolds to Dual section near A46	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	11/01/2016			29/01/2016

Works Ref: A606MELTONRD1**Version:** 1**Work Desc:** Surface Dressing (Joint Sealing)**Notice Type:** 3 Month Initial Notice**Start:** 18/04/2017 00:00:00**Work Status:** Proposed Works**Issued:** 18/04/2017 11:50:45**Work Type:** EToN 4: Major**Est. End:** 19/04/2017**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	A606 Melton Road, Stanton on the Wolds	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	18/04/2017			19/04/2017

Works Ref: BROOKS**Version:** 3**Work Desc:** Ditching works to clear culverts**Notice Type:** Works Stop**Start:** 17/10/2015 00:00:00**Work Status:** Works Stopped**Issued:** 19/10/2015 08:24:39**Work Type:** EToN 4: Minor**Est. End:** 17/10/2015**Completion:** 17/10/2015

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Between its junctions with Station Road and Browns Lane	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	17/10/2015			17/10/2015

Works Ref: CS4058384**Version:** 1**Work Desc:** Road Markings - Road Studs**Notice Type:** 3 Day Initial Notice**Start:** 11/01/2016 00:00:00**Work Status:** Proposed Works**Issued:** 06/01/2016 17:14:55**Work Type:** EToN 4: Minor**Est. End:** 12/01/2016**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Eastbound - From Start of Stanton on the Wolds to Dual section near A46	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	11/01/2016			12/01/2016

Works Ref: OP1600578**Version:** 1**Work Desc:** Pre surface dress patching along A606 with TM team to provide, install and maintain signals**Notice Type:** 10 Day Initial Notice**Start:** 07/11/2016 00:00:00**Work Status:** Proposed Works**Issued:** 02/11/2016 08:39:39**Work Type:** EToN 4: Standard**Est. End:** 11/11/2016**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Along A606	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	07/11/2016			11/11/2016

Effective: 19/04/2015 to 19/04/2017
Street: Melton Road (33019457)

Display Action Officer: Yes

Street Works Notices

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: STANFORD

Version: 1

Work Desc: Trial Hole works for Section 278 works

Notice Type: 3 Day Initial Notice

Start: 28/05/2015 00:00:00

Work Status: Proposed Works

Issued: 29/05/2015 15:44:28

Work Type: EToN 4: Minor

Est. End: 29/05/2015

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Stanford Hall A606	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	28/05/2015			29/05/2015

Organisation: Severn Trent Water East (9103908)

Works Ref: 1101/000011151010

Version: 4

Work Desc: Boundary box Renew 25mm Job in Footway (Bitumen Macadam (Tarmac))

Notice Type: Works Stop

Start: 18/06/2015 00:00:00

Work Status: Works Stopped

Issued: 19/06/2015 09:02:02

Work Type: EToN 4: Minor

Est. End: 22/06/2015

Completion: 18/06/2015

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	126 melton road ng12-5bq	Footway	Up to 1.5 Metres of Cover	1.50	0.50 A Permanent Reinstatement	18/06/2015		18/06/2015	22/06/2015