

2017-2018 Capital Highways Works Programme

Budget Head	Budget Sub Category	Scheme Type	District	Ward	Estimated quarter Start On Site	Description	Contact
Capital Maintenance	Surface Dressing	Surface Dressing	Ashfield	Ashfields	Q2	Lindrick Road, Kirkby in Ashfield - Wentworth Road to Southwell Lane	richard.osborne@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Footway Improvements	Ashfield	Ashfields	Q4	B6018 Sutton Road, Kirkby-in-Ashfield	mike.elliott@viaem.co.uk
Capital Maintenance	Safety Fencing	Safety barriers	Ashfield	Hucknall	Q3	A611 Hucknall By-Pas	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing and Lining	Ashfield	Hucknall	Q3	A611 Watnall Road Roundabout, Hucknall - At its Roundabout junction with A611 Hucknall By-pass and B6009 Watnall Road	helen.north@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Ashfield	Hucknall North	Complete	A611 Hucknall Bypass, Hucknall - First Section, Annesley Road to Wood Lane	richard.osborne@viaem.co.uk
Integrated Transport Measures	Speed management	Speed Limit Reduction	Ashfield	Hucknall North	Q4	B6011 Wighay Road, Hucknall	jeffrey.burton@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Pedestrian Crossing Improvements	Ashfield	Hucknall South	Q4	Storth Avenue, Hucknall - At its junction with Caddaw Avenue	steve.marston@viaem.co.uk
Capital Maintenance	A-Roads PRN	Resurfacing	Ashfield	Hucknall South	Complete	A611 Wood Lane Island, Hucknall - Roundabout at Wood Lane	richard.osborne@viaem.co.uk
Capital Maintenance	Structural Drainage	Improve drainage system	Ashfield	Hucknall South	Q2	Bestwood Footpath No.13, Hucknall - Footpath between Bestwood Village and Butlers Hill	richard.osborne@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Ashfield	Hucknall South	Q2	West Street, Hucknall	richard.osborne@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Pedestrian Crossing Improvements	Ashfield	Hucknall South	Q4	Derbyshire Lane / Yorke Street / Central Avenue, Hucknall - At its junction	adam.lakin@viaem.co.uk
Integrated Transport Measures	Speed management	Installation of 40mph Buffer	Ashfield	Kirkby North	Q3	B6020 Blidworth Road, Kirkby-in-Ashfield - Adjacent to its junction of Diamond Avenue and A611 Derby Road	jeffrey.burton@viaem.co.uk
Capital Maintenance	Footways		Ashfield	Kirkby South	Q2	Belmont Road, Nuncargate	adam.lakin@viaem.co.uk
Capital Maintenance	Safety Fencing	Safety barriers	Ashfield	Kirkby South	Q3	Park Lane, Selston	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Bus improvements	Hotspot management - TROs with DYL and Bus Stop Clearway	Ashfield	Kirkby South	Q3	Kirkby Woodhouse Hotspot Management - Kirkby Woodhouse Primary School at Main Road, Kirkby-in-Ashfield	helen.north@viaem.co.uk
Integrated Transport Measures	Parking	TROs - Waiting restrictions	Ashfield	Kirkby South	Q4	Forest Road, Annesley Woodhouse - Outside Doctor's surgery at No.194 (Adjacent to Skegby Road)	dale.swain@viaem.co.uk
Integrated Transport Measures	Safety improvements	High friction surfacing	Ashfield	Kirkby South	Complete	B6018 Church Hill, Kirkby-in-Ashfield - Bend at Pennine Drive (Southern End)	richard.osborne@viaem.co.uk
Integrated Transport Measures	Speed Management	Part of Countywide Interactive Speed Signs Programme 16/17	Ashfield	Selston	Complete	A608 Cordy Lane, Underwood - 500m South West of B600	steve.marston@viaem.co.uk
Integrated Transport Measures	Speed Management	Part of Countywide Interactive Speed Signs Programme 16/17	Ashfield	Selston	Complete	B6016 Pye Hill Road, Jacksdale - South East of Providence Road	steve.marston@viaem.co.uk
Capital Maintenance	B/C Roads	Resurfacing	Ashfield	Selston	Complete	B600 Alfreton Road, Underwood - Sandhill Road Junction area	richard.osborne@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Installation of Pedestrian Refuge	Ashfield	Sutton Central and East	Q4	High Pavement, Sutton-in-Ashfield - Adjacent to Silk street	helen.north@viaem.co.uk
Integrated Transport Measures	Safety Improvements	Street Lighting Upgrade	Ashfield	Sutton Central and East	Complete	Mansfield Road, Sutton in Ashfield	antonio.biondi@viaem.co.uk
Integrated Transport Measures	Safety Improvements	Safety Improvements - Signing and Lining with upgrade existing Street Lighting	Ashfield	Sutton Central and East	Substantially Complete	Willowbridge Lane / Brook Street, Sutton-in-Ashfield	antonio.biondi@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Ashfield	Sutton Central and East	Q2	Mabel Avenue, Sutton-in-Ashfield	antonio.biondi@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Ashfield	Sutton Central and East	Q2	Sheepwash Lane Area, Sutton-in-Ashfield - Sheepwash Lane / Vellus Court / Pepper Street / Young Crescent	antonio.biondi@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Ashfield	Sutton Central and East	Q2	Wrightson Close, Sutton-in-Ashfield	antonio.biondi@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Ashfield	Sutton Central and East	Q2	Charles Street, Sutton in Ashfield - Garden Lane to Brookdale Road	richard.osborne@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Ashfield	Sutton Central and East	Complete	Redcliffe Street, Sutton-in-Ashfield	richard.osborne@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Pedestrian Refuge	Ashfield	Sutton Central and East	Q4	Unwin Road, Sutton in Ashfield	mike.elliott@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing and Lining	Ashfield	Sutton Central and East	Q3	B6023 Prieststic Road / Northern Bridge Road, Sutton-in-Ashfield - At its mini-roundabout	dale.swain@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing	Ashfield	Sutton Central and East	Q3	Kirkby Folly Road / B6022 Newark Road, Sutton-in-Ashfield - Adjacent to its Roundabout	dale.swain@viaem.co.uk
Integrated Transport Measures	Speed management	Speed Limit Reduction to 40mph	Ashfield	Sutton Central and East	Q3	A60 Nottingham Road, Harlow Wood	dale.swain@viaem.co.uk
Capital Maintenance	A-Roads PRN	Resurfacing - Emergency Repair	Ashfield	Sutton Central and East	Complete	A38 Kings Mill Road, Sutton-in-Ashfield - A38 Kings Mill Road East - Junctions between Coxmoor Road and Mansfield Road	richard.osborne@viaem.co.uk

2017-2018 Capital Highways Works Programme

Budget Head	Budget Sub Category	Scheme Type	District	Ward	Estimated quarter Start On Site	Description	Contact
Capital Maintenance	Street Lighting	Lighting Column Replacement	Ashfield	Sutton North	Q2	Healdswood Street Area, Skegby - included Beech Street / Hazel Street / Oak Street	antonio.biondi@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Ashfield	Sutton North	Q2	Leyton Avenue, Sutton-in-Ashfield - Forest Road to end	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Ashfield	Sutton North	Complete	Pleasley Road, Teversal - Norwood Lane to Silverhill Lane	richard.osborne@viaem.co.uk
Capital Maintenance	B/C Roads	Structural patching	Ashfield	Sutton West	Q2	B6026 Huthwaite Road, Sutton in Ashfield - Phase 2	paul.shacklock@viaem.co.uk
Capital Maintenance	B/C Roads	Reconstruction	Ashfield	Sutton West	Q2	B6027 Common Road, Huthwaite - Phase 3	richard.osborne@viaem.co.uk
Capital Maintenance	B/C Roads	Resurfacing	Ashfield	Sutton West	Complete	C222 Carsic Road, Sutton-in-Ashfield (Phase 1)	richard.osborne@viaem.co.uk
Capital Maintenance	Footways		Ashfield	Sutton West	Q2	Ashlands Close, Sutton-in-Ashfield	adam.lakin@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Ashfield	Sutton West	Q2	High Street, Huthwaite - Unwin Street to North Street	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Ashfield	Sutton West	Q2	Carnarvon Grove, Sutton-in-Ashfield - Sutton Road to end	richard.osborne@viaem.co.uk
Capital Maintenance	Bridge Maintenance	Principal inspections	Ashfield	Various	Ongoing till end of 17/18	Ashfield Bridges Principal Inspections	mike.hawkings@viaem.co.uk
Integrated Transport Measures	Bus Improvements	Bus Stop Clearways	Ashfield	Various	Q4	Ashfield TROs and Bus Stop Clearways	helen.north@viaem.co.uk
Major Projects	Hucknall TCIS	Town Centre Improvements	Ashfield	Various	On Site	Hucknall Town Centre Improvements Scheme	tom.boylan@viaem.co.uk
Capital Maintenance	Safety Fencing	Defect testing and repairs	Ashfield	Various	Q2	Hucknall Town Centre repairs	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Bus improvements	Bus Stop Clearway Programme	Ashfield	Various	Q4	Ashfield Bus Stop Clearway Programme 17-18	dale.swain@viaem.co.uk
Capital Maintenance	Footways	Slurry Seal	Ashfield	Various	Q2	Ashfield Slurry Sealing Programme 17-18	richard.osborne@viaem.co.uk
Capital Maintenance	Structural Drainage	Drainage	Ashfield	Various	Q2	Ashfield Miscellaneous Structural Drainage 17-18	richard.osborne@viaem.co.uk
Integrated Transport Measures	Speed Management	Speed Limit reduction to 50mph	Ashfield / Gedling	Newstead / Kirkby South	Complete	Hucknall Road, Newstead - From Willow House to A611 Annesley Road , Annesley Woodhouse	jeffrey.burton@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Zebra crossing Improvements	Bassetlaw	Blyth and Harworth	Complete	A634 High Street, Blyth - Adjacent to the junction with Retford Road	helen.north@viaem.co.uk
Major Projects	Bassetlaw CIL Schemes	Capacity Improvements	Bassetlaw	Blyth and Harworth	Complete	A1 / A614 Blyth Road Junctions, Blyth - Between A1 / A614 Bawtry Road Roundabout to The Woodland	nigel.barlow@viaem.co.uk
Capital Maintenance	Footways	Resurfacing	Bassetlaw	Blyth and Harworth	Q2	Meadow Way, Harworth	david.burton@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Bassetlaw	Blyth and Harworth	On Site	Styrrup Road, Harworth	antonio.biondi@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Bassetlaw	Blyth and Harworth	Q2	Goldthorpe Avenue, Langold	david.burton@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Bassetlaw	Blyth and Harworth	Q2	Droversdale Road, Bircotes	richard.osborne@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Bassetlaw	Blyth and Harworth	Q2	Beech Road, Harworth	david.burton@viaem.co.uk
Capital Maintenance	Bridge Maintenance	Replace the existing bridge with a culvert	Bassetlaw	Misterton	Q2	RoW Everton Bridleway No.4 - Polly Bell Bank	mike.hawkings@viaem.co.uk
Capital Maintenance	B/C Roads	Resurfacing	Bassetlaw	Misterton	Q2	B1403 Church Street, Misterton - A161 to Minster Road	david.burton@viaem.co.uk
Capital Maintenance	Bridge Maintenance	Parapet replacement	Bassetlaw	Misterton	Q2	A620 Culvert near the Gables, Saundby	mike.hawkings@viaem.co.uk
Capital Maintenance	Footways	Sheet Pile Reinforcement and Resurfacing	Bassetlaw	Misterton	Q4	A631 The Flood Road, Beckingham - Bend at Oil Depot for 80m (Phase 1)	david.burton@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Bassetlaw	Misterton	Q2	A161 Haxey Road / High Street / Station Street, Misterton	antonio.biondi@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Bassetlaw	Misterton	Substantially complete	A631 Bawtry Road / Gainsborough Road, Everton	antonio.biondi@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Bassetlaw	Misterton	Substantially complete	Main Street / Ranskill Road / Mattersey Road, Mattersey	antonio.biondi@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Bassetlaw	Misterton	Complete	Station Road, Ranskill	antonio.biondi@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Bassetlaw	Misterton	Complete	Croft Way, Everton - Include Croft Farm Close	antonio.biondi@viaem.co.uk

2017-2018 Capital Highways Works Programme

Budget Head	Budget Sub Category	Scheme Type	District	Ward	Estimated quarter Start On Site	Description	Contact
Capital Maintenance	Structural Drainage	New gully and soakaway	Bassetlaw	Misterton	Q3	High Street, Gringley-on-the-Hill	david.burton@viaem.co.uk
Capital Maintenance	Structural Drainage	New gully and repair existing pipework (A.I.U. Ref: G767)	Bassetlaw	Misterton	Q2	B1403 Walkeringham Road, Gringley on the Hill - Bend at Wooden Beck Hill	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Misterton	Complete	A631 Gringley Duals	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Misterton	Complete	C69 Daneshill Road, Torworth	david.burton@viaem.co.uk
Integrated Transport Measures	Speed management	Speed limit reduction to 30mph	Bassetlaw	Misterton	Q4	Main Street, Scaftworth - Between A631 Gainsborough Road to Theaker Lane (Track)	dale.swain@viaem.co.uk
Integrated Transport Measures	Environmental Weight limits	HGV Direction Signing	Bassetlaw	Misterton	Q3	Sutton cum Lound HGV Direction Signing	dale.swain@viaem.co.uk
Capital Maintenance	Footways	Resurfacing	Bassetlaw	Retford East	Q2	Hirst Road, Retford	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford East	Q2	Ainsdale Green, Ordsall	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford East	Q2	Birkdale Grove, Ordsall	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford East	Q2	Glen Eagles Way, Ordsall	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford East	Q2	Lockwood Drive, Ordsall	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford East	Q2	Sunningdale, Ordsall	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford East	Q2	Troon Court, Ordsall	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford East	Q2	Wentworth Close, Ordsall	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Bassetlaw	Retford East	Q2	Claters Close, Retford	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford East	Q2	Cornwall Road, Retford	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Bassetlaw	Retford East	Q2	Hillcrest Mews, Retford	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford East	Q2	Hirst Road, Retford	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford East	Q2	Holdenby Close, Retford	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford East	Q2	Palmer Road, Retford	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford East	Q2	Park Lane, Retford	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford East	Q2	Richmond Road, Retford	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford East	Q2	St Saviours Close, Retford	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford East	Q2	Winston Grove, Retford	david.burton@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Footpath upgrade	Bassetlaw	Retford East	Q2	Retford Footpath No.11 - All Hallows Street / Hill Street	jane.baines@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	New footbridge	Bassetlaw	Retford East	Q4	Goosemoor Bridge, Ordsall - Goosemoor Lane	mike.hawkings@viaem.co.uk
Integrated Transport Measures	Safety improvements	additional of removal of foliage and redundant concrete fence post	Bassetlaw	Retford East	Q4	A638 London Road / Grove Road, Retford - At its mini-roundabout	dale.swain@viaem.co.uk
Integrated Transport Measures	Safety Improvements	Bollards and Lining works	Bassetlaw	Retford East / Retford West	To be programmed	A638 London Road / South Street, Retford - At the junction	cathy.gillespie@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Pedestrian improvements	Bassetlaw	Retford West	To be programmed	Railway Station approaches, Retford	cathy.gillespie@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford West	Q2	Heathfield Gardens, Retford	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford West	Q2	New Inn Walk, Retford	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford West	Q2	Newton Street, Retford	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford West	Q2	Stanley Street, Retford	david.burton@viaem.co.uk

2017-2018 Capital Highways Works Programme

Budget Head	Budget Sub Category	Scheme Type	District	Ward	Estimated quarter Start On Site	Description	Contact
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford West	Q2	Thrumpton Close, Retford	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford West	Q2	Water Lane, Retford	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford West	Q2	Woodbeck Rise, Retford	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Retford West	Q2	Woodlands, Retford	david.burton@viaem.co.uk
Integrated Transport Measures	Speed management	Extension of 40mph speed limit / Speed limit reduction to 50mph	Bassetlaw	Retford West	Q4	A638 Great North Road, Bamby Moor / Torworth - Between Billy Bulton Lane to Retford Road	dale.swain@viaem.co.uk
Integrated Transport Measures	Parking	Residents Parking Scheme	Bassetlaw	Retford West	Q4	Retford Railway Station Area Residents Parking Scheme	adam.lakin@viaem.co.uk
Capital Maintenance	A-Roads PRN	Resurfacing	Bassetlaw	Tuxford	Complete	A57 Broad Gate, Darlton	david.burton@viaem.co.uk
Capital Maintenance	B/C Roads	Major patching / Binder course inlay	Bassetlaw	Tuxford	Q2	B6387 Retford Road, Haughton - District boundary to bend at Bothamsall	david.burton@viaem.co.uk
Capital Maintenance	B/C Roads	Major patching / Binder course inlay	Bassetlaw	Tuxford	Q2	C108 Wood Lane, Treswell - Forewood Lane to Grove Road	david.burton@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Bassetlaw	Tuxford	Q2	Church Street, South Leverton	antonio.biondi@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing and Lining	Bassetlaw	Tuxford	Q4	A616 Mansfield Road (Holbeck Road), Holbeck - Bonbusk Farm - Adjacent to Derbyshire Border	helen.north@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing and Lining	Bassetlaw	Tuxford	To be programmed	A57 Cliff Gate, East Markham - Between the A1 and East Markham	dale.swain@viaem.co.uk
Integrated Transport Measures	Safety improvements	Installation of Chevron	Bassetlaw	Tuxford	Q4	Outgang Lane, Treswell - Bend adjacent to Power Station	dale.swain@viaem.co.uk
Capital Maintenance	Bridge Maintenance	Principal inspections	Bassetlaw	Various	Ongoing till end of 17/18	Bassetlaw Bridges Principal Inspections	mike.hawkings@viaem.co.uk
Integrated Transport Measures	Bus improvements	Bus Stop Clearway Programme	Bassetlaw	Various	Q4	Bassetlaw Bus Stop Clearway Programme 17-18	dale.swain@viaem.co.uk
Capital Maintenance	Footways	Slurry Seal	Bassetlaw	Various	Q2	Bassetlaw Slurry Sealing Programme 17-18	david.burton@viaem.co.uk
Capital Maintenance	Salix Grant	Lantern Replacement	Bassetlaw	Various	Ongoing	Salix Bassetlaw Lantern Replacement	clare.murden@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Bassetlaw	Worksop East	Complete	High Hoe Road, Worksop	antonio.biondi@viaem.co.uk
Major Projects	Worksop Bus Station	Various Minor Works	Bassetlaw	Worksop East	On Site	Worksop Bus Station	mike.barnett@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Bassetlaw	Worksop East	Complete	Eastgate, Worksop	antonio.biondi@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop East	Q2	Bean Avenue, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop East	Q2	Bracebridge Avenue, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop East	Q2	Conrad Close, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop East	Q2	Dryden Dale, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop East	Q2	Gordon Close, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop East	Q2	Kingsway, Worksop - The Oval to Queensway	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop East	Q2	South Parade, Worksop - Sunfield to Kingsway	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop East	Q2	Southdene, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop East	Q2	Sunfield Avenue, Worksop - The Oval to South Parade	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop East	Q2	Sunnybank, Worksop - Kingsway to Sunfield Avenue	david.burton@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing and Lining	Bassetlaw	Worksop East	Q3	B6041 High Hoe Road, Worksop	dale.swain@viaem.co.uk
Integrated Transport Measures	Safety improvements	Junction Improvements	Bassetlaw	Worksop East	Q3	Shrewsbury Road / Retford Road, Worksop	antonio.biondi@viaem.co.uk
Integrated Transport Measures	Safety improvements	Zebra Improvements	Bassetlaw	Worksop East	Q4	Stanley Street / Anston Avenue, Worksop	mike.elliott@viaem.co.uk

2017-2018 Capital Highways Works Programme

Budget Head	Budget Sub Category	Scheme Type	District	Ward	Estimated quarter Start On Site	Description	Contact
Integrated Transport Measures	Parking	Residents Parking Scheme	Bassetlaw	Worksop East	Q4	Canal Road, Worksop	dale.swain@viaem.co.uk
Integrated Transport Measures	Parking	Residents Parking Scheme	Bassetlaw	Worksop East	Q4	Eastgate, Worksop	dale.swain@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Allsopp Drive, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Bassetlaw	Worksop North	Q2	Ashley Court, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Beechcroft, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Canterbury Close, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Coventry Drive, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Durham Close, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Greenacre Road, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Hillside Crescent, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Kent Close, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Lichfield Close, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Monmouth Road, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Northwood, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Primrose Way, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Ravenscourt, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Bassetlaw	Worksop North	Q2	Ribblesdale, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Ringwood, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	St Davids Close, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Sunnymede, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Wessex Road, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Westfield Drive, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Winchester Close, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Wingfield Avenue, Worksop - Gloucester Road to Greenacre Road	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop North	Q2	Worcester Close, Worksop	david.burton@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Bassetlaw	Worksop North	Q2	Le Brun Square, Carlton-in-Lindrick	david.burton@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Bassetlaw	Worksop North	Q2	Sycamore Road, Carlton-in-Lindrick	david.burton@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing and Lining	Bassetlaw	Worksop North	Q3	B6045 Blyth Road / Crossley Hill Lane, Worksop - At its junction	helen.north@viaem.co.uk
Capital Maintenance	Structural Drainage	New culvert	Bassetlaw	Worksop North / Worksop West	Q3	Steetley Lane, Shireoaks	david.burton@viaem.co.uk
Capital Maintenance	A-Roads PRN	Resurfacing	Bassetlaw	Worksop South	Q2	A632 Main Road, Nether Langwith - From Wood Lane East for 150m	david.burton@viaem.co.uk
Integrated Transport Measures	Parking	TROs - Modifications of parking restrictions (Members' request)	Bassetlaw	Worksop South	Q4	Ryton Street, Worksop	tom.boylan@viaem.co.uk
Integrated Transport Measures	Parking	Residents Parking Scheme	Bassetlaw	Worksop South	Q4	Devonshire Street / Harrington Street, Worksop	dale.swain@viaem.co.uk
Integrated Transport Measures	Parking	Modifications to Parking Restrictions	Bassetlaw	Worksop South	Q4	Westgate, Worksop	dale.swain@viaem.co.uk

2017-2018 Capital Highways Works Programme

Budget Head	Budget Sub Category	Scheme Type	District	Ward	Estimated quarter Start On Site	Description	Contact
Capital Maintenance	Structural Drainage	New ACO kerbs	Bassetlaw	Worksop West	Q2	Shireoaks Common, Shireoaks - Outside N° 85	david.burton@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Bassetlaw	Worksop West	Complete	B6041 Gateford Road, Worksop - From A57 to 30 Limits at Ashes Park Avenue	david.burton@viaem.co.uk
Integrated Transport Measures	Safety improvements	Street Lighting Upgrade	Bassetlaw	Worksop West	Q3 / Q4	Ashes Park Avenue, Worksop	antonio.biondi@viaem.co.uk
Integrated Transport Measures	Safety improvements	Street Lighting Upgrade	Bassetlaw	Worksop West	Q3 / Q4	Claylands Avenue, Worksop	antonio.biondi@viaem.co.uk
Integrated Transport Measures	Safety improvements	Toucan Crossing Modifications	Bassetlaw	Worksop West	Q2	B6041 Raymoth Lane, Worksop - Adjacent to St Johns Primary School	david.burton@viaem.co.uk
Major Projects	A57 Roundabout	Roundabout / Junction Improvements	Bassetlaw	Worksop West / Worksop East	Q3	A57 / A60 Worksop Roundabout Improvements - At its Roundabout between A60 Mansfield Road, A57 Worksop Bypass, B6024 Newcastle Avenue and St Anne's Drive, Worksop	harfan.ghafoor@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signage and Drainage	Bassetlaw	Worksop West / Worksop East	Q4	A57 Gateford Road / Woodsetts Lane Roundabout, Worksop	mohammed.haque@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Broxtowe	Beeston Central and Rylands	Q2	Beech Avenue, Beeston Rylands	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Beeston Central and Rylands	Q2	East Crescent, Beeston Rylands	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Beeston Central and Rylands	Q2	Elswick Drive, Beeston Rylands	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Beeston Central and Rylands	Q2	Laburnum Grove, Beeston Rylands	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Beeston Central and Rylands	Q2	Lavender Grove, Beeston Rylands	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Beeston Central and Rylands	Q2	Lily Grove, Beeston Rylands	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Beeston Central and Rylands	Q2	Rose Grove, Beeston Rylands	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Beeston Central and Rylands	Q2	Roy Avenue, Beeston Rylands	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Broxtowe	Beeston Central and Rylands	Q2	West Crescent, Beeston Rylands	richard.osborne@viaem.co.uk
Integrated Transport Measures	Safety improvements	Lining	Broxtowe	Beeston Central and Rylands	Substantially complete	A6005 Queens Road, Beeston - Between Humber Road to Read Avenue	steph.walford@viaem.co.uk
Integrated Transport Measures	Safety improvements	Zebra Crossing Improvements	Broxtowe	Beeston Central and Rylands	Q4	Station Road / Nether Street, Beeston	mike.elliott@viaem.co.uk
Integrated Transport Measures	Parking	Extend Existing Residents Parking Scheme	Broxtowe	Beeston Central and Rylands	Q3	Wilkinson Avenue, Beeston - Adjacent to B6006 Wollaton Road	steph.walford@viaem.co.uk
Integrated Transport Measures	Cycling and health	Strategic Cycle Routes	Broxtowe	Rylands / Bramcote and Beeston North	Q3 / Q4 - Phase Construction	Nottingham Enterprise Zone Cycle Routes	cathy.gillespie@viaem.co.uk
Integrated Transport Measures	Safety Improvements	Implementation of central hatching with additional zig zags markings	Broxtowe	Beeston South and Rylands	Substantially Complete	A6005 Queens Road, Beeston - Between Lower Regent Street and Dallas York Road	steph.walford@viaem.co.uk
Integrated Transport Measures	Safety improvements	Traffic Calming - Installation of Road Humps	Broxtowe	Bramcote and Beeston North	Q4	Abbey Road / Marlborough Road, Beeston - At its all junction approaches	richard.osborne@viaem.co.uk
Integrated Transport Measures	Speed management	Speed Limit Reduction To 50mph	Broxtowe	Bramcote and Beeston North	Q3	A6002 Coventry Lane, Bramcote - Adjacent from the Railway line to Longden Close	steph.walford@viaem.co.uk
Capital Maintenance	Safety Fencing	Safety barriers	Broxtowe	Bramcote and Beeston North	Q3	Town Street, Bramcote	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Parking	TROs - Waiting restrictions	Broxtowe	Bramcote and Beeston North	Q3	B6464 Broadgate Avenue, Beeston	steph.walford@viaem.co.uk
Capital Maintenance	Safety Fencing	Safety barriers	Broxtowe	Eastwood	Q3	Newmanleys Road, Eastwood	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Footpath upgrade	Broxtowe	Eastwood	Q3	Eastwood Footpath No.21	jane.baines@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Greasley and Brinsley	Q2	Briar Road, Newthorpe Common	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Greasley and Brinsley	Q2	Clover Rise, Newthorpe Common	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Greasley and Brinsley	Q2	Cowper Road, Newthorpe Common	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Greasley and Brinsley	Q2	Daisy Farm Road, Newthorpe Common	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Greasley and Brinsley	Q2	Foxglove Road, Newthorpe Common	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Greasley and Brinsley	Q2	Gorse Close, Newthorpe Common	richard.osborne@viaem.co.uk

2017-2018 Capital Highways Works Programme

Budget Head	Budget Sub Category	Scheme Type	District	Ward	Estimated quarter Start On Site	Description	Contact
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Greasley and Brinsley	Q2	Lodge Road, Newthorpe Common	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Greasley and Brinsley	Q2	Mayflower Road, Newthorpe Common	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Greasley and Brinsley	Q2	Primrose Rise, Newthorpe Common	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Greasley and Brinsley	Q2	Rolleston Drive, Newthorpe Common	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Greasley and Brinsley	Q2	Thistle Close, Newthorpe Common	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Greasley and Brinsley	Q2	Thorn Drive, Newthorpe Common	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Greasley and Brinsley	Q2	Violet Avenue, Newthorpe Common	richard.osborne@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Toucan Crossing	Broxtowe	Greasley and Brinsley	Q3	B6010 Nottingham Road, Giltbrook - Adjacent to North of Gilt Hill / Ikea Way Junction	chris.ashton@viaem.co.uk
Integrated Transport Measures	Environmental Weight limits	Implementation of HGV Signing	Broxtowe	Greasley and Brinsley	To be Programmed	Main Street, Newthorpe	steph.walford@viaem.co.uk
Capital Maintenance	B/C Roads	Resurfacing	Broxtowe	Greasley and Brinsley / Beauvale	Q2	B6010 Nottingham Road, Giltbrook - From A610 to IKEA island	richard.osborne@viaem.co.uk
Integrated Transport Measures	Capacity Improvements	Signing and Lining improvements	Broxtowe	Kimberley and Trowell / Beauvale	Q3	A610 / A6096 / B6010 Giltbrook Retail Park (Ikea) Roundabouts	steph.walford@viaem.co.uk
Integrated Transport Measures	Safety Improvements	Junction Improvements - Build out with removal of parking spaces	Broxtowe	Nuthall and Kimberley	Complete	Eastwood Road / Maws Lane, Kimberley	rob.driver@viaem.co.uk
Capital Maintenance	Traffic Signal Renewal	Traffic signal renewal	Broxtowe	Nuthall and Kimberley	Q2	A610 / B600 / A6002 Nuthall Roundabout - A610 Nuthall Roundabout Junction with B600 Nottingham Road / A6002 Low Wood Road	chris.ashton@viaem.co.uk
Integrated Transport Measures	Parking	TROs - Parking restrictions	Broxtowe	Nuthall and Kimberley	Q4	Horsendale School, Nuthall - Assarts Road - Junction with Horsendale Avenue	steph.walford@viaem.co.uk
Capital Maintenance	B/C Roads	Resurfacing	Broxtowe	Stapleford and Broxtowe Central	Q2	B6003 Pasture Road, Stapleford - From Trowell Road to Moorbridge Lane	richard.osborne@viaem.co.uk
Capital Maintenance	Footways		Broxtowe	Stapleford and Broxtowe Central	Q2	New Eaton Road, Stapleford (Phase 3)	adam.lakin@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Broxtowe	Stapleford and Broxtowe Central	Q2	Court / Rockford Court / Radburn Court / Merton Court / Bedford Court / Montrose Court / Dryden Court / Denver Court / Maryland Court	antonio.biondi@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Broxtowe	Stapleford and Broxtowe Central	Complete	A609 Ilkeston Road, Trowell - From County Boundary to o/s N° 15 Nottingham Road	richard.osborne@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	New Pedestrian Refuge	Broxtowe	Stapleford and Broxtowe Central	Q3	Pinfold Lane, Stapleford	mike.elliott@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Broxtowe	Toton, Chilwell and Attenborough	To be programmed	c/o - High Road, Chilwell	antonio.biondi@viaem.co.uk
Capital Maintenance	A-Roads PRN	Resurfacing	Broxtowe	Toton, Chilwell and Attenborough	Q3	A6005 Bye Pass Road, Chilwell - Attenborough Lane to Queens Road	richard.osborne@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Broxtowe	Toton, Chilwell and Attenborough	Q2	Bramcote Avenue, Chilwell	richard.osborne@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Broxtowe	Toton, Chilwell and Attenborough	Q2	Meadow Lane, Chilwell - From Queens Road to By-Pass Road	richard.osborne@viaem.co.uk
Integrated Transport Measures	Bus improvements	Bus Stop Improvements - Bus Stop Relocation and Raised Kerb	Broxtowe	Toton, Chilwell and Attenborough	Q3	Inham Road, Chilwell	steph.walford@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing	Broxtowe	Toton, Chilwell and Attenborough	Q3	B6464 High Road / Cator Lane, Chilwell	steph.walford@viaem.co.uk
Capital Maintenance	Bridge Maintenance	Principal inspections	Broxtowe	Various	Ongoing till end of 17/18	Broxtowe Bridges Principal Inspections	mike.hawkings@viaem.co.uk
Integrated Transport Measures	Parking	Waiting Restrictions	Broxtowe	Various	Q2	NET Waiting Restrictions - Hallam Road, Beeston	steph.walford@viaem.co.uk
Integrated Transport Measures	Bus improvements	Traffic Regulation Order and hotspot management	Broxtowe	Various	Q3	Broxtowe TROs and Hotspot Management	steph.walford@viaem.co.uk
Integrated Transport Measures	Bus improvements	Bus Stop Clearway Programme	Broxtowe	Various	Q4	Broxtowe Bus Stop Clearway Programme 17-18	steph.walford@viaem.co.uk
Capital Maintenance	Safety Fencing	Defect repairs	Broxtowe	Various	Q3	Broxtowe Miscellaneous Repairs	paul.shacklock@viaem.co.uk
Capital Maintenance	Footways	Slurry Seal	Broxtowe	Various	Q2	Broxtowe Slurry Sealing Programme 17-18	richard.osborne@viaem.co.uk
Capital Maintenance	Structural Drainage	Drainage	Broxtowe	Various	Q2	Broxtowe Miscellaneous Structural Drainage 17-18	richard.osborne@viaem.co.uk
Integrated Transport Measures	Bus improvements	Bus Stop Infrastructure	Broxtowe	Various	Q3	Southern Growth Corridor Broxtowe Bus Stop Infrastructure	keagan.cooke@viaem.co.uk

2017-2018 Capital Highways Works Programme

Budget Head	Budget Sub Category	Scheme Type	District	Ward	Estimated quarter Start On Site	Description	Contact
Integrated Transport Measures	Environmental Weight Limits	EWL Warning Signs	Countywide	Countywide	Complete	Countywide Advance EWL warning signs	jeffrey.burton@viaem.co.uk
Integrated Transport Measures	Speed Management	20mph advisory speed limits outside schools	Countywide	Countywide	Ongoing	Countywide 20mph advisory speed limits outside schools	alison.stuart@viaem.co.uk
Capital Maintenance	Bridge Maintenance	General bridge repairs	Countywide	Countywide	Ongoing till end of 17/18	Countywide General Bridges Repair Work	mike.hawkings@viaem.co.uk
Capital Maintenance	Bridge Maintenance	Specialist repairs	Countywide	Countywide	Q2	Countywide Minor Bridges Concrete Repairs	mike.hawkings@viaem.co.uk
Capital Maintenance	Bridge Maintenance	Underwater inspections	Countywide	Countywide	Q2	Countywide Bridges Underwater Inspections	mike.hawkings@viaem.co.uk
Capital Maintenance	Bridge Maintenance	Emergency Bridges Repairs	Countywide	Countywide	Ongoing till end of 17/18	Countywide Emergency Bridges Repairs	mike.hawkings@viaem.co.uk
Capital Maintenance	Bridge Maintenance	RoW Bridges Repairs	Countywide	Various	Ongoing till end of 17/18	Countywide Rights of Way Bridges Repairs	mike.hawkings@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Dropped Kerbs	Countywide	Various	Q4	Countywide Dropped Kerb Programme 17-18	helen.jones@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	RoW Signing improvements	Countywide	Various	Ongoing till end of 17/18	Countywide Rights of Way Signing Improvements 17-18	jane.baines@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	RoW Upgrades	Countywide	Various	Ongoing till end of 17/18	Countywide Rights of Way Upgrades 17-18	jane.baines@viaem.co.uk
Integrated Transport Measures	Environmental Weight limits	Countywide EWL Warning Signing	Countywide	Various	To be programmed	Countywide Advance Environmental Weight Limit Warning Signs	helen.north@viaem.co.uk
Integrated Transport Measures	Speed management	Countywide Interactive Speed Signs Programme	Countywide	Various	Q3	Countywide Interactive Speed Signs Programme 17-18	steve.marston@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Cycle Route* and appropriate cycling prohibition signing to deter cyclists from using the footway on	Countywide	Various	Q4	Countywide Local Destination Signing	helen.north@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Gedling	Arnold North	Q2	Bradman Gardens, Arnold	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Gedling	Arnold North	Q2	Cowdrey Gardens, Arnold	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Gedling	Arnold North	Q2	Graveney Gardens, Arnold	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Gedling	Arnold North	Q2	Sobers Gardens, Arnold	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Gedling	Arnold North	Q2	Trueman Gardens, Arnold	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Gedling	Arnold North	Q2	Wembley Road, Arnold	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Gedling	Arnold North	Q2	Cambridge Gardens, Woodthorpe	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Gedling	Arnold North	Q2	Fell Side, Woodthorpe	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Gedling	Arnold North	Q2	Glenside, Woodthorpe	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Gedling	Arnold North	To be programmed	Lambourne Gardens, Woodthorpe	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing / Micro Asphalt	Gedling	Arnold North	To be programmed	Walsingham Road, Woodthorpe	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Gedling	Arnold North	Q3	Weaverthorpe Road, Woodthorpe - From N° 46 to Whitby Crescent N°102	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Gedling	Arnold North	To be programmed	Welbeck Gardens, Woodthorpe - From N° 1 to N°9	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Gedling	Arnold North	To be programmed	Willerby Road, Woodthorpe	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Gedling	Arnold North	To be programmed	Woburn Rise, Woodthorpe	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Gedling	Arnold North	To be programmed	Woodford Road, Woodthorpe	paul.shacklock@viaem.co.uk
Capital Maintenance	Unclassified	Resurface	Gedling	Arnold North	Q2	Ramsey Drive, Arnold	paul.shacklock@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Gedling	Arnold North	Complete	Robinson Road (Area), Mapperley - Plains Road to Haywood Road	paul.shacklock@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Gedling	Arnold North	Q3	Weaverthorpe Road, Woodthorpe - From Whitby Crescent to o/s N°46 incl. Cul de Sac	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Footpath upgrade	Gedling	Arnold North	Q3	Arnold Footpath No.11 - Externally Funded - Churchmoor Lane	jane.baines@viaem.co.uk

2017-2018 Capital Highways Works Programme

Budget Head	Budget Sub Category	Scheme Type	District	Ward	Estimated quarter Start On Site	Description	Contact
Integrated Transport Measures	Safety Improvements	Speed Management	Gedling	Arnold North / Arnold South	Substantially Complete	A60 Mansfield Road, Arnold	george.peszynski@viaem.co.uk
Road Safety	HigCrash Reduction	Installation of Speed Cameras	Gedling	Arnold North / Arnold South	Substantially Complete	A60 Mansfield Road, Arnold - Between Oxclose Lane and Woodthorpe Drive	george.peszynski@viaem.co.uk
Major Projects	Gedling Access Road	Advanced Drainage Works in Country Park	Gedling	Arnold North / Carlton East	Q3	Gedling Access Road Advanced Drainage Works in Country Park	mike.hawkings@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Zebra Improvements	Gedling	Arnold South	Complete	A60 Mansfield Road, Woodthorpe - Adjacent to Marlborough Road	jeffrey.burton@viaem.co.uk
Capital Maintenance	B/C Roads	Resurfacing	Gedling	Arnold South / Carlton West	Q3	C166 Westdale Lane, Carlton	paul.shacklock@viaem.co.uk
Capital Maintenance	B/C Roads	Structural patching	Gedling	Calverton	Q3	C167 Main Street, Woodborough	paul.shacklock@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Gedling	Calverton	Q2	Waterhouse Lane, Gedling	antonio.biondi@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Gedling	Calverton	Complete	A614 Ollerton Road, Calverton - A614 Old Rufford Road (Between Whinbush Lane to Burnstump Hill)	paul.shacklock@viaem.co.uk
Capital Maintenance	Footways	Resurface	Gedling	Calverton	To be programmed	Sherbrooke Close, Calverton	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing	Gedling	Calverton	Q3	Bonner Lane, Calverton - At its bend towards Moor Lane (Adjacent to Springwater Farm)	steph.walford@viaem.co.uk
Integrated Transport Measures	Bus improvements	Section 106 Bus Stop Improvements	Gedling	Calverton	Q4	Spring Lane, Lambley Bus Stop Improvements - Adjacent to the junction of Dawlish Court to the new residential developments	jeffrey.burton@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Pedestrian Crossing	Gedling	Calverton	Q3	Main Street, Calverton	john.patchett@viaem.co.uk
Integrated Transport Measures	Bus Improvements	Pedestrian Crossing with additional High Friction Surfacing	Gedling	Carlton East	Complete	Southern Growth Corridor Pedestrian Crossing - Adjacent to its Junction of A612 Colwick Loop Road Vale Road	keagan.cooke@viaem.co.uk
Capital Maintenance	A-Roads PRN	Structural patching	Gedling	Carlton East	Q3	A612 Burton Road / Nottingham Road, Burton Joyce - Trent Valley Road junction to Burton Joyce	paul.shacklock@viaem.co.uk
Capital Maintenance	Footways	Slurry seal	Gedling	Carlton East	To be programmed	Willow Wong Estate, Burton Joyce	paul.shacklock@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Gedling	Carlton East	Complete	Padleys Lane, Burton Joyce - From Main Street to Foxhill Road	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Parking	TROs - Waiting restrictions	Gedling	Carlton East	Q4	Victoria Road, Netherfield	jeffrey.burton@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Pedestrian Crossing Improvements	Gedling	Carlton West	Complete	Southdale Road, Carlton - At its junction with B686 Carlton Hill	jeffrey.burton@viaem.co.uk
Integrated Transport Measures	Speed Management	Part of Countywide Interactive Speed Signs Programme 16/17	Gedling	Carlton West	Complete	Parkdale Road, Carlton - South West of Cliff Road	steve.marston@viaem.co.uk
Integrated Transport Measures	Speed Management	Part of Countywide Interactive Speed Signs Programme 16/17	Gedling	Carlton West	Complete	Southdale Road, Carlton - South West of Southlea Road	steve.marston@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Gedling	Carlton West	Q2	Church Street, Carlton	antonio.biondi@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Gedling	Carlton West	Q2	Mount Pleasant, Carlton	antonio.biondi@viaem.co.uk
Capital Maintenance	Traffic Signal Renewal	Traffic signal renewal	Gedling	Carlton West	Q3	Carlton Hill / Standhill Road, Carlton - At the pedestrian crossing	chris.ashton@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing and Lining	Gedling	Carlton West	Q4	Oakdale Road / Douglas Avenue, Carlton - Adjacent to its junction	jeffrey.burton@viaem.co.uk
Integrated Transport Measures	Safety improvements	Traffic Calming - Installation of Road Humps	Gedling	Carlton West	Q3	Standhill Road, Carlton	mike.elliott@viaem.co.uk
Capital Maintenance	B/C Roads	Structural patching	Gedling	Newstead	Q3	B6011 Main Street, Linby - From Quarry Lane to bend at The Spinnies	paul.shacklock@viaem.co.uk
Capital Maintenance	Structural Drainage	Drainage Improvements	Gedling	Newstead	Q4	Ravenshead Soakaways	mark.blackburn@viaem.co.uk
Capital Maintenance	Street Lighting	Ornate Replacements	Gedling	Various	Q2	Lambley / Woodborough Ornate Replacements	antonio.biondi@viaem.co.uk
Integrated Transport Measures	Bus improvements	Bus Stop Clearway Programme	Gedling	Various	Q3	Gedling Bus Stop Clearway Programme 17-18	jeffrey.burton@viaem.co.uk
Integrated Transport Measures	Bus improvements	Bus Stop Improvements with 30x Raised Kerbs with Footway Widening	Gedling	Various	On Site	Gedling Bus Stop Access Improvements	jeffrey.burton@viaem.co.uk
Capital Maintenance	Footways	Slurry Seal	Gedling	Various	To be Programmed	Gedling Slurry Sealing Programme 17-18	paul.shacklock@viaem.co.uk
Capital Maintenance	Structural Drainage	Drainage	Gedling	Various	Q4	Gedling Miscellaneous Structural Drainage 17-18	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Bus improvements	Bus Stop Infrastructure	Gedling	Various	Q3	Southern Growth Corridor Gedling Bus Stop Infrastructure	keagan.cooke@viaem.co.uk

2017-2018 Capital Highways Works Programme

Budget Head	Budget Sub Category	Scheme Type	District	Ward	Estimated quarter Start On Site	Description	Contact
Integrated Transport Measures	Bus improvements	TROs & Hotspot Management	Gedling	Various	Q3	Southern Growth Corridor TROs & Hotspot Management	keagan.cooke@viaem.co.uk
Integrated Transport Measures	Bus improvements	AVL TLP	Gedling	Various	Q3	Southern Growth Corridor Bus Priority Signals	keagan.cooke@viaem.co.uk
Integrated Transport Measures	Safety Improvements	Signing Works	Mansfield	Bildworth / Mansfield East	Substantially complete	A617 Rainworth roundabout - Northbound approach to the roundabout (Between A617 Millennium Way / Southwell Road West / B6020 Southwell Road East / A617 Fountindale Way East)	jeffrey.burton@viaem.co.uk
Capital Maintenance	A-Roads PRN	Resurfacing	Mansfield	Mansfield East	Q4	A6191 Southwell Road West, Mansfield - MARR island and inbound carriageway from Oakleaf island	richard.osborne@viaem.co.uk
Capital Maintenance	B/C Roads	Resurfacing	Mansfield	Mansfield East	Complete	B6030 Clipstone Road East, Forest Town - Approach to the roundabout	richard.osborne@viaem.co.uk
Capital Maintenance	Footways	Part of the Mansfield Slurry Sealing Programme	Mansfield	Mansfield East	Q2	Oakfield Close, Mansfield	richard.osborne@viaem.co.uk
Capital Maintenance	Footways	Part of the Mansfield Slurry Sealing Programme	Mansfield	Mansfield East	Q2	Pinewood Drive, Mansfield	richard.osborne@viaem.co.uk
Capital Maintenance	Footways	Part of the Mansfield Slurry Sealing Programme	Mansfield	Mansfield East	Q2	Pineview Close, Mansfield	richard.osborne@viaem.co.uk
Capital Maintenance	Structural Drainage	Drainage Improvements	Mansfield	Mansfield East	Q2	Clipstone Road West, Forest Town - Outside Forest Town Primary School	richard.osborne@viaem.co.uk
Integrated Transport Measures	Bus improvements	Bus stop access improvements	Mansfield	Mansfield East	Q3	A6191 Southwell Road West, Mansfield - Adjacent to Windor Road (Reindeer St Bus Stop)	adam.lakin@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing	Mansfield	Mansfield East	Q4	A6191 Southwell Road West / Big Barn Lane, Mansfield	dale.swain@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Mansfield	Mansfield North	Complete	Gladstone Street, Mansfield Woodhouse	richard.osborne@viaem.co.uk
Integrated Transport Measures	Safety Improvements	Lining improvements	Mansfield	Mansfield North	Substantially complete	Old Mill Lane, Mansfield - East of Hallam way	dale.swain@viaem.co.uk
Capital Maintenance	Footways	Joint maintenance on flagging	Mansfield	Mansfield North	Q2	High Street, Mansfield Woodhouse - Parkers Lane to Rose Lane	adam.lakin@viaem.co.uk
Capital Maintenance	Footways	Part of the Mansfield Slurry Sealing Programme	Mansfield	Mansfield North	Q2	Sandgate Avenue, Mansfield Woodhouse	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Mansfield	Mansfield North	Q2	Ashwood Close, Mansfield Woodhouse - Marples Avenue to end	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Mansfield	Mansfield North	Q2	Balmoral Close, Mansfield Woodhouse - Sandringham Road to end	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Mansfield	Mansfield North	Q2	Buckingham Close, Mansfield Woodhouse - Sandringham Road to end	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Mansfield	Mansfield North	Q2	Dennor Drive, Mansfield Woodhouse - Marples Avenue to end	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Mansfield	Mansfield North	Q2	Dingley Close, Mansfield Woodhouse - Dennor Drive to end	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Mansfield	Mansfield North	Q2	Dormy Close, Mansfield Woodhouse - Marples Avenue to end	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Mansfield	Mansfield North	Q2	Kensington Close, Mansfield Woodhouse - Sandringham Road to end	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Mansfield	Mansfield North	Q2	Leadale Crescent, Mansfield Woodhouse - Marples Avenue to Marples Avenue	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Mansfield	Mansfield North	Q2	Marples Avenue, Mansfield Woodhouse - A60 to Peafield Lane	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Mansfield	Mansfield North	Q2	Norfolk Court, Mansfield Woodhouse - Sandringham Road to end	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Mansfield	Mansfield North	Q2	Sandringham Road, Mansfield Woodhouse - A60 to Wheatfield Crescent	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Mansfield	Mansfield North	Q2	Welwyn Avenue, Mansfield Woodhouse - Marples Avenue to end	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Mansfield	Mansfield North	Q2	Wheatfield Crescent, Mansfield Woodhouse - Sandringham Road to Peafield Lane	richard.osborne@viaem.co.uk
Integrated Transport Measures	Safety improvements	Traffic Signal Modifications	Mansfield	Mansfield North	Complete	A6075 Debdale Lane / Sherwood Street / Priory Square, Mansfield Woodhouse	bob.roth@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing and Lining	Mansfield	Mansfield North	Q4	A6075 Welbeck Road, Mansfield Woodhouse - At Morrisons Entrance	helen.north@viaem.co.uk
Integrated Transport Measures	Safety improvements	Kerb line Amendments and Lining	Mansfield	Mansfield North	Q2	Wood Street, Mansfield - Vicinity of Westfield Lane	atul.patel@viaem.co.uk
Integrated Transport Measures	Capacity Improvements	Right Turn Facility at Traffic Signals	Mansfield	Mansfield North	Complete	Station Street, Mansfield Woodhouse	bob.roth@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing and Lining	Mansfield	Mansfield North / Mansfield South	Q4	A6117 Butt Lane / Church Lane, Mansfield Woodhouse	helen.north@viaem.co.uk

2017-2018 Capital Highways Works Programme

Budget Head	Budget Sub Category	Scheme Type	District	Ward	Estimated quarter Start On Site	Description	Contact
Capital Maintenance	Unclassified	Resurfacing	Mansfield	Mansfield South	Q2	Park Avenue, Mansfield	richard.osborne@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Pedestrian route improvements	Mansfield	Mansfield South	Complete	Toothill Lane, Mansfield - Entire Length	steve.marston@viaem.co.uk
Integrated Transport Measures	Safety Improvements	Signing Works	Mansfield	Mansfield South	To be programmed	A60 Nottingham Road / Cauldwell Road, Mansfield	helen.north@viaem.co.uk
Capital Maintenance	B/C Roads	Resurfacing	Mansfield	Mansfield South	Q2	C142 Littleworth, Mansfield	richard.osborne@viaem.co.uk
Capital Maintenance	Bridge Maintenance	Bearing and concrete repairs	Mansfield	Mansfield South	Q3	Pelham Street Footbridge, Mansfield	mike.hawkings@viaem.co.uk
Capital Maintenance	Footways	Part of the Mansfield Slurry Sealing Programme	Mansfield	Mansfield South	Q2	Pump Hollow Lane, Mansfield	richard.osborne@viaem.co.uk
Capital Maintenance	Footways	Part of the Mansfield Slurry Sealing Programme	Mansfield	Mansfield South	Q2	Robin Down Close, Mansfield	richard.osborne@viaem.co.uk
Capital Maintenance	Footways	Part of the Mansfield Slurry Sealing Programme	Mansfield	Mansfield South	Q2	Rutherford Avenue, Mansfield	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Mansfield	Mansfield South	Q2	Argyle Street, Mansfield - Carter Lane to Hall Street	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Mansfield	Mansfield South	Q2	Gordon Avenue, Mansfield - Carter Lane to Hall Street	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Mansfield	Mansfield South	Q2	Hall Street, Mansfield - Argyle Street to Eakring Road	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Mansfield	Mansfield South	Q2	Hamilton Street, Mansfield - Southwell Road West to Argyle Street	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Mansfield	Mansfield South	Q2	Methuen Avenue, Mansfield - Reindeer Street to end	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Mansfield	Mansfield South	Q2	Newmarket Street, Mansfield - Hall Street to Maltby Road	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Mansfield	Mansfield South	Q2	Reindeer Street, Mansfield - Southwell Road West to Gordon Avenue	richard.osborne@viaem.co.uk
Capital Maintenance	Surface Dressing	Micro Asphalt	Mansfield	Mansfield South	Q2	Smith Street, Mansfield - Eakring Road to Hall Street	richard.osborne@viaem.co.uk
Capital Maintenance	Traffic Signal Renewal	Traffic signal renewal	Mansfield	Mansfield South	Complete	Berry Hill Lane / Jenny Becketts Lane, Mansfield - At the pedestrian crossing	chris.ashton@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Mansfield	Mansfield South	Complete	Skerry Hill, Mansfield	richard.osborne@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing	Mansfield	Mansfield South	Q4	A6009 St Peters Way / A6191 Ratcliffe Gate, Mansfield	dale.swain@viaem.co.uk
Integrated Transport Measures	Safety improvements	Traffic Signal Modifications	Mansfield	Mansfield South	Q3	A6009 St Peters Way / Albert Street, Mansfield	bob.roth@viaem.co.uk
Capital Maintenance	Safety Fencing	Safety barriers	Mansfield	Mansfield South	Q3	Rock Valley, Mansfield	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Capacity Improvements	Traffic Signal Improvements	Mansfield	Mansfield South	Q3	A60 Nottingham Road / Baums Lane / Park Lane, Mansfield - At its Junction	bob.roth@viaem.co.uk
Integrated Transport Measures	Parking	Residents Parking Scheme	Mansfield	Mansfield South	Q4	St Margaret Street, Mansfield	helen.north@viaem.co.uk
Integrated Transport Measures	Safety improvements	Traffic Signal Modifications	Mansfield	Mansfield South / Sutton Central and East	Complete	A60 Nottingham Road / A617 MARR, Mansfield - At its junction with A617 Fountaindale Way West and Sherwood Way South, Sutton-in-Ashfield	bob.roth@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Mansfield	Mansfield West	Complete	A6075 Abbott Road, Mansfield - Westfield Lane to A617 Pleasley Hill Way	richard.osborne@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Mansfield	Mansfield West	Q2	Harrop White Road, Mansfield	richard.osborne@viaem.co.uk
Integrated Transport Measures	Capacity Improvements	Implementation of Box Junction	Mansfield	Mansfield West	Q4	A617 / A6191 Chesterfield Road North, Pleasleyhill - Adjacent to its junction of A617 Pleasley Hill Way	dale.swain@viaem.co.uk
Integrated Transport Measures	Safety improvements	Speed Management - Contribution	Mansfield	Mansfield West	Q3	A6009 Rosemary Street, Mansfield - Between Stockwell Gate and Chesterfield Road South	rob.driver@viaem.co.uk
Capital Maintenance	Safety Fencing	Safety barriers	Mansfield	Mansfield West	Q3	Water Lane, Pleasley	paul.shacklock@viaem.co.uk
Capital Maintenance	Bridge Maintenance	Principal inspections	Mansfield	Various	Ongoing till end of 17/18	Mansfield Bridges Principal Inspections	mike.hawkings@viaem.co.uk
Integrated Transport Measures	Bus improvements	Bus Stop Clearway Programme	Mansfield	Various	Q3	Mansfield Bus Stop Clearway Programme 17-18	dale.swain@viaem.co.uk
Integrated Transport Measures	Cycling and health	Strategic Cycle Route Improvements	Mansfield	Various	Q3	Mansfield Strategic Cycle Route Improvements	tom.boylan@viaem.co.uk
Capital Maintenance	Footways	Mansfield Slurry Sealing Programme	Mansfield	Various	Q2	Mansfield Slurry Sealing Programme 17-18	richard.osborne@viaem.co.uk

2017-2018 Capital Highways Works Programme

Budget Head	Budget Sub Category	Scheme Type	District	Ward	Estimated quarter Start On Site	Description	Contact
Capital Maintenance	Structural Drainage	Drainage	Mansfield	Various	Q2	Mansfield Miscellaneous Structural Drainage 17-18	richard.osborne@viaem.co.uk
Integrated Transport Measures	Safety Improvements	Zebra Improvements	Mansfield	Warsop	Complete - Awaiting for 1x	A60 Church Street, Market Warsop - Adjacent to River View	antonio.biondi@viaem.co.uk
Integrated Transport Measures	Safety Improvements	Zebra Improvements - Implement the Zebrite lighting	Mansfield	Warsop	To be programmed	B6035 Sherwood Street / High Street, Warsop - At the junction	antonio.biondi@viaem.co.uk
Capital Maintenance	B/C Roads	Surface Dressing and Drainage Improvements	Mansfield	Warsop	Q3	C6 Netherfield Lane, Meden Vale - Bends at Gleadthorpe Lodge and Grange	richard.osborne@viaem.co.uk
Integrated Transport Measures	Safety improvements	Street Lighting Upgrade	Mansfield	Warsop	Q3 / Q4	A60 Mansfield Road, Warsop - South of Market Warsop - Old Sookholme Lane to start of SON at Spion Kop	antonio.biondi@viaem.co.uk
Integrated Transport Measures	Speed management	Relocation Of 30mph Speed Limit	Mansfield	Warsop	Q4	B6031 Carter Lane, Warsop Vale - Near between Longster Lane to Mineral Railway Line	dale.swain@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Mansfield	Mansfield East	Q2	Pump Hollow Lane, Mansfield	antonio.biondi@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Mansfield	Mansfield North	Q2	Gordondale Road, Mansfield	antonio.biondi@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Mansfield	Mansfield South	On Site	Nottingham Road, Mansfield	antonio.biondi@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Mansfield	Mansfield South	Q2	Clifton Grove, Mansfield	antonio.biondi@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing and Lining	Newark and Sherwood	Balderton	Q4	Grange Lane, Cotham - Balderton Grange to Cotham Thorns	jeffrey.burton@viaem.co.uk
Integrated Transport Measures	Safety improvements	Junction Improvements - Junction Protection with Signing and Lining	Newark and Sherwood	Balderton	Q4	Main Street, Balderton	jeffrey.burton@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing and Lining	Newark and Sherwood	Balderton	Q4	B6326 Great North Road / Claypole Lane, Balderton	jeffrey.burton@viaem.co.uk
Capital Maintenance	Structural Drainage	Renewal of soakaways	Newark and Sherwood	Blidworth	Complete	Holmwood Road, Rainworth	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Blidworth	Q2	Cambridge Close, Rainworth	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Blidworth	Q2	Cambridge Road, Rainworth	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Blidworth	To be programmed	Coopers Rise, Rainworth	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Blidworth	Q2	Eaton Close, Rainworth	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Blidworth	Q2	Harrow Close, Rainworth	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Blidworth	Q2	Oxford Close, Rainworth	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Blidworth	Q2	Preston Road, Rainworth	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Blidworth	Q2	Rochester Road, Rainworth	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Blidworth	Q2	Rugby Road, Rainworth	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Blidworth	Q2	Station Road, Rainworth	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Blidworth	Q2	Tudor Crescent, Rainworth	peter.topliss@viaem.co.uk
Integrated Transport Measures	Safety improvements	Lining	Newark and Sherwood	Blidworth	Q4	B6020 Warsop Lane / Mansfield Road, Blidworth - At its junction with Blidworth Lane	dale.swain@viaem.co.uk
Capital Maintenance	Footways		Newark and Sherwood	Collingham	On Site	Woodlands, Winthorpe - Whole length	peter.topliss@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Newark and Sherwood	Collingham	Substantially complete	Derwent Way Area, Newark-on-Trent - included Trent Way / Witham Close / Welland Close	antonio.biondi@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Newark and Sherwood	Collingham	Substantially complete	Wolsey Road Area, Newark-on-Trent - Included Stephen Road / Markham Avenue / Hatchets Lane	antonio.biondi@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Collingham	Complete	A1133 High Street, Collingham	peter.topliss@viaem.co.uk
Integrated Transport Measures	Bus improvements	Hotspot management	Newark and Sherwood	Collingham	Q4	Newark Hotspot Management - Brownlows Hill, Coddington / Alexander Avenue, Newark-on-Trent / Morgans Close, Coddington	jeffrey.burton@viaem.co.uk
Integrated Transport Measures	Parking	Amendments to Residents Parking Scheme	Newark and Sherwood	Collingham	Q4	Lincoln Street, Newark-on-Trent	jeffrey.burton@viaem.co.uk
Integrated Transport Measures	Speed management	Installation of Flashing Amber Warning Lights (FAWLs)	Newark and Sherwood	Collingham	Q4	Coddington Primary School FAWLs - Outside School at Brownlows Hill	alison.stuart@viaem.co.uk

2017-2018 Capital Highways Works Programme

Budget Head	Budget Sub Category	Scheme Type	District	Ward	Estimated quarter Start On Site	Description	Contact
Capital Maintenance	A-Roads PRN	Resurfacing / patching	Newark and Sherwood	Farndon and Trent	Q3	A617 Kelham Road, Kelham - From bridge to junction with Home Farm Close	peter.topliss@viaem.co.uk
Capital Maintenance	B/C Roads	Resurfacing	Newark and Sherwood	Farndon and Trent	Complete	C17 Staythorpe Road / Fiskerton Road, Rolleston - From 30 mph to 30 mph limits	peter.topliss@viaem.co.uk
Capital Maintenance	Street Lighting		Newark and Sherwood	Farndon and Trent	Q2	Averham Village Street Lighting - Various in village	antonio.biondi@viaem.co.uk
Capital Maintenance	Structural Drainage	New system required	Newark and Sherwood	Farndon and Trent	Q3	Village Way, Farndon	peter.topliss@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Newark and Sherwood	Farndon and Trent	Complete	Brockton Avenue, Farndon - Whole Length	peter.topliss@viaem.co.uk
Integrated Transport Measures	Parking	Residents Parking Scheme	Newark and Sherwood	Farndon and Trent	Q4	B6166 Victoria Street, Newark-on-Trent	jeffrey.burton@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Dropped kerbs and build out	Newark and Sherwood	Muskham and Farnsfield	Q3	Main Street and Far Back Lane, Farnsfield	cathy.gillespie@viaem.co.uk
Capital Maintenance	B/C Roads	Resurfacing	Newark and Sherwood	Muskham and Farnsfield	Q3	C49 Kirklington Road, Bilsthorpe - Copper beech to Roundabout	peter.topliss@viaem.co.uk
Capital Maintenance	Bridge Maintenance	Parapet repairs	Newark and Sherwood	Muskham and Farnsfield	Q3	South Muskham River Bridge	mike.hawkings@viaem.co.uk
Capital Maintenance	Bridge Maintenance	Concrete repairs	Newark and Sherwood	Muskham and Farnsfield	Q4	North Muskham Railway Bridge - Bridge B1325	mike.hawkings@viaem.co.uk
Capital Maintenance	Bridge Maintenance	Waterproofing	Newark and Sherwood	Muskham and Farnsfield	Q2	C49 Eakring Road Bridge, Bilsthorpe - Bridge B3429	mike.hawkings@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Newark and Sherwood	Muskham and Farnsfield	To be programmed	East Stoke (Old A46)	antonio.biondi@viaem.co.uk
Capital Maintenance	Structural Drainage	Renewal of soakaways	Newark and Sherwood	Muskham and Farnsfield	Q3	Church Street, Sutton-on-Trent	peter.topliss@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing and Lining	Newark and Sherwood	Muskham and Farnsfield	Q3	A617 Main Street / Hockerton Road, Kirklington - East of Kirklington	jeffrey.burton@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Newark and Sherwood	Newark East	To be programmed	Whitfield Street, Newark-on-Trent	antonio.biondi@viaem.co.uk
Integrated Transport Measures	Parking	Residents Parking Scheme	Newark and Sherwood	Newark East	Q3	Barnby Gate, Newark-on-Trent	jeffrey.burton@viaem.co.uk
Capital Maintenance	B/C Roads	Resurfacing	Newark and Sherwood	Newark East	Q2	C3 Bowbridge Road, Newark-on-Trent - From Carlton Road to Earp Avenue	peter.topliss@viaem.co.uk
Integrated Transport Measures	Capacity Improvements	Traffic Signals Improvements	Newark and Sherwood	Newark East / Collingham	To be programmed	Beacon Hill Road / Northern Road, Newark-on-Trent - At its Junction	bob.roth@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Pedestrian crossing facilities	Newark and Sherwood	Newark East / Newark West	To be programmed	Barnby Gate / Sherwood Avenue, Newark-on-Trent	bob.roth@viaem.co.uk
Capital Maintenance	Bridge Maintenance	Masonry and fender repairs	Newark and Sherwood	Newark West	Q3	Newark-on-Trent Town Bridge	mike.hawkings@viaem.co.uk
Capital Maintenance	Footways		Newark and Sherwood	Newark West	Q2	Woodlands Close, Newark-on-Trent - Whole length	peter.topliss@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Newark and Sherwood	Newark West	On Site	Milner Street, Newark-on-Trent - Whole Length	peter.topliss@viaem.co.uk
Integrated Transport Measures	Parking	Residents Parking Scheme	Newark and Sherwood	Newark West	Q4	Earp Avenue, Newark-on-Trent	jeffrey.burton@viaem.co.uk
Integrated Transport Measures	Bus Improvements	Bus Stop Improvements	Newark and Sherwood	Ollerton	Q3	Whinney Lane, Ollerton	steve.marston@viaem.co.uk
Capital Maintenance	A-Roads PRN	Resurfacing	Newark and Sherwood	Ollerton	Q3	A614 Ollerton Roundabout - Roundabout and exits only	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Ollerton	Complete	C57 Newark Road, Boughton - Poplar Street to A616	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Ollerton	Q2	Birklands Avenue, Ollerton	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Ollerton	Q2	Breck Bank Crescent, Ollerton	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Ollerton	Q2	Breck Bank, Ollerton	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Ollerton	Q2	Cedar Lane, Ollerton	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Ollerton	Q2	Chestnut Drive, Ollerton	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Ollerton	Q2	Church Circle, Ollerton	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Ollerton	Q2	Holly Rise, Ollerton	peter.topliss@viaem.co.uk

2017-2018 Capital Highways Works Programme

Budget Head	Budget Sub Category	Scheme Type	District	Ward	Estimated quarter Start On Site	Description	Contact
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Ollerton	Q2	Lansbury Avenue, Ollerton	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Ollerton	Q2	Larch Road, Ollerton	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Ollerton	Q2	Lime Tree Road, Ollerton	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Ollerton	Q2	Petersmith Crescent, Ollerton	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Ollerton	Q2	Petersmith Drive, Ollerton	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Ollerton	Q2	Whitewater Road, Ollerton	peter.topliss@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Ollerton	Complete	A614 Blyth Road, Perlethorpe - Bothamsall roundabout to Whitewater Lane	peter.topliss@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Newark and Sherwood	Ollerton	Q2	Beech Avenue, Ollerton - Whole Length	peter.topliss@viaem.co.uk
Integrated Transport Measures	Bus improvements	Hotspot management	Newark and Sherwood	Ollerton	Q4	Ollerton Hotspot Management - Briar Road / Church Circle	dale.swain@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Newark and Sherwood	Sherwood Forest	Complete	Forest Road, Clipstone - District boundary to Sixth Avenue	peter.topliss@viaem.co.uk
Integrated Transport Measures	Capacity Improvements	Right Turn Facility at Crossroads	Newark and Sherwood	Sherwood Forest	Complete	A6075 Mansfield Road, Edwinstowe - At Crossroads towards High Street	bob.roth@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Newark and Sherwood	Southwell	Q2	Bridle Road, Halloughton	peter.topliss@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing and Lining - with Carriageway edge lines and reflective road studs	Newark and Sherwood	Southwell	Q4	B6386 Southwell Road, Oxtou - Southwest of Blind Lane (Bend at Old Hall Nurseries)	jeffrey.burton@viaem.co.uk
Integrated Transport Measures	Speed management	Speed Limit Reduction To 50mph	Newark and Sherwood	Southwell	Q4	A612 Nottingham Road, Southwell to Thurgarton - Between the Hollows, Thurgarton to Park Lane, Southwell	jeffrey.burton@viaem.co.uk
Integrated Transport Measures	Speed management	Speed Limit Reduction To 50mph	Newark and Sherwood	Southwell	Q4	B6386 Epperstone Road / Southwell Road / Oxtou Hill / Oxtou Road, Oxtou to Southwell - Between A6097 Oxtou Bye Pass to Cooks Lane	jeffrey.burton@viaem.co.uk
Capital Maintenance	Safety Fencing	Safety barrier investigation works	Newark and Sherwood	Southwell	Q3	A617 Spring Wood bends, Upton	paul.shacklock@viaem.co.uk
Capital Maintenance	Bridge Maintenance	Principal inspections	Newark and Sherwood	Various	Ongoing till end of 17/18	Newark Bridges Principal Inspections	mike.hawkings@viaem.co.uk
Integrated Transport Measures	Bus improvements	Bus Stop Clearway Programme	Newark and Sherwood	Various	Q4	Newark & Sherwood Bus Stop Clearway Programme 17-18	jeffrey.burton@viaem.co.uk
Integrated Transport Measures	Cycling and health	Strategic Cycle Route Improvements	Newark and Sherwood	Various	Q3	Newark Strategic Cycle Route Improvements	tom.boylan@viaem.co.uk
Capital Maintenance	Footways	Slurry Seal	Newark and Sherwood	Various	Q2	Newark Slurry Sealing Programme 17-18	peter.topliss@viaem.co.uk
Capital Maintenance	Structural Drainage	Drainage	Newark and Sherwood	Various	Q3	Newark and Sherwood Miscellaneous Structural Drainage 17-18	peter.topliss@viaem.co.uk
Capital Maintenance	Salix Grant	Lantern Replacement	Newark and Sherwood	Various	Ongoing	Salix Newark & Sherwood Lantern Replacement	clare.murden@viaem.co.uk
Capital Maintenance	Safety Fencing	Safety barriers	Rushcliffe	Bingham / Radcliffe on Trent	Q3	A6097 Margidvnm Island, Bingham	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Pedestrian improvements - Footway widening and One Way system	Rushcliffe	Bingham East	Q4	Union Street, Bingham - Carried over from 16/17 - Between Sainsbury's yard access and Market Street	rob.driver@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	Bingham East	Complete	C3 Sutton Lane, Elton on the Hill - From the A52 to C55 Redmile Road	paul.shacklock@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Rushcliffe	Bingham East	Q3	Lombard Street, Orston	paul.shacklock@viaem.co.uk
Capital Maintenance	B/C Roads	Structural patching	Rushcliffe	Bingham West	Q2	C18 Kinoulton Road, Cropwell Bishop - From Cropwell village to Colston Road	paul.shacklock@viaem.co.uk
Capital Maintenance	B/C Roads	Patching for Surface Dressing (A.I.U)	Rushcliffe	Bingham West	Q4	C28 Bingham Road, Langar - A52 to Langar	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Safety Improvements	Surface Upgrade - Contribution to Maintenance Scheme	Rushcliffe	Cotgrave	Complete in 16/17	Hollygate Lane, Cotgrave - 280m South West of Stragglethorpe Road, Stragglethorpe	peter.topliss@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Rushcliffe	Cotgrave	Q2	Stella Avenue, Tollerton	antonio.biondi@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Rushcliffe	Cotgrave	Q3	Woodview, Cotgrave - From Ring Leas to Lingford	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Safety Improvements	Installation of YB Warning Signs and new slow markings with refresh centre line and edge line	Rushcliffe	Keyworth	To be programmed	Bradmore Lane, Plumtree - Through Blackcliffe Hill (Crest and Bend)	paul.shacklock@viaem.co.uk
Capital Maintenance	Bridge Maintenance	Culvert reconstruction	Rushcliffe	Keyworth	Q2	Roehoe Culvert on Melton Road, Widmerpool	ian.hamilton@viaem.co.uk

2017-2018 Capital Highways Works Programme

Budget Head	Budget Sub Category	Scheme Type	District	Ward	Estimated quarter Start On Site	Description	Contact
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	Keyworth	Complete	A606 Melton Road, Stanton on the Wolds - From Laming Gap Lane to surface change at 40 mph signs	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	Keyworth	Complete	A606 Melton Road, Stanton on the Wolds - From Browns Lane to just past Station Road	paul.shacklock@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Rushcliffe	Keyworth	Q3	The Square, Keyworth - From Main Road to Blind Lane	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Safety improvements	Traffic Signal Modifications - To reduce right turn accidents	Rushcliffe	Keyworth / Cotgrave	Q3	A606 Melton Road / Tollerton Lane, Tollerton - At its traffic signals junction	chris.gough@viaem.co.uk
Capital Maintenance	B/C Roads	Resurfacing	Rushcliffe	Leake and Ruddington	Q3	C47 Main Street Normanton on Soar - PH to bend past school	paul.shacklock@viaem.co.uk
Capital Maintenance	B/C Roads	Resurfacing / Structural patching	Rushcliffe	Leake and Ruddington	Q3	C47 Stanford Road / Normanton Lane, Normanton-on-Soar - Stanford to Normanton-on-Soar (Sections within this overall length)	paul.shacklock@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Rushcliffe	Leake and Ruddington	On Site	Kirk Lane, Ruddington	antonio.biondi@viaem.co.uk
Integrated Transport Measures	Safety Improvements	Stick chevrons installation	Rushcliffe	Leake and Ruddington	Complete	C51 West Leake Lane, Radcliffe-on-Soar - Bend adjacent to Winking Hill	cathy.gillespie@viaem.co.uk
Capital Maintenance	B/C Roads	In Lay surfacing	Rushcliffe	Leake and Ruddington	Q3	C48 Leake Road, Gotham (Ridgeway) - From Gypsum Way to Bunny Lane	paul.shacklock@viaem.co.uk
Capital Maintenance	B/C Roads	Haunching / structural surfacing	Rushcliffe	Leake and Ruddington	Q3	C51 West Leake Lane, Kingston-on-Soar - Bend at Winking Hill	paul.shacklock@viaem.co.uk
Capital Maintenance	Footways	Pre patch and slurry seal	Rushcliffe	Leake and Ruddington	Q4	Woodgate Road, East Leake	paul.shacklock@viaem.co.uk
Capital Maintenance	Footways	Resurface	Rushcliffe	Leake and Ruddington	Q4	Castle Hill, East Leake - Brickley Crescent to edge of built up area	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing and Lining	Rushcliffe	Leake and Ruddington	Q4	Gotham Road / West Leake Lane, Kingston-on-Soar - At its crossroads	steph.walford@viaem.co.uk
Integrated Transport Measures	Safety improvements	Signing	Rushcliffe	Leake and Ruddington	Q3	Melton Lane, Sutton Bonington - Between College Road to Brickyard Lane	steph.walford@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Zebra crossing	Rushcliffe	Radcliffe on Trent	Q3	Shelford Road, Radcliffe-on-Trent - Adjacent to its roundabout with Main Road and Hunt Close	steve.marston@viaem.co.uk
Integrated Transport Measures	Bus improvements	Bus Stop Clearway Programme	Rushcliffe	Radcliffe on Trent	Q4	Rushcliffe Bus Stop Clearway Programme 17-18 - Adbolton Lane, Holme Pierrepont	steph.walford@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Pedestrian Crossing	Rushcliffe	Radcliffe on Trent	Q3	Main Road, Radcliffe-on-Trent	helen.north@viaem.co.uk
Integrated Transport Measures	Bus improvements	Raised Kerb and Kerb Extension	Rushcliffe	Radcliffe on Trent / West Bridgford West	Q3	Rushcliffe Bus Stop Access Improvements	helen.north@viaem.co.uk
Capital Maintenance	Bridge Maintenance	Principal inspections	Rushcliffe	Various	Ongoing till end of 17/18	Rushcliffe Bridges Principal Inspections	mike.hawkings@viaem.co.uk
Integrated Transport Measures	Bus Improvements	Bus Stop Clearways	Rushcliffe	Various	Complete	Rushcliffe TROs and Bus Stop Clearways	ann.leigh-browne@viaem.co.uk
Integrated Transport Measures	Cycling and Health	Strategic Cycle Route Improvements	Rushcliffe	Various	On Site	West Bridgford Strategic Cycle Route improvements	mike.elliott@viaem.co.uk
Capital Maintenance	Footways	Slurry Seal	Rushcliffe	Various	To be Programmed	Rushcliffe Slurry Sealing Programme 17-18	paul.shacklock@viaem.co.uk
Capital Maintenance	Structural Drainage	Drainage	Rushcliffe	Various	Q4	Rushcliffe Miscellaneous Structural Drainage 17-18	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Safety Improvements	Surface upgrade	Rushcliffe	West Bridgford North	To be programmed	A6011 Radcliffe Road / Davies Road, West Bridgford - Adjacent to the junction	paul.shacklock@viaem.co.uk
Capital Maintenance	A-Roads PRN	Structural patching	Rushcliffe	West Bridgford North	Q3	A6011 Radcliffe Road, West Bridgford - From Lady Bay bridge to Davies Road	paul.shacklock@viaem.co.uk
Capital Maintenance	Street Lighting	Lighting Column Replacement	Rushcliffe	West Bridgford North	Q2	Lady Bay Bridge, West Bridgford	antonio.biondi@viaem.co.uk
Capital Maintenance	Street Lighting	Street Lighting Improvements	Rushcliffe	West Bridgford North	Q2	Sandringham Avenue, West Bridgford	antonio.biondi@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	Q2	Adbolton Grove, Lady Bay	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	Q2	Belvoir Road, Lady Bay	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	Q2	Chatsworth Road, Lady Bay	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	Q2	Fleeman Grove, Lady Bay	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	Q2	Gertrude Road, Lady Bay	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	Q2	Holme Grove, Lady Bay	paul.shacklock@viaem.co.uk

2017-2018 Capital Highways Works Programme							
Budget Head	Budget Sub Category	Scheme Type	District	Ward	Estimated quarter Start On Site	Description	Contact
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	Q2	Holme Road, Lady Bay - From o/s N°88 to Adbolton Grove	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	Q2	Julian Road, Lady Bay	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	Q2	Lady Bay Road, Lady Bay	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	Q2	Melbourne Road, Lady Bay	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	To be programmed	Mona Road, Lady Bay - North section from Holme Road to Trent Boulevard	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	Q2	Moore Close, Lady Bay	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	Q2	Oakfields Road, Lady Bay	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	Q2	Pierrepoint Road, Lady Bay	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	Q2	Ropsley Crescent, Lady Bay	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	Q2	Rutland Road, Lady Bay	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	Q2	Seymour Road, Lady Bay	paul.shacklock@viaem.co.uk
Capital Maintenance	Surface Dressing	Surface Dressing	Rushcliffe	West Bridgford North	Q2	Woodland Road, Lady Bay	paul.shacklock@viaem.co.uk
Capital Maintenance	Unclassified	Micro Asphalt	Rushcliffe	West Bridgford North	To be programmed	Mona Road, Lady Bay - South section from Trent Boulevard to Oak Tree Close	paul.shacklock@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Rushcliffe	West Bridgford North	To be programmed	Rutland Road, Lady Bay - Link section to Radcliffe Road including junction	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Parking	Strategic parking review - Phase 1	Rushcliffe	West Bridgford North	Q4	West Bridgford Strategic Parking Review	steph.walford@viaem.co.uk
Integrated Transport Measures	Safety improvements	Street Lighting Upgrade	Rushcliffe	West Bridgford North	Q3 / Q4	Trent Boulevard, West Bridgford	antonio.biondi@viaem.co.uk
Integrated Transport Measures	Bus improvements	Section 106 Bus Stop Improvements - Installation of Raised Boarding Kerbs	Rushcliffe	West Bridgford North	Q3	Radcliffe Road, West Bridgford Bus Stop Improvements - A6011 Radcliffe Road, West Bridgford (Adjacent to Trevelyan Road)	helen.north@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Traffic Signals Improvements - MOVA	Rushcliffe	West Bridgford North	Q2	A6011 Radcliffe Road / Mabel Grove / Rutland Road, West Bridgford	chris.gough@viaem.co.uk
Integrated Transport Measures	Speed Management	Part of Countywide Interactive Speed Signs Programme 16/17	Rushcliffe	West Bridgford South	Complete	A606 Melton Road, West Bridgford - North West of Burleigh Road	steve.marston@viaem.co.uk
Capital Maintenance	Traffic Signal Renewal	Traffic signal renewal	Rushcliffe	West Bridgford West	Q3	A60 Loughborough Road, West Bridgford - At the main access to County Hall	chris.ashton@viaem.co.uk
Integrated Transport Measures	Bus improvements	Raised Kerb	Rushcliffe	West Bridgford West	Q3	Queensbury Avenue, West Bridgford - Bus Stop Queensbury Avenue (Adjacent to Greythorn Drive)	helen.north@viaem.co.uk
Capital Maintenance	Unclassified	Resurfacing	Rushcliffe	West Bridgford West	Q3	Queensbury Avenue / Stanhome Square, West Bridgford	paul.shacklock@viaem.co.uk
Integrated Transport Measures	Access to Local Facilities	Contribution to Toucan Crossing	Rushcliffe	West Bridgford West	To be programmed	A60 Loughborough Road, West Bridgford	chris.gough@viaem.co.uk
Capital Maintenance	Street Lighting	Street Lighting Improvements	Rushcliffe	West Bridgford West	Substantially complete	Branston Gardens, West Bridgford	antonio.biondi@viaem.co.uk
Capital Maintenance	Street Lighting	Street Lighting Improvements	Rushcliffe	West Bridgford West	Q2	Lyndhurst Gardens, West Bridgford	antonio.biondi@viaem.co.uk
Capital Maintenance	Street Lighting	Street Lighting Improvements	Rushcliffe	West Bridgford West	Q2	Fairland Crescent, West Bridgford	antonio.biondi@viaem.co.uk
Capital Maintenance	Street Lighting	Street Lighting Improvements	Rushcliffe	West Bridgford West	Q2	Melrose Gardens, West Bridgford	antonio.biondi@viaem.co.uk