

Effective: 01/04/2017 to 01/04/2018

Feature No.: 2000.00 to 2005.00

Display Action Officer: No

Street: Cotgrave Road (33022091)

Street: Cotgrave Road (33022091)

Locality: Normanton on the Wolds, Nottinghamshire

Area: Rushcliffe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: From Melton Road junction to Cotgrave Road, Tollerton.			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20274158 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Mar Saf CW				Date: 22/03/2018
Batch: 20274111 - Inspection Batch				Route: Adhoc Inspection				Date: 22/03/2018
3572319	HWIA - Numerous defects either side of the Carriageway require making safe - unable to mark up due to rainfall. Online report (Enquiry 6087646)	22/03/2018	Leaving Cotgrave and full length of Carriageway towards the Traffic Lights at Plumtree .	CW Repairs-Bituminous	Internal		Committed	2675326
Batch: 20271924 - Inspection Batch				Route: Adhoc Inspection				Date: 09/03/2018
3570503	CW overlay - Section requires overlaying with Hot Bitmac has viafix is no longer an option - defect is marked up.	09/03/2018	Directly on the small Bridge over the stream near house called Havenbrook in the direction of Plumtree Traffic lights	CW Repairs-Bituminous	Internal		Committed	2673487
Batch: 20268559 - Inspection Batch				Route: Adhoc Inspection				Date: 16/02/2018
3568201	Carriageway defect has been made safe during inspection.	16/02/2018	It's just before the bend as approach the newish bungalow heading towards Tollerton	CW Repairs-Bituminous	Internal		Uncommitt	2671157
Batch: 20267019 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Feb Enh CW/FW				Date: 06/02/2018
Batch: 20266072 - Inspection Batch				Route: Adhoc Inspection				Date: 01/02/2018
3566463	Carriageway defects made safe during inspection.	01/02/2018	On the approach to the bend near the new bungalow (Hoe Hill House) on the left hand side of road heading towards Cotgrave	CW Repairs-Bituminous	Internal		Uncommitt	2669412
Batch: 20265560 - Inspection Batch				Route: Adhoc Inspection				Date: 29/01/2018
3566124	HWIA - (Operations not an option) .Cycle Club are complaining with pot holes/cracks/crevasses along this section and defects are marked up and Traffic cone in place on grass verge to indicate the start.Recommend mid day as section gets busy first & last thing .(Enquiry 6078584)	29/01/2018	Stretch of Cotgrave Road going towards Plumtree Traffic lights just past the Chevrons & Hoe Hill House and no further than left hand turn for Clipston Lane.	CW Repairs-Bituminous	Internal		Committed	2669067
Batch: 20264866 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Jan Saf CW				Date: 25/01/2018
Batch: 20264245 - Inspection Batch				Route: Adhoc Inspection				Date: 23/01/2018
3565208	Carriageway defects have been made safe.	23/01/2018	Outside Hoe Hill House in the direction Cotgrave .	CW Repairs-Bituminous	Internal		Uncommitt	2668133

Effective: 01/04/2017 to 01/04/2018

Display Action Officer: No

Feature No.: 2000.00 to 2005.00

Street: Cotgrave Road (33022091)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: From Melton Road junction to Cotgrave Road, Tollerton.			Feature Type: Street Section		Area: Rushcliffe		
Batch: 20262164 - Inspection Batch				Route: Adhoc Inspection		Date: 10/01/2018		
3563527	HWIA - Wearing course erosion at given location requires making safe - markings may have faded due to rainfall so if require info ring Gaz 07753625684 (Enquiry 6075659)	10/01/2018	Starting from just past Hoe Hill Farm and no further than Clipston Lane / Plumtree Traffic lights	CW Repairs-Bituminous	Internal		Committed	2666424
Batch: 20258483 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Dec Saf CW		Date: 08/12/2017		
Batch: 20255534 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Nov Saf CW		Date: 20/11/2017		
Batch: 20253653 - Inspection Batch	No actionable defects found			Route: Review Outcome-Pete Moncaster		Date: 07/11/2017		
Batch: 20250817 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Oct Saf CW		Date: 19/10/2017		
Batch: 20246577 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Sep Saf CW		Date: 20/09/2017		
Batch: 20243111 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Aug Saf CW		Date: 25/08/2017		
Batch: 20238151 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Jul Saf CW		Date: 17/07/2017		
Batch: 20235654 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Jun Saf CW		Date: 26/06/2017		
Batch: 20230853 - Inspection Batch	No actionable defects found			Route: Rush Area 2 May Saf CW		Date: 22/05/2017		
3548903	Defects made safe during inspection	22/05/2017	L / H / S just past Hoe Hill Farm	CW Repairs-Bituminous	Internal		Uncommitt	2650862
Batch: 20225755 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Apr Saf CW		Date: 20/04/2017		

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 2,000.00	Feature Id - Locn.: From Melton Road junction to Cotgrave Road, Tollerton.			Feature Type: Street Section		Area: Rushcliffe	
2650862	Defects made safe during inspection (CW Repairs-Bituminous)	L / H / S just past Hoe Hill Farm	Filled when found (Cat 2H)	Job Completed	22/05/2017	22/05/2017	Act.
2666424	HWIA - Wearing course erosion at given location requires making safe - markings may have faded due to rainfall so if require info ring Gaz 07753625684 (Enquiry 6075659) (CW Repairs-Bituminous)	Starting from just past Hoe Hill Farm and no further than Clipston Lane / Plumtree Traffic lights	Category 2 (High)	Job Completed	10/01/2018	28/02/2018	Act. RUS-AS/5600907

Effective: 01/04/2017 to 01/04/2018

Feature No.: 2000.00 to 2005.00

Display Action Officer: No

Street: Cotgrave Road (33022091)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: From Melton Road junction to Cotgrave Road, Tollerton.		Feature Type: Street Section		Area: Rushcliffe	
2668133	Carriageway defects have been made safe. (CW Repairs-Bituminous)	Outside Hoe Hill House in the direction Cotgrave .	Filled when found (Cat 2H)	Job Completed	24/01/2018	24/01/2018	Act.
2669067	HWIA - (Operations not an option) .Cycle Club are complaining with pot holes/cracks/crevasses along this section and defects are marked up and Traffic cone in place on grass verge to indicate the start.Recommend mid day as section gets busy first & last thing .(Enquiry 6078584) (CW Repairs-Bituminous)	Stretch of Cotgrave Road going towards Plumtree Traffic lights just past the Chevrons & Hoe Hill House and no further than left hand turn for Clipston Lane.	Category 1	Job Completed	30/01/2018	31/01/2018	Act. RUS-AS/5600923
2669412	Carriageway defects made safe during inspection. (CW Repairs-Bituminous)	On the approach to the bend near the new bungalow (Hoe Hill House) on the left hand side of road heading towards Cotgrave	Filled when found (Cat 2H)	Job Completed	01/02/2018	01/02/2018	Act.
2671157	Carriageway defect has been made safe during inspection. (CW Repairs-Bituminous)	It's just before the bend as approach the newish bungalow heading towards Tollerton	Filled when found (Cat 2H)	Job Completed	16/02/2018	16/02/2018	Act.
2673487	CW overlay - Section requires overlaying with Hot Bitmac has viafix is no longer an option - defect is marked up. (CW Repairs-Bituminous)	Directly on the small Bridge over the stream near house called Havenbrook in the direction of Plumtree Traffic lights	Category 1	Job Completed	09/03/2018	13/03/2018	Act. RUSH/3703204
2675326	HWIA - Numerous defects either side of the Carriageway require making safe - unable to mark up due to rainfall. Online report (Enquiry 6087646) (CW Repairs-Bituminous)	Leaving Cotgrave and full length of Carriageway towards the Traffic Lights at Plumtree .	Category 2 (High)	Job Completed	22/03/2018	28/03/2018	Act. RUS-AS/5600989