

Effective: 01/04/2017 to 01/04/2018

Feature No.: 2000.00 to 2005.00

Display Action Officer: No

Street: Tollerton Lane (33002304)

Street: Tollerton Lane (33002304)

Locality: Gamston, Nottinghamshire

Area: Rushcliffe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.:			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20274123 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Mar Saf CW				Date: 22/03/2018
Batch: 20272420 - Inspection Batch				Route: Adhoc Inspection				Date: 14/03/2018
3570969	CW overlay - Section of Carriageway has been overlaid recently however this section has eroded since then and requires overlaying - defect is marked up.	14/03/2018	Just past Bassingfield Lane & the Canal crossing point adjacent with speed sign & farmers gate in the direction of Tollerton L / H / S.	CW Repairs-Bituminous	Internal		Committed	2673958
Batch: 20272020 - Inspection Batch				Route: Adhoc Inspection				Date: 12/03/2018
3570587	CW two course patch .Wearing course erosion to the side of Carriageway requires JCB plane out 1 x 35 metres and relay base course / wearing course back to existing Carriageway level.Be advised Two Way traffic lights will be required and defect marked up during inspection.	12/03/2018	Just past the Wooden shelter & Property called Canine Academy on the Brow of the incline S bend in the direction of Gamston.	CW Repairs-Bituminous	Internal		Committed	2673573
Batch: 20272016 - Inspection Batch				Route: Adhoc Inspection				Date: 12/03/2018
3570583	Carriageway defect has been made safe.	12/03/2018	Just the last property on the left called Canine Academy City inbound side.	CW Repairs-Bituminous	Internal		Uncommitt	2673569
Batch: 20268578 - Inspection Batch				Route: Adhoc Inspection				Date: 16/02/2018
3568221	4 patches as marked out photos added	16/02/2018	just after canal bridge as marked out	CW Repairs-Bituminous	Internal		Committed	2671178
Batch: 20268575 - Inspection Batch				Route: Adhoc Inspection				Date: 16/02/2018
3568218	filled when found	16/02/2018	along tollerton lane as marked filled when found	CW Repairs-Bituminous	Internal		Uncommitt	2671175
Batch: 20267850 - Inspection Batch				Route: Adhoc Inspection				Date: 12/02/2018
3567653	HWIA - Large & smaller defect marked up to be made safe by the Assistants. Online report (Enquiry 6081006)	12/02/2018	Right next to the canal crossing just near Bassingfield Lane at the usual area.	CW Repairs-Bituminous	Internal		Committed	2670609
Batch: 20267485 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Feb Enh CW/FW				Date: 08/02/2018
Batch: 20267318 - Inspection Batch	No actionable defects found			Route: Review Outcome-Pete Moncaster				Date: 07/02/2018
Batch: 20267080 - Inspection Batch				Route: Adhoc Inspection				Date: 07/02/2018
3567128	Carriageway defects have now been made safe.	07/02/2018	Directly outside The Shires, Tollerton Lane, between the A52 and Cotgrave Lane, heading towards the A52 on the left hands side of the road.	CW Repairs-Bituminous	Internal		Uncommitt	2670079
Batch: 20265822 - Inspection Batch				Route: Adhoc Inspection				Date: 31/01/2018
3566310	Carriageway defects have been made safe .	31/01/2018	Outside house named Ivy Cottages	CW Repairs-Bituminous	Internal		Uncommitt	2669257

Effective: 01/04/2017 to 01/04/2018

Feature No.: 2000.00 to 2005.00

Display Action Officer: No

Street: Tollerton Lane (33002304)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.:			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20265266 - Inspection Batch				Route: Adhoc Inspection				Date: 29/01/2018
3565924	CW infill - Carriageway defects marked up to be infilled with hot Bimac as viafix no longer an option Enquiry 6078572)	29/01/2018	On the canal crossing and farmers gated field entrance opposite each other just up from Bassingfield Lane.	CW Repairs-Bituminous	Internal		Committed	2668865
Batch: 20264399 - Inspection Batch				Route: Adhoc Inspection				Date: 24/01/2018
3565302	Defects made safe.	24/01/2018	Canal crossing near Bassingfield Lane	CW Repairs-Bituminous	Internal		Uncommitt	2668228
Batch: 20264323 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Jan Saf CW				Date: 24/01/2018
Batch: 20264247 - Inspection Batch				Route: Adhoc Inspection				Date: 24/01/2018
3565210	Defects made safe	24/01/2018	Outside house numbers 6 & 27 & L / C 34	CW Repairs-Bituminous	Internal		Uncommitt	2668135
Batch: 20263910 - Inspection Batch				Route: Adhoc Inspection				Date: 23/01/2018
3564964	Carriageway defects made safe.	23/01/2018	Canal crossing point near Bassingfield Lane	CW Repairs-Bituminous	Internal		Uncommitt	2667886
Batch: 20260634 - Inspection Batch				Route: Adhoc Inspection				Date: 02/01/2018
3562570	HWIA - Defects marked up to be made safe within the section to be resurfaced at a future date .	02/01/2018	At the Canal crossing near Bassingfield Lane	CW Repairs-Bituminous	Internal		Committed	2665452
Batch: 20258730 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Dec Saf CW				Date: 11/12/2017
Batch: 20255555 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Nov Saf CW				Date: 20/11/2017
Batch: 20250722 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Oct Saf CW				Date: 19/10/2017
Batch: 20248118 - Inspection Batch				Route: Adhoc Inspection				Date: 02/10/2017
3556373	HWIA - Carriageway section is getting resurfaced at some point but until then defects are marked up for repair following complaints from Cyclists .Online report (Enquiry 6065879)	02/10/2017	At the Canal crossing Bassingfield end	CW Repairs-Bituminous	Internal		Committed	2658907
Batch: 20246345 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Sep Saf CW				Date: 19/09/2017
Batch: 20243317 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Aug Saf CW				Date: 25/08/2017
Batch: 20243115 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Aug Saf CW				Date: 25/08/2017
Batch: 20238724 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Jul Saf CW				Date: 19/07/2017
Batch: 20236472 - Inspection Batch				Route: Rush Area 2 Jun Saf CW				Date: 03/07/2017
3551370	HWIA - defects x 8 require making safe	03/07/2017	Canal crossing point near Bassingfeild	CW Repairs-Bituminous	Internal		Committed	2653553

Effective: 01/04/2017 to 01/04/2018

Feature No.: 2000.00 to 2005.00

Display Action Officer: No

Street: Tollerton Lane (33002304)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.:			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20231026 - Inspection Batch	No actionable defects found			Route: Rush Area 2 May Saf CW				Date: 23/05/2017
Batch: 20226160 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Apr Saf CW				Date: 21/04/2017
Batch: 20224839 - Inspection Batch				Route: Adhoc Inspection				Date: 11/04/2017
3546397	Defect made safe .	11/04/2017	Outside property named Ivy Cottage	CW Repairs-Bituminous	Internal		Uncommitt	2648223

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 2,000.00	Feature Id - Locn.:			Feature Type: Street Section		Area: Rushcliffe	
2648223	Defect made safe . (CW Repairs-Bituminous)	Outside property named Ivy Cottage	Filled when found (Cat 2H)	Job Completed	11/04/2017	11/04/2017	Act.
2653553	HWIA - defects x 8 require making safe (CW Repairs-Bituminous)	Canal crossing point near Bassingfeild	Category 2 (High)	Job Completed	03/07/2017	05/07/2017	Act. RUS-AS/5600698
2658907	HWIA - Carriageway section is getting resurfaced at some point but until then defects are marked up for repair following complaints from Cyclists .Online report (Enquiry 6065879) (CW Repairs-Bituminous)	At the Canal crossing Bassingfield end	Category 2 (High)	Job Completed	02/10/2017	10/10/2017	Act. RUS-AS/5600811
2665452	HWIA - Defects marked up to be made safe within the section to be resurfaced at a future date . (CW Repairs-Bituminous)	At the Canal crossing near Bassingfield Lane	Category 1	Job Completed	02/01/2018	03/01/2018	Act. RUS-AS/5600889
2667886	Carriageway defects made safe. (CW Repairs-Bituminous)	Canal crossing point near Bassingfield Lane	Filled when found (Cat 2H)	Job Completed	23/01/2018	23/01/2018	Act.
2668135	Defects made safe (CW Repairs-Bituminous)	Outside house numbers 6 & 27 & L / C 34	Filled when found (Cat 1)	Job Completed	24/01/2018	24/01/2018	Act.
2668228	Defects made safe. (CW Repairs-Bituminous)	Canal crossing near Bassingfield Lane	Filled when found (Cat 1)	Job Completed	24/01/2018	24/01/2018	Act.
2668865	CW infill - Carriageway defects marked up to be infilled with hot Bimac as viafix no longer an option Enquiry 6078572) (CW Repairs-Bituminous)	On the canal crossing and farmers gated field entrance opposite each other just up from Bassingfield Lane.	Category 1	Job Completed	29/01/2018	01/02/2018	Act. RUSH/3703054
2669257	Carriageway defects have been made safe . (CW Repairs-Bituminous)	Outside house named Ivy Cottages	Filled when found (Cat 2H)	Job Completed	01/02/2018	31/01/2018	Act.
2670079	Carriageway defects have now been made safe. (CW Repairs-Bituminous)	Directly outside The Shires, Tollerton Lane, between the A52 and Cotgrave Lane, heading towards the A52 on the left hands side of the road.	Filled when found (Cat 2H)	Job Completed	07/02/2018	07/02/2018	Act.

Effective: 01/04/2017 to 01/04/2018

Feature No.: 2000.00 to 2005.00

Display Action Officer: No

Street: Tollerton Lane (33002304)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:		Feature Type:	Street Section	Area:	Rushcliffe
2670609	HWIA - Large & smaller defect marked up to be made safe by the Assistants. Online report (Enquiry 6081006) (CW Repairs-Bituminous)	Right next to the canal crossing just near Bassingfield Lane at the usual area.	Category 2 (High)	Job Completed	12/02/2018	19/02/2018	Act. RUS-AS/5600935
2671175	filled when found (CW Repairs-Bituminous)	along tollerton lane as marked filled when found	Filled when found (Cat 1)	Job Completed	16/02/2018	16/02/2018	Act.
2671178	4 patches as marked out photos added (CW Repairs-Bituminous)	just after canal bridge as marked out	Category 2 (High)	Job Completed	16/02/2018	23/02/2018	Act. RUSH/3703146
2673569	Carriageway defect has been made safe. (CW Repairs-Bituminous)	Just the last property on the left called Canine Academy City inbound side.	Filled when found (Cat 2H)	Job Completed	12/03/2018	12/03/2018	Act.
2673573	CW two course patch .Wearing course erosion to the side of Carriageway requires JCB plane out 1 x 35 metres and relay base course / wearing course back to existing Carriageway level.Be advised Two Way traffic lights will be required and defect marked up during inspection. (CW Repairs-Bituminous)	Just past the Wooden shelter & Property called Canine Academy on the Brow of the incline S bend in the direction of Gamston.	Category 2 (Low)	Works Order Printed	12/03/2018	09/04/2018	Est. RUSH/3703212
2673958	CW overlay - Section of Carriageway has been overlaid recently however this section has eroded since then and requires overlaying - defect is marked up. (CW Repairs-Bituminous)	Just past Bassingfield Lane & the Canal crossing point adjacent with speed sign & farmers gate in the direction of Tollerton L / H / S.	Category 1	Job Completed	14/03/2018	16/03/2018	Act. RUSH/3703227