

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Street: Musters Road (33001240)

Locality: West Bridgford, Nottinghamshire

Area: Rushcliffe

Condition Survey

Defect No.	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,001.00	Feature Id - Locn.: From Malvern Road to Millicent Road			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20409831 - Inspection Batch				Route: Adhoc Inspection				Date: 14/09/2020
3648641	Footway defect from tree root has been made safe and recorded for future claim . D 30 mm / W 100 mm / L mm 100 (Enquiry 6177452)	14/09/2020	Outside house number 167 Musters Road , junction with Devonshire Road	Musters FW Repairs-Bituminous	Internal		Uncommitted	2752422
Batch: 20409559 - Inspection Batch				Route: Rush Area 2 Sep Saf CW/FW				Date: 11/09/2020
3648513	Defects made safe	11/09/2020	Junction with Sherborne road	CW Repairs-Bituminous	Internal		Uncommitted	2752294
Batch: 20409356 - Inspection Batch	No actionable defects found			Route: Review Outcome-Pete Moncaster				Date: 10/09/2020
Batch: 20408480 - Inspection Batch				Route: Adhoc Inspection				Date: 07/09/2020
3648004	Footway repairs - Customer is having difficulty driving over footpath to his drive with his car scrapping / damaging footpath and vehicle .Section is marked up to removed from kerb line to utility track and reinstated back to footpath level . (Enquiry 6176802)	07/09/2020	Outside house number 188 Musters Road - nearest L / C 31	Musters FW Repairs-Bituminous	Internal		Committed	2751784
Batch: 20403660 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Aug Saf CW				Date: 05/08/2020
Batch: 20399398 - Inspection Batch				Route: Adhoc Inspection				Date: 06/07/2020
3642978	Carriageway defect made safe . (Enquiry 6171225)	06/07/2020	On road outside 43 Musters Road	CW Repairs-Bituminous	Internal		Uncommitted	2746757
Batch: 20399312 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Jul Saf CW				Date: 06/07/2020
Batch: 20396953 - Inspection Batch				Route: Rush Area 2 Jun Enh CW/FW				Date: 17/06/2020
3641531	Defects made safe	17/06/2020	Outside house numbers 52 & 48	CW Repairs-Bituminous	Internal		Uncommitted	2745308
Batch: 20389444 - Inspection Batch				Route: Rush Area 2 May Saf CW				Date: 01/05/2020
3638396	Defects made safe .	01/05/2020	T junctions with Devonshire Rd / Patrick Rd & outside The Friary & outside house numbers 43 / 68 / 67 / 82 .	CW Repairs-Bituminous	Internal		Uncommitted	2742172
Batch: 20388187 - Inspection Batch				Route: Rush Area 2 Apr Saf CW				Date: 17/04/2020
3638016	HWIA - Defects within old utility track marked up to be made safe	17/04/2020	Outside house number 88	CW Repairs-Bituminous	Internal		Uncommitted	2741792
Batch: 20383974 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Mar Saf CW/FW				Date: 23/03/2020
Batch: 20382743 - Inspection Batch				Route: Adhoc Inspection				Date: 13/03/2020
3636531	CW infill - Defects within old utility tracks require infilling with HOT BITMAC	13/03/2020	Outside house numbers 82 & 90	CW Repairs-Bituminous	Internal		Committed	2740301

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,001.00	Feature Id - Locn.: From Malvern Road to Millicent Road			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20381042 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Feb Saf CW				Date: 04/03/2020
Batch: 20380614 - Inspection Batch				Route: Adhoc Inspection				Date: 03/03/2020
3635264	HWIA - Defects marked up to be made safe . (Enquiry 6161950)	03/03/2020	Outside house number 304 & Junction CW Repairs-Bituminous with Malvern Rd & Junction with Wordsworth Rd		Internal		Uncommitted	2739014
Batch: 20380001 - Inspection Batch				Route: Adhoc Inspection				Date: 27/02/2020
3634942	Carriageway defect has been made safe	27/02/2020	Outside house number 58	CW Repairs-Bituminous	Internal		Uncommitted	2738693
Batch: 20374968 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Jan Saf CW				Date: 29/01/2020
Batch: 20372627 - Inspection Batch				Route: Adhoc Inspection				Date: 14/01/2020
3630413	Carriageway defect has been made safe	14/01/2020	Outside house number 66	CW Repairs-Bituminous	Internal		Uncommitted	2734151
Batch: 20369224 - Inspection Batch				Route: Adhoc Inspection				Date: 18/12/2019
3627938	HWIA - Wearing course erosion causing issues for Cyclists which require making safe - unable to mark up due to rainfall .	18/12/2019	Adjacent or nearest L / C numbers 31 / 40 / 42 / 44 .	CW Repairs-Bituminous	Internal		Committed	2731668
Batch: 20366903 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Dec Saf CW/FW				Date: 05/12/2019
Batch: 20364879 - Inspection Batch				Route: Rush Area 2 Nov Saf CW				Date: 26/11/2019
3625701	HWIA - Defects marked up to be made safe	26/11/2019	Outside house numbers 84 / 90 / 122	CW Repairs-Bituminous	Internal		Uncommitted	2729426
Batch: 20360534 - Inspection Batch				Route: Rush Area 2 Oct Saf CW				Date: 24/10/2019
3623269	Defects made safe during inspection	24/10/2019	Various locations along road section	CW Repairs-Bituminous	Internal		Uncommitted	2726988
Batch: 20358681 - Inspection Batch				Route: Adhoc Inspection				Date: 10/10/2019
3622091	Kerb Relay - Existing kerb is undamaged & dislodged and is marked up to be relayed .	10/10/2019	Outside house number 161 - L / C 34	Kerbing/Edging	Internal		Committed	2725803
Batch: 20355242 - Inspection Batch				Route: Rush Area 2 Sep Saf CW/FW				Date: 18/09/2019
3620361	FW repairs - Tarmac footpath at both locations have been uplifted by tree root system and will require the wearing course removing and reinstating as best as possible to footpath level .	18/09/2019	Two areas - Adjacent to L / C 24 & opposite L / C 25	FW Repairs-Bituminous	Internal		Committed	2724063
3620359	Defect marked up to be made safe	18/09/2019	Outside house number 90	CW Repairs-Bituminous	Internal		Uncommitted	2724061

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Customer Services

Enquiry No.: 6177453	Logged by: External to Confirm	on: 11/09/2020 13:54	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS248596383
Desc.: Insurance claim - related to Confirm defect reference: 6177452 Date/Time: 31/08/2020 16:35:00 Direction of travel: Along Devonshire Road footway to cross Musters Road and go down Eton Road Account of what happened: I tripped over it when running and ended up lying in Musters road with just my feet on the footway, sustaining personal injury			
Location: SE corner of the junction between Devonshire Road and Musters road in West Bridgford	Contact:		
Enquiry No.: 6177452	Logged by: External to Confirm	on: 11/09/2020 13:52	
Service: Carriageway/Footway	Subject: Footway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-248596383
Desc.: Insurance claim form requested - Pavement Damage - Trip hazard knuckle of tarmac on the footway . Submitted by Advisor: PERSONAL DATA			
Location: SE corner of the junction between Devonshire Road and Musters road in West Bridgford	Contact:		
Plot Number: 2,001.00	Feature Id - Location: From Malvern Road to Millicent Road	Feature Type: Street Section	
Job Number: 2752422	Defect Number: 3648641		
Enquiry No.: 6176802	Logged by: External to Confirm	on: 07/09/2020 07:44	
Service: Carriageway/Footway	Subject: Footway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-246238135
Desc.: Pavement Damage - pavement tarmac has crumbled and in turn dropped and pot holed at our entrance causing damage to the front of our car and risk to pedestrians . Online report PERSONA			
Location: 188 Musters Road - Drop kerb damage	Contact:		
Plot Number: 2,001.00	Feature Id - Location: From Malvern Road to Millicent Road	Feature Type: Street Section	
Job Number: 2751784	Defect Number: 3648004		
Enquiry No.: 6173016	Logged by: External to Confirm	on: 24/07/2020 13:45	
Service: Carriageway/Footway	Subject: Footway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-231508456
Desc.: Pavement Damage - Customer raising concerns of works that are being carried out, outside 109, Musters Road, West Bridgford. NG2 7PX . The pavement outside of 109 has been dug up and large equipment is currently blocking access to the pavement and one large van is currently blocking the customers drive way. I have rung through to Drop Kerbs and South Co-Ordinations and they have nothing on their systems for approved works. Please could this be looked into urgently. . Submitted by Advisor: PE			
Location: 109 Musters Road, West Bridgford, NG2 7PX	Contact:		
Enquiry No.: 6172396	Logged by: External to Confirm	on: 17/07/2020 10:39	
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	Enquiry Ref: FS-CASE-229045148
Desc.: Overhanging trees - Tree overhangs my front garden - this affects the lighting in my front room and front bedroom, and causes problems with pigeon excrement on my front garden wall/garden, and a significant amount of fallen autumn leaves in my garden. Overhanging branches are very close to touching the front of my property. . Online report PERSONAL			
Location: Tree outside my property 4 South Road NG2 7AG	Contact:		
Enquiry No.: 6171225	Logged by: External to Confirm	on: 06/07/2020 09:10	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-224334144
Desc.: Road Pothole - Large pothole . Online report PERSONAL			
Location: On road outside 43 Musters Road	Contact:		
Plot Number: 2,001.00	Feature Id - Location: From Malvern Road to Millicent Road	Feature Type: Street Section	
Job Number: 2746757	Defect Number: 3642978		

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Customer Services

Enquiry No.: 6171211	Logged by: External to Confirm	on: 03/07/2020 16:45	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS224202493
Desc.: Insurance claim - related to Confirm defect reference: 6171210 Date/Time: 03/07/2020 15:00:00 Direction of travel: My car was parked on Muster's Road. Opposite the Bupa dental practice. Account of what happened: A tree fell on my var and I will need a new wing and windscreen.			
Location: Opposite Bupa dental practice Muster's road W Bridgeford.	Contact:		
Enquiry No.: 6171210	Logged by: External to Confirm	on: 03/07/2020 16:44	
Service: Trees/Verges	Subject: Fallen Tree	Classification: Report or Observation	Enquiry Ref: FS-CASE-224202493
Desc.: Insurance claim form requested - Damaged/dangerous/fallen tree - Already reported but the insurance claim form has not been received.A tree has fell down and fell on my car, . Submitted by Advisor: PERSONAL DATA			
Location: Opposite Bupa dental practice Muster's road W Bridgeford.	Contact:		
Enquiry No.: 6171207	Logged by: External to Confirm	on: 03/07/2020 16:00	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS224184662
Desc.: Insurance claim - related to Confirm defect reference: 6171206 Date/Time: 03/07/2020 15:30:00 Direction of travel: N/A Account of what happened: Large branch from tree has been blown off and landed on a parked vehicle. Passenger side - numerous scratches, wing dented and chipped, bonnet is also dented and chipped, windshield chipped. Passenger side wing and bonnet have taken the brunt of the damage.			
Location: Outside 60 Musters Road	Contact:		
Enquiry No.: 6171206	Logged by: External to Confirm	on: 03/07/2020 15:59	
Service: Trees/Verges	Subject: Fallen Tree	Classification: Report or Observation	Enquiry Ref: FS-CASE-224184662
Desc.: Insurance claim form requested - Damaged/dangerous/fallen tree - Tree fallen on vehicle. . Submitted by Advisor: James Fraser-Miller PERSONAL DATA			
Location: Outside 60 Musters Road	Contact:		
Enquiry No.: 6171205	Logged by: External to Confirm	on: 03/07/2020 15:42	
Service: Trees/Verges	Subject: Fallen Tree	Classification: Report or Observation	Enquiry Ref: FS-CASE-224178748
Desc.: Damaged/dangerous/fallen tree - The customer would like to inform about a fallen tree, half of it is on somebody's car and the other half is on the ground.The customer states that are some heavy branches overhanging over the pavement, completely blocking the pavement. . Submitted by Advisor: PERSONAL DATA			
Location: Musters Road, West Bridgford NG2 7PQ In front of Bupa Dental Care	Contact:		
Enquiry No.: 6171107	Logged by: External to Confirm	on: 02/07/2020 16:51	
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	Enquiry Ref: FS-CASE-223795598
Desc.: Other tree issues - There is a tree that is quite big and branches keep falling of the tree and these are big branches. They are fall onto the pavement and onto the customers car, these haven't caused any damaged yet. Customer would like to know if this could be looked at to see if it needs cutting back so that it doesn't cause any damage. . Submitted by Advisor: PERSONAL DATA			
Location: Outside 175A Musters Road, WEST BRIDGFORD, West Bridgford, Nottinghamshire , NG2 7DQ	Contact:		

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Customer Services

Enquiry No.: 6167653 **Logged by:** External to Confirm **on:** 27/05/2020 14:21
Service: Trees/Verges **Subject:** Tree Enquiry **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-211189402
Desc.: Other tree issues - A tree came down in February and 3/4 of the tree was taken and 1/4 of the tree is there but has lifted and there is now a big hole on the grass verge - customer has seen a rat around this hole. customer would like the hole filling in and the rest of the tree taken away to help with this problem. customer has been informed to contact BC regarding pest control. . Submitted by Advisor: PERSONAL DATA
Location: 14 Musters road **Contact:**

Enquiry No.: 6166879 **Logged by:** External to Confirm **on:** 13/05/2020 13:00
Service: Trees/Verges **Subject:** Overhanging Vegetation/Trees **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-206804171
Desc.: Overhanging trees - Lime tree branches now at around 5 foot height overhanging into the pavement.
. Online report PERSONAL
Location: On pavement outside 183 Musters Road **Contact:**

Enquiry No.: 6162270 **Logged by:** External to Confirm **on:** 02/03/2020 08:12
Service: Traffic Management **Subject:** Pedestrian Crossing Request **Classification:** Service Request **Enquiry Ref:** FS-CASE-179471185
Desc.: Pedestrian crossing - A zebra crossing is all that is needed . Online report - PERSONAL
Location: Musters road in the vicinity of Georges Medical practice, west Bridgford medical centre and most importantly a road frequently crossed by parnets and young children to reach west Bridgford infant school. Something needs to be in place around this junction with george road before an accident happens **Contact:**

Enquiry No.: 6161950 **Logged by:** External to Confirm **on:** 28/02/2020 17:12
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-178915357
Desc.: Road Pothole - 2 large deep potholes before junction with Wordsworth Road . Online report PERSONAL
Location: On Munsters road North bound **Contact:**

Plot Number: 2,001.00 **Feature Id - Location:** From Malvern Road to Millicent Road **Feature Type:** Street Section
Job Number: 2739014 **Defect Number:** 3635264

Enquiry No.: 6161470 **Logged by:** External to Confirm **on:** 26/02/2020 15:15
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-178216974
Desc.: potholes
Location: all across the road **Contact:**

Enquiry No.: 6161146 **Logged by:** External to Confirm **on:** 25/02/2020 15:59
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-177800357
Desc.: Road Pothole - One of the potholes is very deep and huge. It is dangerous to suspensions of vehicles. Stones from a number of them litter the nearby road and pavement. . Online report PERS
Location: On the west side of Musters Rd uphill from the junction with Eton Rd, there are a series of 5 potholes alongside the double yellow lines. Higher up is another pothole which looks as if it was marked for filling but there is not much left of the white lines **Contact:**

Plot Number: 2,001.00 **Feature Id - Location:** From Malvern Road to Millicent Road **Feature Type:** Street Section
Job Number: 2738693 **Defect Number:** 3634942

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Customer Services

Enquiry No.: 6158178	Logged by: External to Confirm	on: 11/02/2020 11:03	Enquiry Ref: FS-CASE-173985754
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	
Desc.: Other tree issues - PE would like to know if he can cut up the tree trunk on Musters road as it is blocking the footpath. PERSONAL DATA			
. Submitted by Advisor: PERSONAL DATA			
Location: Muster road, West Bridgford near the health centre	Contact:		
Enquiry No.: 6158128	Logged by: External to Confirm	on: 11/02/2020 09:42	Enquiry Ref: FS173952538
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	
Desc.: Insurance claim - related to Confirm defect reference: 6157712 Date/Time: 09/02/2020 13:00:00 Direction of travel: n/a - Car parked Account of what happened: Car was parked outside La Storia when the tree came down, the tree has landed on the car. Customer has said that the whole tree had come down and there was not alot of roots on the tree and customer believes that this is why it has fallen down, customer has said the police have said to ask for the tree inspection report if needed - customer has said if there is no valid claim she will want to see this.			
Location: Tree across musters road	Contact:		
Enquiry No.: 6157895	Logged by: External to Confirm	on: 10/02/2020 12:06	Enquiry Ref: FS-CASE-173705865
Service: Trees/Verges	Subject: Fallen Tree	Classification: Report or Observation	
Desc.: Damaged/dangerous/fallen tree - The customer would like to report a fallen tree blocking the pavement.The tree is on thefront of the customer's property. . Submitted by Advisor: PERSONA			
Location: Flat 4 55 Musters Road, West bridgeford, NG2 7PQ,	Contact:		
Enquiry No.: 6157712	Logged by: External to Confirm	on: 09/02/2020 16:06	Enquiry Ref: FS-CASE-173522632
Service: Trees/Verges	Subject: Fallen Tree	Classification: Report or Observation	
Desc.: Damaged/dangerous/fallen tree - Tree across musters road . Online report PERSONAL			
Location: Tree across musters road	Contact:		
Enquiry No.: 6154248	Logged by: External to Confirm	on: 16/01/2020 12:54	Enquiry Ref: FS-CASE-168283833
Service: Carriageway/Footway	Subject: Footway Damage	Classification: Report or Observation	
Desc.: Pavement Damage - Paving slabs are a trip hazard . Online report PERSONAL			
Location: Footway outside no 286 Muster Rd	Contact:		
Enquiry No.: 6153734	Logged by: External to Confirm	on: 13/01/2020 22:42	Enquiry Ref: FS-CASE-167663649
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	
Desc.: Road Pothole - Deep pothole in the middle of the road. . Online report PERSONAL			
Location: Musters Road as you go up from Trent Bridge. In the middle of the road just before Patrick Road junction.	Contact:		
Plot Number: 2,001.00	Feature Id - Location: From Malvern Road to Millicent Road	Feature Type: Street Section	
Job Number: 2734151	Defect Number: 3630413		
Enquiry No.: 6151669	Logged by: External to Confirm	on: 27/12/2019 08:10	Enquiry Ref: FS-CASE-164027185
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	
Desc.: Road Pothole - There are 2 potholes where the passenger side wheel would normally go. Earlier there is a depression forming which runs at right angles to the pavement and goes across the road. . Online report PERSONAL			
Location: On Musters Rd travelling north just before the junction with Eton Rd.	Contact:		

Effective: 14/09/2019 to 14/09/2020

Display Action Officer: No

Feature No.: 2001.00 to 2001.00

Street: Musters Road (33001240)

Customer Services

Enquiry No.: 6151324 **Logged by:** External to Confirm **on:** 23/12/2019 08:18
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-163629842
Desc.: Road Pothole - PERSONAL DATA .

I am very concerned that there are some very dangerous pothole on Musters Road which inevitably will soon result in a serious cycle accident coming down the hill from Boundary Road.

PERSONAL DATA .

These deep potholes would appear to be primarily caused by bad repairs by contractors after they have dug up what is otherwise a good road surface (see attached photo of one of them).

Coming down the hill a cyclist is typically travelling at 20+ mph.

If anyone hits one of these holes, which are increasingly getting bigger, they will have a serious accident.

I ask on behalf of all other fellow cyclists, that you pressure Rushcliffe B.C. to fix these holes asap and, if possible, seek compensation from the previous contractors who weakened the road surface.

I have also informed Ruth Edwards, the new MP for Rushcliffe.

Thank you in anticipation.

Regards,

PERSONAL DATA .

Location: Musters Road, close to Musters Crescent.

Contact:

A number of dangerous potholes which are getting bigger day-by-day.

Enquiry No.: 6151228 **Logged by:** External to Confirm **on:** 23/12/2019 08:16
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS163533610
Desc.: Road Pothole - I reported the pothole a month ago and it stated that it has repaired however when I drove passed the pothole is getting bigger and no sign of repaired . Online report PERSONA
Confirm Case: 6147386
Location: A pothole on the junction of Melton Road turn left into Musters Road. **Contact:**

Enquiry No.: 6150726 **Logged by:** External to Confirm **on:** 18/12/2019 12:57
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-162931064
Desc.: Road Pothole - 222 - potholes in road
228 - tarmac around manhole cover is beginning to disintegrate . Online report PERSONAL .
Location: Near 222 Musters road and again near 228 Musters Road **Contact:**

Enquiry No.: 6144920 **Logged by:** External to Confirm **on:** 07/11/2019 14:51
Service: Trees/Verges **Subject:** Tree Enquiry **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-155648426
Desc.: Other tree issues - Streetlight has been encased by an ivy bush. The light is not yet impacted but won't be long until the ivy is interfering with the light. . Submitted by Advisor: PERSON
Location: Streetlight on Musters Road, West Bridgford. **Contact:**

Enquiry No.: 6144917 **Logged by:** External to Confirm **on:** 07/11/2019 14:48
Service: Trees/Verges **Subject:** Planters **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-155647519
Desc.: Planters - Tree stump is set to be removed but William would like to request that a tree is planted in it's place to replace it. . Submitted by Advisor: PERSONA
Location: Tree stump opposite number 88 Musters Road, West Bridgford. **Contact:**

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Customer Services

Enquiry No.: 6143863	Logged by: External to Confirm	on: 31/10/2019 10:42	Enquiry Ref: FS-CASE-153954071
Service: Carriageway/Footway	Subject: Temporary Sign Issue	Classification: Report or Observation	
Desc.: Temporary sign issue - A52 east Road closed diversion sign been placed on George street, would like to be removed so no pranks can be caused . Submitted by Advisor: PERSONAL			
Location: George Road, WEST BRIDGFORD, West Bridgford, Nottinghamshire , NG2 7QG	Contact:		
Enquiry No.: 6142939	Logged by: External to Confirm	on: 22/10/2019 09:18	Enquiry Ref: FS-CASE-151956351
Service: Traffic Management	Subject: Pedestrian Crossing Request	Classification: Service Request	
Desc.: Pedestrian crossing - Customer would like a zebra crossing put outside the nursery or close by , they are having problems getting the children across the road - the road is busy and there are only 4 car park spaces,thus it is difficult to get the children across. . Submitted by Advisor: PERSONAL			
Location: 9 Musters Road - tinytalkers day nursery - ng2 7pp	Contact:		
Enquiry No.: 6142692	Logged by: External to Confirm	on: 18/10/2019 14:21	Enquiry Ref: FS-CASE-151286013
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	
Desc.: Other tree issues - A tree (18 is marked on the pavement) is planned to be planted outside property 115, however they are having the front of their property changed into a drive way and would appreciate the not having the tree blocking access to their property. . Submitted by Advisor: PERSONAL DATA			
Location: Outside 115 Musters Road	Contact:		
Enquiry No.: 6141901	Logged by: External to Confirm	on: 11/10/2019 15:57	Enquiry Ref: FS-CASE-149695089
Service: Carriageway/Footway	Subject: Dropped Kerb (Vehicle) Request	Classification: Service Request	
Desc.: Dropped kerb - Cars & other vehicles - Dropped kerb to enable reconfiguration of existing driveway . Online report - Quote required 4 whole kerb(s) and 2 tapered kerb(s) to be dropped Position of kerb - To the right of the property when viewed from the road (photo attached) Streetlight - PERSONAL DATA .			
Location: 151 musters road	Contact:		
Enquiry No.: 6141810	Logged by: External to Confirm	on: 11/10/2019 07:18	Enquiry Ref: FS-CASE-149556736
Service: Carriageway/Footway	Subject: Footway Damage	Classification: Report or Observation	
Desc.: Pavement Damage - Wall has collapsed onto the pavement. Concern that a tree will come down over road or pavement. . Online report: PERSONAL			
Location: Corner of Musters and Devonshire Road on the pavement	Contact:		
Enquiry No.: 6141233	Logged by: External to Confirm	on: 06/10/2019 10:48	Enquiry Ref: FS-CASE-148438041
Service: Carriageway/Footway	Subject: Flooding	Classification: Report or Observation	
Desc.: Street flooding - After rain there is large accumulation of water along this stretch of road which takes a long time to drain away (still there the next day). I don't know what is causing the problem but it seems worse than it used to be. Cars driving through it will send up sprays of water soaking pedestrians. Attached photo - shows some of the problem - but partially obscured by tree. Please don't make this photo accessible to the public.. Online reportCustomer title is Miss.			
Location: The kerbside drainage outside 66 and 68 Musters Road	Contact:		

Effective: 14/09/2019 to 14/09/2020

Display Action Officer: No

Feature No.: 2001.00 to 2001.00

Street: Musters Road (33001240)

Customer Services

Enquiry No.: 6139424

Logged by: External to Confirm

on: 19/09/2019 09:45

Service: Trees/Verges

Subject: Tree Enquiry

Classification: Report or Observation

Enquiry Ref: FS-CASE-144667300

Desc.: Other tree issues - Email from customer

PERSONAL
DATAMusters Road - tree probelem
Dear Sirs,

PERSONAL 50 Musters Road, West Bridgford NG2 7PR. There is a crab apple tree planted in the pavement outside our house that is causing a nuisance and a problem for us and members of the public outside our property. Specifically:

1. The tree is dropping a large volume of rotting crab apples on our drive and the pavement. The pavement is very slippery and dangerous as a result. The smell is terrible and the rotting apples attract vermin and insects. Footwear becomes sticky, causing damage to property and the apples are also falling on vehicles on our drive, again causing damage.

2. The tree looks like it has previously been hit by a vehicle and is now growing at an angle. It is interfering with the overhead phone lines, and also obstructing access to our drive for higher vehicles.

3. The roots growing under the pavement are causing the pavement to be uneven and creating a trip hazzard.

We enclose some photos below for your ease of reference.

We would be grateful if this matter could be investigated and the tree removed.

Yours faithfully

PERSONAL
DATA

Location: Outside 50 Musters Road West Bridgford

Contact:

Enquiry No.: 3800719

Logged by: PERSONAL

on: 07/07/2020 15:13

Service: Trees/Verges

Subject: Fallen Tree

Classification: Report or Observation

Enquiry Ref: FS-CASE-224184662

Desc.: Tree is rotten and causing issues to residents - it far too big for the road

Location: Outside No52/54

Contact:

Enquiry No.: 3208603

Logged by: PERSONAL

on: 21/11/2019 08:29

Service: Carriageway/Footway

Subject: Manholes/Gullies

Classification: Report or Observation

Desc.: possible "leak" needs investigating

Location: in front of the Jesse Gray School in foot way

Contact:

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Customer Services

Enquiry No.: 89510

Logged by: Laura Trusler

on: 31/07/2020 12:30

Service: Trees/Verges

Subject: Tree Enquiry

Classification: Report or Observation

Desc.: From: PERSONAL DATA

Subject: Notification of forthcoming tree removal works at No286 Musters Road, West Bridgford (3004145)

PERSONAL DATA

I hope you're keeping well. I am emailing to notify you that we have identified a tree that require felling in your area. Please see the attached form requesting approval form NCC contracts team and photograph of the tree in question.

The decision to remove trees are not taken lightly. Trees are usually felled because it is the best option to reduce the risk of harm to an acceptable level. The tree is scheduled for removal for safety reasons as the tree is standing dead and poses a potential hazards to highway user.

Kindest regards,

PERSONA

Environmental Works Coordinator
Environmental Maintenance Team
Highway Operations
Via East Midlands Ltd

**PERSONAL
DATA**

Head Office: Bilsthorpe Highways Depot, Bilsthorpe Business Park,
Eakring Road, Bilsthorpe, Newark NG22 8ST

Location: O/S No 286

Contact:

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Customer Services

Enquiry No.: 88975 Logged by: P [REDACTED] on: 13/07/2020 10:48

Service: Traffic Management Subject: Pedestrian Crossing Request Classification: Service Request

Desc.: PERSONAL DATA [REDACTED]

Subject: Musters Road, West Bridgford - Zebra Crossing

PERSO

Find attached the consultation letter and plan regarding a proposed new zebra crossing on Musters Road, West Bridgford (Adjacent to Jesse Gray Primary School). If you require any additional information on the scheme, feel free to contact me.

Kind Regards,

PERSONAAssistant Project Engineer
Via East Midlands Ltd**PERSONAL**

DATA [REDACTED]

Head Office: Bilsthorpe Highways Depot, Bilsthorpe Business Park,
Eakring Road, Bilsthorpe, Newark NG22 8ST

Location: Adjacent Jesse Gray Primary School

Contact:

Enquiry No.: 88960 Logged by: **PERSO** [REDACTED] on: 11/07/2020 22:03

Service: Carriageway/Footway Subject: Dropped Kerb (Vehicle) Request Classification: Service Request

Desc.: Contractor Application received from KL Macadam

Location: Outside Number 109.

Contact:

Enquiry No.: 88861 Logged by: **PERSO** [REDACTED] on: 08/07/2020 14:09

Service: Highway Searches Subject: CON29 Classification: Report or Observation

Desc.: con29 questions

Location: 346 Musters Road, West Bridgford Nottingham NG2 7DF

Contact:

Enquiry No.: 87645 Logged by: **PERSON** [REDACTED] on: 12/05/2020 14:40

Service: Trees/Verges Subject: Fallen Tree Classification: Report or Observation

Desc.: Can you tell me what is happening with the uprooted tree at the bottom of Musters Rd? It's been there for ages – even before lockdown.

Location: Junction Bridge Grove

Contact:

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Customer Services

Enquiry No.: 86843

Logged by: PERSON

on: 17/03/2020 11:40

Service: Trees/Verges

Subject: Fallen Tree

Classification: Report or Observation

Desc.: PERSONAL DATA

Subject: Bridge Grove West Bridgford

Hello Both

We have had to cancel this installation with EON due to this tree still being present on Bridge Grove West Bridgford.

My records show that this tree was blown over on the 10th February and has not been removed.

Who is responsible for the tree?

PERSONAL

Location: Junction Bridge Grove

Contact:

Enquiry No.: 86773

Logged by: PERSON

on: 12/03/2020 09:35

Service: Carriageway/Footway

Subject: Flooding

Classification: Report or Observation

Desc.: See Links for email chain regarding flooding of the rear garden of this property from RBC land, known as 'The Green Line)

Location: No 147

Contact:

Enquiry No.: 86542

Logged by: PERSONA

on: 04/03/2020 15:47

Service: Traffic Management

Subject: Parking General

Classification: Report or Observation

Desc.: H bar marking

Location: The Methodist Church

Contact:

Enquiry No.: 85983

Logged by: PERSON

on: 17/02/2020 13:40

Service: Other

Subject: Other Enquiry (Highways)

Classification: Report or Observation

Desc.: See email chain in the Links regarding the flooding to the rear gardens of Nos 147 to 153 Musters Road, from the Green Line

Location: Rear gardens of Nos 147 to 153 Musters Road, West Bridgford

Contact:

Enquiry No.: 85893

Logged by: PERSON

on: 13/02/2020 11:03

Service: Trees/Verges

Subject: Tree Enquiry

Classification: Report or Observation

Desc.: It is completing blocking the pavement resyricting entry to the drive of 55 musters road and pedestrians having to walk into the road with on coming traffic . Many pensioners and children are being put at danger and inconvenience.

Location: O/S No 55

Contact:

Enquiry No.: 84530

Logged by: PERSON

on: 16/12/2019 10:54

Service: Carriageway/Footway

Subject: St Furn/Non Illum Sign Damage

Classification: Report or Observation

Desc.: Posts for street signs has been struck and is leaning

Location: 2 x posts Musters Road near to Mrs Bunns cob shop

Contact:

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Customer Services

Enquiry No.: 84520 Logged by: PERSONAL on: 16/12/2019 09:58
 Service: Traffic Management Subject: Traffic Issues Classification: Report or Observation

Desc.: PERSONAL

Thank you for responding to my email. Now both of my children have received detailed instruction at school about road safety (as well as daily from me) but the behaviour of motorists has not changed. The situation is quite dangerous.

Only this week I stopped a year 6 boy from being squashed as a car overtook another which has stopped to allow us to cross.

Please find attached a number of photos taken on the morning school run. The combination of lack of yellow lines on the corner of Malvern Road (hence parked cars on the corner) turning right onto Musters and the camber of the hill combined with the new addition of a small tree make visibility for pedestrians crossing and drivers at that junction extremely dangerous. The tree is lovely by the way. Parking needs to be restricted too as you can see from my photos there was almost no one parked in Malvern Road which is much safer.

After a year of not being able to replace PE really a permanent solution need to be found. Do you have a plan?

Please consider that obviously this matter affects local residents, the children and families of Jesse Gray Primary School and the children and families of young people crossing both morning and afternoon from and to West Bridgford and Rushcliffe School.

Thank you for your time and consideration,

Location: PERSONAL
 PERSONAL

Contact:

Enquiry No.: 83843 Logged by: PERSONAL on: 14/11/2019 13:15
 Service: Traffic Management Subject: Speed Limits/Issues Classification: Report or Observation

Desc.: concerns about the safety of children and parents crossing Musters Road adjacent to the school

Location: Jesse Gray School

Contact:

Enquiry No.: 83757 Logged by: PERSONAL on: 12/11/2019 12:34
 Service: Carriageway/Footway Subject: Flooding Classification: Report or Observation

Desc.: STW have been called to a 'leak' that turns out to be a pipe draining water onto the verge outside the school. Can this be investigated to see if we need to enforce this issue with the school, please reply back to PERSONAL at Highways South.

Location: o/s Jesse Gray Primary School

Contact:

Enquiry No.: 82795 Logged by: PERSONAL on: 30/09/2019 10:53
 Service: Traffic Management Subject: Pedestrian Crossing Request Classification: Service Request

Desc.: Following Committee yesterday, Gordon has asked me to attend a meeting at Jesse Gray with him and the Head to discuss a petition they are about to send (or have sent) requesting a formal crossing.

Location: Near Jesse Gray school

Contact:

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,001.00	Feature Id - Locn.: From Malvern Road to Millicent Road		Feature Type: Street Section		Area: Rushcliffe	
2724061	Defect marked up to be made safe (CW Repairs-Bituminous)	Outside house number 90	Category 2	Repair Completed	18/09/2019	19/09/2019	Act.

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,001.00	Feature Id - Locn.:	From Malvern Road to Millicent Road	Feature Type:	Street Section	Area:	Rushcliffe
2724063	FW repairs - Tarmac footpath at both locations have been uplifted by tree root system and will require the wearing course removing and reinstating as best as possible to footpath level . (FW Repairs-Bituminous)	Two areas - Adjacent to L / C 24 & opposite L / C 25	Category 3	Job Completed	18/09/2019	26/09/2019	Act. RUSH/3704860
2725803	Kerb Relay - Existing kerb is undamaged & dislodged and is marked up to be relayed . (Kerbing/Edging)	Outside house number 161 - L / C 34	Category 2	Job Completed	10/10/2019	17/10/2019	Act. RUSH/3704934
2726988	Defects made safe during inspection (CW Repairs-Bituminous)	Various locations along road section	Filled when found (Cat 2)	Job Completed	24/10/2019	24/10/2019	Act.
2729426	HWIA - Defects marked up to be made safe (CW Repairs-Bituminous)	Outside house numbers 84 / 90 / 122	Category 2	Repair Completed	26/11/2019	05/12/2019	Act.
2731668	HWIA - Wearing course erosion causing issues for Cyclists which require making safe - unable to mark up due to rainfall . (CW Repairs-Bituminous)	Adjacent or nearest L / C numbers 31 / 40 / 42 / 44 .	Category 2	Job Completed	18/12/2019	24/12/2019	Act. RUSH/3705111
2734151	Carriageway defect has been made safe (CW Repairs-Bituminous)	Outside house number 66	Filled when found (Cat 2)	Job Completed	14/01/2020	14/01/2020	Act.
2738693	Carriageway defect has been made safe (CW Repairs-Bituminous)	Outside house number 58	Filled when found (Cat 2)	Job Completed	28/02/2020	28/02/2020	Act.
2739014	HWIA - Defects marked up to be made safe . (Enquiry 6161950) (CW Repairs-Bituminous)	Outside house number 304 & Junction with Malvern Rd & Junction with Wordsworth Rd	Category 2	Repair Completed	03/03/2020	05/03/2020	Act.
2740301	CW infill - Defects within old utility tracks require infilling with HOT BITMAC (CW Repairs-Bituminous)	Outside house numbers 82 & 90	Category 2	Repair Completed	13/03/2020	20/04/2020	Act. RUSH/3705402
2741792	HWIA - Defects within old utility track marked up to be made safe (CW Repairs-Bituminous)	Outside house number 88	Category 2	Repair Completed	17/04/2020	20/04/2020	Act.
2742172	Defects made safe . (CW Repairs-Bituminous)	T junctions with Devonshire Rd / Patrick Rd & outside The Friary & outside house numbers 43 / 68 / 67 / 82 .	Filled when found (Cat 2)	Job Completed	01/05/2020	01/05/2020	Act.
2745308	Defects made safe (CW Repairs-Bituminous)	Outside house numbers 52 & 48	Filled when found (Cat 2)	Job Completed	17/06/2020	17/06/2020	Act.
2746757	Carriageway defect made safe . (Enquiry 6171225) (CW Repairs-Bituminous)	On road outside 43 Musters Road	Filled when found (Cat 2)	Job Completed	07/07/2020	07/07/2020	Act.

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,001.00	Feature Id - Locn.: From Malvern Road to Millicent Road		Feature Type: Street Section		Area: Rushcliffe	
2751784	Footway repairs - Customer is having difficulty driving over footpath to his drive with his car scrapping / damaging footpath and vehicle .Section is marked up to removed from kerb line to utility track and reinstated back to footpath level . (Enquiry 6176802) (FW Repairs-Bituminous)	Outside house number 188 Musters Road - nearest L / C 31	Category 2	Job Completed	07/09/2020	14/09/2020	Act. RUSH/3705728
2752294	Defects made safe (CW Repairs-Bituminous)	Junction with Sherborne road	Filled when found (Cat 2)	Job Completed	11/09/2020	11/09/2020	Act.
2752422	Footway defect from tree root has been made safe and recorded for future claim . D 30 mm / W 100 mm / L mm 100 (Enquiry 6177452) (FW Repairs-Bituminous)	Outside house number 167 Musters Road , junction with Devonshire Road	Made Safe (Cat 1)	Job Completed	14/09/2020	14/09/2020	Act.

Street Works Inspections

Organisation: BT (0030006)

Works Ref: T1001MW500298440800

Group No: 1	Site No: 1	Street Authority: Nottinghamshire Highway Works	Inspected: 26/05/2020 10:33:50
Category: Category A	Outcome: Passed	Defect No: N/A	Sampled: Yes
Defect Notif. No: N/A	Tel: PERSON	Site Informed: Yes	Sign./Light./Guard. Inadequacy: No
Insp. Notes:		Site Location: IN C/W, JCN SOUTH ROAD, MUSTERS ROAD	Site Post Code:
Defect Notes:		Position: Footway	

Organisation: Fulcrum Pipelines Limited -SEC Ltd (7294014)

Works Ref: 3682

Group No: 2	Site No: 2	Street Authority: Nottinghamshire	Inspected: 01/10/2019 09:15:40
Category: Category C	Outcome: Passed	Defect No: N/A	Sampled: Yes
Defect Notif. No: N/A	Tel: PERSONA	Site Informed: Yes	Sign./Light./Guard. Inadequacy: No
Insp. Notes:		Site Location: o/s 88-90	Site Post Code:
Defect Notes:		Position: Footway	

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Street Works Inspections**Organisation:** NRSWA - Cadent Gas EM (0010001) (Street Works Admin Team NG Gas)**Works Ref:** 1000689888

Group No: 1	Site No: 5	Street Authority: Nottinghamshire	Inspected: 30/01/2020 08:18:28
Category: Category C		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel: PERSON	Site Location: 82 FLAT 1
Insp. Notes:			Position: Footway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Sampled Site No: 5
			Site Post Code:

Organisation: Severn Trent Integra Utility Services (9103906)**Works Ref:** 0000/00004390239

Group No: 1	Site No: 1	Street Authority: NCC - RUSHCLIFFE	Inspected: 14/04/2020 13:21:54
Category: Category C		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel: PERSON	Site Location: ON FOOTWAY OUTSIDE NO 237
Insp. Notes:			Position: Footway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Sampled Site No: 1
			Site Post Code:

Organisation: Severn Trent New Connections East - Water (9103920)**Works Ref:** 5101/000006471600

Group No: 1	Site No: 6	Street Authority: NCC - RUSHCLIFFE	Inspected: 10/10/2019 14:18:15
Category: Category B		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel: PERSON	Site Location: 298 MUSTERS ROAD WEST BRIDGFORD NG2 7DF
Insp. Notes:			Position: Footway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Sampled Site No: 6
			Site Post Code:

Organisation: Severn Trent Water East (9103908)**Works Ref:** 1101/000012303255

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 11/11/2019 11:51:49
Category: Category A		Outcome: Failed (Lower Risk/Non Dangerous)	Sampled: Yes
Defect Notif. No: 11301482		Defect No: 11301482	Site Informed: Yes
		Tel: PERSON	Site Location: 316
Insp. Notes: no info board			Position: Footway
Defect Notes: no info board			Sign./Light./Guard. Inadequacy: No
			Sampled Site No: 1
			Site Post Code:

Organisation: WPD 5154 Keyworth (7011554)**Works Ref:** M51540565920

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 30/01/2020 08:18:13
Category: Category C		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel: PERSON	Site Location: O/S 82 MUSTERS ROAD
Insp. Notes:			Position: Footway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Sampled Site No: 1
			Site Post Code:

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Street Works Inspections

Organisation: WPD 5154 Keyworth (7011554)

Works Ref: M51542040464

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 30/01/2020 12:42:48
Category: Category C		Outcome: Abortive	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel: PERSON	Site Location: OUTSIDE 241
Insp. Notes:			Position: Footway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Sampled Site No: 1
			Site Post Code:

Works Ref: M51542207513

Group No: 1	Site No: 1	Street Authority: Nottinghamshire Highway Works	Inspected: 22/05/2020 08:40:44
Category: Category A		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel: PERSON	Site Location: Outside 77
Insp. Notes:			Position: Footway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Sampled Site No: 1
			Site Post Code:

Works Ref: M51542212774

Group No: 3	Site No: 1	Street Authority: Nottinghamshire	Inspected: 11/09/2020 12:37:17
Category: Category B		Outcome: Passed	Sampled: No
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel:	Site Location: Outside 109
Insp. Notes:			Position: Footway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Sampled Site No:
			Site Post Code:

Group No: 2	Site No: 1	Street Authority: Nottinghamshire	Inspected: 11/09/2020 12:36:10
Category: Category B		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel:	Site Location: Outside 109
Insp. Notes:			Position: Footway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Sampled Site No: 1
			Site Post Code:

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 14/07/2020 10:23:39
Category: Category B		Outcome: Passed	Sampled: No
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel:	Site Location: Outside 109
Insp. Notes:			Position: Footway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Sampled Site No:
			Site Post Code:

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Street Works Notices

Organisation: BT (0030006)

Works Ref: TI001MW500294972301

Version: 4

Work Desc: Install 80m of 1 way poly duct in Footway

Notice Type: Registration of Reinstatement - Full

Start: 17/03/2020 00:00:00

Work Status: Works Stopped

Issued: 19/03/2020 10:22:29

Work Type: EToN 4: Minor

Est. End: 19/03/2020

Completion: 19/03/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	O/S 89 TO O/S 72 , MUSTERS ROAD	Footway	Up to 1.5 Metres of Cover	80.00	0.30 A Permanent Reinstatement	19/03/2020		19/03/2020	18/03/2020

Works Ref: TI001MW500297467500

Version: 5

Work Desc: Locate and excavate 1 blockage in existing duct

Notice Type: Registration of Reinstatement - Full

Start: 05/05/2020 00:00:00

Work Status: Works Stopped

Issued: 13/05/2020 06:49:40

Work Type: EToN 4: Minor

Est. End: 07/05/2020

Completion: 07/05/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	CLR BLK BETWEEN JNC SOUTH ROAD ON O/S 184, MUSTERS ROAD	Footway	Up to 1.5 Metres of Cover	0.60	0.80 A Permanent Reinstatement	07/05/2020		07/05/2020	06/05/2020

Works Ref: TI001MW500297657400

Version: 5

Work Desc: Install 5m of 1 way poly duct in Footway

Notice Type: Registration of Reinstatement - Full

Start: 12/05/2020 00:00:00

Work Status: Works Stopped

Issued: 19/05/2020 05:37:44

Work Type: EToN 4: Minor

Est. End: 14/05/2020

Completion: 14/05/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	JNC BROMLEY ROAD ON, MUSTERS ROAD	Footway	Up to 1.5 Metres of Cover	1.00	0.40 A Permanent Reinstatement	14/05/2020		14/05/2020	14/05/2020

Works Ref: TI001MW500298440800

Version: 5

Work Desc: Locate and excavate 1 blockage in existing duct

Notice Type: Registration of Reinstatement - Full

Start: 20/05/2020 00:00:00

Work Status: Works Stopped

Issued: 05/06/2020 14:53:03

Work Type: EToN 4: Minor

Est. End: 22/05/2020

Completion: 22/05/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	IN C/W, JCN SOUTH ROAD, MUSTERS ROAD	Footway	Up to 1.5 Metres of Cover	1.00	0.70 A Permanent Reinstatement	22/05/2020		22/05/2020	21/05/2020

Works Ref: TI002AP500280799801

Version: 4

Work Desc: Renew 1 Carrier pole

Notice Type: Registration of Reinstatement - Full

Start: 21/10/2019 00:00:00

Work Status: Works Stopped

Issued: 21/10/2019 14:23:25

Work Type: EToN 4: Minor

Est. End: 23/10/2019

Completion: 21/10/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	O/S 259 MUSTERS ROAD, MUSTERS ROAD	Footpath	Up to 1.5 Metres of Cover	0.50	0.50 A Permanent Reinstatement	21/10/2019		21/10/2019	23/10/2019

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Street Works Notices

Organisation: BT (0030006)

Works Ref: T1003MW500286609902

Version: 4

Work Desc: Locate and excavate 1 blockage in existing duct

Notice Type: Registration of Reinstatement - Full

Start: 04/10/2019 00:00:00

Work Status: Works Stopped

Issued: 14/10/2019 12:49:40

Work Type: EToN 4: Minor

Est. End: 08/10/2019

Completion: 07/10/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	carriageway OUTSIDE 328A, MUSTERS ROAD	Footway	Up to 1.5 Metres of Cover	0.90	0.40	A Permanent Reinstatement	07/10/2019		07/10/2019	07/10/2019

Works Ref: T1003MW500289066300

Version: 4

Work Desc: Locate and excavate 1 blockage in existing duct

Notice Type: Registration of Reinstatement - Full

Start: 14/11/2019 00:00:00

Work Status: Works Stopped

Issued: 20/11/2019 07:12:17

Work Type: EToN 4: Minor

Est. End: 18/11/2019

Completion: 14/11/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FW OS 332, MUSTERS ROAD	Footway	Up to 1.5 Metres of Cover	0.80	0.60	A Permanent Reinstatement	14/11/2019		14/11/2019	18/11/2019
2	FW OS 332, MUSTERS ROAD	Footway	Up to 1.5 Metres of Cover	0.80	0.80	A Permanent Reinstatement	14/11/2019		14/11/2019	

Works Ref: T1003MW500293498000

Version: 4

Work Desc: Locate and excavate 4 blockage in existing duct

Notice Type: Registration of Reinstatement - Full

Start: 24/02/2020 00:00:00

Work Status: Works Stopped

Issued: 11/03/2020 15:09:08

Work Type: EToN 4: Minor

Est. End: 26/02/2020

Completion: 26/02/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN FW OS 86, IN FW OS 50, IN FW OS 64 AND IN FW OS 76, MUSTERS ROAD	Footway	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	26/02/2020		26/02/2020	25/02/2020
2	IN FW OS 86, IN FW OS 50, IN FW OS 64 AND IN FW OS 76, MUSTERS ROAD	Footway	Up to 1.5 Metres of Cover	0.30	0.30	A Permanent Reinstatement	26/02/2020		26/02/2020	

Works Ref: T1003MW500294716800

Version: 3

Work Desc: Locate and excavate 3 blockage in existing duct

Notice Type: Works Stop

Start: 09/03/2020 00:00:00

Work Status: Works Stopped

Issued: 11/03/2020 15:16:00

Work Type: EToN 4: Minor

Est. End: 11/03/2020

Completion: 11/03/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FW OS 100, between os 106 and 104, MUSTERS ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	11/03/2020			10/03/2020

Works Ref: T1003MW500294716803

Version: 4

Work Desc: Clear duct blockage

Notice Type: Registration of Reinstatement - Full

Start: 19/03/2020 00:00:00

Work Status: Works Stopped

Issued: 06/04/2020 10:44:08

Work Type: EToN 4: Minor

Est. End: 23/03/2020

Completion: 23/03/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FW OS 100, between os 106 and 104, MUSTERS ROAD	Footway	Up to 1.5 Metres of Cover	1.10	0.50	A Permanent Reinstatement	23/03/2020		23/03/2020	20/03/2020

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Street Works Notices**Organisation:** BT (0030006)**Works Ref:** TI003MW500294961500**Version:** 4**Work Desc:** Locate and excavate 1 blockage in existing duct**Notice Type:** Registration of Reinstatement - Full**Start:** 16/03/2020 00:00:00**Work Status:** Works Stopped**Issued:** 31/03/2020 05:57:56**Work Type:** EToN 4: Minor**Est. End:** 18/03/2020**Completion:** 18/03/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FW OS 100, MUSTERS ROAD	Footway	Up to 1.5 Metres of Cover	0.60	0.60	A Permanent Reinstatement	18/03/2020		18/03/2020	17/03/2020

Works Ref: TI003MW500295618103**Version:** 4**Work Desc:** Locate and excavate 1 blockage in existing duct**Notice Type:** Registration of Reinstatement - Full**Start:** 26/03/2020 00:00:00**Work Status:** Works Stopped**Issued:** 15/04/2020 14:19:49**Work Type:** EToN 4: Minor**Est. End:** 30/03/2020**Completion:** 30/03/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FW OS 194, MUSTERS ROAD	Footway	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	30/03/2020		30/03/2020	27/03/2020

Works Ref: TI003MW500298389400**Version:** 5**Work Desc:** Locate and excavate 2 blockage in existing duct**Notice Type:** Registration of Reinstatement - Full**Start:** 18/05/2020 00:00:00**Work Status:** Works Stopped**Issued:** 03/06/2020 12:00:21**Work Type:** EToN 4: Minor**Est. End:** 20/05/2020**Completion:** 20/05/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN F/W O/S NO.184 AND THEN IN F/W O/S NO.186A, MUSTERS ROAD	Footway	Up to 1.5 Metres of Cover	1.00	0.60	A Permanent Reinstatement	20/05/2020		20/05/2020	19/05/2020
2	IN F/W O/S NO.184 AND THEN IN F/W O/S NO.186A, MUSTERS ROAD	Footway	Up to 1.5 Metres of Cover	0.50	0.40	A Permanent Reinstatement	20/05/2020		20/05/2020	

Works Ref: TI003MW500298459700**Version:** 5**Work Desc:** Locate and excavate 1 blockage in existing duct**Notice Type:** Registration of Reinstatement - Full**Start:** 27/05/2020 00:00:00**Work Status:** Works Stopped**Issued:** 11/06/2020 13:16:26**Work Type:** EToN 4: Minor**Est. End:** 29/05/2020**Completion:** 29/05/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN F/W O/S NO.4, MUSTERS ROAD	Footway	Up to 1.5 Metres of Cover	1.00	0.60	A Permanent Reinstatement	29/05/2020		29/05/2020	29/05/2020

Organisation: BT -MTS - ONSA (0030411)**Works Ref:** IBBGE3GF001**Version:** 3**Work Desc:** TRENTSIDE 758241 - POLING WORKS - Excavate for new BT Openreach Pole (s) or to Replace Existing BT Openreach Pole. Customer out of Service.**Notice Type:** Registration of Reinstatement - Full**Start:** 05/05/2020 09:30:00**Work Status:** Works Stopped**Issued:** 14/05/2020 12:32:08**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 05/05/2020**Completion:** 05/05/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OPP OF JNC OF BRIDGE GROVE ON MUSTERS ROAD	Footway	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	05/05/2020		05/05/2020	05/05/2020

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Street Works Notices**Organisation:** BT -MTS - ONSA (0030411)**Works Ref:** WBMJ191C001**Notice Type:** Registration of Reinstatement - Full**Work Status:** Works Stopped**Work Type:** EToN 4: Standard**Version:** 12**Start:** 02/09/2020 11:15:00**Issued:** 05/09/2020 14:25:04**Est. End:** 04/09/2020**Work Desc:** TRENTSIDE 777653 - POLING WORKS - Excavate for new BT Openreach Pole (s) or to Replace Existing BT Openreach Pole (s) in to facilitate overhead spine cabling works.**Completion:** 04/09/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	side of 214, musters road on musters road, Actual Depth: 1.6	Footway	Over 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	04/09/2020 01:00:00		04/09/2020 01:00:00	03/09/2020

Organisation: BT -Telent - NEMSA (0030210)**Works Ref:** MW00000500298440800**Notice Type:** Registration of Reinstatement - Full**Work Status:** Works Stopped**Work Type:** EToN 4: Minor**Version:** 7**Start:** 23/07/2020 08:00:00**Issued:** 07/08/2020 08:11:00**Est. End:** 27/07/2020**Work Desc:** Locate and excavate 1 blockage in existing duct**Completion:** 24/07/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN C/W, JCN SOUTH ROAD, MUSTERS ROAD, Actual Depth: 0.4	Footway	Up to 1.5 Metres of Cover	1.00	0.70	A Permanent Reinstatement	24/07/2020 01:00:00		24/07/2020 01:00:00	24/07/2020

Works Ref: MW00000500298459701**Notice Type:** Registration of Reinstatement - Full**Work Status:** Works Stopped**Work Type:** EToN 4: Minor**Version:** 5**Start:** 21/07/2020 12:59:00**Issued:** 05/08/2020 15:36:01**Est. End:** 23/07/2020**Work Desc:** Locate and excavate 1 blockage in existing duct**Completion:** 23/07/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN F/W O/S NO.4, MUSTERS ROAD, Actual Depth: 0.6	Footway	Up to 1.5 Metres of Cover	0.30	0.30	A Permanent Reinstatement	23/07/2020 01:00:00		23/07/2020 01:00:00	23/07/2020

Works Ref: MW00000500299466100**Notice Type:** Registration of Reinstatement - Full**Work Status:** Works Stopped**Work Type:** EToN 4: Minor**Version:** 5**Start:** 04/09/2020 09:01:00**Issued:** 04/09/2020 14:55:04**Est. End:** 07/09/2020**Work Desc:** Provide 1 new telegraph pole,Recover 1 existing telegraph pole**Completion:** 04/09/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 134, MUSTERS ROAD, Actual Depth: 1.6	Footway	Over 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	04/09/2020 01:00:00		04/09/2020 01:00:00	07/09/2020

Works Ref: MW00000500300285200**Notice Type:** Registration of Reinstatement - Full**Work Status:** Works Stopped**Work Type:** EToN 4: Minor**Version:** 7**Start:** 13/08/2020 14:39:00**Issued:** 27/08/2020 16:01:01**Est. End:** 17/08/2020**Work Desc:** Install 4m of 1 way poly duct in Footway,Locate and excavate 1 blockage in existing duct,Provide 1 core drill(s) into jointbox or building**Completion:** 14/08/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	WORKS BETWEEN OPP NO.99 TO OPP 111 ON, MUSTERS ROAD, Actual Depth: 0.35	Footway	Up to 1.5 Metres of Cover	3.00	0.40	A Permanent Reinstatement	14/08/2020 01:00:00		14/08/2020 01:00:00	14/08/2020

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Street Works Notices**Organisation:** BT -Telent - NEMSA (0030210)**Works Ref:** MW00000500300416900**Version:** 5**Work Desc:** Provide 1excavation to expose cable damage**Notice Type:** Registration of Reinstatement - Full**Start:** 28/07/2020 11:21:00**Work Status:** Works Stopped**Issued:** 12/08/2020 15:43:00**Work Type:** EToN 4: Minor**Est. End:** 30/07/2020**Completion:** 30/07/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	FW OS 134, MUSTERS ROAD, Actual Depth: 0.4	Footway	Up to 1.5 Metres of Cover	1.00	1.00 A Permanent Reinstatement	30/07/2020 01:00:00		30/07/2020 01:00:00	30/07/2020

Works Ref: MW00000500300418800**Version:** 3**Work Desc:** Locate and excavate 2 blockage in existing duct**Notice Type:** Cancellation**Start:** 28/07/2020 01:00:00**Work Status:** Abandoned Works**Issued:** 28/07/2020 11:33:00**Work Type:** EToN 4: Minor**Est. End:** 30/07/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	FW BETWEEN OS 138 AND OPP JNC RECTORY ROAD ON, MUSTERS ROAD (Footway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	28/07/2020 01:00:00			30/07/2020

Works Ref: MW00000500300522301**Version:** 10**Work Desc:** Locate and excavate 4 blockage in existing duct**Notice Type:** Registration of Reinstatement - Full**Start:** 04/08/2020 08:02:00**Work Status:** Works Stopped**Issued:** 18/08/2020 10:55:01**Work Type:** EToN 4: Standard**Est. End:** 05/08/2020**Completion:** 05/08/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	FW OS 204/206, OPP 179/181, DRIVEWAY OS 230/228, OS 246, MUSTERS ROAD, Actual Depth: 0.5	Footway	Up to 1.5 Metres of Cover	0.40	0.30 A Permanent Reinstatement	05/08/2020 01:00:00		05/08/2020 01:00:00	05/08/2020

Works Ref: MW00000500300612900**Version:** 3**Work Desc:** Locate and excavate 2 blockage in existing duct**Notice Type:** Cancellation**Start:** 10/08/2020 01:00:00**Work Status:** Abandoned Works**Issued:** 12/08/2020 08:03:00**Work Type:** EToN 4: Minor**Est. End:** 12/08/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	WORKS BETWEEN IN F/WAY OS NO. 196 TO JUNC WITH WORDSWORTH ROAD ON, MUSTERS ROAD (Footway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	10/08/2020 01:00:00			12/08/2020

Organisation: NCC - RUSHCLIFFE (3055008)**Works Ref:** 30703557**Version:** 2**Work Desc:** New Tree Pits and Trees Planted**Notice Type:** Revised Duration Estimate**Start:** 14/10/2019 00:00:00**Work Status:** Proposed Works**Issued:** 25/10/2019 10:18:05**Work Type:** EToN 4: Standard**Est. End:** 28/10/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Various Locations Along Musters Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	14/10/2019			25/10/2019

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Street Works Notices**Organisation:** NCC - RUSHCLIFFE (3055008)**Works Ref:** 6141901**Version:** 1**Work Desc:** Construct Vehicle Access**Notice Type:** 3 Day Initial Notice**Start:** 13/12/2019 00:00:00**Work Status:** Proposed Works**Issued:** 16/12/2019 08:44:09**Work Type:** EToN 4: Minor**Est. End:** 13/12/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside No. 151	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	13/12/2019			13/12/2019

Works Ref: 88959**Version:** 4**Work Desc:** Construct Vehicle Access**Notice Type:** Works Stop**Start:** 23/07/2020 00:00:00**Work Status:** Works Stopped**Issued:** 23/07/2020 15:36:53**Work Type:** EToN 4: Minor**Est. End:** 23/07/2020**Completion:** 23/07/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside No. 109	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	23/07/2020			23/07/2020

Organisation: Nottinghamshire Highway Works (3055042)**Works Ref:** 2724063**Version:** 3**Work Desc:** Footway repairs**Notice Type:** Works Stop**Start:** 26/09/2019 00:00:00**Work Status:** Works Stopped**Issued:** 26/09/2019 15:45:40**Work Type:** EToN 4: Minor**Est. End:** 30/09/2019**Completion:** 26/09/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Two areas - adjacent to L/C 24 and opposite L/C 25	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	26/09/2019			26/09/2019

Works Ref: 2725803RL**Version:** 3**Work Desc:** kerbing works**Notice Type:** Works Stop**Start:** 16/10/2019 00:00:00**Work Status:** Works Stopped**Issued:** 18/10/2019 10:08:52**Work Type:** EToN 4: Minor**Est. End:** 18/10/2019**Completion:** 17/10/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	outside 161 - lamp column 34	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	17/10/2019			18/10/2019

Works Ref: 2726663RL**Version:** 2**Work Desc:** footway repairs**Notice Type:** Cancellation**Start:** 11/11/2019 00:00:00**Work Status:** Abandoned Works**Issued:** 11/11/2019 11:17:33**Work Type:** EToN 4: Minor**Est. End:** 13/11/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	outside 257	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	11/11/2019			13/11/2019

Works Ref: 2726663TAL**Version:** 7**Work Desc:** footway repairs**Notice Type:** Works Stop**Start:** 07/11/2019 00:00:00**Work Status:** Works Stopped**Issued:** 18/11/2019 11:05:45**Work Type:** EToN 4: Minor**Est. End:** 16/11/2019**Completion:** 16/11/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	outside no. 257	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	16/11/2019			08/11/2019

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Street Works Notices

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: 2731668TAL

Version: 3

Work Desc: cw repairs

Notice Type: Works Stop

Start: 23/12/2019 00:00:00

Work Status: Works Stopped

Issued: 24/12/2019 13:17:34

Work Type: EToN 4: Minor

Est. End: 24/12/2019

Completion: 24/12/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Musters Rd	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	24/12/2019			24/12/2019

Works Ref: 2734533EW

Version: 3

Work Desc: Footpath slab relay

Notice Type: Works Stop

Start: 29/01/2020 00:00:00

Work Status: Works Stopped

Issued: 03/02/2020 10:45:03

Work Type: EToN 4: Minor

Est. End: 31/01/2020

Completion: 31/01/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside house no's 253/257/259/284/288/292 both sides before Jesse Gray School	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	31/01/2020			31/01/2020

Works Ref: 2751784

Version: 4

Work Desc: Footway repairs

Notice Type: Works Stop

Start: 14/09/2020 00:00:00

Work Status: Works Stopped

Issued: 14/09/2020 15:17:11

Work Type: EToN 4: Minor

Est. End: 16/09/2020

Completion: 14/09/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside house number 188 Musters Road - nearest L / C 31	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	14/09/2020			16/09/2020

Works Ref: 3002571RL

Version: 3

Work Desc: tree planting

Notice Type: Works Stop

Start: 28/11/2019 00:00:00

Work Status: Works Stopped

Issued: 29/11/2019 08:35:19

Work Type: EToN 4: Minor

Est. End: 02/12/2019

Completion: 28/11/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	outside 185	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	28/11/2019			02/12/2019

Works Ref: 3002919RL

Version: 3

Work Desc: tree planting

Notice Type: Works Stop

Start: 29/11/2019 00:00:00

Work Status: Works Stopped

Issued: 29/11/2019 08:26:03

Work Type: EToN 4: Minor

Est. End: 03/12/2019

Completion: 29/11/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	opposite 90	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	29/11/2019			02/12/2019

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Street Works Notices**Organisation:** NRSWA - BT (0030005)

Works Ref: CC1W00000WAQPW93X02 **Version:** 3 **Work Desc:** TM required for safe access to underground structure
Notice Type: Works Stop **Start:** 29/04/2020 00:00:00
Work Status: Works Stopped **Issued:** 29/04/2020 15:30:43
Work Type: EToN 4: Minor **Est. End:** 01/05/2020 **Completion:** 29/04/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Melton Road junction with Musters Road West Bidgford Nottinghamshire NG2 7JZ	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	29/04/2020			01/05/2020

Works Ref: CN17W00000EM0RQR67B **Version:** 2 **Work Desc:** SAFE ACCESS TO BOX IN CARRIAGEWAY BY WAY OF SIGNING AND GUARDING TO ALLOW RESTORATION OF CUSTOMER SERVICE ON FAULT NUMBER EM0RQR67- NO EXCAVATION. WORK TO TAKE PLACE BETWEEN 20.00 AND 06.00. ASSOCIATED NOTICE FOR 2 WAY LIGHTS ON MELTON ROAD
Notice Type: Works Stop **Start:** 07/01/2020 20:00:00
Work Status: Works Stopped **Issued:** 14/01/2020 10:48:50
Work Type: EToN 4: Immediate - Urgent **Est. End:** 11/01/2020 **Completion:** 11/01/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 64 MELTON ROAD TO SLIP ROAD TO MUSTERS ROAD WEST BRIDGFORD NOTTINGHAMSHIRE NG2 7PB	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	11/01/2020			11/01/2020

Organisation: NRSWA - Cadent Gas EM (0010001) (Street Works Admin Team NG Gas)

Works Ref: 1000827754 **Version:** 2 **Work Desc:** EMGA202043. CONNECTION PERMIT ONLY IN CONJUNCTION WITH GAS MAINSREPLACEMENT WORKS ON BROMLEY ROAD & SOUTH ROAD
Notice Type: Confirmation of Major **Start:** 16/09/2019 00:00:00
Work Status: Proposed Works **Issued:** 12/06/2019 14:45:24
Work Type: EToN 4: Major **Est. End:** 14/10/2019 **Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	JUNCTION OF BROMLEY ROAD & JUNCTION OF SOUTH ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	10/07/2019			10/07/2019

Works Ref: 1000923098 **Version:** 4 **Work Desc:** EGULATIONS 1994 EXCAVATE, DISCONNECT DOMESTIC GAS SUPPLY AND RE-INSTATE
Notice Type: Registration of Reinstatement - Full **Start:** 10/03/2020 00:00:00
Work Status: Works Stopped **Issued:** 12/03/2020 13:51:32
Work Type: EToN 4: Minor **Est. End:** 12/03/2020 **Completion:** 12/03/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 16A MUSTERS ROAD IN FOOTWAY AND CARRIAGEWAY	Footway	Up to 1.5 Metres of Cover	0.75	0.70	A Permanent Reinstatement	12/03/2020		12/03/2020	12/03/2020

Organisation: NRSWA - Virgin Media - National (7160100)

Works Ref: /NEMIRE/4390232 **Version:** -1 **Work Desc:** Unknown
Notice Type: Actual Start Date **Start:** 18/03/2013 00:00:00
Work Status: Proposed Works **Issued:** 18/03/2013 14:11:56
Work Type: Not Applicable **Est. End:** 01/01/4000 **Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside 315	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	16/03/2013		20/03/2013	20/03/2013

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Street Works Notices**Organisation:** NRSWA - Virgin Media - National (7160100)**Works Ref:** /NEMRBU/CX00046452**Version:** 4**Work Desc:** extend existing tee in the footway 9m and private carriageway**Notice Type:** Registration of Reinstatement - Full**Start:** 17/09/2019 00:00:00**Work Status:** Works Stopped**Issued:** 25/09/2019 11:09:30**Work Type:** EToN 4: Minor**Est. End:** 18/09/2019**Completion:** 18/09/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 69	Footway	Up to 1.5 Metres of Cover	1.50	0.30	A Permanent Reinstatement	18/09/2019		18/09/2019	18/09/2019

Works Ref: /NEMRBU/CX00049377**Version:** 4**Work Desc:** install swept tee in footway and extend duct 1m in footway towards customer premises**Notice Type:** Registration of Reinstatement - Full**Start:** 08/11/2019 00:00:00**Work Status:** Works Stopped**Issued:** 19/11/2019 13:19:39**Work Type:** EToN 4: Minor**Est. End:** 12/11/2019**Completion:** 12/11/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	23 Musters Road, NG2 7PP	Carriageway	Up to 1.5 Metres of Cover	1.00	0.30	A Permanent Reinstatement	12/11/2019		12/11/2019	12/11/2019

Works Ref: /NEMTRE/NE03153**Version:** -1**Work Desc:** Unknown**Notice Type:** Actual Start Date**Start:** 25/02/2010 00:00:00**Work Status:** Proposed Works**Issued:** 25/02/2010 07:35:41**Work Type:** Not Applicable**Est. End:** 01/01/4000**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	o/s 189	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	25/02/2010		25/02/2010	01/03/2010

Works Ref: /NYNLRE/0330862**Version:** 4**Work Desc:** LOCATE TEE**Notice Type:** Registration of Reinstatement - Full**Start:** 24/09/2019 00:00:00**Work Status:** Works Stopped**Issued:** 25/09/2019 01:01:32**Work Type:** EToN 4: Minor**Est. End:** 26/09/2019**Completion:** 24/09/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE FLAT 7 88-90	Footway	Up to 1.5 Metres of Cover	1.20	0.40	A Permanent Reinstatement	24/09/2019		24/09/2019	26/09/2019

Organisation: Section 50 Rushcliffe (9999008)**Works Ref:** R19657**Version:** 1**Work Desc:** Installation of HV cable to connect to existing network**Notice Type:** 3 Month Initial Notice**Start:** 02/03/2020 00:00:00**Work Status:** Proposed Works**Issued:** 29/01/2020 10:06:00**Work Type:** EToN 4: Major**Est. End:** 20/03/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside 362 Musters Road, West Bridgford	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	02/03/2020			20/03/2020

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Street Works Notices**Organisation:** Severn Trent Integra Utility Services (9103906)

Works Ref: 0000/00004489398	Version: 4	Work Desc: INSTALL NEW MTR AND BBOX DIG IS A METER BY A METER SQUARE WE INTEND TO USE PERMASOIL
Notice Type: Registration of Reinstatement - Full	Start: 12/02/2020 00:00:00	
Work Status: Works Stopped	Issued: 12/02/2020 16:06:58	
Work Type: EToN 4: Minor	Est. End: 14/02/2020	Completion: 12/02/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	ROAD OPENING AND DIG IS TAKING PLACE IN FOOTWAY OUTSIDE NUMBER 312	Footway	Up to 1.5 Metres of Cover	0.60	0.60 A Permanent Reinstatement	12/02/2020		12/02/2020	14/02/2020

Works Ref: 0000/00008215198	Version: -1	Work Desc: Unknown
Notice Type: Actual Start Date	Start: 03/03/2013 00:00:00	
Work Status: Proposed Works	Issued: 04/03/2013 09:29:27	
Work Type: Not Applicable	Est. End: 01/01/4000	Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	358	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	03/03/2013		03/03/2013	05/03/2013

Organisation: Severn Trent New Connections East - Water (9103920)

Works Ref: 5101/000006521382	Version: 9	Work Desc: Ex Long >12m Full Ex 25mm MDPE New Water Connection - 2 x 25mm MDPE service from boundary to 3in CI main located in the footpath Job in Carriageway (10mm Bitmac (Tarmac))
Notice Type: Registration of Reinstatement - Full	Start: 06/07/2020 00:00:00	
Work Status: Works Stopped	Issued: 22/07/2020 12:36:37	
Work Type: EToN 4: Standard	Est. End: 09/07/2020	Completion: 09/07/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 75	Footway	Up to 1.5 Metres of Cover	2.50	0.35 A Permanent Reinstatement	09/07/2020		09/07/2020	09/07/2020
2	OUTSIDE 75	Footway	Up to 1.5 Metres of Cover	0.95	0.85 A Permanent Reinstatement	09/07/2020		09/07/2020	
3	OUTSIDE 73	Footway	Up to 1.5 Metres of Cover	0.70	0.60 A Permanent Reinstatement	09/07/2020		09/07/2020	
4	OUTSIDE 75	Carriageway	Up to 1.5 Metres of Cover	4.20	0.50 A Permanent Reinstatement	09/07/2020		09/07/2020	
5	OUTSIDE 73	Carriageway	Up to 1.5 Metres of Cover	4.40	0.50 A Permanent Reinstatement	09/07/2020		09/07/2020	
6	OPPOSITE 73	Carriageway	Up to 1.5 Metres of Cover	3.85	0.45 A Permanent Reinstatement	09/07/2020		09/07/2020	
7	OPPOSITE 75	Carriageway	Up to 1.5 Metres of Cover	3.85	0.45 A Permanent Reinstatement	09/07/2020		09/07/2020	
8	OUTSIDE 73	Footway	Up to 1.5 Metres of Cover	2.70	0.35 A Permanent Reinstatement	09/07/2020		09/07/2020	
11	OPPOSITE 73	Footway	Up to 1.5 Metres of Cover	2.00	0.65 A Permanent Reinstatement	09/07/2020		09/07/2020	
12	OPPOSITE 75	Footway	Up to 1.5 Metres of Cover	1.60	0.55 A Permanent Reinstatement	09/07/2020		09/07/2020	

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Street Works Notices

Organisation: Severn Trent Water East (9103908)

Works Ref: 1101/000010522834A

Version: -1

Work Desc: Unknown

Notice Type: Actual Start Date

Start: 30/01/2013 00:00:00

Work Status: Proposed Works

Issued: 30/01/2013 11:43:53

Work Type: Not Applicable

Est. End: 01/01/4000

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	233 MUSTERS ROAD	Footway	Up to 1.5 Metres of Cover	1.20	0.80	A Permanent Reinstatement	01/02/2013		01/02/2013	01/02/2013

Works Ref: 1101/000012303255

Version: 6

Work Desc: Small Main Repair Collar 6" LEAKING Job in Footway (6mm Bitmac (Tarmac))

Notice Type: Registration of Reinstatement - Full

Start: 09/11/2019 08:54:00

Work Status: Works Stopped

Issued: 10/12/2019 09:17:41

Work Type: EToN 4: Immediate - Urgent

Est. End: 06/12/2019

Completion: 06/12/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	316	Footway	Up to 1.5 Metres of Cover	1.80	1.30	A Permanent Reinstatement	09/11/2019		09/11/2019	13/11/2019

Works Ref: 1101/000012307265

Version: 5

Work Desc: Long Comm Pipe Cut Off 0.75" Job in Footway (6mm Bitmac (Tarmac))

Notice Type: Registration of Reinstatement - Full

Start: 03/12/2019 00:00:00

Work Status: Works Stopped

Issued: 05/12/2019 08:54:24

Work Type: EToN 4: Minor

Est. End: 05/12/2019

Completion: 04/12/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	134	Footway	Up to 1.5 Metres of Cover	1.10	1.00	A Permanent Reinstatement	04/12/2019		04/12/2019	04/12/2019

Works Ref: 1101/000012334005

Version: 4

Work Desc: Boundary box Install 25mm Job in Footway (Flags (area))

Notice Type: Registration of Reinstatement - Full

Start: 22/01/2020 00:00:00

Work Status: Works Stopped

Issued: 28/01/2020 13:26:10

Work Type: EToN 4: Minor

Est. End: 24/01/2020

Completion: 23/01/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	274	Footway	Up to 1.5 Metres of Cover	1.00	0.80	A Permanent Reinstatement	23/01/2020		23/01/2020	24/01/2020

Works Ref: 1101/000012385349

Version: 4

Work Desc: Small Main Repair Collar 6" Stop visible or significant leakage Job in Footway (Flags (area))

Notice Type: Registration of Reinstatement - Full

Start: 26/02/2020 10:52:00

Work Status: Works Stopped

Issued: 10/03/2020 08:41:06

Work Type: EToN 4: Immediate - Urgent

Est. End: 02/03/2020

Completion: 02/03/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OPPOSITE NO.298	Footway	Up to 1.5 Metres of Cover	1.60	1.60	A Permanent Reinstatement	01/03/2020		01/03/2020	28/02/2020
2	OPPOSITE NO.298	Footway	Up to 1.5 Metres of Cover	2.80	1.60	A Permanent Reinstatement	01/03/2020		01/03/2020	
3	OPPOSITE NO.298	Footway	Up to 1.5 Metres of Cover	1.60	1.60	A Permanent Reinstatement	01/03/2020		01/03/2020	

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Street Works Notices**Organisation:** Severn Trent Water East (9103908)**Works Ref:** 1101/000060305282**Version:** 3**Work Desc:** Long Comm Pipe Repair 25mm Job in Footway (Red Tarmac)**Notice Type:** Registration of Reinstatement - Full**Start:** 26/09/2019 14:02:00**Work Status:** Works Stopped**Issued:** 03/10/2019 15:30:47**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 30/09/2019**Completion:** 30/09/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	302, MUSTERS ROAD, NG2 7DF	Footway	Up to 1.5 Metres of Cover	3.00	0.80 A Permanent Reinstatement	30/09/2019		30/09/2019	30/09/2019
2	302, MUSTERS ROAD, NG2 7DF	Footway	Up to 1.5 Metres of Cover	1.60	1.00 A Permanent Reinstatement	30/09/2019		30/09/2019	

Works Ref: 1101/000073382009**Version:** 2**Work Desc:** Air valve Rebuild chamber Job in Footway (6mm Bitmac (Tarmac)**Notice Type:** Cancellation**Start:** 13/01/2020 00:00:00**Work Status:** Abandoned Works**Issued:** 15/01/2020 14:40:53**Work Type:** EToN 4: Minor**Est. End:** 15/01/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	O/S 136	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	13/01/2020			15/01/2020

Works Ref: 1101/000073382009A**Version:** 3**Work Desc:** Air valve Rebuild chamber Job in Verge (Grass)**Notice Type:** Works Stop**Start:** 22/01/2020 00:00:00**Work Status:** Works Stopped**Issued:** 22/01/2020 09:11:08**Work Type:** EToN 4: Minor**Est. End:** 24/01/2020**Completion:** 22/01/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	O/S 136	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	22/01/2020			24/01/2020

Works Ref: 1101-000012486006**Version:** 5**Work Desc:** HV Boundary box Install 25mm**Notice Type:** Registration of Reinstatement - Full**Start:** 09/07/2020 11:07:00**Work Status:** Works Stopped**Issued:** 16/07/2020 14:08:26**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 13/07/2020**Completion:** 13/07/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	326, MUSTERS ROAD, NG2 7DF, Actual Depth: 1	Footway	Up to 1.5 Metres of Cover	1.40	0.80 Remedial Reinstatement (YES Guar. Reset)	13/07/2020 12:31:50		13/07/2020 12:31:50	13/07/2020

Works Ref: 1101-000012490540**Version:** 7**Work Desc:** HV Short Comm pipe Renew 25mm**Notice Type:** Registration of Reinstatement - Full**Start:** 15/07/2020 10:48:00**Work Status:** Works Stopped**Issued:** 21/07/2020 14:55:08**Work Type:** EToN 4: Minor**Est. End:** 17/07/2020**Completion:** 17/07/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	126, MUSTERS ROAD, NG2 7PW, Actual Depth: 1	Footway	Up to 1.5 Metres of Cover	1.90	0.50 A Permanent Reinstatement	17/07/2020 11:14:50		17/07/2020 11:14:50	17/07/2020

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Street Works Notices**Organisation:** Virgin Media - North Midland Construction (7160106)**Works Ref:** EMID160418A**Version:** 5**Work Desc:** Excavate in footway to clear blocked tee and or replace if damaged**Notice Type:** Registration of Reinstatement - Full**Start:** 22/07/2020 08:10:00**Work Status:** Works Stopped**Issued:** 22/07/2020 08:59:32**Work Type:** EToN 4: Minor**Est. End:** 24/07/2020**Completion:** 22/07/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside number 49, Actual Depth: 1	Footway	Up to 1.5 Metres of Cover	0.40	0.40 A Permanent Reinstatement	22/07/2020		22/07/2020	24/07/2020

Organisation: WPD 5154 Keyworth (7011554)**Works Ref:** 9520385**Version:** 7**Work Desc:** Urgent excavation in highway to locate and repair LV cable fault.**Notice Type:** Registration of Reinstatement - Full**Start:** 05/08/2020 01:59:00**Work Status:** Works Stopped**Issued:** 19/08/2020 09:48:11**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 10/08/2020**Completion:** 10/08/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 82 MUSTERS ROAD, Actual Depth: 0.3	Footway	Up to 1.5 Metres of Cover	1.30	1.00 A Permanent Reinstatement	10/08/2020		10/08/2020	11/08/2020

Works Ref: M51542162696B**Version:** 4**Work Desc:** 1 joint hole in tarmac footway for link box replacement/installation - with excavation. Works in conjunction with DY554M51542162696A**Notice Type:** Registration of Reinstatement - Full**Start:** 16/11/2019 00:00:00**Work Status:** Works Stopped**Issued:** 04/12/2019 10:54:59**Work Type:** EToN 4: Standard**Est. End:** 21/11/2019**Completion:** 21/11/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside 27	Footway	Up to 1.5 Metres of Cover	2.00	1.50 A Permanent Reinstatement	21/11/2019		21/11/2019	21/11/2019

Works Ref: M51542196578**Version:** 2**Work Desc:** 1 joint hole in tarmac footway for disconnection of supply**Notice Type:** Cancellation**Start:** 01/04/2020 00:00:00**Work Status:** Abandoned Works**Issued:** 01/04/2020 14:42:34**Work Type:** EToN 4: Minor**Est. End:** 03/04/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside 109	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	01/04/2020			03/04/2020

Works Ref: M51542207513**Version:** 7**Work Desc:** Urgent excavation in highway to locate and repair LV cable fault.**Notice Type:** Registration of Reinstatement - Full**Start:** 13/05/2020 11:00:00**Work Status:** Works Stopped**Issued:** 19/05/2020 08:15:56**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 15/05/2020**Completion:** 15/05/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside 77	Footway	Up to 1.5 Metres of Cover	3.60	0.60 A Permanent Reinstatement	15/05/2020		15/05/2020	19/05/2020
2	Outside 77	Footway	Up to 1.5 Metres of Cover	2.10	1.10 A Permanent Reinstatement	15/05/2020		15/05/2020	
3	Outside 77	Footway	Up to 1.5 Metres of Cover	2.00	1.00 A Permanent Reinstatement	15/05/2020		15/05/2020	

Effective: 14/09/2019 to 14/09/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Musters Road (33001240)

Street Works Notices

Organisation: WPD 5154 Keyworth (7011554)

Works Ref: M51542212774

Version: 4

Work Desc: 1 joint hole in tarmac footway for disconnection of supply

Notice Type: Registration of Reinstatement - Full

Start: 17/06/2020 00:00:00

Work Status: In Progress

Issued: 23/06/2020 16:50:12

Work Type: EToN 4: Minor

Est. End: 19/06/2020

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside 109	Footway	Up to 1.5 Metres of Cover	4.20	1.00 A Permanent Reinstatement	19/06/2020		19/06/2020	19/06/2020