

Effective: 09/01/2017 to 09/01/2018  
Street: Wheatgrass Hill (26813993)

Display Action Officer: No

Street: Wheatgrass Hill (26813993)

Locality: Hockerton, Nottinghamshire

Area: Newark

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> A617 - End Of Newark Road, Hockerton To Hockerton Road			<b>Feature Type:</b> Street Section			<b>Area:</b> Newark	
<b>Batch:</b> 20260343 - Inspection Batch			<b>Route:</b> Newark Area 2 Dec Saf CW				<b>Date:</b> 27/12/2017	
No actionable defects found								
<b>Batch:</b> 20253688 - Inspection Batch			<b>Route:</b> Newark Area 2 Nov Saf CW				<b>Date:</b> 07/11/2017	
No actionable defects found								
<b>Batch:</b> 20252692 - Inspection Batch			<b>Route:</b> Adhoc Inspection				<b>Date:</b> 01/11/2017	
3558528	x 2 pothole repairs cat 1 high , photo's attached	01/11/2017	outside Brooklyn Care Homes Ltd	CW Repairs-Bituminous	Internal		Uncommitt	2661250
<b>Batch:</b> 20252616 - Inspection Batch			<b>Route:</b> Adhoc Inspection				<b>Date:</b> 01/11/2017	
3558507	cat 1high repair .. when found	01/11/2017	outside Brooklyn House Care Ltd.	CW Repairs-Bituminous	Internal		Uncommitt	2661227
<b>Batch:</b> 20248789 - Inspection Batch			<b>Route:</b> Newark Area 2 Oct Saf CW				<b>Date:</b> 05/10/2017	
No actionable defects found								
<b>Batch:</b> 20246165 - Inspection Batch			<b>Route:</b> Newark Area 2 Sep Saf CW				<b>Date:</b> 18/09/2017	
No actionable defects found								
<b>Batch:</b> 20241677 - Inspection Batch			<b>Route:</b> Newark Area 2 Aug Saf CW				<b>Date:</b> 15/08/2017	
No actionable defects found								
<b>Batch:</b> 20239150 - Inspection Batch			<b>Route:</b> Newark Area 2 Jul Saf CW				<b>Date:</b> 24/07/2017	
No actionable defects found								
<b>Batch:</b> 20233816 - Inspection Batch			<b>Route:</b> Newark Area 2 Jun Saf CW				<b>Date:</b> 13/06/2017	
No actionable defects found								
<b>Batch:</b> 20231868 - Inspection Batch			<b>Route:</b> Newark Area 2 May Enh CW/FW				<b>Date:</b> 31/05/2017	
No actionable defects found								
<b>Batch:</b> 20225912 - Inspection Batch			<b>Route:</b> Newark Area 2 Apr Saf CW				<b>Date:</b> 20/04/2017	
No actionable defects found								
<b>Batch:</b> 20219579 - Inspection Batch			<b>Route:</b> Newark Area 2 Mar Saf CW				<b>Date:</b> 03/03/2017	
No actionable defects found								
<b>Batch:</b> 20216005 - Inspection Batch			<b>Route:</b> Newark Area 2 Feb Saf CW				<b>Date:</b> 09/02/2017	
No actionable defects found								
<b>Batch:</b> 20211421 - Inspection Batch			<b>Route:</b> Newark Area 2 Jan Saf CW				<b>Date:</b> 09/01/2017	
No actionable defects found								
<b>Feat No.:</b> 3,500.00	<b>Feature Id - Locn.:</b> chevron			<b>Feature Type:</b> Non-Illum Sign - 1 Post			<b>Area:</b> Newark	
<b>Batch:</b> 20659893 - Inspection Batch			<b>Route:</b> Ad Hoc SL Countywide				<b>Date:</b> 23/10/2017	
No actionable defects found								
<b>Feat No.:</b> 8,000.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Top Entry			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/08/2017	
No actionable defects found								

Effective: 09/01/2017 to 09/01/2018  
Street: Wheatgrass Hill (26813993)

Display Action Officer: No

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 8,001.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Top Entry			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection				<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/08/2017
No actionable defects found								
<b>Feat No.:</b> 8,002.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Top Entry			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection				<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/08/2017
No actionable defects found								
<b>Feat No.:</b> 8,003.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Top Entry			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection				<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/08/2017
No actionable defects found								
<b>Feat No.:</b> 8,004.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Top Entry			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection				<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/08/2017
No actionable defects found								
<b>Feat No.:</b> 8,005.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Top Entry			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection				<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/08/2017
No actionable defects found								
<b>Feat No.:</b> 8,006.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Top Entry			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection				<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/08/2017
No actionable defects found								
<b>Feat No.:</b> 8,007.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection				<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/08/2017
No actionable defects found								
<b>Feat No.:</b> 8,008.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection				<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/08/2017
No actionable defects found								
<b>Feat No.:</b> 8,009.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection				<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/08/2017
No actionable defects found								

### Customer Services

**Enquiry No.:** 6071485 **Logged by:** External to Confirm **on:** 28/11/2017 07:30  
**Service:** Carriageway/Footway **Subject:** Carriageway Obstruction **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-62885119  
**Desc.:** Road obstructions - Abandoned traffic lights. Nobody has done any work on this road since they've been here. . Online report  
**Location:** See map coordinates and description details **Contact:**

**Enquiry No.:** 6070788 **Logged by:** External to Confirm **on:** 20/11/2017 13:21  
**Service:** Carriageway/Footway **Subject:** Temporary Traffic Lights **Classification:** Service Request **Enquiry Ref:** FS-CASE-62369497  
**Desc.:** Temporary Traffic lights (roadworks) issue - These traffic lights have been up for weeks but no work is being undertaken . Submitted by Advisor: Jason Gutteridge  
**Location:** See map coordinates and description details **Contact:**

Effective: 09/01/2017 to 09/01/2018  
Street: Wheatgrass Hill (26813993)

Display Action Officer: No

### Customer Services

**Enquiry No.:** 6069309      **Logged by:** External to Confirm      **on:** 06/11/2017 08:30  
**Service:** Carriageway/Footway      **Subject:** Temporary Traffic Lights      **Classification:** Service Request      **Enquiry Ref:** FS-CASE-61487507  
**Desc.:** Temporary Traffic lights (roadworks) issue - Brooklyn Care homes on Wheatgrass Hill in Hockerton. Outside the care home there are temporary traffic lights. These have failed causing a backlog of traffic. Police are on site to direct traffic but can someone please go out to fix them. The care home is situated 300 yards past the Hockerton Road turning to southwell going towards newark. . Submitted by Advisor: Nathan Laverty  
**Location:** See map coordinates and description details      **Contact:**

**Enquiry No.:** 6064113      **Logged by:** External to Confirm      **on:** 14/09/2017 09:50  
**Service:** Road Works      **Subject:** Road Works Report      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-58703984  
**Desc.:** Road work issue - Continuous water rising slowly through the road surface, especially at seams in the surface, at multiple locations on the eastbound lane. The road surface is always wet, even in dry weather. , sometimes enough to cause spray from tyres. This is a potential hazard in the event of freezing weather (ice) and is inevitably causing damage to the road subsurface (not potholing yet, but once it does a patch repair won't stick in continuously wet conditions!), with serious risk of breakup in the event of freezing weather in the winter. It could be a water main leak (there have been at least 3 incidences of water main repair on the hill in the last 2 years) but equally, given the variable nature, could be groundwater rising up and requiring new drainage. It requires investigation & a plan to correct, by whichever authority is responsible (water or highways). This really needs to be completed before cold weather starts, to eliminate an avoidable hazard on a main route through the county. This fault has been present for at least 6 months, but has become more noticeable over the summer.

As an aside, there is a design flaw in your webform - it doesn't accept the full form of a phone number, which of course begins with '+' (in my case, +44); I have to work worldwide so naturally default to the full form with country prefix, for clarity. You therefore exclude people who may have a non-Uk phone number, which is not a good welcome to visitors (perhaps regularly around here, e.g. for business or family, with a mobile from another country) who want to help by participating in local processes such as fault reporting Please keep up with the reality of modern communication, guys! . Online report

**Location:** See map coordinates and description details      **Contact:**

**Enquiry No.:** 6060067      **Logged by:** External to Confirm      **on:** 01/08/2017 12:15  
**Service:** Traffic Management      **Subject:** Speed Limits/Issues      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-56741460  
**Desc.:** Speed limits - Following request for information received via email at CSC Travelling along the A617 towards Newark, the road is a 50 mph limit punctuated by signs saying it's 50 for a reason speed kills. As speed patently does not kill, as evidenced by none of the 500mph aeroplanes dropping out of the sky. I would like to know what the reason is . Submitted by Advisor: Claire Shockledge -  
**Location:** See map coordinates and description details      **Contact:**

**Enquiry No.:** 6051716      **Logged by:** External to Confirm      **on:** 03/05/2017 20:18  
**Service:** Carriageway/Footway      **Subject:** Carriageway Obstruction      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-51706732  
**Desc.:** Road obstructions - hi, not really an obstruction but cannot find what I need. in this area you will see a couple of road cones in the verge area where a lorry slid off the road a few weeks ago when I reported it, it damaged a sign which has been fixed but the verge is still a danger as it has all sunk and now needs filling back up which is what I said previously then the cones can be removed with the edge of the road back in tact. thanks . Online report  
**Location:** See map coordinates and description details      **Contact:**

**Enquiry No.:** 6045776      **Logged by:** External to Confirm      **on:** 06/03/2017 22:52  
**Service:** Carriageway/Footway      **Subject:** Verge Damage      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-13726167  
**Desc.:** Street/road sign damage - sign damaged and laying in field . Online report  
**Location:** See map coordinates and description details      **Contact:**

**Enquiry No.:** 3205236      **Logged by:** Andre Lovatt      **on:** 01/11/2017 11:52  
**Service:** Carriageway/Footway      **Subject:** Flooding      **Classification:** Report or Observation  
**Desc.:** burst water main  
**Location:** outside Brooklyn Care Homes Ltd      **Contact:** Checked On

**Plot Number:** 2,000.00      **Feature Id - Location:** A617 - End Of Newark Road, Hockerton To Hockerton Road Jur      **Feature Type:** Street Section

Effective: 09/01/2017 to 09/01/2018  
Street: Wheatgrass Hill (26813993)

Display Action Officer: No

### Customer Services

**Enquiry No.:** 64863      **Logged by:** Rosie Heald      **on:** 24/07/2017 10:18  
**Service:** Highway Searches      **Subject:** Extents and CON29      **Classification:** Report or Observation  
**Desc.:** received      - 24.7.17  
**Location:** Lodge Farm off Wheatgrass Hill, Upton, Newark NG23 5TJ      **Contact:**

**Enquiry No.:** 60588      **Logged by:** Rosie Heald      **on:** 06/03/2017 15:02  
**Service:** Highway Searches      **Subject:** Adoption Extents      **Classification:** Report or Observation  
**Desc.:** requested      6.3.17 - received 9.3.17  
**Location:** land on the south side of Wheatgrass Hill, Hockerton      **Contact:**

### Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> A617 - End Of Newark Road, Hockerton To Hockerton Road Jur			<b>Feature Type:</b> Street Section		<b>Area:</b> Newark	
2661227	cat 1high repair .. when found (CW Repairs-Bituminous)	outside Brooklyn House Care Ltd.	Filled when found (Cat 1)	Job Completed	01/11/2017	01/11/2017	Act.
2661250	x 2 pothole repairs cat 1 high , photo's attached (CW Repairs-Bituminous)	outside Brooklyn Care Homes Ltd	Filled when found (Cat 1)	Job Completed	01/11/2017	01/11/2017	Act.

### Street Works Inspections

**Organisation:** Nottinghamshire (3055001)

**Works Ref:** LCGS24082017135932

**Group No:** 1      **Site No:** 1      **Street Authority:** Nottinghamshire      **Inspected:** 24/08/2017 13:59:32  
**Category:** Apparatus      **Outcome:** Failed (Lower Risk/Non Dangerous)      **Sampled:** No  
**Defect Notif. No:** 11300685      **Defect No:** 11300685      **Tel:** 07557895771      **Site Informed:** Yes      **Sampled Site No:**  
**Insp. Notes:** please attend to assess source of the leak      **Site Location:** on A617 Hockerton - Wheatgrass Hill grid ref x 472327 y 356033  
**Defect Notes:** please attend to assess source of the leak      **Position:** Carriageway      **Sign./Light./Guard. Inadequacy:** No  
**Site Post Code:**

### Street Works Notices

**Organisation:** Nottinghamshire (3055001)

**Works Ref:** LCGS24082017135932

**Version:** 1

**Work Desc:** visible water on the c/way following reinstatement

**Notice Type:** Defective Apparatus

**Start:** 24/08/2017 00:00:00

**Work Status:** In Progress

**Issued:** 24/08/2017 13:59:34

**Work Type:** Not Applicable

**Est. End:** 24/08/2017

**Completion:** 24/08/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop.	End
1	on A617 Hockerton - Wheatgrass Hill grid ref x 472327 y 356033	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	24/08/2017				

Effective: 09/01/2017 to 09/01/2018  
Street: Wheatgrass Hill (26813993)

Display Action Officer: No

### Street Works Notices

**Organisation:** Nottinghamshire Highway Works (3055042)

**Works Ref:** 40808042

**Version:** 3

**Work Desc:** Water Leak under the carriageway compromising the integrity of the highway

**Notice Type:** Revised Duration Estimate

**Start:** 01/11/2017 00:00:00

**Work Status:** Proposed Works

**Issued:** 28/11/2017 14:53:02

**Work Type:** EToN 4: Standard

**Est. End:** 30/11/2017

**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Top of Wheatgrass Hill	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	01/11/2017			13/11/2017

**Organisation:** Severn Trent Water East (9103908)

**Works Ref:** 1101/000011708781

**Version:** 6

**Work Desc:** Burst on Private repair Working under County Council Traffic Lights Job in Carriageway (Hot Rolled Asphalt-30/14 )

**Notice Type:** Registration of Reinstatement - Full

**Start:** 28/11/2017 00:00:00

**Work Status:** Works Stopped

**Issued:** 06/12/2017 11:29:52

**Work Type:** EToN 4: Minor

**Est. End:** 30/11/2017

**Completion:** 29/11/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	(OPPOSITE) 60M WEST FROM ENTRANCE TO LODGE FARM	Carriageway	Up to 1.5 Metres of Cover	1.30	1.20	A Permanent Reinstatement	29/11/2017		29/11/2017	30/11/2017

**Works Ref:** 1101/000060211999

**Version:** 6

**Work Desc:** Long Comm Pipe Repair 2" Job in Verge (Grass )

**Notice Type:** Registration of Reinstatement - Full

**Start:** 27/03/2017 13:19:00

**Work Status:** Works Stopped

**Issued:** 04/04/2017 14:00:55

**Work Type:** EToN 4: Immediate - Urgent

**Est. End:** 31/03/2017

**Completion:** 31/03/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	50M WEST OF LODGE FARM, WHEATGRASS HILL, HOCKERTON, NG23 5TJ	Carriageway	Up to 1.5 Metres of Cover	1.20	1.10	A Permanent Reinstatement	31/03/2017		31/03/2017	29/03/2017
2	50M WEST OF LODGE FARM, WHEATGRASS HILL, HOCKERTON, NG23 5TJ	Verge	Up to 1.5 Metres of Cover	2.70	1.20	A Permanent Reinstatement	31/03/2017		31/03/2017	