

Effective: 01/03/2015 to 31/03/2017

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Burleigh Road (33000732)

Street: Burleigh Road (33000732)

Locality: West Bridgford, Nottinghamshire

Area: Rushcliffe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: From Burleigh Road to Stamford Road			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20222261 - Inspection Batch				Route: Adhoc Inspection				Date: 27/03/2017
3545277	HWIA - Carriageway defects marked up to be made safe	27/03/2017	From outside house number 18 & towards the junction with Gordon Road	CW Repairs-Bituminous	Internal		Committed	2647063
Batch: 20222241 - Inspection Batch				Route: Adhoc Inspection				Date: 20/03/2017
3545268	Carriageway defect made safe during inspection .	20/03/2017	Outside house number 65	CW Repairs-Bituminous	Internal		Uncommitt	2647054
Batch: 20215591 - Inspection Batch				Route: Rush Area 2 Feb Enh CW/FW				Date: 09/02/2017
3541839	HWIA - defects marked up for the Assistants	07/02/2017	On the T junction with Dunster Road adjacent with L / C 13	CW Repairs-Bituminous	Internal		Committed	2643556
Batch: 20204712 - Inspection Batch				Route: Adhoc Inspection				Date: 10/11/2016
3537469	Defect has been made safe during inspection .	10/11/2016	Outside house number 47	CW Repairs-Bituminous	Internal		Uncommitt	2638966
Batch: 20192157 - Inspection Batch				Route: Adhoc Inspection				Date: 05/08/2016
3533127	Defect made safe .	05/08/2016	Outside house number 30	CW Repairs-Bituminous	Internal		Uncommitt	2634284
Batch: 20180176 - Inspection Batch				Route: Adhoc Inspection				Date: 13/05/2016
3529046	Defects made safe at time of inspection .	13/05/2016	Outside house number 2	CW Repairs-Bituminous	Internal		Uncommitt	2630030
Batch: 20173596 - Inspection Batch				Route: Adhoc Inspection				Date: 01/04/2016
3526365	Defect made safe at time of inspection	01/04/2016	Outside house number 18	HW CW Pothole Z1	Internal		Uncommitt	2627313
Batch: 20173595 - Inspection Batch				Route: Adhoc Inspection				Date: 01/04/2016
3526364	Tree roots pushing up tarmaced on footpath (4 sqm) which requires damaged Tarmac excavating and wearing course reinstating around the tree pit - marked up at time of inspection .	01/04/2016	Outside house number 41	HW FW Tree root uplift Z5	Internal		Committed	2627312
Batch: 20165949 - Inspection Batch				Route: Adhoc Inspection				Date: 09/02/2016
3523047	Defects made safe at time of inspection	09/02/2016	Junction with Burleigh / Dunster road	HW CW Pothole Z1	Internal		Uncommitt	2623947
Batch: 20164858 - Inspection Batch				Route: Rush Area 2 Feb Enh CW/FW				Date: 03/02/2016
3522621	Defects made safe at time of inspection	02/02/2016	Outside house numbers 42 & 18	HW CW Pothole Z1	Internal		Uncommitt	2623509
Batch: 20162182 - Inspection Batch				Route: Adhoc Inspection				Date: 18/01/2016
3521550	Two areas that have been made safe at time of inspection .	18/01/2016	On the junction with Melton Rd & outside house number 2A	HW CW Pothole Z1	Internal		Uncommitt	2622408
Batch: 20157576 - Inspection Batch				Route: Adhoc Inspection				Date: 09/12/2015
3519832	Defect made safe at time of inspection	09/12/2015	Outside house number 2	HW CW Pothole Z1	Internal		Uncommitt	2620652
Batch: 20144336 - Inspection Batch				Route: Adhoc Inspection				Date: 14/09/2015
3515320	Gullies X 2 opposite each other at the mentioned location fully silted causing standing water over Tac Tile crossing . Another area that ACL have missed .	14/09/2015	Near too L / C 1 - adjacent to the Junction with Melton Rd	HW DR Blocked Gully Z3	Internal		Committed	2615969

Effective: 01/03/2015 to 31/03/2017

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Burleigh Road (33000732)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: From Burleigh Road to Stamford Road			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20121284 - Inspection Batch				Route: Adhoc Inspection				Date: 02/04/2015
3507763	Defects made safe at time of inspection - no further action required .	02/04/2015	Juntion of Burleigh / Cambridge Rd	HW CW Pothole Z1	Internal		Committed	2608089

Customer Services

Enquiry No.: 6048132	Logged by: External to Confirm	on: 25/03/2017 10:17					Enquiry Ref: FS-CASE-50327883
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation					
Desc.: Road Pothole - Pothole right on junction of Burleigh Rd and Melton Road . Online report							
Location: See map coordinates and description details		Contact:					
Enquiry No.: 6048106	Logged by: External to Confirm	on: 24/03/2017 16:37					Enquiry Ref: FS-CASE-50320327
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation					
Desc.: Road Pothole - There are a number of deep potholes at this junction . Online report							
Location: See map coordinates and description details		Contact:					
Plot Number: 2,000.00	Feature Id - Location: From Burleigh Road to Stamford Road			Feature Type: Street Section			
Job Number: 2647063	Defect Number: 3545277						
Enquiry No.: 6047326	Logged by: External to Confirm	on: 19/03/2017 13:21					Enquiry Ref: FS-CASE-50102664
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation					
Desc.: Road Pothole - Pothole on burleigh road 10 m from junction with rodney road. Quite large (30 cm) and deep (8cm) . Online report							
Location: See map coordinates and description details		Contact:					
Plot Number: 2,000.00	Feature Id - Location: From Burleigh Road to Stamford Road			Feature Type: Street Section			
Job Number: 2647054	Defect Number: 3545268						
Enquiry No.: 6043082	Logged by: External to Confirm	on: 16/02/2017 11:35					Enquiry Ref: FS-CASE-12964549
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation					
Desc.: Road Pothole - There are several potholes along this road - some have been filled in but the filling has been washed out so they are back to pot holes again. From the hill down to the lights (connection with Musters road) has many - some coming up to the lights, others down the centre of the road. All in all not a great stretch of road . Online report							
Location: See map coordinates and description details		Contact:					
Enquiry No.: 6033222	Logged by: External to Confirm	on: 10/11/2016 08:17					Enquiry Ref: FS-CASE-9615616
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation					
Desc.: Road Pothole - Customer called as there is a pothole on the road in front of the customers drive, ^{Peris} Burleigh Road. It's around a foot in diameter and it's getting deeper. Customer is affraid that his car will get damaged if it doesn't get fixed. . Submitted by Advisor: Personal Information							
Location: The pin has been placed near 22 Burleigh Road, Nottingham, United Kingdom, NG2 6FQ		Contact:					
Plot Number: 2,000.00	Feature Id - Location: From Burleigh Road to Stamford Road			Feature Type: Street Section			
Job Number: 2638966	Defect Number: 3537469						

Effective: 01/03/2015 to 31/03/2017

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Burleigh Road (33000732)

Customer Services

Enquiry No.: 6018490	Logged by: External to Confirm	on: 16/06/2016 12:51	Enquiry Ref: FS3594116
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	
Desc.: Other tree or vegetation issue - Email received at CSC : Recently a mature tree has been removed from pavement Personal Information . I am unsure why and hope it is to be replaced? Similarly this last year another tree on the road has been removed, further away, but on same side of Burleigh Road, across Trevor Road. I feel most strongly that these trees give character and amenity to the road, and their (gradual) loss is to be resisted. I would therefore welcome reassurance that in the next planting season these trees are to be replaced? Personal Information Personal Information . Submitted by Advisor: Personal Information			
Location: The pin has been placed near 49-53 Burleigh Road, Nottingham, United Kingdom, NG2 6FQ		Contact:	
Enquiry No.: 6011075	Logged by: External to Confirm	on: 31/03/2016 13:52	Enquiry Ref: 103887968
Service: Carriageway/Footway	Subject: Footway Damage	Classification: Report or Observation	
Desc.: significant damage to pavement outside Personal Information Burleigh Rd - hazardous for pedestrians and pushchairs and now causing damage to my private driveway - related to roots of a very large tree in the pavement ** Customer Requested Auto Updates **			
Location:		Contact:	
Enquiry No.: 6011068	Logged by: External to Confirm	on: 31/03/2016 13:33	Enquiry Ref: 103887957
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	
Desc.: email received: Hello, Personal Information There is a large tree on the pavement outside our house and the roots of the tree are causing significant disruption, not only to the pavement itself but also to our driveway and are encroaching into our main drain to the extent that we have had to have our drain unblocked on two occasions in the past year. Personal Information I would be grateful if someone could come and look at the tree for us in advance of any works. I note that many of the mature trees on Burleigh Rd have either been removed or replaced with younger trees. Thanking you in advance, Personal Information Logged by CSC operator Personal Information			
Location: Right next to Burleigh Road		Contact:	
Enquiry No.: 6005951	Logged by: External to Confirm	on: 17/02/2016 10:30	Enquiry Ref: 103873642
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	
Desc.: Two trees located within 50 yards each way of 17 Burleigh Road were cut down about 2 to 3 years ago due to being diseased. A notice was on the tree trunk that they would be replaced at the next correct planting season. However the area is currently being tarmacked and when the customer asked the workmen about the trees when they were digging up the stump that said it was going to be completely tarmacked. Customer is unhappy about this and feels the environment is going to be spoiled, Can someone look into this and let the customer know what is going to be done about the two trees. Logged by CSC operator: Personal Information			
Location: Right next to Burleigh Road		Contact:	
Enquiry No.: 6004795	Logged by: External to Confirm	on: 08/02/2016 15:29	Enquiry Ref: 103868842
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	
Desc.: number of pot holes			
Location: Near Burleigh Road		Contact:	
Plot Number: 2,000.00	Feature Id - Location: From Burleigh Road to Stamford Road	Feature Type: Street Section	
Job Number: 2623947	Defect Number: 3523047		

Effective: 01/03/2015 to 31/03/2017

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Burleigh Road (33000732)

Customer Services

Enquiry No.: 6003368 **Logged by:** External to Confirm **on:** 28/01/2016 15:55
Service: Other **Subject:** Other Enquiry (Escalated) **Classification:** Report or Observation **Enquiry Ref:** 103861647
Desc.: Customer has rang back saying that the drain is still blocked and there is sewage flowing through her garden and garage. Can this be looked into as it stands the risk of flooding the garage along with the things in there. Thanks
 Closed Enquiry Number: 3199872
 Logged by CSC operator: Bright Baah
Location: Near Burleigh Road **Contact:**

Enquiry No.: 3199872 **Logged by:** External to Confirm **on:** 07/01/2016 12:47
Service: Carriageway/Footway **Subject:** Blocked Drain **Classification:** Report or Observation **Enquiry Ref:** 103836137
Desc.: Drains blocked outside number 41 Burleigh Road. has led to low level flooding outside no 41 up to junction with Trevor Road.
 Resident says that the flooding most likely caused by drains at junction. Please can these be cleaned out.
 Logged by CSC operator: Personal Information
Location: Near Burleigh Road **Contact:**

Enquiry No.: 3196889 **Logged by:** External to Confirm **on:** 08/12/2015 13:22
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** 103810771
Desc.: There is a pothole outside number 2 burleigh road, approximately 12 inches in diameter and about 5 inches deep
 Logged by CSC operator: Personal Information
Location: Near Burleigh Road **Contact:**

Enquiry No.: 3192736 **Logged by:** External to Confirm **on:** 10/11/2015 12:28
Service: Other **Subject:** Other Request (Highways) **Classification:** Service Request **Enquiry Ref:** 103779646
Desc.: There are road works on Burleigh road and the customer is not happy as this has been going on for about 3 months now, there are big holes in the pavements that have been dug up. Please call the customer back about this and let them know when this will be finishing and how long it will take.
 Logged by CSC operator: Personal Information
Location: Near Burleigh Road **Contact:**

Enquiry No.: 3173538 **Logged by:** External to Confirm **on:** 02/06/2015 17:07
Service: Trees/Verges **Subject:** Tree Enquiry **Classification:** Report or Observation **Enquiry Ref:** 103593190
Desc.: customer has called as there are 2 large branches which were obstructing the pavement. They're now on the customer drive as they took them in to prevent someone tripping. She would like them to be removed.
 Logged by CSC operator: Personal Information
Location: Near Burleigh Road **Contact:**

Enquiry No.: 3168998 **Logged by:** External to Confirm **on:** 20/04/2015 21:38
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** 103544733
Desc.: 50 metre section of road has numerous potholes
 ** Customer Requested Auto Updates **
Location: Near Burleigh Road **Contact:**

Enquiry No.: 3166839 **Logged by:** External to Confirm **on:** 31/03/2015 16:42
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** 103524165
Desc.: potholes and major surfacing issues on Burleigh Road in and around the junction of Cambridge Road (including the small pothole on Cambridge Road which was repaired last year but has now degraded again). Also the area near Melton Road has been marked with yellow for a long while but no work has been done yet.
Location: Near Burleigh Road **Contact:**

Plot Number: 2,000.00

Feature Id - Location: From Burleigh Road to Stamford Road

Feature Type: Street Section

Job Number: 2608089

Defect Number: 3507763

Effective: 01/03/2015 to 31/03/2017

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Burleigh Road (33000732)

Customer Services

Enquiry No.: 3165582 **Logged by:** External to Confirm **on:** 23/03/2015 09:10
Service: Traffic Management **Subject:** Parking General **Classification:** Report or Observation **Enquiry Ref:** 103512610
Desc.: Rodney Road, Abbey Road, Burleigh Road, West Brigdford. Parents are parking across Personal Information drive and causing access issues during school drop off and pick up times. Could an inspector visit during these times? Please contact Personal Information before visit is made, thanks.
Location: Near Abbey Road **Contact:**

Enquiry No.: 3163563 **Logged by:** External to Confirm **on:** 06/03/2015 12:25
Service: Trees/Verges **Subject:** Fallen Tree **Classification:** Report or Observation **Enquiry Ref:** 103494834
Desc.: On Burleigh Road between Parkcroft and Villiers a tree was cut down last year but the stump was left. It is about 2-3 feet high and is a hazard. Could this please be removed.
Location: **Contact:**

Enquiry No.: 3163561 **Logged by:** External to Confirm **on:** 06/03/2015 12:23
Service: Trees/Verges **Subject:** Fallen Tree **Classification:** Report or Observation **Enquiry Ref:** 103494830
Desc.: There is a tree with a notice on it to be removed and for people to call if there are any queries. Personal Information doesn't have an issue being removed as it is clearly diseased. However, since there was another tree that was removed last year on the same stretch of road and the stump (about 2-3 feet high) was left as a hazard, she doesn't want the same to happen again to this one. Also, she would like to have the tree replaced as a number of trees have been removed and not replaced and the road is now becoming treeless.
Location: Near Burleigh Road **Contact:**

Enquiry No.: 57328 **Logged by:** Personal Information **on:** 29/11/2016 15:11
Service: Licenses/Permits **Subject:** Skip License Request **Classification:** Service Request
Desc.: 1.8 x 3.4m skip
01/12/16 - 28/12/16
Location: 41 **Contact:**

Enquiry No.: 42653 **Logged by:** Personal Information **on:** 20/11/2015 15:29
Service: Licenses/Permits **Subject:** Skip License Request **Classification:** Service Request
Desc.: 1.8 x 3.4m skip
23/11/15 - 20/12/15
Location: 41 **Contact:**

Enquiry No.: 41483 **Logged by:** Personal Information **on:** 23/10/2015 14:56
Service: Licenses/Permits **Subject:** Skip License Request **Classification:** Service Request
Desc.: 26.10.15 to 22.11.2015 1.8m x 3.4m
Location: 41 Burleigh Road, West Bridgford, NG2 6FQ **Contact:**

Enquiry No.: 33614 **Logged by:** Personal Information **on:** 03/03/2015 15:54
Service: Licenses/Permits **Subject:** Skip License Request **Classification:** Service Request
Desc.: 1.8 x 3.4m skip
10/03/15 - 06/04/15
Location: 1A **Contact:**

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 2,000.00	Feature Id - Locn.: From Burleigh Road to Stamford Road			Feature Type: Street Section		Area: Rushcliffe	
2605828	Various sized wearing course erosion at stated location marked up (HW CW Pothole Z1)	Outside house number 2B	Category 2 (High)	Job Completed	25/02/2015	21/04/2015	Act. RUSH/3700732

Effective: 01/03/2015 to 31/03/2017

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Burleigh Road (33000732)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:	From Burleigh Road to Stamford Road	Feature Type:	Street Section	Area:	Rushcliffe
2608089	Defects made safe at time of inspection - no further action required . (HW CW Pothole Z1)	Junction of Burleigh / Cambridge Rd	Category 2 (High)	Job Completed	02/04/2015	07/04/2015	Act. RUSH/3700966
2615969	Gullies X 2 opposite each other at the mentioned location fully silted causing standing water over Tac Tile crossing . Another area that ACL have missed . (HW DR Blocked Gully Z3)	Near too L / C 1 - adjacent to the Junction with Melton Rd	Category 2 (High)	Job Completed	14/09/2015	18/09/2015	Act. RUSH/3701285
2620652	Defect made safe at time of inspection (HW CW Pothole Z1)	Outside house number 2	Filled when found (Cat 2H)	Job Completed	09/12/2015	09/12/2015	Act.
2622408	Two areas that have been made safe at time of inspection . (HW CW Pothole Z1)	On the junction with Melton Rd & outside house number 2A	Made Safe (Cat 2H)	Job Completed	18/01/2016	18/01/2016	Act.
2623509	Defects made safe at time of inspection (HW CW Pothole Z1)	Outside house numbers 42 & 18	Filled when found (Cat 2H)	Job Completed	03/02/2016	02/02/2016	Act.
2623947	Defects made safe at time of inspection (HW CW Pothole Z1)	Junction with Burleigh / Dunster road	Filled when found (Cat 2H)	Job Completed	09/02/2016	09/02/2016	Act.
2627312	Tree roots pushing up tarmaced on footpath (4 sqm) which requires damaged Tarmac excavating and wearing course reinstating around the tree pit - marked up at time of inspection . (HW FW Tree root uplift Z5)	Outside house number 41	Category 2 (High)	Job Cancelled	01/04/2016	29/04/2016	Est. RUSH/3701663
2627313	Defect made safe at time of inspection (HW CW Pothole Z1)	Outside house number 18	Filled when found (Cat 2H)	Job Completed	01/04/2016	01/04/2016	Act.
2630030	Defects made safe at time of inspection . (CW Repairs-Bituminous)	Outside house number 2	Filled when found (Cat 2H)	Job Completed	13/05/2016	13/05/2016	Act.
2634284	Defect made safe . (CW Repairs-Bituminous)	Outside house number 30	Filled when found (Cat 2H)	Job Completed	05/08/2016	05/08/2016	Act.
2638966	Defect has been made safe during inspection . (CW Repairs-Bituminous)	Outside house number 47	Filled when found (Cat 2H)	Job Completed	10/11/2016	10/11/2016	Act.
2643556	HWIA - defects marked up for the Assistants (CW Repairs-Bituminous)	On the T junction with Dunster Road adjacent with L / C 13	Category 2 (High)	Job Completed	07/02/2017	22/02/2017	Act. RUS-AS/5600573
2647054	Carriageway defect made safe during inspection . (CW Repairs-Bituminous)	Outside house number 65	Filled when found (Cat 2H)	Job Completed	27/03/2017	20/03/2017	Act.
2647063	HWIA - Carriageway defects marked up to be made safe (CW Repairs-Bituminous)	From outside house number 18 & towards the junction with Gordon Road	Category 2 (High)	Job Completed	27/03/2017	28/03/2017	Act. RUS-AS/5600636

Effective: 01/03/2015 to 31/03/2017
Display Action Officer: No

Feature No.: 2000.00 to 2000.00
Street: Burleigh Road (33000732)
