

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxtan Road (26805336)

Street: Oxtan Road (26805336)

Locality: Southwell, Nottinghamshire

Area: Newark

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:	C42 - Southwell	Feature Type: Street Section			Area: Newark	
Batch: 20283896 - Inspection Batch				Route: Newark Area 2 May Enh CW/FW			Date: 17/05/2018	
No actionable defects found								
Batch: 20280415 - Inspection Batch				Route: Adhoc Inspection			Date: 26/04/2018	
3576484	pothole	26/04/2018	opps allenby rd filled when found	CW Repairs-Bituminous	Internal		Committed	2679581
Batch: 20279144 - Inspection Batch				Route: Newark Area 2 Apr Saf CW			Date: 23/04/2018	
3575806	pothole	23/04/2018	near lc no 32 marked with a arrow	CW Repairs-Bituminous	Internal		Committed	2678900
3575808	pothole	23/04/2018	near lc no 28 filled when found	CW Repairs-Bituminous	Internal		Committed	2678898
3575805	potholes	23/04/2018	near lc no 29 marked	CW Repairs-Bituminous	Internal		Committed	2678899
3575807	potholes	23/04/2018	from savesick lane to s bends all marked arrows	CW Repairs-Bituminous	Internal		Committed	2678901
Batch: 20272582 - Inspection Batch				Route: Newark Area 2 Mar Saf CW			Date: 15/03/2018	
3571125	pothole	15/03/2018	near halam turn off marked with a arrow	CW Repairs-Bituminous	Internal		Committed	2674111
3571122	potholes	15/03/2018	on bends filled when found	CW Repairs-Bituminous	Internal		Uncommitted	2674114
3571123	pothole	15/03/2018	up from saversick lane marked with a arrow near gully	CW Repairs-Bituminous	Internal		Committed	2674115
3571121	potholes	15/03/2018	from saversick lane to thorney abbey farm marked	CW Repairs-Bituminous	Internal		Committed	2674113
3571120	pothole	15/03/2018	near junction of halam turn off marked with a arrow	CW Repairs-Bituminous	Internal		Committed	2674112
3571124	potholes	15/03/2018	near lc no 28 marked	CW Repairs-Bituminous	Internal		Committed	2674116
Batch: 20268298 - Inspection Batch				Route: Newark Area 2 Feb Saf CW			Date: 14/02/2018	
No actionable defects found								
Batch: 20261369 - Inspection Batch				Route: Newark Area 2 Jan Saf CW			Date: 04/01/2018	
3562949	potholes	04/01/2018	on bend marked	CW Repairs-Bituminous	Internal		Committed	2665842
3562951	potholes	04/01/2018	near lc no 28 marked	CW Repairs-Bituminous	Internal		Committed	2665837
3562945	pothole	04/01/2018	near learchcroft hill rd next to gully marked	CW Repairs-Bituminous	Internal		Committed	2665838
3562946	potholes	04/01/2018	on bends marked	CW Repairs-Bituminous	Internal		Committed	2665839
3562947	pothole	04/01/2018	on bends marked	CW Repairs-Bituminous	Internal		Committed	2665840
3562950	ptholes	04/01/2018	on bends near chevron marked	CW Repairs-Bituminous	Internal		Committed	2665843
3562948	potholes	04/01/2018	on straight in between bends marked	CW Repairs-Bituminous	Internal		Committed	2665841
Batch: 20259811 - Inspection Batch				Route: Newark Area 2 Dec Saf CW			Date: 19/12/2017	
No actionable defects found								
Batch: 20253606 - Inspection Batch				Route: Newark Area 2 Nov Saf CW			Date: 07/11/2017	
3559032	pothole	07/11/2017	next to mirror marked opps barn	CW Repairs-Bituminous	Internal		Committed	2661777
Batch: 20250917 - Inspection Batch				Route: Newark Area 2 Oct Saf CW			Date: 19/10/2017	
No actionable defects found								

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxtan Road (26805336)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: C42 - Southwell			Feature Type: Street Section			Area: Newark	
Batch: 20247140 - Inspection Batch				Route: Newark Area 2 Sep Saf CW				Date: 22/09/2017
3555883	potholes	22/09/2017	on bad bend up from saversick In marked stop and go advised	CW Repairs-Bituminous	Internal		Committed	2658399
Batch: 20242851 - Inspection Batch				Route: Newark Area 2 Aug Saf CW				Date: 23/08/2017
	No actionable defects found							
Batch: 20240166 - Inspection Batch				Route: Adhoc Inspection				Date: 01/08/2017
3552745	pothole	01/08/2017	0.3 miles from saversick lane hwding to oxtan on righr hand side of C/W marked	CW Repairs-Bituminous	Internal		Committed	2655092
Batch: 20240165 - Inspection Batch				Route: Newark Area 2 Jul Saf CW				Date: 01/08/2017
3552744	potholes	01/08/2017	100 m past saversick lane heading to oxtan marked	CW Repairs-Bituminous	Internal		Committed	2655091
Batch: 20233835 - Inspection Batch				Route: Newark Area 2 Jun Saf CW				Date: 13/06/2017
	No actionable defects found							
Batch: 20231157 - Inspection Batch				Route: Newark Area 2 May Enh CW/FW				Date: 23/05/2017
3549040	potholes	23/05/2017	just before radley rd heading towards southwell,marked	CW Repairs-Bituminous	Internal		Committed	2651004
Batch: 20226898 - Inspection Batch				Route: Newark Area 2 Apr Saf CW				Date: 26/04/2017
	No actionable defects found							
Batch: 20219793 - Inspection Batch				Route: Newark Area 2 Mar Saf CW				Date: 06/03/2017
	No actionable defects found							
Batch: 20215882 - Inspection Batch				Route: Newark Area 2 Feb Saf CW				Date: 08/02/2017
3541987	potholes	08/02/2017	from saversick lane to high friction towards oxtan both side of road not marked	CW Repairs-Bituminous	Internal		Committed	2643706
Batch: 20211895 - Inspection Batch				Route: Newark Area 2 Jan Saf CW				Date: 10/01/2017
	No actionable defects found							
Batch: 20209561 - Inspection Batch				Route: Newark Area 2 Dec Saf CW				Date: 19/12/2016
3539390	potholes	19/12/2016	nr radley road	CW Repairs-Bituminous	Internal		Uncommitted	2641022
3539389	pothole	19/12/2016	as mapped	CW Repairs-Bituminous	Internal		Uncommitted	2641024
3539388	pothole	19/12/2016	as mapped	CW Repairs-Bituminous	Internal		Uncommitted	2641023
Batch: 20207298 - Inspection Batch				Route: Newark Area 2 Feb Enh CW/FW				Date: 01/12/2016
	No actionable defects found							
Batch: 20203869 - Inspection Batch				Route: Newark Area 2 Nov Saf CW				Date: 04/11/2016
3537188	potholes	04/11/2016	heading from southwell to oxtan edge of CW cway 2 just before new radley farm entrance 1 just after marked	Repairs-Bituminous	Internal		Committed	2638656
Batch: 20200602 - Inspection Batch				Route: Newark Area 2 Oct Saf CW				Date: 13/10/2016
	No actionable defects found							

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxtan Road (26805336)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: C42 - Southwell			Feature Type: Street Section			Area: Newark	
Batch: 20195673 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Sep Saf CW				Date: 06/09/2016
Batch: 20192635 - Inspection Batch				Route: Newark Area 2 Aug Saf CW				Date: 09/08/2016
3533304	pothole	09/08/2016	drive entrance just past radley road heading towards oxtan marked	CW Repairs-Bituminous	Internal		Committed	2634469
Batch: 20189390 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Jul Saf CW				Date: 18/07/2016
Batch: 20184057 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Jun Saf CW				Date: 07/06/2016
Batch: 20179334 - Inspection Batch	No actionable defects found			Route: Newark Area 2 May Saf CW				Date: 09/05/2016
Batch: 20174465 - Inspection Batch				Route: Newark Area 2 Apr Saf CW				Date: 06/04/2016
3526672	verge over run needs topsoil	06/04/2016	Outside stables	HW CW Verge Damage Z5	Internal		Committed	2617794
Batch: 20172321 - Inspection Batch				Route: Adhoc Inspection				Date: 18/03/2016
3525825	pothole	18/03/2016	Come past radley road junction towards southwell just at start of bends with anti skid marked	HW CW Pothole Z1	Internal		Committed	2626761
Batch: 20170667 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Mar Saf CW				Date: 07/03/2016
Batch: 20164652 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Feb Enh CW/FW				Date: 02/02/2016
Batch: 20161838 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Jan Saf CW				Date: 14/01/2016
Batch: 20156895 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Dec Saf CW				Date: 03/12/2015
Batch: 20151683 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Nov Saf CW				Date: 02/11/2015
Batch: 20149823 - Inspection Batch				Route: Adhoc Inspection				Date: 19/10/2015
3517090	verge over run needs topsoil	19/10/2015	Outside stables	HW CW Verge Damage Z5	Internal		No Action Required	
Batch: 20147904 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Oct Saf CW				Date: 06/10/2015
Batch: 20146248 - Inspection Batch				Route: Adhoc Inspection				Date: 25/09/2015
3515937	potholes	25/09/2015	Outside old radley farm marked	HW CW Pothole Z1	Internal		Committed	2616612
Batch: 20146247 - Inspection Batch				Route: Adhoc Inspection				Date: 25/09/2015
3515936	verge damage needs stoning	25/09/2015	As leaving southwell heading towards Oxtan just before radley road on left hand side marked with yellow arrows	HW CW Verge Damage Z5	Internal		Committed	2616611

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxton Road (26805336)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: C42 - Southwell			Feature Type: Street Section			Area: Newark	
Batch: 20143504 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Sep Saf CW				Date: 08/09/2015
Batch: 20140724 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Aug Saf CW				Date: 14/08/2015
Batch: 20135897 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Jul Saf CW				Date: 07/07/2015
Batch: 20131829 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Jun Saf CW				Date: 09/06/2015
Batch: 20131061 - Inspection Batch				Route: Adhoc Inspection				Date: 04/06/2015
3511194	Potholes	04/06/2015	Service road that leads to holly cottage off the Oxton road both ends of service road leading to property's need doing	HW CW Pothole Z1	Internal		Committed	2611653

Customer Services

Enquiry No.: 6090931	Logged by: External to Confirm	on: 10/04/2018 13:05					Enquiry Ref: FS-CASE-72509856
Service: Carriageway/Footway	Subject: Flooding	Classification: Report or Observation					
Desc.: Street flooding - Flooding all over the road incident number 357 10/04/2018 pc Debbie Herlihy cllr number 8593. Submitted by Advisor: [REDACTED]							
Location: Oxon Road coming from southwell in towards Oxon Road before the bad bend	Contact:						
Enquiry No.: 6080892	Logged by: External to Confirm	on: 09/02/2018 11:39					Enquiry Ref: FS-CASE-67719304
Service: Road Works	Subject: Road Works Report	Classification: Report or Observation					
Desc.: Road work issue - Customer is calling to recommend that rather than doing roads such as oxton road in which not many cars travel down it can we start doing roads that are more important. Could we also have road works carried out during dry weather as doing a resurface in the wet causes many more problems. . Submitted by Advisor: [REDACTED]							
Location: Oxton Road	Contact:						
Enquiry No.: 6078084	Logged by: External to Confirm	on: 24/01/2018 14:51					Enquiry Ref: FS-CASE-66557959
Service: Carriageway/Footway	Subject: Flooding	Classification: Report or Observation					
Desc.: Street flooding - During medium to heavy rainfall the run off from the fields adjacent the road cause localised flooding of the road.. Online report							
Location: Oxton Road (B6386) between Saversick Lane and the chevron road signs approximately 0.5 miles towards Oxton	Contact:						
Enquiry No.: 6077918	Logged by: External to Confirm	on: 24/01/2018 08:29					Enquiry Ref: FS-CASE-66511480
Service: Trees/Verges	Subject: Fallen Tree	Classification: Report or Observation					
Desc.: Damaged/dangerous/fallen tree - South well road in Oxton close to Holbeck Gardent centre							
A tree is down half covering the carriage way but it on a brow of a hill							
reported by police but she didnt give me a incident number							
. Submitted by Advisor: [REDACTED]							
Location: See map coordinates and description details	Contact:						

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxtan Road (26805336)

Customer Services

Enquiry No.: 6077048	Logged by: External to Confirm	on: 18/01/2018 13:06	Enquiry Ref: FS-CASE-66117451
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	
Desc.: Other tree issues - There is a fallen tree on Oxtan Road. It is on the verge as you pass the garden centre travelling towards Southwell. Just 1/4 mile or so past Radley Lane. There is no imminent danger as the tree has been partially cut now by the callers husband with a chain saw. The tree caused some one to skid onto the grass verge earlier but it is safe now. The customer is asking if we can remove the tree and deal with the damage to the grass verge. Tree is about 8 inches diameter. It is near the dyke. As we spoke - someone was pulling up with a trailer. Don't know who it was though. . Submitted by Advisor: [REDACTED]			
Location: See map coordinates and description details	Contact:		
Enquiry No.: 6071837	Logged by: External to Confirm	on: 01/12/2017 09:42	Enquiry Ref: FS-CASE-63125387
Service: Winter Maintenance	Subject: Gritting Request	Classification: Service Request	
Desc.: Road gritting request - report from PC734 Priestley request grit request urgently On B6356 before junction of Saversick Lane and Leach Croft in southwell going from Oxtan the road is on an incline and has several S bends, covered by trees and the road is black ice (sheet of ice) not melting . Submitted by Advisor: [REDACTED] - - -			
Location: B6386	Contact:		
Enquiry No.: 6064758	Logged by: External to Confirm	on: 20/09/2017 16:00	Enquiry Ref: FS-CASE-59001734
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	
Desc.: Other tree issues - With Ref 6064750 Customer has called to also report the very large overgrown tree that is causing serious visibility problems as your are turning out of Saversick Lane moving onto the Oxtan Road. The tree how it is positioned is blocking visibility and in the passed have caused multiple accidents due to lack of visibility. The customer is concerned that yes the tree is not causing any immediate danger just that visibility is reduced. [REDACTED] would like to know if the inspector would be able to meet with him to discuss this further, i have stressed that this may not be possible. . Submitted by Advisor: [REDACTED]			
Location: See map coordinates and description details	Contact:		
Enquiry No.: 6060214	Logged by: External to Confirm	on: 02/08/2017 13:52	Enquiry Ref: FS-CASE-56804244
Service: Trees/Verges	Subject: Grass Cutting	Classification: Report or Observation	
Desc.: Overgrown grass and verges - Customer has called to report the overgrown grass verge on Oxtan Road, as you are coming out of Cooks lane it is the grass verge that is on the right hand side. Due to the length of the grass drivers cannot see the oncoming traffic and they are pulling out onto 60mph road. The grass was last cut back two months ago but was only cut back half way rather than all the way back. There has been a number of incidents here over the years due to the grass being too long and drivers being unable to see. Can you please see to this section as soon as possible. Thank you. . Submitted by Advisor: [REDACTED]			
Location: See map coordinates and description details	Contact:		
Enquiry No.: 6059638	Logged by: External to Confirm	on: 27/07/2017 11:39	Enquiry Ref: FS-CASE-56532247
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	
Desc.: Other tree issues - As you drive down Oxtan road towards Southwell just before the junction with Saversick Lane there is a very large tree.This tree restricts the view when you are turning off Saversick Lane onto Oxtan road.Can someone have a look at this tree to see if anything can be done to make the turn off Saversick Lane onto Oxtan road safer,Near the tree there are a lot of stones /building materials which also restricts your view,could anything be done about these stones . . Submitted by Advisor: [REDACTED]			
Location: See map coordinates and description details	Contact:		
Enquiry No.: 6055147	Logged by: External to Confirm	on: 12/06/2017 09:48	Enquiry Ref: FS-CASE-54274540
Service: Trees/Verges	Subject: Grass Cutting	Classification: Report or Observation	
Desc.: Overgrown grass and verges - Grass verge near the junction with Oxtan Road and Sunnyside and Westhorpe is very overgrown and needs cutting. . Submitted by Advisor: [REDACTED]			
Location: See map coordinates and description details	Contact:		

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxton Road (26805336)

Customer Services

Enquiry No.: 6054159	Logged by: External to Confirm	on: 31/05/2017 15:44	
Service: Trees/Verges	Subject: Overhanging Vegetation/Trees	Classification: Report or Observation	Enquiry Ref: FS-CASE-53677828
Desc.: Overgrown hedges and vegetation - if you travel down Cooks Lane to the junction with Oxton Road B6386 and turn right - you cannot see traffic coming round bend due to overgrown vegetation on grass verge on this corner. This is an extremely busy road at times with 60 mph speed limit. Caller says its dangerous to pull out of this junction when can't see traffic clearly. . Submitted by Advisor: [REDACTED]			
Location: See map coordinates and description details	Contact:		
Enquiry No.: 6052040	Logged by: External to Confirm	on: 08/05/2017 12:13	
Service: Other	Subject: Other Enquiry (Highways)	Classification: Report or Observation	Enquiry Ref: FS-CASE-51874338
Desc.: Other enquiry - [REDACTED] is wanting a new commercial access/ farm road installed off of Oxton Road in Southwell. Mainly [REDACTED] is wanting a price for this work to be carried out by the council. This road is for access to his farm and he was wondering if the work could be carried out by Notts County Council so this can be done to the correct standards. Can someone call [REDACTED] with this information at the following number: [REDACTED]. Submitted by Advisor: [REDACTED] -			
Location: See map coordinates and description details	Contact:		
Enquiry No.: 6049829	Logged by: External to Confirm	on: 11/04/2017 09:50	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-50901888
Desc.: Road Pothole - Deep pothole near New Hollybeck Garden Centre on Oxton Road . Online report			
Location: See map coordinates and description details	Contact:		
Plot Number: 2,000.00	Feature Id - Location: C42 - Southwell	Feature Type: Street Section	
Job Number: 2649898			
Enquiry No.: 6049827	Logged by: External to Confirm	on: 11/04/2017 09:48	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-50901754
Desc.: Road Pothole - Deep pothole on corner of Cookes Lane and Oxton Road . Online report			
Location: See map coordinates and description details	Contact:		
Plot Number: 2,000.00	Feature Id - Location: C42 - Southwell	Feature Type: Street Section	
Job Number: 2648908			
Enquiry No.: 6032527	Logged by: External to Confirm	on: 02/11/2016 17:53	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-9424908
Desc.: Road Damage - Edge of road missing. Can clip if passing larger vehicle coming other way. Very deep . Online report			
Location: The pin has been placed near Oxton Road, Southwell, United Kingdom, NG25 0RA Contact:			
Plot Number: 2,000.00	Feature Id - Location: C42 - Southwell	Feature Type: Street Section	
Job Number: 2638656	Defect Number: 3537188		
Enquiry No.: 6029129	Logged by: External to Confirm	on: 30/09/2016 09:40	
Service: Trees/Verges	Subject: Overhanging Vegetation/Trees	Classification: Report or Observation	Enquiry Ref: FS-CASE-7588247
Desc.: Overhanging trees - A huge overgrown branch of a tree on customers garden and going towards the house and customer said it needs cutting down. Cant be seen from the road and is only visible once in the garden. Wychelm tree???? . Calverts Farm, Oxton Road, , Southwell, NG25 0NH. Submitted by Advisor: [REDACTED]			
Location: The pin has been placed near 12 Oxton Road, Southwell, United Kingdom, NG25 0NH Contact:			
Enquiry No.: 6028385	Logged by: External to Confirm	on: 23/09/2016 09:55	
Service: Road Works	Subject: Utility Works	Classification: Report or Observation	Enquiry Ref: FS7040863
Desc.: Utility works - The customer wanted to trim back to the hedge less than 20 meters. Theyre installing pipes so they need the area cutting. . Buildings 148 156 And 145, Celanese Acetate, Holme Lane, , Derby, DE21 7BS. Submitted by Advisor: [REDACTED]			
Location: The pin has been placed near Southwell Road, Southwell, United Kingdom, NG25 0RA Contact:			

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxtan Road (26805336)

Customer Services

Enquiry No.: 6027779	Logged by: External to Confirm	on: 17/09/2016 14:11	
Service: Carriageway/Footway	Subject: Dropped Kerb (Vehicle) Request	Classification: Service Request	Enquiry Ref: FS6664392
Desc.: Vehicle dropped kerb request - Access to freehold land from Oxtan Road B6386. Land located at back of 44 Westhorpe, Southwell NG25 0NG (see attached Land Registry map outlined in red). █ Byron Gardens, , Southwell, NG25 0DW. Online report			
Location: The pin has been placed near 22 Oxtan Road, Southwell, United Kingdom, NG25 0NH	Contact:		
Enquiry No.: 6017491	Logged by: External to Confirm	on: 09/06/2016 11:49	
Service: Carriageway/Footway	Subject: Dropped Kerb (Vehicle) Request	Classification: Service Request	Enquiry Ref: FS3470596
Desc.: Vehicle dropped kerb request - The customer would like to request a dropped kerb outside number █ oxtan road. He would like to be present for the inspection so please call him to arrange this. . █ Oxtan Road, , Southwell, NG25 0NH. Submitted by Advisor: █			
Location: █	Contact:		
Enquiry No.: 6016652	Logged by: External to Confirm	on: 01/06/2016 12:01	
Service: Trees/Verges	Subject: Grass Cutting	Classification: Report or Observation	Enquiry Ref: FS3331126
Desc.: Overgrown grass and verges - █ property and 2 other properties there use a lane which takes them to the main road. At the end of the lane there is a grass verge on both sides. 1 verge was cut back last week. The verge on the left hasn't been done and is several feet high. The road is bendy and there is a blind corner. Is there a reason why it hasn't been done? Or has it been missed? . Submitted by Advisor: █			
Location: The pin has been placed near █ Oxtan Road, Southwell, United Kingdom, NG25	Contact:		
Enquiry No.: 6011378	Logged by: External to Confirm	on: 04/04/2016 09:35	
Service: Trees/Verges	Subject: Fallen Tree	Classification: Report or Observation	Enquiry Ref: 10388468
Desc.: Customer says that the trees on this verge were sprayed green before christmas - she would like to know when they will be cut down - she was told after christmas. Logged by CSC operator: █ ** Customer Requested Auto Updates **			
Location:	Contact:		
Enquiry No.: 6011073	Logged by: External to Confirm	on: 31/03/2016 13:50	
Service: Other	Subject: Other Enquiry (Highways)	Classification: Report or Observation	Enquiry Ref: 103887966
Desc.: Unique paving vehicle █ dropped along this section of road various items from the vehicle cabin. Several plastic drinks bottles. food and sweet wrappers and other sundry items that were inside the cabin of the vehicle. This happened on 30/03/2016 at approx 4.45pm company tel number █. Person reporting didn't want to give details Logged by CSC operator: █			
Location: 935 meters from Radley House Farm Oxtan Road	Contact:		
Enquiry No.: 6010420	Logged by: External to Confirm	on: 23/03/2016 19:55	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: 103886751
Desc.: Large pothole near the slow sign in the road, inbound side towards Southwell. Cased damage my car and now have have alignment and a buckled wheel repaired. ** Customer Requested Auto Updates **			
Location:	Contact:		
Plot Number: 2,000.00	Feature Id - Location: C42 - Southwell	Feature Type: Street Section	
Job Number: 2626761	Defect Number: 3525825		
Enquiry No.: 6009773	Logged by: External to Confirm	on: 17/03/2016 18:03	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: 103885434
Desc.: Driving towards Southwell large pot hole at the side of the road. ** Customer Requested Auto Updates **			
Location: 579 meters from Halam Gate Saversick Lane	Contact:		
Plot Number: 2,000.00	Feature Id - Location: C42 - Southwell	Feature Type: Street Section	
Job Number: 2626761	Defect Number: 3525825		

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxtan Road (26805336)

Customer Services

Enquiry No.: 6009096	Logged by: External to Confirm	on: 11/03/2016 21:53	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: 103883720
Desc.: Large deep sharp edged pothole near edge of road as you approach Southwell from Oxtan			
Location: 613 meters from Halam Gate Saversick Lane		Contact:	
Enquiry No.: 6008576	Logged by: External to Confirm	on: 09/03/2016 10:16	
Service: Carriageway/Footway	Subject: Flooding	Classification: Report or Observation	Enquiry Ref: 103882336
Desc.: Oxtan Road from Southwell to Oxtan an S Bend as you go out of Southwell the road also flooded. Logged by CSC operator: [REDACTED]			
Location: 550 meters from Halam Gate Saversick Lane		Contact:	
Enquiry No.: 3185092	Logged by: External to Confirm	on: 15/09/2015 15:16	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: 103713613
Desc.: 2 x pot holes need attending to in front of the gate of OLD RADLEY FARM, OXTON, NEWARK, both about the size of a dustbin lid. metre and metre and a half between road and gate post. Logged by CSC operator: [REDACTED]			
Location: Near Old Radley Farm Oxtan Road		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C42 - Southwell	Feature Type: Street Section	
Job Number: 2616612	Defect Number: 3515937		
Enquiry No.: 3183836	Logged by: External to Confirm	on: 04/09/2015 10:04	
Service: Trees/Verges	Subject: Fallen Tree	Classification: Report or Observation	Enquiry Ref: 103699242
Desc.: There are 2 dead trees on the service road here on oxtan road, near the junction with cooks lane. Other trees on the service road are in need of a cut back Logged by CSC operator: [REDACTED]			
Location: 66 meters from Longwood Oxtan Road		Contact:	
Enquiry No.: 3182806	Logged by: External to Confirm	on: 25/08/2015 14:52	
Service: Other	Subject: Other Request (Highways)	Classification: Service Request	Enquiry Ref: 103688318
Desc.: [REDACTED] would appreciate a call back to discuss in general about having a dropped kerb on some land that will be sold by auction. Logged by CSC operator: [REDACTED]			
Location: 514 meters from Thorney Abbey Farm Oxtan Road		Contact:	
Enquiry No.: 3182797	Logged by: External to Confirm	on: 25/08/2015 14:05	
Service: Other	Subject: Other Enquiry (Highways)	Classification: Report or Observation	Enquiry Ref: 103688187
Desc.: Calling to say he wants to buy aplot of land a week on Thursday - there is a deeeper verge outside the property which you would have to cross to get onto the property, which is our verge. Wants to know if this verge would become a ransom strip - ie - costly to cross it. The land is opposite number 24 Oxtan Road. Logged by CSC operator: [REDACTED]			
Location: Near Oxtan Road		Contact:	
Enquiry No.: 3182544	Logged by: External to Confirm	on: 24/08/2015 12:05	
Service: Other	Subject: Other Enquiry (Highways)	Classification: Report or Observation	Enquiry Ref: 103685896
Desc.: Land is going to auction next week 03/09/15. No planning permission. Customer would like to know if there are any issues with regards to creating vehicle access. Please contact customer on [REDACTED]. Logged by CSC operator: [REDACTED]			
Location: 39 meters from Oxtan Road		Contact:	

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxtan Road (26805336)

Customer Services

Enquiry No.: 3182447 **Logged by:** External to Confirm **on:** 24/08/2015 08:11
Service: Other **Subject:** Other Enquiry (Highways) **Classification:** Report or Observation **Enquiry Ref:** 103684991
Desc.: At Radley House, the boundary stands back 16 ft from the road. Over the weekend they have taken the boundary fence down and mMOVED t right to the edge of the road. They are new owners. The road is busy and this grass vergae is used sometimes by vehicles for passing.
 Logged by CSC operator: Robert Warburton
Location: 37 meters from Radley House Farm Oxtan Road **Contact:**

Enquiry No.: 3182100 **Logged by:** External to Confirm **on:** 19/08/2015 15:08
Service: Carriageway/Footway **Subject:** Dropped Kerb (Vehicle) Request **Classification:** Service Request **Enquiry Ref:** 103681724
Desc.: Customer would like a quote and possibility please for building a dropped kerb connecting the land for sale at the bak of number 44 Westthorpe onto Oxtan Lane. Customer would like to meet the inspector at the site please? Is the land Ranson Land or does it belong to us as well? LAND IS UP FOR AUCTION ON 3RD SEPTEMBER AND WOULD LIKE AN ANSWER AS SOON AS POSSIBLE.
 Logged by CSC operator: [REDACTED]
Location: 30 meters from Oxtan Road **Contact:**

Enquiry No.: 3181171 **Logged by:** External to Confirm **on:** 11/08/2015 12:19
Service: Trees/Verges **Subject:** Overhanging Vegetation/Trees **Classification:** Report or Observation **Enquiry Ref:** 103671644
Desc.: National Speed Limit /30mph speed limit signs entering/leaving Southwell are hidden by overgrown hedgerows making it difficult to see the signs especially the 30mph sign entering Southwell
Location: 59 meters from Sunbury Cottage Oxtan Road **Contact:**

Enquiry No.: 3180871 **Logged by:** External to Confirm **on:** 08/08/2015 14:49
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** 103668910
Desc.: Enquiry 103591752

I wrote to you at the beginning of June and your Inspector visited shortly thereafter and marked various potholes for repair. I also mentioned problems with overhanging trees and road cleaning. The road has been cleaned but nothing else. When is it planned to do the work?
 Since I first reported the problems, I have noticed 2 dead trees on the service road. Also the speed (de)restriction sign is obscured by trees on both sides and the view to the right turning out of the service road is obscured by long grass on the verge.



** Customer Requested Auto Updates **

Location: 96 meters from Longwood Oxtan Road**Contact:****Plot Number:** 2,000.00**Feature Id - Location:** C42 - Southwell**Feature Type:** Street Section**Job Number:** 2611653**Defect Number:** 3511194

Enquiry No.: 3178544 **Logged by:** External to Confirm **on:** 17/07/2015 15:09
Service: Carriageway/Footway **Subject:** Spillage/Debris on Carriageway **Classification:** Report or Observation **Enquiry Ref:** 103645883
Desc.: Notts Police reporting lots of tree debris along the road, and branches.
 Logged by CSC operator: [REDACTED]
Location: 378 meters from Norwood Hill House Saversick Lane **Contact:**

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxtan Road (26805336)

Customer Services

Enquiry No.: 3173363 **Logged by:** External to Confirm **on:** 02/06/2015 10:11
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** 103591752
Desc.: I live at Longwood, the middle of the 3 houses on the service road off Oxtan Road. There are four problems:

1. There is a large pothole at the western end of the service road where it joins Oxtan Road.
2. Although the horizontal part of the verge between Oxtan Road and the service road has recently been mowed, the remainder has been left and is overgrown.
3. The service road has not been cleaned and leaf mould etc has encroached 1m from the verge area.
4. Some of the trees on the verge area are overhanging the service road.

Please let me know what you are going to do about these problems.

** Customer Requested Auto Updates **

Location: 98 meters from Longwood Oxtan Road**Contact:**

Enquiry No.: 3172717 **Logged by:** External to Confirm **on:** 27/05/2015 09:07
Service: Trees/Verges **Subject:** Grass Cutting **Classification:** Report or Observation **Enquiry Ref:** 103584948
Desc.: Grass here is overgrown and blocks vision. This is as you are coming out of Cooks Lane on the right turning on to Oxtan Road. Viability is very poor and this section of road is 60 mph and near a bend. There has already been two accidents in this section of the road and there is one now, the police are attending now.
 Logged by CSC operator: [REDACTED]

Location: 159 meters from Cooks Lane**Contact:**

Enquiry No.: 2504012 **Logged by:** [REDACTED] **on:** 21/12/2015 15:15
Service: Carriageway/Footway **Subject:** Blocked Drain **Classification:** Report or Observation
Desc.: Ditch recently dug. System needs jetting from outlet back towards Oxtan. Headwall potentially needs rebuilding
Location: jctn with Saversick Lane

Contact:

Plot Number: 2,000.00 **Feature Id - Location:** C42 - Southwell **Feature Type:** Street Section

Enquiry No.: 1303868 **Logged by:** [REDACTED] **on:** 19/08/2016 11:11
Service: Trees/Verges **Subject:** Overhanging Vegetation/Trees **Classification:** Report or Observation
Desc.: Veh turning right from Cooks Lane in collision with a veh travelling towards Southwell. Police state visibility at junction hampered by overgrown vegetation restricting view both ways. Please check and action as necessary. No other reported injury accsat junction in last 3 years.
Location: B6386 Oxtan Road/Cooks Lane Southwell

Contact:

Enquiry No.: 53800 **Logged by:** [REDACTED] **on:** 07/09/2016 15:57
Service: Carriageway/Footway **Subject:** Dropped Kerb (Vehicle) Request **Classification:** Service Request
Desc.: Customer wants dropped kerb. They are getting works done for Contry Park Contractors.
Location: [REDACTED] Oxtan Road, Southwell, NG25 0NH

Contact:

Enquiry No.: 49778 **Logged by:** [REDACTED] **on:** 02/06/2016 08:21
Service: Highway Searches **Subject:** Adoption Extents **Classification:** Report or Observation
Desc.:
Location: 4 Oxtan Road

Contact: Andy Shaw

Enquiry No.: 43840 **Logged by:** [REDACTED] **on:** 05/01/2016 12:15
Service: Other **Subject:** Other Enquiry (Highways) **Classification:** Report or Observation
Desc.: Customer says that the Real Milk Company of Halam have erected a sign at the junction of the B6386 and Radley Lane, he doesn't believe this to be a legal sign.
Location: Junction with Radley Lane

Contact:

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxton Road (26805336)

Customer Services

Enquiry No.: 40407 Logged by: [REDACTED] on: 29/09/2015 16:46
 Service: Other Subject: Other Request (Highways) Classification: Service Request
 Desc.: Fencing works at Radley House, Oxton Road, Southwell
 Location: Radley House, Oxton Road, Southwell Contact:

Enquiry No.: 36968 Logged by: [REDACTED] on: 24/06/2015 13:16
 Service: Carriageway/Footway Subject: Emergency Service Request Classification: Report or Observation
 Desc.: RWOS
 Location: Oxton Road, Southwell Contact:

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: C42 - Southwell		Feature Type: Street Section		Area: Newark	
39732	potholes (HW CW Pothole Z1)	from saversick lane heading towards oxton before s bends marked in yellow paint	Category 2	Job Completed	18/12/2013	25/01/2016	Act. NEW/11106
2611653	Potholes (HW CW Pothole Z1)	Service road that leads to holly cottage off the Oxton road both ends of service road leading to property's need doing	Category 2	Job Completed	04/06/2015	03/09/2015	Act. NEW/3602280
2616611	verge damage needs stoning (HW CW Verge Damage Z5)	As leaving southwell heading towards Oxton just before radley road on left hand side marked with yellow arrows	Category 1	Job Completed	25/09/2015	28/09/2015	Act. NEW/3602648
2616612	potholes (HW CW Pothole Z1)	Outside old radley farm marked	Category 1	Job Completed	25/09/2015	30/09/2015	Act. NEW-AS/5500197
2617794	verge over run needs topsoil (HW CW Verge Damage Z5)	Outside stables	Category 2	Job Completed	19/10/2015	06/04/2016	Act. NEW-AS/5500260
2626761	pothole (HW CW Pothole Z1)	Come past radley road junction towards southwell just at start of bends with anti skid marked	Category 2	Job Completed	18/03/2016	22/03/2016	Act. NEW/3603397
2634469	pothole (CW Repairs-Bituminous)	drive entrance just past radley road heading towards oxton marked	Category 1	Job Completed	09/08/2016	10/08/2016	Act. NEW-AS/5501600
2638656	potholes (CW Repairs-Bituminous)	heading from southwell to oxton edge of cway 2 just before new radley farm entrance 1 just after marked	Category 2	Job Completed	04/11/2016	07/11/2016	Act. NEW-AS/5501944
2641022	potholes (CW Repairs-Bituminous)	nr radley road	Filled when found (Cat 2)	Job Completed	19/12/2016	19/12/2016	Act.
2641023	pothole (CW Repairs-Bituminous)	as mapped	Filled when found (Cat 2)	Job Completed	19/12/2016	19/12/2016	Act.
2641024	pothole (CW Repairs-Bituminous)	as mapped	Filled when found (Cat 1)	Job Completed	19/12/2016	19/12/2016	Act.
2643706	potholes (CW Repairs-Bituminous)	from saversick lane to high friction towards oxton both side of road not marked	Category 2	Job Completed	08/02/2017	09/02/2017	Act. NEW-AS/5502340

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxton Road (26805336)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:	C42 - Southwell	Feature Type:	Street Section	Area:	Newark
2648908	Carriageway Pothole - Road Pothole - Deep pothole on corner of Cookes Lane and Oxton Road . Online report (Enquiry 6049827)	See map coordinates and description details	Filled when found (Cat 2)	Job Completed	24/04/2017	12/04/2017	Act.
2649898	Carriageway Pothole - Road Pothole - Deep pothole near New Hollybeck Garden Centre on Oxton Road . Online report (Enquiry 6049829)	See map coordinates and description details	Filled when found (Cat 2)	Job Completed	09/05/2017	04/05/2017	Act.
2651004	potholes (CW Repairs-Bituminous)	just before radley rd heading towards southwell,marked	Category 2	Job Completed	23/05/2017	24/05/2017	Act. NEW-AS/5503022
2655091	potholes (CW Repairs-Bituminous)	100 m past saversick lane heading to oxton marked	Category 2	Job Completed	01/08/2017	03/08/2017	Act. NEW-AS/5503378
2655092	pothole (CW Repairs-Bituminous)	0.3 miles from saversick lane hwading to oxton on righr hand side of C/W marked	Category 2	Job Completed	01/08/2017	03/08/2017	Act. NEW-AS/5503375
2658399	potholes (CW Repairs-Bituminous)	on bad bend up from saversick In marked stop and go advised	Category 3	Job Completed	22/09/2017	11/10/2017	Act. NEW/3605879
2661777	pothole (CW Repairs-Bituminous)	next to mirror marked opps barn	Category 3	Job Completed	07/11/2017	09/11/2017	Act. NEW-AS/5504127
2665837	potholes (CW Repairs-Bituminous)	near lc no 28 marked	Category 3	Job Completed	04/01/2018	14/01/2018	Act. NEW/3607145
2665838	pothole (CW Repairs-Bituminous)	near learchcroft hill rd next to gully marked	Category 3	Job Completed	04/01/2018	14/01/2018	Act. NEW/3607146
2665839	potholes (CW Repairs-Bituminous)	on bends marked	Category 3	Job Completed	04/01/2018	14/01/2018	Act. NEW/3607147
2665840	pothole (CW Repairs-Bituminous)	on bends marked	Category 3	Job Completed	04/01/2018	14/01/2018	Act. NEW/3607148
2665841	potholes (CW Repairs-Bituminous)	on straight in between bends marked	Category 3	Job Completed	04/01/2018	14/01/2018	Act. NEW/3607149
2665842	potholes (CW Repairs-Bituminous)	on bend marked	Category 3	Job Completed	04/01/2018	14/01/2018	Act. NEW/3607150
2665843	ptholes (CW Repairs-Bituminous)	on bends near chevron marked	Category 3	Job Completed	04/01/2018	14/01/2018	Act. NEW/3607151
2674111	pothole (CW Repairs-Bituminous)	near halam turn off marked with a arrow	Category 1	Job Completed	15/03/2018	16/03/2018	Act. NEW-AS/5505410
2674112	pothole (CW Repairs-Bituminous)	near junction of halam turn off marked with a arrow	Category 2	Job Completed	15/03/2018	16/03/2018	Act. NEW-AS/5505412
2674113	potholes (CW Repairs-Bituminous)	from saversick lane to thorney abbey farm marked	Category 3	Job Completed	15/03/2018	01/05/2018	Act. NEW/3608682
2674114	potholes (CW Repairs-Bituminous)	on bends filled when found	Filled when found (Cat 2)	Job Completed	15/03/2018	15/03/2018	Act.
2674115	pothole (CW Repairs-Bituminous)	up from saversick lane marked with a arrow near gully	Category 2	Job Completed	15/03/2018	16/03/2018	Act. NEW-AS/5505413
2674116	potholes (CW Repairs-Bituminous)	near lc no 28 marked	Category 3	Job Completed	15/03/2018	09/05/2018	Act. NEW/3608674

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxtan Road (26805336)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: C42 - Southwell		Feature Type: Street Section		Area: Newark	
2678898	pothole (CW Repairs-Bituminous)	near Ic no 28 filled when found	Filled when found (Cat 1)	Job Completed	23/04/2018	23/04/2018	Act. NEW-AS/5506049
2678899	potholes (CW Repairs-Bituminous)	near Ic no 29 marked	Category 3	Job Completed	23/04/2018	24/04/2018	Act. NEW/3609295
2678900	pothole (CW Repairs-Bituminous)	near Ic no 32 marked with a arrow	Category 2	Job Completed	23/04/2018	26/04/2018	Act. NEW-AS/5506048
2678901	potholes (CW Repairs-Bituminous)	from savesick lane to s bends all marked arrows	Category 2	Job Completed	23/04/2018	26/04/2018	Act. NEW-AS/5506047
2679581	pothole (CW Repairs-Bituminous)	opps allenby rd filled when found	Filled when found (Cat 1)	Job Completed	26/04/2018	26/04/2018	Act. NEW-AS/5506084

Street Works Notices

Organisation: NCC - NEWARK (3055004)

Works Ref: 30603192

Notice Type: Works Stop

Work Status: Works Stopped

Work Type: EToN 4: Minor

Version: 3

Start: 04/05/2016 00:00:00

Issued: 24/06/2016 12:21:29

Est. End: 06/05/2016

Work Desc: Gully Emptying

Completion: 06/05/2016

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Whole length	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	06/05/2016			06/05/2016
	Works Ref: 3633290		Version: 3			Work Desc: Install central reservation				
	Notice Type: Works Stop		Start: 20/03/2018 00:00:00							
	Work Status: Works Stopped		Issued: 21/03/2018 17:27:56							
	Work Type: EToN 4: Minor		Est. End: 21/03/2018			Completion: 21/03/2018				

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	opposite Buckland Cottage	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	21/03/2018			21/03/2018
	Works Ref: OP1700344B		Version: 1			Work Desc: Installing new signs for the reduction of the speed limit				
	Notice Type: 10 Day Initial Notice		Start: 16/01/2018 00:00:00							
	Work Status: Proposed Works		Issued: 16/01/2018 13:44:38							
	Work Type: EToN 4: Standard		Est. End: 19/01/2018			Completion:				

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Between Southwell & Oxtan	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	16/01/2018			19/01/2018

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: /B6386OXTONRSD

Notice Type: Cancellation

Work Status: Abandoned Works

Work Type: EToN 4: Major

Version: 2

Start: 06/05/2016 00:00:00

Issued: 20/04/2016 09:52:10

Est. End: 21/05/2016

Work Desc: Surface Dressing

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	B6386 Oxtan Road Southwell	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	06/05/2016			21/05/2016

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxton Road (26805336)

Street Works Notices**Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** /GULLY16/8/4**Version:** 2**Work Desc:** Gully cleansing works.**Notice Type:** Cancellation**Start:** 16/08/2017 00:00:00**Work Status:** Abandoned Works**Issued:** 21/08/2017 09:14:47**Work Type:** EToN 4: Minor**Est. End:** 18/08/2017**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	B6386 Oxton Road, Southwell to Oxton.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	16/08/2017			18/08/2017

Works Ref: 40804620**Version:** 4**Work Desc:** Removing White Lines and Studs**Notice Type:** Works Stop**Start:** 03/05/2016 00:00:00**Work Status:** Works Stopped**Issued:** 24/06/2016 12:18:35**Work Type:** EToN 4: Major**Est. End:** 03/05/2016**Completion:** 03/05/2016

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	B6386 Oxton Road Southwell	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	03/05/2016			03/05/2016

Works Ref: 40804621**Version:** 4**Work Desc:** Surface Dressing**Notice Type:** Works Stop**Start:** 09/05/2016 00:00:00**Work Status:** Works Stopped**Issued:** 24/06/2016 12:21:58**Work Type:** EToN 4: Major**Est. End:** 09/05/2016**Completion:** 09/05/2016

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	B6386 Oxton Road Southwell	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	09/05/2016			09/05/2016

Works Ref: 40804622**Version:** 4**Work Desc:** Relaying White Lines and Studs**Notice Type:** Works Stop**Start:** 21/05/2016 00:00:00**Work Status:** Works Stopped**Issued:** 24/06/2016 12:23:19**Work Type:** EToN 4: Major**Est. End:** 21/05/2016**Completion:** 21/05/2016

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	B6386 Oxton Road Southwell	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	21/05/2016			21/05/2016

Works Ref: 40808411**Version:** 1**Work Desc:** New Signs to be installed between Southwell and Oxton**Notice Type:** 10 Day Initial Notice**Start:** 08/01/2018 00:00:00**Work Status:** Proposed Works**Issued:** 30/11/2017 16:12:47**Work Type:** EToN 4: Standard**Est. End:** 12/01/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Oxton Road Southwell to Oxton	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	08/01/2018			12/01/2018

Organisation: Severn Trent Water East (9103908)**Works Ref:** 1101/000011200746**Version:** 5**Work Desc:** Long Comm Pipe Repair 0.75" Job in Verge (Grass)**Notice Type:** Registration of Reinstatement - Full**Start:** 24/08/2015 00:00:00**Work Status:** Works Stopped**Issued:** 03/09/2015 07:58:55**Work Type:** EToN 4: Minor**Est. End:** 25/08/2015**Completion:** 26/08/2015

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE OLD RADLEY FARM	Verge	Up to 1.5 Metres of Cover	2.00	1.00	A Permanent Reinstatement	26/08/2015		26/08/2015	25/08/2015

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxtou Road (26805336)

Street Works Notices

Organisation: WPD 5137 Southwell (7011537)

Works Ref: M51371913249B

Version: 10

Work Desc: 7 joint holes in tarmac footway and 235m trenching in tarmac footway and install 250m of cable for reinforcement scheme, This has to be done inconjunction with DY537M51371913249ABC.

Notice Type: Registration of Reinstatement - Full

Start: 11/07/2016 00:00:00

Work Status: Works Stopped

Issued: 30/08/2016 09:12:02

Work Type: EToN 4: Major

Est. End: 17/08/2016

Completion: 16/08/2016

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 4	Footway	Up to 1.5 Metres of Cover	10.80	0.35 A Permanent Reinstatement	16/08/2016		16/08/2016	12/08/2016
2	OUTSIDE 4	Footway	Up to 1.5 Metres of Cover	8.30	0.38 A Permanent Reinstatement	16/08/2016		16/08/2016	
3	OUTSIDE 6	Footway	Up to 1.5 Metres of Cover	20.00	0.32 A Permanent Reinstatement	16/08/2016		16/08/2016	
4	OUTSIDE 8	Footway	Up to 1.5 Metres of Cover	24.00	0.31 A Permanent Reinstatement	16/08/2016		16/08/2016	
5	outside 4	Footway	Up to 1.5 Metres of Cover	3.10	0.70 A Permanent Reinstatement	16/08/2016		16/08/2016	
6	OUTSIDE 10	Footway	Up to 1.5 Metres of Cover	11.40	0.40 A Permanent Reinstatement	16/08/2016		16/08/2016	
7	outside 18	Verge	Up to 1.5 Metres of Cover	1.00	0.30 A Permanent Reinstatement	16/08/2016		16/08/2016	
8	outside 18	Verge	Up to 1.5 Metres of Cover	1.00	0.30 A Permanent Reinstatement	16/08/2016		16/08/2016	
9	outside 18	Verge	Up to 1.5 Metres of Cover	18.00	0.30 A Permanent Reinstatement	16/08/2016		16/08/2016	
10	outside 16	Verge	Up to 1.5 Metres of Cover	4.00	0.30 A Permanent Reinstatement	16/08/2016		16/08/2016	
11	outside 14-16	Verge	Up to 1.5 Metres of Cover	14.00	0.30 A Permanent Reinstatement	16/08/2016		16/08/2016	
12	back lane cottages	Verge	Up to 1.5 Metres of Cover	30.00	0.30 A Permanent Reinstatement	16/08/2016		16/08/2016	
13	back lane cottages	Verge	Up to 1.5 Metres of Cover	1.50	1.00 A Permanent Reinstatement	15/08/2016		15/08/2016	
14	back lane cottages	Footway	Up to 1.5 Metres of Cover	3.30	0.33 A Permanent Reinstatement	15/08/2016		15/08/2016	
15	outside 8/10	Footway	Up to 1.5 Metres of Cover	7.00	0.57 A Permanent Reinstatement	15/08/2016		15/08/2016	
16	outside 8/10	Footway	Up to 1.5 Metres of Cover	4.85	0.32 A Permanent Reinstatement	15/08/2016		15/08/2016	
17	outside 8/10	Footway	Up to 1.5 Metres of Cover	4.13	0.32 A Permanent Reinstatement	16/08/2016		16/08/2016	
18	outside 8/10	Footway	Up to 1.5 Metres of Cover	1.43	0.50 A Permanent Reinstatement	15/08/2016		15/08/2016	
19	OUTSIDE 2	Verge	Up to 1.5 Metres of Cover	2.00	1.30 A Permanent Reinstatement	15/08/2016		15/08/2016	
20	outside 4	Footway	Up to 1.5 Metres of Cover	5.63	1.57 A Permanent Reinstatement	16/08/2016		16/08/2016	
21	outside 2	Footway	Up to 1.5 Metres of Cover	2.32	1.15 A Permanent Reinstatement	15/08/2016		15/08/2016	

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxtou Road (26805336)

Street Works Notices

Organisation: WPD 5137 Southwell (7011537)

Works Ref: M51371913249B

Version: 10

Work Desc: 7 joint holes in tarmac footway and 235m trenching in tarmac footway and install 250m of cable for reinforcement scheme, This has to be done inconjunction with DY537M51371913249ABC.

Notice Type: Registration of Reinstatement - Full

Start: 11/07/2016 00:00:00

Work Status: Works Stopped

Issued: 30/08/2016 09:12:02

Work Type: EToN 4: Major

Est. End: 17/08/2016

Completion: 16/08/2016

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
22	outside 2	Footway	Up to 1.5 Metres of Cover	1.73	0.38 A Permanent Reinstatement	15/08/2016		15/08/2016	
23	outside 20-24	Verge	Up to 1.5 Metres of Cover	20.00	0.30 A Permanent Reinstatement	16/08/2016		16/08/2016	
24	OUTSIDE 6	Footway	Up to 1.5 Metres of Cover	5.00	0.30 A Permanent Reinstatement	15/08/2016		15/08/2016	
25	outside 4	Verge	Up to 1.5 Metres of Cover	1.50	0.90 A Permanent Reinstatement	15/08/2016		15/08/2016	
26	outside 4	Verge	Up to 1.5 Metres of Cover	1.80	0.30 A Permanent Reinstatement	15/08/2016		15/08/2016	
27	OUTSIDE 24	Verge	Up to 1.5 Metres of Cover	3.00	1.00 A Permanent Reinstatement	16/08/2016		16/08/2016	
28	OUTSIDE BUCKLAND COTTAGE	Footway	Up to 1.5 Metres of Cover	3.20	0.80 A Permanent Reinstatement	16/08/2016		16/08/2016	
29	OUTSIDE BUCKLAND COTTAGE	Footway	Up to 1.5 Metres of Cover	1.20	0.30 A Permanent Reinstatement	16/08/2016		16/08/2016	
30	OUTSIDE 6	Footway	Up to 1.5 Metres of Cover	1.60	1.10 A Permanent Reinstatement	16/08/2016		16/08/2016	
31	OUTSIDE 2	Footway	Up to 1.5 Metres of Cover	14.00	0.30 A Permanent Reinstatement	16/08/2016		16/08/2016	
32	outside 2	Footway	Up to 1.5 Metres of Cover	1.00	0.26 A Permanent Reinstatement	16/08/2016		16/08/2016	
33	OUTSIDE 6	Footway	Up to 1.5 Metres of Cover	1.75	0.40 A Permanent Reinstatement	16/08/2016		16/08/2016	
34	outside 2	Footway	Up to 1.5 Metres of Cover	2.40	1.00 A Permanent Reinstatement	16/08/2016		16/08/2016	
35	OUTSIDE 6	Footway	Up to 1.5 Metres of Cover	0.90	0.75 A Permanent Reinstatement	16/08/2016		16/08/2016	
36	12	Footway	Up to 1.5 Metres of Cover	1.50	0.63 A Permanent Reinstatement	16/08/2016		16/08/2016	
37	12	Footway	Up to 1.5 Metres of Cover	1.40	0.30 A Permanent Reinstatement	16/08/2016		16/08/2016	
38	12	Footway	Up to 1.5 Metres of Cover	2.40	0.35 A Permanent Reinstatement	16/08/2016		16/08/2016	

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxton Road (26805336)

Street Works Notices**Organisation:** WPD 5153 Nottingham East (7011553)

Works Ref: M51531895246A **Version:** 6 **Work Desc:** 19m trenching in tarmac road and grass verge for reinforcement scheme
Notice Type: Registration of Reinstatement - Full **Start:** 09/01/2016 00:00:00
Work Status: Works Stopped **Issued:** 20/01/2016 11:19:57
Work Type: EToN 4: Standard **Est. End:** 14/01/2016 **Completion:** 14/01/2016

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE HOLLYBECK NUSERIES	Carriageway	Up to 1.5 Metres of Cover	9.00	0.40	A Permanent Reinstatement	14/01/2016		14/01/2016	14/01/2016

Works Ref: M51531985153A **Version:** 6 **Work Desc:** 1 joint hole in grass verge and 6m trenching in grass verge for reinforcement scheme - Inconjunction DY553M51531985153B,C,D
Notice Type: Registration of Reinstatement - Full **Start:** 06/03/2017 00:00:00
Work Status: Works Stopped **Issued:** 23/03/2017 10:29:47
Work Type: EToN 4: Standard **Est. End:** 10/03/2017 **Completion:** 10/03/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	SIDE OF SUB STATION	Verge	Up to 1.5 Metres of Cover	15.00	0.30	A Permanent Reinstatement	10/03/2017		10/03/2017	10/03/2017
2	SIDE OF SUB STATION	Verge	Up to 1.5 Metres of Cover	1.50	1.00	A Permanent Reinstatement	10/03/2017		10/03/2017	
3	SIDE OF SUB STATION	Verge	Up to 1.5 Metres of Cover	2.50	1.00	A Permanent Reinstatement	10/03/2017		10/03/2017	

Works Ref: M51531985912AZ **Version:** 6 **Work Desc:** 1 joint hole in grass verge for reinforcement scheme. Inconjunction with notice DY553M51531985912AZ
Notice Type: Works Stop **Start:** 20/03/2017 00:00:00
Work Status: Works Stopped **Issued:** 27/03/2017 16:51:43
Work Type: EToN 4: Standard **Est. End:** 24/03/2017 **Completion:** 24/03/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	60metres away from Junction of Thurgaton Quaters Lane to Junction of Oxton Hill	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	24/03/2017			24/03/2017