

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxton Hill (26822304)

Street: Oxton Hill (26822304)

Locality: Oxton, Nottinghamshire

Area: Newark

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b>	2,000.00	<b>Feature Id - Locn.:</b>	C42	<b>Feature Type:</b> Street Section			<b>Area:</b> Newark	
<b>Batch:</b> 20283895 - Inspection Batch		<b>Route:</b> Newark Area 2 May Saf CW			<b>Date:</b> 17/05/2018			
No actionable defects found								
<b>Batch:</b> 20279145 - Inspection Batch		<b>Route:</b> Newark Area 2 Apr Enh CW/FW			<b>Date:</b> 23/04/2018			
No actionable defects found								
<b>Batch:</b> 20272571 - Inspection Batch		<b>Route:</b> Newark Area 2 Mar Saf CW			<b>Date:</b> 15/03/2018			
3571109	potholes	15/03/2018	half way down the hill marked with arrows on side	CW Repairs-Bituminous	Internal		Committed	2674098
3571108	pothole	15/03/2018	near layby marked	CW Repairs-Bituminous	Internal		Committed	2674100
3571107	pothole	15/03/2018	top of hill opps granary barn marked with a arrow	CW Repairs-Bituminous	Internal		Committed	2674099
<b>Batch:</b> 20268300 - Inspection Batch		<b>Route:</b> Newark Area 2 Feb Saf CW			<b>Date:</b> 14/02/2018			
3568020	potholes	14/02/2018	half way down oxton hill, marked	CW Repairs-Bituminous	Internal		Committed	2670977
3568019	pothole	14/02/2018	nr ridgewood, marked	CW Repairs-Bituminous	Internal		Committed	2670976
3568021	potholes	14/02/2018	200m from radley ln, entrance to old radley farm, maked	CW Repairs-Bituminous	Internal		Committed	2670975
<b>Batch:</b> 20261373 - Inspection Batch		<b>Route:</b> Newark Area 2 Jan Saf CW			<b>Date:</b> 04/01/2018			
3562958	potholes	04/01/2018	top of oxton hill marked	CW Repairs-Bituminous	Internal		Committed	2665851
3562957	pothole	04/01/2018	around fh marked	CW Repairs-Bituminous	Internal		Committed	2665850
3562960	potholes	04/01/2018	near layby marked	CW Repairs-Bituminous	Internal		Committed	2665849
3562959	potholes	04/01/2018	on oxton hill marked	CW Repairs-Bituminous	Internal		Committed	2665852
<b>Batch:</b> 20259810 - Inspection Batch		<b>Route:</b> Newark Area 2 Dec Saf CW			<b>Date:</b> 19/12/2017			
No actionable defects found								
<b>Batch:</b> 20253600 - Inspection Batch		<b>Route:</b> Newark Area 2 Nov Saf CW			<b>Date:</b> 07/11/2017			
No actionable defects found								
<b>Batch:</b> 20250916 - Inspection Batch		<b>Route:</b> Newark Area 2 Oct Saf CW			<b>Date:</b> 19/10/2017			
3557779	pothole	19/10/2017	50m from layby around fh marked	CW Repairs-Bituminous	Internal		Uncommitted	2660433
<b>Batch:</b> 20247117 - Inspection Batch		<b>Route:</b> Newark Area 2 Sep Saf CW			<b>Date:</b> 22/09/2017			
3555872	pothole	22/09/2017	at the top of oxton hill marked	CW Repairs-Bituminous	Internal		Committed	2658388
<b>Batch:</b> 20243420 - Inspection Batch		<b>Route:</b> Newark Area 2 Jun Saf CW			<b>Date:</b> 29/08/2017			
No actionable defects found								
<b>Batch:</b> 20242835 - Inspection Batch		<b>Route:</b> Newark Area 2 Aug Saf CW			<b>Date:</b> 23/08/2017			
3553983	pothole	23/08/2017	os clement house marked	CW Repairs-Bituminous	Internal		Committed	2656432
<b>Batch:</b> 20240164 - Inspection Batch		<b>Route:</b> Newark Area 2 Jul Saf CW			<b>Date:</b> 01/08/2017			
No actionable defects found								
<b>Batch:</b> 20229800 - Inspection Batch		<b>Route:</b> Newark Area 2 May Saf CW			<b>Date:</b> 12/05/2017			
No actionable defects found								

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxtan Hill (26822304)

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> C42			<b>Feature Type:</b> Street Section			<b>Area:</b> Newark	
<b>Batch:</b> 20226778 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 25/04/2017
3547160	concrete spillage on carriage way approx 8 sq m , photo's attached	25/04/2017	oxton hill	Other	Internal		Committed	2649029
<b>Batch:</b> 20226655 - Inspection Batch				<b>Route:</b> Newark Area 2 Apr Enh CW/FW				<b>Date:</b> 25/04/2017
	No actionable defects found							
<b>Batch:</b> 20220036 - Inspection Batch				<b>Route:</b> Newark Area 2 Mar Saf CW				<b>Date:</b> 07/03/2017
	No actionable defects found							
<b>Batch:</b> 20218141 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 23/02/2017
3543216	Carriageway Potholes	23/02/2017	in large layby, not marked due to parked vehicles, please just fill the worst	CW Repairs-Bituminous	Internal		Committed	2644943
<b>Batch:</b> 20215856 - Inspection Batch				<b>Route:</b> Newark Area 2 Feb Saf CW				<b>Date:</b> 08/02/2017
	No actionable defects found							
<b>Batch:</b> 20211894 - Inspection Batch				<b>Route:</b> Newark Area 2 Jan Saf CW				<b>Date:</b> 10/01/2017
	No actionable defects found							
<b>Batch:</b> 20209559 - Inspection Batch				<b>Route:</b> Newark Area 2 Dec Saf CW				<b>Date:</b> 19/12/2016
3539386	pothole	19/12/2016	opposite layby towards oxton	CW Repairs-Bituminous	Internal		Uncommitted	2641020
<b>Batch:</b> 20203870 - Inspection Batch				<b>Route:</b> Newark Area 2 Nov Saf CW				<b>Date:</b> 04/11/2016
	No actionable defects found							
<b>Batch:</b> 20200601 - Inspection Batch				<b>Route:</b> Newark Area 2 Oct Saf CW				<b>Date:</b> 13/10/2016
	No actionable defects found							
<b>Batch:</b> 20195644 - Inspection Batch				<b>Route:</b> Newark Area 2 Sep Saf CW				<b>Date:</b> 06/09/2016
3534214	potholes fill as required	06/09/2016	in lay by not marked	CW Repairs-Bituminous	Internal		Committed	2635513
<b>Batch:</b> 20192634 - Inspection Batch				<b>Route:</b> Newark Area 2 Aug Saf CW				<b>Date:</b> 09/08/2016
	No actionable defects found							
<b>Batch:</b> 20189391 - Inspection Batch				<b>Route:</b> Newark Area 2 Jul Saf CW				<b>Date:</b> 18/07/2016
	No actionable defects found							
<b>Batch:</b> 20184056 - Inspection Batch				<b>Route:</b> Newark Area 2 Jun Saf CW				<b>Date:</b> 07/06/2016
	No actionable defects found							
<b>Batch:</b> 20179333 - Inspection Batch				<b>Route:</b> Newark Area 2 May Saf CW				<b>Date:</b> 09/05/2016
	No actionable defects found							
<b>Batch:</b> 20174464 - Inspection Batch				<b>Route:</b> Newark Area 2 Apr Enh CW/FW				<b>Date:</b> 06/04/2016
	No actionable defects found							
<b>Batch:</b> 20170663 - Inspection Batch				<b>Route:</b> Newark Area 2 Mar Saf CW				<b>Date:</b> 07/03/2016
	No actionable defects found							
<b>Batch:</b> 20164642 - Inspection Batch				<b>Route:</b> Newark Area 2 Feb Saf CW				<b>Date:</b> 02/02/2016
	No actionable defects found							

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxtan Hill (26822304)

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> C42			<b>Feature Type:</b> Street Section			<b>Area:</b> Newark	
<b>Batch:</b> 20161830 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 2 Jan Saf CW				<b>Date:</b> 14/01/2016
<b>Batch:</b> 20156897 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 2 Dec Saf CW				<b>Date:</b> 03/12/2015
<b>Batch:</b> 20151689 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 2 Nov Saf CW				<b>Date:</b> 02/11/2015
<b>Batch:</b> 20147911 - Inspection Batch				<b>Route:</b> Newark Area 2 Oct Saf CW				<b>Date:</b> 06/10/2015
3516436 pothole		06/10/2015	On top of Oxtan hill	HW CW Pothole Z1	Internal		Uncommitted	2617119
<b>Batch:</b> 20143482 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 2 Sep Saf CW				<b>Date:</b> 08/09/2015
<b>Batch:</b> 20140725 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 2 Aug Saf CW				<b>Date:</b> 14/08/2015
<b>Batch:</b> 20135898 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 2 Jul Saf CW				<b>Date:</b> 07/07/2015
<b>Batch:</b> 20131830 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 2 Jun Saf CW				<b>Date:</b> 09/06/2015

**Customer Services****Enquiry No.:** 6084707**Logged by:** External to Confirm**on:** 07/03/2018 11:21**Service:** Carriageway/Footway**Subject:** Line Marking/Stud Renewal**Classification:** Report or Observation**Enquiry Ref:** FS-CASE-69693602**Desc.:** Road marking renewal - The solid double white line system on Oxtan Hill (on the bendy bit) has completely worn away and is not visible in several places.

This could lead to inappropriate overtaking and in the event of an RTC, we would be unable to prosecute the offending vehicle for overtaking on the solid white lines in their current condition.

Please could someone visit the location and assess the condition of the lines?

Thank you in anticipation.

██████████  
 Police Volunteer  
 EMOPss SCIU Team.  
 Working Wednesdays Only.

. Online report

**Location:** Oxtan Hill (on the bendy bit)**Contact:****Enquiry No.:** 6058810**Logged by:** External to Confirm**on:** 19/07/2017 14:30**Service:** Traffic Management**Subject:** Parking General**Classification:** Report or Observation**Enquiry Ref:** FS-CASE-56193451**Desc.:** parking issues**Location:** See map coordinates and description details**Contact:**

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxton Hill (26822304)

**Customer Services**

**Enquiry No.:** 6058630      **Logged by:** External to Confirm      **on:** 18/07/2017 10:06  
**Service:** Carriageway/Footway      **Subject:** Carriageway Obstruction      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-56122776  
**Desc.:** Road obstructions - Customer is reporting obstructions due to a building development at Oxton Hill farm. Due to this development, there are numerous problems. Firstly, there are trucks and vans parked everywhere around the area, which is making it very difficult for pedestrians to walk around the area, as there are no footpaths, so children are having to use grass verges to get to their bus stops for school. Secondly, the traffic controls in place are also not helping the area, as the customer almost drove into oncoming traffic due to the congested area, and it is currently dangerous driving in this area. There are also utility works have started also and this is causing further disruption to this area. The customer says the vehicles could park on the land behind so that they are not obstructing the walkways, but are parked on Southwell road, which is adding to disruption. . Submitted by Advisor: [REDACTED]  
**Location:** See map coordinates and description details      **Contact:**

**Enquiry No.:** 6043679      **Logged by:** External to Confirm      **on:** 20/02/2017 15:11  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-13093308  
**Desc.:** Road Pothole - Multiple potholes on the left hand side of the pull in, have previously dented 2 wheels on these potholes . Online report  
**Location:** See map coordinates and description details      **Contact:**

**Plot Number:** 2,000.00      **Feature Id - Location:** C42      **Feature Type:** Street Section  
**Job Number:** 2644943      **Defect Number:** 3543216

**Enquiry No.:** 6032303      **Logged by:** External to Confirm      **on:** 01/11/2016 12:43  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-9369392  
**Desc.:** Road Pothole - Pot hole is located at the entrance of a layby on the B6386 Southwell Road heading from Oxton to Southwell and it is just before the The Spinney School of fine food. 31/10/2016 16:30

Customer email below:

[REDACTED].ukPothole damage.

Dear sir/madam, I visited Oxton on Friday 23rd of September to work at an event at Southwell ploughing match. Whilst on my way to the event I drove over a pothole and it subsequently burst my tyre and damaged my steering. I now would like the highways department of the council to reimburse me for the damage to my vehicle as it is not my fault the local council have not maintained the roads properly in that area. Please can someone contact me about this issue as soon as possible please. Regards [REDACTED]

Submitted by Advisor: [REDACTED]

**Location:** The pin has been placed near Southwell Road, Southwell, United Kingdom, NG25 0RN      **Contact:**

**Plot Number:** 2,000.00      **Feature Id - Location:** C42      **Feature Type:** Street Section  
**Job Number:** 2635513      **Defect Number:** 3534214

**Enquiry No.:** 6006675      **Logged by:** External to Confirm      **on:** 23/02/2016 09:28  
**Service:** Trees/Verges      **Subject:** Tree Enquiry      **Classification:** Report or Observation      **Enquiry Ref:** 103876146  
**Desc.:** Workers were cutting down trees for a whole week on the highway around Marssett House Oxton Hill. Customer wants to know who the workers were, as they have been on her property and taken stuff. There was only about 6 men working cutting down some massive trees on the highway and would have seen into her property. Customer believes the workers has been thieving at her property. Police have been informed. Customer wants to know who the workers were: NCC or contracted out? Information would need releasing to the police if NCC does not want to give it to the customer. Please contact the customer ASAP.  
 Logged by CSC operator: [REDACTED]

**Location:** 45 meters from Oxton Hill      **Contact:**

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxton Hill (26822304)

**Customer Services**

Enquiry No.: 3203267

Logged by: [REDACTED]

on: 01/11/2016 13:06

Service: Claims

Subject: Highway Insurance Claim

Classification: Report or Observation

Enquiry Ref: 6032303

Desc.: Defect raised on 6032303  
Incident details:

Date of incident: 23/09/2016

Time of incident: 2pm

Direction of travel: Heading from in the direction of Southwell from Oxton.

What happened: 31/10/2016 16:30  
[REDACTED]

[REDACTED].ukPothole damage.

Dear sir/madam, I visited Oxton on Friday 23rd of September to work at an event at Southwell ploughing match. Whilst on my way to the event I drove over a pothole and it subsequently burst my tyre and damaged my steering. I now would like the highways department of the council to reimburse me for the damage to my vehicle as it is not my fault the local council have not maintained the roads properly in that area. Please can someone contact me about this issue as soon as possible please. Regards [REDACTED] =

Location: Layby on B3686 Oxton

Contact:

Enquiry No.: 3201721

Logged by: [REDACTED]

on: 07/12/2015 10:05

Service: Carriageway/Footway

Subject: Carriageway Obstruction

Classification: Report or Observation

Desc.: wind blown tree

Location: oxton hill

Contact:

Enquiry No.: 3199044

Logged by: External to Confirm

on: 30/12/2015 13:47

Service: Trees/Verges

Subject: Fallen Tree

Classification: Report or Observation

Enquiry Ref: 103828593

Desc.: Large branch has come down and is blocking the road. Still attached to the tree and has been pushed out of the way but wind is pushing it back into the road.

Incident no: 38130122015

Logged by CSC operator: [REDACTED]

Location: 104 meters from Middlehey Oxton Hill

Contact:

Enquiry No.: 3199040

Logged by: External to Confirm

on: 30/12/2015 13:30

Service: Trees/Verges

Subject: Fallen Tree

Classification: Report or Observation

Enquiry Ref: 103828562

Desc.: On Oxton Hill (Southwell road) there is a tree on the right hand side of the road (as if your travelling towards birkhouse) which has fell and is blocking one side of the road. causing traffic backlog.

Logged by CSC operator: [REDACTED]

Location: 92 meters from Oxton Hill

Contact:

Enquiry No.: 71127

Logged by: [REDACTED]

on: 23/04/2018 11:05

Service: Highway Searches

Subject: Extents and CON29

Classification: Report or Observation

Desc.: requested £62.34 - 23.4.18 received chq 26.4.18

Location: Marsett House, Oxton Hill, Southwell

Contact:

Enquiry No.: 69478

Logged by: [REDACTED]

on: 20/02/2018 11:49

Service: Road Works

Subject: Utility Works

Classification: Report or Observation

Desc.: Permission to site BT Broadband cabinet PCP016

Location: S/O Birkhouse Cottage, Oxton Hill

Contact:

Plot Number: 2,000.00

Feature Id - Location: C42

Feature Type: Street Section

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxton Hill (26822304)

**Customer Services**

Enquiry No.: 66003      Logged by: [REDACTED]      on: 13/09/2017 16:52  
 Service: Carriageway/Footway      Subject: Blocked Drain      Classification: Report or Observation  
 Desc.: From: [REDACTED]  
 Sent: 13 September 2017 13:47  
 To: [REDACTED] >  
 Subject: Clearing of gullies on Oxton Hill B6386

At the Oxton Parish Council meeting last night the issue of the blocked gullies at the side of the road on Oxton Hill (B6386) was raised. Our County Councillor, [REDACTED], suggested I should contact you to request that these gullies be cleared out. You may know that Oxton tries to be proactive in taking any actions which may alleviate the flood risk in Oxton and these gullies will have a direct effect on the amount of water which rushes down Oxton Hill and into the village via Sandy Lane. I would appreciate it if you could arrange for the clearing to take place as soon as possible. For your information I am also contacting District Council to ask them to arrange for Oxton Hill to be swept because there is a large amount of debris at the side of the road which will be washed down in heavy rain.

Regards

[REDACTED] Oxton Parish Council

Location: Oxton Hill

Contact:

Enquiry No.: 65139      Logged by: [REDACTED]      on: 03/08/2017 08:00  
 Service: Highway Searches      Subject: Adoption Extents      Classification: Report or Observation  
 Desc.: requested £42.00 - 2.8.17 received BACS 3.8.17  
 Location: Granary Barn, Oxton Hill Farm, Oxton Hill, Oxton/Southwell      Contact:

Enquiry No.: 38633      Logged by: [REDACTED]      on: 18/08/2015 09:08  
 Service: Highway Searches      Subject: Searches - Other Enquiries      Classification: Report or Observation  
 Desc.: requested £51.00 18.8.15. received 20.8.15  
 Location: land at Oxton Hill Farm, Oxton Hill, Southwell NG25 0RB      Contact:

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: C42		Feature Type: Street Section		Area: Newark	
2617119	pothole ( HW CW Pothole Z1)	On top of Oxton hill	Filled when found (Cat 2)	Job Completed	06/10/2015	06/10/2015	Act.
2635513	potholes fill as required (CW Repairs-Bituminous)	in lay by not marked	Category 3	Job Completed	06/09/2016	27/09/2016	Act. NEW/3604048
2641020	pothole (CW Repairs-Bituminous)	opposite layby towards oxton	Filled when found (Cat 2)	Job Completed	19/12/2016	19/12/2016	Act.
2644943	Carriageway Potholes (CW Repairs-Bituminous)	in large layby, not marked due to parked vehicles, please just fill the worst	Category 2	Job Completed	23/02/2017	27/02/2017	Act. NEW-AS/5502501
2649029	concrete spillage on carriage way oxton hill approx 8 sq m , photo's attached (Other)		Category 2	Job Completed	25/04/2017	28/04/2017	Act. NEW/3604829
2656432	pothole (CW Repairs-Bituminous)	os clement house marked	Category 3	Job Completed	23/08/2017	24/08/2017	Act. NEW-AS/5503629
2658388	pothole (CW Repairs-Bituminous)	at the top of oxton hill marked	Category 3	Job Completed	22/09/2017	25/09/2017	Act. NEW-AS/5503867
2660433	pothole (CW Repairs-Bituminous)	50m from layby around fh marked	Filled when found (Cat 2)	Job Completed	19/10/2017	19/10/2017	Act.

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxtan Hill (26822304)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> C42		<b>Feature Type:</b> Street Section		<b>Area:</b> Newark	
2665849	potholes (CW Repairs-Bituminous)	near layby marked	Category 3	Job Completed	04/01/2018	14/01/2018	Act. NEW/3607152
2665850	pothole (CW Repairs-Bituminous)	around fh marked	Category 2	Job Completed	04/01/2018	05/01/2018	Act. NEW-AS/5504396
2665851	potholes (CW Repairs-Bituminous)	top of oxtan hill marked	Category 3	Job Completed	04/01/2018	02/02/2018	Act. NEW/3607153
2665852	potholes (CW Repairs-Bituminous)	on oxtan hill marked	Category 3	Job Completed	04/01/2018	14/01/2018	Act. NEW/3607154
2670975	potholes (CW Repairs-Bituminous)	200m from radley ln, entrance to old radley farm, maked	Category 2	Job Completed	14/02/2018	15/02/2018	Act. NEW-AS/5505030
2670976	pothole (CW Repairs-Bituminous)	nr ridgewood, marked	Category 3	Job Completed	14/02/2018	03/04/2018	Act. NEW/3608012
2670977	potholes (CW Repairs-Bituminous)	half way down oxtan hill, marked	Category 3	Job Completed	14/02/2018	03/04/2018	Act. NEW/3608013
2674098	potholes (CW Repairs-Bituminous)	half way down the hill marked with arrows on side	Category 2	Job Completed	15/03/2018	19/03/2018	Act. NEW-AS/5505420
2674099	pothole (CW Repairs-Bituminous)	top of hill opps granary barn marked with a arrow	Category 2	Job Completed	15/03/2018	19/03/2018	Act. NEW-AS/5505411
2674100	pothole (CW Repairs-Bituminous)	near layby marked	Category 2	Job Completed	15/03/2018	20/03/2018	Act. NEW/3608687

**Street Works Inspections**

Organisation: Severn Trent Water East (9103908)

Works Ref: 1101/000010986701

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 24/10/2016 13:05:10
<b>Category:</b> Category C		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Sampled Site No:</b> 1
			<b>Site Informed:</b> Yes
			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Site Location:</b> OXTON HILL SOUTHWELL
<b>Insp. Notes:</b>			<b>Position:</b> Carriageway
<b>Defect Notes:</b>			<b>Site Post Code:</b>

Works Ref: 1101/000011176409

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 04/12/2015 09:25:52
<b>Category:</b> Category B		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Sampled Site No:</b> 1
			<b>Site Informed:</b> Yes
			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Site Location:</b> 1
<b>Insp. Notes:</b>			<b>Position:</b> Verge
<b>Defect Notes:</b>			<b>Site Post Code:</b>

Effective: 20/05/2015 to 20/05/2018

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Oxtan Hill (26822304)

**Street Works Inspections**

Organisation: WPD 5153 Nottingham East (7011553)

Works Ref: M51531985703

<b>Group No:</b> 2	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 20/03/2017 07:53:58
<b>Category:</b> Category B		<b>Outcome:</b> Abortive	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Site Location:</b> OPPOSITE BUILDING SITE
<b>Insp. Notes:</b>			<b>Position:</b> Verge
<b>Defect Notes:</b>			<b>Site Post Code:</b>

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 28/02/2017 13:59:57
<b>Category:</b> Category A		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Site Location:</b> OPPOSITE BUILDING SITE
<b>Insp. Notes:</b> working in verge			<b>Position:</b> Verge
<b>Defect Notes:</b> working in verge			<b>Site Post Code:</b>

Works Ref: M51531994927

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 11/05/2017 15:59:01
<b>Category:</b> Category A		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Site Location:</b> OUTSIDE OXTON HILL FARM
<b>Insp. Notes:</b>			<b>Position:</b> Carriageway
<b>Defect Notes:</b>			<b>Site Post Code:</b>

**Street Works Notices**

Organisation: Events in Nottinghamshire (3055365)

<b>Works Ref:</b> NK178-15B	<b>Version:</b> 1	<b>Work Desc:</b> Southwell Ploughing Match
<b>Notice Type:</b> 3 Day Initial Notice	<b>Start:</b> 26/09/2015 00:00:00	
<b>Work Status:</b> Proposed Works	<b>Issued:</b> 08/09/2015 15:09:10	
<b>Work Type:</b> EToN 4: Minor	<b>Est. End:</b> 26/09/2015	<b>Completion:</b>

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Whole length	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	26/09/2015			26/09/2015

Organisation: NCC - NEWARK (3055004)

<b>Works Ref:</b> 30603191	<b>Version:</b> 3	<b>Work Desc:</b> Gully Emptying
<b>Notice Type:</b> Works Stop	<b>Start:</b> 04/05/2016 00:00:00	
<b>Work Status:</b> Works Stopped	<b>Issued:</b> 24/06/2016 12:32:43	
<b>Work Type:</b> EToN 4: Standard	<b>Est. End:</b> 06/05/2016	<b>Completion:</b> 06/05/2016

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Whole length	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	06/05/2016			06/05/2016



Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxton Hill (26822304)

**Street Works Notices****Organisation:** NCC - NEWARK (3055004)**Works Ref:** 4057406**Version:** 1**Work Desc:** Clear overgrown trees and bushes back from carriageway edge**Notice Type:** 10 Day Initial Notice**Start:** 18/01/2016 00:00:00**Work Status:** Proposed Works**Issued:** 21/12/2015 16:12:05**Work Type:** EToN 4: Standard**Est. End:** 29/01/2016**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Oxton Hill west of Marsett House	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	18/01/2016			29/01/2016

**Works Ref:** OP1700344A**Version:** 1**Work Desc:** Installing new signs for the reduction of the speed limit**Notice Type:** 10 Day Initial Notice**Start:** 16/01/2018 00:00:00**Work Status:** Proposed Works**Issued:** 16/01/2018 13:42:46**Work Type:** EToN 4: Standard**Est. End:** 19/01/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Between Southwell & Oxton	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	16/01/2018			19/01/2018

**Organisation:** NRSWA - BT (0030005)**Works Ref:** WP00100500226232300**Version:** 4**Work Desc:** Install 1m of 1 way poly duct in Verge, Provide 1 core drill(s) into jointbox or building**Notice Type:** Registration of Reinstatement - Full**Start:** 02/11/2016 00:00:00**Work Status:** Works Stopped**Issued:** 18/11/2016 09:57:30**Work Type:** EToN 4: Minor**Est. End:** 04/11/2016**Completion:** 04/11/2016

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	13M WEST FROM ENTRANCE TO OXTON HILL FARM ON, OXTON HILL	Verge	Up to 1.5 Metres of Cover	2.00	0.60	A Permanent Reinstatement	04/11/2016		04/11/2016	04/11/2016

**Organisation:** Severn Trent Asset Creation Distribution East (9103502)**Works Ref:** A5W/10605100A**Version:** 4**Work Desc:** EXCAVATE IN VERGE TO BUILD CHAMBER AND INSTALL WASHOUT AND HYDRANT ON 20INCH WATER MAIN**Notice Type:** Registration of Reinstatement - Full**Start:** 03/10/2016 00:00:00**Work Status:** Works Stopped**Issued:** 21/10/2016 07:44:45**Work Type:** EToN 4: Standard**Est. End:** 07/10/2016**Completion:** 07/10/2016

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Approx 20m west and opposite Thurgarton Quarters Lane	Verge	Up to 1.5 Metres of Cover	3.00	2.00	A Permanent Reinstatement	07/10/2016		07/10/2016	07/10/2016

**Organisation:** Severn Trent New Connections East - Water (9103920)**Works Ref:** 0000/00006431517**Version:** 5**Work Desc:** New water Connection New water Connection**Notice Type:** Registration of Reinstatement - Full**Start:** 07/08/2017 00:00:00**Work Status:** Works Stopped**Issued:** 10/08/2017 12:50:07**Work Type:** EToN 4: Minor**Est. End:** 09/08/2017**Completion:** 09/08/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OXTON HILL FARM OXTON HILL OXTON NOTTINGHAMSHIRE	Carriageway	Up to 1.5 Metres of Cover	1.90	0.90	A Permanent Reinstatement	09/08/2017		09/08/2017	09/08/2017
2	OXTON HILL FARM OXTON HILL OXTON NOTTINGHAMSHIRE	Verge	Up to 1.5 Metres of Cover	5.00	1.00	A Permanent Reinstatement	09/08/2017		09/08/2017	

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxtan Hill (26822304)

**Street Works Notices****Organisation:** Severn Trent New Connections East - Water (9103920)**Works Ref:** 0000/00006431517**Version:** 5**Work Desc:** New water Connection New water Connection**Notice Type:** Registration of Reinstatement - Full**Start:** 07/08/2017 00:00:00**Work Status:** Works Stopped**Issued:** 10/08/2017 12:50:07**Work Type:** EToN 4: Minor**Est. End:** 09/08/2017**Completion:** 09/08/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
3	OXTON HILL FARM OXTON HILL OXTON NOTTINGHAMSHIRE	Carriageway	Up to 1.5 Metres of Cover	1.50	1.40	A Permanent Reinstatement	09/08/2017		09/08/2017	

**Organisation:** Severn Trent Water East (9103908)**Works Ref:** 1101/000011137127**Version:** 4**Work Desc:** Boundary box Repair VL Job in Verge (Grass )**Notice Type:** Registration of Reinstatement - Full**Start:** 23/05/2015 11:14:00**Work Status:** Works Stopped**Issued:** 09/06/2015 10:32:32**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 27/05/2015**Completion:** 27/05/2015

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	120METERS FROM DUNBLE END FARM	Verge	Up to 1.5 Metres of Cover	1.20	1.20	A Permanent Reinstatement	27/05/2015		27/05/2015	26/05/2015

**Works Ref:** 1101/000011176409**Version:** 3**Work Desc:** Short Comm Pipe Repair 25mm Job in Verge (Grass )**Notice Type:** Works Stop**Start:** 27/07/2015 13:32:00**Work Status:** Works Stopped**Issued:** 28/07/2015 16:51:12**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 29/07/2015**Completion:** 28/07/2015

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	1	Verge	Up to 1.5 Metres of Cover	1.00	1.00	A Permanent Reinstatement	28/07/2015		28/07/2015	29/07/2015

**Works Ref:** 1101/000011199629**Version:** 2**Work Desc:** Large Main Cut out Piece through 7" Job in Verge (Unmade )**Notice Type:** Cancellation**Start:** 01/09/2015 00:00:00**Work Status:** Abandoned Works**Issued:** 07/09/2015 09:06:22**Work Type:** EToN 4: Minor**Est. End:** 03/09/2015**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	(DISUSED)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	01/09/2015			03/09/2015

**Works Ref:** 1101/000011375944**Version:** 4**Work Desc:** Boundary box Install 25mm Job in Carriageway (Bitumen Macadam (Tarmac) )**Notice Type:** Registration of Reinstatement - Full**Start:** 17/05/2016 00:00:00**Work Status:** Works Stopped**Issued:** 18/05/2016 11:09:12**Work Type:** EToN 4: Minor**Est. End:** 19/05/2016**Completion:** 18/05/2016

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OXTON HILL	Carriageway	Up to 1.5 Metres of Cover	1.10	0.90	A Permanent Reinstatement	18/05/2016		18/05/2016	19/05/2016

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxtan Hill (26822304)

**Street Works Notices****Organisation:** Severn Trent Water East (9103908)**Works Ref:** 1101/000011888977**Version:** 4**Work Desc:** Small Main Repair Collar 4\*\*2WTL Job in Verge (Unmade )**Notice Type:** Registration of Reinstatement - Full**Start:** 14/05/2018 15:26:00**Work Status:** Works Stopped**Issued:** 22/05/2018 10:29:52**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 16/05/2018**Completion:** 15/05/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	37M EAST FROM ENTRANCE TO BIRKHOUSE	Verge	Over 1.5 Metres of Cover	3.00	1.00 A Permanent Reinstatement	15/05/2018		15/05/2018	16/05/2018

**Organisation:** WPD 5153 Nottingham East (7011553)**Works Ref:** M51530551013**Version:** 2**Work Desc:** Overhead Works Only - No excavation for Reconductoring**Notice Type:** Cancellation**Start:** 21/02/2017 00:00:00**Work Status:** Abandoned Works**Issued:** 21/02/2017 15:10:16**Work Type:** EToN 4: Standard**Est. End:** 24/02/2017**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	outside severn trent reservoir	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	21/02/2017			24/02/2017

**Works Ref:** M51531895246B**Version:** 5**Work Desc:** Traffic light head only - no excavation**Notice Type:** Works Stop**Start:** 09/01/2016 00:00:00**Work Status:** Works Stopped**Issued:** 14/01/2016 14:00:03**Work Type:** EToN 4: Standard**Est. End:** 14/01/2016**Completion:** 14/01/2016

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Appropriate distance Oxtan side of Hollybeck nurseries.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	14/01/2016			14/01/2016

**Works Ref:** M51531985153D**Version:** 5**Work Desc:** 1 joint hole in grass verge and 6m trenching in grass verge for reinforcement scheme in conjunction with DY553M51531985153A,B, C**Notice Type:** Registration of Reinstatement - Full**Start:** 06/03/2017 00:00:00**Work Status:** Works Stopped**Issued:** 23/03/2017 10:50:44**Work Type:** EToN 4: Standard**Est. End:** 10/03/2017**Completion:** 10/03/2017

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	OPPOSITE HOLLY COTTAGE	Carriageway	Up to 1.5 Metres of Cover	1.50	1.00 A Permanent Reinstatement	10/03/2017		10/03/2017	10/03/2017

**Works Ref:** M51531985691**Version:** 2**Work Desc:** 2 joint holes in grass verge for new substation**Notice Type:** Cancellation**Start:** 22/02/2017 00:00:00**Work Status:** Abandoned Works**Issued:** 24/02/2017 11:03:07**Work Type:** EToN 4: Standard**Est. End:** 28/02/2017**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	opposite the lodge - 67m west and 86m east of Two Acres	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	22/02/2017			28/02/2017

Effective: 20/05/2015 to 20/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Oxtou Hill (26822304)

**Street Works Notices****Organisation:** WPD 5153 Nottingham East (7011553)**Works Ref:** M51531985703**Version:** 7**Work Desc:** 2 joint holes in grass verge and 63m trenching in tarmac road and grass verge and install**Notice Type:** Registration of Reinstatement - Full**Start:** 22/02/2017 00:00:00

136m of ducting for new substation

**Work Status:** Works Stopped**Issued:** 15/03/2017 11:57:08**Work Type:** EToN 4: Standard**Est. End:** 01/03/2017**Completion:** 01/03/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop.	End
1	OPPOSITE BUILDING SITE	Verge	Up to 1.5 Metres of Cover	22.30	0.40	A Permanent Reinstatement	01/03/2017		01/03/2017		28/02/2017
2	OPPOSITE BUILDING SITE	Carriageway	Up to 1.5 Metres of Cover	7.60	0.40	A Permanent Reinstatement	01/03/2017		01/03/2017		
3	OPPOSITE BUILDING SITE	Verge	Up to 1.5 Metres of Cover	26.00	0.40	A Permanent Reinstatement	01/03/2017		01/03/2017		
4	OPPOSITE BUILDING SITE	Verge	Up to 1.5 Metres of Cover	20.00	0.40	A Permanent Reinstatement	01/03/2017		01/03/2017		
5	OPPOSITE BUILDING SITE	Verge	Up to 1.5 Metres of Cover	20.00	0.40	A Permanent Reinstatement	01/03/2017		01/03/2017		
6	OPPOSITE BUILDING SITE	Verge	Up to 1.5 Metres of Cover	20.00	0.40	A Permanent Reinstatement	01/03/2017		01/03/2017		
7	OPPOSITE BUILDING SITE	Verge	Up to 1.5 Metres of Cover	20.00	0.40	A Permanent Reinstatement	01/03/2017		01/03/2017		
8	OPPOSITE BUILDING SITE	Verge	Up to 1.5 Metres of Cover	20.00	0.40	A Permanent Reinstatement	01/03/2017		01/03/2017		
9	OPPOSITE BUILDING SITE	Verge	Up to 1.5 Metres of Cover	20.00	0.40	A Permanent Reinstatement	01/03/2017		01/03/2017		
10	OPPOSITE BUILDING SITE	Verge	Up to 1.5 Metres of Cover	20.00	0.40	A Permanent Reinstatement	01/03/2017		01/03/2017		
11	OPPOSITE LODGE COTTAGE	Verge	Up to 1.5 Metres of Cover	15.20	0.40	A Permanent Reinstatement	01/03/2017		01/03/2017		
12	OPPOSITE BUILDING SITE	Carriageway	Up to 1.5 Metres of Cover	3.60	0.40	A Permanent Reinstatement	01/03/2017		01/03/2017		
13	OPPOSITE LODGE COTTAGE	Verge	Up to 1.5 Metres of Cover	6.30	2.60	A Permanent Reinstatement	01/03/2017		01/03/2017		

**Works Ref:** M51531985912BZ**Version:** 6**Work Desc:** 2 joint holes in grass verge for supply alteration. Inconjunction with DY553M51531985912A.**Notice Type:** Registration of Reinstatement - Full**Start:** 20/03/2017 00:00:00**Work Status:** Works Stopped**Issued:** 05/04/2017 10:02:11**Work Type:** EToN 4: Standard**Est. End:** 24/03/2017**Completion:** 24/03/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop.	End
1	OPPOSITE HOLLYBECK NURSERIES	Verge	Up to 1.5 Metres of Cover	2.50	1.00	A Permanent Reinstatement	24/03/2017		24/03/2017		24/03/2017
2	OPPOSITE HOLLYBECK NURSERIES	Verge	Up to 1.5 Metres of Cover	3.00	1.00	A Permanent Reinstatement	24/03/2017		24/03/2017		