

Appendix 1

01235	Annesley Primary	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Ashfield
01435	Arnold View Primary	Replacement of the boiler and associated systems	Gedling
01904	Ash Lea School	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments. Mobile Classroom roof repair	Rushcliffe
02991	Beckingham Primary	Resolve Damp issues on internal walls	Bassetlaw
01061	Berry Hill Primary	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Mansfield
01308	Bramcote Hills Primary	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Broxtowe
01030	Brinsley Primary	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Broxtowe
01501	Bunny Primary	Replacement Boiler, associated systems and decarbonisation measures	Rushcliffe
01501	Carnarvon Primary	Replacement Hall ceiling & improved LED lighting	Rushcliffe
01270	Dalestorth Primary	Replacement Boiler, associated systems and decarbonisation measures	Ashfield
01019	Dunham CE Primary	Replacement Boiler, associated systems and decarbonisation measures	Bassetlaw
01020	East Markham Primary	Remedy to damp issues in classrooms	Bassetlaw
01022	Everton Primary	Replacement Boiler, associated systems and decarbonisation measures oiler/Decarbonisation	Bassetlaw
01098	Forest Town Primary	Drainage works	Mansfield
01043	Hallcroft Infants	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Bassetlaw
02910	Heatherley Primary	Repairs to external cladding	Ashfield
01133	High Oakham Primary	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Mansfield
01261	Jacksdale Primary	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	
01531	James Peacock Infant	Roof replacement	Rushcliffe
01159	John Blow Primary	Replacement of the boiler and associated systems	Newark
01103	John T Rice Infant	Improvements to access and layouts to enhance site safeguarding measures	Mansfield
01252	Kingsway Primary	Conversion of the kitchen from Gas to Electric	Ashfield
01522	Kinoulton Primary	Replace Radiator valves to allow more control over temperatures	Rushcliffe
01106	Leas Park Junior	Replacement heating cabinets and conversion of the kitchen from Gas to Electric	Mansfield
01469	Linby Cum Papplewick Primary	Replace ceilings and improved LED lighting	Gedling
01029	Mattersey Primary	Replacement Boiler, associated systems and decarbonisation measures	Bassetlaw
01030	Misson Primary	Replacement Boiler, associated systems and decarbonisation measures	Bassetlaw

01253	Morven Park Primary	Replace heating pipework and cabinets	Ashfield
01108	Netherfield Infant	Roof replacement	Mansfield
01192	North Clifton Primary	Replacement Boiler, associated systems and decarbonisation measures	Newark & Sherwood
01042	Northfield Primary	Replace heating cabinets and Conversion of the kitchen from Gas to Electric	Mansfield
01436	Pinewood Infant	Conversion of the kitchen from Gas to Electric	Gedling
01465	Priory Junior	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Gedling
01171	Queen Eleanor Primary	Replace heating pipework and cabinets	Newark & Sherwood
01528	Radcliffe-on-Trent Junior	Conversion of the kitchen from Gas to Electric	Rushcliffe
01064	St Annes CE Primary	Window replacement	Bassetlaw
01024	St Peters C of E Primary	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments. Including replacement boiler, associated systems and decarbonisation measures	Mansfield
01466	Stanhope Primary	Replacement Roof & Conversion of the kitchen from Gas to Electric	Gedling
01209	Sutton on Trent Primary	Replacement Boiler, associated systems and decarbonisation measures	Newark & Sherwood
01306	Trent Vale Infant	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Broxtowe
01336	Wadsworth Fields Primary	Conversion of the kitchen from Gas to Electric	Broxtowe
01052	Walkeringham Primary	Conversion of the kitchen from Gas to Electric	Bassetlaw
01521	Willowbrook Primary	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Rushcliffe
01477	Woodborough Woods Primary	Replacement of the boiler and associated systems	Gedling
01442	Woodthorpe Infant	Conversion of the kitchen from Gas to Electric	Gedling
01147	Wynndale Primary	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments, also included is the replacement of the boiler and associated systems. Also the conversion of the kitchen from Gas to Electric.	Mansfield