Appendix 1

UPRN	Site	Type of works	District
01333	Albany Junior	Roof replacement	Broxtowe
01235	Annesley Primary	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Ashfield
01061	Berry Hill Primary	Roof replacement	Mansfield
01340	Bispham Drive Junior	Replacement of boiler and associated systems	Broxtowe
01308	Bramcote Hills Primary	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Broxtowe
01268	Brierley Forest Primary	Drainage works	Ashfield
01158	Coddington C of E Primary	Structural repairs to building Floor slab and External retaining wall	Newark and Sherwood
01077	Crescent Primary	Window replacements	Mansfield
01898	Derrymount Special School	Roof replacement	Gedling
01094	Eastlands Junior	Replacement of heating cabinets and associated pipework	Mansfield
01312	Eskdale Junior	Drainage works	Broxtowe
01022	Everton Primary	Roof replacement	Bassetlaw
01260	Holly Hill Primary	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Ashfield
01537	Jesse Gray Primary	Replacement of boiler and associated systems and Window replacements	Rushcliffe
01103	John T Rice Infant	Replacement of boiler and associated systems	Mansfield
01162	King Edwin Primary	Flat Roof replacement	Newark and Sherwood
01522	Kinoulton Primary	Roof replacement, drainage works & electrical upgrades	Rushcliffe
01208	Lowes Wong Anglican Methodist Junior	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Newark and Sherwood
02714	Misterton Primary	Improvements to access and layouts to enhance site safeguarding measures	Bassetlaw
01253	Morven Park Primary	Works repair or replace boundary wall	Ashfield
01111	Newlands Junior	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Newark and Sherwood
02759	North Wheatley C of E Primary	Drainage works	Bassetlaw
01042	Northfield Primary	Windows and ceiling replacement, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Mansfield
01255	Orchard Primary	Replacement of ceiling, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Ashfield
01464	Phoenix Infant	Roof replacement and repairs to the external elevations	Gedling
01436	Pinewood Infant	Drainage works	Gedling
01062	Redlands Primary	Replacement of boiler and associated systems	Bassetlaw
01117	Sherwood Junior	Replacement of heating radiators and associated pipework	Mansfield
01069	St Lukes C of E Primary	Conversion of kitchen from gas to electric.	Bassetlaw
01448	St Wilfrids C of E Primary	Roof replacement	Gedling
01466	Stanhope Primary	Roof and ceiling replacement, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Gedling
01050	Sutton cum Lound C of E Primary	Replacement of boiler and associated systems	Bassetlaw
01306	Trent Vale Infant	Works to repair structural canopy	Broxtowe
01541	West Bridgford Junior	Roof replacement	Rushcliffe
01147	Wynndale Primary	Roof and ceiling replacement, including works to ceiling tiles, Lighting, fire alarm systems and incorporating works identified through the site risk assessments.	Mansfield