| 9/08/2017 | | Street History Report | | | | | | |
|-------------------------------------|--|-----------------------|---|-------------------------|------------------|--|--|--|
| | /04/2016 to 01/05/2017 recinct Road (1219167) | | | | | | | |
| Street: Precinct Road (12 | 19167) | | Locality: Kirkby in Ashfield, Nottinghamshire | Area: Ashfield | | | | |
| Condition Survey | | | | | | | | |
| Defect No: Description | | Log Date Locatio | n Defect Type Cla | ss. Organisation Status | Job No. | | | |
| Feat No.: 2,000.00 | Feature Id - Locn.: | | Feature Type: Street Section | Area: Ashfield | | | | |
| Batch: 20225177 - Inspection Batch | | | Route: Ashfield Kirkby Apr Enh CW/FW | | Date: 13/04/2017 | | | |
| No actionable de | fects found | | | | | | | |
| Batch: 20173467 - Inspection Batch | | | Route: Ashfield Kirkby Apr Enh CW/FW | | Date: 01/04/2016 | | | |
| No actionable de | fects found | | | | | | | |
| Feat No.: 8,000.00 | Feature Id - Locn.: | | Feature Type: Gully | Area: Ashfield | | | | |
| Batch: 10000236 - Ac | Hoc Inspection | | Route: Ad Hoc Inspection | | Date: 10/11/2016 | | | |
| No actionable de | fects found | | | | | | | |
| Feat No.: 8,001.00 | Feature Id - Locn.: | | Feature Type: Gully | Area: Ashfield | | | | |
| Batch: 10000236 - Ad Hoc Inspection | | | Route: Ad Hoc Inspection | | Date: 10/11/2016 | | | |
| No actionable de | fects found | | | | | | | |
| Feat No.: 8,002.00 | Feature Id - Locn.: | | Feature Type: Gully | Area: Ashfield | | | | |
| Batch: 10000236 - Ac | Hoc Inspection | | Route: Ad Hoc Inspection | | Date: 10/11/2016 | | | |
| No actionable de | fects found | | | | | | | |
| Feat No.: 8,003.00 | Feature Id - Locn.: | | Feature Type: Gully | Area: Ashfield | | | | |
| Batch: 10000236 - Ac | Hoc Inspection | | Route: Ad Hoc Inspection | | | | | |
| No actionable de | fects found | | | | | | | |
| Feat No.: 8,004.00 | Feature Id - Locn.: | | Feature Type: Gully | Area: Ashfield | | | | |
| Batch: 10000236 - Ac | Hoc Inspection | | Route: Ad Hoc Inspection | | Date: 10/11/2016 | | | |
| No actionable de | fects found | | | | | | | |
| Feat No.: 8,007.00 | Feature Id - Locn.: | | Feature Type: Gully | Area: Ashfield | | | | |
| Batch: 10000236 - Ac | Hoc Inspection | | Route: Ad Hoc Inspection | | Date: 10/11/2016 | | | |
| No actionable de | fects found | | | | | | | |
| Feat No.: 8,008.00 | Feature Id - Locn.: | | Feature Type: Gully | Area: Ashfield | | | | |
| Batch: 10000236 - Ac | Hoc Inspection | | Route: Ad Hoc Inspection | | Date: 10/11/2016 | | | |
| No actionable de | fects found | | | | | | | |
| Feat No.: 8,009.00 | Feature Id - Locn.: | | Feature Type: Gully | Area: Ashfield | | | | |
| Batch: 10000236 - Ad Hoc Inspection | | | Route: Ad Hoc Inspection | | | | | |
| No actionable de | fects found | | | | | | | |
| Feat No.: 8,010.00 | Feature Id - Locn.: | | Feature Type: Gully | Area: Ashfield | | | | |
| Batch: 10000236 - Ac | Hoc Inspection | | Route: Ad Hoc Inspection | | Date: 10/11/2016 | | | |
| No actionable de | fects found | | | | | | | |

| Effective: 01/04/2016 to 01/05/2 Street: Precinct Road (12191 | | Display Action Officer: No | | | | | | | |
|---|---|-------------------------------------|-------------------|---|--------------------|------------------------|--------------------|------------|--|
| Customer Services | | | | | | | | | |
| Enquiry No.: 58014 L Service: Traffic Management Desc.: Traffic entering box junctions | .ogged by: Dave Walker Subject: Traffic Issues | · · · | | on: 16/12/2016 11:12 ssification: Report or Observation | | | | | |
| Location: On box junctions | | | Contact: | | | | | | |
| Street Works Inspections | | | | | | | | | |
| Organisation: STW Water East (9103908) | | | | | | | | | |
| Works Ref: 1101/000060136038A | | | | | | | | | |
| Group No: 1 Site No: 1 | Street Authority: NCC | MANSFIELD | | Inspected: 11/ | /10/2016 15:35:41 | | | | |
| Category: Category C | Outcome: Passe | Outcome: Passed | | Sampled: Yes Sampled Sit | | | | | |
| Defect Notif. No: N/A | Defect No: N/A Tel: 07825 | Defect No: N/A Tel: 07825 716434 | | Site Informed: Yes Sign./Light./Guard. Inadequacy: No Site Location: MORRISONS SUPERMARKET | | | | | |
| Insp. Notes: Defect Notes: | | | | Position: Foo | otway | Site | Post Code: | | |
| Works Ref: 1101/000060140354 | | | | | | | | | |
| Group No: 2 Site No: 2 | Street Authority: NCC | MANSFIELD | | Inspected: 09/ | /11/2016 10:14:50 | | | | |
| Category: Category C Outcome: Passed | | | | Sampled: Ye | S | Sampled Site No: 2 | | | |
| Defect Notif. No: N/A | Defect No: N/A Tel: 07825 | Defect No: N/A Tel: 07825 716434 | | Site Informed: Yes Sign./Light./Guard. Inadequacy: No Site Location: PRECINT ROAD SUTTON IN ASHFIELD | | | | | |
| Insp. Notes: Defect Notes: | | | | Position: Ver | rge | Site | Post Code: | | |
| Group No: 1 Site No: 1 | Street Authority: NCC | MANSFIELD | | Inspected: 28/ | /09/2016 09:53:43 | | | | |
| Category: Category C | Outcome: Passe | Outcome: Passed | | Sampled: Yes | | | Sampled Site No: 1 | | |
| Defect Notif. No: N/A | Defect No: N/A | | | Site Informed: Ye | | Sign./Light./Guard. Ir | nadequacy: N | No | |
| | Tel: 07825 | 716434 | | | RECINT ROAD SUTT | | | | |
| Insp. Notes: Defect Notes: | | | | Position: Ca | rriageway | Site | Post Code: | | |
| Street Works Notices | | | | | | | | | |
| Organisation: BT (0030005) | | | | | | | | | |
| Works Ref: WP00300500233764100 | Vers | Version: 4 | | Work Desc: Locate and excavate 2 blockage in existing duct | | | | | |
| Notice Type: Registration of Reinstatement - | - Full St | art: 06/04/2017 00:00:00 | | | | | | | |
| Work Status: Works Stopped | | ed: 27/04/2017 10:21:20 | | | | | | | |
| Work Type: EToN 4: Minor | Est. E | nd: 10/04/2017 | Completion: 10/04 | 1/2017 | | | | | |
| Site No. Location | Position | Depth | Lengt | n Width Status | 6 | Site Date Interim | Perm. | Prop. End | |
| 1 IN FOOTWAY ON WEST CORNER OF JUNCTION ONTO POST OFFICE ROAD PRECINCT ROAD TO IN SOFT SIDE O | | Up to 1.5 Metres | of Cover 4.20 | | manent tatement | 10/04/2017 | 10/04/2017 | 07/04/2017 | |