

Effective: 29/10/2017 to 27/12/2017

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Station Road (33002541)

Street: Station Road (33002541)

Locality: Plumtree, Nottinghamshire

Area: Rushcliffe

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> Bradmore Lane to Railway Bridge			<b>Feature Type:</b> Street Section			<b>Area:</b> Rushcliffe	
<b>Batch:</b> 20258487 - Inspection Batch	No actionable defects found			<b>Route:</b> Rush Area 2 Dec Saf CW				<b>Date:</b> 08/12/2017
<b>Batch:</b> 20255471 - Inspection Batch	No actionable defects found			<b>Route:</b> Rush Area 2 Nov Saf CW				<b>Date:</b> 17/11/2017

**Customer Services**

<b>Enquiry No.:</b> 6074331	<b>Logged by:</b> External to Confirm	<b>on:</b> 27/12/2017 15:50	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Carriageway Pothole	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-64547449
<b>Desc.:</b> Road Pothole - A large pothole well beyond intervention level. Roughly 50 metres north of Perking Restaurant, Station Road, Plumtree. . Online report			
<b>Location:</b> See map coordinates and description details	<b>Contact:</b>		
<b>Enquiry No.:</b> 6074310	<b>Logged by:</b> External to Confirm	<b>on:</b> 27/12/2017 13:12	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Carriageway Pothole	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-64537948
<b>Desc.:</b> Road Pothole - Large Pothole in Road- As you drive Into Keyworth just before the Nursery. Having to drive in the Middle of the road to avoid hitting it & damaging my car . Online report			
<b>Location:</b> See map coordinates and description details	<b>Contact:</b>		

Effective: 29/10/2017 to 27/12/2017

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Station Road (33002541)

**Customer Services**

Enquiry No.: 6072061

Logged by: External to Confirm

on: 04/12/2017 15:47

Service: Traffic Management

Subject: Traffic Calming

Classification: Report or Observation

Enquiry Ref: FS-CASE-53734435

Desc.: Traffic calming requests - \*\*ESCALATED CASE\*\*

Please link this case with Hams refs 6053201 &amp; 6051657.

Customer email received on 31/05/2017:

To: enquiries@nottsc.gov.uk

cc: "Noreply.Enquiries@nottsc.gov.uk"; Noreply.Enquiries@nottsc.gov.uk

Fwd: Old Loughborough road/Landmere Lane calming measures

Kind regards,

Location: See map coordinates and description details

Contact:

Enquiry No.: 6068755

Logged by: External to Confirm

on: 31/10/2017 10:25

Service: Trees/Verges

Subject: Overhanging Vegetation/Trees

Classification: Report or Observation

Enquiry Ref: FS-CASE-61163559

Desc.: Overgrown hedges and vegetation - Email received:

Ref FS59216318 Re issue with overgrown pavement on station Rd Keyworth between railway bridge and Park Rd The clocks have now changed and walking from Plumtree to Keyworth in the late afternoon and evening is increasingly dangerous. Please could you update me on expected date of works.

Location: See map coordinates and description details

Contact:

Effective: 29/10/2017 to 27/12/2017

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Station Road (33002541)

**Street Works Inspections**

Organisation: Severn Trent Waste (9103902)

Works Ref: 0000/000011306851

Group No: 1      Site No: 1      Street Authority: NCC - RUSHCLIFFE  
Category: Category C      Outcome: Passed  
Defect Notif. No: N/A      Defect No: N/A  
Tel: 01159772381

Inspected: 20/11/2017 10:03:15  
Sampled: Yes      Sampled Site No: 1  
Site Informed: Yes      Sign./Light./Guard. Inadequacy: No  
Site Location: O/S NURSERY PLUMTREE STATION ROAD PLUMTREE  
NOTTINGHAMSHIRE  
Position: Carriageway      Site Post Code:

Insp. Notes:

Defect Notes:

**Street Works Notices**

Organisation: Severn Trent - GC Contract Team- CSO Monitors (9103521)

Works Ref: A6S/12182807A

Version: 3

Work Desc: We are installing Flood monitoring equipment in the dirty water system to help prevent drains backing up into properties and streets. This work takes 1-2 hours but cannot safely be done when water levels are high so 3 days booked to ensure this vital equ

Notice Type: Works Stop

Start: 24/11/2017 00:00:00

Work Status: Works Stopped

Issued: 24/11/2017 16:32:24

Work Type: EToN 4: Minor

Est. End: 28/11/2017

Completion: 24/11/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Opposite Plum Tree Garage	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	24/11/2017			29/11/2017