

Effective: 29/10/2017 to 27/12/2017  
Street: Main Road (33002492)

Display Action Officer: No

Street: Main Road (33002492)

Locality: Plumtree, Nottinghamshire

Area: Rushcliffe

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> A606 to Bradmore Lane			<b>Feature Type:</b> Street Section			<b>Area:</b> Rushcliffe	
<b>Batch:</b> 20258536	- Inspection Batch No actionable defects found			<b>Route:</b> Rush Area 2 Dec Saf CW				<b>Date:</b> 08/12/2017
<b>Batch:</b> 20255470	- Inspection Batch No actionable defects found			<b>Route:</b> Rush Area 2 Nov Saf CW				<b>Date:</b> 17/11/2017
<b>Batch:</b> 20255251	- Inspection Batch			<b>Route:</b> Adhoc Inspection				<b>Date:</b> 16/11/2017
3559912	HWIA - Carriageway defects are marked up for repairs . Online report (Enquiry 6068378)	16/11/2017	L / H / S lane from L / C 7 to 9 in the direction towards Keyworth opposite Sycamore Farm and no further than the Interactive speed sign .	CW Repairs-Bituminous	Internal		Committed	2662679

### Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> A606 to Bradmore Lane			<b>Feature Type:</b> Street Section		<b>Area:</b> Rushcliffe	
2662679	HWIA - Carriageway defects are marked up for repairs . Online report (Enquiry 6068378) (CW Repairs-Bituminous)	L / H / S lane from L / C 7 to 9 in the direction towards Keyworth opposite Sycamore Farm and no further than the Interactive speed sign .	Category 2 (High)	Job Completed	16/11/2017	17/11/2017	Act. RUS-AS/5600850