

Effective: 07/03/2017 to 07/02/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Victoria Road (15004312)

Street: Victoria Road (15004312)

Locality: Netherfield, Nottinghamshire

Area: Gedling

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:		Feature Type:	Street Section		Area:	Gedling
Batch:	20265730 - Inspection Batch			Route:	Adhoc Inspection			Date: 31/01/2018
3566247	repaired on site	31/01/2018	o/s 168	CW Repairs-Bituminous	Internal		Uncommitt	2669194
Batch:	20265263 - Inspection Batch			Route:	Adhoc Inspection			Date: 29/01/2018
3565921	repaired on site	29/01/2018	nr jcn Deabill St next to speed hump	CW Repairs-Bituminous	Internal		Uncommitt	2668862
Batch:	20264599 - Inspection Batch			Route:	Gedling Area 2 Jan Saf CW/FW			Date: 25/01/2018
3565450		25/01/2018	on jcn Kingsley Dr , o/s Hawk Cycles	CW Repairs-Bituminous	Internal		Committed	2668386
3565447		25/01/2018	nr jcn Deabill St speed hump, o/s 168 , 174	CW Repairs-Bituminous	Internal		Committed	2668383
3565448	reset 1no stainless bollard ,reset block paving around bollard	25/01/2018	o/s Motabits	Bollard Repairs	Internal		Committed	2668384
3565451	repaired on site	25/01/2018	o/s centre nr zebra crossing	CW Repairs-Bituminous	Internal		Uncommitt	2668382
3565449	reset 1no loose slab side m/hole	25/01/2018	o/s 74/76	FW Repairs-Concrete	Internal		Committed	2668385
Batch:	20258995 - Inspection Batch			Route:	Gedling Area 2 Dec Saf CW/FW			Date: 12/12/2017
3561742	reset 4no loose channel blocks	12/12/2017	o/s European Mini Market & Mr Food	Kerbing/Edging	Internal		Committed	2664604
3561741		12/12/2017	o/s St Georges Centre , jcn Manvers St in front of pram crossing, o/s 174 , jcn Grt Northern Way	CW Repairs-Bituminous	Internal		Uncommitt	2664603
3561743	replaced loose black block paver with tarmac while on site	12/12/2017	o/s Bargain Booze	FW Repairs-Concrete	Internal		Uncommitt	2664601
3561740		12/12/2017	o/s Bargain Booze replace loose buff slab with tarmac	FW Repairs-Concrete	Internal		Committed	2664602
Batch:	20255779 - Inspection Batch			Route:	Gedling Area 2 Nov Saf CW/FW			Date: 21/11/2017
3560287		21/11/2017	jcn Grt Northern Way, o/s 174 , jcn Kingsley Dr , 128 , o/s Hawk Cycles	CW Repairs-Bituminous	Internal		Committed	2663069
3560286	replace 1no loose slab with tarmac	21/11/2017	o/s Bargain Booze	FW Repairs-Bituminous	Internal		Committed	2663070
Batch:	20253734 - Ad Hoc Inspection Batch			Route:	Adhoc Inspection			Date: 08/11/2017
3559072	Please resett 3no BUFF slabs. NEED TO SPEAK WITH NETWORK RAIL.	08/11/2017	Adjacent to LEVEL X ING.	FW Repairs-Concrete	Internal		Committed	2661817
Batch:	20250365 - Inspection Batch			Route:	Gedling Area 2 Oct Saf CW/FW			Date: 17/10/2017
3557588		17/10/2017	entrance to Co op reset uneven black block paving side tree pit & opp A B C Flooring reset 2no areas of uneven black block paving side tree pit marked in yellow crayon	FW Repairs-Concrete	Internal		Committed	2660227
3557587	replace 2no broken/loose buff tactile slabs will need cutting	17/10/2017	jcn Manvers St	FW Repairs-Concrete	Internal		Committed	2660226

Effective: 07/03/2017 to 07/02/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Victoria Road (15004312)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.:			Feature Type: Street Section			Area: Gedling	
Batch: 20250365 - Inspection Batch				Route: Gedling Area 2 Oct Saf CW/FW				Date: 17/10/2017
3557589	phoned through to inspector assistants	17/10/2017	o/s bargain booze replace loose slab with tarmac, missing black block paver in m/hole cover with tarmac , opp Post Office side tree pit replace loose paver with tarmac	FW Repairs-Bituminous	Internal		Committed	2660225
Batch: 20247891 - Inspection Batch				Route: Review Outcome-Pete Moncaster				Date: 29/09/2017
No actionable defects found								
Batch: 20246573 - Inspection Batch				Route: Gedling Area 2 May Enh CW/FW				Date: 20/09/2017
3555587		20/09/2017	o/s TSB reset stanless bollard and reset block paving	Bollard Repairs	Internal		Committed	2658104
3555586	phoned through to inspectors assistants	20/09/2017	o/s Robinsons Butcher channel	CW Repairs-Bituminous	Internal		Committed	2658103
3555591		20/09/2017	nr jcn Kingsley Dr 2no, o/s Jackie Bells ,jcn Bourne Mews , opp l/col 45 channel	CW Repairs-Bituminous	Internal		Committed	2658102
3555590	phoned through to inspectors assistants	20/09/2017	o/s Excel Laundry replace loose slab side s/tap with tarmac , & o/s Co op entrance replace loose black block paver nr tree with tarmac	FW Repairs-Bituminous	Internal		Committed	2658107
3555589	reset 5no loose channel blocks	20/09/2017	o/s Mr Food & Robinsons Butchers	Kerbing/Edging	Internal		Committed	2658106
3555588	phoned through to inspectors assistants	20/09/2017	o/s TSB make safe damaged stainless bollard	Other	Internal		Committed	2658105
Batch: 20242738 - Inspection Batch				Route: Gedling Area 2 Aug Saf CW/FW				Date: 23/08/2017
No actionable defects found								

Effective: 07/03/2017 to 07/02/2018

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Victoria Road (15004312)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.:			Feature Type: Street Section			Area: Gedling	
Batch: 20242709 - Ad Hoc Inspection Batch				Route: Adhoc Inspection				Date: 23/08/2017
3553947	Re install 2no stainless steel bollards - Stored in Gamston -	23/08/2017	See map coordinates and description details	Bollard Repairs	Internal		Committed	2656396
	<p>Safety Fence Damage - Safety fence damage - Customer has called in from Its The inn pub on the corner of Victoria Road and Meadow Road. On Saturday night a car came round the corner too fast and has knocked over 2 bollards and a steal bin, near a pelican crossing next to a mini roundabout.</p> <p>Someone had moved these but has since fallen over and again and customer is worried it may fall into the road. Customer has moved this again to make it safer, but it will need looking at properly.</p> <p>Unsure if highways are already aware of this, as the police were called out to the incident and i am aware they may have called us as well, but as it was a Saturday they may not have done. . Submitted by Advisor: David Taylor1 (Enquiry 6061950)</p>							
Batch: 20237803 - Inspection Batch				Route: Gedling Area 2 Jul Saf CW/FW				Date: 12/07/2017
	No actionable defects found							
Batch: 20236777 - Inspection Batch				Route: Gedling Area 2 Jun Saf CW/FW				Date: 05/07/2017
3551485	reset silver steel bollard and reset 5 bricks , cone placed at site 4/7/17 at time of inspection (stats required, please also note rail crossing close by)	05/07/2017	outside TSB bank	Bollard Repairs	Internal		Committed	2653670
3551484	remove x1 400x400 slab at each location and replace viafix.	05/07/2017	outside 68 victoria road and outside ivory nails	FW Repairs-Bituminous	Internal		Committed	2653669
Batch: 20227479 - Inspection Batch				Route: Adhoc Inspection				Date: 28/04/2017
3547440	reset 3no loose black block pavers or replace with tarmac 3pavers together	28/04/2017	o/s Taste of Kashmir	FW Repairs-Bituminous	Internal		Committed	2649329
Batch: 20227010 - Inspection Batch				Route: Gedling Area 2 Apr Saf CW/FW				Date: 26/04/2017
3547240	phoned through to inspectors assistants	26/04/2017	opp l/col 53 15m down side speed hump , jcn Manvers St side gully , o/s 70	CW Repairs-Bituminous	Internal		Committed	2649115
3547239		26/04/2017	o/s T S B reset to level uneven block pavers side bollard 6no , o/s Blush reset to level uneven block paving side bollard 4no pavers , o/s Back in the day reset 1no loose black block paver in m/hole cover	FW Repairs-Concrete	Internal		Committed	2649119

Effective: 07/03/2017 to 07/02/2018

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Victoria Road (15004312)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.:			Feature Type: Street Section			Area: Gedling	
Batch: 20227010 - Inspection Batch				Route: Gedling Area 2 Apr Saf CW/FW				Date: 26/04/2017
3547236		26/04/2017	fcn Grt Northern Way, opp 174 ,nr jcn Kingsley Dr , opp l/col 45 channel , jcn Dennis St , opp 84	CW Repairs-Bituminous	Internal		Committed	2649116
3547238	reset 1no loose buff slab	26/04/2017	o/s Number 1 cafe / 37a	FW Repairs-Concrete	Internal		Committed	2649118
3547237	replace broken gully lid & frame, gully 400 x 450mm	26/04/2017	5m up from Deabill St	CW Ironwork	Internal		Committed	2649117
Batch: 20222819 - Inspection Batch				Route: Adhoc Inspection				Date: 28/03/2017
3545481	repaired on site	28/03/2017	opp Jackie Bells field	CW Repairs-Bituminous	Internal		Uncommitt	2647270
Batch: 20221349 - Inspection Batch				Route: Adhoc Inspection				Date: 20/03/2017
3544857		20/03/2017	o/s 168 , 2 Nether Pastures	CW Repairs-Bituminous	Internal		Uncommitt	2646628

Customer Services

Enquiry No.: 6079070	Logged by: External to Confirm	on: 29/01/2018 18:57	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-66871079
Desc.: Road Damage - Numerous issues with the road surface ie potholes and uneven broken road surface, around and near to all the speed humps along Victoria Road which effects drivers when trying to negotiate them....causing problems with car wheels/tyres and suspensions . Online report			
Location: Victoria Road Netherfield Nottingham		Contact:	
Enquiry No.: 6078580	Logged by: External to Confirm	on: 26/01/2018 13:48	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-66710436
Desc.: Road Damage - In this section there is a dip in the road, if there are cars coming the other way you have to stop to let them past as you do not want to go down the dip. There is a dip of approx 6 inches, and 8-10 inches wide. . Submitted by Advisor: Chelsea1 Tyler			
Location: Along Victoria Road as you go over the zebra crossing and the park is on your right and the nursery is on your left.		Contact:	
Plot Number: 2,000.00	Feature Id - Location:	Feature Type: Street Section	
Job Number: 2668862	Defect Number: 3565921		
Enquiry No.: 6075286	Logged by: External to Confirm	on: 08/01/2018 10:55	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-65211298
Desc.: Road Damage - disgraceful state - potholes, debris and uneven surface -dangerous - on junction near Medical centre . Online report			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6072303	Logged by: External to Confirm	on: 06/12/2017 12:09	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-63408340
Desc.: Road Damage - The caller states that the surface along the whole length of Victoria road, Netherfield is in a bad state of repair, especially near the junction of Bourne Mews. . Submitted by Advisor: Andrew Peutrill			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6066265	Logged by: External to Confirm	on: 04/10/2017 16:11	
Service: Carriageway/Footway	Subject: Spillage/Debris on Carriageway	Classification: Report or Observation	Enquiry Ref: FS-CASE-59697269
Desc.: Spillage/debris in road - There is an oil spillage on Victoria Road and turning into Wright Street which reported as an urgent on Thursday 28th September and customer says is still there. He fell off his bike on Wednesday 27th when he slipped on the oil. . Submitted by Advisor: Claire Shockledge			
Location: See map coordinates and description details		Contact:	

Effective: 07/03/2017 to 07/02/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Victoria Road (15004312)

Customer Services

Enquiry No.: 6061950	Logged by: External to Confirm	on: 21/08/2017 12:06	
Service: Carriageway/Footway	Subject: Safety Fence Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-57581552
Desc.: Safety fence damage - Customer has called in from Its The inn pub on the corner of Victoria Road and Meadow Road. On Saturday night a car came round the corner too fast and has knocked over 2 bollards and a steal bin, near a pelican crossing next to a mini roundabout.			
Someone had moved these but has since fallen over and again and customer is worried it may fall into the road. Customer has moved this again to make it safer, but it will need looking at properly.			
Unsure if highways are already aware of this, as the police were called out to the incident and i am aware they may have called us as well, but as it was a Saturday they may not have done. . Submitted by Advisor: David Taylor1			
Location: See map coordinates and description details		Contact:	
Plot Number: 2,000.00	Feature Id - Location:	Feature Type: Street Section	
Job Number: 2656396	Defect Number: 3553947		
Enquiry No.: 6060411	Logged by: External to Confirm	on: 04/08/2017 10:33	
Service: Trees/Verges	Subject: Overhanging Vegetation/Trees	Classification: Report or Observation	Enquiry Ref: FS-CASE-56893957
Desc.: Overhanging trees - The trees outside number 3 Victoria Road which is a business called Love Hair are overhanging and hiding the business sign. Can these be cut back please. . Submitted by Advisor: Cheryl Evans			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6060402	Logged by: External to Confirm	on: 04/08/2017 09:44	
Service: Licenses/Permits	Subject: Street Trading Enforcement	Classification: Service Request	Enquiry Ref: FS-CASE-56889121
Desc.: Street/roadside trading - This is a time sensitive issue as the customer is needing a response as soon as possible as the customer is wanting to know what action needs to be taken place in order for them to set up a gazebo directly opposite the co -op on Victora street from the 7th Aug to the 11th Aug. The name of the provider is Utilita and they are going to be speaking to the members of the public regarding the gas and electric meters and are going to be handing out free smart meters. The customer has already spoken with Gedling Council and they have said that it does not require a licence from them and to report it through to our highways team. . Submitted by Advisor: Kerrie Scott -			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6060305	Logged by: External to Confirm	on: 03/08/2017 11:04	
Service: Road Works	Subject: Information Request	Classification: Service Request	Enquiry Ref: FS-CASE-56843116
Desc.: PROPERTY - NEVS OFF LICENCE			
Personal Information is calling to request permission for a wheelchair access to be put in place Personal Information It currently has some stairs leading to the entrance and would like that being altered to a ramp for easier access. This would require works being performed on the pavement to accommodate this, and he would just like permissions to be able to do so. If you could please get back to him on 01169611246 . Submitted by Advisor: Ryan Farnsworth -			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6047491	Logged by: External to Confirm	on: 20/03/2017 15:26	
Service: Carriageway/Footway	Subject: Traffic Signal Fault	Classification: Report or Observation	Enquiry Ref: FS-CASE-50151226
Desc.: Traffic light fault - Message sent in on twitter to the digital team regarding the lights at Victoria retail park in Netherfield. No description as to what the issues are, just the fact that the phasing causes issues. Please could you respond directly to the digital team for them to contact the customer. . Submitted by Advisor: neil hursthouse			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6047446	Logged by: External to Confirm	on: 20/03/2017 13:16	
Service: Traffic Management	Subject: Parking General	Classification: Report or Observation	Enquiry Ref: FS-CASE-50141551
Desc.: Parking issues - the traffic light sequence is causing havoc at the weekends . Online report			
Location: See map coordinates and description details		Contact:	

Effective: 07/03/2017 to 07/02/2018

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Victoria Road (15004312)

Customer Services

Enquiry No.: 6045793 **Logged by:** External to Confirm **on:** 07/03/2017 14:24
Service: Carriageway/Footway **Subject:** Footway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-13763457
Desc.: Pavement Damage - on the right had side of the coming on to victoria road off of Nether Pasture there is a paved cover on the pavement, this has collapsed and is now exposed . . Submitted by Advisor: Daniel Betts
Location: See map coordinates and description details **Contact:**

Enquiry No.: 3204921 **Logged by:** Howard Widdowson **on:** 20/09/2017 12:26
Service: Carriageway/Footway **Subject:** Footway Damage **Classification:** Report or Observation
Desc.: 3no loose slabs
Location: nr jcn Station Rd **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** **Feature Type:** Street Section

Enquiry No.: 66826 **Logged by:** Kendra Hourd **on:** 20/10/2017 11:07
Service: Traffic Management **Subject:** Parking General **Classification:** Report or Observation
Desc.: TRO Consultation Oct 2017: Kingsley Dr NW side SYL and 2hr limited waiting bay on Victoria Rd btwn Dennis and Dunstan jcn
Location: Kingsley Dr NW side SYL and 2hr limited waiting bay on Victoria Rd btwn Dennis and Dunstan jcn **Contact:**

Enquiry No.: 64355 **Logged by:** Zanda Pepper **on:** 30/06/2017 11:37
Service: Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation
Desc.: Incident on 30/03/17: Claimant was crossing the road with her 3-wheel walker when the front wheel hit a pothole. (raised on receipt of claim notification)
Location: outside the church **Contact:**

Enquiry No.: 62989 **Logged by:** Paula Johnson **on:** 09/05/2017 15:14
Service: Trees/Verges **Subject:** Grass Cutting **Classification:** Report or Observation
Desc.: From: [REDACTED] **Personal Information**
Sent: 09 May 2017 14:15
To: Paula Johnson <paula.johnson@viaem.co.uk>
Subject: grass cutting

Hi Paula

[REDACTED] **Personal Information**

I have had a complaint about the grassed area opposite Lidl on Victoria Road, Netherfield (near the 'Welcome to Ntherfield' sign).

Gedling do not cut it as it is not theirs and they do not know if its Notts CC or privately owned are you able to shed any light on this. [REDACTED] **Personal Information**[REDACTED] **Personal Information****Location:** Opposite Lidl**Contact:**

Effective: 07/03/2017 to 07/02/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Victoria Road (15004312)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:	Feature Type: Street Section		Area: Gedling		
2638978	Please repair / replace as required damaged Ped Fencing - Ornate Type. This is a possible recharge from an RTC. (Fencing Repairs)	Outside 'BILLY SMOKES' adj to Zebra X ing.	Category 2 (Low)	Job Completed	11/11/2016	28/03/2017	Act. GED/3403404
2643689	replace existing broken tactile slabs on pram crossing, on a full depth concrete bed, 16no required.(FW Repairs-Bituminous)	jcn Manvers St	Category 2 (Low)	Job Completed	08/02/2017	12/04/2017	Act. GED/3403625
2646628	CW Repairs-Bituminous	o/s 168 , 2 Nether Pastures	Filled when found (Cat 1)	Job Completed	20/03/2017	20/03/2017	Act.
2647270	repaired on site (CW Repairs-Bituminous)	opp Jackie Bells field	Filled when found (Cat 1)	Job Completed	28/03/2017	28/03/2017	Act.
2649115	phoned through to inspectors assistants (CW Repairs-Bituminous)	opp l/col 53 15m down side speed hump , jcn Manvers St side gully , o/s 70	Category 1	Job Completed	26/04/2017	26/04/2017	Act. GED-AS/5302681
2649116	CW Repairs-Bituminous	jcn Grt Northern Way, opp 174 ,nr jcn Kingsley Dr , opp l/col 45 channel , jcn Dennis St , opp 84	Category 2 (High)	Job Completed	26/04/2017	02/05/2017	Act. GED-AS/5302682
2649117	replace broken gully lid & frame, gully 400 x 450mm (CW Ironwork)	5m up from Deabill St	Category 1	Job Completed	26/04/2017	02/05/2017	Act. GED/3403814
2649118	reset 1no loose buff slab (FW Repairs-Concrete)	o/s Number 1 cafe / 37a	Category 1	Job Completed	26/04/2017	28/04/2017	Act. GED/3403815
2649119	FW Repairs-Concrete	o/s T S B reset to level uneven block pavers side bollard 6no , o/s Blush reset to level uneven block paving side bollard 4no pavers , o/s Back in the day reset 1no loose black block paver in m/hole cover	Category 2 (High)	Job Completed	26/04/2017	02/05/2017	Act. GED/3403816
2649329	reset 3no loose black block pavers or replace with tarmac 3pavers together (FW Repairs-Bituminous)	o/s Taste of Kashmir	Category 2 (High)	Job Completed	28/04/2017	03/05/2017	Act. GED-AS/5302706
2653669	remove x1 400x400 slab at each location and replace viafix. (FW Repairs-Bituminous)	outside 68 victoria road and outside ivory nails	Category 2 (High)	Job Completed	05/07/2017	05/07/2017	Act. GED-AS/5302991
2653670	reset silver steel bollard and reset 5 bricks , cone placed at site 4/7/17 at time of inspection (stats required, please also note rail crossing close by) (Bollard Repairs)	outside TSB bank	Category 2 (High)	Job Completed	05/07/2017	10/07/2017	Act. GED/3404032

Effective: 07/03/2017 to 07/02/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Victoria Road (15004312)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:		Feature Type:	Street Section	Area:	Gedling
2656396	Re install 2no stainless steel bollards - Stored in Gamston -	See map coordinates and description details	Category 2 (High)	Job Completed	23/08/2017	01/09/2017	Act. GED/3404114
	<p>Safety Fence Damage - Safety fence damage - Customer has called in from lts The inn pub on the corner of Victoria Road and Meadow Road. On Saturday night a car came round the corner too fast and has knocked over 2 bollards and a steal bin, near a pelican crossing next to a mini roundabout.</p> <p>Someone had moved these but has since fallen over and again and customer is worried it may fall into the road. Customer has moved this again to make it safer, but it will need looking at properly.</p> <p>Unsure if highways are already aware of this, as the police were called out to the incident and i am aware they may have called us as well, but as it was a Saturday they may not have done. . Submitted by Advisor: David Taylor1 (Enquiry 6061950) (Bollard Repairs)</p>						
2658102	CW Repairs-Bituminous	nr jcn Kingsley Dr 2no, o/s Jackie Bells ,jcn Bourne Mews , opp l/col 45 channel	Category 2 (Low)	Job Completed	20/09/2017	16/10/2017	Act. GED-AS/5303201
2658103	phoned through to inspectors assistants (CW Repairs-Bituminous)	o/s Robinsons Butcher channel	Category 1	Job Completed	20/09/2017	20/09/2017	Act. GED-AS/5303202
2658104	Bollard Repairs	o/s TSB reset stanless bollard and reset block paving	Category 2 (High)	Job Completed	20/09/2017	22/09/2017	Act. GED/3404201
2658105	phoned through to inspectors assistants (Other)	o/s TSB make safe damaged stainless bollard	Category 1	Job Completed	20/09/2017	20/09/2017	Act. GED-AS/5303203
2658106	reset 5no loose channel blocks (Kerbing/Edging)	o/s Mr Food & Robinsons Butchers	Category 2 (High)	Job Completed	20/09/2017	27/09/2017	Act. GED/3404212
2658107	phoned through to inspectors assistants (FW Repairs-Bituminous)	o/s Excel Laundry replace loose slab side s/tap with tarmac , & o/s Co op entrance replace loose black block paver nr tree with tarmac	Category 1	Job Completed	20/09/2017	20/09/2017	Act. GED-AS/5303204

Effective: 07/03/2017 to 07/02/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Victoria Road (15004312)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:		Feature Type: Street Section		Area: Gedling	
2660225	phoned through to inspector assistants (FW Repairs-Bituminous)	o/s bargain booze replace loose slab with tarmac, missing black block paver in m/hole cover with tarmac , opp Post Office side tree pit replace loose paver with tarmac	Category 1	Job Completed	17/10/2017	23/10/2017	Act. GED-AS/5303308
2660226	replace 2no broken/loose buff tactile slabs will need cutting (FW Repairs-Concrete)	jcn Manvers St	Category 2 (High)	Job Completed	17/10/2017	23/10/2017	Act. GED/3404314
2660227	FW Repairs-Concrete	entrance to Co op reset uneven black block paving side tree pit & opp A B C Flooring reset 2no areas of uneven black block paving side tree pit marked in yellow crayon	Category 2 (High)	Job Completed	17/10/2017	23/10/2017	Act. GED/3404315
2661817	Please resett 3no BUFF slabs. NEED TO SPEAK WITH NETWORK RAIL. (FW Repairs-Concrete)	Adjacent to LEVEL X ING.	Category 2 (Low)	Job Cancelled	08/11/2017	06/12/2017	Est. GED/3404351
2663069	CW Repairs-Bituminous	jcn Grt Nortern Way, o/s 174 , jcn Kingsley Dr , 128 , o/s Hawk Cycles	Category 2 (High)	Job Completed	21/11/2017	22/12/2017	Act. GED-AS/5303453
2663070	replace 1no loose slab with tarmac (FW Repairs-Bituminous)	o/s Bargain Booze	Category 2 (High)	Job Completed	21/11/2017	22/11/2017	Act. GED-AS/5303454
2664601	replaced loose black block paver with tarmac while on site (FW Repairs-Concrete)	o/s Bargain Booze	Filled when found (Cat 2H)	Job Completed	12/12/2017	12/12/2017	Act.
2664602	FW Repairs-Concrete	o/s Bargain Booze replace loose buff slab with tarmac	Category 2 (High)	Job Completed	12/12/2017	14/12/2017	Act. GED-AS/5303575
2664603	CW Repairs-Bituminous	o/s St Georges Centre , jcn Manvers St in front of pram crossing, o/s 174 , jcn Grt Northern Way	Filled when found (Cat 2H)	Job Completed	12/12/2017	12/12/2017	Act.
2664604	reset 4no loose channel blocks (Kerbing/Edging)	o/s European Mini Market & Mr Food	Category 2 (Low)	Works Order Committed	12/12/2017	09/01/2018	Est. GED/3404562
2668382	repaired on site (CW Repairs-Bituminous)	o/s centre nr zebra crossing	Filled when found (Cat 1)	Job Completed	25/01/2018	25/01/2018	Act.
2668383	CW Repairs-Bituminous	nr jcn Deabill St speed hump, o/s 168 , 174	Category 1	Job Completed	25/01/2018	30/01/2018	Act. GED-AS/5303750
2668384	reset 1no stainless bollard ,reset block paving around bollard (Bollard Repairs)	o/s Motabits	Category 2 (High)	Job Completed	25/01/2018	05/02/2018	Act. GED/3404772
2668385	reset 1no loose slab side m/hole (FW Repairs-Concrete)	o/s 74/76	Category 2 (High)	Job Completed	25/01/2018	30/01/2018	Act. GED/3404773
2668386	CW Repairs-Bitumino PLEASE USE HOT MATERIAL	on jcn Kingsley Dr , o/s Hawk Cycles	Category 2 (High)	Job Completed	25/01/2018	30/01/2018	Act. GED/3404774

Effective: 07/03/2017 to 07/02/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Victoria Road (15004312)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.:		Feature Type: Street Section		Area: Gedling	
2668862	repaired on site (CW Repairs-Bituminous)	nr jcn Deabill St next to speed hump	Filled when found (Cat 1)	Job Completed	29/01/2018	29/01/2018	Act.
2669194	repaired on site (CW Repairs-Bituminous)	o/s 168	Filled when found (Cat 1)	Job Completed	31/01/2018	31/01/2018	Act.

Street Works Notices**Organisation:** BT (0030006)**Works Ref:** CT002AP500253011900**Version:** 3**Work Desc:** Provide 1 new pole**Notice Type:** Registration of Reinstatement - Full**Start:** 03/12/2017 05:00:00**Work Status:** Works Stopped**Issued:** 04/12/2017 14:52:59**Work Type:** EToN 4: Immediate - Emergency**Est. End:** 03/12/2017**Completion:** 03/12/2017

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	O/S 64/66 VICTORIA RD, VICTORIA ROAD	Verge	Up to 1.5 Metres of Cover	0.50	0.50 A Permanent Reinstatement	03/12/2017		03/12/2017	03/12/2017

Organisation: Cadent - National Gas Transmission (0010100)**Works Ref:** S100000004072**Version:** -1**Work Desc:** Unknown**Notice Type:** Actual Start Date**Start:** 06/02/2013 00:00:00**Work Status:** Proposed Works**Issued:** 06/02/2013 11:42:29**Work Type:** Not Applicable**Est. End:** 01/01/4000**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Work in verge/footway only. Opp LIDL, Victoria Rd, Netherfield, Notts (Rear of 3 Nether Pasture).	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	07/02/2013		07/02/2013	08/02/2013

Organisation: Network Rail -LNE IMDM DERBY (7093670)**Works Ref:** CARLTON121117**Version:** 5**Work Desc:** Signals & Telecoms Annual Level crossing test, Site times Sunday 2330 12/11/17 - 0530 13/11/17**Notice Type:** Works Stop**Start:** 12/11/2017 00:00:00**Work Status:** Works Stopped**Issued:** 13/11/2017 06:42:52**Work Type:** EToN 4: Major**Est. End:** 13/11/2017**Completion:** 13/11/2017

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Carlton Level crossing	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	13/11/2017			13/11/2017

Organisation: Network Rail -LNE IMDM LINCOLN (7093667)**Works Ref:** WD2000/NOB1**Version:** 3**Work Desc:** To carry out crossing reliability works. Hours of works 22.00 - 10.00**Notice Type:** Works Stop**Start:** 15/04/2017 00:00:00**Work Status:** Works Stopped**Issued:** 25/05/2017 11:20:43**Work Type:** EToN 4: Minor**Est. End:** 16/04/2017**Completion:** 16/04/2017

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Level Crossing CCTV Controlled Named: CARLTON STATION	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	16/04/2017			16/04/2017

Effective: 07/03/2017 to 07/02/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Victoria Road (15004312)

Street Works Notices**Organisation:** Network Rail -LNE IMDM LINCOLN (7093667)**Works Ref:** WDJ1017**Notice Type:** Works Stop**Work Status:** Works Stopped**Work Type:** EToN 4: Minor**Version:** 3**Start:** 17/10/2017 00:00:00**Issued:** 19/10/2017 09:31:23**Est. End:** 19/10/2017**Work Desc:** On Track plant - Temporary Obstruction Boards in use to allow the access & egress of road rail vehicles at the level crossing. Hours of works between 01.15 - 05.00 daily**Completion:** 19/10/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Carlyton Level Crossing	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	19/10/2017			19/10/2017

Organisation: Network Rail STRUCTURES ASSESSMENT (7093645)**Works Ref:** 20170906CARLTONLC**Notice Type:** Cancellation**Work Status:** Abandoned Works**Work Type:** EToN 4: Minor**Version:** 2**Start:** 06/09/2017 00:00:00**Issued:** 05/09/2017 09:30:37**Est. End:** 06/09/2017**Work Desc:** Access to manhole in footway adjacent to level crossing. Hours of works 09.30 - 15.30.**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Carlton Level Crossing	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	06/09/2017			06/09/2017

Works Ref: 20171115CARLTONLC**Notice Type:** Works Stop**Work Status:** Works Stopped**Work Type:** EToN 4: Minor**Version:** 5**Start:** 13/12/2017 00:00:00**Issued:** 14/12/2017 08:37:48**Est. End:** 14/12/2017**Work Desc:** Access to manhole in footway adjacent to level crossing. 23.30 - 05.10.**Completion:** 14/12/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Carlton Level Crossing	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	15/11/2017			14/12/2017

Organisation: Nottinghamshire Highway Works (3055042)**Works Ref:** /CCH270317**Notice Type:** 3 Day Initial Notice**Work Status:** Proposed Works**Work Type:** EToN 4: Minor**Version:** 1**Start:** 27/03/2017 00:00:00**Issued:** 27/03/2017 12:41:37**Est. End:** 27/03/2017**Work Desc:** Urgent replacement of or make safe damaged barrier rail**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	o/s 34 (The Bank)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	27/03/2017			27/03/2017

Works Ref: 2668384**Notice Type:** Actual Start Date**Work Status:** In Progress**Work Type:** EToN 4: Minor**Version:** 2**Start:** 05/02/2018 00:00:00**Issued:** 06/02/2018 15:34:30**Est. End:** 07/02/2018**Work Desc:** bollard repairs**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	outside motabits	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	05/02/2018			07/02/2018

Effective: 07/03/2017 to 07/02/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Victoria Road (15004312)

Street Works Notices**Organisation:** NRSWA - Virgin Media (7160100)**Works Ref:** /NEMRBU/CX00026387**Version:** 4**Work Desc:** footway blockage**Notice Type:** Registration of Reinstatement - Full**Start:** 22/01/2018 00:00:00**Work Status:** Works Stopped**Issued:** 02/02/2018 13:49:01**Work Type:** EToN 4: Minor**Est. End:** 24/01/2018**Completion:** 24/01/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	outside unit 4-5 Victoria Road, NG4 2LA	Footway	Up to 1.5 Metres of Cover	0.60	0.40	A Permanent Reinstatement	24/01/2018		24/01/2018	23/01/2018

Works Ref: /NYNLRE/016959**Version:** 4**Work Desc:** UNBLOCK TEE**Notice Type:** Registration of Reinstatement - Full**Start:** 04/04/2017 00:00:00**Work Status:** Works Stopped**Issued:** 05/04/2017 09:23:03**Work Type:** EToN 4: Minor**Est. End:** 06/04/2017**Completion:** 04/04/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE FLAT 112	Footway	Up to 1.5 Metres of Cover	0.30	0.30	A Permanent Reinstatement	04/04/2017		04/04/2017	06/04/2017

Works Ref: /NYNLRE/016998**Version:** 4**Work Desc:** UNBLOCK DUCT**Notice Type:** Registration of Reinstatement - Full**Start:** 05/04/2017 00:00:00**Work Status:** Works Stopped**Issued:** 06/04/2017 08:45:41**Work Type:** EToN 4: Minor**Est. End:** 07/04/2017**Completion:** 05/04/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 41	Footway	Up to 1.5 Metres of Cover	0.30	0.30	A Permanent Reinstatement	05/04/2017		05/04/2017	06/04/2017

Organisation: Severn Trent - GC Contract Team- CSO Monitors (9103521)**Works Ref:** A6S/121821142A**Version:** 3**Work Desc:** We are initially inspecting the Combined Sewer Outfall (CSO) as these are a potential source of pollution from high level sewer flow discharging to stormwater outfalls. If suitable we will remove the chapter 8 and assess to then return under the same perm**Notice Type:** Works Stop**Start:** 25/10/2017 00:00:00**Work Status:** Works Stopped**Issued:** 30/10/2017 07:45:50**Work Type:** EToN 4: Minor**Est. End:** 27/10/2017**Completion:** 27/10/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	In carriageway opposite meadow road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	27/10/2017			27/10/2017

Organisation: Severn Trent Waste (9103902)**Works Ref:** 2103/000011772003**Version:** 4**Work Desc:** Rep/reset MH cover In H'way to 675mmsq Job in Carriageway (Bitumen Macadam (Tarmac))**Notice Type:** Registration of Reinstatement - Full**Start:** 09/01/2018 00:00:00**Work Status:** Works Stopped**Issued:** 09/01/2018 13:41:31**Work Type:** EToN 4: Minor**Est. End:** 09/01/2018**Completion:** 09/01/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	VICTORIA ROAD	Carriageway	Up to 1.5 Metres of Cover	1.20	1.20	A Permanent Reinstatement	09/01/2018		09/01/2018	09/01/2018

Effective: 07/03/2017 to 07/02/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Victoria Road (15004312)

Street Works Notices

Organisation: WPD - 5152 Nottingham City (7011552)

Works Ref: M51522024450

Version: 4

Work Desc: 1 joint hole in modular footway and 3m trenching in modular footway for supply alteration

Notice Type: Registration of Reinstatement - Full

Start: 22/11/2017 00:00:00

Work Status: Works Stopped

Issued: 30/11/2017 10:46:37

Work Type: EToN 4: Minor

Est. End: 23/11/2017

Completion: 23/11/2017

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 36 VICTORIA ROAD	Footway	Up to 1.5 Metres of Cover	4.20	0.60 A Permanent Reinstatement	23/11/2017		23/11/2017	23/11/2017