

Effective: 24/05/2016 to 24/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No


Street: Loughborough Road (33000188)

Street: Loughborough Road (33000188)

Locality: East Leake, Nottinghamshire

Area: Rushcliffe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:	From Castle Hill/Mill Lane junction to Melton Road	Feature Type:	Street Section		Area: Rushcliffe	
Batch:	20281911 - Inspection Batch			Route:	Rush Area 2 May Enh CW/FW			Date: 04/05/2018
	No actionable defects found							
Batch:	20279380 - Inspection Batch			Route:	Rush Area 2 Apr Saf CW			Date: 24/04/2018
	No actionable defects found							
Batch:	20277673 - Inspection Batch			Route:	Adhoc Inspection			Date: 16/04/2018
3574756	CW overlay - Numerous sizes of wearing course erosion marked up to be overlaid .Online report (Enquiry 6091044)	16/04/2018	Starting from Sheep wash bridge (S bend) either side of the Carriageway and up towards the A6006.	CW Repairs-Bituminous	Internal		Committed	2677818
Batch:	20274189 - Inspection Batch			Route:	Rush Area 2 Mar Saf CW			Date: 23/03/2018
	No actionable defects found							
Batch:	20272916 - Inspection Batch			Route:	Adhoc Inspection			Date: 16/03/2018
3571394	C/W defects repaired 14.00hrs - 16/03/18.	16/03/2018	Travelling from EAST LEAKE in the direction of the A6006 Melton Road - R/H/S just past MANOR FARM entrance, R/H/S inbetween the two bends before the Sheep Wash brook bridge, L/H/S 50m before the entrance to MICRO PROPAGATION, R/H/S 75m before entrance to GRUMPY JOE'S FLOORING SALES, R/H/S 30m before entrance to GOULDS FARM.	CW Repairs-Bituminous	Internal		Uncommitt	2674387
Batch:	20270452 - Inspection Batch			Route:	Rush Area 2 Feb Saf CW			Date: 28/02/2018
	No actionable defects found							
Batch:	20268572 - Inspection Batch			Route:	Adhoc Inspection			Date: 16/02/2018
3568215	Carriageway Pothole - Road Pothole - pot hole - #2	16/02/2018	6 potholes filled at the time of inspection. Various locations both side of the Cw from Grumpy Joes to East Leake entrance	CW Repairs-Bituminous	Internal		Uncommitt	2671172
	 .Online report (Enquiry 6081887)							

Effective: 24/05/2016 to 24/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Loughborough Road (33000188)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.: From Castle Hill/Mill Lane junction to Melton Road		Feature Type: Street Section		Area: Rushcliffe		
Batch: 20264946 - Inspection Batch		Route: Rush Area 2 Jan Saf CW				Date: 26/01/2018		
3565656	Defects made safe during inspection.	26/01/2018	Full length of road section either side of the Carriageway	CW Repairs-Bituminous	Internal		Uncommitt	2668593
Batch: 20258889 - Inspection Batch No actionable defects found		Route: Rush Area 2 Dec Saf CW				Date: 12/12/2017		
Batch: 20256590 - Inspection Batch		Route: Rush Area 2 Nov Saf CW				Date: 27/11/2017		
3560830	Defects made safe	24/11/2017	Approx 20 metters from A6006 & 30 meters from Grumpy Joes in the direction of East Laeke	CW Repairs-Bituminous	Internal		Uncommitt	2663632
Batch: 20251181 - Inspection Batch No actionable defects found		Route: Rush Area 2 Oct Saf CW				Date: 23/10/2017		
Batch: 20249540 - Inspection Batch No actionable defects found		Route: Review Outcome-Pete Moncaster				Date: 10/10/2017		
Batch: 20247142 - Inspection Batch No actionable defects found		Route: Rush Area 2 Sep Saf CW				Date: 22/09/2017		
Batch: 20243689 - Inspection Batch		Route: Rush Area 2 Aug Saf CW				Date: 31/08/2017		
3554233	Defect made safe .	31/08/2017	Just past Grumpy Joes in the direction of Castle Hill	CW Repairs-Bituminous	Internal		Uncommitt	2656690
Batch: 20238440 - Inspection Batch No actionable defects found		Route: Rush Area 2 Jul Saf CW				Date: 18/07/2017		
Batch: 20235765 - Inspection Batch No actionable defects found		Route: Rush Area 2 Jun Saf CW				Date: 26/06/2017		
Batch: 20235761 - Inspection Batch		Route: Adhoc Inspection				Date: 26/06/2017		
3551046	HWIA - Carriageway defects where it crosses Sheepbrook Wash on both sides of the carriageway - defects marked up	26/06/2017	On the Bridge span (sheepbrook Wash) S bend .	CW Repairs-Bituminous	Internal		Committed	2653174
Batch: 20229705 - Inspection Batch No actionable defects found		Route: Rush Area 2 May Enh CW/FW				Date: 11/05/2017		
Batch: 20226647 - Inspection Batch		Route: Rush Area 2 Apr Saf CW				Date: 25/04/2017		
3547098	Defect made safe during inspection.	25/04/2017	On the T junction with Mill Lane	CW Repairs-Bituminous	Internal		Uncommitt	2648967
Batch: 20222660 - Inspection Batch No actionable defects found		Route: Rush Area 2 Mar Saf CW				Date: 28/03/2017		
Batch: 20218034 - Inspection Batch No actionable defects found		Route: Rush Area 2 Feb Saf CW				Date: 22/02/2017		
Batch: 20214334 - Inspection Batch		Route: Adhoc Inspection				Date: 27/01/2017		
3541241	HWIA - wearing course erosion causing issues for Bike users ,please make safe defects marked up	27/01/2017	Section is on the Bridge decking over the stream just past Manor Farm Woodlands turning on the S bend in the direction of the A6006.	CW Repairs-Bituminous	Internal		Committed	2642915

Effective: 24/05/2016 to 24/05/2018

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Loughborough Road (33000188)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.: From Castle Hill/Mill Lane junction to Melton Road			Feature Type: Street Section		Area: Rushcliffe	
Batch: 20214255 - Inspection Batch No actionable defects found		Route: Rush Area 2 Jan Saf CW			Date: 26/01/2017			
Batch: 20213553 - Ad Hoc Inspection Batch		Route: Adhoc Inspection			Date: 24/01/2017			
3540962	Please repair c/w defects -	24/01/2017	On SHEEPWASH BRIDGE area and on r/h/s just before bridge, travelling from East Leake end.	CW Repairs-Bituminous	Internal		Committed	2642623
Batch: 20210082 - Inspection Batch No actionable defects found		Route: Rush Area 2 Dec Saf CW			Date: 22/12/2016			
Batch: 20209884 - Inspection Batch		Route: Adhoc Inspection			Date: 20/12/2016			
3539465	Defect made safe	20/12/2016	Approx 100 meters from Home Farm heading towards A6006	CW Repairs-Bituminous	Internal		Uncommitt	2641101
Batch: 20206581 - Inspection Batch No actionable defects found		Route: Rush Area 2 Nov Saf CW			Date: 29/11/2016			
Batch: 20202879 - Inspection Batch No actionable defects found		Route: Rush Area 2 Oct Saf CW			Date: 01/11/2016			
Batch: 20198648 - Inspection Batch No actionable defects found		Route: Rush Area 2 Sep Saf CW			Date: 30/09/2016			
Batch: 20193302 - Inspection Batch No actionable defects found		Route: Rush Area 2 Aug Saf CW			Date: 15/08/2016			
Batch: 20189586 - Inspection Batch No actionable defects found		Route: Rush Area 2 Jul Saf CW			Date: 20/07/2016			
Batch: 20188246 - Inspection Batch		Route: Rush Area 2 Jun Saf CW			Date: 07/07/2016			
3531735	Defect made safe at time of inspection	07/07/2016	Adjacent to L / C 14	CW Repairs-Bituminous	Internal		Uncommitt	2632824

Customer Services**Enquiry No.:** 6091044**Logged by:** External to Confirm**on:** 10/04/2018 18:26**Service:** Carriageway/Footway**Subject:** Carriageway Damage**Classification:** Report or Observation**Enquiry Ref:** FS-CASE-72553701

Desc.: Road Damage - The stretch of road, as described above, is in a very poor condition with numerous potholes. The condition of the road has been caused by many factors, including numerous road works, bad weather and general poor maintenance. I appreciate that funds are scarce and will be targeted to areas deemed to be of high importance, but resurfacing would be an ideal solution (particularly Main Street in Stanford on Soar) rather than patching up. . Online report

Location: The road from Main Street, Stanford on Soar, along Leake Lane and Loughborough Road, up to and including Castle Hill, East Leake. **Contact:**

Plot Number: 2,000.00**Feature Id - Location:** From Castle Hill/Mill Lane junction to Melton Road**Feature Type:** Street Section**Job Number:** 2677818**Defect Number:** 3574756**Enquiry No.:** 6086818**Logged by:** External to Confirm**on:** 17/03/2018 13:15**Service:** Carriageway/Footway**Subject:** Carriageway Damage**Classification:** Report or Observation**Enquiry Ref:** FS-CASE-70585868**Desc.:** Road Damage - Potholes and road detrition . Online report

Location: Loughborough Road in the direction of Rempstone Road (away from Castle Hill) just after the bridge over the brook. **Contact:**

Effective: 24/05/2016 to 24/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Loughborough Road (33000188)

Customer Services

Enquiry No.: 6086766 **Logged by:** External to Confirm **on:** 16/03/2018 19:03
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-70561197
Desc.: Road Pothole - Around the S bend at the bottom of the hill there are new potholes that are very large . Online report
Location: Around the S bend at the bottom of the hill there are new potholes that are very large **Contact:**

Enquiry No.: 6086764 **Logged by:** External to Confirm **on:** 16/03/2018 19:00
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-70561119
Desc.: Road Pothole - Some large potholes have opened up on the stretch of road on Loughborough Road between A6006 junction and cross roads with rempstone road . Online report
Location: Loughborough Road between A6006 junction and cross roads with rempstone road **Contact:**

Enquiry No.: 6082662 **Logged by:** External to Confirm **on:** 21/02/2018 09:21
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-68560032
Desc.: Road Damage - I #2 numerous pot holes on Loughborough Road between the top of Castle Hill road and the A6006.

#2

Please survey the whole stretch of Loughborough Road as there are countless large pot holes and the road is in a terrible condition.

#2

numerous pot holes on Loughborough Road between the top of Castle Hill road and the A6006. **Contact:**

#2

Please survey the whole stretch of Loughborough Road as there are countless large pot holes and the road is in a terrible condition.

#2

Enquiry No.: 6082274 **Logged by:** External to Confirm **on:** 19/02/2018 11:06
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-68372643
Desc.: Road Pothole - It is only a matter of time before someones car is damaged due to the size of these pot holes or an accident is caused by people driving on the wrong side of the road to avoid the holes.
Location: They are numerous in number on both sides of the road and getting larger by the day. . Online report
There are numerous large pot holes on Loughborough road between the top of Castle Hill road and the A6006 junction. **Contact:**
I was only able to click once on the map to identify the location but there are several large potholes over the roads entire length so I highly suggest an inspection of the entire stretch of the road on both sides.

Effective: 24/05/2016 to 24/05/2018

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Loughborough Road (33000188)

Customer Services

Enquiry No.: 6081887 Logged by: External to Confirm on: 15/02/2018 17:48
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation Enquiry Ref: FS-CASE-68184608
 Desc.: Road Pothole - pot hole - #2

. Online report

Location: left-hand side of road as you approach the village

Contact:

Plot Number: 2,000.00

Feature Id - Location: From Castle Hill/Mill Lane junction to Melton Road

Feature Type: Street Section

Job Number: 2671172

Defect Number: 3568215

Enquiry No.: 6081886 Logged by: External to Confirm on: 15/02/2018 17:42
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation Enquiry Ref: FS-CASE-68184511
 Desc.: Road Pothole - pothole . Online report
 Location: left-hand side of road as you approach the village

Contact:

Enquiry No.: 6081743 Logged by: External to Confirm on: 15/02/2018 10:36
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation Enquiry Ref: FS-CASE-68125444
 Desc.: Road Pothole - Lots of pot holes along this road. . Submitted by Advisor: #2
 Location: On Loughborough Road, along from the Sheepwash to the crossroads with rempstone road

Contact:

Enquiry No.: 6068289 Logged by: External to Confirm on: 25/10/2017 15:30
 Service: Traffic Management Subject: Traffic Calming Classification: Report or Observation Enquiry Ref: FS-CASE-60867413
 Desc.: Traffic calming requests - Customer Email:

#2 X roads Regpstone Road/Loughborough Road. #2
 s - a notorious accident black spot.

Please can I suggest that you consider putting Rumble Strips at this junction - the only alternative would be a round a bout which would also slow the traffic. . Submitted by Advisor: #2

Location: See map coordinates and description details

Contact:

Enquiry No.: 6066547 Logged by: External to Confirm on: 07/10/2017 06:46
 Service: Carriageway/Footway Subject: Line Marking/Stud Renewal Classification: Report or Observation Enquiry Ref: FS-CASE-59827686
 Desc.: Road marking renewal - #2 travelling from Loughborough towards Castle Hill when a car went straight across me that was travelling along Rempstone Road , the car should have given way at the junction but obviously missed any road signs.
 A second or two later and this would have been disastrous. I have heard of a few accidents and near misses at this junction. I think at the very least this junction requires re lining, a light up give Way sign and rumble strips up to the junction on either side of Rempstone Road. . Online report
 Location: See map coordinates and description details

Contact: East Leake and was very sorry to learn of your

Enquiry No.: 6063815 Logged by: External to Confirm on: 11/09/2017 15:35
 Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation Enquiry Ref: FS-CASE-58563049
 Desc.: Road Damage - Customer is reporting that where the road intersects with Riseholme Farm is very damaged, #2
 #2 #2 The road is very sunken and there are many potholes all over the road. #2

. Submitted by #2

Location: See map coordinates and description details

Contact:

Effective: 24/05/2016 to 24/05/2018

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Loughborough Road (33000188)

Customer Services

Enquiry No.: 6056206 **Logged by:** External to Confirm **on:** 21/06/2017 16:45
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-54795161
Desc.: Road Pothole - Strip of potholes across Loughborough road where it crosses Sheepbrook Wash. On both sides of the carriageway. . Submitted by Advisor: #2
Location: See map coordinates and description details **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** From Castle Hill/Mill Lane junction to Melton Road **Feature Type:** Street Section
Job Number: 2653174 **Defect Number:** 3551046

Enquiry No.: 6055504 **Logged by:** External to Confirm **on:** 14/06/2017 13:01
Service: Trees/Verges **Subject:** Grass Cutting **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-54395665
Desc.: Overgrown grass and verges - Email received:

The grass verges on castle hill/ Loughborough road are over grown causing obstruction when trying to come out onto Rempstone road and the cross road and the loughborough road. . Submitted by Advisor: #2

Location: See map coordinates and description details **Contact:**

Enquiry No.: 6055467 **Logged by:** External to Confirm **on:** 14/06/2017 10:25
Service: Trees/Verges **Subject:** Grass Cutting **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-54384896
Desc.: Overgrown grass and verges - We receive the following email at the customer service centre:

The grass verge at the junction of Loughborough Road leaving East Leake where it meets A6006 - the verge has not been sufficiently trimmed to enable drivers in small cars to see the oncoming traffic.

This is a very busy junction and I feel it has the potential to be 'an accident waiting to happen'.

I would be grateful if this matter could be dealt with URGENTLY! . Submitted by Advisor: #2

Location: See map coordinates and description details **Contact:**

Enquiry No.: 6046855 **Logged by:** External to Confirm **on:** 15/03/2017 08:02
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-14104119
Desc.: Road Pothole - Going out of East Leake on Loughborough Road there are 2 sharp bends heading towards the A6006 after Manor Farm on the nearside. On the second bend going round to the left there are numerous potholes across both sides of the road. I have noticed the surface has been getting worse over the last few months as it is breaking up. From there up to the A6006 the road has had recent road works in patches and the surface has been laid too high. . Online report
Location: See map coordinates and description details **Contact:**

Enquiry No.: 6039787 **Logged by:** External to Confirm **on:** 19/01/2017 19:43
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-12009549
Desc.: Road Damage - Some roadworks were carried out on the stretch of road between Castle Hill, East leake and the end of Loughborough Road (up to Rempstone Road) Q3 or Q4 2016. The repair to the road after the works is terrible. The tarmac laid is higher than the original road surface. This goes on for about 1.2 miles. Also about 80 yards from the Rempstone road Junction the road rises into a sort of dome around 6 inches high and 6 foot across (very strange).
It is terrible for suspension on cars and awful for cyclists commuting to Loughborough every day.
Please try and improve the road surface . Online report
Location: The pin has been placed near Loughborough Road, Loughborough, United Kingdom, **Contact:**
LE12 6NE

Enquiry No.: 6031221 **Logged by:** External to Confirm **on:** 20/10/2016 10:13
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-9054557
Desc.: Road Damage - large hump appeared in centre of road on Loughborough road at East Leake approx 250 meters before the junction with A6006 . , , , . Online report
Location: The pin has been placed near Loughborough Road, Loughborough, United Kingdom, **Contact:**
LE12 5EG

Effective: 24/05/2016 to 24/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Loughborough Road (33000188)

Customer Services

Enquiry No.: 6019852 **Logged by:** External to Confirm **on:** 28/06/2016 11:14
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** 103898692
Desc.: The pothole has recently been filled in but the filling has not lasted and it is beginning to appear again.
 ** Customer Requested Auto Updates **
Location: 83 meters from Castle Hill **Contact:**

Enquiry No.: 3203445 **Logged by:** Gary Cain **on:** 29/11/2016 10:53
Service: Carriageway/Footway **Subject:** St Furn/Non Illum Sign Damage **Classification:** Report or Observation
Desc.: Stop sign missing
Location: Cross Roads **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** From Castle Hill/Mill Lane junction to Melton Road **Feature Type:** Street Section

Enquiry No.: 55995 **Logged by:** Kendra Hourd **on:** 26/10/2016 16:39
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation
Desc.: Recent roadworks using a mole under the road have made it lumpy
Location: Somewhere between Rempstone Rd and Castle Hill **Contact:**

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:	From Castle Hill/Mill Lane junction to Melton Road	Feature Type:	Street Section	Area:	Rushcliffe
2632824	Defect made safe at time of inspection (CW Repairs-Bituminous)	Adjacent to L / C 14	Filled when found (Cat 2H)	Job Completed	07/07/2016	07/07/2016	Act.
2641101	Defect made safe (CW Repairs-Bituminous)	Approx 100 meters from Home Farm heading towards A6006	Filled when found (Cat 2H)	Job Completed	21/12/2016	20/12/2016	Act.
2642623	Please repair c/w defects - (CW Repairs-Bituminous)	On SHEEPWASH BRIDGE area and on r/h/s just before bridge, travelling from East Leake end.	Category 2 (High)	Job Completed	24/01/2017	03/02/2017	Act. RUS-AS/5600546
2642915	HWIA - wearing course erosion causing issues for Bike users ,please make safe defects marked up (CW Repairs-Bituminous)	Section is on the Bridge decking over the stream just past Manor Farm Woodlands turning on the S bend in the direction of the A6006.	Category 2 (High)	Job Completed	27/01/2017	03/02/2017	Act. RUS-AS/5600555
2648967	Defect made safe during inspection. (CW Repairs-Bituminous)	On the T junction with Mill Lane	Filled when found (Cat 2H)	Job Completed	25/04/2017	25/04/2017	Act.
2653174	HWIA - Carriageway defects where it crosses Sheepbrook Wash on both sides of the carriageway - defects marked up (CW Repairs-Bituminous)	On the Bridge span (sheepbrook Wash) S bend .	Category 2 (High)	Job Completed	26/06/2017	30/06/2017	Act. RUS-AS/5600696
2656690	Defect made safe . (CW Repairs-Bituminous)	Just past Grumpy Joes in the direction of Castle Hill	Filled when found (Cat 2H)	Job Completed	31/08/2017	31/08/2017	Act.
2663632	Defects made safe (CW Repairs-Bituminous)	Approx 20 metrs from A6006 & 30 meters from Grumpy Joes in the direction of East Laeke	Filled when found (Cat 2H)	Job Completed	27/11/2017	24/11/2017	Act.

Effective: 24/05/2016 to 24/05/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Loughborough Road (33000188)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.: From Castle Hill/Mill Lane junction to Melton Road		Feature Type: Street Section		Area: Rushcliffe	
2668593	Defects made safe during inspection. (CW Repairs-Bituminous)	Full length of road section either side of the Carriageway	Filled when found (Cat 1)	Job Completed	26/01/2018	26/01/2018	Act.
2671172	Carriageway Pothole - Road Pothole - #2	6 potholes filled at the time of inspection. Various locations both side of the Cw from Grumpy Joes to East Leake entrance	Filled when found (Cat 1)	Job Completed	16/02/2018	16/02/2018	Act.
	. Online report (Enquiry 6081887) (CW Repairs-Bituminous)						
2674387	C/W defects repaired 14.00hrs - 16/03/18. (CW Repairs-Bituminous)	Travelling from EAST LEAKE in the direction of the A6006 Melton Road - R/H/S just past MANOR FARM entrance, R/H/S inbetween the two bends before the Sheep Wash brook bridge, L/H/S 50m before the entrance to MICRO PROPAGATION, R/H/S 75m before entrance to GRUMPY JOE'S FLOORING SALES, R/H/S 30m before entrance to GOULDS FARM.	Filled when found (Cat 1)	Job Completed	16/03/2018	16/03/2018	Act.
2677818	CW overlay - Numerous sizes of wearing course erosion marked up to be overlayed .Online report (Enquiry 6091044) (CW Repairs-Bituminous) T/M REQUIRED DUE TO LOCATION -	Starting from Sheep wash bridge (S bend) either side of the Carriageway and up towards the A6006.	Category 2 (High)	Works Order Printed	16/04/2018	23/04/2018	Est. RUSH/3703367

Effective: 24/05/2016 to 24/05/2018		Feature No.: 2000.00 to 2000.00	
Display Action Officer: No		Street: Loughborough Road (33000188)	
