

Effective: 18/11/2016 to 18/11/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (1203184)

Street: Mansfield Road (1203184)

Locality: Annesley, Nottinghamshire

Area: Ashfield

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: A608 - Annesley			Feature Type: Street Section			Area: Ashfield	
Batch: 20311306 - Inspection Batch				Route: Ashfield Kirkby Nov Enh CW/FW				Date: 15/11/2018
3593791	Pothole x 5 outbound toward Motorway. Pothole x 1 inbound toward Kirkby. Offpeak Jerry can assist.	15/11/2018	Osier Road Roundabout	CW Repairs-Bituminous	Internal		Committed	2697172
Batch: 20310532 - Inspection Batch				Route: Adhoc Inspection				Date: 09/11/2018
3593194	Carriageway Pothole x 2 in channel, Jerry can help with TM.	09/11/2018	A608 Mansfield Road Roundabout before main M1 J27 Roundabout	CW Repairs-Bituminous	Internal		Committed	2696570
Batch: 20307412 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Oct Saf CW				Date: 18/10/2018
Batch: 20304051 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Sep Saf CW				Date: 26/09/2018
Batch: 20299880 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Aug Saf CW				Date: 30/08/2018
Batch: 20295255 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Jul Saf CW				Date: 30/07/2018
Batch: 20290734 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Jun Saf CW				Date: 27/06/2018
Batch: 20285113 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk May Saf CW				Date: 23/05/2018
Batch: 20282590 - Inspection Batch				Route: Adhoc Inspection				Date: 10/05/2018
3577893	Carriageway Pothole on joint	10/05/2018	Opposite lamp post 56	CW Repairs-Bituminous	Internal		Committed	2681017
Batch: 20282464 - Inspection Batch				Route: Adhoc Inspection				Date: 09/05/2018
3577798	C way pothole.	09/05/2018	At first gully through lights left side	CW Repairs-Bituminous	Internal		Committed	2680921
Batch: 20279673 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Apr Saf CW				Date: 24/04/2018
Batch: 20278980 - Inspection Batch				Route: Adhoc Inspection				Date: 20/04/2018
3575684	Pothole at gully	20/04/2018	On roundabout to Osier opp l post 13	CW Repairs-Bituminous	Internal		Committed	2678772
Batch: 20275634 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Mar Saf CW				Date: 04/04/2018
Batch: 20270880 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Feb Saf CW				Date: 05/03/2018
Batch: 20267646 - Inspection Batch				Route: Adhoc Inspection				Date: 09/02/2018
3567477	Fill in at ironwork	09/02/2018	At roundabout to osier dr	CW Repairs-Bituminous	Internal		Committed	2670433
Batch: 20263953 - Inspection Batch				Route: Adhoc Inspection				Date: 23/01/2018
3564984		23/01/2018	At manhole nr roundabout	CW Repairs-Bituminous	Internal		Uncommitt	2667906

Effective: 18/11/2016 to 18/11/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (1203184)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: A608 - Annesley			Feature Type: Street Section			Area: Ashfield	
Batch: 20263946 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Jan Saf CW				Date: 23/01/2018
Batch: 20259900 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Dec Saf CW				Date: 20/12/2017
Batch: 20252636 - Inspection Batch	No actionable defects found			Route: Ashfield Kirkby Nov Enh CW/FW				Date: 01/11/2017
Batch: 20251290 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Oct Saf CW				Date: 24/10/2017
Batch: 20246611 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Sep Saf CW				Date: 20/09/2017
Batch: 20243374 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Aug Saf CW				Date: 29/08/2017
Batch: 20239221 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Jul Saf CW				Date: 25/07/2017
Batch: 20234762 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Jun Saf CW				Date: 20/06/2017
Batch: 20230934 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk May Saf CW				Date: 23/05/2017
Batch: 20225220 - Inspection Batch				Route: Ashfield Kirk Apr Saf CW				Date: 18/04/2017
3546624		18/04/2017	Gully at osier dr	CW Repairs-Bituminous	Internal		Uncommitt	2648455
3546627		18/04/2017	Gully at roundabout as marked	CW Repairs-Bituminous	Internal		Uncommitt	2648458
3546625		18/04/2017	Aprox 80 mtrs from roundabout as marked	CW Repairs-Bituminous	Internal		Uncommitt	2648456
Batch: 20221396 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Mar Saf CW				Date: 21/03/2017
Batch: 20218869 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Feb Saf CW				Date: 28/02/2017
Batch: 20218548 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Feb Saf CW				Date: 27/02/2017
Batch: 20213897 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Jan Saf CW				Date: 26/01/2017
Batch: 20213702 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Jan Saf CW				Date: 25/01/2017
Batch: 20209645 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Dec Saf CW				Date: 20/12/2016

Effective: 18/11/2016 to 18/11/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (1203184)

Customer Services

Enquiry No.: 6111541 **Logged by:** External to Confirm **on:** 09/11/2018 09:30
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-95004892
Desc.: Road Pothole - Email from customer

Turning onto the roundabout off Mansfield road there is a small trench i have to run over every day . Submitted by Advisor: #2

Location: A608 Mansfield Road Roundabout before main M1 J27 Roundabout **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** A608 - Annesley **Feature Type:** Street Section
Job Number: 2696570 **Defect Number:** 3593194

Enquiry No.: 6109439 **Logged by:** External to Confirm **on:** 17/10/2018 14:06
Service: Other **Subject:** Other Enquiry (Highways) **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-92192728
Desc.: Other enquiry - customer email:

#2

Location: not applicable **Contact:**

Enquiry No.: 6103897 **Logged by:** External to Confirm **on:** 14/08/2018 11:24
Service: Cycling **Subject:** Damage to cycle track surface **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-84773876
Desc.: Cycle track damage - Reported in a poor condition, . Online report #2
Location: A608 cycle path running from junc 27 M1 to A611 **Contact:**

Enquiry No.: 6102820 **Logged by:** External to Confirm **on:** 01/08/2018 15:16
Service: Carriageway/Footway **Subject:** Carriageway Obstruction **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-83495620
Desc.: Road obstructions - Incident number Highways England #2 major incident RTA police have closed road both ways two crews requested for clear up. . Submitted by Advisor: #2
Location: East and west bound of the a608 off junction 27 of the M1 police have closed the road both ways **Contact:**

Enquiry No.: 6102406 **Logged by:** External to Confirm **on:** 27/07/2018 09:49
Service: Carriageway/Footway **Subject:** Spillage/Debris on Carriageway **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-82940159
Desc.: Spillage/debris in road - Information reported to ADC and forwarded to us ,There is a diesel spillage on the roundabout . Submitted by Advisor: #2
Location: Roundabout on Derby Rd Annesley with the junction of A608 **Contact:**

Enquiry No.: 6095339 **Logged by:** External to Confirm **on:** 16/05/2018 16:54
Service: Carriageway/Footway **Subject:** Line Marking/Stud Renewal **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-75817844
Desc.: Road marking renewal - This problem has been happening for years - every time there is a problem on the M1 near Junction 27, traffic diverts down the A608 and queuing traffic blocks traffic on the Business Park from exiting Willow Drive at both roundabouts. This causes several hours delay in leaving the estate. Box junctions at each of these roundabouts would go some way towards helping the situation. There may also be other solutions. . Online report #2
Location: 2 x roundabouts connecting the A608 with Willow Drive / Sherwood Business Park **Contact:**

Effective: 18/11/2016 to 18/11/2018
Display Action Officer: No

Feature No.: 2000.00 to 2000.00
Street: Mansfield Road (1203184)

Customer Services

Enquiry No.: 6094566 Logged by: External to Confirm on: 09/05/2018 20:36
Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation Enquiry Ref: FS-CASE-75164134
Desc.: Road Pothole - pothole . Online report Customer title is Mrs.
Location: just before roundabout Contact:

Plot Number: 2,000.00 Feature Id - Location: A608 - Annesley Feature Type: Street Section
Job Number: 2681017 Defect Number: 3577893

Enquiry No.: 6092409 Logged by: External to Confirm on: 19/04/2018 10:00
Service: Other Subject: Other Request (Highways) Classification: Service Request Enquiry Ref: FS-CASE-73316462
Desc.: #2

[Redacted] Contact:
[Redacted] House

Enquiry No.: 6087697 Logged by: External to Confirm on: 22/03/2018 12:57
Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation Enquiry Ref: FS-CASE-71015379
Desc.: Road Pothole - SIZE: 12" " APPROX. DEPTH: 3" " APPROX. DISTANCE FROM KERB: middle of the road . Submitted by Advisor: #2
Location: A608 going south just as you come off roundabout for Osier Drive Contact:

Plot Number: 2,000.00 Feature Id - Location: A608 - Annesley Feature Type: Street Section
Job Number: 2675855

Enquiry No.: 6076817 Logged by: External to Confirm on: 17/01/2018 13:06
Service: Carriageway/Footway Subject: Spillage/Debris on Carriageway Classification: Report or Observation Enquiry Ref: FS-CASE-66020645
Desc.: Spillage/debris in road - On the A608 there has been an RTC and is now an oil spillage - it is considerable but they have managed to scrape some dirt from side of the road to go over the top of it to make it safer.
101
Extension - 3191743
Badge Number 9482
Incident Number 328/17012018
. Submitted by Advisor: #2
Location: See map coordinates and description details Contact:

Enquiry No.: 6072579 Logged by: External to Confirm on: 08/12/2017 13:36
Service: Winter Maintenance Subject: Gritting Request Classification: Service Request Enquiry Ref: FS-CASE-63559432
Desc.: Road gritting request - Mansfield road on left before motorway junction 27

Annesley House Psychiatric Hospital
Requires clear roads for ambulances at all time and all emergency services
they have a grit bin which they are using at the moment but they are concerned for emergency services gaining access . Submitted by Advisor: #2 - -
Location: See map coordinates and description details Contact:

Effective: 18/11/2016 to 18/11/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (1203184)

Customer Services

Enquiry No.: 6069679 **Logged by:** External to Confirm **on:** 08/11/2017 15:28
Service: Other **Subject:** Other Enquiry (Highways) **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-61671790
Desc.: Other enquiry - I always use the A608 to get to Mercury house, nearly every day cars, van and lorries are always in the wrong lane, as i will be turning right to go up Osier Drive i always stay in the right hand lane, on a daily bases i have to contend with drivers being in the wrong lane , forcing me to have to slam my breaks on for those to either come into the lane or to move out of it,
i was wondering if signs could be placed to make driver aware . Submitted by Advisor: #2
Location: See map coordinates and description details **Contact:**

Enquiry No.: 6068953 **Logged by:** External to Confirm **on:** 01/11/2017 15:44
Service: Other **Subject:** Other Enquiry (Highways) **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-61264346
Desc.: #2 . . Submitted by Advisor: #2
Location: See map coordinates and description details **Contact:**

Enquiry No.: 6059815 **Logged by:** External to Confirm **on:** 28/07/2017 16:37
Service: Carriageway/Footway **Subject:** Spillage/Debris on Carriageway **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-56609031
Desc.: Spillage/debris in road - Highways already aware of this issue, reporting through now due to an earlier error with the firmstep system.
RTC at the J27 Roundabout with A608 Mansfield Road. Road is very slippy as there is a lot of rubber on the road, and it is partially closed off.
#2
#2 . . Submitted by Advisor: #2
Location: See map coordinates and description details **Contact:**

Enquiry No.: 6059350 **Logged by:** External to Confirm **on:** 25/07/2017 09:21
Service: Traffic Management **Subject:** Traffic Issues **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-56417469
Desc.: Traffic issues - At busy times, esp when the M1 has a delay or there are roadworks in Annesley Sherwood business park becomes gridlocked as right turners on the roundabout out of the estate (and the one further down) are blocked by traffic stationery on the roundabout. Would it be possible to paint yellow boxes on these roundabouts (just as there is on the Hucknall / Annesley island further down. This would help clear access from the business park. On the evening of 24 July delays of over 1 hour were experienced due entirely to this problem, There are NCC offices on the estate, staff I'm sure will back this up about these issues. . Online report -
Location: See map coordinates and description details **Contact:**

Enquiry No.: 6054852 **Logged by:** External to Confirm **on:** 07/06/2017 15:51
Service: Traffic Management **Subject:** Noise Pollution **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-54114899
Desc.: Traffic noise complaints - Customer is advising that this stretch of road is in constantly being used a race track for performance cars and this is a issue with noise pollution and anti-social behaviour.
#2
Location: See map coordinates and description details **Contact:**

Enquiry No.: 6054519 **Logged by:** External to Confirm **on:** 05/06/2017 13:21
Service: Traffic Management **Subject:** Traffic Issues **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-53970804
Desc.: Traffic issues - On Sunday evenings there are 100s of cars parking up on the laybys of the A608. They are racing down around the round about towards Annesley. The police are aware of this and there is an restraining order for this section of the road to stop them doing it but nothing has been stopped. #2
Location: See map coordinates and description details **Contact:**

Enquiry No.: 6048111 **Logged by:** External to Confirm **on:** 24/03/2017 16:47
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-50320861
Desc.: Road Damage - Coming up to the island going towards the motorway - road is bumpy and very badly damaged, some potholes too . Online report
Location: See map coordinates and description details **Contact:**

Effective: 18/11/2016 to 18/11/2018
Display Action Officer: No

Feature No.: 2000.00 to 2000.00
Street: Mansfield Road (1203184)

Customer Services

Enquiry No.: 6041604 Logged by: External to Confirm on: 06/02/2017 13:59
Service: Carriageway/Footway Subject: St Furn/Non Illum Sign Damage Classification: Report or Observation Enquiry Ref: FS-CASE-12620073
Desc.: Street/road sign request - #2, regarding some of the signage directing people to the the hotel.

He is looking at rebranding the hotel, with a potential name change, and needs to arrange having the signs changed.

There is one sign just as you come off the M1 at junction 27, and then another just off the roundabout as you enter Sherwood Business Park.

#2

Location: See map coordinates and description details Contact:

Enquiry No.: 6041190 Logged by: External to Confirm on: 02/02/2017 14:40
Service: Traffic Management Subject: Cycling Issues Classification: Report or Observation Enquiry Ref: FS-CASE-12449548
Desc.: Cycling issues caused by road works - Eastbound carriageway A608, between M1 and Sherwood Business Park roundabout

Is there any way you can stop people parking on the shared use pavement / cycle lane alongside the A608? People frequently park on the verge but this is currently very muddy so they occasionally block the pavement (see attached photo). Mud from the verge also gets on the tarmac which then makes it unsafe to cycle on. . Online report

Location: See map coordinates and description details Contact:

Enquiry No.: 6040106 Logged by: External to Confirm on: 23/01/2017 14:28
Service: Carriageway/Footway Subject: St Furn/Non Illum Sign Damage Classification: Report or Observation Enquiry Ref: FS-CASE-12097107
Desc.: #2

#2

Location: See map coordinates and description details Contact:

Enquiry No.: 6039371 Logged by: External to Confirm on: 16/01/2017 17:52
Service: Carriageway/Footway Subject: Guard Rail Damage Classification: Report or Observation Enquiry Ref: FS-CASE-11885384
Desc.: Guard rail damage - #2 coming off of junction 27 heading north . this has caused damage to the guide rail . customer says that highways England do not maintain this part of the road . however they have removed any debris from the carriageway onto the side of the road. #2
Location: The pin has been placed near Mansfield Road, Nottingham, United Kingdom, NG15 ODF Contact:

Enquiry No.: 6038347 Logged by: External to Confirm on: 06/01/2017 11:17
Service: Claims Subject: #2 Classification: Report or Observation Enquiry Ref: FS11315090
Desc.: #2

#2

UDF Contact:

Effective: 18/11/2016 to 18/11/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (1203184)

Customer Services

Enquiry No.: 6038346 Logged by: External to Confirm on: 06/01/2017 11:16
 Service: Carriageway/Footway Subject: Spillage/Debris on Carriageway Classification: Report or Observation Enquiry Ref: FS-CASE-11315090
 Desc.: Spillage/debris in road - There was a RTA on the approach to this roundabout on 27th November approx 2.00 pm. #2
 #2
 Location: The pin has been placed near Mansfield Road, Nottingham, United Kingdom, NG15 0DF Contact:

Enquiry No.: 3206102 Logged by: #2 on: 27/03/2018 16:52
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation
 Desc.: Carriageway pothole
 Location: Kodak Island (M1 Bound) Contact:

Plot Number: 2,000.00 Feature Id - Location: A608 - Annesley Feature Type: Street Section
 Job Number: 2675851

Enquiry No.: 3206062 Logged by: #2 on: 21/03/2018 07:39
 Service: Carriageway/Footway Subject: Manholes/Gullies Classification: Report or Observation
 Desc.: Gully - sunklen - requires replacing
 Location: Just after Sherwood Island (just before last lay by to M1) Contact:

Plot Number: 2,000.00 Feature Id - Location: A608 - Annesley Feature Type: Street Section
 Job Number: 2674865

Enquiry No.: 3206061 Logged by: #2 on: 21/03/2018 07:30
 Service: Carriageway/Footway Subject: Manholes/Gullies Classification: Report or Observation
 Desc.: Replace Highway Drainage manhole cover / frame (TM required)
 Location: At Kodak Island before turn offto Hotel Contact:

Plot Number: 2,000.00 Feature Id - Location: A608 - Annesley Feature Type: Street Section
 Job Number: 2674864

Enquiry No.: 3206060 Logged by: #2 on: 21/03/2018 07:17
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation
 Desc.: Carriageway pothole around gully
 Location: At Gully - just off Island (just before M1 lay by) Contact:

Plot Number: 2,000.00 Feature Id - Location: A608 - Annesley Feature Type: Street Section
 Job Number: 2674863

Enquiry No.: 3206045 Logged by: #2 on: 20/03/2018 06:59
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation
 Desc.: Carriageway pothole
 Location: Opposite Hotel at Kodak Island Contact:

Plot Number: 2,000.00 Feature Id - Location: A608 - Annesley Feature Type: Street Section
 Job Number: 2674612

Enquiry No.: 3205928 Logged by: #2 on: 02/03/2018 07:01
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation
 Desc.: Carriageway pothole
 Location: At Kodak Island near turn for Hotel (around cover) Contact:

Plot Number: 2,000.00 Feature Id - Location: A608 - Annesley Feature Type: Street Section
 Job Number: 2672619

Effective: 18/11/2016 to 18/11/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (1203184)

Customer Services

Enquiry No.: 3205883	Logged by: #2	on: 20/02/2018 12:26
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation
Desc.: Carriageway pothole around gully		
Location: Opposite 56 (Col)	Contact:	
Plot Number: 2,000.00	Feature Id - Location: A608 - Annesley	Feature Type: Street Section
Job Number: 2671585		
Enquiry No.: 3205533	Logged by: #2	on: 12/12/2017 13:21
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation
Desc.: Carriageway pothole		
Location: Around cover at Kodak Island junction and at gully around island	Contact:	
Plot Number: 2,000.00	Feature Id - Location: A608 - Annesley	Feature Type: Street Section
Job Number: 2664570		
Enquiry No.: 76170	Logged by: #2	on: 16/11/2018 11:10
Service: Highway Searches	Subject: Extents and CON29	Classification: Report or Observation
Desc.: #2		
Location: symmetry Park, Mansfield Road, Annesley	Contact:	
Enquiry No.: 73922	Logged by: Dave Wa ker	on: 17/08/2018 11:06
Service: Carriageway/Footway	Subject: Temporary Sign Request	Classification: Service Request
Desc.: Poppy Sign		
Location: Junc 27 heading to businss park	Contact:	
Enquiry No.: 73751	Logged by: #2	on: 09/08/2018 11:50
Service: Highway Searches	Subject: Adoption Extents	Classification: Report or Observation
Desc.: extent required 9.8.18 pay by card 9.8.18		
Location: 1 Mansfield Road, Annesley	Contact:	
Enquiry No.: 71495	Logged by: #2	on: 08/05/2018 14:32
Service: Highway Searches	Subject: Adoption Extents	Classification: Report or Observation
Desc.: #2		
Location: land south east of J27, M1, Mansfield Road, Annesley	Contact:	
Enquiry No.: 66591	Logged by: #2	on: 10/10/2017 16:56
Service: Traffic Management	Subject: Parking General	Classification: Report or Observation
Desc.: Parking in laybye		
Location: In laybye on A608	Contact:	
Enquiry No.: 66507	Logged by: #2	on: 06/10/2017 14:43
Service: Other	Subject: Other Enquiry (Highways)	Classification: Report or Observation
Desc.: Carriageway issues		
Location: A608 junc 27	Contact:	
Enquiry No.: 64486	Logged by: #2	on: 06/07/2017 13:09
Service: Traffic Management	Subject: Traffic Issues	Classification: Report or Observation
Desc.: Car Crusing enforcement		
Location: Entire	Contact:	

Effective: 18/11/2016 to 18/11/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (1203184)

Customer Services

Enquiry No.: 64432 Logged by: #2 on: 04/07/2017 12:12
 Service: Trees/Verges Subject: Overhanging Vegetation/Trees Classification: Report or Observation
 Desc.: Vegetation blocking footpaths
 Location: Entire Contact:

Enquiry No.: 61470 Logged by: #2 on: 24/03/2017 15:26
 Service: Other Subject: Other Enquiry (Highways) Classification: Report or Observation
 Desc.: Upgrade of existing signs
 Location: A608 Contact:

Enquiry No.: 61358 Logged by: #2 on: 22/03/2017 15:34
 Service: Traffic Management Subject: Traffic Issues Classification: Report or Observation
 Desc.: Request for traffic signals on island
 Location: Junc 27 Contact:

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: A608 - Annesley		Feature Type: Street Section		Area: Ashfield	
2648455	CW Repairs-Bituminous	Gully at osier dr	Filled when found (Cat 1)	Job Completed	18/04/2017	18/04/2017	Act.
2648456	CW Repairs-Bituminous	Aprox 80 mtrs from roundabout as marked	Filled when found (Cat 2)	Job Completed	18/04/2017	18/04/2017	Act.
2648458	CW Repairs-Bituminous	Gully at roundabout as marked	Filled when found (Cat 2)	Job Completed	18/04/2017	18/04/2017	Act.
2664570	Carriageway Pothole - Carriageway pothole (Enquiry 3205533)	Around cover at Kodak Island junction and at gully around island (Not marked see map -all 4 Assistants required)	Category 2	Job Completed	12/12/2017	13/12/2017	Act. ASH-AS/5002839
2667906	CW Repairs-Bituminous	At manhole nr roundabout	Filled when found (Cat 1)	Job Completed	23/01/2018	23/01/2018	Act.
2670433	Fill in at ironwork (CW Repairs-Bituminous)	At roundabout to osier dr	Category 2	Job Completed	09/02/2018	12/02/2018	Act. ASH-AS/5003269
2671585	Carriageway Pothole - Carriageway pothole around gully (Enquiry 3205883)	Opposite 56 (Col)	Filled when found (Cat 1)	Job Completed	20/02/2018	12/02/2018	Act.
2672619	Carriageway Pothole - Carriageway pothole (Enquiry 3205928)	At Kodak Island near turn for Hotel (around cover)	Category 1	Job Completed	02/03/2018	02/03/2018	Act. ASH-AS/5003401
2674612	Carriageway Pothole - Carriageway pothole (Enquiry 3206045)	Opposite Hotel at Kodak Island	Category 1	Job Completed	20/03/2018	20/03/2018	Act. ASH-AS/5003538
2674863	Carriageway Pothole - Carriageway pothole around gully (Enquiry 3206060)	At Gully - just off Island (just before M1 lay by) - Make safe only - follow up job to Ops	Category 1	Job Completed	21/03/2018	21/03/2018	Act. ASH-AS/5003572
2674864	Manholes/Gullies - Replace Highway Drainage manhole cover / frame (TM required) (Enquiry 3206061)	At Kodak Island before turn off to Hotel- STATS 450375 - 352697	Category 3	Job Completed	21/03/2018	15/04/2018	Act. ASH/3802452

Effective: 18/11/2016 to 18/11/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (1203184)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: A608 - Annesley		Feature Type: Street Section		Area: Ashfield	
2674865	Manholes/Gullies - Gully - sunklen - requires replacing (Enquiry 3206062)	Just after Sherwood Island (just before last lay by to M1) - TM required: STATS 449544 - 352134	Category 3	Job Completed	21/03/2018	15/04/2018	Act. ASH/3802453
2675851	Carriageway Pothole - Carriageway pothole (Enquiry 3206102)	Kodak Island (M1 Bound)	Category 1	Job Completed	27/03/2018	28/03/2018	Act. ASH-AS/5003650
2675855	Carriageway Pothole - Road Pothole - SIZE: 12" ; APPROX. DEPTH: 3" ; APPROX. DISTANCE FROM KERB: middle of the road . Submitted by Advisor: #2 s #2 (Enquiry 6087697)	A608 going south just as you come off roundabout for Osier Drive: 2 x potholes just after turn from Osier Drive	Category 1	Job Completed	28/03/2018	28/03/2018	Act. ASH-AS/5003652
2678772	Pothole at gully (CW Repairs-Bituminous)	On roundabout to Osier opp I post 13	Category 2	Job Completed	20/04/2018	23/04/2018	Act. ASH-AS/5003890
2680921	C way pothole. (CW Repairs-Bituminous)	At first gully through lights left side	Category 2	Job Completed	09/05/2018	14/05/2018	Act. ASH-AS/5004053
2681017	Carriageway Pothole on joint (CW Repairs-Bituminous)	Opposite lamp post 56	Category 2	Job Completed	10/05/2018	16/05/2018	Act. ASH-AS/5004060
2696570	Carriageway Pothole x 2 in channel, Jerry can help with TM. (CW Repairs-Bituminous)	A608 Mansfield Road Roundabout before main M1 J27 Roundabout	Category 2	Job Completed	09/11/2018	14/11/2018	Act. ASH-AS/5005033
2697172	Pothole x 5 outbound toward Motorway. Pothole x 1 inbound toward Kirkby. Offpeak Jerry can assist. (CW Repairs-Bituminous)	Osier Road Roundabout	Category 2	Job Completed	15/11/2018	16/11/2018	Act. ASH-AS/5005059

Street Works Inspections

Organisation: Severn Trent Water East (9103908)

Works Ref: 1101/000011132597

Group No: 2 **Site No:** 1 **Street Authority:** NCC - MANSFIELD
Category: Category C **Outcome:** Passed
Defect Notif. No: N/A **Defect No:** N/A
Tel: #2

Inspected: 10/03/2017 11:26:57**Sampled:** Yes**Site Informed:** Yes**Site Location:** ANNESLEY HALL**Position:** Footway**Sampled Site No:** 1**Sign./Light./Guard. Inadequacy:** No**Site Post Code:****Insp. Notes:****Defect Notes:**

Effective: 18/11/2016 to 18/11/2018

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Mansfield Road (1203184)

Street Works Notices**Organisation:** BT (0030006)**Works Ref:** TI002AP500259529900**Version:** 4**Work Desc:** RENEW POLE**Notice Type:** Registration of Reinstatement - Full**Start:** 20/06/2018 00:00:00**Work Status:** Works Stopped**Issued:** 21/06/2018 09:04:58**Work Type:** EToN 4: Minor**Est. End:** 22/06/2018**Completion:** 20/06/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	450027 352178ON PUBLIC FOOTPATH OS ANNESLEY HALLANNESLEY NOTTS, MANSFIELD ROAD	Verge	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	20/06/2018		20/06/2018	22/06/2018

Organisation: NCC - ASHFIELD (3055005) (NCC HIGHWAYS VIA)**Works Ref:** 30102228**Version:** 1**Work Desc:** installation of new bus stop pole**Notice Type:** 3 Day Initial Notice**Start:** 23/11/2016 00:00:00**Work Status:** Proposed Works**Issued:** 10/11/2016 15:03:16**Work Type:** EToN 4: Minor**Est. End:** 23/11/2016**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	In the layby on the east of junction 27 M1	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	23/11/2016			23/11/2016

Works Ref: 30102229**Version:** 1**Work Desc:** installation of new bus stop pole**Notice Type:** 3 Day Initial Notice**Start:** 23/11/2016 00:00:00**Work Status:** Proposed Works**Issued:** 10/11/2016 15:17:44**Work Type:** EToN 4: Minor**Est. End:** 23/11/2016**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	In the layby on the east of junction 27 M1. This stop is on the westbound carriageway	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	23/11/2016			23/11/2016

Works Ref: 30102456**Version:** 1**Work Desc:** Replace damaged signs**Notice Type:** 3 Day Initial Notice**Start:** 19/10/2017 00:00:00**Work Status:** Proposed Works**Issued:** 16/10/2017 13:01:12**Work Type:** EToN 4: Minor**Est. End:** 19/10/2017**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Near to its junction with Osier Drive	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	19/10/2017			19/10/2017

Works Ref: 30102520**Version:** 1**Work Desc:** Replace Lamp Column**Notice Type:** 3 Day Initial Notice**Start:** 08/02/2018 00:00:00**Work Status:** Proposed Works**Issued:** 07/02/2018 14:00:35**Work Type:** EToN 4: Minor**Est. End:** 08/02/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	400m East of J27 M1	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	08/02/2018			08/02/2018

Effective: 18/11/2016 to 18/11/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (1203184)

Street Works Notices**Organisation:** NCC - ASHFIELD (3055005) (NCC HIGHWAYS VIA)**Works Ref:** 30102529**Version:** 1**Work Desc:** Ashfield DC- Litter Clearance**Notice Type:** 3 Day Initial Notice**Start:** 14/03/2018 00:00:00**Work Status:** Proposed Works**Issued:** 05/03/2018 16:09:24**Work Type:** EToN 4: Minor**Est. End:** 14/03/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	From its junction with Mansfield Road to its junction with Wighay Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	14/03/2018			14/03/2018

Works Ref: 30102560**Version:** 1**Work Desc:** Replace existing camera on lamp column**Notice Type:** 3 Day Initial Notice**Start:** 16/07/2018 00:00:00**Work Status:** Proposed Works**Issued:** 11/07/2018 13:03:02**Work Type:** EToN 4: Minor**Est. End:** 17/07/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Lamp Column 114- Near to the junction with Willow Drive	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	16/07/2018			17/07/2018

Organisation: Nottinghamshire Highway Works (3055042)**Works Ref:** /A608ANNESLEY**Version:** 2**Work Desc:** Gully cleansing works.**Notice Type:** Cancellation**Start:** 20/12/2016 00:00:00**Work Status:** Abandoned Works**Issued:** 22/12/2016 10:14:41**Work Type:** EToN 4: Minor**Est. End:** 21/12/2016**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	A608 Annesley area.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	20/12/2016			21/12/2016

Works Ref: /A608DUALS**Version:** 2**Work Desc:** Gully cleansing works.**Notice Type:** Cancellation**Start:** 24/07/2017 00:00:00**Work Status:** Abandoned Works**Issued:** 26/07/2017 14:36:47**Work Type:** EToN 4: Minor**Est. End:** 25/07/2017**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	A608 Mansfield Road, Annesley.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	24/07/2017			25/07/2017

Works Ref: /A608GULLIES**Version:** 2**Work Desc:** Gully cleansing works.**Notice Type:** Cancellation**Start:** 24/07/2017 00:00:00**Work Status:** Abandoned Works**Issued:** 26/07/2017 14:37:10**Work Type:** EToN 4: Minor**Est. End:** 25/07/2017**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	A608 Mansfield Road duals, Annesley.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	24/07/2017			25/07/2017

Works Ref: /A608GULLIES2**Version:** 2**Work Desc:** Gully cleansing works.**Notice Type:** Cancellation**Start:** 17/07/2017 00:00:00**Work Status:** Abandoned Works**Issued:** 14/07/2017 08:09:13**Work Type:** EToN 4: Minor**Est. End:** 18/07/2017**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	A608 Mansfield Road, Annesley.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	17/07/2017			18/07/2017

Effective: 18/11/2016 to 18/11/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Mansfield Road (1203184)

Street Works Notices**Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** /A608ISLANDS**Version:** 2**Work Desc:** Gully cleansing works. Mixture of lane closures and stop and go TM.**Notice Type:** Cancellation**Start:** 17/11/2016 00:00:00**Work Status:** Abandoned Works**Issued:** 18/11/2016 14:27:15**Work Type:** EToN 4: Minor**Est. End:** 18/11/2016**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	A608 Between A611 and M1 Island.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	17/11/2016			18/11/2016

Works Ref: GULLIES22031**Version:** 1**Work Desc:** gully emptying**Notice Type:** 3 Day Initial Notice**Start:** 03/04/2018 00:00:00**Work Status:** Proposed Works**Issued:** 22/03/2018 18:52:21**Work Type:** EToN 4: Minor**Est. End:** 05/04/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Annesley1203184 Mansfield Road (A608),	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	03/04/2018			05/04/2018

Works Ref: MANSFIELDROAD**Version:** 3**Work Desc:** Highway repairs**Notice Type:** Works Stop**Start:** 15/04/2018 00:00:00**Work Status:** Works Stopped**Issued:** 16/04/2018 14:02:27**Work Type:** EToN 4: Minor**Est. End:** 15/04/2018**Completion:** 15/04/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Mansfield Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	15/04/2018			15/04/2018

Works Ref: OSIERDRIVE**Version:** 3**Work Desc:** Highway repairs**Notice Type:** Works Stop**Start:** 15/04/2018 00:00:00**Work Status:** Works Stopped**Issued:** 16/04/2018 14:03:07**Work Type:** EToN 4: Minor**Est. End:** 15/04/2018**Completion:** 15/04/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Osier Drive	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	15/04/2018			15/04/2018

Organisation: WPD - 5131 Alfreton (7011531)**Works Ref:** M51310377602**Version:** 3**Work Desc:** Urgent excavation in highway to locate and repair LV cable fault.**Notice Type:** Registration of Reinstatement - Full**Start:** 30/05/2017 09:45:00**Work Status:** Works Stopped**Issued:** 16/06/2017 09:39:18**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 05/06/2017**Completion:** 05/06/2017

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Cabinet Approx. 380 Metres East from the Junction 27 of the M1 on Roundabout	Verge	Up to 1.5 Metres of Cover	2.40	1.20 A Permanent Reinstatement	05/06/2017		05/06/2017	05/06/2017