

Effective: 01/01/2018 to 23/01/2019

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Whinney Lane (26805563)

Street: Whinney Lane (26805563)

Locality: Ollerton, Nottinghamshire

Area: Newark

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> From Brake Lane to Hallam Road.			<b>Feature Type:</b> Street Section			<b>Area:</b> Newark	
<b>Batch:</b> 20316275 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 20/12/2018
3596823	pothole.	20/12/2018	40m before Boughton Brake sign.	CW Repairs-Bituminous	Internal		Uncommitt	2700278
<b>Batch:</b> 20316179 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 19/12/2018
3596764	pothole filled when found cat 1 . 400 x 42 mm	19/12/2018	at side of pumping station column number 6 & 7	between lamp CW Repairs-Bituminous	Internal		Uncommitt	2700217
<b>Batch:</b> 20311671 - Inspection Batch				<b>Route:</b> Newark Area 1 Nov Saf FW				<b>Date:</b> 19/11/2018
3594087	potholes	19/11/2018	300 m past brake lane heading to walesby	CW Repairs-Bituminous	Internal		Uncommitt	2697475
<b>Batch:</b> 20296218 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Aug Saf CW/FW				<b>Date:</b> 03/08/2018
<b>Batch:</b> 20296215 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 03/08/2018
3585830	potholes	03/08/2018	to the rear of pumping station	CW Repairs-Bituminous	Internal		Uncommitt	2689094
<b>Batch:</b> 20296213 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 03/08/2018
3585828	potholea	03/08/2018	to the rear of pumping station	CW Repairs-Bituminous	Internal		Uncommitt	2689092
<b>Batch:</b> 20290248 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Jun Enh CW/FW				<b>Date:</b> 22/06/2018
<b>Batch:</b> 20286199 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 30/05/2018
3580240	potholes near lamp column numbers 6 , 7 , 8 near green steel fence	30/05/2018	all through this section not marked as wet	CW Repairs-Bituminous	Internal		Committed	2683388
<b>Batch:</b> 20281347 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 02/05/2018
3577102	potholes	02/05/2018	all through this section not marked as wet	CW Repairs-Bituminous	Internal		Committed	2680211
<b>Batch:</b> 20275270 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Mar Saf CW/FW				<b>Date:</b> 29/03/2018
<b>Batch:</b> 20270005 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 26/02/2018
3569451	pothole	26/02/2018	green fenced section just befor lamp column number 8 . , marked	CW Repairs-Bituminous	Internal		Committed	2672417
<b>Feat No.:</b> 2,001.00	<b>Feature Id - Locn.:</b> From Hallam Road to Newark Road			<b>Feature Type:</b> Street Section			<b>Area:</b> Newark	
<b>Batch:</b> 20319484 - Inspection Batch				<b>Route:</b> Newark Area 1 Jan Saf FW				<b>Date:</b> 21/01/2019
3598906	potholes	21/01/2019	outside house number 125 , 122 marked in yellow paint	FW Repairs-Bituminous	Internal		Committed	2702425
3598905	depression to the rear of drop kerbs	21/01/2019	outside house number 3 , opposite junction area of pine avenue marked in white paint	FW Repairs-Bituminous	Internal		Committed	2702426
<b>Batch:</b> 20315460 - Inspection Batch				<b>Route:</b> Newark Area 1 Dec Saf FW				<b>Date:</b> 13/12/2018
3596339	potholes	13/12/2018	house numbers 32 , 34 33 , 35 , 8 in yellow paint	FW Repairs-Bituminous	Internal		Committed	2699781

Effective: 01/01/2018 to 23/01/2019

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Whinney Lane (26805563)

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,001.00	<b>Feature Id - Locn.:</b> From Hallam Road to Newark Road			<b>Feature Type:</b> Street Section			<b>Area:</b> Newark	
<b>Batch:</b> 20311394 - Inspection Batch				<b>Route:</b> Newark Area 1 Nov Saf CW/FW				<b>Date:</b> 15/11/2018
3593883	potholes	15/11/2018	outside house 118 , 122 . marked in yellow paint	FW Repairs-Bituminous	Internal		Committed	2697267
<b>Batch:</b> 20307931 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 22/10/2018
3591627	replace bollard that assistants have took back to yard for safe keeping , cone placed at location of defect ,	22/10/2018	Near 89 Whinney Lane ollerton, by the street humps	Bollard Repairs	Internal		Committed	2694981
<b>Batch:</b> 20305862 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Oct Saf CW/FW				<b>Date:</b> 05/10/2018
<b>Batch:</b> 20301568 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Sep Saf CW/FW				<b>Date:</b> 10/09/2018
<b>Batch:</b> 20296220 - Inspection Batch				<b>Route:</b> Newark Area 1 Aug Saf CW/FW				<b>Date:</b> 03/08/2018
3585833	pothole	03/08/2018	outside house 65 marked	CW Repairs-Bituminous	Internal		Committed	2689097
<b>Batch:</b> 20293147 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Jul Saf CW/FW				<b>Date:</b> 11/07/2018
<b>Batch:</b> 20289851 - Inspection Batch				<b>Route:</b> Newark Area 1 Jun Enh CW/FW				<b>Date:</b> 20/06/2018
3582370	potholes	20/06/2018	lamp column numbers 3 , 6 7 , 8 , marked near pumping station	CW Repairs-Bituminous	Internal		Committed	2685549
<b>Batch:</b> 20281454 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 May Saf CW/FW				<b>Date:</b> 02/05/2018
<b>Batch:</b> 20277153 - Inspection Batch				<b>Route:</b> Newark Area 1 Apr Saf CW/FW				<b>Date:</b> 11/04/2018
3574372	please replace bollard	11/04/2018	outside house 115	Bollard Repairs	Internal		Committed	2677427
<b>Batch:</b> 20275016 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Mar Saf CW/FW				<b>Date:</b> 27/03/2018
<b>Batch:</b> 20273725 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 21/03/2018
3572094	potholes	21/03/2018	near lamp column number 10 , just off mini roundabout near number 1 tuxford road opposite paddyfields restaurant , marked	CW Repairs-Bituminous	Internal		Committed	2675100
<b>Batch:</b> 20267550 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Feb Saf CW/FW				<b>Date:</b> 08/02/2018
<b>Batch:</b> 20264219 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Jan Saf CW/FW				<b>Date:</b> 23/01/2018

Effective: 01/01/2018 to 23/01/2019

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Whinney Lane (26805563)

**Customer Services**

**Enquiry No.:** 6115037      **Logged by:** External to Confirm      **on:** 19/12/2018 13:45  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-100136029  
**Desc.:** Road Pothole - It was said to the customer that the road would be repaired before any work was due to begin on the new development on a field north of the houses on Whinney Lane. This hasn't happened and cars and lorries are finding it hard to pass without going in to the potholes. . Submitted by Advisor: Jakub Gan Customer title is Mr.  
**Location:** Just north of where the housing ends on Whinney Lane      **Contact:**

**Plot Number:** 2,000.00      **Feature Id - Location:** From Brake Lane to Hallam Road.      **Feature Type:** Street Section  
**Job Number:** 2700217      **Defect Number:** 3596764

**Enquiry No.:** 6110257      **Logged by:** External to Confirm      **on:** 26/10/2018 07:30  
**Service:** Carriageway/Footway      **Subject:** Dropped Kerb (Vehicle) Request      **Classification:** Service Request      **Enquiry Ref:** FS-CASE-93241046  
**Desc.:** Dropped kerb - Cars & other vehicles - Wanting to extend dropped curb to access driveway for ease of access with parking the car on the front . Online report - Quote required 2 whole kerb(s) and 1 tapered kerb(s) to be dropped Position of kerb - Entend current drop curb to the left for ease of access onto the drive Customer title is Mrs.  
**Location:** 59 newark road  
Ollerton  
Newark  
Ng229pz  
One way section of street

**Enquiry No.:** 6109851      **Logged by:** External to Confirm      **on:** 22/10/2018 12:48  
**Service:** Carriageway/Footway      **Subject:** St Furn/Non Illum Sign Damage      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-92736093  
**Desc.:** Street furniture damage - A bollard that indicates a narrowing of the road and a speed hump has been knocked over and is in the road. This leaves an exposed kerb stone with no indication it is there. . Submitted by Advisor: Stephen Towson Customer title is Mr.  
**Location:** Near 89 Whinney Lane ollerton, by the street humps      **Contact:**

**Plot Number:** 2,001.00      **Feature Id - Location:** From Hallam Road to Newark Road      **Feature Type:** Street Section  
**Job Number:** 2694981      **Defect Number:** 3591627

**Enquiry No.:** 6100078      **Logged by:** External to Confirm      **on:** 29/06/2018 13:32  
**Service:** Trees/Verges      **Subject:** Overhanging Vegetation/Trees      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-80109145  
**Desc.:** Overgrown hedges and vegetation - Overgrown hedge, makes it very difficult to see oncoming traffic from the right hand side when turning out of Hallam Road Area onto Whinney Lane. Reported to Ollerton & Boughton Town Council by a member of the public. . Online report Customer title is Mr.  
**Location:** Junction of Hallam Road & Whinney Lane      **Contact:**

**Enquiry No.:** 6091123      **Logged by:** External to Confirm      **on:** 11/04/2018 09:33  
**Service:** Road Works      **Subject:** Road Works Report      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-72586179  
**Desc.:** Road work issue - The customer is wanting to know why her driveway access has been blocked by works being carried out by Virgin Media. A sign was placed in front of her driveway blocking half of it, a mini digger is also being parked in front and although it has been moved slightly it is now in the bus stop. There are also green marks in the pavement with an arrow pointing down. They have also turned up in cars and parked them along the road, which is making the pavement unsafe. . Submitted by Advisor: Jakub Gan  
**Location:** In front of the customer's dropped kerb      **Contact:**

Effective: 01/01/2018 to 23/01/2019

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Whinney Lane (26805563)

**Customer Services**

**Enquiry No.:** 6090886      **Logged by:** External to Confirm      **on:** 10/04/2018 11:23  
**Service:** Other      **Subject:** Other Enquiry (Highways)      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-72491912  
**Desc.:** Other enquiry - Hi

RE: Residential Parking

Please could you advise what criteria is required to remove double lines from public roads.

As I have previously contacted Nottingham CC to raise an issue regarding parking, and to request the justification for double yellow lines restricting parking on both sides of Whinney lane. The section of Whinney Lane affected is around the Gleeson's development of Park Row on Whinney Lane in Ollerton NG22 9WD.

I live at Number 1 Park Row, Whinney lane, my front door is on Whinny Lane, which currently has double yellow lines both sides of the street, this makes parking difficult, especially with a 5 and a 1 year old. I requested that resident zones be added and a permit granted to park on the main road.

The road is a residential street located near to the town centre. The adjacent primary/junior school has a pedestrian access from Whinney lane, but due to the yellow lines it makes parking difficult and there is no additional available parking within a safe walkable distant with young children.

I understand that DYL are only implemented as waiting restrictions (yellow lines) for safety reasons, however I am unsure to why they are implemented outside my house. Over the last 2.5years there has been no evidence of parked vehicles causing personal injury crashes, therefore the DYL are no longer required for safety reasons.

Too often yellow lines are imposed on neighbourhoods or the high street without fair consideration of the livelihood of residents, local shops or the availability of parking spaces. I have a direct and democratic right to trigger a formal council led review of road restrictions in my area.

Regards

Matt . Submitted by Advisor: Jason Gutteridge - - -

**Location:** 1 Park Row, Whinney lane, Ollerton.**Contact:**

**Enquiry No.:** 6087501      **Logged by:** External to Confirm      **on:** 21/03/2018 11:24  
**Service:** Carriageway/Footway      **Subject:** Spillage/Debris on Carriageway      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-70895399  
**Desc.:** Spillage/debris in road - Mark Munnoch

mark@munnoch.org.ukTo: enquiries@nottscc.gov.ukcc: mark.spencer.mp@parliament.ukMud on Road / Verge destruction

Dear Nottinghamshire County Council I'd like to raise some issue with the ongoing farming activities that occur opposite our house. We recognise that agricultural tractors must have access to the land to continue the production of crops. We are concerned about the safety of all road users, including pedestrians which is being put at risk.

There are two distinct issues, for which I understand both you and Nottinghamshire Police have responsibility for:

Verges being narrowed

Tractors have driven onto the grass verges along the road, reducing the amount of useable space for pedestrians.

Yesterday a convoy of tractors pulling tankers, with a liquid which was eventually spread onto the fields arrived at about 0730am. At most I saw 5 different agricultural vehicles waiting, stationary along the road. At one point overtaking each other and mounting the grass verges. This also happens when the tractors turn out of the field onto the road. The issue is that these grass verges are the only safe means in which pedestrians can use the road. (I draw you to my earlier mention of the bend in the road, whereby vehicles travel at speed.) The tractors tyres have made deep cuts into the raised verge, which in real terms, simply causes the road to be widened.

I have already agreed with NCC that I will maintain the verges to the best of my ability in either direction from our house to the border of the next property north (where once around the bend, the verge disappears completely) and south to the far border of the Severn Trent Works. This is intrinsically in our interests, as when my family (2 adults, a 10 year old and an 8 year old) want to walk anywhere, we need to have a place of safety by use of the verge.

Mud On Road (Nottinghamshire Police Incident 1 . Submitted by Advisor: Sarah Kennett

**Location:** Mark Munnoch  
Orchard House  
Boughton Waterworks  
Walesby  
Newark  
NG22 9NF

**Contact:**

Effective: 01/01/2018 to 23/01/2019

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Whinney Lane (26805563)

**Customer Services**

**Enquiry No.:** 6086440      **Logged by:** External to Confirm      **on:** 15/03/2018 15:57  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-70438809  
**Desc.:** Road Pothole - All down brake lane there is potholes on both sides of the road. They are quite large. The road needs closing and re surfacing once and for all instead of keep bodging . Online report  
**Location:** Brake lane      **Contact:**

**Plot Number:** 2,000.00      **Feature Id - Location:** From Brake Lane to Hallam Road.      **Feature Type:** Street Section  
**Job Number:** 2672417      **Defect Number:** 3569451

**Enquiry No.:** 6086368      **Logged by:** External to Confirm      **on:** 15/03/2018 13:26  
**Service:** Carriageway/Footway      **Subject:** Bus Shelter/Stop Damage      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-70413586  
**Desc.:** Bus Stop Electronic Display damage - The are live wires exposed at the above bus stop.This was rang in to Newark District council who have forwarded it to us. . Submitted by Advisor: Robert Simpson  
**Location:** The bus stop on Whinney lane.Bus stop Number NS0530 near the sales office for Gleeson Homes.      **Contact:**

**Enquiry No.:** 6086297      **Logged by:** External to Confirm      **on:** 15/03/2018 09:39  
**Service:** Carriageway/Footway      **Subject:** Carriageway Obstruction      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-70375091  
**Desc.:** Road obstructions - A tree has fallen over and the branches are overhanging into the road. . Online report  
**Location:** 25 metres south of Orchard House. Opposite side of the road.      **Contact:**

**Enquiry No.:** 6083354      **Logged by:** External to Confirm      **on:** 26/02/2018 15:13  
**Service:** Carriageway/Footway      **Subject:** Carriageway Damage      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-68954756  
**Desc.:** Insurance claim form requested - Road Damage - Customer was driving on whinney Lane when he drove into a pothole which is around 5 - 6 inch - 1.5 foot long , 4-5 inch deep. this has caused damage to customers vehicle. . Submitted by Advisor: Candy Cooper  
**Location:** Coming out of the village near the pumping station past the S bend on whinney Lane      **Contact:**

**Plot Number:** 2,000.00      **Feature Id - Location:** From Brake Lane to Hallam Road.      **Feature Type:** Street Section  
**Job Number:** 2672417      **Defect Number:** 3569451

**Enquiry No.:** 6083001      **Logged by:** External to Confirm      **on:** 22/02/2018 19:27  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-68732965  
**Desc.:** Road Pothole - Deep potholes on the edges of the road and in some areas several holes in the middle, it is increasingly difficult to avoid all the potholes when driving along this lane.it is a busy lane, and at this time of the year, heavy farm machinery is in and out of the fields. . Online report  
**Location:** Whinney lane ,several potholes opposite the water board cottages, and quite severe the further down the lane you go. The worst seem to be just past the houses and three quarters the way down the lane towards whitewater lane/brake road,      **Contact:**

**Plot Number:** 2,000.00      **Feature Id - Location:** From Brake Lane to Hallam Road.      **Feature Type:** Street Section  
**Job Number:** 2672417      **Defect Number:** 3569451

**Enquiry No.:** 3207074      **Logged by:** John English      **on:** 22/10/2018 13:53  
**Service:** Other      **Subject:** Other Request (Highways)      **Classification:** Service Request  
**Desc.:** please provide and e mail stats to mark woodward and link to defect  
**Location:** as mapped      **Contact:**

**Plot Number:** 2,001.00      **Feature Id - Location:** From Hallam Road to Newark Road      **Feature Type:** Street Section

Effective: 01/01/2018 to 23/01/2019

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Whinney Lane (26805563)

**Customer Services**

**Enquiry No.:** 3207073      **Logged by:** John English      **on:** 22/10/2018 13:49  
**Service:** Other      **Subject:** Other Request (Highways)      **Classification:** Service Request  
**Desc.:** please provide stats and e mail to mark woodward . and link to defect  
**Location:** as mapped      **Contact:**

**Plot Number:** 2,001.00      **Feature Id - Location:** From Hallam Road to Newark Road      **Feature Type:** Street Section  
**Job Number:** 2694981      **Defect Number:** 3591627

**Enquiry No.:** 74972      **Logged by:** Pauline Laughton      **on:** 03/10/2018 13:39  
**Service:** Other      **Subject:** Other Enquiry (Highways)      **Classification:** Report or Observation  
**Desc.:** From: Bonnie x [mailto:melonlollypop28@hotmail.com]  
Sent: 01 October 2018 16:32  
To: Complaints Team <complaints@nottsc.gov.uk>  
Subject: advice  
Hiya I have no idea where to go to next but I have approached the school and basically been fobbed off.

They have a security light that shines in my front windows every night, even on the weekends when the school gates are locked and the school is not being used. I have asked the school to please look into this for me but they have not done anything at all I have attached a photo of the light it may not look like much but it comes on at 6pm and stays on until morning and it is blinding bright. Where do I go from here please?  
The school is the Dukeries academy, in Ollerton

I would appreciate any advice on this matter or an idea if any other department could help me.

**Location:** Access to Dukeries Academy      **Contact:**

**Enquiry No.:** 72698      **Logged by:** Rosie Heald      **on:** 26/06/2018 14:23  
**Service:** Highway Searches      **Subject:** Searches - Other Enquiries      **Classification:** Report or Observation  
**Desc.:** status enquiry 26.6.18  
**Location:** 120 Whinney Lane, New Ollerton      **Contact:**

**Enquiry No.:** 72478      **Logged by:** Rosie Heald      **on:** 18/06/2018 08:16  
**Service:** Highway Searches      **Subject:** Searches - Other Enquiries      **Classification:** Report or Observation  
**Desc.:** status enquiry 15.6.18  
**Location:** 120 Whinney Lane      **Contact:**

**Enquiry No.:** 70079      **Logged by:** Sarah Hird      **on:** 15/03/2018 10:17  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation  
**Desc.:** PH in c/way resulting in requesting claim form. (SH)  
**Location:** Brake Road, Walesby Stretch of road past the walesby scout camp      **Contact:**

**Plot Number:** 2,000.00      **Feature Id - Location:** From Brake Lane to Hallam Road.      **Feature Type:** Street Section  
**Job Number:** 2672417      **Defect Number:** 3569451

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> From Brake Lane to Hallam Road.		<b>Feature Type:</b> Street Section		<b>Area:</b> Newark	
2672417	pothole (CW Repairs-Bituminous)	green fenced section just befor lamp column number 8 . , marked	Category 1	Job Completed	26/02/2018	28/02/2018	Act. NEW-AS/5505148
2680211	potholes (CW Repairs-Bituminous)	all through this section not marked as wet	Category 3	Job Completed	02/05/2018	23/05/2018	Act. NEW/3609458

Effective: 01/01/2018 to 23/01/2019

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Whinney Lane (26805563)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Feat No.:</b>	2,000.00	<b>Feature Id - Locn.:</b> From Brake Lane to Hallam Road.		<b>Feature Type:</b> Street Section		<b>Area:</b> Newark	
2683388	potholes near lamp column numbers 6 , 7 , 8 near green steel fence (CW Repairs-Bituminous)	all through this section not marked as wet	Category 2	Job Completed	30/05/2018	14/06/2018	Act. NEW/3610075
2689092	potholea (CW Repairs-Bituminous)	to the rear of pumping station	Filled when found (Cat 1)	Job Completed	03/08/2018	03/08/2018	Act.
2689094	potholes (CW Repairs-Bituminous)	to the rear of pumping station	Filled when found (Cat 2)	Job Completed	03/08/2018	03/08/2018	Act.
2697475	potholes (CW Repairs-Bituminous)	300 m past brake lane heading to walesby	Filled when found (Cat 2)	Job Completed	19/11/2018	19/11/2018	Act.
2700217	pothole filled when found cat 1 . 350 x 400 x 42 mm (CW Repairs-Bituminous)	at side of pumping station between lamp column number 6 & 7	Filled when found (Cat 1)	Job Completed	19/12/2018	19/12/2018	Act.
2700278	pothole. (CW Repairs-Bituminous)	40m before Boughton Brake sign.	Filled when found (Cat 2)	Job Completed	20/12/2018	20/12/2018	Act.
<b>Feat No.:</b>	2,001.00	<b>Feature Id - Locn.:</b> From Hallam Road to Newark Road		<b>Feature Type:</b> Street Section		<b>Area:</b> Newark	
2675100	potholes (CW Repairs-Bituminous)	near lamp column number 10 , just off mini roundabout near number 1 tuxford road opposite paddyfields restaurant , marked outside house 115	Category 2	Job Completed	21/03/2018	23/03/2018	Act. NEW-AS/5505559
2677427	please replace bollard (Bollard Repairs)	outside house 115	Category 2	Job Completed	11/04/2018	17/04/2018	Act. NEW/3609080
2685549	potholes (CW Repairs-Bituminous)	lamp column numbers 3 , 6 7 , 8 , marked near pumping station	Category 2	Job Completed	20/06/2018	22/06/2018	Act. NEW-AS/5506681
2689097	pothole (CW Repairs-Bituminous)	outside house 65 marked	Category 3	Job Completed	03/08/2018	16/08/2018	Act. NEW/3611144
2694981	replace bollard that assistants have took back to yard for safe keeping , cone placed at location of defect , (Bollard Repairs)	Near 89 Whinney Lane ollerton, by the street humps	Category 3	Job Completed	22/10/2018	13/11/2018	Act. NEW/3611945
2697267	potholes (FW Repairs-Bituminous)	outside house 118 , 122 . marked in yellow paint	Category 3	Job Completed	15/11/2018	05/12/2018	Act. NEW/3612293
2699781	potholes (FW Repairs-Bituminous)	house numbers 32 , 34 33 , 35 , 8 marked in yellow paint	Category 3	Works Order Printed	13/12/2018	13/03/2019	Est. NEW/3612673
2702425	potholes (FW Repairs-Bituminous)	outside house number 125 , 122 marked in yellow paint	Category 3	Works Order Committed	21/01/2019	21/04/2019	Est. NEW/3612959
2702426	depression to the rear of drop kerbs (FW Repairs-Bituminous)	outside house number 3 , opposite junction area of pine avenue marked in white paint	Category 2	Works Order Committed	21/01/2019	18/02/2019	Est. NEW/3612957

Effective: 01/01/2018 to 23/01/2019

Display Action Officer: No

Feature No.: 2000.00 to 2001.00

Street: Whinney Lane (26805563)

**Street Works Inspections****Organisation:** Harlaxton Energy Networks (7342001)**Works Ref:** 5346-SVC

<b>Group No:</b> 4	<b>Site No:</b> 4	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 08/02/2018 16:04:26
<b>Category:</b> Category C		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
		<b>Tel:</b> 07825716438	<b>Site Location:</b> On Whinney Lane close to junction of Alder Close
<b>Insp. Notes:</b>			<b>Position:</b> Footway
<b>Defect Notes:</b>			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Sampled Site No:</b> 4
			<b>Site Post Code:</b>

<b>Group No:</b> 3	<b>Site No:</b> 3	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 08/02/2018 16:04:08
<b>Category:</b> Category C		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
		<b>Tel:</b> 07825716438	<b>Site Location:</b> On Whinney Lane close to junction of Alder Close
<b>Insp. Notes:</b>			<b>Position:</b> Footway
<b>Defect Notes:</b>			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Sampled Site No:</b> 3
			<b>Site Post Code:</b>

<b>Group No:</b> 2	<b>Site No:</b> 2	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 08/02/2018 16:03:51
<b>Category:</b> Category C		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
		<b>Tel:</b> 07825716438	<b>Site Location:</b> On Whinney Lane close to junction of Alder Close
<b>Insp. Notes:</b>			<b>Position:</b> Footway
<b>Defect Notes:</b>			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Sampled Site No:</b> 2
			<b>Site Post Code:</b>

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 08/02/2018 16:03:33
<b>Category:</b> Category C		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
		<b>Tel:</b> 07825716438	<b>Site Location:</b> On Whinney Lane close to junction of Alder Close
<b>Insp. Notes:</b>			<b>Position:</b> Footway
<b>Defect Notes:</b>			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Sampled Site No:</b> 1
			<b>Site Post Code:</b>

**Organisation:** NRSWA - Cadent Gas - East Midlands (0010001) (Street Works Admin Team NG Gas)**Works Ref:** 1000342860

<b>Group No:</b> 3	<b>Site No:</b> 2	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 06/03/2018 16:02:39
<b>Category:</b> Category C		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
		<b>Tel:</b> 07825716438	<b>Site Location:</b> 43A
<b>Insp. Notes:</b>			<b>Position:</b> Footway
<b>Defect Notes:</b>			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Sampled Site No:</b> 2
			<b>Site Post Code:</b>

<b>Group No:</b> 2	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 08/02/2018 08:23:46
<b>Category:</b> Category C		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
		<b>Tel:</b> 07825716438	<b>Site Location:</b> 43A
<b>Insp. Notes:</b>			<b>Position:</b> Footway
<b>Defect Notes:</b>			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Sampled Site No:</b> 1
			<b>Site Post Code:</b>



Effective: 01/01/2018 to 23/01/2019

Display Action Officer: No

Feature No.: 2000.00 to 2001.00

Street: Whinney Lane (26805563)

**Street Works Inspections****Organisation:** NRSWA - Cadent Gas - East Midlands (0010001) (Street Works Admin Team NG Gas)**Works Ref:** 1000652033

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 15/01/2018 14:42:57
<b>Category:</b> Category B		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
		<b>Tel:</b> 07825716438	<b>Site Location:</b> F/P O/S NO41
<b>Insp. Notes:</b>			<b>Position:</b> Footway
<b>Defect Notes:</b>			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Sampled Site No:</b> 1
			<b>Site Post Code:</b>

**Organisation:** Virgin Media NATIONAL NOTICING (7160100)**Works Ref:** /NEMBPL/ID63110/A

<b>Group No:</b> 2	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 06/06/2018 15:21:40
<b>Category:</b> Category B		<b>Outcome:</b> Passed	<b>Sampled:</b> No
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
		<b>Tel:</b> 07825716438	<b>Site Location:</b> From the junctionwith Tuxford Road to outside number 21
<b>Insp. Notes:</b>			<b>Position:</b> Footway
<b>Defect Notes:</b>			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Sampled Site No:</b>
			<b>Site Post Code:</b>

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 06/06/2018 15:19:32
<b>Category:</b> Category A		<b>Outcome:</b> Passed	<b>Sampled:</b> No
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
		<b>Tel:</b> 07825716438	<b>Site Location:</b> From the junctionwith Tuxford Road to outside number 21
<b>Insp. Notes:</b>			<b>Position:</b> Footway
<b>Defect Notes:</b>			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Sampled Site No:</b>
			<b>Site Post Code:</b>

**Works Ref:** /NEMBPL/ID63116/L

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 02/07/2018 11:31:00
<b>Category:</b> Category A		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
		<b>Tel:</b> 07825716438	<b>Site Location:</b> From the junction with Petersmith Drive to outside number 173
<b>Insp. Notes:</b>			<b>Position:</b> Verge
<b>Defect Notes:</b>			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Sampled Site No:</b> 1
			<b>Site Post Code:</b>

**Works Ref:** /NEMBPL/ID63512/D

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 20/06/2018 15:24:13
<b>Category:</b> Category A		<b>Outcome:</b> Passed	<b>Sampled:</b> No
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
		<b>Tel:</b> 07825716438	<b>Site Location:</b> From outside number 152 to outside number 170
<b>Insp. Notes:</b>			<b>Position:</b> Footway
<b>Defect Notes:</b>			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Sampled Site No:</b>
			<b>Site Post Code:</b>

Effective: 01/01/2018 to 23/01/2019

Display Action Officer: No

Feature No.: 2000.00 to 2001.00

Street: Whinney Lane (26805563)

**Street Works Inspections**

Organisation: WPD 5137 Southwell (7011537)

Works Ref: M51372076129

<b>Group No:</b> 1	<b>Site No:</b> 5	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 07/01/2019 11:39:32
<b>Category:</b> Category B		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
		<b>Tel:</b> 07825716438	<b>Site Location:</b> side of 173
<b>Insp. Notes:</b>			<b>Position:</b> Verge
<b>Defect Notes:</b>			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Site Post Code:</b>

**Street Works Notices**

Organisation: BT (0030006)

Works Ref: T1001MW500272919100

Version: 4

Work Desc: Install 73m of 1 way poly duct in Footway

Notice Type: Registration of Reinstatement - Full

Start: 10/12/2018 00:00:00

Work Status: Works Stopped

Issued: 12/12/2018 11:33:32

Work Type: EToN 4: Minor

Est. End: 12/12/2018

Completion: 11/12/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 59, WHINNEY LANE	Footway	Up to 1.5 Metres of Cover	73.40	0.30 A Permanent Reinstatement	11/12/2018		11/12/2018	12/12/2018

Organisation: Harlaxton Energy Networks (7342001)

Works Ref: 5346-SVC

Version: 8

Work Desc: Excavation required fr the connection of services. Excavation in F/W &amp; C/W. Approx restriction measurement 7mtrs X 2mtrs. Two way signals required 24hr use. Footway closure required.

Notice Type: Registration of Reinstatement - Full

Start: 12/04/2018 00:00:00

Work Status: Works Stopped

Issued: 27/04/2018 15:24:41

Work Type: EToN 4: Minor

Est. End: 16/04/2018

Completion: 15/04/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	On Whinney Lane close to junction of Alder Close	Footway	Up to 1.5 Metres of Cover	3.00	1.90 A Permanent Reinstatement	12/05/2016		12/05/2016	16/04/2018
2	On Whinney Lane close to junction of Alder Close	Footway	Up to 1.5 Metres of Cover	2.00	0.60 A Permanent Reinstatement	12/05/2016		12/05/2016	
3	On Whinney Lane close to junction of Alder Close	Footway	Up to 1.5 Metres of Cover	0.70	0.70 A Permanent Reinstatement	12/05/2016		12/05/2016	
4	On Whinney Lane close to junction of Alder Close	Footway	Up to 1.5 Metres of Cover	1.20	0.70 A Permanent Reinstatement	12/05/2016		12/05/2016	
5	On Whinney Lane close to junction of Alder Close	Carriageway	Up to 1.5 Metres of Cover	2.00	1.00 A Permanent Reinstatement	15/04/2018		15/04/2018	
6	On Whinney Lane close to junction of Alder Close	Footpath	Up to 1.5 Metres of Cover	2.00	1.00 A Permanent Reinstatement	15/04/2018		15/04/2018	

Effective: 01/01/2018 to 23/01/2019

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Whinney Lane (26805563)

**Street Works Notices****Organisation:** NCC - NEWARK (3055004)**Works Ref:** 30604229**Version:** 1**Work Desc:** Installing Lighting Column**Notice Type:** 3 Day Initial Notice**Start:** 24/07/2018 00:00:00**Work Status:** Proposed Works**Issued:** 20/07/2018 11:29:09**Work Type:** EToN 4: Minor**Est. End:** 24/07/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside No. 45	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	24/07/2018			24/07/2018

**Works Ref:** HW10183CN1700163A**Version:** 1**Work Desc:** Install raised bus stop kerbs & associated lining**Notice Type:** 10 Day Initial Notice**Start:** 18/06/2018 00:00:00**Work Status:** Proposed Works**Issued:** 12/06/2018 16:35:54**Work Type:** EToN 4: Standard**Est. End:** 22/06/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	o/s bus stops in various locations	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	18/06/2018			22/06/2018

**Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** 40812108**Version:** 1**Work Desc:** column Installation**Notice Type:** 3 Day Initial Notice**Start:** 11/09/2018 00:00:00**Work Status:** Proposed Works**Issued:** 06/09/2018 10:28:11**Work Type:** EToN 4: Minor**Est. End:** 11/09/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Whinney Lane Ollerton	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	11/09/2018			11/09/2018

**Works Ref:** WHINNEYLANE1**Version:** 1**Work Desc:** Parking Enforcement Lines**Notice Type:** Immediate Initial Notice**Start:** 14/01/2019 08:00:00**Work Status:** In Progress**Issued:** 08/01/2019 12:04:58**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 18/01/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Parking Enforcement Lines	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	14/01/2019 08:00:00			18/01/2019

**Organisation:** NRSWA - Cadent Gas - East Midlands (0010001) (Street Works Admin Team NG Gas)**Works Ref:** 1000245886**Version:** -1**Work Desc:** Unknown**Notice Type:** Actual Start Date**Start:** 07/07/2014 00:00:00**Work Status:** Proposed Works**Issued:** 07/07/2014 11:31:15**Work Type:** Not Applicable**Est. End:** 01/01/4000**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE NO.181 IN FOOTPATH	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	07/07/2014		08/07/2014	09/07/2014

Effective: 01/01/2018 to 23/01/2019

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Whinney Lane (26805563)

**Street Works Notices****Organisation:** NRSWA - Cadent Gas - East Midlands (0010001) (Street Works Admin Team NG Gas)**Works Ref:** 1000762820**Version:** 6**Work Desc:** DR4 CAMERA SURVEY TO IDENTIFY FULL ROUTE OF AN UNKNOWN GAS PIPE**Notice Type:** Registration of Reinstatement - Full**Start:** 22/10/2018 00:00:00**Work Status:** Works Stopped**Issued:** 26/10/2018 10:25:41**Work Type:** EToN 4: Standard**Est. End:** 26/10/2018**Completion:** 26/10/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	67	Footway	Up to 1.5 Metres of Cover	0.95	0.65	A Permanent Reinstatement	25/10/2018		25/10/2018	26/10/2018

**Organisation:** Virgin Media NATIONAL NOTICING (7160100)**Works Ref:** /NEMBPL/ID63108/L**Version:** 5**Work Desc:** Installation of cabinets digging of narrow trenches and subsequent installation of ducts  
Excavating approx 200m in footway**Notice Type:** Registration of Reinstatement - Full**Start:** 16/04/2018 00:00:00**Work Status:** Works Stopped**Issued:** 04/05/2018 10:51:00**Work Type:** EToN 4: Major**Est. End:** 25/04/2018**Completion:** 25/04/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	From the junction with Tuxford Road to outside number 41a	Footway	Up to 1.5 Metres of Cover	33.50	0.30	A Permanent Reinstatement	25/04/2018		25/04/2018	25/04/2018

**Works Ref:** /NEMBPL/ID63110/A**Version:** 6**Work Desc:** Installation of cabinets digging of narrow trenches and subsequent installation of ducts  
Excavating approx 395m in footway and 7m in carriageway**Notice Type:** Registration of Reinstatement - Full**Start:** 24/05/2018 00:00:00**Work Status:** Works Stopped**Issued:** 05/07/2018 07:28:30**Work Type:** EToN 4: Major**Est. End:** 22/06/2018**Completion:** 22/06/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	From the junction with Tuxford Road to outside number 21	Footway	Up to 1.5 Metres of Cover	103.80	0.30	A Permanent Reinstatement	22/06/2018		22/06/2018	12/06/2018
2	From outside to opposite number 21	Carriageway	Up to 1.5 Metres of Cover	7.00	0.40	A Permanent Reinstatement	22/06/2018		22/06/2018	
3	From outside number 21 to outside number 1	Footway	Up to 1.5 Metres of Cover	104.40	0.30	A Permanent Reinstatement	22/06/2018		22/06/2018	
4	From outside to opposite number 1	Carriageway	Up to 1.5 Metres of Cover	7.50	0.40	A Permanent Reinstatement	22/06/2018		22/06/2018	
5	From outside number 1 to the junction with Newark Road	Footway	Up to 1.5 Metres of Cover	45.60	0.30	A Permanent Reinstatement	22/06/2018		22/06/2018	
6	From outside number 65 to the junction with Pine Avenue	Footway	Up to 1.5 Metres of Cover	83.60	0.30	A Permanent Reinstatement	22/06/2018		22/06/2018	
7	From the junction with Pine Avenue to the junction with Oak Avenue	Footway	Up to 1.5 Metres of Cover	72.70	0.30	A Permanent Reinstatement	22/06/2018		22/06/2018	

**Works Ref:** /NEMBPL/ID63112/L**Version:** 12**Work Desc:** Interim to permanent reinstatement**Notice Type:** Registration of Reinstatement - Full**Start:** 12/04/2018 00:00:00**Work Status:** Works Stopped**Issued:** 12/04/2018 14:48:08**Work Type:** EToN 4: Minor**Est. End:** 16/04/2018**Completion:** 12/04/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	From outside number 135 to outside number 111	Footway	Up to 1.5 Metres of Cover	103.80	0.30	A Permanent Reinstatement	12/03/2018		12/03/2018	16/04/2018
2	From outside to opposite number 111	Carriageway	Up to 1.5 Metres of Cover	7.80	0.50	A Permanent Reinstatement	12/03/2018		12/03/2018	

Effective: 01/01/2018 to 23/01/2019

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Whinney Lane (26805563)

**Street Works Notices**

Organisation: Virgin Media NATIONAL NOTICING (7160100)

Works Ref: /NEMBPL/ID63112/L

Version: 12

Work Desc: Interim to permanent reinstatement

Notice Type: Registration of Reinstatement - Full

Start: 12/04/2018 00:00:00

Work Status: Works Stopped

Issued: 12/04/2018 14:48:08

Work Type: EToN 4: Minor

Est. End: 16/04/2018

Completion: 12/04/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop.	End
3	From outside number 111 to the junction with Dukeries Academy	Footway	Up to 1.5 Metres of Cover	39.60	0.30	A Permanent Reinstatement	12/03/2018		12/03/2018		
4	Across the junction with Dukeries Academy	Carriageway	Up to 1.5 Metres of Cover	13.60	0.30	A Permanent Reinstatement	12/03/2018		12/03/2018		
5	From the junction with Dukeries Academy to outside number 97	Footway	Up to 1.5 Metres of Cover	48.90	0.30	A Permanent Reinstatement	12/03/2018		12/03/2018		
6	From outside number 97 to outside number 114	Carriageway	Up to 1.5 Metres of Cover	7.70	0.50	A Permanent Reinstatement	12/03/2018		12/03/2018		
7	From outside number 97 to opposite the junction with Alder Grove	Footway	Up to 1.5 Metres of Cover	63.30	0.30	A Permanent Reinstatement	12/03/2018		12/03/2018		
8	From opposite the junction with Alder Grove to the junction with Alder Grove	Carriageway	Up to 1.5 Metres of Cover	7.80	0.50	A Permanent Reinstatement	12/03/2018		12/03/2018		
9	From opposite the junction with Alder Grove to outside number 87	Footway	Up to 1.5 Metres of Cover	116.00	0.30	A Permanent Reinstatement	12/03/2018		12/03/2018		
10	From outside to opposite number 87	Carriageway	Up to 1.5 Metres of Cover	7.70	0.50	A Permanent Reinstatement	12/03/2018		12/03/2018		
11	From outside number 87 to the junction with Hazel Grove	Footway	Up to 1.5 Metres of Cover	70.10	0.30	A Permanent Reinstatement	12/03/2018		12/03/2018		
12	From the junction with Hazel Road to opposite	Carriageway	Up to 1.5 Metres of Cover	7.80	0.50	A Permanent Reinstatement	12/03/2018		12/03/2018		
13	From outside number 73 to outside number 43	Footway	Up to 1.5 Metres of Cover	161.30	0.30	A Permanent Reinstatement	12/03/2018		12/03/2018		
14	From outside to opposite number 43	Carriageway	Up to 1.5 Metres of Cover	8.40	0.50	A Permanent Reinstatement	12/03/2018		12/03/2018		
15	From outside number 43 to the side of Paddyfields	Footway	Up to 1.5 Metres of Cover	17.90	0.30	A Permanent Reinstatement	12/03/2018		12/03/2018		
16	At the side of Paddyfields	Footway	Up to 1.5 Metres of Cover	1.00	1.00	A Permanent Reinstatement	12/04/2018	12/03/2018	12/04/2018		
17	From opposite number 43 to opposite the junction with Hazel Road	Footway	Up to 1.5 Metres of Cover	187.30	0.30	A Permanent Reinstatement	12/03/2018		12/03/2018		
18	From outside number 1 Park Row to the junction with Griffin Road	Footway	Up to 1.5 Metres of Cover	67.20	0.30	A Permanent Reinstatement	12/03/2018		12/03/2018		
19	From the junction with Griffin Road to outside number 17 Park Row	Footway	Up to 1.5 Metres of Cover	52.30	0.30	A Permanent Reinstatement	12/03/2018		12/03/2018		
20	From outside number 60 to the junction with Alder Grove	Footway	Up to 1.5 Metres of Cover	10.00	0.30	A Permanent Reinstatement	12/03/2018		12/03/2018		
21	From outside number 104 to the junction with Fir View	Footway	Up to 1.5 Metres of Cover	97.00	0.30	A Permanent Reinstatement	12/03/2018		12/03/2018		
22	From outside number 128 to outside number 150	Footway	Up to 1.5 Metres of Cover	102.20	0.30	A Permanent Reinstatement	12/03/2018		12/03/2018		

Effective: 01/01/2018 to 23/01/2019

Display Action Officer: No

Feature No.: 2000.00 to 2001.00

Street: Whinney Lane (26805563)

**Street Works Notices****Organisation:** Virgin Media NATIONAL NOTICING (7160100)

<b>Works Ref:</b> /NEMBPL/ID63116/L	<b>Version:</b> 9	<b>Work Desc:</b> Installation of cabinets digging of narrow trenches and subsequent installation of ducts
<b>Notice Type:</b> Registration of Reinstatement - Full	<b>Start:</b> 29/06/2018 00:00:00	Excavating approx 116 in the footway
<b>Work Status:</b> Works Stopped	<b>Issued:</b> 06/08/2018 14:35:45	
<b>Work Type:</b> EToN 4: Major	<b>Est. End:</b> 27/07/2018	<b>Completion:</b> 26/07/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	From the junction with Petersmith Drive to outside number 173	Verge	Up to 1.5 Metres of Cover	18.50	0.30	A Permanent Reinstatement	26/07/2018		26/07/2018	29/06/2018
2	From outside number 173 to outside number 175	Footway	Up to 1.5 Metres of Cover	9.20	0.30	A Permanent Reinstatement	26/07/2018		26/07/2018	
3	From the junction with Petersmith Drive to outside number 200	Footway	Up to 1.5 Metres of Cover	32.20	0.30	A Permanent Reinstatement	26/07/2018		26/07/2018	
4	From outside number 200 to outside number 328	Footway	Up to 1.5 Metres of Cover	14.20	0.30	A Permanent Reinstatement	26/07/2018		26/07/2018	
5	From outside number 328 to outside number 326	Verge	Up to 1.5 Metres of Cover	5.00	0.30	A Permanent Reinstatement	26/07/2018		26/07/2018	
6	From outside number 326 to the junction with Walesby Lane	Footway	Up to 1.5 Metres of Cover	23.00	0.30	A Permanent Reinstatement	26/07/2018		26/07/2018	

<b>Works Ref:</b> /NEMBPL/ID63512/D	<b>Version:</b> 14	<b>Work Desc:</b> Installation of cabinets digging of narrow trenches and subsequent installation of ducts
<b>Notice Type:</b> Registration of Reinstatement - Full	<b>Start:</b> 08/06/2018 00:00:00	Excavating approx 10m in footway
<b>Work Status:</b> Works Stopped	<b>Issued:</b> 03/07/2018 07:45:44	
<b>Work Type:</b> EToN 4: Minor	<b>Est. End:</b> 25/06/2018	<b>Completion:</b> 25/06/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	From outside number 152 to outside number 170	Footway	Up to 1.5 Metres of Cover	120.70	0.30	A Permanent Reinstatement	01/06/2018		01/06/2018	11/06/2018
2	From outside number 170 to outside number 161	Carriageway	Up to 1.5 Metres of Cover	7.80	0.40	A Permanent Reinstatement	01/06/2018		01/06/2018	
3	From the footway junction with Hallam Road to outside number 185	Footway	Up to 1.5 Metres of Cover	31.80	0.30	A Permanent Reinstatement	01/06/2018		01/06/2018	
4	From outside number 185 to outside number 181	Verge	Up to 1.5 Metres of Cover	25.50	0.30	A Permanent Reinstatement	01/06/2018		01/06/2018	
5	From outside number 181 to outside number 135	Footway	Up to 1.5 Metres of Cover	227.50	0.30	A Permanent Reinstatement	01/06/2018		01/06/2018	
6	At the junction with Hallam Road to outside number 199	Verge	Up to 1.5 Metres of Cover	3.00	0.30	A Permanent Reinstatement	01/06/2018		01/06/2018	
7	From the junction with Hallam Road to outside number 199	Footway	Up to 1.5 Metres of Cover	55.10	0.30	A Permanent Reinstatement	01/06/2018		01/06/2018	
8	Outside number 221	Footway	Up to 1.5 Metres of Cover	1.40	0.30	A Permanent Reinstatement	25/06/2018		25/06/2018	
9	Outside number 213	Footway	Up to 1.5 Metres of Cover	1.00	0.30	A Permanent Reinstatement	25/06/2018		25/06/2018	
10	From the junction with Blackburn View to outside number 219	Footway	Up to 1.5 Metres of Cover	26.00	0.30	A Permanent Reinstatement	25/06/2018		25/06/2018	

Effective: 01/01/2018 to 23/01/2019

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Whinney Lane (26805563)

**Street Works Notices****Organisation:** WPD 5137 Southwell (7011537)**Works Ref:** M51372059868**Version:** 3**Work Desc:** Urgent excavation in highway to locate and repair LV cable fault.**Notice Type:** Registration of Reinstatement - Full**Start:** 13/06/2018 08:45:00**Work Status:** Works Stopped**Issued:** 28/06/2018 10:11:38**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 20/06/2018**Completion:** 20/06/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 199	Verge	Up to 1.5 Metres of Cover	2.00	1.00	A Permanent Reinstatement	14/06/2018		14/06/2018	20/06/2018
2	OUTSIDE 199	Footway	Up to 1.5 Metres of Cover	7.90	1.10	A Permanent Reinstatement	20/06/2018		20/06/2018	

**Works Ref:** M51372076129**Version:** 3**Work Desc:** Urgent excavation in highway to locate and repair street light cable fault.**Notice Type:** Registration of Reinstatement - Full**Start:** 14/09/2018 09:00:00**Work Status:** Works Stopped**Issued:** 27/09/2018 15:52:33**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 18/09/2018**Completion:** 18/09/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	side of 173	Footway	Up to 1.5 Metres of Cover	4.00	0.30	A Permanent Reinstatement	18/09/2018		18/09/2018	18/09/2018
2	side of 173	Verge	Up to 1.5 Metres of Cover	1.20	0.80	A Permanent Reinstatement	18/09/2018		18/09/2018	
3	side of 173	Verge	Up to 1.5 Metres of Cover	4.00	0.40	A Permanent Reinstatement	18/09/2018		18/09/2018	
4	side of 173	Verge	Up to 1.5 Metres of Cover	1.20	0.80	A Permanent Reinstatement	18/09/2018		18/09/2018	
5	side of 173	Verge	Up to 1.5 Metres of Cover	1.20	0.80	A Permanent Reinstatement	18/09/2018		18/09/2018	