

Effective: 27/10/2018 to 26/12/2018

Display Action Officer: No

Feature No.: 2003.00 to 2003.00

Street: Nottingham Road (24621625)

Street: Nottingham Road (24621625)

Locality: Mansfield, Mansfield Town, Nottinghamshire

Area: Mansfield

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,003.00	Feature Id - Locn.: Cauldwell Road to A6009 Portland Street junction			Feature Type: Street Section			Area: Mansfield	
Batch: 20316223 - Inspection Batch	No actionable defects found			Route: Mansfield West Dec Saf CW				Date: 19/12/2018
Batch: 20315283 - Inspection Batch				Route: Adhoc Inspection				Date: 13/12/2018
3596222		13/12/2018	317(1) 213(1)	CW Repairs-Bituminous	Internal		Committed	2699663
Batch: 20312316 - Inspection Batch				Route: Mansfield West Nov Saf CW/FW				Date: 22/11/2018
3594520		22/11/2018	242(3) opp forest road (1) central island pc world (1)	FW Repairs-Bituminous	Internal		Committed	2697913
3594522		22/11/2018	214	FW Repairs-Bituminous	Internal		Committed	2697915
3594523	park low side service road to kfc barrow work to complete job.	22/11/2018	kfc	FW Repairs-Bituminous	Internal		Committed	2697916
3594524		22/11/2018	lamp 91	FW Repairs-Bituminous	Internal		Committed	2697911
3594521		22/11/2018	217(1) 213(2) lamp 54(1) lamp 61(1)	CW Repairs-Bituminous	Internal		Committed	2697914
3594519		22/11/2018	lamp 29 out side B&M	FW Repairs-Bituminous	Internal		Committed	2697912
Batch: 20308915 - Inspection Batch				Route: Adhoc Inspection				Date: 31/10/2018
3592205	2 number infill areas PASSED TO HIGHWAY ASSISTANTS 10-10 hrs	31/10/2018	outside 217	CW Repairs-Bituminous	Internal		Committed	2695572

Customer Services

Enquiry No.: 6115446	Logged by: External to Confirm	on: 26/12/2018 20:39
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation
Desc.: Road Pothole - Massive pothole with wires visible, if a motorbike or cyclist hits the pothole, they will definitely fall off or badly damage a car. . Online report Customer title is Mrs.		
Location: High Oakham traffic lights on the A60 heading out of Mansfield.	Contact:	Enquiry Ref: FS-CASE-100596058
Plot Number: 2,003.00	Feature Id - Location: Cauldwell Road to A6009 Portland Street junction	Feature Type: Street Section
Job Number: 2700545	Defect Number: 3597083	
Enquiry No.: 6115409	Logged by: External to Confirm	on: 24/12/2018 16:17
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation
Desc.: Road Pothole - A collection of potholes that are getting larger and larger. Hit one at 30 and it felt like driving into a kerb. About 1+ inches deep. Been like this months and I can see that there are reports inspected 9 months ago and also a declined request. This work needs to be carried out. . Online report Customer title is Mr.		
Location: Before the lights south bound road A60 Berry Hill lane junction.	Contact:	Enquiry Ref: FS-CASE-100516041
Plot Number: 2,003.00	Feature Id - Location: Cauldwell Road to A6009 Portland Street junction	Feature Type: Street Section
Job Number: 2700541	Defect Number: 3597079	
Enquiry No.: 6115291	Logged by: External to Confirm	on: 21/12/2018 15:45
Service: Carriageway/Footway	Subject: Traffic Signal Fault	Classification: Report or Observation
Desc.: Traffic light fault - Traffic lights do not let enough traffic through when they change in all direction. this is always a problem getting in to sainsburys. it is rare to get to the traffic lights and turn in on the same rotation. . Submitted by Advisor: Ross McDonald Customer title is Mr.		
Location: on the turning from the A60 onto park lane - where the sainsburys is	Contact:	Enquiry Ref: FS-CASE-100360227
	NG18 1BW	

Effective: 27/10/2018 to 26/12/2018

Feature No.: 2003.00 to 2003.00

Display Action Officer: No

Street: Nottingham Road (24621625)

Customer Services

Enquiry No.: 6111839	Logged by: External to Confirm	on: 13/11/2018 10:24	
Service: Carriageway/Footway	Subject: St Furn/Non Illum Sign Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-95490048
Desc.: Street furniture request - Customer has raised concerns about the red signs on Nottingham before the bus lane. Customer has said that she has been put off going down Bath street because the signs are misleading her. . Submitted by Advisor: Adam Newell - Customer title is Mrs.			
Location: Nottingham road, towards the bus lane, the three large red no entry signs.	Contact:		
Enquiry No.: 6111831	Logged by: External to Confirm	on: 13/11/2018 10:09	
Service: Carriageway/Footway	Subject: St Furn/Non Illum Sign Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-95488044
Desc.: Street furniture request - Customer has suggested that the bus sign is illegal and does not give enough warning. It is against the traffic sign manual 2013 chapter 4, 1.26. . Submitted by Advisor: Adam Newell - Customer title is Mrs.			
Location: Corner of Commercial Gate and Nottingham road. The blue bus sign before the bus lane.	Contact:		
Enquiry No.: 6110359	Logged by: External to Confirm	on: 27/10/2018 07:54	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-93368228
Desc.: Road Damage - 2 large potholes with wires exposed - one of which i photographed - isnt visible in the dark if pedestrians dont use the crossing at the lights . Online report Customer title is Ms.			
Location: at traffic lights nottm road and berry hill lane - leading upto cemetary	Contact:		
Plot Number: 2,003.00	Feature Id - Location: Cauldwell Road to A6009 Portland Street junction	Feature Type: Street Section	
Job Number: 2695572	Defect Number: 3592205		
Enquiry No.: 76739	Logged by: Kendra Hourd	on: 12/12/2018 16:07	
Service: Traffic Management	Subject: Traffic Issues	Classification: Report or Observation	
Desc.: Speed of traffic, buses for the college unloading on double yellow lines, increasing traffic flow and lorries, planning decisions by Mansfield District Council, noise, safety pulling out of driveway			
Location: Around No 419 just south of Lichfield Ave jcn	Contact:		

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,003.00	Feature Id - Locn.: Cauldwell Road to A6009 Portland Street junction		Feature Type: Street Section		Area: Mansfield	
2695572	2 number infill areas PASSED TO HIGHWAY ASSISTANTS 10-10 hrs (CW Repairs-Bituminous)	outside 217	Category 1	Job Completed	31/10/2018	31/10/2018	Act. MAN-AS/5405991
2697911	FW Repairs-Bituminous	lamp 91	Category 1	Job Completed	22/11/2018	23/11/2018	Act. MAN-AS/5406196
2697912	FW Repairs-Bituminous	lamp 29 out side B&M	Category 1	Job Completed	22/11/2018	23/11/2018	Act. MAN-AS/5406197
2697913	FW Repairs-Bituminous	242(3) opp forest road (1) central island pc world (1)	Category 2	Job Completed	22/11/2018	26/11/2018	Act. MAN-AS/5406198
2697914	CW Repairs-Bituminous	217(1) 213(2) lamp 54(1) lamp 61(1)	Category 2	Job Completed	22/11/2018	26/11/2018	Act. MAN-AS/5406199
2697915	FW Repairs-Bituminous	214	Category 3	Job Completed	22/11/2018	07/01/2019	Act. MAN/3505942
2697916	park low side service road to kfc barrow work to complete job. (FW Repairs-Bituminous)	kfc	Category 2	Job Completed	22/11/2018	07/01/2019	Act. MAN/3505943
2699663	CW Repairs-Bituminous	317(1) 213(1)	Category 2	Job Completed	13/12/2018	21/12/2018	Act. MAN-AS/5406437

Effective: 27/10/2018 to 26/12/2018

Feature No.: 2003.00 to 2003.00

Display Action Officer: No

Street: Nottingham Road (24621625)

Street Works Notices**Organisation:** NCC - MANSFIELD (3055003)**Works Ref:** 30502359**Version:** 1**Work Desc:** installation of bus stop pole**Notice Type:** 3 Day Initial Notice**Start:** 16/11/2018 00:00:00**Work Status:** Proposed Works**Issued:** 16/11/2018 14:31:45**Work Type:** EToN 4: Minor**Est. End:** 16/11/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	at its junction with Caudwell Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	16/11/2018			16/11/2018

Works Ref: 30502360**Version:** 1**Work Desc:** installation of bus stop pole**Notice Type:** 3 Day Initial Notice**Start:** 16/11/2018 00:00:00**Work Status:** Proposed Works**Issued:** 16/11/2018 14:38:54**Work Type:** EToN 4: Minor**Est. End:** 16/11/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside West Notts College	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	16/11/2018			16/11/2018

Organisation: Nottinghamshire Highway Works (3055042)**Works Ref:** 40813345**Version:** 1**Work Desc:** Installing cycle count site**Notice Type:** 3 Day Initial Notice**Start:** 11/11/2018 00:00:00**Work Status:** Proposed Works**Issued:** 08/11/2018 13:58:54**Work Type:** EToN 4: Minor**Est. End:** 11/11/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	A60 Nottingham Road Mnasfield	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	11/11/2018			11/11/2018

Organisation: WPD 5134 Mansfield (7011534)**Works Ref:** M51340275588**Version:** 3**Work Desc:** Urgent excavation in highway to locate and repair LV cable fault.**Notice Type:** Registration of Reinstatement - Full**Start:** 29/11/2018 09:43:00**Work Status:** Works Stopped**Issued:** 18/12/2018 10:05:04**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 05/12/2018**Completion:** 05/12/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside 83	Footway	Up to 1.5 Metres of Cover	1.00	0.60 A Permanent Reinstatement	05/12/2018		05/12/2018	05/12/2018

Works Ref: M51342080856**Version:** 2**Work Desc:** 1 joint hole in tarmac footway and 9m trenching in tarmac footway for link box replacement/installation - with excavation**Notice Type:** Cancellation**Start:** 28/10/2018 00:00:00**Work Status:** Abandoned Works**Issued:** 19/10/2018 14:05:17**Work Type:** EToN 4: Standard**Est. End:** 01/11/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	os KFC	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	28/10/2018			01/11/2018

Effective: 27/10/2018 to 26/12/2018

Feature No.: 2003.00 to 2003.00

Display Action Officer: No

Street: Nottingham Road (24621625)

Street Works Notices**Organisation:** WPD 5134 Mansfield (7011534)**Works Ref:** M51342086613**Version:** 4**Work Desc:** 1 joint hole in tarmac footway and 7m trenching in tarmac footway for link box replacement/installation - with excavation**Notice Type:** Registration of Reinstatement - Full**Start:** 18/11/2018 00:00:00**Work Status:** Works Stopped**Issued:** 23/11/2018 15:57:59**Work Type:** EToN 4: Standard**Est. End:** 22/11/2018**Completion:** 22/11/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	52.5M NORTH OF PARK LANE	Footway	Up to 1.5 Metres of Cover	8.00	1.10 A Permanent Reinstatement	22/11/2018		22/11/2018	22/11/2018

Organisation: WPD 5137 Southwell (7011537)**Works Ref:** M51372081483**Version:** 4**Work Desc:** 1 joint hole in tarmac footway for cable overlay**Notice Type:** Registration of Reinstatement - Full**Start:** 07/11/2018 00:00:00**Work Status:** Works Stopped**Issued:** 19/11/2018 09:40:59**Work Type:** EToN 4: Standard**Est. End:** 14/11/2018**Completion:** 14/11/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE NUMBER 409	Verge	Up to 1.5 Metres of Cover	1.20	0.50 A Permanent Reinstatement	14/11/2018		14/11/2018	14/11/2018