

Effective: 13/10/2017 to 13/10/2018

Asset Number: 2000.00 to 2000.00

Display Action Officer: No

Site: Unwin Road (1218986)

Site: Unwin Road (1218986)

Locality: Sutton in Ashfield, Nottinghamshire

Area: Ashfield

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 2,000.00	Asset - Locn.: Sutton in Ashfield			Feature Type: Street Section			Area: Ashfield	
Batch: 20304511 - Inspection Batch	No actionable defects found			Route: Ashfield Sut Sep Saf CW				Date: 27/09/2018
Batch: 20299323 - Inspection Batch	No actionable defects found			Route: Ashfield Sut Aug Saf CW				Date: 22/08/2018
Batch: 20299246 - Inspection Batch	No actionable defects found			Route: Ashfield Sut Aug Saf CW				Date: 22/08/2018
Batch: 20295488 - Inspection Batch	No actionable defects found			Route: Ashfield Sut Jul Saf CW				Date: 30/07/2018
Batch: 20290143 - Inspection Batch	No actionable defects found			Route: Ashfield Sut Jun Saf CW				Date: 21/06/2018
Batch: 20285802 - Inspection Batch	No actionable defects found			Route: Ashfield Sut May Saf CW				Date: 25/05/2018
Batch: 20282953 - Inspection Batch	No actionable defects found			Route: Ashfield Sut Apr Saf CW				Date: 14/05/2018
Batch: 20280681 - Inspection Batch	No actionable defects found			Route: Ashfield Sutton Mar Enh CW/FW				Date: 27/04/2018
Batch: 20272403 - Inspection Batch				Route: Ashfield Sut Feb Saf CW				Date: 14/03/2018
3570960		14/03/2018	Outside no75 to 91	CW Repairs-Bituminous	Internal		Committed	2673948
Batch: 20267034 - Inspection Batch	No actionable defects found			Route: Ashfield Sut Jan Saf CW				Date: 06/02/2018
Batch: 20267033 - Inspection Batch				Route: Adhoc Inspection				Date: 06/02/2018
3567106	10 potholes Carriageway Pothole - Road Pothole - Huge area of damage which is impossible to avoid, had to have a new tyre for the SECOND time this winter! . Online report (Enquiry 6080049)	06/02/2018	Between no79 - 89	CW Repairs-Bituminous	Internal		Committed	2670057
Batch: 20263087 - Inspection Batch				Route: Adhoc Inspection				Date: 16/01/2018
3564242	9 potholes	16/01/2018	Between no 77 - 89	CW Repairs-Bituminous	Internal		Committed	2667156
Batch: 20262320 - Inspection Batch	No actionable defects found			Route: Ashfield Sut Dec Saf CW				Date: 10/01/2018
Batch: 20260090 - Inspection Batch				Route: Adhoc Inspection				Date: 20/12/2017
3562344	12 potholes	20/12/2017	Near Tom Simpson Way, junc Phoenix St and between no79 - 91	CW Repairs-Bituminous	Internal		Committed	2665226
Batch: 20257164 - Inspection Batch	No actionable defects found			Route: Ashfield Sut Nov Saf CW				Date: 30/11/2017

Effective: 13/10/2017 to 13/10/2018

Asset Number: 2000.00 to 2000.00

Display Action Officer: No

Site: Unwin Road (1218986)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2,000.00	Asset - Locn.:	Sutton in Ashfield	Feature Type:	Street Section		Area:	Ashfield
Batch:	20252046 - Inspection Batch			Route:	Ashfield Sut Oct Saf CW		Date:	26/10/2017
No actionable defects found								

Customer Services

Enquiry No.: 6094377 **Logged by:** External to Confirm **on:** 08/05/2018 14:42
Service: Carriageway/Footway **Subject:** Manholes/Gullies **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-74989868
Desc.: Missing manhole/drain covers - There is a manhole cover on the road and this has dropped (sunken one side) and every time a vehicle drives over the cover it makes a clatter

We would be grateful if this could be inspected , as the cover seems loose and rocking. Submitted by Advisor: Anne LopintoCustomer title is Mr.

Location: Opp 119a Unwin road, Sutton in ashfield , nr Ashcourt gardens

Contact:

Enquiry No.: 6093408 **Logged by:** External to Confirm **on:** 28/04/2018 05:27
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-74103287
Desc.: Road Damage - Lots of severe road damage . Online report Customer title is Mr.
Location: Lhs of carriageway, going towards hospital **Contact:**

Plot Number: 2,000.00
Job Number: 2673948

Feature Id - Location: Sutton in Ashfield

Feature Type: Street Section

Enquiry No.: 6092918 **Logged by:** External to Confirm **on:** 24/04/2018 15:09
Service: Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation **Enquiry Ref:** FS73756865
Desc.: Insurance claim - related to Confirm defect reference: 6089370
Date/Time: 20/04/2018 19:30:00
Direction of travel: From the McDonalds/Kings Mill end of the road, towards the customer address at 75 Unwin Road (West bound)
Account of what happened: Jasmin was travelling along and went over one of the numerous potholes on this road. Eventually after pulling up at her address at number 75, her neighbour pointed out that her exhaust had become damaged and was loose, hanging just above the level of the tarmac. Jasmin is looking to pursue a claim for the damages caused to her vehicle.

Location: Unwin Rd, Centre of road between Phoenix and Mason Street

Contact:

Enquiry No.: 6092815 **Logged by:** External to Confirm **on:** 23/04/2018 18:51
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-73668435
Desc.: Road Pothole - Potholes and road surface damage . Online report Customer title is
Location: Unwin road **Contact:**

Plot Number: 2,000.00
Job Number: 2673948

Feature Id - Location: Sutton in Ashfield

Feature Type: Street Section

Enquiry No.: 6091716 **Logged by:** External to Confirm **on:** 13/04/2018 14:38
Service: Traffic Management **Subject:** Parking General **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-72836715
Desc.: Parking issues - I live on The Hillocks, Unwin Road. There is a social club on the road; Unwin Social Club which have at least 2 auctions a week, generally on a Monday and Wednesday evening. At weekends there are social events. These events cause the road to blocked. Cars are parked all the way down the road on both sides, making it extremely difficult to drive off the drive and see oncoming cars. At times, cars are mounting the kerb and parking on the grass. This is directly outside my house, making it a horrible view from the window and again obstructing our view of oncoming traffic. There are double yellow lines down the road, which no one seems to take any notice off. It is a busy road, which many drivers ignoring the 30 speed limit and are coming down the road at speed add that to people unable to see when coming off their own drive, there will be an accident someday. It is a nice area to live in, but it's a shame that members of the public feel they can ditch their car on double yellows, mount their van out someone's house and think it's acceptable.
. Online report Customer title is

Location: Unwin Road.

Contact:

Effective: 13/10/2017 to 13/10/2018

Asset Number: 2000.00 to 2000.00

Display Action Officer: No

Site: Unwin Road (1218986)

Customer Services

Enquiry No.: 6091709	Logged by: External to Confirm	on: 13/04/2018 14:11	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS72832244
Desc.: Insurance claim - related to Confirm defect reference: 6091708 Date/Time: 12/04/2018 16:30:00 Direction of travel: Travelling from Aldi to Eastfield side Account of what happened: When driving along, as we hit the 1st pothole they heard a crack. The they tried to drive out of them but hit others and they could hear the car banging at the front. Took it straight to a garage and on inspection it has broken the suspension spring on the driver side and taken a chunk out of the wheel. Caller is disabled and they cannot use the car.			
Location: Across from 97 Unwin Road Sutton		Contact:	
Enquiry No.: 6091708	Logged by: External to Confirm	on: 13/04/2018 14:09	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-72832244
Desc.: Insurance claim form requested - Road Pothole - Caller reports there are 5 potholes at this location, all of which caller believes are dangerous and have damaged the vehicle. . Submitted by Advisor: Dawn Smith Customer title is Mrs.			
Location: Across from 97 Unwin Road Sutton		Contact:	
Plot Number: 2,000.00	Feature Id - Location: Sutton in Ashfield	Feature Type: Street Section	
Job Number: 2673948			
Enquiry No.: 6090773	Logged by: External to Confirm	on: 10/04/2018 07:44	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-72462479
Desc.: Road Damage - The whole part of the road is damaged . Online report			
Location: Beginning of unwin road as you join from Coxmoor road bear the new houses		Contact:	
Plot Number: 2,000.00	Feature Id - Location: Sutton in Ashfield	Feature Type: Street Section	
Job Number: 2673948			
Enquiry No.: 6089370	Logged by: External to Confirm	on: 03/04/2018 18:33	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-71934089
Desc.: Road Damage - Area of damage and a collection of large potholes that present a hazard to motorists swerving to avoid the the damage, . Online report			
Location: Unwin Rd, Centre of road between Phoenix and Mason Street		Contact:	
Plot Number: 2,000.00	Feature Id - Location: Sutton in Ashfield	Feature Type: Street Section	
Job Number: 2673948			
Enquiry No.: 6086402	Logged by: External to Confirm	on: 15/03/2018 14:48	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-70427564
Desc.: Road Pothole - Large collection of potholes in centre of road . Online report			
Location: Centre of Road between Mason street and Phoenix street		Contact:	
Plot Number: 2,000.00	Feature Id - Location: Sutton in Ashfield	Feature Type: Street Section	
Job Number: 2673948			
Enquiry No.: 6085671	Logged by: External to Confirm	on: 13/03/2018 08:54	
Service: Licences/Permits	Subject: Res Park Permit Request (new)	Classification: Service Request	Enquiry Ref: FS-CASE-70152409
Desc.: Residents parking scheme proposal - Insufficient parking for public vehicles outside my property due to design of Drives. Urgently require site visit to resolve problem as on occasions had to ring police for vehicles to be moved due to blocking my access to my property. Also my neighbor has the same problem. . Online report - - -			
Location: 117A Unwin Road		Contact:	
Enquiry No.: 6085655	Logged by: External to Confirm	on: 13/03/2018 08:12	
Service: Carriageway/Footway	Subject: Flooding	Classification: Report or Observation	Enquiry Ref: FS-CASE-70150048
Desc.: Street flooding - Very poor drainage/Not enough covers to drain the water. Constant standing water . Online report			
Location: 117A Unwin Road		Contact:	

Effective: 13/10/2017 to 13/10/2018

Asset Number: 2000.00 to 2000.00

Display Action Officer: No

Site: Unwin Road (1218986)

Customer Services

Enquiry No.: 6085378	Logged by: External to Confirm	on: 12/03/2018 11:23	
Service: Carriageway/Footway	Subject: Carriageway Obstruction	Classification: Report or Observation	Enquiry Ref: FS-CASE-70063092
Desc.: Road obstructions - Parking on the pavement and on the corner at the bottom of the street, making it very dangerous to get out from Ashcourt Gardens as you cannot see cars coming up or down Unwin Road. . Online report			
Location: Bottom corner of Ashcourt Gardens	Contact:		
Enquiry No.: 6084897	Logged by: External to Confirm	on: 08/03/2018 11:48	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-69806466
Desc.: Road Damage - The road had crumbled away for about 12ft of length. This has got even worse since the bad weather. . Online report			
Location: Across from Polly Bowls.	Contact:		
Plot Number: 2,000.00	Feature Id - Location: Sutton in Ashfield	Feature Type: Street Section	
Job Number: 2673948			
Enquiry No.: 6080049	Logged by: External to Confirm	on: 05/02/2018 09:22	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-67249214
Desc.: Road Pothole - Huge area of damage which is impossible to avoid, had to have a new tyre for the SECOND time this winter! . Online report			
Location: Unwin Rd, center of road nr junction of mason street	Contact:		
Plot Number: 2,000.00	Feature Id - Location: Sutton in Ashfield	Feature Type: Street Section	
Job Number: 2670057	Defect Number: 3567106		
Enquiry No.: 6077435	Logged by: External to Confirm	on: 22/01/2018 09:58	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-66267309
Desc.: Road Damage - Collection of large potholes causing damage to vehicles . Online report			
Location: See map coordinates and description details	Contact:		
Enquiry No.: 6076754	Logged by: External to Confirm	on: 17/01/2018 10:21	
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-65997789
Desc.: Road Damage - Series of holes/ road damage . Online report			
Location: See map coordinates and description details	Contact:		
Enquiry No.: 6076294	Logged by: External to Confirm	on: 15/01/2018 08:31	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-65731276
Desc.: Road Pothole - There are several potholes on Unwin Road around no 14. These have been filled in several times over the last 18 months. They are leaving lots or debris on the road and this is affecting our cars. The tenant at Number 12 also sweeps the debris into the drain outside number 12 this in itself creates another issue as the drain then becomes blocked. The road is a disgrace and is getting worse . I have photos of the potholes. The road needs sorting and not just filling up the potholes again. . Online report			
Location: See map coordinates and description details	Contact:		
Plot Number: 2,000.00	Feature Id - Location: Sutton in Ashfield	Feature Type: Street Section	
Job Number: 2667156	Defect Number: 3564242		
Enquiry No.: 6069090	Logged by: External to Confirm	on: 02/11/2017 15:10	
Service: Road Works	Subject: Road Works Report	Classification: Report or Observation	Enquiry Ref: FS-CASE-61326966
Desc.: Road work issue - Adam Gilbert from Woodset homes would like to speak to someone about roadworks for Unwin Road Sutton In Ashfield. Please contact him back on 07880798422. . Submitted by Advisor: Liam Newton			
Location: See map coordinates and description details	Contact:		
Enquiry No.: 6069012	Logged by: External to Confirm	on: 02/11/2017 09:03	
Service: Road Works	Subject: Road Works Report	Classification: Report or Observation	Enquiry Ref: FS-CASE-61294249
Desc.: Road work issue - The customer reported a parking issue on the 10/10, HAMS No. 6066821. He has not yet had a response about installing some double yellow lines on the junction. . Submitted by Advisor: Jakub Gan			
Location: See map coordinates and description details	Contact:		

Effective: 13/10/2017 to 13/10/2018

Asset Number: 2000.00 to 2000.00

Display Action Officer: No

Site: Unwin Road (1218986)

Customer Services

Enquiry No.: 6067879 **Logged by:** External to Confirm **on:** 20/10/2017 15:51
Service: Traffic Management **Subject:** Parking General **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-60581495

Desc.: Parking issues - Received via e-mail

-----Date: 20/10/2017

Reference number: FS-Case-60544666

Full name: julie Godfrey

Email address: julesgodfrey1@outlook.com

Telephone number: 01623364783

What district do you live in?: Ashfield

Full Address : 77, Unwin Road, , Sutton In Ashfield, NG17 4HN

Your message : I am a disabled person, and I would like to say that the company that is run on our street park their cars outside my house and make it difficult for me to park. Most of the vehicles on our street belong to the builders yard at the end of the street, so this makes it difficult for any permanent resident to park outside their home. I suffer with spondylosis and Arthritis and have just recently found out through an MRI scan that my spine on my right side as deteriorated more. so this makes it more difficult for me to walk any distance from my house. Would appreciate it if some one could have words with person[s] involved with the company to have words with their staff.

YOURS SINCERELY

MRS JULIE GODFREY

----- . Submitted by Advisor: Kerry Carby

Location: See map coordinates and description details**Contact:**

Enquiry No.: 6067342 **Logged by:** External to Confirm **on:** 16/10/2017 14:04
Service: Carriageway/Footway **Subject:** Blocked Drain **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-60313932

Desc.: Blocked drains - The drain outside no.12 and 14 Unwin Road, Sutton in Ashfield is completely blocked full of leaves, and needs to be cleared out.

Customer has confirmed that this goes right down to the bottom of the drain, and isn't just on the surface. Whenever there is any rain, the drain doesn't carry any water away, and the street gets flooded.. Submitted by Advisor: Jason Gutteridge

Location: See map coordinates and description details**Contact:**

Enquiry No.: 70493 **Logged by:** Caroline Cooksey **on:** 28/03/2018 10:48
Service: Highway Searches **Subject:** Searches - Other Enquiries **Classification:** Report or Observation

Desc.:**Location:** 25**Contact:**

Enquiry No.: 67549 **Logged by:** Dave Walker **on:** 22/11/2017 08:50
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation

Desc.: Mud on Road**Location:** Near new Development**Contact:**

Enquiry No.: 67361 **Logged by:** Rosie Heald **on:** 13/11/2017 14:21
Service: Highway Searches **Subject:** Searches - Other Enquiries **Classification:** Report or Observation

Desc.: status enquiry 13.11.2017**Location:** Plot 4, 28 Unwin Road, Sutton in Ashfield**Contact:**

Enquiry No.: 66997 **Logged by:** Dave Walker **on:** 26/10/2017 16:11
Service: Carriageway/Footway **Subject:** Carriageway Obstruction **Classification:** Report or Observation

Desc.: Widening of ped refuge in programme**Location:** Entire**Contact:**

Effective: 13/10/2017 to 13/10/2018

Asset Number: 2000.00 to 2000.00

Display Action Officer: No

Site: Unwin Road (1218986)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 2,000.00	Asset - Locn.: Sutton in Ashfield		Feature Type: Street Section		Area: Ashfield	
2665226	12 potholes (CW Repairs-Bituminous)	Near Tom Simpson Way, junc Phoenix St and between no79 - 91	Category 1	Job Completed	20/12/2017	21/12/2017	Act. ASH-AS/5002880
2667156	9 potholes (CW Repairs-Bituminous)	Between no 77 - 89	Category 1	Job Completed	16/01/2018	17/01/2018	Act. ASH-AS/5003026
2670057	10 potholes Carriageway Pothole - Road Pothole - Huge area of damage which is impossible to avoid, had to have a new tyre for the SECOND time this winter! . Online report (Enquiry 6080049) (CW Repairs-Bituminous)	Between no79 - 89	Category 1	Job Completed	06/02/2018	07/02/2018	Act. ASH-AS/5003242
2673948	CW Repairs-Bituminous	Outside no75 to 91	Category 3	Job Completed	14/03/2018	14/05/2018	Act. ASH/3802441

Street Works Inspections**Organisation:** Fulcrum Pipelines Limited -Harlaxton ES Ltd (7294010)**Works Ref:** 6860-GC2

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 16/08/2018 13:30:33
Category: Category A		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel: 07557895771	Site Location: On unwin road up from junction to Ashcourt Gardens
Insp. Notes:			Position: Footway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Site Post Code:

Organisation: Harlaxton Energy Networks (7342001)**Works Ref:** 6860-EC

Group No: 1	Site No: 3	Street Authority: Nottinghamshire	Inspected: 19/06/2018 09:10:19
Category: Category B		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel: 07393 789518	Site Location: on unwin road outside existng 105 unwin road and down from junction to ashcourt gardens
Insp. Notes:			Position: Verge
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Site Post Code:

Works Ref: 6860-EC2

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 16/08/2018 13:30:02
Category: Category A		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel: 07557895771	Site Location: on Unwin Rd up from junction to ashcourt gardens
Insp. Notes:			Position: Carriageway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Site Post Code:

Effective: 13/10/2017 to 13/10/2018

Asset Number: 2000.00 to 2000.00

Display Action Officer: No

Site: Unwin Road (1218986)

Street Works Inspections

Organisation: Severn Trent Water East (9103908)

Works Ref: 1101/000060194644

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 19/06/2018 09:06:39	Sampled Site No: 1
Category: Category C		Outcome: Passed	Sampled: Yes	Sign./Light./Guard. Inadequacy: No
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes	
		Tel: 07393 789518	Site Location: 69	Site Post Code:
Insp. Notes:			Position: Footway	
Defect Notes:				

Organisation: Virgin Media NATIONAL NOTICING (7160100)

Works Ref: /NEMRF/CX00029187

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 19/06/2018 09:17:19	Sampled Site No: 1
Category: Category B		Outcome: Passed	Sampled: Yes	Sign./Light./Guard. Inadequacy: No
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes	
		Tel: 07393 789518	Site Location: outside 20	Site Post Code:
Insp. Notes:			Position: Footway	
Defect Notes:				

Works Ref: /NYNLRE/0319772A

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 19/06/2018 09:14:40	Sampled Site No: 1
Category: Category B		Outcome: Passed	Sampled: Yes	Sign./Light./Guard. Inadequacy: No
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes	
		Tel: 07393 789518	Site Location: SIDE OF 5 THE HILLOCKS	Site Post Code:
Insp. Notes:			Position: Footway	
Defect Notes:				

Organisation: WPD 5131 Alfreton (7011531)

Works Ref: M51312024261

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 12/12/2017 11:39:36	Sampled Site No: 1
Category: Category A		Outcome: Passed	Sampled: Yes	Sign./Light./Guard. Inadequacy: No
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes	
		Tel: 07557895771	Site Location: OUTSIDE NUMBER 117	Site Post Code:
Insp. Notes:			Position: Carriageway	
Defect Notes:				

Street Works Notices

Organisation: BT (0030006)

Works Ref: CT001MW500254873700

Notice Type: Registration of Reinstatement - Full

Work Status: Works Stopped

Work Type: EToN 4: Minor

Version: 4

Start: 17/01/2018 00:00:00

Issued: 29/01/2018 11:04:40

Est. End: 19/01/2018

Work Desc: Build 2 precast chamber in 915mm x 445mm x 965mm deep in Footway, Install 25m of 1 way poly duct in Footway, Provide 2 core drill(s) into jointbox or building

Completion: 19/01/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	WORKS BETWEEN OPP 103 & OPP 119b, UNWIN ROAD	Footway	Up to 1.5 Metres of Cover	25.00	0.40	A Permanent Reinstatement	19/01/2018		19/01/2018	19/01/2018

Effective: 13/10/2017 to 13/10/2018

Asset Number: 2000.00 to 2000.00

Display Action Officer: No

Site: Unwin Road (1218986)

Street Works Notices**Organisation:** BT (0030006)

Works Ref: CT001MW500254873700 **Version:** 4 **Work Desc:** Build 2 precast chamber in 915mm x 445mm x 965mm deep in Footway, Install 25m of 1 way poly duct in Footway, Provide 2 core drill(s) into jointbox or building
Notice Type: Registration of Reinstatement - Full **Start:** 17/01/2018 00:00:00
Work Status: Works Stopped **Issued:** 29/01/2018 11:04:40
Work Type: EToN 4: Minor **Est. End:** 19/01/2018 **Completion:** 19/01/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
2	WORKS BETWEEN OPP 103 & OPP 119b, UNWIN ROAD	Footway	Up to 1.5 Metres of Cover	1.60	1.10	A Permanent Reinstatement	19/01/2018		19/01/2018	
3	WORKS BETWEEN OPP 103 & OPP 119b, UNWIN ROAD	Footway	Up to 1.5 Metres of Cover	1.60	1.40	A Permanent Reinstatement	19/01/2018		19/01/2018	

Organisation: Fulcrum Pipelines Limited -Harlaxton ES Ltd (7294010)

Works Ref: 6860-GC **Version:** 5 **Work Desc:** Ecavation required in C/W & F/W for installation of mains and connection for new development.
Notice Type: Registration of Reinstatement - Full **Start:** 03/04/2018 00:00:00
Work Status: Works Stopped **Issued:** 27/04/2018 15:45:05
Work Type: EToN 4: Standard **Est. End:** 15/04/2018 **Completion:** 15/04/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	on unwin road outside existing 105 unwin road and down from junction to ashcourt gardens	Footway	Up to 1.5 Metres of Cover	2.00	1.00	A Permanent Reinstatement	15/04/2018		15/04/2018	15/04/2018
2	on unwin road outside existing 105 unwin road and down from junction to ashcourt gardens	Carriageway	Up to 1.5 Metres of Cover	4.50	0.50	A Permanent Reinstatement	15/04/2018		15/04/2018	
3	on unwin road outside existing 105 unwin road and down from junction to ashcourt gardens	Verge	Up to 1.5 Metres of Cover	50.00	0.30	A Permanent Reinstatement	15/04/2018		15/04/2018	

Works Ref: 6860-GC2 **Version:** 6 **Work Desc:** excavation required in C/W & F/W for installtion of mains and connection for new development via rd crossing. Approx excavation measurements 8m x 1m.
Notice Type: Registration of Reinstatement - Full **Start:** 13/08/2018 00:00:00
Work Status: Works Stopped **Issued:** 10/09/2018 15:34:52
Work Type: EToN 4: Standard **Est. End:** 24/08/2018 **Completion:** 24/08/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	On unwin road up from junction to Ashcourt Gardens	Footway	Up to 1.5 Metres of Cover	7.00	2.00	A Permanent Reinstatement	24/08/2018		24/08/2018	24/08/2018
2	On unwin road up from junction to Ashcourt Gardens	Carriageway	Up to 1.5 Metres of Cover	6.00	0.80	A Permanent Reinstatement	24/08/2018		24/08/2018	

Organisation: Harlaxton Energy Networks (7342001)

Works Ref: 6860-EC **Version:** 5 **Work Desc:** excavation required in C/W & F/W for installation of mains and connection for new development.
Notice Type: Registration of Reinstatement - Full **Start:** 03/04/2018 00:00:00
Work Status: Works Stopped **Issued:** 26/04/2018 09:52:39
Work Type: EToN 4: Standard **Est. End:** 15/04/2018 **Completion:** 15/04/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	on unwin road outside existitng 105 unwin road and down from junction to ashcourt gardens	Footway	Up to 1.5 Metres of Cover	2.00	1.00	A Permanent Reinstatement	15/04/2018		15/04/2018	15/04/2018
2	on unwin road outside existitng 105 unwin road and down from junction to ashcourt gardens	Carriageway	Up to 1.5 Metres of Cover	4.50	0.50	A Permanent Reinstatement	15/04/2018		15/04/2018	
3	on unwin road outside existitng 105 unwin road and down from junction to ashcourt gardens	Verge	Up to 1.5 Metres of Cover	50.00	0.30	A Permanent Reinstatement	15/04/2018		15/04/2018	

Effective: 13/10/2017 to 13/10/2018

Asset Number: 2000.00 to 2000.00

Display Action Officer: No

Site: Unwin Road (1218986)

Street Works Notices**Organisation:** Harlaxton Energy Networks (7342001)

Works Ref: 6860-EC2	Version: 7	Work Desc: excavation required in F/W & C/W for installation of mains / Link box and connection for new development via rd crossing. Approx F/W excavation meausremrnts 5m x 1m - Rd excavation approx 8m x 1m.
Notice Type: Registration of Reinstatement - Full	Start: 13/08/2018 00:00:00	
Work Status: Works Stopped	Issued: 10/09/2018 14:58:18	
Work Type: EToN 4: Standard	Est. End: 24/08/2018	Completion: 24/08/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	on Unwin Rd up from junction to ashcourt gardens	Carriageway	Up to 1.5 Metres of Cover	6.00	0.80	A Permanent Reinstatement	24/08/2018		24/08/2018	24/08/2018
2	on Unwin Rd up from junction to ashcourt gardens	Footway	Up to 1.5 Metres of Cover	7.00	2.00	A Permanent Reinstatement	24/08/2018		24/08/2018	

Works Ref: 6860-LB	Version: 3	Work Desc: excavation required in F/W for installation of link box and connection. Approx excavation required 5m x 1.5m. Pedestrian walkway to be installed.
Notice Type: Cancellation	Start: 13/08/2018 00:00:00	
Work Status: Abandoned Works	Issued: 06/08/2018 16:17:07	
Work Type: EToN 4: Standard	Est. End: 16/08/2018	Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	On Unwin road O/S existing 111 unwin road.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	13/08/2018			16/08/2018

Organisation: NCC - ASHFIELD (3055005) (NCC HIGHWAYS VIA)

Works Ref: 30102546	Version: 1	Work Desc: To widen the existing pedestrian refuge on Unwin Road at the mouth of the junction of Coxmoor Road
Notice Type: 10 Day Initial Notice	Start: 04/06/2018 00:00:00	
Work Status: Proposed Works	Issued: 16/05/2018 15:14:27	
Work Type: EToN 4: Standard	Est. End: 13/06/2018	Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	At the junction of Coxmoor Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	04/06/2018			13/06/2018

Organisation: NCC - MANSFIELD (3055003)

Works Ref: 30502283	Version: 1	Work Desc: Detection Loop repairs
Notice Type: 10 Day Initial Notice	Start: 25/06/2018 00:00:00	
Work Status: Proposed Works	Issued: 20/06/2018 16:30:57	
Work Type: EToN 4: Standard	Est. End: 06/07/2018	Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Unwin Road junction of Mansfield Raod sutton in ashfield	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	25/06/2018			06/07/2018

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: UNWIN	Version: 3	Work Desc: CW works
Notice Type: Works Stop	Start: 13/05/2018 00:00:00	
Work Status: Works Stopped	Issued: 15/05/2018 08:25:01	
Work Type: EToN 4: Minor	Est. End: 13/05/2018	Completion: 13/05/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	75 Unwin Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	13/05/2018			13/05/2018

Effective: 13/10/2017 to 13/10/2018

Asset Number: 2000.00 to 2000.00

Display Action Officer: No

Site: Unwin Road (1218986)

Street Works Notices**Organisation:** Virgin Media NATIONAL NOTICING (7160100)

Works Ref: /NEMRFI/CX00024797 **Version:** 4 **Work Desc:** APPROX 1M IN CARRIAGEWAY
Notice Type: Registration of Reinstatement - Full **Start:** 02/11/2017 00:00:00
Work Status: Works Stopped **Issued:** 17/11/2017 08:24:43
Work Type: EToN 4: Minor **Est. End:** 06/11/2017 **Completion:** 06/11/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 7	Verge	Up to 1.5 Metres of Cover	1.00	0.50	A Permanent Reinstatement	06/11/2017		06/11/2017	06/11/2017

Works Ref: /NEMRFI/CX00029187 **Version:** 4 **Work Desc:** lay 11m of duct in footway
Notice Type: Registration of Reinstatement - Full **Start:** 30/05/2018 00:00:00
Work Status: Works Stopped **Issued:** 14/06/2018 15:10:40
Work Type: EToN 4: Minor **Est. End:** 01/06/2018 **Completion:** 01/06/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	outside 20	Footway	Up to 1.5 Metres of Cover	15.50	0.30	A Permanent Reinstatement	01/06/2018		01/06/2018	31/05/2018

Works Ref: /NYNLRE/0315088 **Version:** 3 **Work Desc:** UNBLOCK TEE
Notice Type: Works Stop **Start:** 20/10/2017 00:00:00
Work Status: Works Stopped **Issued:** 21/10/2017 08:43:02
Work Type: EToN 4: Minor **Est. End:** 24/10/2017 **Completion:** 20/10/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 19	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	20/10/2017			23/10/2017

Works Ref: /NYNLRE/0317374 **Version:** 4 **Work Desc:** FIT NEW TEE
Notice Type: Registration of Reinstatement - Full **Start:** 08/02/2018 00:00:00
Work Status: Works Stopped **Issued:** 10/02/2018 09:03:59
Work Type: EToN 4: Minor **Est. End:** 12/02/2018 **Completion:** 09/02/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 47	Footway	Up to 1.5 Metres of Cover	0.40	0.50	A Permanent Reinstatement	09/02/2018		09/02/2018	09/02/2018

Works Ref: /NYNLRE/0319772A **Version:** 4 **Work Desc:** UNBLOCK DUCT
Notice Type: Registration of Reinstatement - Full **Start:** 25/05/2018 00:00:00
Work Status: Works Stopped **Issued:** 26/05/2018 09:31:03
Work Type: EToN 4: Minor **Est. End:** 30/05/2018 **Completion:** 25/05/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	SIDE OF 5 THE HILLOCKS	Footway	Up to 1.5 Metres of Cover	0.40	0.40	A Permanent Reinstatement	25/05/2018		25/05/2018	30/05/2018

Organisation: WPD 5131 Alferton (7011531)

Works Ref: M51310443462 **Version:** 3 **Work Desc:** Urgent excavation in highway to locate and repair LV cable fault.
Notice Type: Registration of Reinstatement - Full **Start:** 03/10/2018 23:42:00
Work Status: Works Stopped **Issued:** 23/10/2018 15:58:02
Work Type: EToN 4: Immediate - Urgent **Est. End:** 10/10/2018 **Completion:** 10/10/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Adjacent 12	Footway	Up to 1.5 Metres of Cover	4.30	1.00	A Permanent Reinstatement	10/10/2018		10/10/2018	10/10/2018

Effective: 13/10/2017 to 13/10/2018

Asset Number: 2000.00 to 2000.00

Display Action Officer: No

Site: Unwin Road (1218986)

Street Works Notices**Organisation:** WPD 5131 Alfreton (7011531)**Works Ref:** M51312024261**Version:** 6**Work Desc:** 2 joint holes in tarmac footway and 5m trenching in tarmac footway for under grounding cables**Notice Type:** Registration of Reinstatement - Full**Start:** 04/12/2017 00:00:00**Work Status:** Works Stopped**Issued:** 20/12/2017 11:05:35**Work Type:** EToN 4: Minor**Est. End:** 13/12/2017**Completion:** 13/12/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE NUMBER 117	Carriageway	Up to 1.5 Metres of Cover	12.50	0.30	A Permanent Reinstatement	12/12/2017		12/12/2017	06/12/2017
2	OUTSIDE NUMBER 117	Footway	Up to 1.5 Metres of Cover	3.50	1.10	A Permanent Reinstatement	12/12/2017		12/12/2017	
3	OUTSIDE NUMBER 117	Footway	Up to 1.5 Metres of Cover	2.30	1.00	A Permanent Reinstatement	12/12/2017		12/12/2017	
4	OUTSIDE NUMBER 117	Footway	Up to 1.5 Metres of Cover	1.50	0.50	A Permanent Reinstatement	12/12/2017		12/12/2017	
5	OUTSIDE NUMBER 117	Footway	Up to 1.5 Metres of Cover	1.50	0.50	A Permanent Reinstatement	12/12/2017		12/12/2017	