

Effective: 25/07/2018 to 23/09/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: John Street (2201361)

Street: John Street (2201361)

Locality: Worksop, Nottinghamshire

Area: Bassetlaw

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Street Section			<b>Area:</b> Bassetlaw	
<b>Batch:</b> 20326791 - Inspection Batch				<b>Route:</b> Bassetlaw Area 2 Mar Enh CW/F <sup>1</sup>			<b>Date:</b> 12/03/2019	
No actionable defects found								
<b>Batch:</b> 20325396 - Inspection Batch				<b>Route:</b> Adhoc Inspection			<b>Date:</b> 04/03/2019	
3602882	Bent pedestrian guardrail, that has been hit by a car. Please see attached photo.	04/03/2019	On John Street, Worksop, on the bend leading towards Crown Street and the Redlands Primary School	Guardrail Repairs	Internal		Committed	2706479
<b>Batch:</b> 20318060 - Inspection Batch				<b>Route:</b> Adhoc Inspection			<b>Date:</b> 10/01/2019	
3598016	Carriageway Potholes	10/01/2019	outside number 28 maked	CW Repairs-Bituminous	Internal		Committed	2701510

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Street Section		<b>Area:</b> Bassetlaw	
2674749	footpath profile erosion please see attached photos (FW Repairs-Bituminous)	opposite properties numbered from 124 to 106 marked	Category 3	Job Completed	20/03/2018	10/09/2018	Act. BASS/3901494
2701510	Carriageway Potholes (CW Repairs-Bituminous)	outside number 28 maked	Category 2	Job Completed	10/01/2019	11/01/2019	Act. BAS-AS/5105987
2706479	Bent pedestrian guardrail, that has been hit by a car. Please see attached photo. (Guardrail Repairs)	On John Street, Worksop, on the bend leading towards Crown Street and the Redlands Primary School	Category 2	Job Completed	04/03/2019	07/03/2019	Act. BASS/3903261

**Street Works Inspections**

Organisation: Cadent Gas EM (0010001) (Street Works Admin Team NG Gas)

Works Ref: 1000623568

<b>Group No:</b> 1	<b>Site No:</b> 2	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 14/05/2019 13:50:07
<b>Category:</b> Category C		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
		<b>Tel:</b> [REDACTED]	<b>Site Location:</b> O/S 94
<b>Insp. Notes:</b>			<b>Position:</b> Carriageway
<b>Defect Notes:</b>			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Site Post Code:</b>

Works Ref: 1000777769

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 15/04/2019 11:15:53
<b>Category:</b> Category B		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
		<b>Tel:</b> [REDACTED]	<b>Site Location:</b> 59
<b>Insp. Notes:</b>			<b>Position:</b> Carriageway
<b>Defect Notes:</b>			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Site Post Code:</b>

Effective: 25/07/2018 to 23/09/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: John Street (2201361)

**Street Works Notices****Organisation:** Cadent Gas EM (0010001) (Street Works Admin Team NG Gas)**Works Ref:** 1000777769**Version:** 5**Work Desc:** LAY NEW DOMESTIC SERVICE 3M FROM MAIN IN FOOTWAY**Notice Type:** Registration of Reinstatement - Full**Start:** 14/12/2018 00:00:00**Work Status:** Works Stopped**Issued:** 19/12/2018 08:55:57**Work Type:** EToN 4: Standard**Est. End:** 19/12/2018**Completion:** 18/12/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	59	Carriageway	Up to 1.5 Metres of Cover	1.40	0.60	A Permanent Reinstatement	17/12/2018		17/12/2018	19/12/2018
2	59	Footway	Up to 1.5 Metres of Cover	1.40	0.40	A Permanent Reinstatement	17/12/2018		17/12/2018	

**Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** 2674749**Version:** 3**Work Desc:** Repairs to footpath erosion**Notice Type:** Works Stop**Start:** 05/09/2018 00:00:00**Work Status:** Works Stopped**Issued:** 12/09/2018 11:33:53**Work Type:** EToN 4: Standard**Est. End:** 14/09/2018**Completion:** 10/09/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside numbers 106 -124	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	10/09/2018			14/09/2018

**Organisation:** WPD 5136 Retford (7011536)**Works Ref:** M51360454222**Version:** 3**Work Desc:** Urgent excavation in highway to locate and repair LV cable fault.**Notice Type:** Registration of Reinstatement - Full**Start:** 21/01/2019 11:30:00**Work Status:** Works Stopped**Issued:** 18/02/2019 15:17:10**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 28/01/2019**Completion:** 28/01/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside 5	Footway	Up to 1.5 Metres of Cover	2.60	1.35	A Permanent Reinstatement	28/01/2019		28/01/2019	28/01/2019