

Effective: 03/01/2019 to 03/01/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Great North Road (26805775)

Street: Great North Road (26805775)

Locality: South Muskham, Nottinghamshire

Area: Newark

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,001.00	Feature Id - Locn.:	B6325 - South Muskham	Feature Type: Street Section			Area: Newark	
Batch: 20368828 - Inspection Batch				Route: Adhoc Inspection			Date: 16/12/2019	
3627670	potholes marked in yellow	16/12/2019	from layby to 30mph sign	CW Repairs-Bituminous	Internal		Committed	2731400
Batch: 20367987 - Inspection Batch				Route: Adhoc Inspection			Date: 11/12/2019	
3627242	potholes marked in yellow	11/12/2019	100m from 30mph sign	CW Repairs-Bituminous	Internal		Committed	2730970
Batch: 20367984 - Inspection Batch				Route: Adhoc Inspection			Date: 11/12/2019	
3627239	potholes marked in yellow	11/12/2019	adj to layby	CW Repairs-Bituminous	Internal		Committed	2730967
Batch: 20366929 - Inspection Batch				Route: Newark Area 1 Dec Saf CW			Date: 05/12/2019	
No actionable defects found								
Batch: 20365759 - Inspection Batch				Route: Adhoc Inspection			Date: 29/11/2019	
3626065	potholes	29/11/2019	on bend	CW Repairs-Bituminous	Internal		Uncommitted	2729791
Batch: 20365758 - Inspection Batch				Route: Adhoc Inspection			Date: 29/11/2019	
3626064	potholes marked	29/11/2019	form layby to 30mph sign	CW Repairs-Bituminous	Internal		Committed	2729790
Batch: 20365753 - Inspection Batch				Route: Adhoc Inspection			Date: 29/11/2019	
3626062	potholes marked	29/11/2019	adj to layby	CW Repairs-Bituminous	Internal		Committed	2729788
Batch: 20365746 - Inspection Batch				Route: Adhoc Inspection			Date: 29/11/2019	
3626057	potholes fwf	29/11/2019	100m from A1 roundabout	CW Repairs-Bituminous	Internal		Uncommitted	2729783
Batch: 20364836 - Inspection Batch				Route: Adhoc Inspection			Date: 26/11/2019	
3625686	potholes marked	26/11/2019	100m before 30mph sign	CW Repairs-Bituminous	Internal		Committed	2729410
3625685	potholes marked	26/11/2019	adj. to layby	CW Repairs-Bituminous	Internal		Committed	2729411
Batch: 20364104 - Inspection Batch				Route: Adhoc Inspection			Date: 21/11/2019	
3625271	potholes	21/11/2019	between 30 mph sign going out of village to north muskham	CW Repairs-Bituminous	Internal		Uncommitted	2728996
Batch: 20363229 - Inspection Batch				Route: Newark Area 1 Nov Saf CW			Date: 14/11/2019	
3624677	potholes marked	14/11/2019	between layby & 30mph sign	CW Repairs-Bituminous	Internal		Uncommitted	2728402
3624678	pothole marked	14/11/2019	adj layby	CW Repairs-Bituminous	Internal		Uncommitted	2728401
Batch: 20362713 - Inspection Batch				Route: Adhoc Inspection			Date: 11/11/2019	
3624361	Carriageway Pothole - Road Pothole - Potholes . Online report Customer title is [REDACTED] (Enquiry 6145191)	11/11/2019	On north bound carriageway x2 potholes Between the national speed limit and the bend to the right heading north.	CW Repairs-Bituminous	Internal		Uncommitted	2728085
3624362	Carriageway Pothole - Road Pothole - Potholes . Online report Customer title is [REDACTED] (Enquiry 6145191)	11/11/2019	On north bound carriageway x2 potholes Between the national speed limit and the bend to the right heading north.	CW Repairs-Bituminous	Internal		Uncommitted	2728084
Batch: 20362041 - Inspection Batch				Route: Adhoc Inspection			Date: 06/11/2019	
3623963	Carriageway Pothole - Road Pothole - Pot hole . Online report Customer title is [REDACTED] (Enquiry 6144159)	06/11/2019	Inside village boundary this time	CW Repairs-Bituminous	Internal		Uncommitted	2727683

Effective: 03/01/2019 to 03/01/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Great North Road (26805775)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,001.00	Feature Id - Locn.: B6325 - South Muskham			Feature Type: Street Section			Area: Newark	
Batch: 20359740 - Inspection Batch				Route: Adhoc Inspection				Date: 18/10/2019
3622762	potholes photos attached	18/10/2019	75m & 150m from south muskham sign	CW Repairs-Bituminous	Internal		Uncommitted	2726475
Batch: 20359513 - Inspection Batch				Route: Adhoc Inspection				Date: 16/10/2019
3622597		16/10/2019	as mapped jst before bend	CW Repairs-Bituminous	Internal		Uncommitted	2726310
Batch: 20359512 - Inspection Batch				Route: Adhoc Inspection				Date: 16/10/2019
3622595	potholes	16/10/2019	as marked on bend	CW Repairs-Bituminous	Internal		Uncommitted	2726308
Batch: 20357741 - Inspection Batch				Route: Newark Area 1 Oct Saf CW				Date: 07/10/2019
3621660	pothole marked	07/10/2019	just after layby towards newalk	CW Repairs-Bituminous	Internal		Uncommitted	2725368
Batch: 20355115 - Inspection Batch				Route: Newark Area 1 Sep Saf CW				Date: 17/09/2019
	No actionable defects found							
Batch: 20350578 - Inspection Batch				Route: Newark Area 1 Aug Saf CW				Date: 16/08/2019
3618199	potholes	16/08/2019	near 30mph signs marked	CW Repairs-Bituminous	Internal		Committed	2721887
Batch: 20347219 - Inspection Batch				Route: Newark Area 1 Jul Saf CW				Date: 23/07/2019
	No actionable defects found							
Batch: 20343206 - Inspection Batch				Route: Adhoc Inspection				Date: 24/06/2019
3614055	Carriageway Potholes	24/06/2019	north bound heading to north muskham on the right just before laybye on the left marked in white paint	CW Repairs-Bituminous	Internal		Committed	2717727
Batch: 20342364 - Inspection Batch				Route: Newark Area 1 Jun Saf CW				Date: 20/06/2019
	No actionable defects found							
Batch: 20341916 - Inspection Batch				Route: Adhoc Inspection				Date: 19/06/2019
3613473	potholes	19/06/2019	south muskham to north muskham 80 m before north muskham sign left side and right side marked in white paint	CW Repairs-Bituminous	Internal		Committed	2717144
Batch: 20341135 - Inspection Batch				Route: Adhoc Inspection				Date: 13/06/2019
3612897	Carriageway Potholes	13/06/2019	from lamp column number 4 heading out the village to north muskham marked in white paint	CW Repairs-Bituminous	Internal		Committed	2716568
Batch: 20337054 - Inspection Batch				Route: Adhoc Inspection				Date: 22/05/2019
3610850	Carriageway Pothole	22/05/2019	opp lc no 5 marked	CW Repairs-Bituminous	Internal		Committed	2714510
Batch: 20334837 - Inspection Batch				Route: Newark Area 1 May Enh CW/FW				Date: 03/05/2019
3609152	pothole in footway	03/05/2019	northbound just before right hand laybye before north muskham sign marked in yellow paint	FW Repairs-Bituminous	Internal		Committed	2712810
Batch: 20331947 - Inspection Batch				Route: Newark Area 1 Apr Saf CW				Date: 16/04/2019
	No actionable defects found							

Effective: 03/01/2019 to 03/01/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Great North Road (26805775)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,001.00	Feature Id - Locn.: B6325 - South Muskham			Feature Type: Street Section			Area: Newark	
Batch: 20328757 - Inspection Batch				Route: Adhoc Inspection				Date: 25/03/2019
3605156	Carriageway pothole	25/03/2019	near lamp column number 3 there is a post box pothole is at side of manhole causing raised edge marked in white paint	CW Repairs-Bituminous	Internal		Committed	2708778
Batch: 20326961 - Inspection Batch				Route: Adhoc Inspection				Date: 13/03/2019
3603920	Carriageway Potholes	13/03/2019	On leaving South Muskham towards North Muskham immediately before the speed delimit signs. opposite lamp column number 5 , and then 100 m forward all marked in white paint heading to north muskham	CW Repairs-Bituminous	Internal		Committed	2707532
Batch: 20326057 - Inspection Batch				Route: Newark Area 1 Mar Saf CW				Date: 06/03/2019
3603270	pothole filled during inspection L. 2 m x W. 400 mm x D. 60 mm	06/03/2019	edge of laybye	CW Repairs-Bituminous	Internal		Committed	2706875
3603269	pothole	06/03/2019	opposite laybye just before north muskham sign north bound , south bound heading to south muskham just before first splitter island	CW Repairs-Bituminous	Internal		Committed	2706874
3603268	potholes filled during inspection near refuge island	06/03/2019	opposite lamp column number 5	CW Repairs-Bituminous	Internal		Committed	2706873
3603271	pothole	06/03/2019	near fire hydrant at south muskham approach yo mini round a bout	CW Repairs-Bituminous	Internal		Committed	2706872
Batch: 20325373 - Inspection Batch				Route: Adhoc Inspection				Date: 01/03/2019
3602863	pothole	01/03/2019	opposite mill lane on right bend before railway bridge to north muskham . marked in white	CW Repairs-Bituminous	Internal		Committed	2706458
Batch: 20323375 - Inspection Batch				Route: Newark Area 1 Feb Saf CW				Date: 18/02/2019
No actionable defects found								
Batch: 20323074 - Inspection Batch				Route: Adhoc Inspection				Date: 14/02/2019
3601368	Carriageway Pothole filled during inspection ,L. 950 x W 450 x D 30 mm photo's attached	14/02/2019	Just leaving village near village sign	CW Repairs-Bituminous	Internal		Uncommitted	2704937
Batch: 20319779 - Inspection Batch				Route: Newark Area 1 Jan Saf CW				Date: 22/01/2019
3599031	potholes	22/01/2019	past salvage place just before refuge island opposite lamp column number 5 marked in white paint	CW Repairs-Bituminous	Internal		Committed	2702552

Effective: 03/01/2019 to 03/01/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Great North Road (26805775)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,001.00	Feature Id - Locn.:	B6325 - South Muskham	Feature Type:	Street Section	Area:	Newark
2702552	potholes (CW Repairs-Bituminous)	past salvage place just before refuge island opposite lamp column number 5 marked in white paint	Category 2	Repair Completed	22/01/2019	24/01/2019	Act. NEW-AS/5507953
2704937	Carriageway Pothole filled during inspection .L. 950 x W 450 x D 30 mm photo's attached (CW Repairs-Bituminous)	Just leaving village near village sign	Filled when found (Cat 2)	Job Completed	14/02/2019	14/02/2019	Act.
2706458	pothole (CW Repairs-Bituminous)	opposite mill lane on right bend before railway bridge to north muskham . marked in white	Category 2	Repair Completed	01/03/2019	04/03/2019	Act. NEW-AS/5508236
2706872	pothole (CW Repairs-Bituminous)	near fire hydrant at south muskham approach yo mini round a bout	Filled when found (Cat 2)	Job Completed	06/03/2019	06/03/2019	Act. NEW-AS/5508270
2706873	potholes filled during inspection near refuge island (CW Repairs-Bituminous)	opposite lamp column number 5	Filled when found (Cat 2)	Job Completed	06/03/2019	06/03/2019	Act. NEW-AS/5508269
2706874	pothole (CW Repairs-Bituminous)	opposite laybye just before north muskham sign north bound , south bound heading to south muskham just before first splitter island	Filled when found (Cat 2)	Job Completed	06/03/2019	06/03/2019	Act. NEW-AS/5508268
2706875	pothole filled during inspection L. 2 m x W. 400 mm x D. 60 mm (CW Repairs-Bituminous)	edge of laybye	Filled when found (Cat 1)	Job Completed	06/03/2019	06/03/2019	Act. NEW-AS/5508267
2707532	Carriageway Potholes (CW Repairs-Bituminous)	On leaving South Muskham towards North Muskham immediately before the speed delimit signs. opposite lamp column number 5 , and then 100 m forward all marked in white paint heading to north muskham	Category 2	Repair Completed	13/03/2019	15/03/2019	Act. NEW-AS/5508315
2708778	Carriageway pothole (CW Repairs-Bituminous)	near lamp column number 3 there is a post box pothole is at side of manhole causing raised edge marked in white paint	Category 2	Repair Completed	25/03/2019	28/03/2019	Act. NEW-AS/5508456
2712810	pothole in footway (FW Repairs-Bituminous)	northbound just before right hand laybye before north muskham sign marked in yellow paint	Category 3	Job Completed	03/05/2019	31/05/2019	Act. NEW/3614419
2714510	Carriageway Pothole (CW Repairs-Bituminous)	opp lc no 5 marked	Category 2	Repair Completed	22/05/2019	23/05/2019	Act. NEW-AS/5508999
2716568	Carriageway Potholes (CW Repairs-Bituminous)	from lamp column number 4 heading out the village to north muskham marked in white paint	Category 2	Repair Completed	13/06/2019	17/06/2019	Act. NEW-AS/5509170

Effective: 03/01/2019 to 03/01/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Great North Road (26805775)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,001.00	Feature Id - Locn.:	B6325 - South Muskham	Feature Type:	Street Section	Area:	Newark
2717144	potholes (CW Repairs-Bituminous)	south muskham to north muskham 80 m before north muskham sign left side and right side marked in white paint	Category 2	Job Completed	19/06/2019	20/06/2019	Act. NEW-AS/5509204
2717727	Carriageway Potholes (CW Repairs-Bituminous)	north bound heading to north muskham on the right just before laybye on the left marked in white paint	Category 2	Repair Completed	24/06/2019	02/07/2019	Act. NEW-AS/5509239
2721887	potholes (CW Repairs-Bituminous)	near 30mph signs marked	Category 2	Repair Completed	16/08/2019	20/08/2019	Act. NEW-AS/5509632
2725368	pothole marked (CW Repairs-Bituminous)	just after layby towards newalk	Category 2	Repair Completed	07/10/2019	29/10/2019	Act. NEW-AS/5510129
2726308	potholes (CW Repairs-Bituminous)	as marked on bend	Category 2	Repair Completed	16/10/2019	29/10/2019	Act.
2726310	CW Repairs-Bituminous	as mapped jst before bend	Category 2	Repair Completed	16/10/2019	29/10/2019	Act.
2726475	potholes photos attached (CW Repairs-Bituminous)	75m & 150m from south muskham sign	Category 2	Repair Completed	18/10/2019	29/10/2019	Act.
2727683	Carriageway Pothole - Road Pothole - Pot hole . Online report Customer title is [REDACTED] (Enquiry 6144159) (CW Repairs-Bituminous)	Inside village boundary this time	Filled when found (Cat 2)	Job Completed	06/11/2019	07/11/2019	Act.
2728084	Carriageway Pothole - Road Pothole - Potholes . Online report Customer title is [REDACTED] (Enquiry 6145191) (CW Repairs-Bituminous)	On north bound carriageway x2 potholes Between the national speed limit and the bend to the right heading north.	Filled when found (Cat 2)	Job Completed	12/11/2019	11/11/2019	Act.
2728085	Carriageway Pothole - Road Pothole - Potholes . Online report Customer title is [REDACTED] (Enquiry 6145191) (CW Repairs-Bituminous)	On north bound carriageway x2 potholes Between the national speed limit and the bend to the right heading north.	Filled when found (Cat 2)	Job Completed	12/11/2019	11/11/2019	Act.
2728401	pothole marked (CW Repairs-Bituminous)	adj layby	Category 2	Repair Completed	14/11/2019	21/11/2019	Act.
2728402	potholes marked (CW Repairs-Bituminous)	between layby & 30mph sign	Category 2	Repair Completed	14/11/2019	21/11/2019	Act.
2728996	potholes (CW Repairs-Bituminous)	between 30 mph sign going out of village to north muskham	Filled when found (Cat 2)	Job Completed	21/11/2019	21/11/2019	Act.
2729410	potholes marked (CW Repairs-Bituminous)	100m before 30mph sign	Category 2	Job Completed	26/11/2019	04/12/2019	Act. NEW/3615603
2729411	potholes marked (CW Repairs-Bituminous)	adj. to layby	Category 2	Job Completed	26/11/2019	04/12/2019	Act. NEW/3615601
2729783	potholes fwf (CW Repairs-Bituminous)	100m from A1 roundabout	Filled when found (Cat 2)	Job Completed	29/11/2019	29/11/2019	Act.
2729788	potholes marked (CW Repairs-Bituminous)	adj to layby	Category 2	Job Completed	29/11/2019	04/12/2019	Act. NEW/3615620

Effective: 03/01/2019 to 03/01/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Great North Road (26805775)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,001.00	Feature Id - Locn.: B6325 - South Muskham		Feature Type: Street Section		Area: Newark	
2729790	potholes marked (CW Repairs-Bituminous)	form layby to 30mph sign	Category 2	Job Completed	29/11/2019	04/12/2019	Act. NEW/3615619
2729791	potholes (CW Repairs-Bituminous)	on bend	Filled when found (Cat 2)	Job Completed	29/11/2019	29/11/2019	Act.
2730967	potholes marked in yellow (CW Repairs-Bituminous)	adj to layby	Category 2	Works Order Printed	11/12/2019	08/01/2020	Est. NEW/3615678
2730970	potholes marked in yellow (CW Repairs-Bituminous)	100m from 30mph sign	Category 2	Works Order Printed	11/12/2019	08/01/2020	Est. NEW/3615679
2731400	potholes marked in yellow (CW Repairs-Bituminous)	from layby to 30mph sign	Category 2	Job Completed	16/12/2019	27/12/2019	Act. NEW/3615713