

Effective: 03/01/2019 to 03/01/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Great North Road (26822191)

Street: Great North Road (26822191)

Locality: Bathley, Nottinghamshire

Area: Newark

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> B6325 - A1 Roundabout, North Muskham To Junction With Moo			<b>Feature Type:</b> Street Sect on			<b>Area:</b> Newark	
<b>Batch:</b> 20368824 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 16/12/2019
3627667	potholes marked in yellow	16/12/2019	adj mill ln	CW Repairs-Bituminous	Internal		Committed	2731397
<b>Batch:</b> 20368821 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 16/12/2019
3627664	potholes marked in yellow	16/12/2019	adj to bridge	CW Repairs-Bituminous	Internal		Committed	2731394
<b>Batch:</b> 20368820 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 16/12/2019
3627663	potholes marked in yellow	16/12/2019	50m from roundabout	CW Repairs-Bituminous	Internal		Committed	2731393
<b>Batch:</b> 20368817 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 16/12/2019
3627660	pothole fwf 1000x550x73	16/12/2019	50m from roundabout	CW Repairs-Bituminous	Internal		Uncommitted	2731390
<b>Batch:</b> 20367982 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 11/12/2019
3627237	potholes marked in yellow	11/12/2019	on bend adj mill ln	CW Repairs-Bituminous	Internal		Committed	2730965
<b>Batch:</b> 20367981 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 11/12/2019
3627236	potholes marked in yellow	11/12/2019	100m from A1 roundabout	CW Repairs-Bituminous	Internal		Committed	2730964
<b>Batch:</b> 20366930 - Inspection Batch				<b>Route:</b> Newark Area 1 Dec Saf CW				<b>Date:</b> 05/12/2019
	No actionable defects found							
<b>Batch:</b> 20365760 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 29/11/2019
3626066	potholes fwf	29/11/2019	on bridge deck	CW Repairs-Bituminous	Internal		Uncommitted	2729792
<b>Batch:</b> 20365446 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 27/11/2019
3625887	pothole marked	27/11/2019	adj to bridge deck	CW Repairs-Bituminous	Internal		Uncommitted	2729612
<b>Batch:</b> 20365445 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 27/11/2019
3625886	potholes marked	27/11/2019	100m from roundabout	CW Repairs-Bituminous	Internal		Uncommitted	2729611
<b>Batch:</b> 20364114 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 21/11/2019
3625276	potholes	21/11/2019	adj to old tipping depot north heading south	CW Repairs-Bituminous	Internal		Uncommitted	2729001
<b>Batch:</b> 20363497 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 15/11/2019
3624800	potholes marked	15/11/2019	between A1 roundabout and 30mph sign	CW Repairs-Bituminous	Internal		Committed	2728525
3624802	pothole	15/11/2019	100m before bridge	CW Repairs-Bituminous	Internal		Uncommitted	2728524
3624801	pothol	15/11/2019	100m past bridge	CW Repairs-Bituminous	Internal		Uncommitted	2728526
<b>Batch:</b> 20363227 - Inspection Batch				<b>Route:</b> Newark Area 1 Nov Saf CW				<b>Date:</b> 14/11/2019
3624675	pothole	14/11/2019	adj mill ln	CW Repairs-Bituminous	Internal		Uncommitted	2728398
3624674	pothole marked	14/11/2019	adj mill ln	CW Repairs-Bituminous	Internal		Uncommitted	2728399
<b>Batch:</b> 20362355 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 08/11/2019
3624131	potholes	08/11/2019	adj motor value	CW Repairs-Bituminous	Internal		Uncommitted	2727854
<b>Batch:</b> 20361207 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 30/10/2019
3623562	pothole	30/10/2019	A1 side of bridge	CW Repairs-Bituminous	Internal		Uncommitted	2727280
3623561	potholes	30/10/2019	just before 30 MPH sign	CW Repairs-Bituminous	Internal		Uncommitted	2727282
3623560	pothole	30/10/2019	adj. to layby	CW Repairs-Bituminous	Internal		Uncommitted	2727281

Effective: 03/01/2019 to 03/01/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Great North Road (26822191)

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> B6325 - A1 Roundabout, North Muskham To Junction With Moo			<b>Feature Type:</b> Street Sect on			<b>Area:</b> Newark	
<b>Batch:</b> 20357742 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Oct Saf CW				<b>Date:</b> 07/10/2019
<b>Batch:</b> 20355116 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Sep Saf CW				<b>Date:</b> 17/09/2019
<b>Batch:</b> 20350577 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Aug Saf CW				<b>Date:</b> 16/08/2019
<b>Batch:</b> 20347220 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Jul Saf CW				<b>Date:</b> 23/07/2019
<b>Batch:</b> 20342366 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Jun Saf CW				<b>Date:</b> 20/06/2019
<b>Batch:</b> 20341915 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 19/06/2019
3613472	pothole 1 m x 1 m x 70 mm	19/06/2019	near mill lane junction to timber yard	CW Repairs-Bituminous	Internal		Uncommitted	2717143
<b>Batch:</b> 20334838 - Inspection Batch				<b>Route:</b> Newark Area 1 May Enh CW/FW				<b>Date:</b> 03/05/2019
3609153	potholes	03/05/2019	junction area going into car sales and up to the far end weregarage is before going over railway bridge marked in yellow paint	CW Repairs-Bituminous	Internal		Committed	2712811
<b>Batch:</b> 20331948 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Apr Saf CW				<b>Date:</b> 16/04/2019
<b>Batch:</b> 20328397 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 21/03/2019
3604967	Carriageway Pothole filled during inspection L 300 x W 300 x D 40 mm	21/03/2019	Inbetween roundabout and bridge	CW Repairs-Bituminous	Internal		Uncommitted	2708589
<b>Batch:</b> 20326058 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Mar Saf CW				<b>Date:</b> 06/03/2019
<b>Batch:</b> 20323379 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Feb Saf CW				<b>Date:</b> 18/02/2019
<b>Batch:</b> 20319780 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 1 Jan Saf CW				<b>Date:</b> 22/01/2019

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> B6325 - A1 Roundabout, North Muskham To Junction With Moo			<b>Feature Type:</b> Street Section			<b>Area:</b> Newark
2697757	re new post and rail . 8 posts and tubing stats requested (Other)	north muskham roundabout opposite old recycle depot	Category 3	Job Completed	21/11/2018	15/02/2019	Act. NEW/3612415
2708589	Carriageway Pothole filled during inspection L 300 x W 300 x D 40 mm (CW Repairs-Bituminous)	Inbetween roundabout and bridge	Filled when found (Cat 1)	Job Completed	21/03/2019	21/03/2019	Act.

Effective: 03/01/2019 to 03/01/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Great North Road (26822191)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:	B6325 - A1 Roundabout, North Muskhams To Junction With Moo	Feature Type:	Street Section	Area:	Newark
2712811	potholes (CW Repairs-Bituminous)	junction area going into car sales and up to the far end weregarage is before going over railway bridge marked in yellow paint	Category 3	Job Completed	03/05/2019	28/05/2019	Act. NEW/3614420
2717143	pothole 1 m x 1 m x 70 mm (CW Repairs-Bituminous)	near mill lane junction to timber yard	Filled when found (Cat 1)	Job Completed	19/06/2019	19/06/2019	Act.
2727280	pothole (CW Repairs-Bituminous)	A1 side of bridge	Category 2	Repair Completed	30/10/2019	06/11/2019	Act.
2727281	pothole (CW Repairs-Bituminous)	adj. to layby	Category 2	Repair Completed	30/10/2019	06/11/2019	Act.
2727282	potholes (CW Repairs-Bituminous)	just before 30 MPH sign	Category 2	Repair Completed	30/10/2019	06/11/2019	Act.
2727854	potholes (CW Repairs-Bituminous)	adj motor value	Filled when found (Cat 1)	Job Completed	08/11/2019	08/11/2019	Act.
2728398	pothole (CW Repairs-Bituminous)	adj mill ln	Filled when found (Cat 2)	Job Completed	14/11/2019	14/11/2019	Act.
2728399	pothole marked (CW Repairs-Bituminous)	adj mill ln	Category 2	Repair Completed	14/11/2019	21/11/2019	Act.
2728524	pothole (CW Repairs-Bituminous)	100m before bridge	Filled when found (Cat 1)	Job Completed	15/11/2019	15/11/2019	Act.
2728525	potholes marked (CW Repairs-Bituminous)	between A1 roundabout and 30mph sign	Category 2	Job Completed	15/11/2019	04/12/2019	Act. NEW/3615577
2728526	pothol (CW Repairs-Bituminous)	100m past bridge	Filled when found (Cat 1)	Job Completed	15/11/2019	15/11/2019	Act.
2729001	potholes (CW Repairs-Bituminous)	adj to old tipping depot north heading south	Filled when found (Cat 2)	Job Completed	21/11/2019	21/11/2019	Act.
2729611	potholes marked (CW Repairs-Bituminous)	100m from roundabout	Category 2	Repair Completed	27/11/2019	02/12/2019	Act.
2729612	pothole marked (CW Repairs-Bituminous)	adj to bridge deck	Category 2	Repair Completed	27/11/2019	02/12/2019	Act.
2729792	potholes fwf (CW Repairs-Bituminous)	on bridge deck	Filled when found (Cat 2)	Job Completed	29/11/2019	29/11/2019	Act.
2730964	potholes marked in yellow (CW Repairs-Bituminous)	100m from A1 roundabout	Category 2	Works Order Printed	11/12/2019	08/01/2020	Est. NEW/3615676
2730965	potholes marked in yellow (CW Repairs-Bituminous)	on bend adj mill ln	Category 2	Works Order Printed	11/12/2019	08/01/2020	Est. NEW/3615677
2731390	pothole fwf 1000x550x73 (CW Repairs-Bituminous)	50m from roundabout	Filled when found (Cat 1)	Job Completed	16/12/2019	16/12/2019	Act.
2731393	potholes marked in yellow (CW Repairs-Bituminous)	50m from roundabout	Category 2	Job Completed	16/12/2019	27/12/2019	Act. NEW/3615710
2731394	potholes marked in yellow (CW Repairs-Bituminous)	adj to bridge	Category 2	Job Completed	16/12/2019	27/12/2019	Act. NEW/3615711
2731397	potholes marked in yellow (CW Repairs-Bituminous)	adj mill ln	Category 2	Job Completed	16/12/2019	27/12/2019	Act. NEW/3615712