

Effective: 23/12/2018 to 23/12/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Fiskerton Road (26806051)

Street: Fiskerton Road (26806051)

Locality: Rolleston, Nottinghamshire

Area: Newark

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: C17 - Stream Crossing (By Fiskerton Mill Access Road) To Stay			Feature Type: Street Section			Area: Newark	
Batch: 20369365 - Inspection Batch				Route: Adhoc Inspection				Date: 18/12/2019
3628041	potholes	18/12/2019	between chilli bobs and the rolleston sign marked	CW Repairs-Bituminous	Internal		Committed	2731771
Batch: 20367245 - Inspection Batch				Route: Newark Area 2 Dec Saf CW				Date: 06/12/2019
3626911	potholes	06/12/2019	near lc 8 marked	CW Repairs-Bituminous	Internal		Uncommitted	2730638
3626909	pothole	06/12/2019	near lc 5 marked	CW Repairs-Bituminous	Internal		Uncommitted	2730639
3626910	pothole	06/12/2019	50 meters after leaving rolleston marked	CW Repairs-Bituminous	Internal		Uncommitted	2730640
Batch: 20366634 - Inspection Batch				Route: Adhoc Inspection				Date: 04/12/2019
3626563	pothole	04/12/2019	just past chilibobs heading into rolleston marked	CW Repairs-Bituminous	Internal		Uncommitted	2730291
Batch: 20364636 - Inspection Batch				Route: Newark Area 2 Nov Enh CW/FW				Date: 25/11/2019
No actionable defects found								
Batch: 20364456 - Inspection Batch				Route: Adhoc Inspection				Date: 25/11/2019
3625551	pothole cat 1 filled when found . L. 500 mm x W. 450 mm x D. 60 mm . photo's attached .	25/11/2019	just before 30 mph signage coming into village	CW Repairs-Bituminous	Internal		Uncommitted	2729276
Batch: 20364342 - Inspection Batch				Route: Adhoc Inspection				Date: 22/11/2019
3625471	Carriageway Pothole	22/11/2019	next to the public bridleway sign marked	CW Repairs-Bituminous	Internal		Uncommitted	2729196
Batch: 20364341 - Inspection Batch				Route: Adhoc Inspection				Date: 22/11/2019
3625470	pothole	22/11/2019	next to the public bridleway sign marked.	Other	Internal		Uncommitted	2729195
Batch: 20362508 - Inspection Batch				Route: Adhoc Inspection				Date: 08/11/2019
3624213	potholes	08/11/2019	nr lc 2 marked	CW Repairs-Bituminous	Internal		Uncommitted	2727936
Batch: 20362506 - Inspection Batch				Route: Adhoc Inspection				Date: 08/11/2019
3624211	all sides all the way up need filling in..aprox 1ton of tarmac..	08/11/2019	from the chili farm on fiskerton road upto the bridge over the dyke..	CW Repairs-Bituminous	Internal		Committed	2727934
Batch: 20357511 - Inspection Batch				Route: Newark Area 2 Oct Saf CW				Date: 04/10/2019
No actionable defects found								
Batch: 20353399 - Inspection Batch				Route: Newark Area 2 Sep Saf CW				Date: 05/09/2019
No actionable defects found								
Batch: 20350585 - Inspection Batch				Route: Newark Area 2 Aug Saf CW				Date: 16/08/2019
3618202	pothole	16/08/2019	near culvert marked	CW Repairs-Bituminous	Internal		Committed	2721890
Batch: 20346651 - Inspection Batch				Route: Newark Area 2 Jul Saf CW				Date: 17/07/2019
No actionable defects found								
Batch: 20343811 - Inspection Batch				Route: Newark Area 3 Jun Saf CW				Date: 26/06/2019
3614301	potholes	26/06/2019	near 30mph signs filled when found	CW Repairs-Bituminous	Internal		Uncommitted	2717971

Effective: 23/12/2018 to 23/12/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Fiskerton Road (26806051)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: C17 - Stream Crossing (By Fiskerton Mill Access Road) To Stay			Feature Type: Street Section			Area: Newark	
Batch: 20343811 - Inspection Batch				Route: Newark Area 3 Jun Saf CW				Date: 26/06/2019
3614300	potholes	26/06/2019	from chilly bobs to culvert filled when found	CW Repairs-Bituminous	Internal		Uncommitted	2717973
3614299	pothole	26/06/2019	near chilly bobs filled when found	CW Repairs-Bituminous	Internal		Uncommitted	2717972
Batch: 20334748 - Inspection Batch				Route: Newark Area 3 May Saf CW				Date: 03/05/2019
3609081	pothole	03/05/2019	passed chilli bobs, just before rolleston sign marked	CW Repairs-Bituminous	Internal		Committed	2712737
3609080	pothole	03/05/2019	just after chill bobs heading away from rolleston, marked	CW Repairs-Bituminous	Internal		Committed	2712738
Batch: 20329963 - Inspection Batch				Route: Adhoc Inspection				Date: 03/04/2019
3605887	pothole	03/04/2019	near sign for rolleston, marked white	CW Repairs-Bituminous	Internal		Committed	2709515
Batch: 20329962 - Inspection Batch				Route: Adhoc Inspection				Date: 03/04/2019
3605886	pothole	03/04/2019	between lc2&3, marked white	CW Repairs-Bituminous	Internal		Committed	2709514
Batch: 20329961 - Inspection Batch				Route: Adhoc Inspection				Date: 03/04/2019
3605885	pothole	03/04/2019	approx 150yds from speed limit sign, opo bus stop, before bend, marked wite	CW Repairs-Bituminous	Internal		Committed	2709513
Batch: 20327694 - Inspection Batch				Route: Adhoc Inspection				Date: 19/03/2019
3604545	potholes	19/03/2019	just after bend near bridleway heading to fiskerton marked white	CW Repairs-Bituminous	Internal		Committed	2708162
Batch: 20323333 - Inspection Batch				Route: Adhoc Inspection				Date: 18/02/2019
3601626	fill potholes with stone, some quite large (width)	18/02/2019	os chilly bobs on road just off bend, marked yellow	CW Repairs-Bituminous	Internal		Committed	2705198
Batch: 20321690 - Inspection Batch				Route: Newark Area 3 Feb Saf CW				Date: 05/02/2019
3600316	potholes	05/02/2019	os and opp springfield, near speed limit signs, marked white	CW Repairs-Bituminous	Internal		Committed	2703864
3600315	pothole	05/02/2019	opp comer farm close, marked white	CW Repairs-Bituminous	Internal		Committed	2703865
Batch: 20318277 - Inspection Batch				Route: Adhoc Inspection				Date: 14/01/2019
3598197	potholes	14/01/2019	heading from rolleston towards fiskerton, just after farm entrance, before bridge, marked white	CW Repairs-Bituminous	Internal		Committed	2701694

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 2,000.00	Feature Id - Locn.: C17 - Stream Crossing (By Fiskerton Mill Access Road) To Stay			Feature Type: Street Section			Area: Newark
2701694	potholes (CW Repairs-Bituminous)	heading from rolleston towards fiskerton, just after farm entrance, before bridge, marked white	Category 2	Repair Completed	14/01/2019	21/01/2019	Act. NEW-AS/5507864
2703864	potholes (CW Repairs-Bituminous)	os and opp springfield, near speed limit signs, marked white	Category 2	Repair Completed	05/02/2019	06/02/2019	Act. NEW-AS/5508048

Effective: 23/12/2018 to 23/12/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Fiskerton Road (26806051)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:	C17 - Stream Crossing (By Fiskerton Mill Access Road) To Stay	Feature Type:	Street Section	Area:	Newark
2703865	pothole (CW Repairs-Bituminous)	opp corner farm close, marked white	Category 2	Repair Completed	05/02/2019	06/02/2019	Act. NEW-AS/5508049
2705198	fill potholes with stone, some quite large (width) (CW Repairs-Bituminous)	os chilly bobs on road just off bend, marked yellow	Category 2	Job Completed	18/02/2019	18/03/2019	Act. NEW/3613199
2708162	potholes (CW Repairs-Bituminous)	just after bend near bridleway heading to fiskerton marked white	Category 2	Repair Completed	19/03/2019	25/03/2019	Act. NEW-AS/5508351
2709513	pothole (CW Repairs-Bituminous)	approx 150yds from speed limit sign, opo bus stop, before bend, marked wite	Category 2	Repair Completed	03/04/2019	08/04/2019	Act. NEW-AS/5508545
2709514	pothole (CW Repairs-Bituminous)	between lc2&3, marked white	Category 2	Repair Completed	03/04/2019	08/04/2019	Act. NEW-AS/5508546
2709515	pothole (CW Repairs-Bituminous)	near sign for rolleston, marked white	Category 2	Repair Completed	03/04/2019	08/04/2019	Act. NEW-AS/5508547
2712737	pothole (CW Repairs-Bituminous)	passed chilli bobs, just before rolleston sign marked	Category 2	Repair Completed	03/05/2019	16/05/2019	Act. NEW-AS/5508816
2712738	pothole (CW Repairs-Bituminous)	just after chillibobs heading away from rolleston, marked	Category 2	Repair Completed	03/05/2019	16/05/2019	Act. NEW-AS/5508811
2717971	potholes (CW Repairs-Bituminous)	near 30mph signs filled when found	Filled when found (Cat 2)	Job Completed	26/06/2019	26/06/2019	Act.
2717972	pothole (CW Repairs-Bituminous)	near chilly bobs filled when found	Filled when found (Cat 1)	Job Completed	26/06/2019	26/06/2019	Act.
2717973	potholes (CW Repairs-Bituminous)	from chilly bobs to culvert filled when found	Filled when found (Cat 2)	Job Completed	26/06/2019	26/06/2019	Act.
2721890	pothole (CW Repairs-Bituminous)	near culvert marked	Category 2	Repair Completed	16/08/2019	20/08/2019	Act. NEW-AS/5509624
2727934	all sides all the way up need filling in.. aprox 1ton of tarmac.. (CW Repairs-Bituminous)	from the chili farm on fiskerton road upto the bridge over the dyke..	Category 2	Works Order Printed	08/11/2019	06/12/2019	Est. NEW/3615562
2727936	potholes (CW Repairs-Bituminous)	nr lc 2 marked	Category 2	Repair Completed	08/11/2019	25/11/2019	Act.
2729195	pothole (Other)	next to the public bridleway sign marked.	Made Safe (Cat 1)	Job Completed	22/11/2019	22/11/2019	Act.
2729196	Carriageway Pothole (CW Repairs-Bituminous)	next to the public bridleway sign marked	Made Safe (Cat 1)	Job Completed	22/11/2019	22/11/2019	Act.
2729276	pothole cat 1 filled when found . L. 500 mm x W. 450 mm x D. 60 mm . photo's attached . (CW Repairs-Bituminous)	just before 30 mph signage coming into village	Filled when found (Cat 1)	Job Completed	25/11/2019	25/11/2019	Act.
2730291	pothole (CW Repairs-Bituminous)	just past chilibobs heading into rolleston marked	Category 2	Repair Completed	04/12/2019	10/12/2019	Act.
2730638	potholes (CW Repairs-Bituminous)	near lc 8 marked	Category 2	Repair Completed	06/12/2019	10/12/2019	Act.
2730639	pothole (CW Repairs-Bituminous)	near lc 5 marked	Category 2	Repair Completed	06/12/2019	10/12/2019	Act.

Effective: 23/12/2018 to 23/12/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Fiskerton Road (26806051)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: C17 - Stream Crossing (By Fiskerton Mill Access Road) To Stay		Feature Type: Street Section		Area: Newark	
2730640	pothole (CW Repairs-Bituminous)	50 meters after leaving rolleston marked	Category 2	Repair Completed	06/12/2019	10/12/2019	Act.
2731771	potholes (CW Repairs-Bituminous)	between chilli bobs and the rolleston sign marked	Category 2	Works Order Committed	18/12/2019	15/01/2020	Est. NEW/3615733

Street Works Inspections

Organisation: Cadent Gas EM (0010001) (Street Works Admin Team NG Gas)

Works Ref: 1000806702

Group No: 1	Site No: 2	Street Authority: Nottinghamshire	Inspected: 01/05/2019 14:40:28
Category: Category B		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel: [REDACTED]	Site Location: linden house
Insp. Notes:			Position: Footway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Site Post Code: