

Effective: 23/12/2018 to 23/12/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Main Street (26806075)

Street: Main Street (26806075)

Locality: Fiskerton, Nottinghamshire

Area: Newark

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> C17 - Trent Lane Junction, Fiskerton To Stream Crossing (Mill H			<b>Feature Type:</b> Street S	ction		<b>Area:</b> Newark	
<b>Batch:</b> 20367270	- Inspection Batch			<b>Route:</b> Newark Area 2	Dec	Saf	CW	<b>Date:</b> 06/12/2019
	No actionable defects found							
<b>Batch:</b> 20364616	- Inspection Batch			<b>Route:</b> Newark Area 2	Nov	Enh	CW/FW	<b>Date:</b> 25/11/2019
	No actionable defects found							
<b>Batch:</b> 20357526	- Inspection Batch			<b>Route:</b> Newark Area 2	Oct	Saf	CW	<b>Date:</b> 04/10/2019
	No actionable defects found							
<b>Batch:</b> 20353396	- Inspection Batch			<b>Route:</b> Newark Area 2	Sep	Saf	CW	<b>Date:</b> 05/09/2019
	No actionable defects found							
<b>Batch:</b> 20350593	- Inspection Batch			<b>Route:</b> Newark Area 2	Aug	Saf	CW	<b>Date:</b> 16/08/2019
	No actionable defects found							
<b>Batch:</b> 20346665	- Inspection Batch			<b>Route:</b> Newark Area 2	Jul	Saf	CW	<b>Date:</b> 17/07/2019
	No actionable defects found							
<b>Batch:</b> 20343619	- Inspection Batch			<b>Route:</b> Newark Area 3	Jun	Saf	CW	<b>Date:</b> 26/06/2019
	No actionable defects found							
<b>Batch:</b> 20334788	- Inspection Batch			<b>Route:</b> Newark Area 3	May	Saf	CW	<b>Date:</b> 03/05/2019
	No actionable defects found							
<b>Batch:</b> 20329965	- Inspection Batch			<b>Route:</b> Newark Area 3	Apr	Saf	CW	<b>Date:</b> 03/04/2019
	No actionable defects found							
3605889	pothole	03/04/2019	on entrance to carpark near bridge marked white	CW Repairs-Bituminous		Internal	Committed	2709517
<b>Batch:</b> 20327691	- Inspection Batch			<b>Route:</b> Newark Area 3	Mar	Saf	CW	<b>Date:</b> 19/03/2019
	No actionable defects found							
<b>Batch:</b> 20321679	- Inspection Batch			<b>Route:</b> Newark Area 3	Feb	Saf	CW	<b>Date:</b> 05/02/2019
	No actionable defects found							
<b>Batch:</b> 20318572	- Inspection Batch			<b>Route:</b> Newark Area 3	Jan	Saf	CW	<b>Date:</b> 15/01/2019
	No actionable defects found							

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> C17 - Trent Lane Junction, Fiskerton To Stream Crossing (Mill H			<b>Feature Type:</b> Street Section		<b>Area:</b> Newark	
2697662	pothole (FW Repairs-Bituminous) os the old maltings marked		Category 3	Job Completed	20/11/2018	04/01/2019	Act. NEW/3612479
2697663	pothole (FW Repairs-Bituminous) os waterside marked		Category 3	Job Completed	20/11/2018	11/01/2019	Act. NEW/3612480
2697664	pothole (CW Repairs-Bituminous) os kelham farm marked		Category 3	Job Completed	20/11/2018	11/01/2019	Act. NEW/3612481
2697665	pothole (FW Repairs-Bituminous) os post office marked		Category 3	Job Completed	20/11/2018	11/01/2019	Act. NEW/3612482
2709517	pothole (CW Repairs-Bituminous) on entrance to carpark near bridge marked white		Category 2	Repair Completed	03/04/2019	08/04/2019	Act. NEW-AS/5508532

---

Effective: 23/12/2018 to 23/12/2019  
Display Action Officer: No

Feature No.: 2000.00 to 2000.00  
Street: Main Street (26806075)

---