

Effective: 23/12/2018 to 23/12/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Inham Road (4911238)

Street: Inham Road (4911238)

Locality: Chilwell, Nottinghamshire

Area: Broxtowe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:		Feature Type:	Street Section		Area: Broxtowe	
Batch:	20366801 - Inspection Batch			Route:	Adhoc Inspection			Date: 04/12/2019
3626663	Fill 1 x Pothole CAT 1	04/12/2019	Nr LC 51	CW Repairs-Bituminous	Internal		Uncommitted	2730391
Batch:	20366794 - Inspection Batch			Route:	Adhoc Inspection			Date: 04/12/2019
3626659	Fill 1 X Pothole	04/12/2019	No31	CW Repairs-Bituminous	Internal		Uncommitted	2730387
Batch:	20366461 - Inspection Batch			Route:	Broxtowe South Nov Saf CW			Date: 03/12/2019
3626460	C way pothole.	03/12/2019	outde 21	CW Repairs-Bituminous	Internal		Uncommitted	2730186
Batch:	20360883 - Inspection Batch			Route:	Adhoc Inspection			Date: 29/10/2019
3623437	Found & Filled 1 X Pothole Cat 2	29/10/2019	No 25	CW Repairs-Bituminous	Internal		Uncommitted	2727157
Batch:	20360882 - Inspection Batch			Route:	Adhoc Inspection			Date: 29/10/2019
3623436	Found & Filled 1 X Pothole Cat 2	29/10/2019	No75	CW Repairs-Bituminous	Internal		Uncommitted	2727156
Batch:	20360881 - Inspection Batch			Route:	Broxtowe South Oct Saf CW			Date: 29/10/2019
3623435	Found & Filled 1 X Pothole Cat 2	29/10/2019	Junc of Meer Rd	CW Repairs-Bituminous	Internal		Uncommitted	2727155
Batch:	20356873 - Inspection Batch			Route:	Adhoc Inspection			Date: 30/09/2019
3621193	Please collect TM, Job completed 9 days ago 2 Barrier, 2 x Cones Please ref to photo's	30/09/2019	Outside No 103	Other	Internal		Uncommitted	2724900
Batch:	20356631 - Inspection Batch			Route:	Broxtowe South Sep Saf CW			Date: 27/09/2019
	No actionable defects found							
Batch:	20354857 - Inspection Batch			Route:	Adhoc Inspection			Date: 16/09/2019
3620205	Make safe steps with cones on 16th, provide barrier sandbags etc17th re conversation Graham Jerry 12.45.	16/09/2019	103 Inham Road	FW Repairs-Bituminous	Internal		Uncommitted	2723904
3620204	Provide and lay 600 x 900 slab on mortar bed (top of steps) asap please.	16/09/2019	103 Inham Road	FW Repairs-Concrete	Internal		Committed	2723905
Batch:	20352353 - Inspection Batch			Route:	Broxtowe South Aug Saf CW			Date: 29/08/2019
	No actionable defects found							
Batch:	20347907 - Inspection Batch			Route:	Broxtowe South Jul Saf CW			Date: 26/07/2019
3616829	pothole	26/07/2019	os 4a	CW Repairs-Bituminous	Internal		Uncommitted	2720511
Batch:	20343987 - Inspection Batch			Route:	Broxtowe South Jun Enh CW/FW			Date: 27/06/2019
3614411	Cway potholes	27/06/2019	Lamp columns 47, 51, 55, 59, 61, 64, 65, 68, 73 & 79	CW Repairs-Bituminous	Internal		Committed	2718083
3614410	Excavate damaged /loose slabs and tarmac and re patch with tarmac	27/06/2019	Outside numbers 4A, 31, 74, 133, 150, 173 & lamp column 63	FW Repairs-Bituminous	Internal		Committed	2718084
Batch:	20337910 - Inspection Batch			Route:	Broxtowe South May Saf CW			Date: 28/05/2019
3611205	Found & Filled 1 x PH Cat 2	28/05/2019	No 31	CW Repairs-Bituminous	Internal		Uncommitted	2714867

Effective: 23/12/2018 to 23/12/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Inham Road (4911238)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:		Feature Type: Street Section			Area: Broxtowe	
Batch: 20333177 - Inspection Batch No actionable defects found				Route: Broxtowe South Apr Saf CW			Date: 25/04/2019	
Batch: 20330304 - Inspection Batch				Route: Adhoc Inspection			Date: 04/04/2019	
3606116	Patch required Fway Approx 2 x 2mtr P60 2 Coat160mm Depth. Please ref to Photo's	04/04/2019	No117	FW Repairs-Bituminous	Internal		Committed	2709749
Batch: 20327603 - Inspection Batch No actionable defects found				Route: Broxtowe South Mar Saf CW			Date: 19/03/2019	
Batch: 20323808 - Inspection Batch				Route: Broxtowe South Feb Saf CW			Date: 20/02/2019	
3601834	Found & Filled 1 x PH	20/02/2019	No 25	CW Repairs-Bituminous	Internal		Uncommitted	2705411
Batch: 20323807 - Inspection Batch				Route: Adhoc Inspection			Date: 20/02/2019	
3601833	Remove uplifting Slab (Tree Roots) Replace P60 Approx 2 x 1mtr. please ref to photo	20/02/2019	No 156	FW Repairs-Bituminous	Internal		Committed	2705410
Batch: 20320384 - Inspection Batch No actionable defects found				Route: Broxtowe South Jan Saf CW			Date: 25/01/2019	
Batch: 20316654 - Inspection Batch No actionable defects found				Route: Broxtowe South Dec Saf CW			Date: 28/12/2018	

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:		Feature Type: Street Section		Area: Broxtowe	
2619837	New bollard required. (HW Damaged Glasdon Bollard Z6)	Adjacent tram line near Eskdale Dr.	Category 2	Job Cancelled	25/11/2015	23/12/2015	Est.
2656550	Replace damaged bollard (Bollard Repairs)	Near lamp column 74	Category 3	Job Cancelled	25/08/2017	22/09/2017	Est.
2700227	Patch required Approx 1.5 x 1.5mtr, P40 Tarmac. please see photo. (CW Repairs-Bituminous)	No 145 on Cway prior to speed hump.	Category 3	Job Completed	19/12/2018	10/01/2019	Act. BROX/3305516
2705410	Remove uplifting Slab (Tree Roots) Replace P60 Approx 2 x 1mtr. please ref to photo (FW Repairs-Bituminous)	No 156	Category 3	Job Completed	20/02/2019	18/02/2019	Act. BROX/3305709
2705411	Found & Filled 1 x PH (CW Repairs-Bituminous)	No 25	Filled when found (Cat 2)	Job Completed	20/02/2019	20/02/2019	Act.
2709749	Patch required Fway Approx 2 x 2mtr P60 2 Coat160mm Depth. Please ref to Photo's (FW Repairs-Bituminous)	No117	Category 2	Job Completed	04/04/2019	16/04/2019	Act. BROX/3305818
2714867	Found & Filled 1 x PH Cat 2 (CW Repairs-Bituminous)	No 31	Filled when found (Cat 2)	Job Completed	28/05/2019	28/05/2019	Act.

Effective: 23/12/2018 to 23/12/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Inham Road (4911238)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:	Feature Type: Street Section		Area: Broxtowe		
2718083	Cway potholes (CW Repairs-Bituminous)	Lamp columns 47, 51, 55, 59, 61, 64, 65, 68, 73 & 79	Category 2	Job Completed	27/06/2019	05/07/2019	Act. BRO-AS/5205125
2718084	Excavate damaged /loose slabs and tarmac and re patch with tarmac (FW Repairs-Bituminous)	Outside numbers 4A, 31, 74, 133, 150, 173 & lamp column 63	Category 3	Job Completed	27/06/2019	09/07/2019	Act. BROX/3306141
2720511	pothole (CW Repairs-Bituminous)	os 4a	Filled when found (Cat 2)	Job Completed	26/07/2019	26/07/2019	Act.
2723904	Make safe steps with cones on 16th, provide barrier sandbags etc17th re conversation Graham Jerry 12.45. (FW Repairs-Bituminous)	103 Inham Road	Category 1	Repair Completed	16/09/2019	17/09/2019	Act.
2723905	Provide and lay 600 x 900 slab on mortar bed (top of steps) asap please. (FW Repairs-Concrete)	103 Inham Road	Category 2	Job Completed	16/09/2019	18/09/2019	Act. BROX/3306334
2724900	Please collect TM, Job completed 9 days ago 2 Barrier, 2 x Cones Please ref to photo's (Other)	Outside No 103	Category 2	Repair Completed	30/09/2019	02/10/2019	Act.
2727155	Found & Filled 1 X Pothole Cat 2 (CW Repairs-Bituminous)	Junc of Meer Rd	Filled when found (Cat 2)	Job Completed	29/10/2019	29/10/2019	Act.
2727156	Found & Filled 1 X Pothole Cat 2 (CW Repairs-Bituminous)	No75	Filled when found (Cat 2)	Job Completed	29/10/2019	29/10/2019	Act.
2727157	Found & Filled 1 X Pothole Cat 2 (CW Repairs-Bituminous)	No 25	Filled when found (Cat 2)	Job Completed	29/10/2019	29/10/2019	Act.
2730186	C way pothole. (CW Repairs-Bituminous)	outde 21	Category 2	Repair Completed	03/12/2019	05/12/2019	Act.
2730387	Fill 1 X Pothole (CW Repairs-Bituminous)	No31	Category 2	Repair Completed	04/12/2019	05/12/2019	Act.
2730391	Fill 1 x Pothole CAT 1 (CW Repairs-Bituminous)	Nr LC 51	Category 1	Repair Completed	04/12/2019	05/12/2019	Act.