

Effective: 01/06/2018 to 23/12/2019

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Marriott Close (4911287)

Street: Marriott Close (4911287)

Locality: Chilwell, Nottinghamshire

Area: Broxtowe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:		Feature Type:	Street Section		Area: Broxtowe	
Batch:	20343171 - Inspection Batch			Route:	Broxtowe South Jun Enh CW/FW		Date:	24/06/2019
3614033	Remove Broken/uplifting Concrete Patch required (loss of Material) 5 x 3mtr. please ref to photo's	24/06/2019	Junc withb	FW Repairs-Bituminous	Internal		Committed	2717705
Batch:	20290404 - Inspection Batch			Route:	Broxtowe South Jun Enh CW/FW		Date:	25/06/2018
	No actionable defects found							

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:		Feature Type:	Street Section		Area: Broxtowe
2717705	Remove Broken/uplifting Concrete Patch required (loss of Material) 5 x 3mtr. please ref to photo's (FW Repairs-Bituminous)	Junc withb	Category 3	Job Completed	24/06/2019	22/07/2019	Act. BROX/3306130