

Effective: 02/08/2017 to 02/08/2018

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Westhorpe (33021824)

Street: Westhorpe (33021824)

Locality: Willoughby on the Wolds, Nottinghamshire

Area: Rushcliffe

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> C101 - From East Road to Main Street			<b>Feature Type:</b> Street Section			<b>Area:</b> Rushcliffe	
<b>Batch:</b> 20293798 - Inspection Batch	No actionable defects found			<b>Route:</b> Rush Area 1 Jul Saf CW				<b>Date:</b> 17/07/2018
<b>Batch:</b> 20288140 - Inspection Batch	No actionable defects found			<b>Route:</b> Rush Area 1 Jun Enh CW/FW				<b>Date:</b> 11/06/2018
<b>Batch:</b> 20284337 - Inspection Batch	No actionable defects found			<b>Route:</b> Rush Area 1 May Saf CW				<b>Date:</b> 21/05/2018
<b>Batch:</b> 20284317 - Inspection Batch	No actionable defects found			<b>Route:</b> Adhoc Inspection				<b>Date:</b> 21/05/2018
3579077	Carriageway Pothole - Road Pothole - deep pothole . Online report Customer title is Mr. (Enquiry 6095612)	21/05/2018	Entrance /exit of the village.	CW Repairs-Bituminous	Internal		Uncommitt	2682216
<b>Batch:</b> 20278689 - Inspection Batch	No actionable defects found			<b>Route:</b> Rush Area 1 Apr Saf CW				<b>Date:</b> 19/04/2018
<b>Batch:</b> 20275298 - Inspection Batch	No actionable defects found			<b>Route:</b> Rush Area 1 Mar Saf CW				<b>Date:</b> 03/04/2018
<b>Batch:</b> 20268610 - Inspection Batch	No actionable defects found			<b>Route:</b> Rush Area 1 Feb Saf CW				<b>Date:</b> 16/02/2018
<b>Batch:</b> 20263146 - Inspection Batch	No actionable defects found			<b>Route:</b> Rush Area 1 Jan Saf CW				<b>Date:</b> 17/01/2018
<b>Batch:</b> 20258443 - Inspection Batch	No actionable defects found			<b>Route:</b> Rush Area 1 Dec Saf CW				<b>Date:</b> 08/12/2017
<b>Batch:</b> 20256242 - Inspection Batch	No actionable defects found			<b>Route:</b> Rush Area 1 Nov Saf CW				<b>Date:</b> 23/11/2017
<b>Batch:</b> 20251093 - Inspection Batch	No actionable defects found			<b>Route:</b> Rush Area 1 Oct Saf CW				<b>Date:</b> 23/10/2017
<b>Batch:</b> 20246261 - Inspection Batch	No actionable defects found			<b>Route:</b> Rush Area 1 Sep Saf CW				<b>Date:</b> 18/09/2017
<b>Batch:</b> 20244396 - Inspection Batch	No actionable defects found			<b>Route:</b> Rush Area 1 Aug Saf CW				<b>Date:</b> 05/09/2017
<b>Feat No.:</b> 2,001.00	<b>Feature Id - Locn.:</b> From Main Street To village limits at 60mph speed limit signs			<b>Feature Type:</b> Street Section			<b>Area:</b> Rushcliffe	
<b>Batch:</b> 20288139 - Inspection Batch	No actionable defects found			<b>Route:</b> Rush Area 1 Jun Enh CW/FW				<b>Date:</b> 11/06/2018

Effective: 02/08/2017 to 02/08/2018

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Westhorpe (33021824)

**Customer Services**

**Enquiry No.:** 6095612      **Logged by:** External to Confirm      **on:** 18/05/2018 16:33  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-76023966  
**Desc.:** Road Pothole - deep pothole . Online report Customer title is Mr.  
**Location:** centre of road as shown on map      **Contact:**

**Plot Number:** 2,000.00      **Feature Id - Location:** C101 - From East Road to Main Street      **Feature Type:** Street Section  
**Job Number:** 2682216      **Defect Number:** 3579077

**Enquiry No.:** 71698      **Logged by:** [REDACTED]      **on:** 15/05/2018 14:11  
**Service:** Carriageway/Footway      **Subject:** St Furn/Non Illum Sign Damage      **Classification:** Report or Observation  
**Desc.:** Damage to direction signs and fingerpost by an RTC  
**Location:** Back Ln Crossroads      **Contact:**

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> C101 - From East Road to Main Street		<b>Feature Type:</b> Street Section		<b>Area:</b> Rushcliffe	
2682216	Carriageway Pothole - Road Pothole - deep pothole . Online report Customer title is Mr. (Enquiry 6095612) (CW Repairs-Bituminous)	Entrance /exit of the village.	Filled when found (Cat 2H)	Job Completed	21/05/2018	21/05/2018	Act.