

Effective: 01/04/2015 to 31/03/2018

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Carlton Hill (15003893)

Street: Carlton Hill (15003893)

Locality: Carlton, Nottinghamshire

Area: Gedling

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,001.00	Feature Id - Locn.: From Dale Road to Cavendish Road			Feature Type: Street Section		Area: Gedling	
2607424	traffic management required (HW CW Pothole Z1)	Jcn Church St. , jcn Ivy Grove also 1no on Ivy Grove , o/s 210 , 275	Howard Widdowson	(Inspe Category 2 (High))	Job Completed	18/03/2015	23/03/2015	Act. GED/3401148
2608491	7 day traffic management required (HW CW Crazying Z1)	o/s 178 patch c/w depression	Howard Widdowson	(Inspe Category 2 (High))	Job Completed	10/04/2015	20/04/2015	Act. GED/3401332
2609239	repaired while on site (HW CW Pothole Z1)	opp 220 , o/s Windsor Castle pub	Howard Widdowson	(Inspe Category 1)	Job Completed	21/04/2015	21/04/2015	Act. GED/3401480
2609240	7 day traffic management required (HW CW Crazying Z1)	opp 244 246. 248 .250 patch c/w joint , opp 238 patch joint , opp 220 218. Jcn Hastings St patch joint. , o/s 218 , opp Jcn Southdale Rd patch side uneven c/w side m/hole	Howard Widdowson	(Inspe Category 2 (High))	Job Completed	21/04/2015	29/04/2015	Act. GED/3401479
2611262	repaired while on site (HW CW Pothole Z1)	jcn Hooton Rd , o/s 230 ,208 , jcn Brookwood Cres	Howard Widdowson	(Inspe Filled when found (Cat 1))	Job Completed	28/05/2015	28/05/2015	Act. GED/3401737
2612555	phoned through to inspectors assistants (HW CW Pothole Z1)	Jcn Southdale Rd	Howard Widdowson	(Inspe Filled when found (Cat 1))	Job Completed	18/06/2015	18/06/2015	Act.
2612756	repaired while on site (HW CW Pothole Z1)	opp l/col 13 side of gully , opp 238 , opp jcn Hooton Rd	Howard Widdowson	(Inspe Filled when found (Cat 1))	Job Completed	23/06/2015	23/06/2015	Act.
2614009	Two areas of f/w erosion at the side of two 'cheese corner kerbs' at edge of driveway, were repaired by o/laying area with Viafix on Wednesday 22nd July 15 by Pete #2 at 12.30hrs. No further action required. (HW FW Profile erosion Z1)	Right next to RECKLESS HAIRDRESSING and COMPUTER SHOP (Opp side to Southdale Road Jnc) Carlton Hill	Pete Moncaster	(Rushcliffe Filled when found (Cat 1))	Job Completed	22/07/2015	22/07/2015	Act.
2614290	repaired While on site. NC & EC (HW CW Pothole Z1)	opp Windsor Castle	Howard Widdowson	(Inspe Category 1)	Job Completed	30/07/2015	31/07/2015	Act.
2617287	repaired while on site (HW CW Pothole Z1)	Jcn Ivy Gr	Howard Widdowson	(Inspe Filled when found (Cat 1))	Job Completed	09/10/2015	09/10/2015	Act.
2617288	7 day traffic management required (HW CW Pothole Z1)	Jcn Ivy Gr	Howard Widdowson	(Inspe Category 2 (High))	Job Completed	09/10/2015	14/10/2015	Act. GED-AS/5300387
2617784	7 day traffic management required (HW CW Pothole Z1)	opp 222. fill c/w joint	Howard Widdowson	(Inspe Category 2 (High))	Job Completed	19/10/2015	21/10/2015	Act. GED-AS/5300425
2618776	7 day traffic management required next to central refuge (HW CW Crazying Z1)	opp 232/230 2no patches , opp 228 , opp 224 ,	Howard Widdowson	(Inspe Category 2 (High))	Job Completed	06/11/2015	11/11/2015	Act. GED/3402290
2619509	repaired while on site (HW CW Pothole Z1)	o/s Windsor Castle , entrance to Shell garage ,	Howard Widdowson	(Inspe Filled when found (Cat 1))	Job Completed	18/11/2015	18/11/2015	Act.
2619510	(HW FW Profile erosion Z1)	patch section f/w l/col 5 full width f/w , l/col 4 rear kerbs	Howard Widdowson	(Inspe Category 2 (High))	Job Completed	18/11/2015	01/02/2016	Act. GED/3402325

Effective: 01/04/2015 to 31/03/2018

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Carlton Hill (15003893)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,001.00	Feature Id - Locn.:	From Dale Road to Cavendish Road	Feature Type:	Street Section	Area:	Gedling	
2620911	7 day (HW CW Pothole Z1)	opp Windsor castle pub. , Jcn Ivy Howard Widdowson (Inspe Category 2 (High) Gr. , opp Jcn Hooton Rd., 278 , 284	Howard Widdowson (Inspe Filled when found (Cat 1)	Job Completed	15/12/2015	04/01/2016	Act.	GED-AS/5300600
2621292	repaired while on site (HW CW Pothole Z1)	opp Windsor Castle	Howard Widdowson (Inspe Filled when found (Cat 1)	Job Completed	29/12/2015	30/12/2015	Act.	
2623123	HW CW Pothole Z1	o/s Windsor Castle pub , Jcn Southdale Rd side m/hole , Jcn Ivy Gr , o/s 270	Howard Widdowson (Inspe Category 2 (High)	Job Completed	27/01/2016	02/02/2016	Act.	GED-AS/5300735
2623417	repaired on site (HW CW Pothole Z1)	nr l/col 6	Howard Widdowson (Inspe Filled when found (Cat 1)	Job Completed	02/02/2016	18/02/2016	Act.	
2623707	repaired on site (HW FW Pothole Z1)	o/s 139	Howard Widdowson (Inspe Filled when found (Cat 1)	Job Completed	05/02/2016	05/02/2016	Act.	
2625195	repaired on site (HW CW Pothole Z1)	l/col 30 , o/s 198 , opp Jcn Cromwell St f/w in bus shelter	Howard Widdowson (Inspe Filled when found (Cat 1)	Job Completed	25/02/2016	25/02/2016	Act.	
2625196	7 day (HW CW Pothole Z1)	o/s 272 , 273 , o/s & opp 268 , opp Jcn Hooton Rd , 260 on crossing point , opp 238 , 230 , 220 , 216 in front pram crossing , Jcn Ivy Gr , 184 , opp 143& opp 139 f/w , Methodist Church o/s Windsor Castle channel 10m down from Windsor Castle side gully , Jcn Greenhill Rise , entrance to Shell garage , opp Windsor Castle , entrance to Dog House , o/s Church fill missing kerb ,	Howard Widdowson (Inspe Category 2 (High)	Job Completed	25/02/2016	13/02/2017	Act.	GED/3402750
2625197	HW CW Crazing Z1	182 to Ivy Gr 9m x 1m , opp Methodist Church around gullys , o/s 281	Howard Widdowson (Inspe Category 2 (High)	Job Completed	25/02/2016	06/04/2016	Act.	GED/3402751
2625198	HW FW Profile erosion Z1	o/s 170 / l/col 24 low reinstatement , 170 radius , opp 155 , o/s 155 patch old reinstatement , from l/col 6 down 13m patch full width f/w , Jcn New Row around m/hole , 139 rear f/w , 173 , opp 246 patch old reinstatement , opp 240/242 ,	Howard Widdowson (Inspe Category 2 (High)	Job Completed	25/02/2016	06/04/2016	Act.	GED/3402752
2626898	HW CW Pothole Z1	o/s Rosa Rhodes	Howard Widdowson (Inspe Category 2 (High)	Job Completed	22/03/2016	20/04/2016	Act.	GED-AS/5301001
2628616	7 day (HW CW Pothole Z1)	Jcn Southdale Rd side m/hole , opp 188 , nr Jcn Carlton Mews	Howard Widdowson (Inspe Category 2 (High)	Job Completed	21/04/2016	29/04/2016	Act.	GED-AS/5301080
2629848	FW Repairs-Bituminous	opp 155	Howard Widdowson (Inspe Category 1	Job Completed	11/05/2016	12/05/2016	Act.	GED-AS/5301125
2631362	repaired on site (CW Repairs-Bituminous)	opp jcn Hooton Rd	Howard Widdowson (Inspe Filled when found (Cat 1)	Job Completed	07/06/2016	07/06/2016	Act.	
2631797	flood damage to c/w patch & remove debris (CW Repairs-Bituminous)	o/s & opp 230	Howard Widdowson (Inspe Category 1	Job Completed	16/06/2016	16/06/2016	Act.	GED/3403116

Effective: 01/04/2015 to 31/03/2018

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Carlton Hill (15003893)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,001.00	Feature Id - Locn.:	From Dale Road to Cavendish Road	Feature Type:	Street Section	Area:	Gedling	
2631985	repaired carriageway pothole & floated in front pram crossing (CW Repairs-Bituminous)	opp 232	Howard Widdowson (Inspe	Filled when found (Cat 1)	Job Completed	22/06/2016	23/06/2016	Act.
2632363	phoned through to inspectors assistants (CW Repairs-Bituminous)	opp 230/232 c/w lifted in front of pram crossing float out , c/w pothole o/s 228	Howard Widdowson (Inspe	Category 1	Job Completed	28/06/2016	30/06/2016	Act. GED-AS/5301405
2633053	CW Repairs-Bituminous	opp 232 near pram crossing	Howard Widdowson (Inspe	Category 1	Job Completed	12/07/2016	14/07/2016	Act. GED-AS/5301434
2633646	CW Repairs-Bituminous	opp Windsor Castle	Howard Widdowson (Inspe	Category 2 (High)	Job Completed	22/07/2016	26/08/2016	Act. GED-AS/5301515
2634180	c/w edge has pushed up over 6x5 kerbs, Viafix used to ramp off level difference. (CW Repairs-Bituminous)	On ped xing point, adj to l/c no30.	Pete Moncaster (Rushcliffe	Filled when found (Cat 1)	Job Completed	03/08/2016	03/08/2016	Act.
2634945	repaired on site (CW Repairs-Bituminous)	opp Dog House	Howard Widdowson (Inspe	Filled when found (Cat 1)	Job Completed	22/08/2016	25/08/2016	Act.
2634946	CW Repairs-Bituminous	o/s 208 , opp Windsor Castle	Howard Widdowson (Inspe	Category 2 (High)	Job Completed	22/08/2016	30/08/2016	Act. GED-AS/5301601
2637402	reset 2no loose tactile slabs on pram crossing (FW Repairs-Concrete)	jcn Cavendish Rd Tesco side	Howard Widdowson (Inspe	Category 1	Job Completed	11/10/2016	12/10/2016	Act. GED-AS/5301774
2639683	repaired on site (CW Repairs-Bituminous)	o/s 208	Howard Widdowson (Inspe	Filled when found (Cat 1)	Job Completed	25/11/2016	25/11/2016	Act.
2639684	CW Repairs-Bituminous	o/s 198	Howard Widdowson (Inspe	Category 2 (High)	Job Completed	25/11/2016	28/11/2016	Act. GED-AS/5301946
2640514	CW Repairs-Bituminous	o/s Windsor Castle pub , opp 232 , 268	Howard Widdowson (Inspe	Category 2 (High)	Job Completed	09/12/2016	20/12/2016	Act. GED-AS/5302037
2641702	replace damaged plastic/comp bollard (Bollard Repairs)	o/s 138	Howard Widdowson (Inspe	Category 2 (High)	Job Completed	09/01/2017	12/01/2017	Act. GED/3403561
2644526	repaired on site (FW Repairs-Bituminous)	o/s The Doghouse pub , jcn New Row side m/hole , c/w opp The Doghouse pub	Howard Widdowson (Inspe	Filled when found (Cat 1)	Job Completed	17/02/2017	17/02/2017	Act.
2646503	CW Repairs-Bituminous	o/s 230, o/s & down from Windsor Castle	Howard Widdowson (Inspe	Category 1	Job Completed	16/03/2017	17/03/2017	Act. GED-AS/5302490
2646504	CW Repairs-Bituminous	jcn Church St , 175 ,nr jcn Carlton Mews, 261, 409 , opp 425/682 , 282 , 226 , 208 , Windsor Castle	Howard Widdowson (Inspe	Category 2 (Low)	Job Completed	16/03/2017	17/06/2017	Act. GED-AS/5302491
2647799	CW Repairs-Bituminous	o/s 175a	Howard Widdowson (Inspe	Category 1	Job Completed	05/04/2017	06/04/2017	Act. GED-AS/5302587
2648097	CW Repairs-Bituminous	opp Windsor Castle , jcn Church St ,jcn Ivy Gr , 208 , l/col 28 , 5m down from jcn Carlton Mews , 282 ,	Howard Widdowson (Inspe	Category 2 (Low)	Job Completed	10/04/2017	09/05/2017	Act. GED-AS/5302666
2649317	repaired on site 28/4/17 (FW Repairs-Bituminous)	opp 155	Howard Widdowson (Inspe	Filled when found (Cat 1)	Job Completed	28/04/2017	28/04/2017	Act.
2651035	phoned inspectors assistants (CW Repairs-Bituminous)	jcn Church St	Howard Widdowson (Inspe	Category 2 (High)	Job Completed	23/05/2017	24/05/2017	Act. GED-AS/5302817

Effective: 01/04/2015 to 31/03/2018

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Carlton Hill (15003893)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,001.00	Feature Id - Locn.:	From Dale Road to Cavendish Road	Feature Type:	Street Section	Area:	Gedling	
2651249	phoned through to inspectors assistants (CW Repairs-Bituminous)	o/s 282 , opp Hooton Rd , 214 f/w , 208 , opp 149 & 147 , opp 117 & 115 f/w potholes, opp Doghouse , o/s Nags Head f/w , 5m down from Chesterfield St , on Gladstone St, ent to Shell garage , opp 88 , opp 198 f/w , 281	Howard Widdowson (Inspe	Category 1	Job Completed	30/05/2017	31/05/2017	Act. GED-AS/5302831
2651250	o/s Windsor castle replace 12m total d/yellow lines (CW Repairs-Bituminous)	o/s 272 , 270, 230 ,opp 224 /226 , 224 , jcn Ivy Gr , 178 ,opp 147/149, opp Doghouse, o/s Windsor Castle 3no , jcn Greenhill Rise , opp Windsor Castle, jcn Church St , opp 88 around gullys , 175a , 177, opp 216, 281	Howard Widdowson (Inspe	Category 2 (Low)	Job Completed	30/05/2017	08/06/2017	Act. GED/3403945
2651251	FW Repairs-Bituminous	fcn Celia Dr ,opp 155 replace 2no broken 10 x 5 kerbs, opp 151 rear f/w , l/col 5 , l/col 6 , 93 ,opp l/col 26 ,opp Fearn, opp 187 , 179 rear kerbs ,l/col 26	Howard Widdowson (Inspe	Category 2 (Low)	Job Completed	30/05/2017	13/06/2017	Act. GED/3403946
2651252	2/c f/w patch root damage , (FW Repairs-Bituminous)	opp 240	Howard Widdowson (Inspe	Category 2 (Low)	Job Completed	30/05/2017	25/07/2017	Act. GED/3403947
2651253	make safe missing f/w gully lid phoned through to inspectors assistants (FW Ironwork)	o/s Chesterfield arms	Howard Widdowson (Inspe	Category 1	Job Completed	30/05/2017	01/06/2017	Act. GED-AS/5302832
2651254	rear f/w missing gully lid 150 x 150 (FW Ironwork)	o/s Chesterfield arms	Howard Widdowson (Inspe	Category 2 (High)	Job Completed	30/05/2017	05/06/2017	Act. GED/3403948
2654280	2 course patch required both sides of cw due lifting after flood.Carriageway Damage - Road Damage - Road surface breaking up on Carlton Hill between Hooton Road and Ivy Grove heading towards Southwell out of Nottingham . . Submitted by Advisor: Samantha King (Enquiry 6057983) (CW Repairs-Bituminous)	outside 230	Nicholas Clarke DO NOT L	Category 2 (High)	Job Completed	18/07/2017	31/08/2017	Act. GED/3404066
2654694	cw potholes (CW Repairs-Bituminous)	opposite the earl of chesterfield pub	John Buxton (Inspector)	Filled when found (Cat 2L)	Job Completed	25/07/2017	25/07/2017	Act.
2656420	Cw pothole. (CW Repairs-Bituminous)	Outside number 88	John Buxton (Inspector)	Filled when found (Cat 2H)	Job Completed	23/08/2017	23/08/2017	Act.
2659013	repaired on site (CW Repairs-Bituminous)	o/s 208	Howard Widdowson (Inspe	Filled when found (Cat 1)	Job Completed	03/10/2017	03/10/2017	Act.
2660688	repaired on site (CW Repairs-Bituminous)	o/s 230 & opp 230	Howard Widdowson (Inspe	Filled when found (Cat 1)	Job Completed	24/10/2017	24/10/2017	Act.

Effective: 01/04/2015 to 31/03/2018

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Carlton Hill (15003893)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,001.00	Feature Id - Locn.: From Dale Road to Cavendish Road			Feature Type: Street Section		Area: Gedling	
2664795	repaired on site (CW Repairs-Bituminous)	opp 230	Howard Widdowson (Inspe Filled when found (Cat 1)		Job Completed	14/12/2017	14/12/2017	Act.
2666166	repaired on site (CW Repairs-Bituminous)	jcn Church St , opp 88 , opp 230 , 282	Howard Widdowson (Inspe Filled when found (Cat 1)		Job Completed	08/01/2018	08/01/2018	Act.
2666167	CW Repairs-Bituminous	o/s Windsor Castle	Howard Widdowson (Inspe Category 2 (High)		Job Completed	08/01/2018	11/01/2018	Act. GED-AS/5303673
2667895	c/way depression (CW Repairs-Bituminous)	outside No 281 Carlton Hill	Lynn Connelly (NRSWA) Category 2 (Low)		Job Completed	23/01/2018	14/02/2018	Act. GED/3404718
2674057	repaired on site (CW Repairs-Bituminous)	o/s Windsor Castle pub	Howard Widdowson (Inspe Filled when found (Cat 1)		Job Completed	15/03/2018	15/03/2018	Act.
2674226	repaired on site (CW Repairs-Bituminous)	o/s Windsor Castle	Howard Widdowson (Inspe Filled when found (Cat 1)		Job Completed	15/03/2018	15/03/2018	Act.
2674227	CW Repairs-Bituminous	opp Windsor Castle , l/col 9 depression , l/col 35	Howard Widdowson (Inspe Category 2 (High)		Job Completed	15/03/2018	19/03/2018	Act. GED-AS/5303943