

This matter is being dealt with by:

**Name Jilly Walden**

Reference: NCC-042777-19

T 0115 977 2788

E [complaints@nottscc.gov.uk](mailto:complaints@nottscc.gov.uk)

W [www.nottinghamshire.gov.uk](http://www.nottinghamshire.gov.uk)



**Nottinghamshire  
County Council**

02 March 2020


**Request for Information: Ref NCC-042777-19  
Pothole repairs**

Thank you for your request for information relating to pothole repairs. I can now let you have the following information in response to the questions you raised.

**Please can you provide details of pothole repairs on the stretch of the A614 (Blyth Road) between the Netherfield Lane Roundabout, and the A614 / A57 / A1 roundabout (map attached and circled for reference). I would like to know when and what potholes have been reported and/or repaired on this stretch of road for the months of December 2019, and Jan 2020, including the severity of the pothole. Please include specific dates potholes were reported and/or repaired.**

The Street History report attached details the Works raised/repaired during the period requested (01/12/2019 to 31/01/2020) on Blyth Road – Clumber Park – 2214605-2000. The plan below shows the Street Section covered by the Street History report. There were no Customer Enquiries raised for Potholes or Carriageway damage during the requested period.

A Street History report, for the same period, was ran for Blyth Road – Perlethorpe – 26814620 – 2000, shown on the plan below. No Customer Enquiries or Jobs raised/completed during the requested period.



We hope this now satisfies your request, and should you have any further enquiries please do not hesitate to contact me directly using the contact details below. In addition and for future reference Nottinghamshire County Council regularly publish previous Freedom of Information Requests and answers on our website, [click here](#) to see the Disclosure logs.

If you are unhappy with the service you have received in relation to your request and wish to make a complaint or request a review of our decision, you should write to the

Team Manager,  
Complaints and Information Team,  
County Hall,  
West Bridgford,  
Nottingham,  
NG2 7QP

or email : [FOI@nottsc.gov.uk](mailto:FOI@nottsc.gov.uk).

Yours sincerely

Name : Jilly Walden  
Position: Complaints information and Mediation Officer  
Nottinghamshire County Council

Effective: 01/12/2019 to 28/02/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Blyth Road (2214605)

Street: Blyth Road (2214605)

Locality: Clumber Park, Nottinghamshire

Area: Bassetlaw

**Maintenance Management**

| Job No.          | Description                         | Location  | Priority   | Job Status                          | Entered    | Completion             | Works Order |
|------------------|-------------------------------------|---|------------|-------------------------------------|------------|------------------------|-------------|
| <b>Feat No.:</b> | 2,000.00                            | <b>Feature Id - Locn.:</b> Blyth Road On To A1T Five Lanes End Roundabout - Clumber F |            | <b>Feature Type:</b> Street Section |            | <b>Area:</b> Bassetlaw |             |
| 2730826          | c/w pothole (CW Repairs-Bituminous) | just past clumber park turn   | Category 2 | Repair Completed                    | 10/12/2019 | 31/12/2019             | Act.        |
| 2733495          | c/w pothole (CW Repairs-Bituminous) | just before layby   | Category 2 | Repair Completed                    | 09/01/2020 | 10/01/2020             | Act.        |
| 2736991          | c/w pothole (CW Repairs-Bituminous) | just before horse crossing, opposite to clumber park, just after entrance to clumber  | Category 2 | Repair Completed                    | 11/02/2020 | 12/02/2020             | Act.        |