

10/06/2020

Enquiry Trace Form - Preview


Enquiry: 6165847	Logged by: External to Confirm	on 15/04/2020 11:27
Service: Carriageway/Footway	Classification: Report or Observation	
Subject: Manholes/Gullies	Enquiry Ref: FS-CASE-196244685	
Desc.: Missing and damaged manhole/drain covers - Large hole in a grate on the floor, large enough that the customers foot went through it. A cone has been placed temporarily and a picture will be provided. . Submitted by Advisor: [REDACTED] [REDACTED] 2Customer title is [REDACTED]		

Street: Sherwood Street (24609042), Warsop, Nottinghamshire

Street Address: Sherwood Street **Area:** Mansfield

Location: Outside the Jet garage on Sherwood Street, Warsop. On the walking pavement next to the garage. **Ward:** Warsop

Street Notes:



Current Status:			
No. Effective	Status	Officer	Follow up Date
6 13/05/2020 10:15:21	Work Complete	[REDACTED]	

Status history:			
No. Effective	Status	Officer	Notes
5 20/04/2020 11:23	Section 81-Utilities notified	[REDACTED]	pass over to open reach by phone prior this enquiry their ref number is EM0UQU58.
4 20/04/2020 11:12	Inspection Required	[REDACTED]	site checked 20-4-20 british telecom have put barriers around damaged cover
3 20/04/2020 08:33	Inspection Required	[REDACTED]	
2 16/04/2020 10:13	Inspection Required	[REDACTED]	IRT attended site 15/04/2020. BT already made safe.
1 15/04/2020 11:27	Enquiry Received	[REDACTED]	

Attributes:	
Parameter	Value
Emergency Response	No (NO)
Avoidable Contact	Not Known (NK)
Method	Not Known (NK)
Comments	
Feedback	Not Known (NK)
Rechargeable Works	No (NO)

Revised Status:

Name : Signed : Date : Time :

Report generated by : [REDACTED]

11:15:04