

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

Street: Sherwood Street (24609042)

Locality: Warsop, Nottinghamshire

Area: Mansfield

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,002.00	<b>Feature Id - Locn.:</b> From Clumber Street to Tichfield Street - Pre 01-Mar-2019 was i			<b>Feature Type:</b> Street Section			<b>Area:</b> Mansfield	
<b>Batch:</b> 20388279 - Inspection Batch				<b>Route:</b> Mansfield East Apr Saf CW/FW				<b>Date:</b> 20/04/2020
3638037	infill area	20/04/2020	opp 252	CW Repairs-Bituminous	Internal		Uncommitted	2741813
3638036	infill area	20/04/2020	junction short street	CW Repairs-Bituminous	Internal		Uncommitted	2741812
<b>Batch:</b> 20384366 - Inspection Batch				<b>Route:</b> Mansfield East Mar Saf CW/FW				<b>Date:</b> 25/03/2020
No actionable defects found								
<b>Batch:</b> 20379195 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 25/02/2020
3634550	4 number infill areas	25/02/2020	Outside the garage ( 3 on entrance , 1 on exit)	CW Repairs-Bituminous	Internal		Committed	2738301
<b>Batch:</b> 20379170 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 25/02/2020
3634541	infill area	25/02/2020	junction sherwood street and short street	CW Repairs-Bituminous	Internal		Committed	2738292
<b>Batch:</b> 20379149 - Inspection Batch				<b>Route:</b> Mansfield East Feb Saf CW/FW				<b>Date:</b> 25/02/2020
No actionable defects found								
<b>Batch:</b> 20374424 - Inspection Batch				<b>Route:</b> Mansfield East Jan Saf CW/FW				<b>Date:</b> 27/01/2020
3631656	5 number infill areas	27/01/2020	outside 43 (1), entrance petrol station (4)	FW Repairs-Bituminous	Internal		Uncommitted	2735395
3631655	12 number infill areas	27/01/2020	junction maid marion rise (1), junction short street (4), opp 57 (1), entrance petrol station (1), exit petrol station (3), outside school (2)	CW Repairs-Bituminous	Internal		Uncommitted	2735394
<b>Batch:</b> 20368313 - Inspection Batch				<b>Route:</b> Mansfield East Dec Saf CW/FW				<b>Date:</b> 12/12/2019
3627403	7 number infill areas	12/12/2019	outside 33 (1 in channel ) outside 43 (1), outside 53 (2), junction shortstreet (2), spar garage entrance (1)	CW Repairs-Bituminous	Internal		Uncommitted	2731131
<b>Batch:</b> 20364959 - Inspection Batch				<b>Route:</b> Mansfield East Nov Saf CW/FW				<b>Date:</b> 26/11/2019
3625718	5 number infill areas	26/11/2019	outside 53 (2), junction short street (2), petrol station (1)	CW Repairs-Bituminous	Internal		Uncommitted	2729443
<b>Batch:</b> 20360308 - Inspection Batch				<b>Route:</b> Mansfield East Oct Saf CW/FW				<b>Date:</b> 23/10/2019
3623145	2 number infill areas	23/10/2019	entrance jet garage ( 1 footpath infill ), exit jet garage (1 in carriageway )	CW Repairs-Bituminous	Internal		Uncommitted	2726864
<b>Batch:</b> 20355086 - Inspection Batch				<b>Route:</b> Mansfield East Sep Saf CW/FW				<b>Date:</b> 17/09/2019
No actionable defects found								
<b>Batch:</b> 20350356 - Inspection Batch				<b>Route:</b> Mansfield East Aug Enh CW/FW				<b>Date:</b> 15/08/2019
3618090	7 number infill areas	15/08/2019	outside 45 (1), outside 33 (1), jet garage entrance (1), outside 39 (2), windmill fish bar (2 in carriageway )	FW Repairs-Bituminous	Internal		Committed	2721778
3618092	stop and go traffic control	15/08/2019	opp bargain booze	CW Repairs-Bituminous	Internal		Committed	2721780

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,002.00	<b>Feature Id - Locn.:</b> From Clumber Street to Tichfield Street - Pre 01-Mar-2019 was i			<b>Feature Type:</b> Street Section			<b>Area:</b> Mansfield	
<b>Batch:</b> 20345617 - Inspection Batch				<b>Route:</b> Mansfield East Jul Saf CW/FW				<b>Date:</b> 10/07/2019
3615490	replace gully grate bitmac reinstate 1.5 x 1.4	10/07/2019	opp 35a	CW Ironwork	Internal		Committed	2719168
3615489	6 number infill areas	10/07/2019	opp bargain booze (1), opp 33 (1), opp 33b (2),outside 47 (2),	CW Repairs-Bituminous	Internal		Committed	2719167
3615491		10/07/2019	junction maid marion rise	CW Repairs-Bituminous	Internal		Committed	2719169
<b>Batch:</b> 20342766 - Inspection Batch				<b>Route:</b> Mansfield East Jun Saf CW/FW				<b>Date:</b> 21/06/2019
	No actionable defects found							
<b>Batch:</b> 20338027 - Inspection Batch				<b>Route:</b> Mansfield East May Saf CW/FW				<b>Date:</b> 28/05/2019
3611246	5 number infill areas	28/05/2019	spar petrol station (3),top side short street (1), shaping futures (1)	CW Repairs-Bituminous	Internal		Committed	2714908
<b>Batch:</b> 20333610 - Inspection Batch				<b>Route:</b> Mansfield East Apr Saf CW/FW				<b>Date:</b> 26/04/2019
3608198	10 number infill areas	26/04/2019	junction the homesteads (1), junction short street (5), opp short street (1), petrol station exit (2),junction cherry grove (1)	CW Repairs-Bituminous	Internal		Committed	2711849
<b>Batch:</b> 20327658 - Inspection Batch				<b>Route:</b> Mansfield East Mar Saf CW/FW				<b>Date:</b> 19/03/2019
3604524	2 number footpath infills	19/03/2019	outside 33 a (1),outside 35c (1)	FW Repairs-Bituminous	Internal		Committed	2708141
3604523	7 number infill areas	19/03/2019	opp bargain booze (3),junction short street (4)	CW Repairs-Bituminous	Internal		Committed	2708140
<b>Batch:</b> 20323983 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 20/02/2019
3601903	stop tap lid missing lid found on top sandy lane put back in frame by inspectors	20/02/2019	junction top sandy lane outside 171	Other	Internal		Uncommitted	2705480
<b>Batch:</b> 20323936 - Inspection Batch				<b>Route:</b> Mansfield East Feb Saf CW/FW				<b>Date:</b> 20/02/2019
3601894	5 number infill areas	20/02/2019	outside 173 (2),outside 175 (2),outside 187 (1)	CW Repairs-Bituminous	Internal		Committed	2705471
3601891	11 number infill areas	20/02/2019	junction maid marion rise (1),junction short street (5),junction the homesteads (1),spar garage entrance (2), spar garage exit (1),fish shop ( 1 in footpath )	CW Repairs-Bituminous	Internal		Committed	2705468
<b>Batch:</b> 20319074 - Inspection Batch				<b>Route:</b> Mansfield East Jan Saf CW/FW				<b>Date:</b> 17/01/2019
3598634	12 number infill areas	17/01/2019	junction forest rise (2),outside 227 (1),outside 232 (2),outside 248 (4),l bridge (2), lamp 45 (1)	CW Repairs-Bituminous	Internal		Committed	2702137
3598635	2 number footpath infills	17/01/2019	outside 159 (1),outside 191 (1)	FW Repairs-Bituminous	Internal		Committed	2702138
3598630	13 number infill areas	17/01/2019	lamp 25 (3),outside 175 (2),outside 183 (2),outside 189 (2),outside 144 (4)	CW Repairs-Bituminous	Internal		Committed	2702133
3598629	10 number infill areas	17/01/2019	opp bargain booze (1),outside 51 (2),outside 109 (1),junction topsandy lane (6),	CW Repairs-Bituminous	Internal		Committed	2702132

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,002.00	<b>Feature Id - Locn.:</b> From Clumber Street to Tichfield Street - Pre 01-Mar-2019 was i			<b>Feature Type:</b> Street Section			<b>Area:</b> Mansfield	
<b>Batch:</b> 20315367 - Inspection Batch				<b>Route:</b> Mansfield East Dec Saf CW/FW				<b>Date:</b> 13/12/2018
3596278	7 number infill areas	13/12/2018	junction maid marion rise (2),low side maid marion rise (1 in footpath ),opp side short street (1 at rear footpath ) ,outside 113 (2),opp 174 (1)	CW Repairs-Bituminous	Internal		Committed	2699720
<b>Batch:</b> 20312538 - Inspection Batch				<b>Route:</b> Mansfield East Nov Saf CW/FW				<b>Date:</b> 26/11/2018
3594636	provide 6.4 m wooden edgings sides	26/11/2018	outside 199	FW Repairs-Bituminous	Internal		Committed	2698035
3594634	seal patch area	26/11/2018	opp top sandy lane	CW Repairs-Bituminous	Internal		Committed	2698033
3594632	8 number infill areas	26/11/2018	lamp 25 (3),lamp 43 (1),lamp 44 (2),lamp 45 (2),	CW Repairs-Bituminous	Internal		Committed	2698031
3594630	12 number infill areas	26/11/2018	outside 51 (1), junction short street (4), junction oakfield lane (3),opp 191 (2),outside 193 (1),outside 205 (1).	CW Repairs-Bituminous	Internal		Committed	2698029
3594628	5 number infill areas	26/11/2018	fat boy slim ink tattoo (2), classicurls hair salon (1) jet garage (2 in crossing entrance )	FW Repairs-Bituminous	Internal		Committed	2698027
3594626		26/11/2018	bargain booze	CW Repairs-Bituminous	Internal		Committed	2698025
3594637	provide wood edgings sides	26/11/2018	outside 201	FW Repairs-Bituminous	Internal		Committed	2698036
<b>Batch:</b> 20307537 - Inspection Batch				<b>Route:</b> Mansfield East Oct Saf CW				<b>Date:</b> 18/10/2018
3591398	4 number infill areas	18/10/2018	top side bridge (4)	CW Repairs-Bituminous	Internal		Committed	2694752
<b>Batch:</b> 20302854 - Inspection Batch				<b>Route:</b> Mansfield East Sep Saf CW				<b>Date:</b> 19/09/2018
	No actionable defects found							
<b>Batch:</b> 20297924 - Inspection Batch				<b>Route:</b> Mansfield East Aug Enh CW/FW				<b>Date:</b> 14/08/2018
3586736	5 number infill areas	14/08/2018	junction cottage lane (2),outside 210 (1),outside 218 (1),outside 221 (1)	CW Repairs-Bituminous	Internal		Committed	2690010
3586715		14/08/2018	outside 161	FW Repairs-Bituminous	Internal		Committed	2689989
3586735		14/08/2018	outside 250	FW Repairs-Bituminous	Internal		Committed	2690009
3586734		14/08/2018	opp 173	FW Repairs-Bituminous	Internal		Committed	2690008
3586713		14/08/2018	outside 199	FW Repairs-Bituminous	Internal		Committed	2689987
3586732		14/08/2018	opp top sandy lane	FW Repairs-Bituminous	Internal		Committed	2690006
3586731	2 number infill areas	14/08/2018	opp side maid marion rise (1),outside 44 (1)	FW Repairs-Bituminous	Internal		Committed	2690005
3586730	9 number infill areas	14/08/2018	outside 35b (1),outside 25 (2),bargain booze (3),opp side short street (2),outside 132 (1)	CW Repairs-Bituminous	Internal		Committed	2690004
3586729	13 number infill areas	14/08/2018	outside 188 (1),outside 199 (1),outside 139 (1),outside 127 (2),outside 115 (4),outside garage (4)	CW Repairs-Bituminous	Internal		Committed	2690003
3586725		14/08/2018	outside 146	FW Repairs-Bituminous	Internal		Committed	2689999
3586724		14/08/2018	outside 137	CW Repairs-Bituminous	Internal		Committed	2689998
3586722		14/08/2018	120 b	FW Repairs-Bituminous	Internal		Committed	2689996
3586721	provide 10 x 5 kerb STATS REQUIRED	14/08/2018	opp side 51 outside O A P bungalows	Kerbing/Edging	Internal		Committed	2689995
3586720		14/08/2018	opp 33	CW Repairs-Bituminous	Internal		Committed	2689994

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,002.00	<b>Feature Id - Locn.:</b> From Clumber Street to Tichfield Street - Pre 01-Mar-2019 was i			<b>Feature Type:</b> Street Section			<b>Area:</b> Mansfield	
<b>Batch:</b> 20297924 - Inspection Batch				<b>Route:</b> Mansfield East Aug Enh CW/FW				<b>Date:</b> 14/08/2018
3586719	stop and go traffic control	14/08/2018	fish and chip shop	FW Repairs-Bituminous	Internal		Committed	2689993
3586717		14/08/2018	143 to 145	CW Repairs-Bituminous	Internal		Committed	2689991
3586716		14/08/2018	outside 141	CW Repairs-Bituminous	Internal		Committed	2689990
<b>Batch:</b> 20293376 - Inspection Batch				<b>Route:</b> Mansfield East Jul Saf CW				<b>Date:</b> 12/07/2018
	No actionable defects found							
<b>Batch:</b> 20293368 - Inspection Batch				<b>Route:</b> Mansfield East Jul Saf CW				<b>Date:</b> 12/07/2018
3584273	7 number infill areas	12/07/2018	junction cherry grove (2),outside 155 (1),outside 163 (1),outside 167 (3)	CW Repairs-Bituminous	Internal		Committed	2687495
3584265		12/07/2018	outside 121	CW Repairs-Bituminous	Internal		Committed	2687487
<b>Batch:</b> 20291600 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 02/07/2018
3583330	replace 3 number brokeb buff colour tactile slabs	02/07/2018	on corner of Clumber Street outside carols cafe	FW Repairs-Concrete	Internal		Committed	2686527
<b>Batch:</b> 20290603 - Inspection Batch				<b>Route:</b> Mansfield East Jun Saf CW				<b>Date:</b> 26/06/2018
3582871	4 number infill areas	26/06/2018	opp lamp 37 (1),outside 248 (3)	CW Repairs-Bituminous	Internal		Committed	2686063
3582869	plus provide new gully grate STATS REQUIRED	26/06/2018	classiecurls hair salon	CW Repairs-Bituminous	Internal		Committed	2686061
<b>Batch:</b> 20289619 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 19/06/2018
3582256	2 number infill areas	19/06/2018	outside 172 (1), outside 191 (1)	CW Repairs-Bituminous	Internal		Committed	2685430
<b>Batch:</b> 20288163 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 11/06/2018
3581341	replace 1 number 2 metre pedestrian barrier site gap and staggered infill STATS REQUIRED	11/06/2018	low side the homesteads	Guardrail Repairs	Internal		Committed	2684498
<b>Batch:</b> 20285352 - Inspection Batch				<b>Route:</b> Mansfield East May Saf CW				<b>Date:</b> 24/05/2018
3579807	6 number infill areas	24/05/2018	junction maid marion rise (3),outside 53 (2), windmill chippy (1)	CW Repairs-Bituminous	Internal		Committed	2682951
<b>Batch:</b> 20279943 - Inspection Batch				<b>Route:</b> Mansfield East Apr Saf CW				<b>Date:</b> 25/04/2018
3576169	5 number infill areas	25/04/2018	outside 147 (2),outside 189 (3)	CW Repairs-Bituminous	Internal		Committed	2679265
<b>Batch:</b> 20277717 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 16/04/2018
3574800	6 number infill areas	16/04/2018	opp lamp 44 (1),opp lamp 42 (1),lamp 41 (2),junction top sandy lane (1),opp bargain booze (1)	CW Repairs-Bituminous	Internal		Committed	2677863
<b>Batch:</b> 20277713 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 16/04/2018
3574794	PLUS 3 NUMBER INFILL AREAS STOP AND GO TRAFFIC CONTROL REQUIRED	16/04/2018	lamp 45 (top side bridge)	CW Repairs-Bituminous	Internal		Committed	2677857
<b>Batch:</b> 20277319 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 12/04/2018
3574489	previous issued job waiting for repair area infilled by inspectors	12/04/2018	opp short street	CW Repairs-Bituminous	Internal		Uncommitted	2677550

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Customer Services**

**Enquiry No.:** 6165847      **Logged by:** External to Confirm      **on:** 15/04/2020 11:27  
**Service:** Carriageway/Footway      **Subject:** Manholes/Gullies      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-196244685  
**Desc.:** Missing and damaged manhole/drain covers - Large hole in a grate on the floor, large enough that the customers foot went through it. A cone has been placed temporarily and a picture will be provided. . Submitted by Advisor: Matthew Jackson2Customer title is Miss.  
**Location:** Outside the Jet garage on Sherwood Street, Warsop. On the walking pavement next to the garage.      **Contact:**

**Enquiry No.:** 6165726      **Logged by:** External to Confirm      **on:** 09/04/2020 08:52  
**Service:** Carriageway/Footway      **Subject:** Manholes/Gullies      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-193941602  
**Desc.:** Missing and damaged manhole/drain covers - Dmaged manhole cover - Hole in the centre with debris on the top. Submitted by Advisor: [REDACTED] title is [REDACTED]  
**Location:** THE PIN ON THE MAP IS INCORRECT - THE LOCATION OF DAMAGED MANHOLE COVER IS AS BELOW:  
  
Outside the pavement of Castelle Service Station, Sherwood St, Warsop, Mansfield NG20 0JU

**Enquiry No.:** 6164200      **Logged by:** External to Confirm      **on:** 11/03/2020 17:03  
**Service:** Carriageway/Footway      **Subject:** Request new line marking/studs      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-182717060  
**Desc.:** New road marking - Double yellow lines- To stop cars parking in front of customer's property- Cars park on the dropped kerb in front of the property. . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]  
**Location:** outside- 43 Sherwood Street, WARSOP, Warsop, Nottinghamshire, NG20 0JR,      **Contact:**

**Enquiry No.:** 6161613      **Logged by:** External to Confirm      **on:** 27/02/2020 10:27  
**Service:** Carriageway/Footway      **Subject:** Carriageway Damage      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-178422009  
**Desc.:** Road Damage - Customer fell over because of the road surface. He received a fractured wrist which he had to have surgery on and a pin and plate put in. This happened on 12 February. His fall was witnessed by Barry Snowdon council worker and a lady passer by who both came to my aid. . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]  
**Location:** Outside the Greyhound rescue shop, 1 Sherwood Street, Warsop.      **Contact:**

**Enquiry No.:** 6159640      **Logged by:** External to Confirm      **on:** 18/02/2020 17:12  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-175851794  
**Desc.:** Road Pothole - Potholes in the road, causing road surface to be quite gravelly. could do with resurfacing. . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]  
**Location:** junction sherwood street and short street      **Contact:**

**Plot Number:** 2,002.00      **Feature Id - Location:** From Clumber Street to Tichfield Street - Pre 01-Mar-2019 was i      **Feature Type:** Street Section  
**Job Number:** 2735394

**Enquiry No.:** 6159478      **Logged by:** External to Confirm      **on:** 18/02/2020 17:06  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-175851794  
**Desc.:** Road Pothole - Potholes in the road, causing road surface to be quite gravelly. could do with resurfacing. . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]  
**Location:** junction sherwood street and short street      **Contact:**

**Plot Number:** 2,002.00      **Feature Id - Location:** From Clumber Street to Tichfield Street - Pre 01-Mar-2019 was i      **Feature Type:** Street Section  
**Job Number:** 2738292      **Defect Number:** 3634541

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Customer Services**

**Enquiry No.:** 6159224      **Logged by:** External to Confirm      **on:** 17/02/2020 10:54  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-175506256  
**Desc.:** Road Pothole - There are numerous potholes at this location- customer advises around 6-8 small potholes here. They have been here while but are now getting bigger due to the weather. Customer walks past here most days and has noticed they have gotten bigger. . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]  
**Location:** Outside the garage on Sherwood Street, past the junction of Short Street      **Contact:**

**Plot Number:** 2,002.00      **Feature Id - Location:** From Clumber Street to Tichfield Street - Pre 01-Mar-2019 was i      **Feature Type:** Street Section  
**Job Number:** 2738301      **Defect Number:** 3634550

**Enquiry No.:** 6157310      **Logged by:** External to Confirm      **on:** 06/02/2020 11:30  
**Service:** Trees/Verges      **Subject:** Overhanging Vegetation/Trees      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-172863503  
**Desc.:** Overgrown hedges and vegetation - Overgrown hedge at property 123. . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]  
**Location:** Sherwood Street property 123      **Contact:**

**Enquiry No.:** 6156992      **Logged by:** External to Confirm      **on:** 04/02/2020 13:30  
**Service:** Carriageway/Footway      **Subject:** Footway Obstruction      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-172354628  
**Desc.:** Pavement obstructions - Email sent  
We have had one of our customers contact us to report an issue with a pavement obstruction in Warsop Notts.  
He reported anonymously that there is a Beauty Salon on Sherwood Street Warsop NG20 0JT, that is having some work carried out and the builders are using a car parked on the pavement with tape attached to it to cordon off the area.  
Residents are having to walk on the road to avoid the obstruction and the customer is worried that they will be hit by cars as that part of the street is fairly narrow and there is a bend in the road, so motorists cannot see if there are pedestrians in the road.  
He was quite vague where the salon is but he said it is next to an old bank premises.  
He is asking if an inspector could visit the site please to check the safety.  
I do apologise that he didn't provide us with any more information.  
Kind Regards,  
[REDACTED]  
. Submitted by Advisor: [REDACTED] Customer title is Unknown  
**Location:** Sherwood Street Warsop NG20 0JT next to an old bank premises      **Contact:**

**Enquiry No.:** 6156384      **Logged by:** External to Confirm      **on:** 30/01/2020 14:00  
**Service:** Claims      **Subject:** Highway Insurance Claim      **Classification:** Report or Observation      **Enquiry Ref:** FS171301404  
**Desc.:** Insurance claim - related to Confirm defect reference: 6156382  
Date/Time: 03/01/2020 06:30:00  
Direction of travel: Turning right from cottage lane onto sherwood street  
Account of what happened: Was going over the speed bump and it caved in  
Knocked the alignment of it, damaged front near side tyre  
**Location:** Pothole in speed bump on Sherwood street coming off cottage lan      **Contact:**

**Enquiry No.:** 6156382      **Logged by:** External to Confirm      **on:** 30/01/2020 13:58  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-171301404  
**Desc.:** Insurance claim form requested - Road Pothole - \*Now been repaired\*  
Pothole in speed bump on Sherwood street coming off cottage lane  
Damaged vehicle . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]  
**Location:** Pothole in speed bump on Sherwood street coming off cottage lan      **Contact:**

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Customer Services**

**Enquiry No.:** 6140182      **Logged by:** External to Confirm      **on:** 26/09/2019 10:48  
**Service:** Road Works      **Subject:** Road Works Report      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-146171773  
**Desc.:** Road work issue - Virgin media have gone out to complete some road works. Re-tarmacked the pavement but the tarmac has sunk and is now a trip hazard. There are strips of sunken tarmac that need to be filled to level out the pavement.

0.5 - 1 inch in depth.

. Submitted by Advisor: [REDACTED] Customer title is [REDACTED]

**Location:** Sherwood street, Warsop. Road stretching from The Studio hair dressers and the Bargain Booze.      **Contact:**

**Enquiry No.:** 6137120      **Logged by:** External to Confirm      **on:** 22/08/2019 10:27  
**Service:** Carriageway/Footway      **Subject:** Dropped Kerb (Vehicle) Request      **Classification:** Service Request      **Enquiry Ref:** FS-CASE-138923784  
**Desc.:** Dropped kerb - Cars & other vehicles - Dropped kerb . Online report - Quote NOT required 3 whole kerb(s) and 2 tapered kerb(s) to be dropped Position of kerb - Dropped kerb facing the property and more to the left hand side Streetlight - No Customer title is [REDACTED]  
**Location:** 43, Sherwood Street, Warsop, Mansfield, Notts, NG20 0JR      **Contact:**

**Enquiry No.:** 6134339      **Logged by:** External to Confirm      **on:** 25/07/2019 09:18  
**Service:** Trees/Verges      **Subject:** Overhanging Vegetation/Trees      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-133197815  
**Desc.:** Overgrown hedges and vegetation - Hedges are overgrown and blocking access to the footpath. Need trimming back to allow access for wheelchair/buggy access. . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]  
**Location:** Small walk through connected to the highway pavement. Just off Sherwood street. Right hand side, south bound, inbetween the first house and the field just after Oakfield Lane.      **Contact:**

**Enquiry No.:** 6128428      **Logged by:** External to Confirm      **on:** 23/05/2019 08:54  
**Service:** Trees/Verges      **Subject:** Grass Cutting      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-120409605  
**Desc.:** Overgrown grass and verges - grass verges are very overgrown, they have grown over half of the pavement, customer is worried about someone have an accident on them because of the cars going so fast in that area. . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]  
**Location:** SHerwood Street, Warsop, Under the bridge to the windmill      **Contact:**

**Enquiry No.:** 6124960      **Logged by:** External to Confirm      **on:** 05/04/2019 15:57  
**Service:** Traffic Management      **Subject:** Parking General      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-112763579  
**Desc.:** Parking issues - Problem with parents parking close to the school (including on zigzags) around pickup and dropoff times - making it dangerous to drive in surrounding areas because it affects visibility and means children have to cross the road between parked cars.  
Local Councillor [REDACTED] who said traffic wardens daren't enforce zigzags etc because of abuse from parents  
Customer has recommended double yellow lines might be needed

best to inspect the area around 3.00 - 3.15pm when children are being picked up in term time - problem is at its worst . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]  
**Location:** Around Sherwood Junior School  
Sherwood Street, Warsop  
and surrounding streets (eg Titchfield street)      **Contact:**

**Enquiry No.:** 6121025      **Logged by:** External to Confirm      **on:** 25/02/2019 17:45  
**Service:** Carriageway/Footway      **Subject:** Dropped Kerb (Vehicle) Request      **Classification:** Service Request      **Enquiry Ref:** FS-CASE-107068655  
**Desc.:** Dropped kerb - Cars & other vehicles - To drop kerb in front of property as there isnt one at present . Online report - Quote required 3 whole kerb(s) and 2 tapered kerb(s) to be dropped  
Position of kerb - Outside the house Streetlight - No Customer title is [REDACTED]  
**Location:** 43 sherwood street warsop ng20 0qf      **Contact:**

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Customer Services**

**Enquiry No.:** 6113235      **Logged by:** External to Confirm      **on:** 28/11/2018 15:51  
**Service:** Carriageway/Footway      **Subject:** Footway Damage      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-97597764  
**Desc.:** Pavement Damage - There is a ramp and it is causing the customer's house to shake when certain cars drive over it. When lying down/resting you can definitely feel it. The customer seems to think this is due to the cars hitting the ramp at a certain point. . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]  
**Location:** The ramp/wide sleeping policeman in front of the customer's property on the road.      **Contact:**

**Enquiry No.:** 6108518      **Logged by:** External to Confirm      **on:** 08/10/2018 13:24  
**Service:** Carriageway/Footway      **Subject:** Carriageway Damage      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-91047129  
**Desc.:** Road Damage - Speed ramp sinking  
Warsop, Sherwood Street. B6035  
Leading edge of the tarmac ramp has become dangerous and it threw me up in the air and made me come off my bike today.  
Please sort out by either renewing the ramp or PROPERLY REPAIRING the sunk in section. . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]  
**Location:** Warsop, Sherwood Street. B6035      **Contact:**  
Easting/Northing: 456932/367513

**Enquiry No.:** 6103838      **Logged by:** External to Confirm      **on:** 13/08/2018 17:12  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-84706298  
**Desc.:** Road Pothole - There is a lot of potholes on the road, doesn't know how big the pothole are only they have made her fall off of her scooter and injure herself. NCC have repaired some potholes on the road, however there is still a lot on the road that need sorting. . Submitted by Advisor: Faith [REDACTED] title is [REDACTED]  
**Location:** On Short Street, just after the turning off of Sherwood Street.      **Contact:**

**Enquiry No.:** 6102802      **Logged by:** External to Confirm      **on:** 01/08/2018 12:59  
**Service:** Trees/Verges      **Subject:** Overhanging Vegetation/Trees      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-83471537  
**Desc.:** Overhanging trees - Customer has called through to report heavily overgrown and overhanging trees at the side of property 237.  
Previously customers husband used to call through to Network Rail to ask for the tree's to be cut back, This was a while back, the customer today contacted Network Rail to ask for the same thing and was told that it is nothing to do with them and to speak to the council.  
Customer has then spoken with Mansfield District council they said they couldn't do anything either and was advised to speak with [REDACTED].  
Please could this be looked into as the tree's must 50ft high and the customer is concerned that the tree's could cause damage to their property. . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]  
**Location:** Trees are located at the side of property 237.      **Contact:**

**Enquiry No.:** 6100704      **Logged by:** External to Confirm      **on:** 06/07/2018 15:11  
**Service:** Carriageway/Footway      **Subject:** Dropped Kerb (Vehicle) Request      **Classification:** Service Request      **Enquiry Ref:** FS-CASE-80821780  
**Desc.:** Dropped kerb - Cars & other vehicles - I would like to drop a kerb outside my property for access . Online report - Quote NOT required 3 whole kerb(s) and 1 tapered kerb(s) to be dropped  
Position of kerb - 129 Sherwood street, Warsop, NG20 0JX Customer title is [REDACTED]  
**Location:** 129 Sherwood Street      **Contact:**

**Enquiry No.:** 6100159      **Logged by:** External to Confirm      **on:** 02/07/2018 10:01  
**Service:** Carriageway/Footway      **Subject:** Footway Damage      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-80268118  
**Desc.:** Pavement Damage - Several cracked pavement slabs approx 2 loose needs looking as a trip hazard . Submitted by Advisor: [REDACTED] Customer title is [REDACTED]  
**Location:** on corner of Clumber Street and Sherwood Street loose pavement slabs opposite bargain booze .      **Contact:**

Plot Number: 2,002.00

Feature Id - Location: From Clumber Street to Tichfield Street - Pre 01-Mar-2019 was i

Feature Type: Street Section

Job Number: 2686527

Defect Number: 3583330

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Customer Services**

<b>Enquiry No.:</b> 6098799	<b>Logged by:</b> External to Confirm	<b>on:</b> 16/06/2018 17:03	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Carriageway Pothole	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-78973750
<b>Desc.:</b> Road Pothole - 5cm to 6cm deep hole where the speed hump starts . Online report Customer title is			
<b>Location:</b> outside 172 Sherwood Street, full width speed hump.		<b>Contact:</b>	
<b>Plot Number:</b> 2,002.00	<b>Feature Id - Location:</b> From Clumber Street to Tichfield Street - Pre 01-Mar-2019 was i		<b>Feature Type:</b> Street Section
<b>Job Number:</b> 2685430	<b>Defect Number:</b> 3582256		
<b>Enquiry No.:</b> 6097914	<b>Logged by:</b> External to Confirm	<b>on:</b> 08/06/2018 11:30	
<b>Service:</b> Traffic Management	<b>Subject:</b> Parking General	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-78138878
<b>Desc.:</b> Parking issues - I have recently had to revert to using a wheelchair getting to town is becoming difficult due to parked cars and the state of the pavements . Online report Customer title is Mr.			
<b>Location:</b> From sherwood street to town centre		<b>Contact:</b>	
<b>Enquiry No.:</b> 6097863	<b>Logged by:</b> External to Confirm	<b>on:</b> 08/06/2018 08:16	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Carriageway Obstruction	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-78108847
<b>Desc.:</b> Road obstructions - Appears to have been an RTC overnight, problem with the barrier, the railing is snapped into the footpath, I've managed to bend it back around, the light is broken and water is going to get in, please call on my work mobile I can return the dome it is not broken but I took it to keep secure so kids don't get to it. I work for Mansfield District council as a street cleaner. .			
<b>Submitted by Advisor:</b> ██████████ <b>Customer title is</b> ██████████			
<b>Location:</b> Outside 3 and 4 Sherwood Street in Warsop.		<b>Contact:</b>	
<b>Plot Number:</b> 2,002.00	<b>Feature Id - Location:</b> From Clumber Street to Tichfield Street - Pre 01-Mar-2019 was i		<b>Feature Type:</b> Street Section
<b>Job Number:</b> 2684498	<b>Defect Number:</b> 3581341		
<b>Enquiry No.:</b> 6092869	<b>Logged by:</b> External to Confirm	<b>on:</b> 24/04/2018 10:51	
<b>Service:</b> Traffic Management	<b>Subject:</b> Parking General	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-73712517
<b>Desc.:</b> Parking issues - There are issues with people parking on the jct. which causes visibility issues when pulling onto Sherwood Street. Its a rather busy road as Lorries and cars use this for the recycle centre nearby. Cars need to edge out to see which is dangerous. Is worried an accident could happen if nothing is done. The ideal thing would be yellow lines so far back from the jct. People may also park here if they need to take a call when in their car. . Submitted by Advisor: ██████████ <b>Customer title is</b> ██████████			
<b>Location:</b> Jct of Sherwood Street and Oakfield Lane.		<b>Contact:</b>	
<b>Enquiry No.:</b> 6091981	<b>Logged by:</b> External to Confirm	<b>on:</b> 16/04/2018 14:11	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Blocked Drain	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-73021578
<b>Desc.:</b> Blocked drains - Drain on pavement - liquid is seeping out the the cover and a very unpleasant smell !!. Submitted by Advisor: ██████████ <b>toCustomer title is</b> ██████████			
<b>Location:</b> Outside Tung Kong takeaway on Sherwood street Warsop		<b>Contact:</b>	
<b>Enquiry No.:</b> 6091557	<b>Logged by:</b> External to Confirm	<b>on:</b> 12/04/2018 19:41	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Carriageway Pothole	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-72771199
<b>Desc.:</b> Road Pothole - Large hole in road thats been previously attempted to be repaired and now has all lifted and holed, and another one thats a 100yards further up on the opposite side of the road opposite blakley Lane turning . Online report			
<b>Location:</b> Warsop, heading towards forest road under the train bridge right where the wheels run		<b>Contact:</b>	
<b>Plot Number:</b> 2,002.00	<b>Feature Id - Location:</b> From Clumber Street to Tichfield Street - Pre 01-Mar-2019 was i		<b>Feature Type:</b> Street Section
<b>Job Number:</b> 2677857	<b>Defect Number:</b> 3574794		
<b>Enquiry No.:</b> 2506692	<b>Logged by:</b> ██████████	<b>on:</b> 29/11/2019 08:41	
<b>Service:</b> Bridges/Structures	<b>Subject:</b> Bridges/Structures Damage	<b>Classification:</b> Report or Observation	
<b>Desc.:</b> Good afternoon ██████████, we have been given the opportunity as a council to acquire the asset below (old mineral line). Looking at liability are any of the bridges highway assets?			
<b>Location:</b> various locations from warsop to meden vale		<b>Contact:</b>	

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Customer Services**

<b>Enquiry No.:</b> 2506164	<b>Logged by:</b> [REDACTED]	<b>on:</b> 04/06/2019 11:59
<b>Service:</b> Traffic Management	<b>Subject:</b> Parking General	<b>Classification:</b> Report or Observation
<b>Desc.:</b> parent parking on junctions		
<b>Location:</b> sherwood street warsop near burns lane	<b>Contact:</b>	
<b>Enquiry No.:</b> 2506025	<b>Logged by:</b> [REDACTED]	<b>on:</b> 24/04/2019 11:29
<b>Service:</b> Trees/Verges	<b>Subject:</b> Overhanging Vegetation/Trees	<b>Classification:</b> Report or Observation
<b>Desc.:</b> vegetation on the junction		
<b>Location:</b> near junction of Maid Marion Rise	<b>Contact:</b>	
<b>Enquiry No.:</b> 2505701	<b>Logged by:</b> [REDACTED]	<b>on:</b> 04/10/2018 13:35
<b>Service:</b> Traffic Management	<b>Subject:</b> Weight/Height Restrictions	<b>Classification:</b> Report or Observation
<b>Desc.:</b> Customer has called to advised that there is a lorry park, nearby and the HGV'S drive down the road more likly very fast. When they go over the speed bumps this is causing the customer alot of distress and by load noise and also customer has advised that his property shakes. Customer has advised that he has reported this in the past year.		
<b>Location:</b>	<b>Contact:</b>	
<b>Enquiry No.:</b> 86430	<b>Logged by:</b> [REDACTED]	<b>on:</b> 02/03/2020 13:46
<b>Service:</b> Highway Searches	<b>Subject:</b> CON29	<b>Classification:</b> Report or Observation
<b>Desc.:</b> CON enquiry - £20.40 - 2.3.2020		
<b>Location:</b> 23 Sherwood Street, Warsop, Mansfield NG20 0JP	<b>Contact:</b>	
<b>Enquiry No.:</b> 85733	<b>Logged by:</b> [REDACTED]	<b>on:</b> 06/02/2020 14:51
<b>Service:</b> Licences/Permits	<b>Subject:</b> Scaffold Licence Request	<b>Classification:</b> Service Request
<b>Desc.:</b> Scaffolding 4m long x 10m high x 1.2m wide to be sited from 11/02/20 to 24/02/20 Licence fee is £99 - paid VIAPH2578 Want 1 week extension to 02/03/20 £77 - paid. Licence extended to 09/03/20. Wish to extend licence to 23/03/20		
<b>Location:</b> Number 23	<b>Contact:</b>	
<b>Plot Number:</b> 2,002.00	<b>Feature Id - Location:</b> From Clumber Street to Tichfield Street - Pre 01-Mar-2019 was i	<b>Feature Type:</b> Street Section
<b>Enquiry No.:</b> 82157	<b>Logged by:</b> [REDACTED]	<b>on:</b> 02/09/2019 14:04
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Footway Obstruction	<b>Classification:</b> Report or Observation
<b>Desc.:</b> Plannng Application for 2 bollards to be fitted in front of an ATM cash machine. Formal notice. Response not expected.		
<b>Location:</b> 19-21	<b>Contact:</b>	
<b>Plot Number:</b> 2,002.00	<b>Feature Id - Location:</b> From Clumber Street to Tichfield Street - Pre 01-Mar-2019 was i	<b>Feature Type:</b> Street Section
<b>Enquiry No.:</b> 78155	<b>Logged by:</b> [REDACTED]	<b>on:</b> 21/02/2019 15:26
<b>Service:</b> Trees/Verges	<b>Subject:</b> Planters	<b>Classification:</b> Report or Observation
<b>Desc.:</b> I have a councillor in Warsop who is wanting to install ground standing flower boxes by the various Warsop (boundary) signs. I assume that these are all on highway land therefore could you please advise who he should contact?		
<b>Location:</b> Warsop village signs	<b>Contact:</b>	
<b>Enquiry No.:</b> 77531	<b>Logged by:</b> [REDACTED]	<b>on:</b> 28/01/2019 14:23
<b>Service:</b> Traffic Management	<b>Subject:</b> Traffic Calming	<b>Classification:</b> Report or Observation
<b>Desc.:</b> Request for removal of traffic calming or reduction in size on noise grounds		
<b>Location:</b> Near 174	<b>Contact:</b>	
<b>Enquiry No.:</b> 76365	<b>Logged by:</b> [REDACTED]	<b>on:</b> 23/11/2018 15:18
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Dropped Kerb (Vehicle) Request	<b>Classification:</b> Service Request
<b>Desc.:</b> Standard 5 kerb access required for disabled gentleman (OT reccommendation for grant for hard standing).		
<b>Location:</b> 17A The Homesteads, Sherwood Street	<b>Contact:</b>	

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Customer Services**

**Enquiry No.:** 75051      **Logged by:** [REDACTED]      **on:** 05/10/2018 15:24  
**Service:** Traffic Management      **Subject:** Pedestrian Crossing Request      **Classification:** Service Request  
**Desc.:** Request for new zebra crossing in the absence of being able to recruit a school crossing patrol here.  
**Location:** Outside Sherwood Junior School      **Contact:**

**Enquiry No.:** 71790      **Logged by:** [REDACTED]      **on:** 18/05/2018 11:16  
**Service:** Carriageway/Footway      **Subject:** Carriageway Damage      **Classification:** Report or Observation  
**Desc.:** See attached Letters. The constituent is complaining about the road surface conditions at this location.  
**Location:** Sherwood Street      **Contact:**

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Feat No.:</b> 2,002.00	<b>Feature Id - Locn.:</b> From Clumber Street to Tichfield Street - Pre 01-Mar-2019 was			<b>Feature Type:</b> Street Section		<b>Area:</b> Mansfield	
2671550	2 seperate patches 5.2x1.0 ,3.3x1.0 (CW Repairs-Bituminous)	junction cottage lane	Category 3	Job Completed	20/02/2018	13/04/2018	Act. MAN/3504474
2671555	CW Repairs-Bituminous	outside 94	Category 3	Job Completed	20/02/2018	13/04/2018	Act. MAN/3504475
2673895	CW Repairs-Bituminous	junction cherry grove	Category 3	Job Completed	14/03/2018	13/04/2018	Act. MAN/3504592
2675234	3 number infill areas (CW Repairs-Bituminous)	petrol station in and out entrances	Category 2	Job Completed	22/03/2018	13/04/2018	Act. MAN-AS/5404633
2675494	Carriageway Damage - Carriageway ptch required (Enquiry 3206084)	Opposite The Homesteads	Category 3	Job Completed	26/03/2018	27/04/2018	Act. MAN/3504653
2677550	previous issued job waiting for repair area infilled by inspectors (CW Repairs-Bituminous)	opp short street	Filled when found (Cat 1)	Job Completed	12/04/2018	12/04/2018	Act.
2677857	PLUS 3 NUMBER INFILL AREAS STOP AND GO TRAFFIC CONTROL REQUIRED (CW Repairs-Bituminous)	lamp 45 (top side bridge)	Category 2	Job Completed	16/04/2018	06/06/2018	Act. MAN/3504758
2677863	6 number infill areas (CW Repairs-Bituminous)	opp lamp 44 (1),opp lamp 42 (1),lamp 41 (2),junction top sandy lane (1),opp bargain booze (1)	Category 2	Job Completed	16/04/2018	16/04/2018	Act. MAN-AS/5404770
2679265	5 number infill areas (CW Repairs-Bituminous)	outside 147 (2),outside 189 (3)	Category 2	Job Completed	25/04/2018	26/04/2018	Act. MAN-AS/5404881
2682951	6 number infill areas (CW Repairs-Bituminous)	junction maid marion rise (3),outside 53 (2), windmill chippy (1)	Category 2	Job Completed	24/05/2018	29/05/2018	Act. MAN-AS/5405124
2684498	replace 1 number 2 metre pedestrian barrier site gap and staggered infill STATS REQUIRED (Guardrail Repairs)	low side the homesteads: STATS 456879 - 367670	Category 3	Job Completed	11/06/2018	04/07/2018	Act. MAN/3505064
2685430	2 number infill areas (CW Repairs-Bituminous)	outside 172 (1), outside 191 (1)	Category 2	Job Completed	20/06/2018	20/06/2018	Act. MAN-AS/5405256

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Feat No.:</b> 2,002.00	<b>Feature Id - Locn.:</b> From Clumber Street to Tichfield Street - Pre 01-Mar-2019 was i		<b>Feature Type:</b> Street Section		<b>Area:</b> Mansfield	
2686061	plus provide new gully grate STATS REQUIRED (CW Repairs-Bituminous)	classiecurls hair salon: STATS 456789 - 367811	Category 3	Job Completed	26/06/2018	18/07/2018	Act. MAN/3505189
2686063	4 number infill areas (CW Repairs-Bituminous)	opp lamp 37 (1),outside 248 (3)	Category 2	Job Completed	26/06/2018	28/06/2018	Act. MAN-AS/5405296
2686527	replace 3 number brokeb buff colour tactile slabs (FW Repairs-Concrete)	on corner of Clumber Street outside carols cafe	Category 2	Job Completed	03/07/2018	05/07/2018	Act. MAN/3505215
2687487	CW Repairs-Bituminous	outside 121	Category 3	Job Completed	12/07/2018	07/09/2018	Act. MAN/3505287
2687495	7 number infill areas (CW Repairs-Bituminous)	junction cherry grove (2),outside 155 (1),outside 163 (1),outside 167 (3)	Category 2	Job Completed	12/07/2018	16/07/2018	Act. MAN-AS/5405393
2689987	FW Repairs-Bituminous	outside 199	Category 3	Job Completed	14/08/2018	21/09/2018	Act. MAN/3505424
2689989	FW Repairs-Bituminous	outside 161	Category 3	Job Completed	14/08/2018	18/09/2018	Act. MAN/3505425
2689990	CW Repairs-Bituminous	outside 141	Category 3	Job Completed	14/08/2018	07/09/2018	Act. MAN/3505426
2689991	stop and go traffic control (CW Repairs-Bituminous)	143 to 145	Category 3	Job Completed	14/08/2018	10/09/2018	Act. MAN/3505427
2689993	FW Repairs-Bituminous	fish and chip shop	Category 3	Job Completed	14/08/2018	20/09/2018	Act. MAN/3505428
2689994	CW Repairs-Bituminous	opp 33	Category 3	Job Completed	14/08/2018	07/09/2018	Act. MAN/3505429
2689995	provide 10 x 5 kerb STATS REQUIRED (Kerbing/Edging)	opp side 51 outside O A P bungalows: STATS 456860 - 367682	Category 2	Job Completed	14/08/2018	30/08/2018	Act. MAN/3505430
2689996	FW Repairs-Bituminous	120 b	Category 3	Job Completed	14/08/2018	28/09/2018	Act. MAN/3505431
2689998	CW Repairs-Bituminous	outside 137	Category 3	Job Completed	14/08/2018	10/09/2018	Act. MAN/3505432
2689999	FW Repairs-Bituminous	outside 146	Category 3	Job Completed	14/08/2018	21/09/2018	Act. MAN/3505433
2690003	13 number infill areas (CW Repairs-Bituminous)	outside 188 (1),outside 199 (1),outside 139 (1),outside 127 (2),outside 115 (4),outside garage (4)	Category 3	Job Completed	14/08/2018	15/08/2018	Act. MAN-AS/5405517
2690004	9 number infill areas (CW Repairs-Bituminous)	outside 35b (1),outside 25 (2),bargain booze (3),opp side short street (2),outside 132 (1)	Category 3	Job Completed	14/08/2018	15/08/2018	Act. MAN-AS/5405518
2690005	2 number infill areas (FW Repairs-Bituminous)	opp side maid marion rise (1),outside 44 (1)	Category 2	Job Completed	14/08/2018	15/08/2018	Act. MAN-AS/5405519
2690006	FW Repairs-Bituminous	opp top sandy lane	Category 3	Job Completed	14/08/2018	20/09/2018	Act. MAN/3505434
2690008	FW Repairs-Bituminous	opp 173	Category 3	Job Completed	14/08/2018	18/09/2018	Act. MAN/3505435
2690009	FW Repairs-Bituminous	outside 250	Category 3	Job Completed	14/08/2018	19/09/2018	Act. MAN/3505436
2690010	5 number infill areas (CW Repairs-Bituminous)	junction cottage lane (2),outside 210 (1),outside 218 (1),outside 221 (1)	Category 3	Job Completed	14/08/2018	15/08/2018	Act. MAN-AS/5405520
2694752	4 number infill areas (CW Repairs-Bituminous)	top side bridge (4)	Category 2	Job Completed	18/10/2018	19/10/2018	Act. MAN-AS/5405905
2698025	CW Repairs-Bituminous	bargain booze	Category 2	Job Completed	26/11/2018	13/12/2018	Act. MAN/3505949

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Feat No.:</b> 2,002.00	<b>Feature Id - Locn.:</b> From Clumber Street to Tichfield Street - Pre 01-Mar-2019 was i		<b>Feature Type:</b> Street Section		<b>Area:</b> Mansfield	
2698027	5 number infill areas (FW Repairs-Bituminous)	fat boy slim ink tattoo (2), classicurls hair salon (1) jet garage (2 in crossing entrance )	Category 2	Job Completed	26/11/2018	29/11/2018	Act. MAN-AS/5406215
2698029	12 number infill areas (CW Repairs-Bituminous)	outside 51 (1), junction short street (4), junction oakfield lane (3),opp 191 (2),outside 193 (1),outside 205 (1).	Category 2	Job Completed	26/11/2018	29/11/2018	Act. MAN-AS/5406217
2698031	8 number infill areas (CW Repairs-Bituminous)	lamp 25 (3),lamp 43 (1),lamp 44 (2),lamp 45 (2),	Category 2	Job Completed	26/11/2018	29/11/2018	Act. MAN-AS/5406219
2698033	seal patch area (CW Repairs-Bituminous)	opp top sandy lane	Category 2	Job Completed	26/11/2018	12/12/2018	Act. MAN/3505950
2698035	provide 6.4 m wooden edgings sides (FW Repairs-Bituminous)	outside 199: STATS 457124 - 367041	Category 3	Job Completed	26/11/2018	11/12/2018	Act. MAN/3505951
2698036	provide wood edgings sides (FW Repairs-Bituminous)	outside 201	Category 3	Job Completed	26/11/2018	11/12/2018	Act. MAN/3505952
2699720	7 number infill areas (CW Repairs-Bituminous)	junction maid marion rise (2),low side maid marion rise (1 in footpath ),opp side short street (1 at rear footpath ) ,outside 113 (2),opp 174 (1)	Category 2	Job Completed	13/12/2018	18/12/2018	Act. MAN-AS/5406442
2702132	10 number infill areas (CW Repairs-Bituminous)	opp bargain booze (1),outside 51 (2),outside 109 (1),junction topsandy lane (6),	Category 2	Job Completed	17/01/2019	18/01/2019	Act. MAN-AS/5406613
2702133	13 number infill areas (CW Repairs-Bituminous)	lamp 25 (3),outside 175 (2),outside 183 (2),outside 189 (2),outside 144 (4)	Category 2	Job Completed	17/01/2019	18/01/2019	Act. MAN-AS/5406614
2702137	12 number infill areas (CW Repairs-Bituminous)	junction forest rise (2),outside 227 (1),outside 232 (2),outside 248 (4),l bridge (2), lamp 45 (1)	Category 2	Job Completed	17/01/2019	18/01/2019	Act. MAN-AS/5406615
2702138	2 number footpath infills (FW Repairs-Bituminous)	outside 159 (1),outside 191 (1)	Category 2	Job Completed	17/01/2019	18/01/2019	Act. MAN-AS/5406616
2705468	11 number infill areas (CW Repairs-Bituminous)	junction maid marion rise (1),junction short street (5),junction the homesteads (1),spar garage entrance (2), spar garage exit (1),fish shop ( 1 in footpath )	Category 2	Job Completed	20/02/2019	22/02/2019	Act. MAN-AS/5406861
2705471	5 number infill areas (CW Repairs-Bituminous)	outside 173 (2),outside 175 (2),outside 187 (1)	Category 2	Job Completed	20/02/2019	22/02/2019	Act. MAN-AS/5406862
2705480	stop tap lid missing lid found on top sandy lane put back in frame by inspectors (Other)	junction top sandy lane outside 171	Filled when found (Cat 1)	Job Completed	20/02/2019	20/02/2019	Act.
2708140	7 number infill areas (CW Repairs-Bituminous)	opp bargain booze (3),junction short street (4)	Category 2	Job Completed	19/03/2019	21/03/2019	Act. MAN-AS/5407063
2708141	2 number footpath infills (FW Repairs-Bituminous)	outside 33 a (1),outside 35c (1)	Category 2	Job Completed	19/03/2019	21/03/2019	Act. MAN-AS/5407064

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Feat No.:</b> 2,002.00	<b>Feature Id - Locn.:</b> From Clumber Street to Tichfield Street - Pre 01-Mar-2019 was i		<b>Feature Type:</b> Street Section		<b>Area:</b> Mansfield	
2711849	10 number infill areas (CW Repairs-Bituminous)	junction the homesteads (1), junction short street (5), opp short street (1), petrol station exit (2),junction cherry grove (1)	Category 2	Job Completed	26/04/2019	29/04/2019	Act. MAN-AS/5407372
2714908	5 number infill areas (CW Repairs-Bituminous)	spar petrol station (3),top side short street (1), shaping futures (1)	Category 2	Job Completed	28/05/2019	29/05/2019	Act. MAN-AS/5407589
2719167	6 number infill areas (CW Repairs-Bituminous)	opp bargain booze (1), opp 33 (1), opp 33b (2),outside 47 (2), opp 35a	Category 2	Job Completed	10/07/2019	12/07/2019	Act. MAN-AS/5407877
2719168	replace gully grate bitmac reinstate 1.5 x 1.4 (CW Ironwork)	opp 35a	Category 2	Job Completed	10/07/2019	16/07/2019	Act. MAN/3506994
2719169	CW Repairs-Bituminous	junction maid marion rise	Category 2	Job Completed	10/07/2019	16/07/2019	Act. MAN/3506993
2721778	7 number infill areas (FW Repairs-Bituminous)	outside 45 (1),outside 33 (1), jet garage entrance (1),outside 39 (2),windmill fish bar (2 in carriageway )	Category 2	Job Completed	15/08/2019	16/08/2019	Act. MAN-AS/5408078
2721780	stop and go traffic control (CW Repairs-Bituminous)	opp bargain booze	Category 3	Job Completed	15/08/2019	06/09/2019	Act. MAN/3507187
2726864	2 number infill areas (CW Repairs-Bituminous)	entrance jet garage ( 1 footpath infill ), exit jet garage (1in carriageway )	Category 2	Repair Completed	23/10/2019	25/10/2019	Act.
2729443	5 number infill areas (CW Repairs-Bituminous)	outside 53 (2),junction short street (2), petrol station (1)	Category 2	Repair Completed	26/11/2019	28/11/2019	Act.
2731131	7 number infill areas (CW Repairs-Bituminous)	outside 33 (1 in channel ) outside 43 (1),outside 53 (2),junction shortstreet (2), spar garage entrance (1)	Category 2	Repair Completed	12/12/2019	24/12/2019	Act.
2735394	12 number infill areas (CW Repairs-Bituminous)	junction maid marion rise (1),junction short street (4),opp 57 (1),entrance petrol station (1),exit petrol station (3), outside school (2)	Category 2	Repair Completed	27/01/2020	30/01/2020	Act.
2735395	5 number infill areas (FW Repairs-Bituminous)	outside 43 (1), entrance petrol station (4)	Category 2	Repair Completed	27/01/2020	30/01/2020	Act.
2738292	infill area (CW Repairs-Bituminous)	junction sherwood street and short street	Category 2	Job Completed	25/02/2020	03/03/2020	Act. MAN/3507968
2738301	4 number infill areas (CW Repairs-Bituminous)	Outside the garage ( 3 on entrance , 1 on exit)	Category 2	Job Completed	25/02/2020	03/03/2020	Act. MAN/3507971
2741812	infill area (CW Repairs-Bituminous)	junction short street	Category 1	Repair Completed	20/04/2020	21/04/2020	Act.
2741813	infill area (CW Repairs-Bituminous)	opp 252	Category 1	Repair Completed	20/04/2020	21/04/2020	Act.

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Street Works Inspections**

Organisation: BT (0030006)

Works Ref: T1001MW500275173000

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 19/06/2019 12:44:48
<b>Category:</b> Category B		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Site Location:</b> O/S 150, SHERWOOD STREET
<b>Insp. Notes:</b>			<b>Position:</b> Carriageway
<b>Defect Notes:</b>			<b>Sampled Site No:</b> 1
			<b>Site Post Code:</b>

Organisation: NRSWA - Cadent Gas EM (0010001) (Street Works Admin Team NG Gas)

Works Ref: 1000681120

<b>Group No:</b> 1	<b>Site No:</b> 2	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 21/01/2020 10:56:18
<b>Category:</b> Category C		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Site Location:</b> IN ROAD O/SIDE 149
<b>Insp. Notes:</b>			<b>Position:</b> Carriageway
<b>Defect Notes:</b>			<b>Sampled Site No:</b> 2
			<b>Site Post Code:</b>

Organisation: NRSWA - Virgin Media - National (7160100)

Works Ref: /NEMBPL/ID111135/B

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 07/10/2019 12:36:57
<b>Category:</b> Category A		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Site Location:</b> From outside number 206 to outside number 258
<b>Insp. Notes:</b>			<b>Position:</b> Footway
<b>Defect Notes:</b>			<b>Sampled Site No:</b> 1
			<b>Site Post Code:</b>

Organisation: Severn Trent Water East (9103908)

Works Ref: 1101/000060199600

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 06/09/2018 10:54:59
<b>Category:</b> Category C		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Site Location:</b> OPPOSITE 163
<b>Insp. Notes:</b>			<b>Position:</b> Footway
<b>Defect Notes:</b>			<b>Sampled Site No:</b> 1
			<b>Site Post Code:</b>

Organisation: WPD 5134 Mansfield (7011534)

Works Ref: M51340478382

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 17/06/2019 11:42:55
<b>Category:</b> Category A		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> Yes
			<b>Sign./Light./Guard. Inadequacy:</b> No
			<b>Site Location:</b> OUTSIDE 19
<b>Insp. Notes:</b>			<b>Position:</b> Footway
<b>Defect Notes:</b>			<b>Sampled Site No:</b> 1
			<b>Site Post Code:</b>

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Street Works Notices****Organisation:** BT (0030006)**Works Ref:** T1001MW500275173000**Version:** 8**Work Desc:** permanent reinstatement of carriageway works**Notice Type:** Registration of Reinstatement - Full**Start:** 19/03/2019 00:00:00**Work Status:** Works Stopped**Issued:** 19/03/2019 14:41:16**Work Type:** EToN 4: Minor**Est. End:** 19/03/2019**Completion:** 19/03/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	O/S 150, SHERWOOD STREET	Carriageway	Up to 1.5 Metres of Cover	2.00	1.00 A Permanent Reinstatement	19/03/2019	20/02/2019	19/03/2019	18/03/2019

**Works Ref:** T1001MW500280598900**Version:** 2**Work Desc:** Install 2m of 1 way poly duct in Footway,Install 9m of 1 way poly duct in Carriageway**Notice Type:** Cancellation**Start:** 11/08/2019 00:00:00**Work Status:** Abandoned Works**Issued:** 15/08/2019 08:26:22**Work Type:** EToN 4: Minor**Est. End:** 14/08/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	FROM JCNT WITH HIGH STREET AND ACROSS C/W TO JCTN WITH BURNS LANE ON, SHERWOOD STREET	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	11/08/2019			14/08/2019

**Works Ref:** T1001MW500280598902**Version:** 4**Work Desc:** Install 2m of 1 way poly duct in Footway,Install 9m of 1 way poly duct in Carriageway**Notice Type:** Registration of Reinstatement - Full**Start:** 03/11/2019 00:00:00**Work Status:** Works Stopped**Issued:** 19/11/2019 13:32:50**Work Type:** EToN 4: Minor**Est. End:** 06/11/2019**Completion:** 06/11/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	FROM JCNT WITH HIGH STREET AND ACROSS C/W TO JCTN WITH BURNS LANE ON, SHERWOOD STREET	Carriageway	Up to 1.5 Metres of Cover	10.00	0.40 A Permanent Reinstatement	06/11/2019		06/11/2019	06/11/2019

**Organisation:** NCC - MANSFIELD (3055003)**Works Ref:** 30502314**Version:** 1**Work Desc:** Warsop Carnival**Notice Type:** 3 Month Initial Notice**Start:** 08/07/2018 00:00:00**Work Status:** Proposed Works**Issued:** 05/07/2018 14:43:11**Work Type:** EToN 4: Major**Est. End:** 08/07/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Shwerwoos Street from its junction with Totchfield Street to its junction of HighjStreet	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	08/07/2018			08/07/2018

**Works Ref:** 6150995**Version:** 1**Work Desc:** Construct Vehicle Access**Notice Type:** 3 Day Initial Notice**Start:** 01/02/2020 00:00:00**Work Status:** Proposed Works**Issued:** 31/01/2020 09:21:16**Work Type:** EToN 4: Minor**Est. End:** 01/02/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside No. 43	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	01/02/2020			01/02/2020

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Street Works Notices****Organisation:** Network Rail BUILDING AND CIVILS (B&C) (7093644)**Works Ref:** WKC/1/A**Version:** 4**Work Desc:** 0800-1700. Painting, de vegetation, steelwork repairs.**Notice Type:** Works Stop**Start:** 27/08/2019 00:00:00**Work Status:** Works Stopped**Issued:** 02/09/2019 08:15:41**Work Type:** ETon 4: Major**Est. End:** 30/08/2019**Completion:** 30/08/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Bridge (Rail Over Road) referenced by Network Rail as - ELR: WKC No:1	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	30/08/2019			30/08/2019

**Organisation:** Network Rail STRUCTURES ASSESSMENT (7093645)**Works Ref:** 20180716WKC1**Version:** 3**Work Desc:** Bridge examination. Hours of works 08.00 - 16.00**Notice Type:** Works Stop**Start:** 16/07/2018 00:00:00**Work Status:** Works Stopped**Issued:** 17/07/2018 08:52:58**Work Type:** ETon 4: Minor**Est. End:** 16/07/2018**Completion:** 16/07/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Bridge referenced by Network Rail as WKC 1	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	16/07/2018			16/07/2018

**Organisation:** North East Public Lighting Moor Green Sleaford (7011030)**Works Ref:** /49627**Version:** -3**Work Desc:** DISCONNECTION,NEW CONNECTION AND TRANSFER OF SERVICE ENQ. NO. 400010217**Notice Type:** Actual Start Date**Start:** 20/04/2009 00:00:00**Work Status:** In Progress**Issued:** 20/04/2009 09:52:44**Work Type:** ETon 4: Major**Est. End:** 01/01/4000**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	SERVICES TO VARIOUS CLOUMN X41	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	01/01/4000		21/04/2009	08/05/2009
2	OUTSIDE 216 100333956	Footway	Over 1.5 Metres of Cover	0.01	0.01	A Permanent Reinstatement	23/04/2009		23/04/2009	
3	OUTSIDE 206 100333955	Footway	Over 1.5 Metres of Cover	0.01	0.01	A Permanent Reinstatement	23/04/2009		23/04/2009	
4	OPPOSITE 205 100333952 TCE2175	Footway	Over 1.5 Metres of Cover	0.01	0.01	A Permanent Reinstatement	23/04/2009		23/04/2009	
5	OUTSIDE 204 100333953 TCE2176	Footway	Over 1.5 Metres of Cover	0.01	0.01	A Permanent Reinstatement	23/04/2009		23/04/2009	
6	OPPOSITE 193 100333950 TCE2177	Footway	Over 1.5 Metres of Cover	0.01	0.01	A Permanent Reinstatement	23/04/2009		23/04/2009	
7	OUTSIDE 188 100333951 TCE2178	Footway	Over 1.5 Metres of Cover	0.01	0.01	A Permanent Reinstatement	23/04/2009		23/04/2009	
8	OUTSIDE 246 100333958 TCE2179	Footway	Over 1.5 Metres of Cover	0.01	0.01	A Permanent Reinstatement	23/04/2009		23/04/2009	
9	O/S PROPERTY 216 TCE2157	Footway	Up to 1.5 Metres of Cover	4.80	0.30	A Permanent Reinstatement	21/04/2009		21/04/2009	
10	O/S PROPERTY 206 TCE2158	Footway	Up to 1.5 Metres of Cover	2.10	0.30	A Permanent Reinstatement	21/04/2009		21/04/2009	
11	O/S PROPERTY 216 TCE2157	Footway	Up to 1.5 Metres of Cover	1.80	0.60	A Permanent Reinstatement	21/04/2009		21/04/2009	
12	O/S PROPERTY 206 TCE2158	Footway	Up to 1.5 Metres of Cover	1.10	0.80	A Permanent Reinstatement	21/04/2009		21/04/2009	

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Street Works Notices****Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** /HW20614**Version:** 1**Work Desc:** Carriageway resurfacing works along Sherwood St, Warsop.**Notice Type:** 3 Month Initial Notice**Start:** 29/07/2019 00:00:00**Work Status:** Proposed Works**Issued:** 17/05/2019 08:31:42**Work Type:** EToN 4: Major**Est. End:** 02/08/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Sherwood St, Warsop	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	29/07/2019			02/08/2019

**Works Ref:** /SHERWOOD210619**Version:** 1**Work Desc:** Gully Cleansing**Notice Type:** 10 Day Initial Notice**Start:** 24/06/2019 00:00:00**Work Status:** Proposed Works**Issued:** 21/06/2019 08:52:24**Work Type:** EToN 4: Standard**Est. End:** 28/06/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Entire length	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	24/06/2019			28/06/2019

**Works Ref:** /TOPSANDY**Version:** 1**Work Desc:** New Lining Scheme**Notice Type:** 3 Day Initial Notice**Start:** 26/11/2018 00:00:00**Work Status:** Proposed Works**Issued:** 22/11/2018 10:56:19**Work Type:** EToN 4: Minor**Est. End:** 28/11/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Sherwood Street & surrounding streets	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	26/11/2018			28/11/2018

**Works Ref:** SHERWOODSTREET**Version:** 2**Work Desc:** Refresh the line Marking on Sherwood Street Warsop**Notice Type:** Works Stop**Start:** 17/07/2019 09:30:00**Work Status:** Works Stopped**Issued:** 26/07/2019 13:03:24**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 18/07/2019**Completion:** 17/07/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Refresh the line Marking on Sherwood Street Warsop	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	17/07/2019			18/07/2019

**Works Ref:** SHERWOODSTREETAMCLW**Version:** 3**Work Desc:** EON to install new broad base post**Notice Type:** Works Stop**Start:** 10/12/2019 00:00:00**Work Status:** Works Stopped**Issued:** 11/12/2019 08:40:45**Work Type:** EToN 4: Minor**Est. End:** 10/12/2019**Completion:** 10/12/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Sherwood Street, Warsop	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	10/12/2019			10/12/2019

**Works Ref:** SHERWOODSTTA**Version:** 2**Work Desc:** CW repairs**Notice Type:** Confirmation of Minor**Start:** 17/02/2020 00:00:00**Work Status:** Proposed Works**Issued:** 14/02/2020 15:27:01**Work Type:** EToN 4: Minor**Est. End:** 17/02/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Sherwood Street	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	17/02/2020		17/02/2020	17/02/2020

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Street Works Notices****Organisation:** NRSWA - Cadent Gas EM (0010001) (Street Works Admin Team NG Gas)**Works Ref:** 1000824985**Version:** 3**Work Desc:** Urgent work due to possible loss of gas supply**Notice Type:** Registration of Reinstatement - Full**Start:** 30/03/2019 12:51:00**Work Status:** Works Stopped**Issued:** 03/04/2019 16:55:23**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 05/04/2019**Completion:** 03/04/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN CARRIAGEWAY O/S 107	Carriageway	Up to 1.5 Metres of Cover	1.35	1.10	A Permanent Reinstatement	02/04/2019		02/04/2019	05/04/2019

**Works Ref:** 1000894599**Version:** 2**Work Desc:** Trace then excavate to repair gas escape and reinstate where possible**Notice Type:** Works Stop**Start:** 04/12/2019 12:46:00**Work Status:** Works Stopped**Issued:** 05/12/2019 13:50:36**Work Type:** EToN 4: Immediate - Emergency**Est. End:** 10/12/2019**Completion:** 05/12/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside 182 in the verge	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	05/12/2019			10/12/2019

**Works Ref:** 1000894628**Version:** 2**Work Desc:** Trace, then excavate to repair gas escape and reinstate where possible**Notice Type:** Works Stop**Start:** 04/12/2019 12:39:00**Work Status:** Works Stopped**Issued:** 05/12/2019 13:51:30**Work Type:** EToN 4: Immediate - Emergency**Est. End:** 10/12/2019**Completion:** 05/12/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	some carridgeway incursions	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	05/12/2019			10/12/2019

**Works Ref:** 1000894629**Version:** 2**Work Desc:** Trace, then excavate to repair gas escape and reinstate where possible**Notice Type:** Works Stop**Start:** 04/12/2019 12:40:00**Work Status:** Works Stopped**Issued:** 05/12/2019 13:51:06**Work Type:** EToN 4: Immediate - Emergency**Est. End:** 10/12/2019**Completion:** 05/12/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	some carridgeway incursions	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	05/12/2019			10/12/2019

**Works Ref:** 1000894681**Version:** 2**Work Desc:** Trace, then excavate to repair gas escape and reinstate where possible**Notice Type:** Works Stop**Start:** 04/12/2019 12:33:00**Work Status:** Works Stopped**Issued:** 05/12/2019 13:52:16**Work Type:** EToN 4: Immediate - Emergency**Est. End:** 10/12/2019**Completion:** 05/12/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	excavtion in public, notice raised for chapter 8	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	05/12/2019			10/12/2019

**Works Ref:** 1000894682**Version:** 2**Work Desc:** Trace, then excavate to repair gas escape and reinstate where possible**Notice Type:** Works Stop**Start:** 04/12/2019 12:34:00**Work Status:** Works Stopped**Issued:** 05/12/2019 13:51:55**Work Type:** EToN 4: Immediate - Emergency**Est. End:** 10/12/2019**Completion:** 05/12/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	outside 182	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	05/12/2019			10/12/2019

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Street Works Notices****Organisation:** NRSWA - Virgin Media - National (7160100)

**Works Ref:** /NEMBPL/ID111132/J      **Version:** 11      **Work Desc:** Remedial reinstatement to clear blockage  
**Notice Type:** Registration of Reinstatement - Full      **Start:** 08/11/2019 00:00:00  
**Work Status:** Works Stopped      **Issued:** 20/11/2019 11:43:12  
**Work Type:** EToN 4: Minor      **Est. End:** 12/11/2019      **Completion:** 12/11/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	From the junction with Maid Marion to outside number 23	Footway	Up to 1.5 Metres of Cover	104.20	0.20	A Permanent Reinstatement	25/10/2019		25/10/2019	11/11/2019
2	From outside to opposite Stuart Mitchells Stop	Carriageway	Up to 1.5 Metres of Cover	7.20	0.40	A Permanent Reinstatement	25/10/2019		25/10/2019	
3	From outside number 18 to the junction with The Homesteads	Footway	Up to 1.5 Metres of Cover	212.10	0.30	A Permanent Reinstatement	25/10/2019		25/10/2019	
4	From outside number 23 to outside the Sherwood Jounior School	Footway	Up to 1.5 Metres of Cover	109.20	0.20	A Permanent Reinstatement	25/10/2019		25/10/2019	
5	From outside number 95 to the junction with Short Street	Footway	Up to 1.5 Metres of Cover	29.30	0.20	A Permanent Reinstatement	25/10/2019		25/10/2019	
6	From the side of number 55 to the junction with Maid Marion Rise	Footway	Up to 1.5 Metres of Cover	86.60	0.20	A Permanent Reinstatement	25/10/2019		25/10/2019	
7	outside 55	Verge	Up to 1.5 Metres of Cover	1.60	0.30	A Permanent Reinstatement	12/11/2019		12/11/2019	
8	outside 39	Footway	Up to 1.5 Metres of Cover	1.80	0.30	A Permanent Reinstatement	12/11/2019		12/11/2019	
9	outside 37	Footway	Up to 1.5 Metres of Cover	1.70	0.30	A Permanent Reinstatement	12/11/2019		12/11/2019	
10	outside 31a	Footway	Up to 1.5 Metres of Cover	1.10	0.80	A Permanent Reinstatement	12/11/2019		12/11/2019	

**Works Ref:** /NEMBPL/ID111135/B      **Version:** 10      **Work Desc:** Remedial reinstatement  
**Notice Type:** Registration of Reinstatement - Full      **Start:** 29/11/2019 00:00:00  
**Work Status:** Works Stopped      **Issued:** 10/12/2019 15:47:09  
**Work Type:** EToN 4: Minor      **Est. End:** 03/12/2019      **Completion:** 03/12/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	From outside number 206 to outside number 258	Footway	Up to 1.5 Metres of Cover	219.60	0.20	A Permanent Reinstatement	30/10/2019		30/10/2019	03/12/2019
2	From outside number 202 to outside number 170	Footway	Up to 1.5 Metres of Cover	125.90	0.20	A Permanent Reinstatement	30/10/2019		30/10/2019	
3	From outside number 170 to outside number 193	Carriageway	Up to 1.5 Metres of Cover	6.10	0.40	A Permanent Reinstatement	30/10/2019		30/10/2019	
4	From outside number 193 to the junction with Top Sandy Lane	Footway	Up to 1.5 Metres of Cover	140.50	0.20	A Permanent Reinstatement	30/10/2019		30/10/2019	
5	From the side of number 169 to outside number 125	Footway	Up to 1.5 Metres of Cover	259.30	0.20	A Permanent Reinstatement	30/10/2019		30/10/2019	
6	From the side of number 123 to outside number 103a	Footway	Up to 1.5 Metres of Cover	105.70	0.20	A Permanent Reinstatement	30/10/2019		30/10/2019	
7	From outside number 120a to outside number 148	Footway	Up to 1.5 Metres of Cover	139.00	0.20	A Permanent Reinstatement	30/10/2019		30/10/2019	

Effective: 12/04/2018 to 20/04/2020

Feature No.: 2002.00 to 2002.00

Display Action Officer: No

Street: Sherwood Street (24609042)

**Street Works Notices**

**Organisation:** NRSWA - Virgin Media - National (7160100)

**Works Ref:** /NEMBPL/ID111135/B  
**Notice Type:** Registration of Reinstatement - Full  
**Work Status:** Works Stopped  
**Work Type:** EToN 4: Minor

**Version:** 10  
**Start:** 29/11/2019 00:00:00  
**Issued:** 10/12/2019 15:47:09  
**Est. End:** 03/12/2019

**Work Desc:** Remedial reinstatement  
**Completion:** 03/12/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
8	From outside number 148 to outside number 151	Carriageway	Up to 1.5 Metres of Cover	7.20	0.40	A Permanent Reinstatement	30/10/2019		30/10/2019	
9	At the junction with Cherry Grove	Footway	Up to 1.5 Metres of Cover	1.00	0.50	A Permanent Reinstatement	03/12/2019		03/12/2019	

**Works Ref:** /NEMRBU/CX00051156  
**Notice Type:** Registration of Reinstatement - Full  
**Work Status:** Works Stopped  
**Work Type:** EToN 4: Minor

**Version:** 4  
**Start:** 06/01/2020 00:00:00  
**Issued:** 16/01/2020 13:30:48  
**Est. End:** 08/01/2020

**Work Desc:** core into existing tee in footway and extend duct across customers carpark  
**Completion:** 08/01/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	105 Sherwood Street, NG20 0JU	Footway	Up to 1.5 Metres of Cover	0.70	0.30	A Permanent Reinstatement	08/01/2020		08/01/2020	08/01/2020

**Works Ref:** /NYNLRE/0334123  
**Notice Type:** Registration of Reinstatement - Full  
**Work Status:** Works Stopped  
**Work Type:** EToN 4: Minor

**Version:** 4  
**Start:** 29/02/2020 00:00:00  
**Issued:** 02/03/2020 08:55:49  
**Est. End:** 04/03/2020

**Work Desc:** FTTP -UNBLOCK DUCT (FOOTWAY ONLY)  
**Completion:** 29/02/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 206	Footway	Up to 1.5 Metres of Cover	1.20	0.50	A Permanent Reinstatement	29/02/2020		29/02/2020	04/03/2020

**Organisation:** Severn Trent Waste (9103902)

**Works Ref:** 2103/000012127388  
**Notice Type:** Registration of Reinstatement - Full  
**Work Status:** Works Stopped  
**Work Type:** EToN 4: Major

**Version:** 5  
**Start:** 16/07/2019 00:00:00  
**Issued:** 16/07/2019 14:15:24  
**Est. End:** 16/07/2019

**Work Desc:** Rep/reset MH cover In H'way to 675mmsq WORKS NEEDED TO REPAIR 2X DAMAGED FRAME AND COVERS Job in Carriageway (10mm StoneMastic Asphalt )  
**Completion:** 16/07/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	jnt of cherry grove	Carriageway	Up to 1.5 Metres of Cover	1.20	1.20	A Permanent Reinstatement	16/07/2019		16/07/2019	29/07/2019

**Works Ref:** 2103/000012221405  
**Notice Type:** Registration of Reinstatement - Full  
**Work Status:** Works Stopped  
**Work Type:** EToN 4: Standard

**Version:** 4  
**Start:** 03/09/2019 00:00:00  
**Issued:** 05/09/2019 09:05:37  
**Est. End:** 16/09/2019

**Work Desc:** SewRep225mm3m SCHEDULING NOT 3WAY Excavation required to repair defects within the foul pipeline Job in Carriageway (10mm Bitmac (Tarmac) )  
**Completion:** 03/09/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	CW OS 123 SHERWOOD STREET	Carriageway	Up to 1.5 Metres of Cover	1.40	2.70	A Permanent Reinstatement	03/09/2019		03/09/2019	13/09/2019