

Effective: 15/03/2019 to 15/03/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216089)

Street: Pinxton Lane (1216089)

Locality: Kirkby in Ashfield, Nottinghamshire

Area: Ashfield

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: B6019 - Kirkby in Ashfield			Feature Type: Street Section			Area: Ashfield	
Batch: 20382594 - Inspection Batch				Route: Ashfield Kirk Mar Saf CW				Date: 12/03/2020
3636456	p hole x 3	12/03/2020	At car sales L post 18 St Helens	CW Repairs-Bituminous	Internal		Uncommitted	2740226
Batch: 20379614 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Feb Saf CW				Date: 26/02/2020
Batch: 20377018 - Inspection Batch				Route: Adhoc Inspection				Date: 07/02/2020
3633112	C way pothole	07/02/2020	50m past Frandegrade farm heading for Kirkby.	CW Repairs-Bituminous	Internal		Uncommitted	2736858
Batch: 20375188 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Jan Saf CW				Date: 30/01/2020
Batch: 20374051 - Inspection Batch				Route: Adhoc Inspection				Date: 24/01/2020
3631456	Carriageway Pothole x 2	24/01/2020	Jctn Mayfield street	CW Repairs-Bituminous	Internal		Uncommitted	2735195
Batch: 20373092 - Inspection Batch				Route: Adhoc Inspection				Date: 16/01/2020
3630720	Carriageway Pothole X 8	16/01/2020	From Mayfield street to black car storage garage.	CW Repairs-Bituminous	Internal		Uncommitted	2734457
3630719	Carriageway Pothole x 3	16/01/2020	Junction Mayfield street	CW Repairs-Bituminous	Internal		Uncommitted	2734458
Batch: 20370131 - Inspection Batch				Route: Adhoc Inspection				Date: 24/12/2019
3628568	C way pothole	24/12/2019	Opp I post 19	CW Repairs-Bituminous	Internal		Uncommitted	2732305
Batch: 20369231 - Inspection Batch				Route: Adhoc Inspection				Date: 18/12/2019
3627945	Carriageway Pothole x 2	18/12/2019	On bends near Chevrons At double bends sign near Cliff cottages.	CW Repairs-Bituminous	Internal		Uncommitted	2731675
Batch: 20367644 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Dec Saf CW				Date: 10/12/2019
Batch: 20363527 - Inspection Batch				Route: Ashfield Kirkby Nov Enh CW/FW				Date: 18/11/2019
3624822	C way p hole x 2	18/11/2019	On bends opposite chevrons	CW Repairs-Bituminous	Internal		Uncommitted	2728546
Batch: 20362361 - Inspection Batch				Route: Adhoc Inspection				Date: 08/11/2019
3624136	C way pothole x 2	08/11/2019	On bends near chevrons marked with arrows on verge as wet	CW Repairs-Bituminous	Internal		Uncommitted	2727859
Batch: 20361349 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Oct Saf CW				Date: 31/10/2019
Batch: 20355019 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Sep Saf CW				Date: 17/09/2019
Batch: 20350896 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Aug Saf CW				Date: 20/08/2019

Effective: 15/03/2019 to 15/03/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216089)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: B6019 - Kirkby in Ashfield			Feature Type: Street Section			Area: Ashfield	
Batch: 20347165 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Jul Saf CW				Date: 23/07/2019
Batch: 20341964 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Jun Saf CW				Date: 19/06/2019
Batch: 20337091 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk May Saf CW				Date: 22/05/2019
Batch: 20335718 - Inspection Batch				Route: Adhoc Inspection				Date: 13/05/2019
3609786	C way pothole x 31	13/05/2019	From Mayfield Street to Cliff Farm cottages	CW Repairs-Bituminous	Internal		Committed	2713444
Batch: 20332660 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Apr Saf CW				Date: 24/04/2019
Batch: 20331878 - Inspection Batch				Route: Adhoc Inspection				Date: 16/04/2019
3607255	Make up edge of carriageway with 10mm two areas.	16/04/2019	Opposite Select cars	CW Repairs-Bituminous	Internal		Committed	2710902
Batch: 20328094 - Inspection Batch	No actionable defects found			Route: Ashfield Kirk Mar Saf CW				Date: 21/03/2019

Customer Services

Enquiry No.: 6162900 **Logged by:** External to Confirm **on:** 03/03/2020 18:09
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-180109283
Desc.: Road Damage - The road edge is disintegrating narrowing the road exactly at the point where cars coming the opposite way are on your side of the road avoiding another pothole. This is in my opinion a very dangerous situation. . Online report Customer title is **Pe**
Location: At the start of the S bend heading towards Kirkby. Close to that car sales place **Contact:**

Enquiry No.: 6162868 **Logged by:** External to Confirm **on:** 03/03/2020 16:15
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-180065869
Desc.: Road Damage - Road has disintegrated on the blind bend I kely to cause an accident especially to motor cyclists and cyclists. . Online report Customer title is **Per**
Location: Right on the blind bend **Contact:**

Enquiry No.: 6161720 **Logged by:** External to Confirm **on:** 27/02/2020 17:00
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-178586432
Desc.: Road Pothole - Huge potholes . Online report Customer title is **Pers**
Location: Near the bend on Pinxton Lane **Contact:**

Enquiry No.: 6155361 **Logged by:** External to Confirm **on:** 23/01/2020 15:45
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-169784764
Desc.: Road Pothole - Porthole . Online report Customer title is **Per**
Location: Bottom of Mayfield street big pothole again **Contact:**

Plot Number: 2,000.00**Feature Id - Location:** B6019 - Kirkby in Ashfield**Feature Type:** Street Section**Job Number:** 2735195**Defect Number:** 3631456

Effective: 15/03/2019 to 15/03/2020
 Display Action Officer: No

Feature No.: 2000.00 to 2000.00
 Street: Pinxton Lane (1216089)

Customer Services

Enquiry No.: 6154053	Logged by: External to Confirm	on: 16/01/2020 08:44	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-168042627
Desc.: Road Pothole - Potholes . Online report Customer title is Per			
Location: Potholes in road on the side traveling away from Kirkby.			
Contact:			
Plot Number: 2,000.00	Feature Id - Location: B6019 - Kirkby in Ashfield	Feature Type: Street Section	
Job Number: 2734457	Defect Number: 3630720		
Enquiry No.: 6150660	Logged by: External to Confirm	on: 18/12/2019 00:00	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-162834419
Desc.: Road Pothole - Large pot hole as you go round the bend it threw me on to the opposite side of the road luckily there was no car coming in the other direction . Online report Customer title is Pe			
Location: Pinxton Lane on the bad bend going towards Pinxton			
Contact:			
Plot Number: 2,000.00	Feature Id - Location: B6019 - Kirkby in Ashfield	Feature Type: Street Section	
Job Number: 2731675	Defect Number: 3627945		
Enquiry No.: 6130775	Logged by: External to Confirm	on: 17/06/2019 14:15	
Service: Carriageway/Footway	Subject: Footway Obstruction	Classification: Report or Observation	Enquiry Ref: FS-CASE-125168208
Desc.: Overgrown grass and verges - the hedge was cut this morning around the area of the bus stop and when the Per returned 3 hours later all the hedge clippings had been left. She thought this quite dangerous in a small space confined area as there was no option but to walk on them. . Submitted by Advise Personal Customer title is Per			
Location: bus stop opposite the end of Mayfield street			
Contact:			

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 2,000.00	Feature Id - Locn.: B6019 - Kirkby in Ashfield			Feature Type: Street Section		Area: Ashfield	
2612575	Carriageway Damage - Gully cover missing, reported several time already (Enquiry 3174386)	Near Mayfield House Pinxton Lane: STATS 448516 - 355419	Category 2	Job Cancelled	19/06/2015	17/07/2015	Est.
2668197	CW Repairs-Bituminous	Nr lamp no 18	Category 2	Job Cancelled	24/01/2018	31/01/2018	Est. ASH/3802363
2668200	CW Repairs-Bituminous	Nr lamp col no 12	Category 2	Job Cancelled	24/01/2018	31/01/2018	Est. ASH/3802364
2710902	Make up edge of carriageway with 10mm two areas. (CW Repairs-Bituminous)	Opposite Select cars	Category 3	Job Completed	16/04/2019	28/04/2019	Act. ASH/3803574
2713444	C way pothole x 31 (CW Repairs-Bituminous)	From Mayfield Street to Cliff Farm cottages	Category 2	Job Completed	13/05/2019	15/05/2019	Act. ASH-AS/5006080
2727859	C way pothole x 2 (CW Repairs-Bituminous)	On bends near chevrons marked with arrows on verge as wet	Category 2	Repair Completed	08/11/2019	11/11/2019	Act.
2728546	C way p hole x 2 (CW Repairs-Bituminous)	On bends opposite chevrons	Category 2	Repair Completed	18/11/2019	19/11/2019	Act.
2731675	Carriageway Pothole x 2 (CW Repairs-Bituminous)	On bends near Chevrons At double bends sign near Cliff cottages.	Filled when found (Cat 2)	Job Completed	18/12/2019	18/12/2019	Act.
2732305	C way pothole (CW Repairs-Bituminous)	Opp l post 19	Filled when found (Cat 2)	Job Completed	24/12/2019	24/12/2019	Act.
2734457	Carriageway Pothole X 8 (CW Repairs-Bituminous)	From Mayfield street to black car storage garage.	Category 2	Repair Completed	16/01/2020	03/02/2020	Act.
2734458	Carriageway Pothole x 3 (CW Repairs-Bituminous)	Junction Mayfield street	Category 1	Repair Completed	16/01/2020	17/01/2020	Act.
2735195	Carriageway Pothole x 2 (CW Repairs-Bituminous)	Jctn Mayfield street	Category 2	Repair Completed	24/01/2020	07/02/2020	Act.

Effective: 15/03/2019 to 15/03/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216089)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 2,000.00		Feature Id - Locn.: B6019 - Kirkby in Ashfield		Feature Type: Street Section		Area: Ashfield	
2736858	C way pothole (CW Repairs-Bituminous)	50m past Frandegrande farm heading for Kirkby.	Filled when found (Cat 2)	Job Completed	07/02/2020	07/02/2020	Act.
2740226	p hole x 3 (CW Repairs-Bituminous)	At car sales L post 18 St Helens	Filled when found (Cat 2)	Job Completed	12/03/2020	12/03/2020	Act.

Street Works Inspections

Organisation: BT (0030006)

Works Ref: CT002AP500253288200

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 12/09/2019 11:19:15
Category: Category C		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
		Tel: 07393 789518	Site Location: OUTSIDE 4/6, PINXTON LANE
Insp. Notes:			Position: Footpath
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Sampled Site No: 1
			Site Post Code:

Street Works Notices

Organisation: NCC - ASHFIELD (3055005)

Works Ref: 30102734	Version: 1	Work Desc: Installation of new bus shelter.
Notice Type: 3 Day Initial Notice	Start: 28/03/2019 00:00:00	
Work Status: Proposed Works	Issued: 25/03/2019 12:18:29	
Work Type: EToN 4: Minor	Est. End: 28/03/2019	Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Near to junction with Mayfield Street	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	28/03/2019			28/03/2019

Works Ref: OP1900102-AM	Version: 1	Work Desc: VIA TO INSTALL NEW 8 MTR LIGHTING COLUMN
Notice Type: 10 Day Initial Notice	Start: 13/06/2019 00:00:00	
Work Status: Proposed Works	Issued: 11/06/2019 15:47:30	
Work Type: EToN 4: Standard	Est. End: 13/06/2019	Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	PINXTON LANE LIGHTING COLUMN 13 NXT TO PLAYING FIELDS	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	13/06/2019			13/06/2019

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: PINXTONLANE2	Version: 3	Work Desc: Excavate existing pavement and lay new surface course
Notice Type: Works Stop	Start: 28/04/2019 00:00:00	
Work Status: Works Stopped	Issued: 29/04/2019 15:13:15	
Work Type: EToN 4: Minor	Est. End: 28/04/2019	Completion: 28/04/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Pinxton Lane, Kirkby in Ashfield	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	28/04/2019			28/04/2019

Effective: 15/03/2019 to 15/03/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Pinxton Lane (1216089)

Street Works Notices**Organisation:** Nottinghamshire Highway Works (3055042)

Works Ref: PINXTONLANECLW **Version:** 3 **Work Desc:** Install new 8mtr LC and 76MM post
Notice Type: Works Stop **Start:** 29/10/2019 00:00:00
Work Status: Works Stopped **Issued:** 01/11/2019 09:18:19
Work Type: EToN 4: Minor **Est. End:** 31/10/2019 **Completion:** 31/10/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Pinxton Lane, Kirkby in Ashfield LC13	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	31/10/2019			31/10/2019

Organisation: NRSWA - Cadent Gas EM (0010001) (Street Works Admin Team NG Gas)

Works Ref: 40084046 **Version:** 3 **Work Desc:** Urgent work being carried out on a low pressure gas main including excavation to prevent a loss of supplies
Notice Type: Registration of Reinstatement - Full **Start:** 21/11/2019 14:52:00
Work Status: Works Stopped **Issued:** 29/11/2019 08:02:29
Work Type: EToN 4: Immediate - Emergency **Est. End:** 27/11/2019 **Completion:** 27/11/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside no 4 in the carriageway	Carriageway	Up to 1.5 Metres of Cover	1.00	1.00	A Permanent Reinstatement	27/11/2019		27/11/2019	27/11/2019
2	Outside no 4 in the carriageway	Carriageway	Up to 1.5 Metres of Cover	1.00	1.00	A Permanent Reinstatement	27/11/2019		27/11/2019	
3	Outside no 4 in the carriageway	Footway	Up to 1.5 Metres of Cover	0.80	0.30	A Permanent Reinstatement	27/11/2019		27/11/2019	
4	Outside no 4 in the carriageway	Footway	Up to 1.5 Metres of Cover	0.90	0.60	A Permanent Reinstatement	27/11/2019		27/11/2019	