

Effective: 20/05/2019 to 20/05/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Westdale Lane East (15004327)

Street: Westdale Lane East (15004327)

Locality: Carlton, Nottinghamshire

Area: Gedling

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b>	2,001.00	<b>Feature Id - Locn.:</b>	From Burlington Road to West Dale Lane West	<b>Feature Type:</b>	Street Section		<b>Area:</b> Gedling	
<b>Batch:</b>	20391477 - Inspection Batch			<b>Route:</b>	Adhoc Inspection			<b>Date:</b> 14/05/2020
3639122	Please replace damaged TS chamber / cover for the adjacent speed camera.	14/05/2020	Outside no159	FW Ironwork	Internal		Committed	2742898
<b>Batch:</b>	20391118 - Inspection Batch			<b>Route:</b>	Gedling Area 2 May Saf CW/FW			<b>Date:</b> 13/05/2020
3638955	infill potholes	13/05/2020	at 282-274 (either side of junction with Digby Ave) and at Freda Ave both lanes	CW Repairs-Bituminous	Internal		Uncommitted	2742731
<b>Batch:</b>	20385911 - Inspection Batch			<b>Route:</b>	Gedling Area 2 Apr Saf CW			<b>Date:</b> 02/04/2020
3637586	filled when found	02/04/2020	opp lamp col 57	CW Repairs-Bituminous	Internal		Uncommitted	2741357
3637585	infill potholes in each lane	02/04/2020	opp junction with Glendale Close	CW Repairs-Bituminous	Internal		Uncommitted	2741358
<b>Batch:</b>	20382471 - Inspection Batch			<b>Route:</b>	Adhoc Inspection			<b>Date:</b> 12/03/2020
3636374	marked up previously	12/03/2020	on Westdale lane at the junction with Hartington Ave	CW Repairs-Bituminous	Internal		Uncommitted	2740139
<b>Batch:</b>	20380881 - Inspection Batch			<b>Route:</b>	Gedling Area 2 Mar Saf CW			<b>Date:</b> 03/03/2020
	No actionable defects found							
<b>Batch:</b>	20380293 - Inspection Batch			<b>Route:</b>	Adhoc Inspection			<b>Date:</b> 28/02/2020
3635048	infill pothole. Submitted by Advisor: <b>3rd party info</b> Customer title is <b>3r</b> . (Enquiry 6161777)	28/02/2020	at the junction of Welbeck Avenue	CW Repairs-Bituminous	Internal		Uncommitted	2738799
<b>Batch:</b>	20378339 - Inspection Batch			<b>Route:</b>	Gedling Area 2 Feb Saf CW/FW			<b>Date:</b> 19/02/2020
3633979	infill potholes as marked	19/02/2020	opp house 286, junction with Digby Ave, opp houses 274-272 and at junction with Freda Ave,	CW Repairs-Bituminous	Internal		Uncommitted	2737726
3633978	infill potholes as marked	19/02/2020	at houses 207-205 (opp Welbeck Ave) and near junctions with Haddon Close, Perlethorpe Ave, Hartington Ave and Baslow Ave	CW Repairs-Bituminous	Internal		Uncommitted	2737727
<b>Batch:</b>	20374185 - Inspection Batch			<b>Route:</b>	Gedling Area 2 Jan Saf CW			<b>Date:</b> 24/01/2020
	No actionable defects found							
<b>Batch:</b>	20373782 - Inspection Batch			<b>Route:</b>	Adhoc Inspection			<b>Date:</b> 22/01/2020
3631249	filled when found	22/01/2020	opp 171 and at 181 and 203	CW Repairs-Bituminous	Internal		Uncommitted	2734988
<b>Batch:</b>	20373422 - Inspection Batch			<b>Route:</b>	Adhoc Inspection			<b>Date:</b> 20/01/2020
3630967	filled when found	20/01/2020	outside house 87, 205 and 255	CW Repairs-Bituminous	Internal		Uncommitted	2734705
<b>Batch:</b>	20373318 - Inspection Batch			<b>Route:</b>	Adhoc Inspection			<b>Date:</b> 20/01/2020
3630872	patch as marked and infill at man hole	20/01/2020	at speedbump, junction with Priory Road	CW Repairs-Bituminous	Internal		Committed	2734610
<b>Batch:</b>	20370965 - Inspection Batch			<b>Route:</b>	Adhoc Inspection			<b>Date:</b> 06/01/2020
3629237	patch and infill as marked	06/01/2020	up hill at lamp col 60 to brow of hill at 206	CW Repairs-Bituminous	Internal		Committed	2732973

Effective: 20/05/2019 to 20/05/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Westdale Lane East (15004327)

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,001.00	<b>Feature Id - Locn.:</b> From Burlington Road to West Dale Lane West			<b>Feature Type:</b> Street Section			<b>Area:</b> Gedling	
<b>Batch:</b> 20370965 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 06/01/2020
3629236	filled due to deterioration after marking up in December	06/01/2020	opp house 208	CW Repairs-Bituminous	Internal		Uncommitted	2732974
<b>Batch:</b> 20370910 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 06/01/2020
3629197	filed when found	06/01/2020	pothole on Westdale Lane East - next to number 254 Westdale Lane East	CW Repairs-Bituminous	Internal		Uncommitted	2732934
<b>Batch:</b> 20369541 - Inspection Batch				<b>Route:</b> Gedling Area 2 Dec Saf CW				<b>Date:</b> 19/12/2019
3628163	infill as marked	19/12/2019	going up the hill opp house 204, junc with freda at house, 254 and 271	CW Repairs-Bituminous	Internal		Committed	2731898
<b>Batch:</b> 20367506 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 09/12/2019
3627041	filled when found Carriageway Pothole - Road Pothole - Several potholes on westdale Lane near freda Ave heading east. . Online report Customer title is 3r (Enquiry 6149211)	09/12/2019	Top of freda avenue, right onto west Dale lane	CW Repairs-Bituminous	Internal		Uncommitted	2730770
<b>Batch:</b> 20366254 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 02/12/2019
3626331	filled when aware of defect. 170 long, 50 wide, 22 deep	02/12/2019	outside house 262	FW Repairs-Bituminous	Internal		Uncommitted	2730057
<b>Batch:</b> 20364321 - Inspection Batch				<b>Route:</b> Gedling Area 2 Nov Enh CW/FW				<b>Date:</b> 22/11/2019
3625445	reset and replace kerbs	22/11/2019	outside house 64 and 99(replace)	Kerbing/Edging	Internal		Committed	2729171
3625444	patch and infill as marked	22/11/2019	79, 101, 147, 155-157, 181, 257, Lamp col 60 and Westdale Court (near Junc with Southview Rd)	FW Repairs-Bituminous	Internal		Committed	2729170
3625446	patch and infill as marked	22/11/2019	at house 79, 166, 188, 194 204, 247, 254, Lamp cl 58 and junctions with Bakewell, Besecar, Haddon Close, Welbeck and South View Rd	CW Repairs-Bituminous	Internal		Committed	2729169
<b>Batch:</b> 20364011 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 20/11/2019
3625209	filled when found related to Claim 6142407 400x400x54deep	20/11/2019	at junction with Haddon Close	CW Repairs-Bituminous	Internal		Uncommitted	2728933
<b>Batch:</b> 20361184 - Inspection Batch				<b>Route:</b> Gedling Area 2 Oct Saf CW				<b>Date:</b> 30/10/2019
	No actionable defects found							
<b>Batch:</b> 20356136 - Inspection Batch				<b>Route:</b> Gedling Area 2 Sep Saf CW				<b>Date:</b> 24/09/2019
	No actionable defects found							
<b>Batch:</b> 20350789 - Inspection Batch				<b>Route:</b> Gedling Area 2 Aug Saf CW/FW				<b>Date:</b> 19/08/2019
3618286	patch and infill as marked	19/08/2019	Opp Junc with Lascelles, houses 264, 204, Haddon Close junc, Lamp col 60 houses 173, 119 & opp Texaco	CW Repairs-Bituminous	Internal		Committed	2721972
3618285	reset kerb	19/08/2019	outside house 94	Kerbing/Edging	Internal		Committed	2721974

Effective: 20/05/2019 to 20/05/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Westdale Lane East (15004327)

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,001.00	<b>Feature Id - Locn.:</b> From Burlington Road to West Dale Lane West			<b>Feature Type:</b> Street Section			<b>Area:</b> Gedling	
<b>Batch:</b> 20350789 - Inspection Batch				<b>Route:</b> Gedling Area 2 Aug Saf CW/FW				<b>Date:</b> 19/08/2019
3618284	patch and infill as marked. Remove old signpost base in footway outside 81	19/08/2019	Manns Pharmacy, houses 286, 237 -234, 211, 204, LC 57, opp Perlethorpe, 192-182 177, 163, 155-144 junc with Buxton, 113, 100, 88-87, 56, 31 and opp Texaco	FW Repairs-Bituminous	Internal		Committed	2721973
<b>Batch:</b> 20348520 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 01/08/2019
3617119	infill as marked	01/08/2019	outside house 255 if going from mapperley end its between junction of Cavendish and digby ave	CW Repairs-Bituminous	Internal		Committed	2720804
<b>Batch:</b> 20348222 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 29/07/2019
3616941	infill as marked	29/07/2019	Going up the hill on Westdale at junctions with Hartington ave, Haddon Close & opp Thoresby Ave	CW Repairs-Bituminous	Internal		Committed	2720623
<b>Batch:</b> 20348004 - Inspection Batch	No actionable defects found			<b>Route:</b> Gedling Area 2 Jul Saf CW				<b>Date:</b> 26/07/2019
<b>Batch:</b> 20342690 - Inspection Batch				<b>Route:</b> Gedling Area 2 Jun Saf CW				<b>Date:</b> 21/06/2019
3613811	infill as marked	21/06/2019	outside house 205 and opp junction with Thoresby Avenue	CW Repairs-Bituminous	Internal		Committed	2717482
<b>Batch:</b> 20340879 - Inspection Batch				<b>Route:</b> Adhoc Inspection				<b>Date:</b> 12/06/2019
3612689	filled when found	12/06/2019	264 Westdale Lane, CARLTON, Gedling, Nottinghamshire, NG4 4FW, United Kingdom	FW Repairs-Bituminous	Internal		Uncommitted	2716360
<b>Batch:</b> 20337665 - Inspection Batch				<b>Route:</b> Gedling Area 2 May Saf CW/FW				<b>Date:</b> 23/05/2019
3611066	relay sunken kerbs	23/05/2019	outside house 216 and 194	Kerbing/Edging	Internal		Committed	2714725
3611065	infill as marked	23/05/2019	at junctions with Glendale and Lacelles and besecar, outside houses 56, 71-73, 149, 194, 205 Coffi Shot and opp McColls	CW Repairs-Bituminous	Internal		Committed	2714726

**Customer Services**

Enquiry No.: 6166713

Logged by: External to Confirm

on: 11/05/2020 09:21

Service: Carriageway/Footway

Subject: Carriageway Damage

Classification: Report or Observation

Enquiry Ref: FS-CASE-205184566

**Desc.:** Road Damage - Road damage - general condition of road is terrible - so many bumps and holes, that my car shook all the way uphill, from the uneven surface. Needs totally resurfacing! . Online report Customer title is 3r

**Location:** From approx Royal mail on the left, uphill all the way until the road flattens, just before co-op on the right.

**Contact:**

Effective: 20/05/2019 to 20/05/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Westdale Lane East (15004327)

**Customer Services**

**Enquiry No.:** 6164987      **Logged by:** External to Confirm      **on:** 18/03/2020 15:15  
**Service:** Carriageway/Footway      **Subject:** Carriageway Damage      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-184955070  
**Desc.:** Road Damage - Metal surfacing of the road in this area has deteriorated to a serious degree and is causing notable difference in drive. Very dangerous for cyclists. . Submitted by Advisor: 3rd  
 Customer title is 3r  
**Location:** Westdale Lane East, Gedling. at the Besecar Avenue and Hartington Avenue      **Contact:**  
 Junction.

**Enquiry No.:** 6163783      **Logged by:** External to Confirm      **on:** 09/03/2020 15:54  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-181963700  
**Desc.:** Road Pothole - Section from coop on westdale.lane right down to Gedling road is full of potholes and damaged man hole covers . Online report Customer title is 3r  
**Location:** Westdale lane      **Contact:**

**Enquiry No.:** 6163743      **Logged by:** External to Confirm      **on:** 09/03/2020 13:57  
**Service:** Other      **Subject:** Other Enquiry (Highways)      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-181904487  
**Desc.:** Other enquiry - want to confirm that the hedge has been cut back as requested, but has wanted to note as well that there is an obstruction by cars who park on the pavement regularly, which causes a similar problem. has requested contact to confirm that the work done is acceptable. . Submitted by Advisor: 3rd party - Customer title is 3rd  
**Location:** 30 Westdale Lane,  
 CARLTON,  
 Gedling,  
 Nottinghamshire,  
 NG4 3JA      **Contact:**

**Enquiry No.:** 6161777      **Logged by:** External to Confirm      **on:** 28/02/2020 09:27  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-178733896  
**Desc.:** Road Pothole - Customer reports pot hole at the junction of Westdale lane east and Welbeck avenue . Submitted by Advisor: 3rd party info Customer title is 3r  
**Location:** On West dale lane east at the junction of Welbeck Avenue      **Contact:**

**Plot Number:** 2,001.00      **Feature Id - Location:** From Burlington Road to West Dale Lane West      **Feature Type:** Street Section  
**Job Number:** 2737727

**Enquiry No.:** 6161548      **Logged by:** External to Confirm      **on:** 27/02/2020 08:27  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-178325436  
**Desc.:** Road Pothole - A long, wide cluster of potholes from McCoys Newsagents towards Welbeck Avenue. This whole stretch needs resurfacing as surface tarmac badly deteriorated . . Online report Customer title is 3r  
**Location:** A long, wide cluster of potholes from McCoys Newsagents towards Welbeck Avenue. This whole stretch needs resurfacing as surface tarmac badly deteriorated  
 .      **Contact:**

**Plot Number:** 2,001.00      **Feature Id - Location:** From Burlington Road to West Dale Lane West      **Feature Type:** Street Section  
**Job Number:** 2737727

**Enquiry No.:** 6160721      **Logged by:** External to Confirm      **on:** 24/02/2020 10:15  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-177402863  
**Desc.:** Road Pothole - Email from customer. Had signposted to self serve but he came back wanting to escalate this to the leader of the council, so I have reported it for him.

Advises that all three of these roads just for example, are appalling.

When is the administration going to attend to fixing the appalling roads in our county? Throwing buckets of ashphalt in pot holes is not the answer! Take Arnold Lane, Carlton Hill and Westdale Lane for example. . Submitted by Advisor: 3rd party info Customer title is 3r

**Location:** Westdale Lane, Arnold Lane and Carlton Hill.      **Contact:**

Effective: 20/05/2019 to 20/05/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Westdale Lane East (15004327)

**Customer Services**

**Enquiry No.:** 6155498      **Logged by:** External to Confirm      **on:** 24/01/2020 14:36  
**Service:** Carriageway/Footway      **Subject:** Carriageway Damage      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-170018067  
**Desc.:** Road Damage - The whole stretch of Westdale Lane East going up the hill around Salamander Close, has been really bad for some time - not so much potholes, but the actual road surface is 'rough' giving a really bad ride - I have seen cars travel on the other side of the road when it is quiet to avoid this area! . Online report Customer title is 3rd  
**Location:** The whole stretch of Westdale Lane East going up the hill around Salamander Close      **Contact:**  
, down the hill,that side is fine

**Enquiry No.:** 6153350      **Logged by:** External to Confirm      **on:** 10/01/2020 10:09  
**Service:** Carriageway/Footway      **Subject:** Carriageway Damage      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-167016253  
**Desc.:** Road Damage - Road surface is falling apart . Online report Customer title is 3rd  
**Location:** Westdale Lane just before you get to freda ave      **Contact:**

**Enquiry No.:** 6152550      **Logged by:** External to Confirm      **on:** 06/01/2020 07:27  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-165676365  
**Desc.:** Road Pothole - This is a large pothole - suggest a member of staff is able to look at it fairly soon. . Online report Customer title is 3rd  
**Location:** pothole on Westdale Lane East - next to number 254 Westdale Lane East      **Contact:**

**Plot Number:** 2,001.00      **Feature Id - Location:** From Burlington Road to West Dale Lane West      **Feature Type:** Street Section  
**Job Number:** 2732934      **Defect Number:** 3629197

**Enquiry No.:** 6152549      **Logged by:** External to Confirm      **on:** 06/01/2020 07:27  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-165674894  
**Desc.:** Road Pothole - A reasonable size pothole . Online report Customer title is 3rd  
**Location:** Pothole on Westdale Lane East near junction with Freda Avenue- the closest house is number 252 Westdale Lane East      **Contact:**

**Plot Number:** 2,001.00      **Feature Id - Location:** From Burlington Road to West Dale Lane West      **Feature Type:** Street Section  
**Job Number:** 2731898

**Enquiry No.:** 6152485      **Logged by:** External to Confirm      **on:** 03/01/2020 18:33  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-165553412  
**Desc.:** Road Pothole - Pot holes and road surface is awful . Online report Customer title is 3rd  
**Location:** Westdale lane going up hill on the steep part of the road      **Contact:**

**Plot Number:** 2,001.00      **Feature Id - Location:** From Burlington Road to West Dale Lane West      **Feature Type:** Street Section  
**Job Number:** 2732973      **Defect Number:** 3629237

**Enquiry No.:** 6149211      **Logged by:** External to Confirm      **on:** 09/12/2019 08:15  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-161078803  
**Desc.:** Road Pothole - Several potholes on westdale Lane near freda Ave heading east. . Online report Customer title is 3rd  
**Location:** Top of freda avenue, right onto west Dale lane      **Contact:**

**Plot Number:** 2,001.00      **Feature Id - Location:** From Burlington Road to West Dale Lane West      **Feature Type:** Street Section  
**Job Number:** 2730770      **Defect Number:** 3627041

**Enquiry No.:** 6145607      **Logged by:** External to Confirm      **on:** 12/11/2019 10:27  
**Service:** Carriageway/Footway      **Subject:** Bus Shelter/Stop Damage      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-156539643  
**Desc.:** Bus Stop Electronic Display damage - Electronic sign isn't working . Online report Customer title is 3rd  
**Location:** The bus stop GEO191 RAMSDALE ROAD      **Contact:**

Effective: 20/05/2019 to 20/05/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Westdale Lane East (15004327)

**Customer Services**

**Enquiry No.:** 6144721 **Logged by:** External to Confirm **on:** 07/11/2019 10:18  
**Service:** Other **Subject:** Other Enquiry (Highways) **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-155561777  
**Desc.:** Other enquiry - /In the email it states that there is advertising billboard located on that junction without permission and it needs to be removed, however customer cannot reply to the email because of his email, and prefers to do it verbally so if someone can contact him to give him more information. Customer believes that if there was indeed an advertisement of any kind it would have been on a their customers drive as they don't put billboards on posts or anything as such. . Submitted by Advisor: 3rd party - Customer title is 3r  
**Location:** Junction of Oakley avenue and westdale lane according to Email heading to customer **Contact:**

**Enquiry No.:** 6143127 **Logged by:** External to Confirm **on:** 23/10/2019 15:09  
**Service:** Trees/Verges **Subject:** Overhanging Vegetation/Trees **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-152297929  
**Desc.:** Overgrown hedges and vegetation - Overgrown hedge at the bottom of Roslyn Avenue, joining on to Westdale lane, belonging to the property at 132 Westdale lane. It is so overgrown that it is now becoming impossible to pass with a pushchair, this situation is also made worse by cars being parked half on the pavement. Customer had to walk on the road on the corner of the street, if a car had turned in left off Westdale Lane this could have been very dangerous, as at this point you are impossible to see until it is too late. . Submitted by Advisor: 3rd party info - Customer title is Unknown  
**Location:** 132 Westdale lane **Contact:**

**Enquiry No.:** 6142407 **Logged by:** External to Confirm **on:** 16/10/2019 11:57  
**Service:** Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation **Enquiry Ref:** FS150730851  
**Desc.:** Insurance claim - related to Confirm defect reference: 6142405  
Date/Time: 15/10/2019 09:00:00  
Direction of travel: Travelling up Westdale Lane towards Westdale Lane West  
Account of what happened: Customer has struck a large pot hole which has damaged his tyre.  
**Location:** Just past junction with Haddon Close **Contact:**

**Enquiry No.:** 6142405 **Logged by:** External to Confirm **on:** 16/10/2019 11:55  
**Service:** Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-150730851  
**Desc.:** Insurance claim form requested - Road Pothole - Customer has struck a large port hole which has damaged his tyre. This is on the same side of the road as heading towards Westdale Lane West .  
Submitted by Advisor: 3rd party - Customer title is 3r  
**Location:** Outside McColls on Westdale Lane East **Contact:**

**Enquiry No.:** 6142005 **Logged by:** External to Confirm **on:** 14/10/2019 03:51  
**Service:** Carriageway/Footway **Subject:** Carriageway Obstruction **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-150098079  
**Desc.:** Road obstructions - See above . Online report Customer title is 3rd  
**Location:** Parked Van's on Westdale lane between Besecar Avenue and Perlethorpe Avenue causing a large blind spot for traffic exiting Besecar Avenue on to Westdale lane I nearly got hit today are these drivers so stupid that they don't know what problem they are causing **Contact:**

**Enquiry No.:** 6140319 **Logged by:** External to Confirm **on:** 27/09/2019 12:24  
**Service:** Carriageway/Footway **Subject:** Blocked Drain **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-146445900  
**Desc.:** Blocked drains - Due to the rainfall a flood as presented itself out side this property gullies blocked. Submitted by Advisor: 3rd party - Customer title is  
**Location:** Blocked Gillie Creating flooding outside the property of 262 westfield lane **Contact:**

**Enquiry No.:** 6139915 **Logged by:** External to Confirm **on:** 24/09/2019 13:24  
**Service:** Carriageway/Footway **Subject:** Flooding **Classification:** Report or Observation **Enquiry Ref:** FS145726816  
**Desc.:** Street flooding - The caller received an email today that the case had been closed and the issue repaired. After today's heavy rain the issue is the same as it was and nothing seems to have been done, the drains were marked a while ago. Can this be looked at again please or the caller informed of if there are any further works to be carried out.  
The water fills at the dip then halfway up the pavement and has in the past gone halfway up the caller's drive through car spray. . Submitted by Advisor: 3rd - Customer title is 3rd - Previous Confirm Case: 6130073  
**Location:** Directly in front of the caller's property on 264 Westdale Lane, Carton. **Contact:**

Effective: 20/05/2019 to 20/05/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Westdale Lane East (15004327)

**Customer Services**

**Enquiry No.:** 6139116      **Logged by:** External to Confirm      **on:** 16/09/2019 18:27  
**Service:** Road Works      **Subject:** Road Works Report      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-144083530  
**Desc.:** Road work issue - temporary lights and road signs with other signs - blocking people from crossing the road at the pedestrian cross point - dangerous as when lights on stop cars block the crossing ie not leaving space for pedestrians to cross! then people have to cross knowing that the cars will be then coming the other way and having to cross from behind the cars now stopped due to the lights on stop. in other words having to step out from behind stationary cars - at the red light - into oncoming traffic. could you make it safe for pedestrians to cross? are you sure it has to be like that.  
contact by email please only . Online report Customer title is 3rd  
**Location:** westdale lane close to adbolton opposite side to the new coop - the pedestrian cross point      **Contact:**

**Enquiry No.:** 6135477      **Logged by:** External to Confirm      **on:** 05/08/2019 14:06  
**Service:** Traffic Management      **Subject:** Traffic Calming      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-135475888  
**Desc.:** Traffic calming requests - Customer is wondering if any traffic calming measures could be place don the street. Customer explains that there is a slight bend up from their property and people come speeding round there and often nearly hit them when they are trying to exit their driveway. . Submitted by Advisor: 3rd party - Customer title is 3rd  
**Location:** Westdale Lane E      **Contact:**

**Enquiry No.:** 6134318      **Logged by:** External to Confirm      **on:** 24/07/2019 19:03  
**Service:** Carriageway/Footway      **Subject:** Carriageway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-133112599  
**Desc.:** Road Pothole - The whole of the Gedling borough area require a complete resurface . Online report Customer title is  
**Location:** Virtual the whole of Gedling borough are      **Contact:**

**Enquiry No.:** 6133964      **Logged by:** External to Confirm      **on:** 21/07/2019 14:27  
**Service:** Carriageway/Footway      **Subject:** Dropped Kerb (Vehicle) Request      **Classification:** Service Request      **Enquiry Ref:** FS-CASE-132351870  
**Desc.:** Dropped kerb - Cars & other vehicles - I would like a dropped kerb in line with the centre of my building to form a new driveway . Online report - Quote required 4 whole kerb(s) and 2 tapered kerb(s) to be dropped Position of kerb - Centre of dropped kerb in line with centre of the building Streetlight - Yes Customer title is 3r  
**Location:** 97 Westdale lane      **Contact:**

**Enquiry No.:** 6133656      **Logged by:** External to Confirm      **on:** 17/07/2019 10:15  
**Service:** Carriageway/Footway      **Subject:** Carriageway Damage      **Classification:** Report or Observation      **Enquiry Ref:** FS131482538  
**Desc.:** Road Damage - Email from customer:

Dear sir/madam,

This morning workers arrived and started to repair the 24 marked potholes at the junction of Glendale Close and Westdale Lane. The 24 have been reduced to 16 as some were so close together. It now looks like a patchwork quilt on a road that has a very high volume of traffic 39 weeks of the year owing to school drop off morning and afternoon.

I feel that the repairs will not last more than a year and will need to be done again. If the repairs had been done with hot rolled asphalt then maybe they would last longer.

Less than 100 yards from Glendale lies Welbeck Avenue where the whole road has been resurfaced yet no pot holes were marked for repair. Is there a reason for this?.

I have taken pictures of the repairs which I will attempt to send to you and wonder if you would like to address this issue.

Yours faithfully,

3rd

. Submitted by Advisor: 3rd party - Customer title is 3r - Previous Confirm Case: 6129576

**Location:** Junction of Glendale Close and Westdale Lane Carlton.

**Contact:**

Effective: 20/05/2019 to 20/05/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Westdale Lane East (15004327)

**Customer Services**

**Enquiry No.:** 6133498      **Logged by:** External to Confirm      **on:** 15/07/2019 17:27  
**Service:** Trees/Verges      **Subject:** Tree Enquiry      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-131120988  
**Desc.:** Other tree issues - Customer called on behalf of 3rd party info received a letter from Highways requesting she cut back a tree to her boundary. 3rd party has no tree so he think that the letter has gone to wrong address even tho it is addressed to her. . Submitted by Advisor: 3rd party Customer title is 3r  
**Location:** Regarding HAMS 6131482      **Contact:**

**Enquiry No.:** 6132402      **Logged by:** External to Confirm      **on:** 03/07/2019 15:27  
**Service:** Carriageway/Footway      **Subject:** Footway Pothole      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-128584844  
**Desc.:** Pavement Pothole - There is a pothole in this location which is about 10 inches deep, customer has said this has been reported before but there is nothing covering it and nothing has been done to fix this. The customer has fell on this pothole today around 2.30pm. Customer has damaged her knee, she got her foot stuck in the hole and went over. Customer would like this to be fixed as it is very dangerous for people go in an out of the pharmacy. The fact that it has already been reported by the pharmacy is concerning that nothing has been done. . Submitted by Advisor: 3rd  
3rd Customer title is 3r  
**Location:** Westdale Lane East, Gedling, Outside of the pharmacy before you get to Gedling Road      **Contact:**

**Enquiry No.:** 6131482      **Logged by:** External to Confirm      **on:** 24/06/2019 11:21  
**Service:** Trees/Verges      **Subject:** Tree Enquiry      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-126516671  
**Desc.:** Other tree issues - Vvegetation has started to encroach onto the signage.The first is near No 3 Welbeck Ave & the second is near 176 Westdale Lane . Could you please get someone to have a look at these for me.  
. Submitted by Advisor: 3rd party info Customer title is  
**Location:** Westdale Lane. Carlton. VEG GROWING FROM NO 2 WELBECK AVENUE      **Contact:**

**Enquiry No.:** 6130820      **Logged by:** External to Confirm      **on:** 17/06/2019 17:09  
**Service:** Carriageway/Footway      **Subject:** Footway Damage      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-125211669  
**Desc.:** Street furniture damage - The black parking bollard to stop people driving into the shop has been knocked over by a car and needs replacing . Submitted by Advisor: 3rd party Customer title is  
is  
**Location:** Outside Peak Pharmacy Westdale Lane East Gedling      **Contact:**

**Enquiry No.:** 6130075      **Logged by:** External to Confirm      **on:** 11/06/2019 16:57  
**Service:** Carriageway/Footway      **Subject:** Footway Damage      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-124089612  
**Desc.:** Pavement Damage - The pavement was tar maceded this year. This has meant that the stop tap has been covered over with tar mac and is unaccessible. . Submitted by Advisor: 3rd party  
Customer title is  
**Location:** 264 Westdale Lane,  
CARLTON,  
Gedling,  
Nottinghamshire,  
NG4 4FW,  
United Kingdom      **Contact:**

Plot Number: 2,001.00

Feature Id - Location: From Burlington Road to West Dale Lane West

Feature Type: Street Section

Job Number: 2716360

Defect Number: 3612689



Effective: 20/05/2019 to 20/05/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Westdale Lane East (15004327)

**Customer Services**

<b>Enquiry No.:</b> 6130074	<b>Logged by:</b> External to Confirm	<b>on:</b> 11/06/2019 16:53	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Footway Damage	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-124088740
<b>Desc.:</b> Pavement Damage - Because of the rain a small pothole has turned into a large pothole around 10 inches by 15 inches. The debris from the pot hole is all over the pavement - pieces of tarmac and concrete. . Submitted by Advisor: Candy Cooper Customer title is			
<b>Location:</b> 264 Westdale Lane, CARLTON, Gedling, Nottinghamshire, NG4 4FW, United Kingdo	<b>Contact:</b>		
<b>Enquiry No.:</b> 6128472	<b>Logged by:</b> External to Confirm	<b>on:</b> 23/05/2019 13:42	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Carriageway Pothole	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-120489660
<b>Desc.:</b> Road Pothole - Potholes and major poor surface area . Online report Customer title is			
<b>Location:</b> TOP OF WESTDALE LANE ON THE HILL	<b>Contact:</b>		
<b>Plot Number:</b> 2,001.00	<b>Feature Id - Location:</b> From Burlington Road to West Dale Lane West	<b>Feature Type:</b> Street Section	
<b>Job Number:</b> 2714726			
<b>Enquiry No.:</b> 6128302	<b>Logged by:</b> External to Confirm	<b>on:</b> 21/05/2019 16:27	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Footway Obstruction	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-120107613
<b>Desc.:</b> Pavement obstructions - There is some form of blue coloured pipe stuck in the pavement, approximately a foot from the wall but 3 feet in height which is causing a possible obstruction/hazard for pedestrians. If any further details are needed please contact 3rd party info . Submitted by Advisor: 3rd party Customer title is 3rd			
<b>Location:</b> Junction of Adbolton Avenue and Westdale Lane, Gedling, near the new Co-op.	<b>Contact:</b>		
<b>Enquiry No.:</b> 3208984	<b>Logged by:</b> 3rd party info (ush)	<b>on:</b> 14/05/2020 15:46	
<b>Service:</b> Other	<b>Subject:</b> Utility STATS requested	<b>Classification:</b> Service Request	
<b>Desc.:</b> Replace damaged chamber for the adjacent speed camera in the f/w. Excavation about .5m deep.			
<b>Location:</b> Outside no159	<b>Contact:</b>		
<b>Plot Number:</b> 2,001.00	<b>Feature Id - Location:</b> From Burlington Road to West Dale Lane West	<b>Feature Type:</b> Street Section	
<b>Job Number:</b> 2742898	<b>Defect Number:</b> 3639122		
<b>Enquiry No.:</b> 87541	<b>Logged by:</b> 3rd party	<b>on:</b> 05/05/2020 10:36	
<b>Service:</b> Road Works	<b>Subject:</b> Information Request	<b>Classification:</b> Service Request	
<b>Desc.:</b> Resurfacing			
<b>Location:</b> Part	<b>Contact:</b>		
<b>Enquiry No.:</b> 85404	<b>Logged by:</b> 3rd party	<b>on:</b> 28/01/2020 10:24	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Carriageway Pothole	<b>Classification:</b> Report or Observation	
<b>Desc.:</b> Carriageway Condition			
<b>Location:</b> Entire	<b>Contact:</b>		
<b>Enquiry No.:</b> 85314	<b>Logged by:</b> 3rd party	<b>on:</b> 23/01/2020 14:33	
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Carriageway Pothole	<b>Classification:</b> Report or Observation	
<b>Desc.:</b> Carriageway Condition			
<b>Location:</b> Entire	<b>Contact:</b>		

Effective: 20/05/2019 to 20/05/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Westdale Lane East (15004327)

**Customer Services**

Enquiry No.: 84205      Logged by: 3rd party      on: 28/11/2019 15:08  
 Service: Claims      Subject: Highway Insurance Claim      Classification: Report or Observation  
 Desc.: Incident date 03.10.2019 Fott went into a pothole causing claimant to fall (on receipt of a Claim form an insurance claim has been raised)  
 Location: Outside no 262 Westdale Lane East      Contact:

Plot Number: 2,001.00      Feature Id - Location: From Burlington Road to West Dale Lane West      Feature Type: Street Section

Enquiry No.: 82492      Logged by: 3rd party      on: 16/09/2019 10:03  
 Service: Highway Searches      Subject: Adoption Extents      Classification: Report or Observation  
 Desc.: extent plan - paid BACS 16.9.19  
 Location: Premier Extra, 2-4 Westdale Lane End, Carlton, Nottingham, NG4 3JA      Contact:

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,001.00	Feature Id - Locn.: From Burlington Road to West Dale Lane West		Feature Type: Street Section		Area: Gedling	
238596	HW DR Blocked Gully Z3	opp 188	Category 2	Job Cancelled	25/07/2013	22/08/2013	Est. GED/82942
243021	HW DR Blocked Gully Z3	opp 244 & opp 254	Category 2	Job Cancelled	06/08/2014	03/09/2014	Est. GED/85487
2713494	patch as marked (CW Repairs-Bituminous)	outside and opposite house 203 FW & CW	Category 2	Job Completed	14/05/2019	29/05/2019	Act. GED/3407524
2714725	relay sunken kerbs (Kerbing/Edging)	outside house 216 and 194	Category 2	Job Completed	23/05/2019	04/06/2019	Act. GED/3407591
2714726	infill as marked (CW Repairs-Bituminous)	at junctions with Glendale and Lascelles and besecar, outside houses 56, 71-73, 149, 194, 205 Coffi Shot and opp McColls	Category 2	Job Completed	23/05/2019	11/06/2019	Act. GED/3407592
2716360	filled when found (FW Repairs-Bituminous)	264 Westdale Lane, CARLTON, Gedling, Nottinghamshire, NG4 4FW, United Kingdom	Filled when found (Cat 2)	Job Completed	12/06/2019	12/06/2019	Act.
2717482	infill as marked (CW Repairs-Bituminous)	outside house 205 and opp junction with Thoresby Avenue	Category 2	Job Completed	21/06/2019	25/06/2019	Act. GED-AS/5306513
2720623	infill as marked (CW Repairs-Bituminous)	Going up the hill on Westdale at junctions with Hartington ave, Haddon Close & opp Thoresby Ave	Category 2	Job Completed	29/07/2019	30/07/2019	Act. GED-AS/5306653
2720804	infill as marked (CW Repairs-Bituminous)	outside house 255 if going from mapperley end its between junction of Cavendish and digby ave	Category 2	Job Completed	01/08/2019	05/08/2019	Act. GED-AS/5306679
2721972	patch and infill as marked (CW Repairs-Bituminous)	Opp Junc with Lascelles, houses 264, 204, Haddon Close junc, Lamp col 60 houses 173, 119 & opp Texaco	Category 2	Job Completed	19/08/2019	04/09/2019	Act. GED/3407963

Effective: 20/05/2019 to 20/05/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Westdale Lane East (15004327)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,001.00	Feature Id - Locn.:	From Burlington Road to West Dale Lane West	Feature Type:	Street Section	Area:	Gedling
2721973	patch and infill as marked. Remove old signpost base in footway outside 81 (FW Repairs-Bituminous)	Manns Pharmacy, houses 286, 237 -234, 211, 204, LC 57, opp Perlethorpe , 192-182 177, 163, 155-144 junc with Buxton, 113, 100, 88-87, 56, 31 and opp Texaco	Category 2	Job Completed	19/08/2019	04/09/2019	Act. GED/3407962
2721974	reset kerb (Kerbing/Edging)	outside house 94	Category 2	Job Completed	19/08/2019	10/09/2019	Act. GED/3407964
2728933	filled when found related to Claim 6142407 400x400x54deep (CW Repairs-Bituminous)	at junction with Haddon Close	Filled when found (Cat 1)	Job Completed	20/11/2019	20/11/2019	Act.
2729169	patch and infill as marked (CW Repairs-Bituminous)	at house 79, 166, 188, 194 204, 247, 254, Lamp cl 58 and junctions with Bakewell, Besecar, Haddon Close, Welbeck and South View Rd	Category 2	Job Completed	22/11/2019	04/12/2019	Act. GED/3408393
2729170	patch and infill as marked (FW Repairs-Bituminous)	79, 101, 147, 155-157, 181, 257, Lamp col 60 and Westdale Court (near Junc with Southview Rd)	Category 2	Job Completed	22/11/2019	04/12/2019	Act. GED/3408394
2729171	reset and replace kerbs (Kerbing/Edging)	outside house 64 and 99(replace)	Category 2	Job Completed	22/11/2019	04/12/2019	Act. GED/3408395
2730057	filled when aware of defect. 170 long, 50 wide, 22 deep (FW Repairs-Bituminous)	outside house 262	Filled when found (Cat 1)	Job Completed	02/12/2019	02/12/2019	Act.
2730770	filled when found Carriageway Pothole - Road Pothole - Several potholes on westdale Lane near freda Ave heading east. Online report Customer title is 3rd (Enquiry 6149211) (CW Repairs-Bituminous)	Top of freda avenue, right onto west Dale lane	Filled when found (Cat 2)	Job Completed	09/12/2019	09/12/2019	Act.
2731898	infill as marked (CW Repairs-Bituminous)	going up the hill opp house 204, junc with freda at house, 254 and 271	Category 2	Job Completed	19/12/2019	09/01/2020	Act. GED/3408539
2732934	filled when found (CW Repairs-Bituminous)	pothole on Westdale Lane East - next to number 254 Westdale Lane East	Filled when found (Cat 2)	Job Completed	06/01/2020	06/01/2020	Act.
2732973	patch and infill as marked (CW Repairs-Bituminous)	up hill at lamp col 60 to brow of hill at 206	Category 2	Job Completed	06/01/2020	09/01/2020	Act. GED/3408587
2732974	filled due to deterioration after marking up in December (CW Repairs-Bituminous)	opp house 208	Filled when found (Cat 1)	Job Completed	06/01/2020	06/01/2020	Act.
2734610	patch as marked and infill at man hole (CW Repairs-Bituminous)	at speedbump, junction with Priory Road	Category 2	Job Completed	20/01/2020	12/02/2020	Act. GED/3408706
2734705	filled when found (CW Repairs-Bituminous)	outside house 87, 205 and 255	Filled when found (Cat 2)	Job Completed	20/01/2020	20/01/2020	Act.
2734988	filled when found (CW Repairs-Bituminous)	opp 171 and at 181 and 203	Filled when found (Cat 2)	Job Completed	22/01/2020	22/01/2020	Act.

Effective: 20/05/2019 to 20/05/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Westdale Lane East (15004327)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Feat No.:</b> 2,001.00	<b>Feature Id - Locn.:</b> From Burlington Road to West Dale Lane West		<b>Feature Type:</b> Street Section		<b>Area:</b> Gedling	
2737726	infill potholes as marked (CW Repairs-Bituminous)	opp house 286, junction with Digby Ave, opp houses 274-272 and at junction with Freda Ave,	Category 2	Repair Completed	19/02/2020	28/02/2020	Act.
2737727	infill potholes as marked (CW Repairs-Bituminous)	at houses 207-205 (opp Welbeck Ave) and near junctions with Haddon Close, Perlethorpe Ave, Hartington Ave and Baslow Ave	Category 2	Repair Completed	19/02/2020	28/02/2020	Act.
2738799	infill pothole. Submitted by Advisor: 3rd party info Customer title is 3r (Enquiry 6161777) (CW Repairs-Bituminous)	at the junction of Welbeck Avenue	Category 2	Repair Completed	28/02/2020	09/03/2020	Act.
2740139	marked up previously (CW Repairs-Bituminous)	on Westdale lane at the junction with Hartington Ave	Category 2	Repair Completed	12/03/2020	13/03/2020	Act.
2741357	filled when found (CW Repairs-Bituminous)	opp lamp col 57	Filled when found (Cat 2)	Job Completed	02/04/2020	02/04/2020	Act.
2741358	infill potholes in each lane (CW Repairs-Bituminous)	opp junction with Glendale Close	Category 2	Repair Completed	02/04/2020	06/04/2020	Act.
2742731	infill potholes (CW Repairs-Bituminous)	at 282-274 (either side of junction with Digby Ave) and at Freda Ave both lanes	Category 2	Repair Completed	13/05/2020	14/05/2020	Act.
2742898	Please replace damaged TS chamber / cover for the adjacent speed camera. (FW Ironwork)	Outside no159	Category 2	Job Completed	14/05/2020	05/06/2020	Act. GED/3408934

**Street Works Inspections****Organisation:** Nottinghamshire (3055001)**Works Ref:** RIMA22012020132353

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 22/01/2020 13:23:53
<b>Category:</b> Apparatus		<b>Outcome:</b> Failed (Higher Risk/Dangerous)	<b>Sampled:</b> No
<b>Defect Notif. No:</b> 11301564		<b>Defect No:</b> 11301564	<b>Site Informed:</b> No
		<b>Tel:</b> 07971375916	<b>Sign./Light./Guard. Inadequacy:</b> No
<b>Insp. Notes:</b>			<b>Site Location:</b> at pedestrian crossing point near the junction with Main Road
<b>Defect Notes:</b>			<b>Position:</b> Carriageway
			<b>Site Post Code:</b>

**Organisation:** Severn Trent New Connections East - Water (9103920)**Works Ref:** 5101/000006501400

<b>Group No:</b> 1	<b>Site No:</b> 1	<b>Street Authority:</b> Nottinghamshire	<b>Inspected:</b> 22/07/2019 14:37:35
<b>Category:</b> Category B		<b>Outcome:</b> Passed	<b>Sampled:</b> Yes
<b>Defect Notif. No:</b> N/A		<b>Defect No:</b> N/A	<b>Site Informed:</b> No
		<b>Tel:</b> 07557895771	<b>Sign./Light./Guard. Inadequacy:</b> No
<b>Insp. Notes:</b>			<b>Site Location:</b> 70A WESTDALE LANE EAST CARLTON NG4 3NA
<b>Defect Notes:</b>			<b>Position:</b> Footway
			<b>Site Post Code:</b>

Effective: 20/05/2019 to 20/05/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Westdale Lane East (15004327)

**Street Works Notices**

Organisation: BT (0030006)

Works Ref: MU1WFFMCM01048710

Version: 5

Work Desc: GEDLING V6156 - PON 010487 - BLOCKAGES – Excavate onto BT ducts for the clearance of duct blockages in FW/CW to facilitate spine cabling works.

Notice Type: Works Stop

Start: 14/08/2019 00:00:00

Work Status: Works Stopped

Issued: 03/09/2019 11:21:23

Work Type: EToN 4: Minor

Est. End: 16/08/2019

Completion: 16/08/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	From outside 111 to outside 115-117 on WESTDALE LANE EAST	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	16/08/2019			15/08/2019

Works Ref: MU1WFFMCM01072805

Version: 4

Work Desc: GEDLING V6011 - PON 010728 - Overlay – Lay approx 1m of Duct 54/56 in fw to link existing BT Boxes to facilitate spine cabling works.

Notice Type: Registration of Reinstatement - Full

Start: 22/08/2019 00:00:00

Work Status: Works Stopped

Issued: 28/08/2019 13:51:23

Work Type: EToN 4: Minor

Est. End: 27/08/2019

Completion: 27/08/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Near the junc with BUXTON AVENUE on WESTDALE LANE	Footway	Up to 1.5 Metres of Cover	1.00	0.40	A Permanent Reinstatement	27/08/2019		27/08/2019	27/08/2019

Works Ref: MU1WFFMCM01854609

Version: 6

Work Desc: GEDLING V6031 - PON 018546 - DESILITING – Required on sections of duct in order to complete spine route to Exchange Area

Notice Type: Works Stop

Start: 19/08/2019 00:00:00

Work Status: Works Stopped

Issued: 20/08/2019 11:16:00

Work Type: EToN 4: Minor

Est. End: 21/08/2019

Completion: 19/08/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	At the junction with GEDLING ROAD on WESTDALE LANE EAST	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	19/08/2019			20/08/2019

Works Ref: MU1WFFMCM01876003

Version: 4

Work Desc: GEDLING V6015 - PON 018760 - BLOCKAGES – Excavate onto BT ducts for the clearance of duct blockages in footway to facilitate spine cabling works.

Notice Type: Registration of Reinstatement - Full

Start: 09/08/2019 00:00:00

Work Status: Works Stopped

Issued: 20/08/2019 11:30:42

Work Type: EToN 4: Minor

Est. End: 13/08/2019

Completion: 13/08/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	APRX 23M SE FROM O/S 189 ON WESTDALE LANE EAST	Footway	Up to 1.5 Metres of Cover	0.50	0.40	A Permanent Reinstatement	13/08/2019		13/08/2019	12/08/2019
2	O/S 189 ON WESTDALE LANE EAST	Footway	Up to 1.5 Metres of Cover	0.50	0.40	A Permanent Reinstatement	13/08/2019		13/08/2019	
3	O/S 189 ON WESTDALE LANE EAST	Footway	Up to 1.5 Metres of Cover	0.40	0.40	A Permanent Reinstatement	13/08/2019		13/08/2019	
4	O/S 189 ON WESTDALE LANE EAST	Footway	Up to 1.5 Metres of Cover	0.40	0.30	A Permanent Reinstatement	13/08/2019		13/08/2019	
5	O/S 189 ON WESTDALE LANE EAST	Footway	Up to 1.5 Metres of Cover	0.80	0.30	A Permanent Reinstatement	13/08/2019		13/08/2019	

Effective: 20/05/2019 to 20/05/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Westdale Lane East (15004327)

**Street Works Notices****Organisation:** BT (0030006)**Works Ref:** MU1WFFMUSIBYAF6RS01**Version:** 6**Work Desc:** GEDLING V6053 - PON 010162 - Renew / Raise / Lower Frame and Cover on footway in**Notice Type:** Registration of Reinstatement - Full**Start:** 15/05/2019 00:00:00**Work Status:** Works Stopped**Issued:** 05/06/2019 15:32:46**Work Type:** EToN 4: Standard**Est. End:** 21/05/2019**Completion:** 21/05/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	outside of 75 WESTDALE LANE EAST on WESTDALE LANE EAST	Footway	Up to 1.5 Metres of Cover	0.30	0.20	A Permanent Reinstatement	21/05/2019		21/05/2019	16/05/2019

**Works Ref:** MU1WFFMUSWAKFF90M03**Version:** 8**Work Desc:** GEDLING V6188 - PON 010503 - INTERIM TO PERMANENT - in footway**Notice Type:** Registration of Reinstatement - Full**Start:** 02/07/2019 00:00:00**Work Status:** Works Stopped**Issued:** 17/07/2019 12:10:03**Work Type:** EToN 4: Minor**Est. End:** 03/07/2019**Completion:** 03/07/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OPP 239 WESTDALE LANE EAST ON WESTDALE LANE EAST	Footway	Up to 1.5 Metres of Cover	0.80	0.20	A Permanent Reinstatement	03/07/2019	18/04/2019	03/07/2019	02/07/2019

**Works Ref:** MU1WFFMUSWAKFFN8B05**Version:** 9**Work Desc:** GEDLING V6137 - PON 010432 - INTERIM TO PERMANENT - in footway**Notice Type:** Registration of Reinstatement - Full**Start:** 04/06/2019 00:00:00**Work Status:** Works Stopped**Issued:** 07/06/2019 09:32:28**Work Type:** EToN 4: Minor**Est. End:** 05/06/2019**Completion:** 05/06/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	O/S 83 WESTDALE LANE EAST ON WESTDALE LANE EAST	Footway	Up to 1.5 Metres of Cover	0.60	0.30	A Permanent Reinstatement	05/06/2019	12/04/2019	05/06/2019	04/06/2019

**Organisation:** NCC - GEDLING (3055007)**Works Ref:** 30404481**Version:** 2**Work Desc:** Install 2x new gullies and connections**Notice Type:** Confirmation of Minor**Start:** 02/10/2019 00:00:00**Work Status:** Proposed Works**Issued:** 30/09/2019 11:55:40**Work Type:** EToN 4: Minor**Est. End:** 04/10/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside No. 264 - 264a	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	02/10/2019			04/10/2019

**Works Ref:** 30404517**Version:** 1**Work Desc:** Replace Kerbs and New Bin**Notice Type:** 3 Day Initial Notice**Start:** 22/11/2019 00:00:00**Work Status:** Proposed Works**Issued:** 20/11/2019 12:04:25**Work Type:** EToN 4: Minor**Est. End:** 22/11/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside Co Op Car Park, Opposite Ramsdale Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	22/11/2019			22/11/2019

Effective: 20/05/2019 to 20/05/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Westdale Lane East (15004327)

**Street Works Notices****Organisation:** NCC - GEDLING (3055007)**Works Ref:** 6116975**Version:** 1**Work Desc:** Vehicle access**Notice Type:** 3 Day Initial Notice**Start:** 25/06/2019 00:00:00**Work Status:** Proposed Works**Issued:** 24/06/2019 14:48:55**Work Type:** EToN 4: Minor**Est. End:** 25/06/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	o/s 15	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	25/06/2019			25/06/2019

**Works Ref:** OP1900069**Version:** 2**Work Desc:** Replace kerbs and new bin**Notice Type:** Cancellation**Start:** 11/11/2019 00:00:00**Work Status:** Abandoned Works**Issued:** 11/11/2019 08:40:59**Work Type:** EToN 4: Minor**Est. End:** 12/11/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside the Co-op Car Park	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	11/11/2019			12/11/2019

**Organisation:** Nottinghamshire (3055001)**Works Ref:** RIMA22012020132353**Version:** 1**Work Desc:** sunken Hydrant cover. Trip hazard. Reported previously but has become worse**Notice Type:** Defective Apparatus**Start:** 22/01/2020 00:00:00**Work Status:** In Progress**Issued:** 22/01/2020 13:23:55**Work Type:** Not Applicable**Est. End:** 22/01/2020**Completion:** 22/01/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	at pedestrian crossing point near the junction with Main Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	22/01/2020			

**Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** /WESTDALE010819**Version:** 1**Work Desc:** Lining Works**Notice Type:** 3 Day Initial Notice**Start:** 01/08/2019 00:00:00**Work Status:** Proposed Works**Issued:** 01/08/2019 11:29:35**Work Type:** EToN 4: Minor**Est. End:** 03/08/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Junction with Pierrepont Avenue	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	01/08/2019			03/08/2019

**Works Ref:** 2712293**Version:** 1**Work Desc:** replacement of gully pot and repair of broken connection**Notice Type:** 3 Day Initial Notice**Start:** 20/05/2019 00:00:00**Work Status:** Proposed Works**Issued:** 16/05/2019 08:22:32**Work Type:** EToN 4: Minor**Est. End:** 22/05/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	outside 32	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	20/05/2019			22/05/2019

Effective: 20/05/2019 to 20/05/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Westdale Lane East (15004327)

**Street Works Notices****Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** 2714726**Version:** 1**Work Desc:** carriageway repairs**Notice Type:** 3 Day Initial Notice**Start:** 05/06/2019 00:00:00**Work Status:** Proposed Works**Issued:** 04/06/2019 15:02:22**Work Type:** EToN 4: Minor**Est. End:** 07/06/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	various locations	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	05/06/2019			07/06/2019

**Works Ref:** 2717860**Version:** 2**Work Desc:** replace damaged kerb**Notice Type:** Cancellation**Start:** 28/06/2019 00:00:00**Work Status:** Abandoned Works**Issued:** 15/07/2019 11:18:33**Work Type:** EToN 4: Minor**Est. End:** 02/07/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	outside royal mail	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	28/06/2019			02/07/2019

**Works Ref:** 2721970**Version:** 3**Work Desc:** reset sunken kerbs**Notice Type:** Works Stop**Start:** 10/09/2019 00:00:00**Work Status:** Works Stopped**Issued:** 13/09/2019 13:06:53**Work Type:** EToN 4: Minor**Est. End:** 12/09/2019**Completion:** 10/09/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	outside 11	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	10/09/2019			12/09/2019

**Works Ref:** 2721974**Version:** 3**Work Desc:** reset kerb**Notice Type:** Works Stop**Start:** 10/09/2019 00:00:00**Work Status:** Works Stopped**Issued:** 13/09/2019 13:11:51**Work Type:** EToN 4: Minor**Est. End:** 12/09/2019**Completion:** 10/09/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	outside 94	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	10/09/2019			12/09/2019

**Works Ref:** 2729169RL**Version:** 3**Work Desc:** carriageway repairs**Notice Type:** Works Stop**Start:** 02/12/2019 00:00:00**Work Status:** Works Stopped**Issued:** 05/12/2019 10:43:07**Work Type:** EToN 4: Minor**Est. End:** 04/12/2019**Completion:** 04/12/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	various locations	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	04/12/2019			04/12/2019

**Works Ref:** 2729170RL**Version:** 3**Work Desc:** footway repairs**Notice Type:** Works Stop**Start:** 02/12/2019 00:00:00**Work Status:** Works Stopped**Issued:** 05/12/2019 10:44:24**Work Type:** EToN 4: Minor**Est. End:** 04/12/2019**Completion:** 04/12/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	various locations	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	04/12/2019			04/12/2019



Effective: 20/05/2019 to 20/05/2020

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Westdale Lane East (15004327)

**Street Works Notices****Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** 2729171RL**Version:** 3**Work Desc:** kerbing works**Notice Type:** Works Stop**Start:** 04/12/2019 00:00:00**Work Status:** Works Stopped**Issued:** 06/12/2019 14:38:09**Work Type:** EToN 4: Minor**Est. End:** 06/12/2019**Completion:** 04/12/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	outside 66 and 99	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	04/12/2019			06/12/2019

**Works Ref:** 2731898RL**Version:** 3**Work Desc:** carriageway repairs**Notice Type:** Works Stop**Start:** 07/01/2020 00:00:00**Work Status:** Works Stopped**Issued:** 10/01/2020 11:07:59**Work Type:** EToN 4: Minor**Est. End:** 09/01/2020**Completion:** 09/01/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	various locations	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	09/01/2020			09/01/2020

**Works Ref:** 2732973RL**Version:** 3**Work Desc:** carriageway repairs**Notice Type:** Works Stop**Start:** 08/01/2020 00:00:00**Work Status:** Works Stopped**Issued:** 13/01/2020 10:41:28**Work Type:** EToN 4: Minor**Est. End:** 10/01/2020**Completion:** 10/01/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	between l/c 60 and house 206	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	10/01/2020			10/01/2020

**Works Ref:** 2734610RL**Version:** 5**Work Desc:** carriageway repairs**Notice Type:** Works Stop**Start:** 11/02/2020 00:00:00**Work Status:** Works Stopped**Issued:** 14/02/2020 13:29:15**Work Type:** EToN 4: Minor**Est. End:** 12/02/2020**Completion:** 12/02/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	at speedbump at junction with priory road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	12/02/2020			13/02/2020

**Works Ref:** EA1902321A**Version:** 1**Work Desc:** Temporary signal head only - replace damaged traffic signal pole on Gedling Road following an RTA**Notice Type:** 3 Day Initial Notice**Start:** 16/12/2019 00:00:00**Work Status:** Proposed Works**Issued:** 29/11/2019 10:59:13**Work Type:** EToN 4: Minor**Est. End:** 16/12/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Gedling Road junction with Westdale Lane East/Main Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	16/12/2019			16/12/2019

**Organisation:** NRSWA - BT (0030005)**Works Ref:** PT001W0000001446911**Version:** 1**Work Desc:** Registration of Non-Notifiable Works**Notice Type:** Registration of Non-Notifiable Works**Start:** 27/01/2020 00:00:00**Work Status:** Permanent Reinstatement - Bar Holes**Issued:** 30/01/2020 08:01:19**Work Type:** EToN 4: Minor**Est. End:** 27/01/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	WESTDALE LANE GEDLING O/S 199A	Verge	Up to 1.5 Metres of Cover	0.00	0.00 Pole Test Reinstatement	27/01/2020			27/01/2020