

Looking S. from No. 109



Looking N. at frontage of No. 109



Inspectors Comments:-

“ Hi Jim, The owner came out as I was taking photo's, I suggested they be removed or make an application. whether this is adhered to we can't be be sure. There is also a sign out from another shop, there are no other obstructions on this Fway outside the shops. Please see attached photo's”.



Inspector comments:-

5 29/04/2020 12:52 Holding Response Sent

Laura Trusler

Hi Laura, hope your well,
please see attached
photo's. Regards Karina

Jim F had short telephone discussion with inspector to query the general condition of surfaces / effect of plant pots on them. No unusual concerns were raised. The conversation was not recorded on HAMS.