

Effective: 19/07/2018 to 19/07/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Field Lane (26804910)

Street: Field Lane (26804910)

Locality: Blidworth, Nottinghamshire

Area: Newark

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.:	2,000.00	Feature Id - Locn.:		Feature Type:	Street Section		Area: Newark	
Batch:	20397362 - Inspection Batch			Route:	Adhoc Inspection		Date:	19/06/2020
3641772	please clear gullies and pipe to outfall in the area between the road and pub car park	19/06/2020	bottom of Field Lane at junction with calverton road	Drainage-Blocked Asset	Internal		Committed	2745549
Batch:	20376075 - Inspection Batch			Route:	Adhoc Inspection		Date:	04/02/2020
3632532	this is a ongoing issue..lets cut some new grips in so the standing water can run into the ditch behind the hedge	04/02/2020	Field lane Blidworth Bottoms end	Drainage Issue	Internal		Committed	2736275
Batch:	20365995 - Inspection Batch			Route:	Adhoc Inspection		Date:	02/12/2019
3626171	Carriageway Damage	02/12/2019	bottom of field lane,blidworth .Floods have damaged the road.	CW Repairs-Siding Up & Infill	Internal		Committed	2729897
Batch:	20359118 - Inspection Batch			Route:	Adhoc Inspection		Date:	15/10/2019
3622379	potholes	15/10/2019	Field LAne, Blidworth near farm gates marked.	CW Repairs-Bituminous	Internal		Uncommitted	2726093
3622378	potholes	15/10/2019	Field LAne, Blidworth half way down hill marked	CW Repairs-Bituminous	Internal		Uncommitted	2726092
3622380	potholes	15/10/2019	Field LAne, Blidworth just before overhead lines marked	CW Repairs-Bituminous	Internal		Uncommitted	2726094
3622381	potholes	15/10/2019	next to lc 1 matked	CW Repairs-Bituminous	Internal		Uncommitted	2726090
3622377	potholes	15/10/2019	Field LAne, Blidworth heading down hill marked	CW Repairs-Bituminous	Internal		Uncommitted	2726091
Batch:	20351428 - Inspection Batch No actionable defects found			Route:	Newark Area 2 Jul Enh CW/FW		Date:	22/08/2019
Batch:	20351141 - Inspection Batch			Route:	Adhoc Inspection		Date:	20/08/2019
3618429	Carriageway Damage - Road Damage - Damaged and narrowing road surface causing damage to vehicles . Online report Customer title is #Th (Enquiry 6136812)	20/08/2019	left hand side going up hill 60 meters from top	CW Repairs-Bituminous	Internal		Committed	2722120
Batch:	20305244 - Inspection Batch			Route:	Newark Area 2 Oct Saf CW		Date:	03/10/2018
3590118	pothole	03/10/2018	half way down this road marked	CW Repairs-Bituminous	Internal		Committed	2693455

Customer Services

Enquiry No.: 6156683 **Logged by:** External to Confirm **on:** 03/02/2020 07:35
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-171900148
Desc.: Road Damage - Continuous flooding to road causing damage to cars and no acces for pedestrians and cyclists. This has been ongoing since Oct 2019 . Online report Customer title is #Th
Location: Field lane Blidworth Bottoms end **Contact:**

Plot Number: 2,000.00**Feature Id - Location:****Feature Type:** Street Section**Job Number:** 2736275**Defect Number:** 3632532

Effective: 19/07/2018 to 19/07/2020
Display Action Officer: No

Feature No.: 2000.00 to 2000.00
Street: Field Lane (26804910)

Customer Services

Enquiry No.: 6148449 **Logged by:** External to Confirm **on:** 02/12/2019 08:32
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-160108191
Desc.: Road Damage - flood damage.Mostly stones,sand overflow onto road in piles. . Online report Customer title is
Location: bottom of field lane,blidworth .Floods have damaged the road. **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** **Feature Type:** Street Section
Job Number: 2729897 **Defect Number:** 3626171

Enquiry No.: 6145606 **Logged by:** External to Confirm **on:** 12/11/2019 10:25
Service: Carriageway/Footway **Subject:** Flooding **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-156539679
Desc.: ***SEE ALSO HAMS 6140957***Street flooding - Road flooding, 2 feet deep and is 10ft in length. Flooding has kicked up debris over the road, stones and mud. Road is unlit and is dangerous this time of year, driving through fairly deep water in the dark. . Submitted by Advisor: #Third party
Location: Bottom of field lane, where it meets calverton road. **Contact:**

Enquiry No.: 6141843 **Logged by:** External to Confirm **on:** 11/10/2019 11:48
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS149625766
Desc.: Road Pothole #Third party
#Third party o: "Nottinghamshire County Council" enquiries@nottsc.gov.ukcc: "Noreply.Enquiries@nottsc.gov.uk" Noreply.Enquiries@nottsc.gov.ukRe: Pothole, road or pavement damage - FS149029214: The problem has been fixed
Hi
Please can you explain how this problem has been fixed when the majority of the road need resurfacing?
Do you have the correct road?
I have reported Field Lane in Blidworth twice now only to be told that the repairs have been done.

As previously detailed there will be a cycling accident if this road is not repaired. There are so many holes and ruts to negotiate.

Please can you detail what repairs have been done and where?

Many thanks
#Third party

Sent from my iPhone . Submitted by Advisor #Third party Previous Confirm Case: 6141528
Location: Field LAne, Blidworth **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** **Feature Type:** Street Section
Job Number: 2726090 **Defect Number:** 3622381

Enquiry No.: 6141528 **Logged by:** External to Confirm **on:** 08/10/2019 21:42
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-149029214
Desc.: Road Damage - There are potholes and damaged areas down the full length of field lane from the top to bottom. The Road edges are crumbling away and each time we have heavy rain it causes loose stone and mud to be spread on the road. This is very dangerous. The road does get many cyclists up and down. It is used as a cut through by cars and does get a lot of traffic for an ever increasingly narrowing road. . Online report Customer title is Miss.
Location: Field lane blidworth requires major works. I have reported this road on a previous occassion only to be told it has been repaired! It certainly has not. There are many potholes and damaged areas along the full length of field lane. The road edges are damaged and deteriorate every time we have heavy rain. There will be an accident with a cyclist if this is not repaired soon. This needs urgent attention. **Contact:**

Effective: 19/07/2018 to 19/07/2020
Display Action Officer: No

Feature No.: 2000.00 to 2000.00
Street: Field Lane (26804910)

Customer Services

Enquiry No.: 6140957 **Logged by:** External to Confirm **on:** 03/10/2019 11:27
Service: Carriageway/Footway **Subject:** Flooding **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-147839265
Desc.: Street flooding - email - Good Morning


I am not actually sure where this should be sent, however, I am hoping that you can do that for me.

This is an ongoing situation that just gets worse very time the weather is bad. The problem is whenever the sides of the roads are infilled any rain washes it all out. This has the consequence of it all being dragged all over the lane, this I am sure you can see is extremely dangerous .

The flooding at the bottom of Field Lane, Blidworth Bottoms is getting beyond a joke, there are many people who have to wa k the lane to get to the Pub at the bottom for work reasons, again this is becoming a huge problem. I myself drive this lane 3-4 times daily and have to wade through the lake at the bottom.

I would be most grateful if this issue could be addressed as soon as poss ble, again before the winter sets in and we have the same issues.

I have attached just a few pictures highlighting this problem.



photos to follow via email as there is more than one. Submitted by Advisor #Third party

Location: Bottom of field lane - blidworth. at junction with calverton road **Contact:**

Enquiry No.: 6136812 **Logged by:** External to Confirm **on:** 19/08/2019 19:06
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-138357791
Desc.: Road Damage - Damaged and narrowing road surface causing damage to vehicles . Online report Customer title is Miss.
Location: Field lane Blidworth - The road surface on The steep part of field lane has got worse **Contact:**

and is dangerous and very uneven.
The full length of field lane is also getting narrower and the drop off edges cause damage to vehicles. There has been some loose stone added to the edges but this just washes away in the rain and causes more damage to vehicles as it is spread over the road.
Please contact me to provide an update for works?

Plot Number: 2,000.00 **Feature Id - Location:** **Feature Type:** Street Section
Job Number: 2722120 **Defect Number:** 3618429

Effective: 19/07/2018 to 19/07/2020
 Display Action Officer: No

Feature No.: 2000.00 to 2000.00
 Street: Field Lane (26804910)

Customer Services

Enquiry No.: 6115115 **Logged by:** External to Confirm **on:** 20/12/2018 11:06
Service: Carriageway/Footway **Subject:** Manholes/Gullies **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-100221398
Desc.: Blocked gullies - Customer has called to report the gully at the bottom of Field lane which is blocked and causing standing water on the highway. This has always been an issue and needs looking into. . Submitted by Advisor: #Third party
Location: Bottom of Field Lane hire, NG21 0NW **Contact:**

Enquiry No.: 83532 **Logged by:** Pauline Laughton **on:** 01/11/2019 16:15
Service: Carriageway/Footway **Subject:** Flooding **Classification:** Report or Observation
Desc.: #Third party kTo: "Nottinghamshire County Council" enquiries@nottscc.gov.ukcc: "Noreply.Enquiries@nottscc.gov.uk" Noreply.Enquiries@nottscc.gov.ukRe: Flooding & drainage cted and awaiting further action

Hi
 An update on the flooding at the bottom of Field Lane, Blidworth- my husband drove a village bus down Field Lane this morning and the flooding was so severe it set off the alarms on the bus!

#Third party

Location: bottom of Field Lane **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** **Feature Type:** Street Section
Job Number: 2745549 **Defect Number:** 3641772

Enquiry No.: 80634 **Logged by:** Dawn Smith **on:** 19/06/2019 10:11
Service: Carriageway/Footway **Subject:** Spillage/Debris on Carriageway **Classification:** Report or Observation
Desc.: Recent rain has washed a substantial amount of stones, gravel and sand/soil down the hill which has gathered at this location. It is rutted and presents a skid risk.
Location: Junction of Field Lane and Calverton Road **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** **Feature Type:** Street Section

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.:		Feature Type:	Street Section	Area:	Newark
2687395	pothole (CW Repairs-Bituminous)	at bottom of hill marked	Category 3	Job Completed	11/07/2018	19/07/2018	Act. NEW/3610866
2693455	pothole (CW Repairs-Bituminous)	half way down this road marked	Category 2	Job Completed	03/10/2018	05/10/2018	Act. NEW-AS/5507254
2722120	Carriageway Damage - Road Damage - Damaged and narrowing road surface causing damage to vehicles . Online report Customer title is Miss. (Enquiry 6136812) (CW Repairs-Bituminous)	left hand side going up hill 60 meters from top	Category 2	Repair Completed	20/08/2019	27/08/2019	Act. NEW-AS/5509728
2726090	potholes (CW Repairs-Bituminous)	next to lc 1 matked	Category 2	Repair Completed	15/10/2019	17/10/2019	Act.
2726091	potholes (CW Repairs-Bituminous)	Field LANE, Blidworth heading down hill marked	Category 2	Repair Completed	15/10/2019	17/10/2019	Act.
2726092	potholes (CW Repairs-Bituminous)	Field LANE, Blidworth half way down hill marked	Category 2	Repair Completed	15/10/2019	17/10/2019	Act.

Effective: 19/07/2018 to 19/07/2020
 Display Action Officer: No

Feature No.: 2000.00 to 2000.00
 Street: Field Lane (26804910)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.:		Feature Type: Street Section		Area: Newark	
2726093	potholes (CW Repairs-Bituminous)	Field LAne, Blidworth near farm gates marked.	Category 2	Repair Completed	15/10/2019	17/10/2019	Act.
2726094	potholes (CW Repairs-Bituminous)	Field LAne, Blidworth just before overhead lines marked	Category 2	Repair Completed	15/10/2019	17/10/2019	Act.
2729897	Carriageway Damage (CW Repairs-Siding Up & Infill)	bottom of field lane,blidworth .Floods have damaged the road.	Category 3	Job Completed	02/12/2019	30/01/2020	Act. NEW/3615626
2736275	recut existing grips	Field lane Blidworth Bottoms end at junction	Category 2	Job Completed	04/02/2020	02/03/2020	Act. NEW/3616287
2745549	please clear gullies and pipe to outfall in the area between the road and pub car park (Drainage-Blocked Asset)	bottom of Field Lane at junction with calverton road	Drainage P5	Works Order Committed	19/06/2020	19/06/2021	Est. DC-NEW/1200010

Street Works Inspections

Organisation: Severn Trent Water East (9103908)

Works Ref: 1101/000060268153

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 03/12/2018 14:16:04
Category: Category A	Outcome: Abortive	Defect No: N/A	Sampled: Yes
Defect Notif. No: N/A	Tel: #Third party	Site Informed: Yes	Sign./Light./Guard. Inadequacy: No
Insp. Notes:		Site Location: FORGE HOUSE	Sampled Site No: 1
Defect Notes:		Position: Carriageway	Site Post Code:

Works Ref: 1101/000060268153A

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 02/04/2019 14:13:46
Category: Category B	Outcome: Passed	Defect No: N/A	Sampled: Yes
Defect Notif. No: N/A	Tel: #Third party	Site Informed: Yes	Sign./Light./Guard. Inadequacy: No
Insp. Notes:		Site Location: The verge is being backfilled by ourselves as its a dry hole	Sampled Site No: 1
Defect Notes:		Position: Verge	Site Post Code:

Street Works Notices

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: FIELDLANEDCA **Version:** 3 **Work Desc:** STONE VERGE INFILL
Notice Type: Works Stop **Start:** 30/01/2020 00:00:00
Work Status: Works Stopped **Issued:** 31/01/2020 15:24:15
Work Type: EToN 4: Minor **Est. End:** 03/02/2020 **Completion:** 31/01/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	BOTTOM END OF FIELD LANE	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	31/01/2020			03/02/2020

Effective: 19/07/2018 to 19/07/2020

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Field Lane (26804910)

Street Works Notices**Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** LINES3108/01**Version:** 2**Work Desc:** Road Marking**Notice Type:** Actual Start Date**Start:** 11/09/2018 00:00:00**Work Status:** In Progress**Issued:** 03/09/2018 10:01:29**Work Type:** EToN 4: Minor**Est. End:** 13/09/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	At Junction	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	11/09/2018			12/09/2018

Organisation: Severn Trent Water East (9103908)**Works Ref:** 1101/000011969504**Version:** 6**Work Desc:** 2 x Boundary box Install 25mm Job in Footway (6mm Bitmac (Tarmac))**Notice Type:** Works Stop**Start:** 14/09/2018 00:00:00**Work Status:** Works Stopped**Issued:** 17/09/2018 12:37:57**Work Type:** EToN 4: Minor**Est. End:** 18/09/2018**Completion:** 17/09/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	verge next to road	Verge	Up to 1.5 Metres of Cover	1.10	0.65 A Permanent Reinstatement	17/09/2018		17/09/2018	18/09/2018
2	0	Carriageway	Up to 1.5 Metres of Cover	0.90	0.70 A Permanent Reinstatement	17/09/2018		17/09/2018	
3	0	Carriageway	Up to 1.5 Metres of Cover	1.40	1.00 A Permanent Reinstatement	17/09/2018		17/09/2018	
4	verge next to road	Verge	Up to 1.5 Metres of Cover	0.70	0.50 A Permanent Reinstatement	17/09/2018		17/09/2018	

Works Ref: 1101/000060268153**Version:** 4**Work Desc:** Short Comm Pipe Repair 25mm Job in Verge (Grass)**Notice Type:** Cancellation**Start:** 17/12/2018 00:00:00**Work Status:** Abandoned Works**Issued:** 11/12/2018 11:09:50**Work Type:** EToN 4: Minor**Est. End:** 19/12/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	FORGE HOUSE	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	03/12/2018 08:23:00			19/12/2018

Works Ref: 1101/000060268153A**Version:** 4**Work Desc:** Short Comm Pipe Repair 25mm Job in Verge (Grass)**Notice Type:** Works Stop**Start:** 17/12/2018 00:00:00**Work Status:** Works Stopped**Issued:** 19/12/2018 13:29:35**Work Type:** EToN 4: Minor**Est. End:** 19/12/2018**Completion:** 19/12/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	The verge is being backfilled by ourselves as its a dry hole	Verge	Up to 1.5 Metres of Cover	1.00	0.50 A Permanent Reinstatement	17/12/2018		17/12/2018	19/12/2018