

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street: Loughborough Road (33001159)

Locality: West Bridgford, Nottinghamshire

Area: Rushcliffe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,001.00	Feature Id - Locn.: Bridgford Road To Asda			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20444254 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 20/04/2021
3670845	HWIA - Defects causing issue for cyclist's are marked up to be made safe . (Enquiry 6205551)	20/04/2021	Outside house number 36 adjacent to L CW Repairs-Bituminous / C 49		Internal		Uncommitted	2774660
Batch: 20441468 - Inspection Batch				Route: Rus Area 2 Apr MONT Saf CW	Officer: person			Date: 07/04/2021
3669168	HWIA - Defect around utility defect is marked up to be made safe	07/04/2021	Adjacent to L / C 38 just before left turn for Balmoral Avenue if travelling from Wilford Lane junction to County Hall		Internal		Committed	2772981
Batch: 20439574 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 26/03/2021
3668032	HWIA - Defect requires making safe (Enquiry 96697)	26/03/2021	Junction Welbeck Road around Ironwork		Internal		Uncommitted	2771842
Batch: 20436744 - Inspection Batch				Route: Rush Area 2 Mar Saf CW/FW	Officer: person			Date: 11/03/2021
3665624	Defects made safe	11/03/2021	Outside Ryan House Day Nursery and house numbers 56 / 71		Internal		Uncommitted	2769429
Batch: 20434221 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 02/03/2021
3664044	HWIA - Road section is on the resurfacing program and the worst erosion requires making safe - 1. Aries garage with traffic loops protruding & L / C number erosion are around gully surrounds . (Enquiry 95812)	02/03/2021	O/S Aries Motors - L / C 33 & just before L / C 41 Cambridge Court		Internal		Uncommitted	2767848
Batch: 20433161 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 24/02/2021
3663319	HWIA - Carriageway defects require making safe - (Enquiry 6198119)	24/02/2021	On the entrance for Asda around gully & the traffic lights stop line before the left turn into Wilford Lane		Internal		Uncommitted	2767125
Batch: 20430131 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 04/02/2021
3660560	Carriageway repairs - Defects require making safe - unable to mark up due heavy traffic (Enquiry 94920)	04/02/2021	Adjacent to "The Point" Building left lane turning off Wilford lane & junction with Welbeck Road around Hydrant lids		Internal		Uncommitted	2764360
Batch: 20429578 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Feb Saf CW	Officer: person			Date: 03/02/2021
Batch: 20426261 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Jan Saf CW	Officer: person			Date: 11/01/2021
Batch: 20424147 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Dec Saf CW/FW	Officer: person			Date: 21/12/2020
Batch: 20416450 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Nov Saf CW	Officer: person			Date: 02/11/2020

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,001.00	Feature Id - Locn.: Bridgford Road To Asda			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20413306 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 09/10/2020
3650322	out side aries moters	09/10/2020	loughborough road	CW Repairs-Bituminous	Internal		Uncommitted	2754105
Batch: 20412438 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Oct Saf CW	Officer: person			Date: 05/10/2020
Batch: 20409513 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Sep Saf CW/FW	Officer: person			Date: 11/09/2020
Batch: 20403477 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Aug Saf CW	Officer: person			Date: 05/08/2020
Batch: 20399475 - Inspection Batch				Route: Rush Area 2 Jul Saf CW	Officer: person			Date: 07/07/2020
3643011	CW infill - Carriageway has sections of erosion including central which are marked up to be infilled with Hot Bitmac. Road section is TM sensitive with high volume of Traffic .	07/07/2020	Either side of L / C 52 & adjacent to L / C 59 & L / C 54	CW Repairs-Bituminous	Internal		Committed	2746790
Batch: 20396809 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Jun Enh CW/FW	Officer: person			Date: 16/06/2020
Batch: 20392187 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 19/05/2020
3639300	Defects / erosion causing issuse for road users and are marked up to be made safe / infilled .	19/05/2020	On the T junction for South Road & entrance for Vertu Volkswagen car dealership .	CW Repairs-Bituminous	Internal		Committed	2743076
Batch: 20389494 - Inspection Batch				Route: Rush Area 2 May Saf CW	Officer: person			Date: 01/05/2020
3638403	Footpath defect made safe	01/05/2020	At the entrance for Ryan House Day Nursery	FW Repairs-Bituminous	Internal		Uncommitted	2742179
Batch: 20388179 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Apr Saf CW	Officer: person			Date: 17/04/2020
Batch: 20386248 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 03/04/2020
3637630	Defects made safe .	03/04/2020	From the junction of Millicent Road to Traffic lights at Melton Road & directly opposite on the the corner outside building called The Point .	CW Repairs-Bituminous	Internal		Uncommitted	2741402
Batch: 20384748 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 27/03/2020
3637401	Carriageway defect made safe & recorded - D 60 W 300 L 300 . (Enquiry 6165399)	27/03/2020	Located on the double yellow lines outside the retirement living complex on Loughborough Road just before the traffic lights for Wilford Lane .	CW Repairs-Bituminous	Internal		Uncommitted	2741172
Batch: 20383964 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Mar Saf CW/FW	Officer: person			Date: 23/03/2020
Batch: 20383963 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 23/03/2020
3637136	Carriageway defect made safe	23/03/2020	Outside house number 167	CW Repairs-Bituminous	Internal		Uncommitted	2740907

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,001.00	Feature Id - Locn.: Bridford Road To Asda			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20382008 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 10/03/2020
3636101	HWIA - Defects require making safe (Enquiry 6163860)	10/03/2020	Inbetween L / C 50 to L / C 51	CW Repairs-Bituminous	Internal		Uncommitted	2739851
Batch: 20381290 - Inspection Batch				Route: Rush Area 2 Feb Saf CW	Officer: person			Date: 05/03/2020
	No actionable defects found							
Batch: 20380616 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 03/03/2020
3635267	HWIA - Short road section of defects are marked up to be made safe . Be advised location gets heavy traffic so recommend early start if possible . (Enquiry 6162693)	03/03/2020	City out bound side starting from the junction with South Rd to the right turning into ASDA and no further than The Wolds Pub .	CW Repairs-Bituminous	Internal		Committed	2739017
Batch: 20377265 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 11/02/2020
3633264	Carriageway repairs - Road section has been recommended for the resurface program and until this takes place various lengths of wide spread erosion requires overlaying . TM sensitive . (Enquiry 6157969)	11/02/2020	Opposite County Hall outbound side from L / C 31 (Aries Garage) to L / C 35 - no further than the main Traffic lights .	CW Repairs-Bituminous	Internal		Committed	2737010
Batch: 20376344 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 04/02/2020
3632692	Defect has been made safe .	04/02/2020	City out bound side (opposite County Hall) on the lane that takes you to Loughborough Rd directly on the stop line with the main Traffic lights adjacent to property called Welbeck House .	CW Repairs-Bituminous	Internal		Uncommitted	2736435
Batch: 20374992 - Inspection Batch				Route: Rush Area 2 Jan Saf CW	Officer: person			Date: 29/01/2020
	No actionable defects found							
Batch: 20373398 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 20/01/2020
3630948	CW repairs - Section of Carriageway has an old repair with the wearing course eroding off which is now causing the customers house to vibrate when lorries / buses pass over it . Section is near a splitter Island so TM will be required during the works - photo in link . . Online report Customer title is pe (Enquiry 6154642)	20/01/2020	On the southbound carriageway of the A60 by the gate of house number 161 , directly opposite L / C 68 .	CW Repairs-Bituminous	Internal		Committed	2734686
Batch: 20369491 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 19/12/2019
3628136	Carriageway defect has been made safe .	19/12/2019	Outside number 81	CW Repairs-Bituminous	Internal		Uncommitted	2731871
Batch: 20367286 - Inspection Batch				Route: Rush Area 2 Dec Saf CW/FW	Officer: person			Date: 06/12/2019
	No actionable defects found							

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,001.00	Feature Id - Locn.: Bridgford Road To Asda			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20365757 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 29/11/2019
3626063	HWIA - Please make safe any wearing erosion & infill around STW utility lid , unable to mark up due to rainfall .This location is TM sensitive and recommend early start if possible . (Enquiry 6148067)	29/11/2019	On the corner of Wilford road adjacent to building called The Point & around manhole surround situated in the middle of the crossroad .	CW Repairs-Bituminous	Internal		Uncommitted	2729789
Batch: 20365569 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 28/11/2019
3625977	pothole cat 1 repaired on site with via fix 500x500 and 200ml depth	28/11/2019	outside old peoples rest home	CW Repairs-Bituminous	Internal		Uncommitted	2729702
Batch: 20364656 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Nov Saf CW	Officer: person			Date: 25/11/2019
Batch: 20363448 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 15/11/2019
3624745	Carriageway defects require making safe and unable to mark up due to rainfall (Enquiry 83835)	15/11/2019	From the junction with Millicent road city outbound side L / C 37 (opposite county hall) to the traffic lights with Melton road	CW Repairs-Bituminous	Internal		Uncommitted	2728469
Batch: 20360517 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Oct Saf CW	Officer: person			Date: 24/10/2019
Batch: 20355306 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Sep Saf CW/FW	Officer: person			Date: 18/09/2019
Batch: 20350496 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Aug Saf CW	Officer: person			Date: 15/08/2019
Batch: 20346539 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Jul Saf CW	Officer: person			Date: 16/07/2019
Batch: 20341323 - Inspection Batch				Route: Rush Area 2 Jun Enh CW/FW	Officer: person			Date: 14/06/2019
3613029	HWIA - Defects are marked up for repairs .	14/06/2019	Near L / C 54 & outside house number 73 & the central lining opposite the T junction of South Road (near ASDA)	CW Repairs-Bituminous	Internal		Committed	2716700
Batch: 20338480 - Inspection Batch	No actionable defects found			Route: Rush Area 2 May Saf CW	Officer: person			Date: 29/05/2019
Batch: 20333580 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Apr Saf CW	Officer: person			Date: 26/04/2019
Batch: 20327073 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Mar Saf CW/FW	Officer: person			Date: 13/03/2019
Batch: 20326581 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 11/03/2019
3603645	CW repairs - Wearing course erosion marked up for repairs .Footpath is wide so vehicle can park on it if required .	11/03/2019	Directly opposite The Wolds pub on the exit for the row of shops	CW Repairs-Bituminous	Internal		Committed	2707255
Batch: 20323884 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Feb Saf CW	Officer: person			Date: 20/02/2019

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,001.00	Feature Id - Locn.: Bridgford Road To Asda			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20322581 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 11/02/2019
3600940	HWIA - Various defects marked up along road section require making safe . (Enquiry 6119513)	11/02/2019	From Bridgford Rd junction (old sandcliffe garage) to the Traffic lights with Melton / Loughborough Rd Junction.	CW Repairs-Bituminous	Internal		Committed	2704500
Batch: 20322579 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 11/02/2019
3600938	HWIA - Various defects marked up along road section require making safe . (Enquiry 6119513)	11/02/2019	From Bridgford Rd junction (old sandcliffe garage) to the Traffic lights with Melton / Loughborough Rd Junction .	CW Repairs-Bituminous	Internal		Committed	2704498
Batch: 20321058 - Inspection Batch				Route: Rush Area 2 Jan Saf CW	Officer: person			Date: 31/01/2019
3599915	HWIA - Unable to mark up defect during inspection .	30/01/2019	Travelling past Asda city inbound side directly on the stop line for the Traffic lights adjacent with L / C 46 which is to the side of new care home just before the left Wilford Lane turning .	CW Repairs-Bituminous	Internal		Committed	2703451
Batch: 20319885 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 22/01/2019
3599099	Carriageway defect made safe during inspection.	22/01/2019	Adjacent with L / C 47 just before the left turning for Wilford Lane .	CW Repairs-Bituminous	Internal		Uncommitted	2702620
Batch: 20319527 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 21/01/2019
3598924	HWIA - Defect is marked up to be made safe .(Enquiry 6117447)	21/01/2019	At the Traffic lights on the Junction with right hand turn to Wilford / Clifton adjacent with L / C 39 .	CW Repairs-Bituminous	Internal		Committed	2702445
Batch: 20315588 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 17/12/2018
3596445	HWIA - Defects on the crossing point require making safe - unable to mark up.	17/12/2018	At the traffic lights / Tac Tile crossing form County Hall to Bridgford Road .	CW Repairs-Bituminous	Internal		Committed	2699889
Batch: 20313633 - Inspection Batch				Route: Rush Area 2 Dec Saf CW/FW	Officer: person			Date: 03/12/2018
3595145	HWIA - Defects are marked up to be made safe .	03/12/2018	From leaving Bridgford Road (TBI) & no further than the Traffic Lights (closed Sandcliffe Garage)	CW Repairs-Bituminous	Internal		Committed	2698556
Batch: 20312771 - Inspection Batch				Route: Rush Area 2 Nov Saf CW	Officer: person			Date: 27/11/2018
	No actionable defects found							
Batch: 20308110 - Inspection Batch				Route: Rush Area 2 Oct Saf CW	Officer: person			Date: 23/10/2018
	No actionable defects found							
Batch: 20303092 - Inspection Batch				Route: Rush Area 2 Sep Saf CW	Officer: person			Date: 20/09/2018
	No actionable defects found							
Batch: 20299055 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 22/08/2018
3587293	Defects have already been made safe by person following phone conversation with ticket only requiring signing off.	22/08/2018	From Victoria Road junction to the traffic lights adjacent with the junction of Wilford lane.	CW Repairs-Bituminous	Internal		Committed	2690584

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,001.00	Feature Id - Locn.: Bridgford Road To Asda			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20298379 - Inspection Batch				Route: Rush Area 2 Aug Saf CW	Officer: person			Date: 17/08/2018
3586945	HWIA - Small deep defects causing complaints form Bike users which require making safe and unable to mark up due to rainfall & traffic - please add more onto ticket if required .	16/08/2018	Either side of the Carriageway from the Traffic lights with Wilford Lane to Traffic Lights with Bridgford Road .	CW Repairs-Bituminous	Internal		Committed	2690220
Batch: 20294548 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Jul Saf CW	Officer: person			Date: 23/07/2018
Batch: 20293653 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 16/07/2018
3584476	Road Works Report - Priority road sign left by Utility at given location requires removing from grass verge and into stock at Gamston (Enquiry 6100858)	16/07/2018	Near L / C 46 which is just before the left turn into Wilford Lane - city in bound side of the Carriageway .	Other	Internal		Committed	2687698
Batch: 20288094 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Jun Enh CW/FW	Officer: person			Date: 11/06/2018
Batch: 20284447 - Inspection Batch				Route: Rush Area 2 May Saf CW	Officer: person			Date: 21/05/2018
3579167	CW infill - Defects are within the centre lining of Carriageway and causing issues for road users and require infilling with HOT BITMAC which are marked up .	21/05/2018	Starting from L / C 54 (Ryan House Day Nursery) and no further than L / C 51 city in bound side .	CW Repairs-Bituminous	Internal		Committed	2682306
Batch: 20280494 - Inspection Batch				Route: Rush Area 2 Apr Saf CW	Officer: person			Date: 26/04/2018
3576511	HWIA - Defects require making safe and unable to mark up due to rainfall .	26/04/2018	Outside the Old Sandcliffe Garage & property called West One L / C 37 (around hydrant cover) City outbound side .	CW Repairs-Bituminous	Internal		Committed	2679611
Batch: 20274260 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Mar Saf CW	Officer: person			Date: 23/03/2018
Batch: 20270327 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 27/02/2018
3569583	CW overlay - Wide spread Carriageway erosion along this location that will require making safe .The location gets large volume of Traffic so TM sensitive and unable to mark up due to this .	27/02/2018	From the Junction with Welbeck Road to Balmoral Avenue	CW Repairs-Bituminous	Internal		Committed	2672552
Batch: 20270233 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Feb Saf CW	Officer: person			Date: 27/02/2018
Batch: 20268253 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 14/02/2018
3567985	Carriageway defect has now been made safe and ticket in the system for other actionable defects to be made safe by the Assistants .	14/02/2018	Loughborough Road near to its junction with Sandringham Avenue city inbound.	CW Repairs-Bituminous	Internal		Committed	2670941

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,001.00	Feature Id - Locn.: Bridgford Road To Asda			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20268000 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 13/02/2018
3567767	HWIA - Numerous defects require making safe which been unable to mark up due to high volume of traffic & rainfall .Recommend early start as road section gets very busy.	13/02/2018	From the Junctions of Welbeck Road to CW Repairs-Bituminous Bridgford Road (TBI / Cricket Ground) either side of the Carriageway.	Internal			Committed	2670723
Batch: 20263916 - Inspection Batch	No actionable defects found			Route: Rush Area 2 Jan Saf CW	Officer: person			Date: 23/01/2018
Batch: 20261140 - Inspection Batch				Route: Adhoc Inspection	Officer: person			Date: 03/01/2018
3562793	HWIA - Numerous defects require making safe and unable to mark up due to high volume of traffic and job will require early start because of this - please add any extra defects made safe to ticket.	03/01/2018	From the Junctions of Welbeck Road to CW Repairs-Bituminous Bridgford Road (TBI) either side of Carriageway .	Internal			Committed	2665680

Customer Services

Enquiry No.: 6205551	Logged by: External to Confirm	on: 20/04/2021 09:38	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: CSC327499195
Desc.: Road Pothole - Large long linear pothole down the centre of the road. Due to parked cars you often end up driving over the middle of the road and in the potholes. Looks to be the seam between two tarmaced sections. . Online report Customer title is pe			
Location: A60 Loughborough Rd south of the junction with Melton Rd & Wilford Lane	Contact:		
Plot Number: 2,001.00	Feature Id - Location: Bridgford Road To Asda	Feature Type: Street Section	
Job Number: 2774660	Defect Number: 3670845		
Enquiry No.: 6205125	Logged by: External to Confirm	on: 14/04/2021 21:57	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: CSC326009777
Desc.: Road Pothole - Thousands of potholes. . Online report Customer title is pe			
Location: In between Central avenue and Wilford Lane on London Road is just one big pothole.	Contact:		
Enquiry No.: 6204938	Logged by: External to Confirm	on: 13/04/2021 13:57	Officer: person
Service: Carriageway/Footway	Subject: Line Marking/Stud Renewal	Classification: Report or Observation	Enquiry Ref: FS-CASE-325497526
Desc.: Road marking renewal - Poor white lining on this stretch of the A60, especially where the road branches out onto three lanes. . Online report Customer title is pe			
Location: Loughborough Road A60, where it branches out onto A60 southbound and Melton Road A606 (adj to the four way traffic signals).	Contact:		
Enquiry No.: 6204842	Logged by: External to Confirm	on: 13/04/2021 08:26	Officer: Gary Cain
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-325320005
Desc.: Road Pothole - It's like shallow potholes, it covers a car span of the road and is the same in both of the two places I am talking about. One is just near to the ng2 building surveyors and one is a few meters further up . Online report Customer title is per			
Location: There are two parts of the road which are affected and have road damage/ potholes - in the right hand side lane which then leads to the turning for Wilford Lane where there is quite bad damage to the road. It's been there for over a month and is getting worse	Contact:		

Effective: 01/01/2018 to 22/04/2021

Display Action Officer: Yes

Feature No.: 2001.00 to 2001.00

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6204726 **Logged by:** External to Confirm **on:** 12/04/2021 09:42 **Officer:** Gary Cain
Service: Road Works **Subject:** Road Works Report **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-324961601
Desc.: Road work issue - You are aware that when contractors dug up parts of boundary Road, and then along the grass verge next to the fencing of Wilford Cemetery. You arranged for them to return and lay top soil on the grass verge.

However in digging up the route to lay new gas pipe they had to cross the end of the Bridle path close to the pavement. Only a short length of what was dug up was finished with a layer of asphalt, but this left a square metre that although was filled in no asphalt was laid over where the trench had been dug. Furthermore the depth of Asphalt is so thin that it is breaking up as a result of the number of vehicles that are driven up and down this Bridle path.

Furthermore there as been a problem of water running down this path and over the pavement onto the A60. With heavy rain the run off brings mud, and stones also across the pavement and on to the A60. In winter after a heavy downpour and then a frosty morning the pavement becomes very slippery. and dangerous to pedestrians.

This morning I had a good look at the end of the bridle path. about 4 years ago a drain was laid across the path in an attempt to prevent rain water pouring over the pavement and bringing it with it sand and gravel etc.

I estimate that the end of the Bridle path from this drain to the pavement needs to be laid with a fresh layer of asphalt about 50 to 60 square metres. It would be helpful if a camber was installed in such a way that it diverts water running down the bridle path into the ditch that runs along side the path and between the metal railings of Wilford Cemetery.

I do not know who is responsible for the maintenance of the Bridle path but it is used by many vehicles including those from Seven trent from time to time because there is an underground reservoir towards the top of this path.

Regards

Location: personal along the grass verge next to the fencing of Wilford Cemetery

Contact:

Enquiry No.: 6204504 **Logged by:** External to Confirm **on:** 09/04/2021 11:18 **Officer:** personal
Service: Carriageway/Footway **Subject:** Request new line marking/studs **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-324276211
Desc.: New road marking (including disabled parking bay / yellow lines) - Email
Dear highway team I live at per Loughborough Rd west bridgford ng2-7eh and from just past my drive to per Loughborough Rd 2or3 cars park there most of the day half on the road and half on the pavement and it is very difficult for me to see the traffic coming down loughborough when I go out of my drive I almost have to go in the middle of the Rd before I can turn left or right also across from my drive is the bus stop and the Minch bus from Loughborough to Nottingham stopes there every 30 minutes making it even more dangerous could you please put yellow lines between pe and pe to stop cars parking there they can park further up on Loughborough on the opposite side which will sort the problem out I am forwarding some photos I took that you can see the situation which I think is a bit dangerous kind regards mr jacob lobl
. Submitted by Advisor: personal

Location: per Loughborough Road,
WEST BRIDGFORD,
West Bridgford,
NG2 7EH,

Contact:

Enquiry No.: 6204446 **Logged by:** External to Confirm **on:** 08/04/2021 21:57 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-324130531
Desc.: Road Damage - Road surface is chipped off to a depth of 3-6cm in multiple areas - very patchy . Online report Customer title is per
Location: On the southbound carriageway between county hall and the turning for wilford lane. **Contact:**
The road surface is pretty awful, no landmarks needed!

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6204402 **Logged by:** External to Confirm **on:** 08/04/2021 16:03 **Officer:** personal
Service: Traffic Management **Subject:** Parking General **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-324020755
Desc.: Parking issues - Cars parking on this street especially in between personal which is causing very low visibility for residents to get off their drive. Also making it difficult to pass buses that come by due to making the road too narrow

Has reported before but told there's not enough money to lay down yellow lines etc. . Submitted by Advisor: personal Customer title is pe

Location: Outside property pe Loughborough Road, West Bridgford, NG2 7EH **Contact:**

Enquiry No.: 6203906 **Logged by:** External to Confirm **on:** 01/04/2021 08:08 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-321392409
Desc.: Road Damage - The whole road is an absolute disgrace. Dangerous to ride a bike/motorbike on and needs sorting ASAP! . Online report Customer title is
Location: A60 southbound for around 100m before the crossing with Melton Road. **Contact:**

Enquiry No.: 6203671 **Logged by:** External to Confirm **on:** 29/03/2021 16:33 **Officer:** Transport Facilities
Service: Carriageway/Footway **Subject:** Bus Shelter/Stop Enquiry **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-320812443
Desc.: Electronic real time display (display providing next bus information) - Customer is unsure as to why the electronic board at this bus stop has been removed. Whether it is temporary and just being replaced, or whether has been removed completely. . Submitted by Advisor: personal - Customer title is
Location: Opposite the county hall, on the other side of the road in front of the Tesla garage **Contact:**

Enquiry No.: 6203526 **Logged by:** External to Confirm **on:** 29/03/2021 09:30 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-320588466
Desc.: Road Pothole - potholes/broken surface
Location: broken road surface across whole carriage way **Contact:**

Enquiry No.: 6203459 **Logged by:** External to Confirm **on:** 29/03/2021 07:58 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-320393376
Desc.: Road Damage - There are strips of tarmac that is literally crumbling away . Online report Customer title is pe
Location: This is present on the stretch of road going out of Nottingham on the Melton Rd and gets worse the closer you get to the junction with Loughborough Rd **Contact:**

Enquiry No.: 6203342 **Logged by:** External to Confirm **on:** 26/03/2021 14:21 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-320012983
Desc.: Road Damage - Your poor quality, Soviet socialist style work requires Build Back Better change. Surface of Loughborough Road requires resurfacing . Online report Customer title per
Location: Loughborough Road near Millicent Road oposit to Sandringham Road and Balmoral Roads **Contact:**

Enquiry No.: 6203338 **Logged by:** External to Confirm **on:** 26/03/2021 14:09 **Officer:** person
Service: Carriageway/Footway **Subject:** Footway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-320010735
Desc.: Pavement Pothole - Urgent repairs required, dangerous potholes on the key road . Online report Customer title per
Location: Over 15 potholes Loughborough Road **Contact:**

Enquiry No.: 6203171 **Logged by:** External to Confirm **on:** 25/03/2021 14:35 **Officer:** person
Service: Carriageway/Footway **Subject:** Footway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-319669960
Desc.: Pavement Pothole - Pothole on grassed area outside of pe Loughborough road. Resident concerned due the West Bridgford secondary school being across the road. . Submitted by Advisor: personal
Location: pe Loughborough Road **Contact:**

Enquiry No.: 6202932 **Logged by:** External to Confirm **on:** 24/03/2021 09:42 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-319151259
Desc.: Road Pothole - Very dangerous large pothole, if not slowing down to 5mph or so will cause significant damage to cars . Online report Customer title per
Location: On road going from Trent Bridge towards the new Tesla , in the right hand lane **Contact:**

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6202528	Logged by: External to Confirm	on: 22/03/2021 10:27	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-318413420
Desc.: Road Damage - Large area of lifted road surface creating quite a substantial hole in the area where it goes from 2 lanes wide to 3 lanes wide for the junction . Online report Customer title pers			
Location: A60 southbound just prior to the junction of Wilford Lane, Melton Road & Loughborough Road		Contact:	
Enquiry No.: 6202484	Logged by: External to Confirm	on: 22/03/2021 08:10	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-318329149
Desc.: Road Pothole - Multiple potholes & Road surface breaking down . Online report Customer title is Mrs.			
Location: Quite an area of damage on the A60 approach to the traffic lights junction at Wilford Lane/Melton Road/Loughborough Road, heading away from Trent Bridge.		Contact:	
Enquiry No.: 6202468	Logged by: External to Confirm	on: 22/03/2021 08:10	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-318287755
Desc.: Road Pothole - A series of large potholes along this right hand lane up to the traffic lights to turn right onto Wilford lane. Causes significant wear on car suspension travelling over these series of potholes. Please fix. This is a very busy road and these potholes will be doing a significant amount of damage to car's suspension . Online report Customer title pers			
Location: Loughborough rd - In the lane to turn right onto Wilford lane		Contact:	
Enquiry No.: 6202399	Logged by: External to Confirm	on: 22/03/2021 08:08	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-318160143
Desc.: Road Damage - Road damaged and getting worse, some potholes over 100mm deep. . Online report Customer title pers.			
Location: Road outside asda leading upto eton road		Contact:	
Enquiry No.: 6202392	Logged by: External to Confirm	on: 22/03/2021 08:08	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-318134371
Desc.: Road Pothole - The state of the road is atrocious, far too many pot holes, some of which are so deep they will cause damage to cars . Online report Customer person			
Location: Various points from and including the start of Trent Bridge to the Wilford Lane junction		Contact:	
Enquiry No.: 6202389	Logged by: External to Confirm	on: 22/03/2021 08:08	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-318134572
Desc.: Road Damage - Between Europa way and Landmere lane on Loughborough Rd (much closer to Europa way) heading into WB there is a damaged manhole cover that makes a very loud noise every time a car drives over it. . Online report Customer title pers			
Location: Opposite side of road to a row of newish small terraced houses on Loughborough Rd. See below.		Contact:	
Enquiry No.: 6202356	Logged by: External to Confirm	on: 22/03/2021 08:07	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-318093448
Desc.: Road Damage - Whole junction from Wilford Lane to loughborough road is coming away and dangerous especially for motorbikes . Online report Customer pers			
Location: Road damage potholes and junction		Contact:	
Enquiry No.: 6202327	Logged by: External to Confirm	on: 22/03/2021 08:06	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-318020118
Desc.: Road Pothole - Multiple holes in the road . Online report Customer title per .			
Location: The stretch of road from the cricket ground to the junction of Henry road		Contact:	

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6202076 **Logged by:** External to Confirm **on:** 18/03/2021 18:03 **Officer:** personal
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-317546140
Desc.: Road Pothole - Pothole in road . Online report Customer title pers
Location: Top of Loughborough road first lane to get on to the roundabout **Contact:**

Enquiry No.: 6201509 **Logged by:** External to Confirm **on:** 16/03/2021 10:54 **Officer:** personal
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-316591967
Desc.: Road Damage - Lots of potholes on a good stretch of the road for at least 100 yards and they are that bad it takes steering wheel out your hand on that stretch of the road quite a few potholes dotted around the road . Submitted by Advisor: personal
Location: Outside ARIES motor company on the right hand carriage heading south **Contact:**

Plot Number: 2,001.00 **Feature Id - Location:** Bridgford Road To Asda **Feature Type:** Street Section
Job Number: 2767848

Enquiry No.: 6201183 **Logged by:** External to Confirm **on:** 15/03/2021 07:51 **Officer:** personal
Service: Road Works **Subject:** Road Works Report **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-315992776
Desc.: Road work issue - Manhole cover on road has not been secured correctly. Makes very loud banging noises every time a vehicle wheel drives over it. This can be heard from bedroom and is causing ill health due to lack of sleep during night shift work. . Online report Customer title pers
Location: Location on road outside DE Europa View. NG116FG **Contact:**

Enquiry No.: 6200816 **Logged by:** External to Confirm **on:** 11/03/2021 16:30 **Officer:** personal
Service: Carriageway/Footway **Subject:** Manholes/Gullies **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-315300459
Desc.: Missing and damaged manhole/drain covers - the noise from this cover is now becoming unbearable and affecting sleep time. There is also the safety aspect should the lid lift off.

I would be extremely grateful if you could look into this problem as a matter of urgency please.

The man-hole in question is outside my house on Loughborough Road past the Crematorium 1st house on the left named Southern Wood just past the traffic lights (coming from West Bridgford).. Submitted by Advisor: personal

Location: A60 past ASDA and the Wilford Hill Crematorium with Greythorne Drive on the RHS **Contact:**
there are some traffic lights after these lights carrying on towards the Nottingham Knight roundabout we are the first house on the left and the man-hole cover is just outside my property

Enquiry No.: 6200379 **Logged by:** External to Confirm **on:** 09/03/2021 14:57 **Officer:** Dropped Kerb Requests
Service: Carriageway/Footway **Subject:** Dropped Kerb (Vehicle) Request **Classification:** Service Request **Enquiry Ref:** FS-CASE-314524588
Desc.: Dropped kerb - Cars & other vehicles - Would like to request for her dropped kerb to be extended . Submitted by Advisor: personal - Quote required 2 whole kerb(s) and 1 tapered kerb(s) to be dropped Position of kerb - Outside DE Loughborough Road, WEST BRIDGFORD, West Bridgford, Ng2 7eh Streetlight - No Customer title pers
Location: DE Loughborough Road, WEST BRIDGFORD, West Bridgford, Ng2 7eh **Contact:**

Enquiry No.: 6200202 **Logged by:** External to Confirm **on:** 08/03/2021 16:00 **Officer:** personal
Service: Traffic Management **Subject:** Speed Limits/Issues **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-314173683
Desc.: Speed limits - The junction before the cemetery , Boundary Road is where the 30 mph limit is enforced but the cars are speeding by causing hazardous situations for residents who need to reverse out from their driveways. Please advise. . Submitted by Advisor: personal - Customer title is per
Location: personal, WEST BRIDGFORD- The entirety of the road **Contact:**

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6200200 **Logged by:** External to Confirm **on:** 08/03/2021 15:54 **Officer:** personal
Service: Carriageway/Footway **Subject:** Carriageway Obstruction **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-314171290
Desc.: Road obstructions - Customer is concerned that there are lots of cars that are parking on the road which is causing obstruction issues. The customer and the neighbours are unable to see the road when reversing out from the driveway. The cars seem to be speeding which makes it more difficult. Please advise. . Submitted by Advisor: Saima Faisal Customer title pers.
Location: Loughborough Road, WEST BRIDGFORD - The entirety of the road **Contact:**

Enquiry No.: 6200189 **Logged by:** External to Confirm **on:** 08/03/2021 15:21 **Officer:** personal
Service: Carriageway/Footway **Subject:** Request new line marking/studs **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-314147311
Desc.: New road marking (including disabled parking bay / yellow lines) - personal has contact us today to request if it is possible to have double yellow lines or zigzag lines marked out to the left of person Loughborough Road, WEST BRIDGFORD, West Bridgford, NG2 7EH. Serious parking issues caused by the police and fire station staff, across the road.
Customer has had 3 near misses due to obstruction. Please could this be looked into and the customer contacted. . Submitted by Advisor: personal - Customer title is pe
Location: Loughborough Road, WEST BRIDGFORD, West Bridgford, NG2 7EH **Contact:**

Enquiry No.: 6200020 **Logged by:** External to Confirm **on:** 07/03/2021 10:33 **Officer:** personal
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-313767216
Desc.: Road Damage - Road very badly broken up . Online report Customer title per.
Location: Loughborough Road, either side of the junction with Millicent Road outbound from City side **Contact:**

Plot Number: 2,001.00 **Feature Id - Location:** Bridgford Road To Asda **Feature Type:** Street Section
Job Number: 2767848

Enquiry No.: 6199351 **Logged by:** External to Confirm **on:** 02/03/2021 21:00 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-312518952
Desc.: Road Damage - About 5 to 8 potholes coming upto lights loughborough rd upto wilford lane junction from town . Online report Customer title per.
Location: . **Contact:**

Enquiry No.: 6199324 **Logged by:** External to Confirm **on:** 02/03/2021 17:15 **Officer:** personal
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-312464633
Desc.: Road Pothole - Lots of potholes together (2 separate patches) . Online report Customer title is pe
Location: Outside "West One" letting. **Contact:**

Plot Number: 2,001.00 **Feature Id - Location:** Bridgford Road To Asda **Feature Type:** Street Section
Job Number: 2767848

Enquiry No.: 6198967 **Logged by:** External to Confirm **on:** 01/03/2021 08:13 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-311697810
Desc.: Road Damage - Multiple pot holes and road surface damage make the road dangerous for cyclists and all road users . Online report Customer title per.
Location: From Rushworth Avenue Junction on Melton Road A60 to Patrick Road Junction on Melton Road A60 **Contact:**

Enquiry No.: 6198715 **Logged by:** External to Confirm **on:** 26/02/2021 10:21 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS311134618
Desc.: Road Pothole - Clusters of potholes that are unavoidable when needing to be in the right lane, need filling in before serious suspension damage occurs. . Online report Customer title pers. . - Previous Confirm Case: 6198060
Location: Both before and after the lights near NG surveyors on Loughborough road. **Contact:**

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6198119	Logged by: External to Confirm	on: 23/02/2021 12:00	Officer: personal
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-310158794
Desc.: Road Pothole - pothole size of dinner plate			
Location: exit road out of Asda Loughborough Road, West Bridgford		Contact:	
Plot Number: 2,001.00	Feature Id - Location: Bridgford Road To Asda	Feature Type: Street Section	
Job Number: 2767125	Defect Number: 3663319		
Enquiry No.: 6198060	Logged by: External to Confirm	on: 23/02/2021 08:45	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-310058211
Desc.: Road Pothole - Several large potholes , exposed cabling. Previously repaired(very badly) - now worse than before and debris and loose tarmac making the pavement dangerous also . Online report Customer title is per			
Location: Directly outside our entrance gates		Contact:	
Enquiry No.: 6197816	Logged by: External to Confirm	on: 22/02/2021 08:06	Officer: personal
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-309692593
Desc.: Road Damage - loose drain covers			
Location: on carriageway outside No. p Loughborough Road		Contact:	
Enquiry No.: 6197691	Logged by: External to Confirm	on: 22/02/2021 07:34	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-309500365
Desc.: Road Pothole - Road is crumbling, full of potholes . Online report Customer title is per			
Location: Opposite the covid test centre the road all the way down to the crossroads heading towards asda weat bridgford is full of holes.		Contact:	
Enquiry No.: 6197517	Logged by: External to Confirm	on: 19/02/2021 13:42	Officer: personal
Service: Road Works	Subject: Road Works Report	Classification: Report or Observation	Enquiry Ref: FS-CASE-309226027
Desc.: Road work issue - loose drain covers			
Location: middle of road		Contact:	
Enquiry No.: 6196524	Logged by: External to Confirm	on: 15/02/2021 10:21	Officer: personal
Service: Carriageway/Footway	Subject: St Furn/Non Illum Sign Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-307863708
Desc.: Traffic sign damage - The sign is covered in weeds and hedges. It is completely unseeable from the road as it is so covered in weeds and the hedge that is growing underneath it. . Submitted by Advisor: personal			
Location: Just behind the bus shelter past the Nottingham Knight, towards West Bridgford		Contact:	
Enquiry No.: 6196358	Logged by: External to Confirm	on: 13/02/2021 00:27	Officer: personal
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-307497887
Desc.: Road Pothole - Series of major potholed along Lane markings, shocking reaily considering its outside county hall! . Online report Customer title pers			
Location: Southbound A60 at traffic lights just south of counth hall		Contact:	
Plot Number: 2,001.00	Feature Id - Location: Bridgford Road To Asda	Feature Type: Street Section	
Job Number: 2764360			
Enquiry No.: 6195346	Logged by: External to Confirm	on: 08/02/2021 23:42	Officer: Dropped Kerb Requests
Service: Carriageway/Footway	Subject: Dropped Kerb (Vehicle) Request	Classification: Service Request	Enquiry Ref: FS-CASE-305900982
Desc.: Dropped kerb - Cars & other vehicles - To install drop kerb for new driveway access point on left of property to replace existing dangerous driveway access on right of property that is by traffic lights and pedestrian crossing . Online report - Quote required 5 whole kerb(s) and 2 tapered kerb(s) to be dropped Position of kerb - Drop kerb to be running left to right starting from the left hand boundary fence Streetlight - No Customer title pers			
Location: Facing the front of per Loughborough Road drop kerb proposed from left hand boundary fence across front of property. Near bike cycle sign on bent pole.		Contact:	

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6195128

Logged by: External to Confirm

on: 08/02/2021 12:18

Officer: personal

Service: Carriageway/Footway

Subject: Bus Shelter/Stop Enquiry

Classification: Report or Observation

Enquiry Ref: FS-CASE-305666140

Desc.: Bus shelter request - 05/02/2021 16:18:42

personal

Transport Department

or the Public

Dear Sir/Madam

I would like to request that NCT build a bus shelter at the number 8 bus stop at Cloverlands on Landmere Lane, West Bridgford NG2. The stop is very exposed to the elements

This bus stop is a large gathering point for all number 8 bus users that live off Brompton way, Botany Close, Cloverlands, Bressingham Drive, Belgrave Mews, Slaone Court & Ennismore Mews etc.etc.

It would greatly appreciated by all the users to take shelter under cover whilst waiting for the bus.

I am a frequent user of NCT & from Nottingham City centre & it is very often the topic of conversation that is spoken about with other bus users whilst waiting for the No 8 bus.

Kind regards

pe

South . Submitted by Advisor: personal - Customer title pers

Location: Number 8 bus stop at Cloverlands on Landmere Lane, West Bridgford NG2

Contact:

Enquiry No.: 6194472

Logged by: External to Confirm

on: 05/02/2021 10:36

Officer: Dropped Kerb Requests

Service: Carriageway/Footway

Subject: Dropped Kerb (Vehicle) Request

Classification: Service Request

Enquiry Ref: FS-CASE-304686577

Desc.: Dropped kerb - Cars & other vehicles - Calling with regards to the ongoing issues with the development. The developers are Lindon Homes and they are working on the area. The caller needs to speak with someone urgent. I have spoken with the licencing team to gain an update but it might be being managed by personal. I have been unable to get hold of per. Can someone please contact the customer as he is concerned as the work on the road is starting next week.

It is to make sure that his property can have double parking spots. . Submitted by Advisor: person - Quote NOT required 2 whole kerb(s) and 2 tapered kerb(s) to be dropped Position of kerb - It is the front of the property as previously discussed. Streetlight - No Customer title pers

Location: Magpie Crescent,
WEST BRIDGFORD,
West Bridgford,
Nottinghamshire,
NG2 7ZJ,

Contact:

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6192527	Logged by: External to Confirm	on: 28/01/2021 10:24	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-301398941
Desc.: Road Pothole - Potholed and badly broken road surface . Online report Customer title is pe			
Location: Loughborough Road and Cambridge Court		Contact:	
Enquiry No.: 6190797	Logged by: External to Confirm	on: 19/01/2021 21:39	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-298043600
Desc.: Road Damage - There is a considerable chunk of badly damaged road surface covering approx 30 feet in the outer lane. Due to the close proximity to the property I live in every time a lorry or other heavy vehicle drives over this it causes very noticeable vibration to the whole property. A couple of years ago the northbound section of this road was resurfaced all the way down to Trent Bridge but the southbound section has been ignored. There is also road damage at the junction where Millicent Road joins Loughborough Road where the traffic lights are. . Online report Customer title is pe			
Location: Directly opposite p Loughborough Road on the southbound carriageway also directly opposite the bus stop.		Contact:	
Enquiry No.: 6187827	Logged by: External to Confirm	on: 30/12/2020 13:42	Officer: person
Service: Carriageway/Footway	Subject: Traffic Signal Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-289413155
Desc.: Traffic light damage - Sticker placed on 'pedestrian' green/red man crossing indicator - please see photo. . Online report Customer title per			
Location: Pedestrian crossing signal at junction of Bridgford Road and Loughborough Road, West Bridgford.		Contact:	
Enquiry No.: 6187306	Logged by: External to Confirm	on: 23/12/2020 15:21	Officer: person
Service: Carriageway/Footway	Subject: Flooding	Classification: Report or Observation	Enquiry Ref: FS-CASE-287203811
Desc.: Street flooding - Flooding to road and pavement at ASDA junction Gullies and manholes surcharged back to Fire Station on Loughborough road. This is a repetitive problem that has been ongoing for a number of years with no signs of improvement, making it a very unpleasant road to navigate as a pedestrian and dangerous as a driver with manholes moved under pressure of water in the carriage way.. Online report Customer title pers			
Location: Flooding to the junction of Asda/Loughborough road - Manholes surcharged to Fire Station		Contact:	
Enquiry No.: 6187279	Logged by: External to Confirm	on: 23/12/2020 14:08	Officer: person
Service: Carriageway/Footway	Subject: Manholes/Gullies	Classification: Report or Observation	Enquiry Ref: FS-CASE-287175558
Desc.: Missing and damaged manhole/drain covers - water from drain has lifted the man hole cover so the drain is now not covered. Submitted by Advisor: person ers			
Location: outside west bridgeford fire station		Contact:	
Enquiry No.: 6186498	Logged by: External to Confirm	on: 15/12/2020 15:36	Officer: person
Service: Licences/Permits	Subject: Skip Licence Request	Classification: Service Request	Enquiry Ref: FS-CASE-284217093
Desc.: Parking issues - Customer is reporting that the pavement is being blocked at an address near the second set of traffic lights on Loughborough Road with a skip which is causing pedestrian to go onto the road to avoid it which is quite dangerous due to the speed the vehicles travel on this stretch of road. . Submitted by Advisor: person			
Location: Loughborough Road in West Bridgeford coming from Traffic lights where Wilford Lane and Melton Road meet, in the direction towards Trent Bridge at the second set of traffic lights.		Contact:	
Enquiry No.: 6186434	Logged by: External to Confirm	on: 15/12/2020 09:51	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-284019113
Desc.: Road Pothole - Large pothole . Online report Customer person			
Location: I was cycling by it and had to avoid it.		Contact:	
Enquiry No.: 6186072	Logged by: External to Confirm	on: 11/12/2020 15:45	Officer: person
Service: Road Works	Subject: Road Works Report	Classification: Report or Observation	Enquiry Ref: FS-CASE-282856572
Desc.: Road work issue - Wheelchairs and pushchairs cannot get through the adjacent street furniture. Photo taken is too large for your files . Online report Customer title pers			
Location: Resident having work done had stacks of bricks on public footpath preventing access to safely get to the pefestrian crossing.		Contact:	

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6185241	Logged by: External to Confirm	on: 03/12/2020 16:30	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-279740665
Desc.: Road Pothole - Large break and pothole in the road which cannot be avoided as you have to turn here to get off Wilford lane. This results in cars sometimes even sliding in wet conditions and is dangerous . Online report Customer title per			
Location: As you turn left off Wilford lane on to the A60	Contact:		
Enquiry No.: 6185004	Logged by: External to Confirm	on: 01/12/2020 12:25	Officer: personal
Service: Carriageway/Footway	Subject: Line Marking/Stud Renewal	Classification: Report or Observation	Enquiry Ref: FS-CASE-278702079
Desc.: New road marking (including disabled parking bay / yellow lines) - I would like to request the road markings at and around 'the Point' junction be repainted. From all directions, the traffic light stop lines are faded and unclear, as well as the cycle boxes being almost non-existent - the traffic light stop line heading southbound on Loughborough Road (where you can either turn right onto Wilford Lane or carry straight on to stay on Loughborough Road) has completely faded away! This is causing an inordinate number of drivers to pull all the way forwards and into what should be the cycle box, pushing cyclists and motorcyclists that filter to the front of traffic much further forwards than is safe. This also means that a fair number of drivers who like to creep forwards at red lights (because as we all know, the more you creep forwards, the faster the light changes...) end up blocking the pedestrian crossings; in fact, I have seen a handful of drivers that have crept so far forwards, they had to reverse to see the lights go green. The final issue I wish to raise is when heading southbound on Loughborough Road, just after the junction with Millicent Road, where Loughborough Road splits from two lanes to three. According to the road markings, the left hand lane stays as the left hand lane and takes you on to Melton Road, whereas the right hand lane splits into the turn right and straight-on lanes. I know this from being observant, but the lane-dividing lines are very unclear. I therefore know from an almost daily experience that drivers will drift across from the left lane to the middle lane without much care or thought, nearly crashing into me in the process, as they are simply unaware of how the lanes split. . Online report - Customer title pers			
Location: 'The Point' junction, where Wilford Lane, Loughborough Road and Melton Road all converge	Contact:		
Enquiry No.: 6183600	Logged by: External to Confirm	on: 16/11/2020 11:15	Officer: personal
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS272837766
Desc.: Insurance claim - related to Confirm defect reference: 6183599 Date/Time: 14/11/2020 10:30:00 Direction of travel: Southbound on Loughbough rd Account of what happened: Was running on the main st of Loughbough rd going south to run back to home property when the wire loose out of the pavement got caught of customers foot and caused her to fall down. Extensive facial lacerations where nose couldn't be stitched and forehead and to be glued back in place, Black eyes from the impact and quite swollen and also Huge gash open wound on Knees area. Went into the NHS walk in center to get treatment for injuries .			
Location: Outside of Property D Loughborough Rd, West Bridgford, Nottingham NG2 7JT	Contact:		
Enquiry No.: 6183599	Logged by: External to Confirm	on: 16/11/2020 11:13	Officer: personal
Service: Carriageway/Footway	Subject: Footway Obstruction	Classification: Report or Observation	Enquiry Ref: FS-CASE-272837766
Desc.: Insurance claim form requested - Pavement obstructions - Massive black cable 2cm in diameter - 87cm long that is hanging out of the pavement. very dangerous. caused injury to the customer who has had to go to the walk in due to the trip hazard . Submitted by Advisor: personal Customer title is per			
Location: Outside of Property D Loughborough Rd, West Bridgford, Nottingham NG2 7JT	Contact:		
Enquiry No.: 6181264	Logged by: External to Confirm	on: 21/10/2020 16:30	Officer: personal
Service: Other	Subject: Other Enquiry (Highways)	Classification: Report or Observation	Enquiry Ref: FS-CASE-263575204
Desc.: Other enquiry - There was a crossing installed 2-3 years ago and wants to know the statics of putting the crossing in. There is planning application on property that if passed would increase the traffic and they are concerned about the safety of residents etc. They would like to know what the reasons were for putting the crossing in.			
If someone could contact the customer asap with the information or if they require more information. . Submitted by Advisor: personal - Customer title pers			
Location: De Loughborough Road Westbridgford	Contact:		

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6180373

Logged by: External to Confirm

on: 13/10/2020 10:51

Officer: personal

Service: Road Works

Subject: Temporary TROs

Classification: Report or Observation

Enquiry Ref: FS-CASE-260356323

Desc.: Other requests - Email enquiry:

Hi, Please can someone call me about this? We need to progress with this pole installation asap. Thanks

Hi Thank you for this information. However, we are a code powers operator and use the governments Street Manager system which puts all this information required and more to local councils. Looking at your forms I can only assume that the reason it was rejected was because it was less than 14 weeks notice? Can this be confirmed and if so I will re-submit for 14 weeks time.

It is however very urgent so if possible we would like to do this in less than 14 weeks – I would be happy to speak to someone regarding this issue. personal

Thanks

Dear personal,

Thank you for your e-mail.

To request a road closure on the public highway in Nottinghamshire please use the link provided below which includes the application for this and the contact details for the team are listed on the applications.

personal

[Redacted]

Original email:

Your message : Hi, I work for a broadband company "Quickline Communications" we install to rural areas. As part of our installations we install telegraph poles and masts. We use the "Street Manager" gov system to put in requests to install on Council land. One we are trying to push through requires a road closure. I have been trying to put it through on the system, but it keeps being rejected. I have tried emailing the contact on there but no response. Please can i be put in touch with someone from that department to progress this applications.

. Submitted by Advisor: personal Customer title is

Location: Unknown

Contact:

Enquiry No.: 6179384

Logged by: External to Confirm

on: 02/10/2020 13:39

Officer: personal

Service: Trees/Verges

Subject: Grass Cutting

Classification: Report or Observation

Enquiry Ref: FS-CASE-256426589

Desc.: Overgrown grass and verges - I belong to several Heritage groups and the condition of the old Trent Bridge remains has become a talking point. I would like to know who I would need to contact as regards to clearing the weeds and maintaining this important landmark. . Submitted by Advisor: personal

Location: Old Trent Bridge, West Bridgford

Contact:

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6179061 **Logged by:** External to Confirm **on:** 29/09/2020 14:09 **Officer:** person
Service: Carriageway/Footway **Subject:** Dropped Kerb (Vehicle) Request **Classification:** Service Request **Enquiry Ref:** FS-CASE-255145799
Desc.: Dropped kerb - Cars & other vehicles - I need a dropped kerb so I can get my car on the drive. I have bought the house subject to contract but the sale has not gone through yet. There is a sign on the pavement that will need to be moved to get the dropped kerb in. . Submitted by Advisor: person - Quote required 7 whole kerb(s) and 0 tapered kerb(s) to be dropped Position of kerb - I would like to join the dropped kerbs form both neighbours Streetlight - No Customer title pers.
Location: Loughborough road,
West Bridgford,
NG2 7JJ, **Contact:**

Enquiry No.: 6178754 **Logged by:** External to Confirm **on:** 25/09/2020 14:23 **Officer:** person
Service: Carriageway/Footway **Subject:** Footway Obstruction **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-253834214
Desc.: Pavement obstructions - property next door to the pharmacy is empty, unsure of ownership but the signage on the property has fallen and shattered on the footpath. employees have swept up as bet they can but there is more signage that looks as though it will fall at any moment. . Submitted by Advisor: person
Location: Manor Pharmacy Loughborough Road,
West Bridgford ,
Nottinghamshire,
NG2 7JR **Contact:**

Enquiry No.: 6178406 **Logged by:** External to Confirm **on:** 22/09/2020 09:33 **Officer:** person
Service: Carriageway/Footway **Subject:** Manholes/Gullies **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-252400228
Desc.: Missing and damaged manhole/drain covers - In relation to the surrounding issues:
Customer has reported this issue to BT connect following confirmation from a BT worker inspecting the site that it is their equipment under the road. They stated that they would put in a request to get it resolved but this was roughly 2 weeks ago and since the BT employee removed the manhole cover and replaced it during the inspection, the noise issue in this area has become worse.
This issue is causing unbelievable frustration for many residents of this area due to how loud and constant it is and many night shift workers are having difficulties at work due to the noise issues keeping them awake.
Customer would like to request that another request for this to be remedied is sent to BT Connect via NCC to hopefully expedite the remedial works. They are also attempting to try to contact BT via standard customer service routes but are uncertain about how successful this may be.
Finally, due to issues with receiving emails from the previous reports made, customer would like to request a confirmation be sent to them once the above is completed so they can update other residents who are also suffering due to these issues.. Submitted by Advisor: person
Location: A60 Loughborough Road, West Bridgford **Contact:**

Enquiry No.: 6177819 **Logged by:** External to Confirm **on:** 16/09/2020 09:24 **Officer:** person
Service: Carriageway/Footway **Subject:** Traffic Signal Fault **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-250242720
Desc.: Traffic light fault - Crossing Loughborough Road from Millicent Road heading towards Sandringham Ave, using the city bound pedestrian crossing. When the crossing button is pressed, and the light comes on around it, it sometimes goes off again without the traffic being shown the red light. Sometimes it takes 2 or three sequences to stop the traffic. . Online report Customer person
Location: Central Reservation between Millicent Rd and Sandringham Ave **Contact:**

Enquiry No.: 6177293 **Logged by:** External to Confirm **on:** 10/09/2020 11:51 **Officer:** person
Service: Other **Subject:** Other Enquiry (Highways) **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-248101953
Desc.: Other enquiry - PLanning ref - 20/01817/ful
change of use
customer would like to query the response from highways. the main issue is some of the assumptions in the report - email to follow.
Deadline of 15/09/2020 for resolution for the planning . Submitted by Advisor: person
Location: Loughborough Road **Contact:**

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6177215	Logged by: External to Confirm	on: 09/09/2020 15:09	Officer: personal
Service: Other	Subject: Other Enquiry (Highways)	Classification: Report or Observation	Enquiry Ref: FS-CASE-247754774
Desc.: Other enquiry - Can the general public use County Hall's Electrical charging station? . Submitted by Advisor: personal			
Location: County Hall	Contact:		
Enquiry No.: 6175298	Logged by: External to Confirm	on: 20/08/2020 13:51	Officer: personal
Service: Carriageway/Footway	Subject: Manholes/Gullies	Classification: Report or Observation	Enquiry Ref: FS-CASE-240313413
Desc.: Missing and damaged manhole/drain covers - Inbound lane towards nottingham city - Cust has reported this to STW who advised not a sewer cover and cust has reported it to rushcliffe, this was reported by pe and every time a vichle goes over the drain cover it is a clatter and the 2 part cover is loose and it rattling keeping the residents up during the night as Doctors and Nurses live around here.			
Location: pe Loughborough Road, WEST BRIDGFORD, West Bridgford, Nottinghamshire, NG2 7FD			
Contact:			
on A60			
Enquiry No.: 6174833	Logged by: External to Confirm	on: 17/08/2020 07:32	Officer: personal
Service: Carriageway/Footway	Subject: Line Marking/Stud Renewal	Classification: Report or Observation	Enquiry Ref: FS-CASE-238634881
Desc.: Road marking renewal - Give way markings illegible. There are no supporting give way signs therefore the markings are an essential safety feature. Last year a temporary give way sign was place there but was removed. I've witnessed many near misses as drivers are unaware of the priorities. . Online report Customer title pers			
Location: Junction of Bridgford Road/London Road where traffic merges	Contact:		

Effective: 01/01/2018 to 22/04/2021
Display Action Officer: Yes

Feature No.: 2001.00 to 2001.00
Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6174777 Logged by: External to Confirm on: 14/08/2020 13:03 Officer: [redacted]
Service: Other Subject: Other Request (Highways) Classification: Service Request Enquiry Ref: FS-CASE-238409300
Desc.: Other requests - 13/08/2020 15:20:22
[redacted] personal [redacted] Unattributable Works DetailsJK008GCAI28042020120436

URGENT 3rd Chase

Good afternoon guys.

Please may I 3rd chase as a matter of urgency any additional photo evidence for t[his enquiry.

I have had no response on [redacted] per for this and wish to bring this enquiry to an aggregable close.

[redacted] personal

[redacted] personal

[redacted]

[redacted]

. Submitted by Advisor: [redacted] personal - Customer title [redacted] pers

Location: N/A

Contact:

Enquiry No.: 6174650 Logged by: External to Confirm on: 13/08/2020 08:21 Officer: [redacted] personal
Service: Carriageway/Footway Subject: Manholes/Gullies Classification: Report or Observation Enquiry Ref: FS237925917
Desc.: Missing and damaged manhole/drain covers - Customer has called today to advise that [redacted] personal [redacted] Severn Trent has been out to look at this manhole cover however he has stated that it is not theirs but belongs to the Nottinghamshire County Council - Severn Trent are due to write a report that it is not theirs.

This has a yellow mark on it for repair but nothing has yet been done (customer does not know how long the yellow mark has been there)

Please can this be looked into again for the customer as this is keeping the residents away all night and is all they can hear day/night.. Submitted by Advisor: [redacted] personal [redacted] . -
Previous Confirm Case: 6173884

Location: Man hole cover Loughborough Road - 6173884

Contact:

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6174457 **Logged by:** External to Confirm **on:** 11/08/2020 10:54 **Officer:** personal
Service: Trees/Verges **Subject:** Fallen Tree **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-237239436
Desc.: Damaged/dangerous/fallen tree -

The house across the road from us has a 15 metre high dead tree in the garden. It sits adjacent to Loughborough Road and is next to a bus stop with a 7 ft stone wall on the boundary. The dead tree has been mentioned to the home owner before and nothing has been done. I am concerned it will fall into the main road or drop large branches onto cars/pedestrians. . Online report Customer title is per

Location: pe Loughborough road**Contact:**

Enquiry No.: 6174174 **Logged by:** External to Confirm **on:** 07/08/2020 07:45 **Officer:** person
Service: Carriageway/Footway **Subject:** Traffic Signal Fault **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-235983264
Desc.: Traffic light fault - Traffic lights not working . Online report Customer title per .
Location: Pelican crossing at end of Millicent Road **Contact:**

Enquiry No.: 6173929 **Logged by:** External to Confirm **on:** 04/08/2020 13:18 **Officer:** personal
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-235012429
Desc.: Road Damage - The illegible appropriate direction arrows have recently been refreshed, however, the arrow in the centre lane now only indicates the appropriate use for ahead. Prior to the refreshment this was a combination of ahead and right. The layout of the roundabout hasn't changed therefore it is still appropriate to use the centre lane. Drivers unfamiliar with this may not realise and switch lanes on exiting. . Online report Customer title is pe
Location: Entrance to Nottingham Knight roundabout **Contact:**

Enquiry No.: 6173927 **Logged by:** External to Confirm **on:** 04/08/2020 13:15 **Officer:** personal
Service: Trees/Verges **Subject:** Tree Enquiry **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-235010272
Desc.: Road Damage - Road traffic direction sign almost completely covered in foliage. . Online report Customer title per .
Location: Between the junction of Europa Way and Landmere Lane. **Contact:**

Enquiry No.: 6173884 **Logged by:** External to Confirm **on:** 04/08/2020 09:30 **Officer:** person
Service: Carriageway/Footway **Subject:** Manholes/Gullies **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-234905897
Desc.: Missing and damaged manhole/drain covers - Loose man hole cover making a lot of noise when being ran over, disturbing the residents. . Submitted by Advisor: personal Customer title is per
Location: On the A60, Loughborough Road, West Bridgford **Contact:**

Enquiry No.: 6173784 **Logged by:** External to Confirm **on:** 03/08/2020 10:27 **Officer:** personal (NRSWA)
Service: Carriageway/Footway **Subject:** Manholes/Gullies **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-234537706
Desc.: Missing and damaged manhole/drain covers - Cust email report -

The above manhole cover is banging every time a vehicle wheel or wheels runs over it, This is happening 24 hrs a day and started about a month ago.

I tried to highlight the location on your online map but it would not allow me to focus on the precise position. You have already received a copy of my observations from Rushcliffe Borough Council

Regards

personal

. Submitted by Advisor: personal

Location: On the inbound A60 near to the entrance to Southern Cemetery Wilford Hill.**Contact:**

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6173154 **Logged by:** External to Confirm **on:** 27/07/2020 09:42 **Officer:** personal
Service: Carriageway/Footway **Subject:** St Furn/Non Illum Sign Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-232207086
Desc.: Traffic sign request - Asked to log by personal for response.

I am on our local parish council and we are wondering about trying to install an interactive speed sign ourselves in the village. I have a few queries.

- a) Is this something that we can do or would if have to have the consent of the council?
- b) Would a solar powered unit work 24/7 continuously
- c) What would the cost per unit be approx
- d) Is it something that we cab install ourselves?

Is there anything else that we should know? . Submitted by Advisor: personal

Location: unknown but personal **Contact:**

Enquiry No.: 6172867 **Logged by:** External to Confirm **on:** 23/07/2020 10:27 **Officer:** Vehicle Access Licences
Service: Carriageway/Footway **Subject:** Dropped Kerb (Vehicle) Request **Classification:** Service Request **Enquiry Ref:** FS-CASE-231064283
Desc.: Contractor App
Location: Loughborough Road, West Bridgford, Nottingham , NG2 7qq **Contact:**

Enquiry No.: 6171268 **Logged by:** External to Confirm **on:** 06/07/2020 09:11 **Officer:** personal
Service: Trees/Verges **Subject:** Overhanging Vegetation/Trees **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-224645720
Desc.: Overgrown hedges and vegetation - Hedge possibly belonging to the Housing Association needs cutting back to the path line. . Online report Customer person
Location: Loughborough Road/Old Road **Contact:**

Enquiry No.: 6170180 **Logged by:** External to Confirm **on:** 23/06/2020 15:48 **Officer:** personal
Service: Other **Subject:** Other Request (Highways) **Classification:** Service Request **Enquiry Ref:** FS-CASE-220425718
Desc.: Other requests - Speed bump removal or adjustment

There is a speed bump right outside the door of this establishment which a customer has tripped over and injured themselves severely - landed on chest and head, laceration to head, compression injury to chest, grazing on fore arms knees and hands.

personal

Customer would like this removing, moving or making more obvious.

. Submitted by Advisor: personal

Location: Herring Bone off of Loughborough Road, outside Wolds Fish Bar **Contact:**

Enquiry No.: 6169789 **Logged by:** External to Confirm **on:** 19/06/2020 13:12 **Officer:** personal
Service: Trees/Verges **Subject:** Overhanging Vegetation/Trees **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-219101364
Desc.: Overhanging trees - The hedges from the Boundary Road play area are overhanging on to the pavement and in some cases you have to step out into a very busy dangerous road to avoid the branches . Online report Customer person.
Location: Loughborough Road West Bridgford, near the Boundary Road junction **Contact:**

Enquiry No.: 6169761 **Logged by:** External to Confirm **on:** 19/06/2020 09:57 **Officer:** personal
Service: Road Works **Subject:** Road Works Report **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-218648593
Desc.: Road work issue - Raw sewage rising from mahole cover . Online report Customer person
Location: Rugby Court on Loughborough Road **Contact:**

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6169376	Logged by: External to Confirm	on: 17/06/2020 12:51	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-218279276
Desc.: Road Pothole - We have received the following email from a customer:			
Pothole on Loughborough Road, West Bridgford near Aries Motors Dear Customer Services Centre There is a pothole on Loughborough Road, West Bridgford, when heading south near County Hall, just outside Aries Motors Yours sincerely personal			
. Submitted by Advisor: personal			
Location: Loughborough Road near Aries Motors	Contact:		
Enquiry No.: 6169264	Logged by: External to Confirm	on: 16/06/2020 15:06	Officer: personal
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	Enquiry Ref: FS-CASE-217937983
Desc.: Other tree issues - There is a cherry tree located in front of the caller's flat which has been dead for 3 years now, every year the cherry blossom blooms but this trees branches remain bare. Is there a reason why this hasn't been cut down yet? . Submitted by Advisor: personal			
Location: On the A60 Loughborough Road in the raised beds in front of the caller's flat.	Contact:		
Enquiry No.: 6167426	Logged by: External to Confirm	on: 26/05/2020 07:39	Officer: personal
Service: Other	Subject: Other Enquiry (Highways)	Classification: Report or Observation	Enquiry Ref: FS-CASE-210058372
Desc.: Other enquiry - Cust email -			
Verges twitter enquiry To whom it may concern,			
I have been in contact on twitter about the practices which have been adopted in West Bridgford for the mowing of verges and other areas of public open space. I would like to have sight of the visibility studies and impact assessments which have been carried out to determine the viability of leaving verges as wildflower habitats. Particularly the verge on the corner of Loughborough Road opposite the junction with Boundary Road which has apparently had to be cut short to maintain visibility of the highway. Regards personal			
Location: Loughborough Road opposite the junction with Boundary Road West Bridgford the verges	Contact:		
Enquiry No.: 6165603	Logged by: External to Confirm	on: 06/04/2020 10:54	Officer: personal
Service: Carriageway/Footway	Subject: St Furn/Non Illum Sign Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-192628730
Desc.: Traffic sign damage - There is a cycle sign that is tilted and the tarmac is coming up, possibly been hit by a car. . Submitted by Advisor: personal			
Location: Just before the traffic lights next to Carphone warehouse in West Bridgford on Loughborough Road	Contact:		
Enquiry No.: 6165399	Logged by: External to Confirm	on: 27/03/2020 12:50	Officer: personal
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-188514210
Desc.: Road Pothole - Pothole . Online report Customer title pers			
Location: Located on the double yellow lines outside the retirement living complex on Loughborough Road just before the traffic light junction.	Contact:		
Plot Number: 2,001.00	Feature Id - Location: Bridgford Road To Asda	Feature Type: Street Section	
Job Number: 2741172	Defect Number: 3637401		

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6165185 Logged by: External to Confirm on: 23/03/2020 07:39 Officer: **personal**
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation Enquiry Ref: FS-CASE-186338070
 Desc.: Road Pothole - Significant pot hole at edge of road, causing damage to car suspension when drive over daily to access driveway . Online report Customer **personal** .
 Location: **DE** Loughborough Road, west bridgford, NG2 7JS Contact:

Plot Number: 2,001.00 Feature Id - Location: Bridgford Road To Asda Feature Type: Street Section
 Job Number: 2740907 Defect Number: 3637136

Enquiry No.: 6165125 Logged by: External to Confirm on: 20/03/2020 12:56 Officer: **personal**
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation Enquiry Ref: FS-CASE-185613626
 Desc.: Road Pothole - developing pothole in middle of carriageway. . Online report Customer title is
 Location: Loughborough Road, Trent Bridge, inbound. Contact:

Enquiry No.: 6164253 Logged by: External to Confirm on: 12/03/2020 09:21 Officer: **personal**
 Service: Road Works Subject: Road Works Report Classification: Report or Observation Enquiry Ref: FS-CASE-182870770
 Desc.: Road work issue - A large road sign has been placed inside residents driveway blocking his entrance. He is unable to open his gates. No indication of who will be doing works no notification of works to be carried out near his property. Dangerous to exit his property onto a busy road with one gate open open. Please can we have this sign moved from his drive asap p[lease] . Submitted by Advisor: **personal** .
 Location: Outside **personal** Loughborough Road, Contact:
 RUDDINGTON,
 West Bridgford,
 Nottinghamshire,
 NG11 6LU

Enquiry No.: 6164250 Logged by: External to Confirm on: 12/03/2020 08:24 Officer: South Highways Management
 Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation Enquiry Ref: FS-CASE-182855806
 Desc.: Road Damage - Main Wilford Lane traffic junction road is in a terrible state. Multiple potholes. It's like driving over a pile of rocks. . Online report Customer title **pers** .
 Location: Wilford Lane traffic lights. Turning left to drive North towards county hall from Wilford Lane. Contact:

Enquiry No.: 6164094 Logged by: External to Confirm on: 11/03/2020 10:33 Officer: **personal**
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation Enquiry Ref: FS-CASE-182546435
 Desc.: Road Pothole - Deep pothole . Online report Customer **personal** .
 Location: Outside Century residential Home on Loughborough road heading towards the city Contact:

Plot Number: 2,001.00 Feature Id - Location: Bridgford Road To Asda Feature Type: Street Section
 Job Number: 2739851

Enquiry No.: 6163860 Logged by: External to Confirm on: 09/03/2020 22:12 Officer: **personal**
 Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation Enquiry Ref: FS-CASE-182066193
 Desc.: Road Pothole - pothole . Online report Customer **personal** .
 Location: outside no. **p** loughborough road Contact:

Plot Number: 2,001.00 Feature Id - Location: Bridgford Road To Asda Feature Type: Street Section
 Job Number: 2739851 Defect Number: 3636101

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6163421	Logged by: External to Confirm	on: 06/03/2020 10:57	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-181017013
Desc.: Road Pothole - Pothole at junction on right hand side of southbound lane. I drove over it this morning, slowly owing to approaching the traffic lights, and it was a terrific jolt. May be damage to tyre. . Online report Customer title pers			
Location: A60 Asda junction at traffic lights, southbound	Contact:		
Plot Number: 2,001.00	Feature Id - Location: Bridgford Road To Asda	Feature Type: Street Section	
Job Number: 2739017			
Enquiry No.: 6163142	Logged by: External to Confirm	on: 04/03/2020 20:54	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-180514815
Desc.: Road Damage - various damages, worst is close to left kerb. . Online report Customer person			
Location: wilford lane / loughborough road. across both lanes of wilford lane before entering loughborough road. in front of the Point building,	Contact:		
Enquiry No.: 6163093	Logged by: External to Confirm	on: 04/03/2020 16:33	Officer: person
Service: Carriageway/Footway	Subject: Traffic Signal Fault	Classification: Report or Observation	Enquiry Ref: FS-CASE-180438751
Desc.: Traffic light fault - The pedestrian crossing just before Trent Bridge as you drive into the City Centre is working, however the traffic lights which stop cars driving over the pedestrian crossing are not there. Therefore, when the green man is displayed and pedestrians are crossing, cars are still driving over it. . Submitted by Advisor: personal			
Location: The pedestrian crossing just before Trent Bridge as you drive into the City Centre	Contact:		
Enquiry No.: 6162696	Logged by: External to Confirm	on: 03/03/2020 10:00	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-179893942
Desc.: Road Damage - Various locations along A60 Loughborough Rd, both down the centre line of the whole road as well as on each lane, and edges near pavements: too many to list and photograph. Been there far too long causing vehicle damage, traffic to swerve and dangers to cuclists/motorcyclists. . Online report Customer title pers			
Location: Various locations along A60 Loughborough Rd, both down the centre line of the whole road as well as on each lane, and edges near pavements.	Contact:		
Enquiry No.: 6162693	Logged by: External to Confirm	on: 03/03/2020 09:54	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-179890951
Desc.: Road Pothole - Various deep potholes around junction of Asda supercentre entry & exit and directly at traffic lights, facing south on Loughborough Rd, adjacent to Asda exit. Dangerously and damagingly deep, causing traffic to swerve. . Online report Customer title pers			
Location: Various deep potholes around junction of Asda supercentre entry & exit and at traffic lights on Loughborough Rd, adjacent to Asda exit	Contact:		
Plot Number: 2,001.00	Feature Id - Location: Bridgford Road To Asda	Feature Type: Street Section	
Job Number: 2739017	Defect Number: 3635267		
Enquiry No.: 6161856	Logged by: External to Confirm	on: 28/02/2020 12:39	Officer: Dropped Kerb Requests
Service: Carriageway/Footway	Subject: Dropped Kerb (Vehicle) Request	Classification: Service Request	Enquiry Ref: FS-CASE-178814758
Desc.: Dropped kerb - Cars & other vehicles - Kerb already dropped but is requesting a further drop. Spoke to private contractors and they say they need permission from ourselves before doing so. Kerbs to be altered about a metre and a half stretch . Submitted by Advisor: personal Quote NOT required 1 whole kerb(s) and 1 tapered kerb(s) to be dropped Position of kerb - Extension of one and a half meters Streetlight - No Customer person			
Location: pe Hollies Day Nursery Loughborough Road, West Bridgford, NG2 7JX,	Contact:		

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6161112 **Logged by:** External to Confirm **on:** 25/02/2020 15:58 **Officer:** person
Service: Traffic Management **Subject:** Parking General **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-177760017
Desc.: Parking issues - There is a gentleman living in his car at the bottom person drive. He is urinating and causing a disturbance.

He is parked on restriction lines and needs to be moved.

person already contacted the police and district council. Both are unable to act quickly. Police have outright said they will not act on the matter.

Please can someone look into this.

Vehicle reg: person Submitted by Advisor: person

Location: pe Loughborough Road,
WEST BRIDGFORD,
West Bridgford,
NG2 7FB **Contact:**

Enquiry No.: 6160110 **Logged by:** External to Confirm **on:** 20/02/2020 10:15 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-176439835
Desc.: pothole
Location: pothole **Contact:**

Enquiry No.: 6160109 **Logged by:** External to Confirm **on:** 20/02/2020 10:12 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-176439492
Desc.: deep and wide
Location: large pothole **Contact:**

Enquiry No.: 6160108 **Logged by:** External to Confirm **on:** 20/02/2020 10:12 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-176439345
Desc.: deep and wide
Location: large pothole **Contact:**

Enquiry No.: 6159183 **Logged by:** External to Confirm **on:** 17/02/2020 09:15 **Officer:** person
Service: Carriageway/Footway **Subject:** Flooding **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-175467102
Desc.: Street flooding - flooding on the highway adjacent to bus stop. This seems to be a routine occurrence after rain, perhaps due to a lack of drainage at this location. It makes it difficult for buses to approach the stop without causing water to be washed onto the footway, and waiting passengers.. Online report Customer title per .
Location: adjacent to bus stop RU0002, County Hall, Loughborough Road, northbound. **Contact:**

Enquiry No.: 6158661 **Logged by:** External to Confirm **on:** 13/02/2020 12:39 **Officer:** South Highways Management
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-174623449
Desc.: Road Damage - Potholes, road damage and stones/debris . Online report Customer person .
Location: Road damage and deterioration starting outside Aries Motor Co. and between the lanes outside Baron's court/Slater and Brandley. **Contact:**

Plot Number: 2,001.00
Job Number: 2728469

Feature Id - Location: Bridgford Road To Asda

Feature Type: Street Section

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6158328 **Logged by:** External to Confirm **on:** 11/02/2020 20:30 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-174159091
Desc.: Road Damage - The Loughborough Road from the Wolds Pubs is a shocking state big potholes and a lot of the road looks like it is breaking up. It is badly in need of resurfacing, it makes for dangerous driving with other car users swerving to miss the large potholes . Online report Customer title is
Location: Loughborough Road West Bridgford from the Wolds Pub all the way to County Hall **Contact:**

Plot Number: 2,001.00 **Feature Id - Location:** Bridgford Road To Asda **Feature Type:** Street Section
Job Number: 2737010

Enquiry No.: 6158317 **Logged by:** External to Confirm **on:** 11/02/2020 19:03 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-174144787
Desc.: Road Pothole - Large pothole right hand side of right-most lane travelling from trent Bridge To West Bridgford (North to South) at junction with Balmoral Avenue. . Online report Customer title is
Location: Large pothole right hand side of right-most lane travelling from trent Bridge To West Bridgford (North to South) at junction with Balmoral Avenue. **Contact:**

Plot Number: 2,001.00 **Feature Id - Location:** Bridgford Road To Asda **Feature Type:** Street Section
Job Number: 2737010

Enquiry No.: 6158279 **Logged by:** External to Confirm **on:** 11/02/2020 16:24 **Officer:** person
Service: Carriageway/Footway **Subject:** Traffic Signal Fault **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-174107436
Desc.: Traffic light fault - Please see customer email below
Traffic lights at junction of A60/ A606 / Wilford Lane.
During "normal" hours, these lights operate to a sequence, but "out-of-hours" are activated by vehicles.

I ride for Nottingham Blood Bikes and am often out overnight. When I return from a call out, the sensors are not picking up a motorbike (quite a large one - Yamaha FJR1300) and therefore I have to either detour to get home, or wait for a car to set the lights for me to travel through. I have waited for 5 minutes before, so the sensors are definitely not picking up a bike.
Can you get someone to look at this to ensure us motorcyclists don't have to detour to get through this junction. (I'm turning right into Wilford Lane, having come across Trent Bridge, i.e. heading south).
Please do get in touch with me if you need further info. to resolve this.
Regards
per

. Submitted by Advisor: person
Location: junction of A60/ A606 / Wilford Lane **Contact:**

Enquiry No.: 6158205 **Logged by:** External to Confirm **on:** 11/02/2020 12:21 **Officer:** South Highways Management
Service: Carriageway/Footway **Subject:** Manholes/Gullies **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-174017008
Desc.: Blocked gullies - Gully has been blocked for a while, leading to frequent localised flooding in front of the bus stop.. Submitted by Advisor: person
Location: Fix My Street map shows the location as the bus stop on Loughborough Road outside County Hall. **Contact:**

Enquiry No.: 6157969 **Logged by:** External to Confirm **on:** 10/02/2020 14:45 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-173768414
Desc.: Road Pothole - potholes . Online report person
Location: roughly where marked but there are a number in this area that need doing. **Contact:**

Plot Number: 2,001.00 **Feature Id - Location:** Bridgford Road To Asda **Feature Type:** Street Section
Job Number: 2737010 **Defect Number:** 3633264

Effective: 01/01/2018 to 22/04/2021
 Display Action Officer: Yes

Feature No.: 2001.00 to 2001.00
 Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6157952 **Logged by:** External to Confirm **on:** 10/02/2020 14:34 **Officer:** personal
Service: Cycling & Covid-19 temp **Subject:** Cycling Issues **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-173748050
Desc.: All other cycling issues - Vehicles using footpath / cycleway to access Loughborough Road. Needs a new bollard installing to prevent vehicle access and ensure they use the proper road to access. . Online report Customer person
Location: Loughborough Road cul-de-sac opposite Boundary Road, West Bridgford **Contact:**

Enquiry No.: 6157387 **Logged by:** External to Confirm **on:** 06/02/2020 16:27 **Officer:** personal
Service: Trees/Verges **Subject:** Tree Enquiry **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-172963350
Desc.: Other enquiry - Customer has called today to make an enquiry as to where the wood goes when highways chop a tree down and if this is wood is available to collect for local residents.
 Parents live within the Gedling area and believes that they would benefit from the wood due to them having a wood stove.
 Please can you contact the customer back if this information is available and if so where he can go to collect the wood. . Submitted by Advisor: personal
Location: PIN NOT RELEVANT **Contact:**

Enquiry No.: 6157339 **Logged by:** External to Confirm **on:** 06/02/2020 13:18 **Officer:** personal
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-172899640
Desc.: Road Damage - Large area of road crumbling. Black tarmac square at junction past traffic lights with traffic coming from Wilford Lane turning left to A60 towards County Hall is in a bad state of repair. . Online report person
Location: Large area of road crumbling. Black tarmac square at junction past traffic lights with traffic coming from Wilford Lane turning left to A60 towards County Hall is in a bad state of repair. **Contact:**

Enquiry No.: 6157225 **Logged by:** External to Confirm **on:** 05/02/2020 15:30 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-172672513
Desc.: approx 2ft wide and 3ft long and must be 2-3 inches deep
Location: large pothole centre of the lane **Contact:**

Enquiry No.: 6156975 **Logged by:** External to Confirm **on:** 04/02/2020 11:57 **Officer:** personal
Service: Carriageway/Footway **Subject:** Blocked Drain **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-172318709
Desc.: Blocked drains - Water gushing out of the road drain - running down the road on the surface towards the school entrance. Online report Customer person
Location: Just below the fire station towards ASDA **Contact:**

Enquiry No.: 6156954 **Logged by:** External to Confirm **on:** 04/02/2020 10:39 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-172292946
Desc.: Road Pothole - Large potholes and road deterioration . Online report Customer person
Location: Outside the SkIn clinic **Contact:**

Plot Number: 2,001.00 **Feature Id - Location:** Bridgford Road To Asda **Feature Type:** Street Section
Job Number: 2736435 **Defect Number:** 3632692

Enquiry No.: 6156714 **Logged by:** External to Confirm **on:** 03/02/2020 07:36 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-171956035
Desc.: Road Pothole - A huge hole in the road lined up perfectly for your passenger side wheel to fall into. There is a notice on your map saying it was reported 14 days ago. If that is the case then why hasn't it been repaired yet? It's deep enough to cause serious damage leading to compensation claims so needs fixing straight away. . Online report Customer title pers
Location: O/S of pe Loughborough Road, West Bridgford. **Contact:**

Plot Number: 2,001.00 **Feature Id - Location:** Bridgford Road To Asda **Feature Type:** Street Section
Job Number: 2734686

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6156648	Logged by: External to Confirm	on: 03/02/2020 07:35	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-171844327
Desc.: Road Pothole - All along Loughborough road through west Bridfgord is like Swiss cheese . Online report Customer person .			
Location: All along Loughborough road through west Bridfgord is like Swiss cheese		Contact:	
Enquiry No.: 6156468	Logged by: External to Confirm	on: 31/01/2020 08:30	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-171457104
Desc.: Road Damage - Junction driving from Wilford Lane towards County Hall has a large area of road in poor condition. A large square of black tarmac that was presumably an attempted road repair is crumbling and doesn't feel like a road at all. . Online report Customer person .			
Location: Junction driving from Wilford Lane towards County Hall has a large area of road in poor condition. A large square of black tarmac that was presumably an attempted road repair is crumbling and doesn't feel like a road at all.		Contact:	
Enquiry No.: 6155299	Logged by: External to Confirm	on: 23/01/2020 10:57	Officer: person
Service: Carriageway/Footway	Subject: Line Marking/Stud Renewal	Classification: Report or Observation	Enquiry Ref: FS-CASE-169690046
Desc.: Road marking renewal - The white lines on the southbound A60 Loughborough Road at the junction with the Nottingham Knight roundabout are virtually worn away. They need to be repainted so that people can see the lane definitions. . Online report Customer title is			
Location: Southbound A60 Loughborough Road at its junction with the Nottingham Knight roundabout.		Contact:	
Enquiry No.: 6155188	Logged by: External to Confirm	on: 22/01/2020 14:27	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-169509533
Desc.: Road Pothole - Pot holes . Online report Customer title pers .			
Location: A60 Loughborough Road, several potholes on outward bound lanes - getting larger day by day		Contact:	
Enquiry No.: 6154712	Logged by: External to Confirm	on: 20/01/2020 10:11	Officer: person
Service: Carriageway/Footway	Subject: Traffic Signal Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-168918111
Desc.: Traffic light damage - The pedestrian controller on post K3 the conical spinning aid for visual impaired people is missing . . Submitted by Advisor: person person .			
Location: The junction of Loughborough Road and Melton Rd West Briidfgord		Contact:	
Enquiry No.: 6154642	Logged by: External to Confirm	on: 20/01/2020 08:19	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-168815635
Desc.: Road Damage - Very wide pothole. This is shaking our house when lorries pass. This pothole has been re-appearing here for years. It now needs a carriageway repair not another patch up. . Online report Customer title pers .			
Location: On the southbound carriageway of the A60 by the gate of pe Loughborough Road, NG27JS.		Contact:	
Plot Number: 2,001.00	Feature Id - Location: Bridfgord Road To Asda	Feature Type: Street Section	
Job Number: 2734686	Defect Number: 3630948		
Enquiry No.: 6154473	Logged by: External to Confirm	on: 17/01/2020 13:36	Officer: person
Service: Winter Maintenance	Subject: Gritting Request	Classification: Service Request	Enquiry Ref: FS-CASE-168531075
Desc.: Road gritting request - Email from customer dated 16/01/2020 -			
Could you please advise why it was necessary for roads to be gritted in Rushcliffe last evening when the temperature was six degrees and the weather forecast for today was mild and wet. It appears to be unjustified and a waste of our money.			
I await your response			
. Submitted by Advisor: person ers			
Location: Rushcliffe.		Contact:	

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6154441 **Logged by:** External to Confirm **on:** 17/01/2020 12:09 **Officer:** South Highways Management
Service: Carriageway/Footway **Subject:** Footway Obstruction **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-168506233
Desc.: Other enquiry - Very long handle fork has been left by the drainage company who were doing some work about 6 weeks ago. This fork is leaning against the customer's property fence and they are concerned that someone might get hold of it as it looks very dangerous. . Submitted by Advisor: **personal** .
Location: **pe** Loughborough Road,
WEST BRIDGFORD,
West Bridgford,
Nottinghamshire **Contact:**

Enquiry No.: 6153779 **Logged by:** External to Confirm **on:** 14/01/2020 10:27 **Officer:** **personal**
Service: Carriageway/Footway **Subject:** Flooding **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-167736172
Desc.: Street flooding - Large amount of surface water by bus stop. Risk of soaking while waiting for bus.. Online reportCustomer title **per** .
Location: By bus stop **Contact:**

Enquiry No.: 6153553 **Logged by:** External to Confirm **on:** 13/01/2020 08:12 **Officer:** South Highways Management
Service: Carriageway/Footway **Subject:** Blocked Drain **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-167329901
Desc.: Blocked drains - Drain blocked due to soil .
Regular problem because of organic water drained down the street and accumulation of organic matter has led to growth of grass beyond the kerb. Needs clearing the whole extended growth of grass beyond the kerb and also regular clearing to prevent accumulation of organic matter in the first place which could be coincided when cutting the grass in the green area in the surrounding . .
Online reportCustomer title **per**
Location: On the service road in front of property no **pe** Loughborough Road **Contact:**

Enquiry No.: 6153409 **Logged by:** External to Confirm **on:** 10/01/2020 13:21 **Officer:** **personal**
Service: Carriageway/Footway **Subject:** Flooding **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-167077173
Desc.: Street flooding - Customer thinks there is a blocked drain - Every time someone is waiting at the bus shelter, they get splashed by passing vehicles.. Submitted by Advisor: **Spersonal** .
Location: Bus shelter, on Loughborough Road near West Bridgford Orthodontic Centre- **Contact:**

Enquiry No.: 6150806 **Logged by:** External to Confirm **on:** 19/12/2019 09:09 **Officer:** **person**
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-163076600
Desc.: Road Pothole - When travelling southbound on the A60 (Loughborough Rd) there is a pothole roughly outside number **pe** Due to the onstreet parking that occurs in this location in the morning and the degraded centreline (which is also in need of repair) if traffic is heading towards you (northbound into the City) then the neerside wheels always hit this pothole causing a noticeable jar and its difficult to spot in flowing traffic with limited forward visibility of the road surfacing especially in the dark mornings - it's the hole big enough to do your washing up in! . Online report Customer title is **pe**
Location: Roughly outside number **p** Loughborough Road, heading southbound **Contact:**

Plot Number: 2,001.00 **Feature Id - Location:** Bridgford Road To Asda **Feature Type:** Street Section
Job Number: 2731871 **Defect Number:** 3628136

Enquiry No.: 6149879 **Logged by:** External to Confirm **on:** 12/12/2019 16:47 **Officer:** **personal**
Service: Carriageway/Footway **Subject:** Blocked Drain **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-162028533
Desc.: Blocked drains - Drains down the road are blocked and need clearing. Water is collecting on the surface of the road.
Water has been known to be ankle deep and running onto the pavement. Higher than the kerb.
Currently there is no issue but this does need to be resolved as soon as possible to avoid issues where water is running into the properties. . Submitted by Advisor: **personal**
Location: Loughborough Road, West Bridgford, NG2 7JJ. Near the junction of Victoria Road. **Contact:**

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6149828 **Logged by:** External to Confirm **on:** 12/12/2019 13:06 **Officer:** South Highways Management
Service: Carriageway/Footway **Subject:** Manholes/Gullies **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-161979831
Desc.: Missing and damaged manhole/drain covers - 3 x Missing / damaged manhole covers on the pavement- There was a near miss yesterday when the customer saved a lady who almost fell in ..
Submitted by Advisor: **personal**
Location: Loughborough Road - Outside West Park gates **Contact:**

Enquiry No.: 6148850 **Logged by:** External to Confirm **on:** 04/12/2019 10:57 **Officer:** **personal**
Service: Claims **Subject:** Highway Insurance Claim **Classification:** Report or Observation **Enquiry Ref:** FS160579127
Desc.: Insurance claim - related to Confirm defect reference: 6146335
Date/Time: 14/11/2019 14:30:00
Direction of travel: Came out of ASDA & turned right at the lights to head towards Ruddington & it was just after the lights at ASDA, directly opposite the Wolds Public House.

Account of what happened: Dear Sir/Madam

I called today & spoke with **pers** to enquire about how I would make a claim against Nottinghamshire County Council in respect of damage caused to my vehicle after a Manhole cover shot up from its position & smacked the underneath of my car. The manhole cover shot up due to the lack of regular drainage clearance on the A60 Loughborough Road near ASDA causing it to shoot up due to the pressure of the water within there & this occurred on Thursday 14/11/19 during the flooding.

Exact Location A60 Loughborough Road opposite the Wolds Public House, near the Traffic Lights for ASDA on the side facing/heading towards the Nottingham Knight Roundabout (as you come out of ASDA, you turn right & within a few yard - the manhole cover is there).

Description of problem Drains had not been cleared & all the water runs down hill from Wilford Hill Cemetery & the manhole cover could not cope with the pressure of water & shot up (Rushcliffe Borough Council were also made aware of another manhole cover, just further up near the Fire Station doing exactly the same thing.

Description of what happenedAs we approached the manhole cover & our Drivers side wheel got near enough on top of it, it then shot up at force destroying our Drivers side Front shock absorber as well as the top mount & Track Rod end

Location: A60 loughborough road outside wolds pub west bridford **Contact:**

Enquiry No.: 6148578 **Logged by:** External to Confirm **on:** 02/12/2019 14:03 **Officer:** **personal**
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-160235572
Desc.: Road Pothole - Large pot hole around manhole cover causing vehicles to swerve on the other side of the road. in order to avoid it. Damage to vehicles could occur given the depth of the pothole and damage to the road surface around the manhole cover. Why has this not been repaired given how severe it is?! . Online report Customer title **pers**
Location: Loughborough road A60 heading towards the roundabout large pot hole around manhole cover. **Contact:**

Enquiry No.: 6148313 **Logged by:** External to Confirm **on:** 29/11/2019 16:54 **Officer:** **personal**
Service: Carriageway/Footway **Subject:** Traffic Signal Fault **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-159906113
Desc.: Traffic light fault - The traffic lights are not changing properly,They are changing when there is no traffic on Wilford Lane when there is a big queue on the A606.It has been like this for while . .
Submitted by Advisor: **personal**
Location: Junction of Wilford Lane and A606 **Contact:**

Enquiry No.: 6148067 **Logged by:** External to Confirm **on:** 28/11/2019 10:12 **Officer:** **personal**
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-159177334
Desc.: Road Pothole - large deep pothole of left hand side of road . Online report Customer title **perso**
Location: Just before the last set of traffic lights (going towards Loughborough road) on Wilford lane **Contact:**

Plot Number: 2,001.00

Feature Id - Location: Bridgford Road To Asda

Feature Type: Street Section

Job Number: 2729789

Defect Number: 3626063

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6147352	Logged by: External to Confirm	on: 22/11/2019 23:18	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-158337897
Desc.: Road Damage - various potholes from free masons hall towards Melton road . Online report Customer title is			
Location: large pothole surrounding inspection cover and various potholes up to melton road junction			
Contact:			
Enquiry No.: 6146487	Logged by: External to Confirm	on: 16/11/2019 11:27	Officer: personal
Service: Carriageway/Footway	Subject: Traffic Signal Fault	Classification: Report or Observation	Enquiry Ref: FS-CASE-157240779
Desc.: Traffic light fault - The pedestrian signals are incredibly unreliable. Sometimes you will press the button and the light just goes out after a while. If you do get a green man, it only lasts a few seconds. This is kinda dangerous at the best of times, but I'm often pushing a baby in a buggy. . Online report Customer title pers			
Location: The pedestrian crossing signals at the crossroads of Musters, Eton and Rugby Road.			
Contact:			
Enquiry No.: 6146295	Logged by: External to Confirm	on: 15/11/2019 08:12	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Manholes/Gullies	Classification: Report or Observation	Enquiry Ref: FS-CASE-157055103
Desc.: Missing and damaged manhole/drain covers - Missing manhole cover - in the middle of the road. . Submitted by Advisor: personal			
Location: Outside the Wolds Pub on the A60			
Contact:			
Enquiry No.: 6146088	Logged by: External to Confirm	on: 14/11/2019 14:39	Officer: personal
Service: Carriageway/Footway	Subject: Traffic Signal Fault	Classification: Report or Observation	Enquiry Ref: FS-CASE-156965851
Desc.: Other requests - The traffic lights have advanced cycle boxes, but the sensor on Eton Road (and possibly the others) does not recognise a single cyclist, and the lights frequently stay red despite no traffic on the other roads. Is it possible to recalibrate them so a cyclist will trigger the lights? Thanks . Online report - Customer title per			
Location: The traffic light controlled junction between Eton, Loughborough and Rugby Roads			
Contact:			
Enquiry No.: 6146081	Logged by: External to Confirm	on: 14/11/2019 14:34	Officer: personal
Service: Carriageway/Footway	Subject: Flooding	Classification: Report or Observation	Enquiry Ref: FS-CASE-156964341
Desc.: Street flooding - Road flooded. Depth - over a small car wheel. Extends across the entrance. The petrol station is completely flooded and has had to be closed. Any traffic going along Loughborough Road, or in and out of the store is creating bow wave which is making the flooding worse. Flooding will be in the kiosk if the rain doesn't stop,..			
Extention pe if need to call them. May be someone called person if after 5 pm. . Submitted by Advisor: personal			
Location: Loughborough Road, West Bridgford, at the opening to Asda and the petrol station.			
Contact:			
Enquiry No.: 6146034	Logged by: External to Confirm	on: 14/11/2019 13:42	Officer: personal
Service: Carriageway/Footway	Subject: Flooding	Classification: Report or Observation	Enquiry Ref: FS-CASE-156950484
Desc.: Street flooding - Flooding of street buses cause wave of water to toward the houses risk of flooding could this road be closed . Submitted by Advisor: personal			
Location: Along Long Loughborough Road West Bridgford outside p down to West Bridgford School			
Contact:			
Enquiry No.: 6146022	Logged by: External to Confirm	on: 14/11/2019 13:21	Officer: personal
Service: Carriageway/Footway	Subject: Flooding	Classification: Report or Observation	Enquiry Ref: FS-CASE-156946011
Desc.: Street flooding - Drains are pumping water up onto the road and it is now flooding.			
"Coming up like fountains"			
ASDA is flooded too.			
Water is getting up to 2 foot deep in place. Well above tyre level.. Submitted by Advisor: personal			
Location: Drains down the A60 outside ASDA and Carphone warehouse.			
Contact:			

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6145446 **Logged by:** External to Confirm **on:** 11/11/2019 12:51 **Officer:** personal
Service: Carriageway/Footway **Subject:** St Furn/Non Illum Sign Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-156386615
Desc.: Traffic sign damage - Streetlights were recently replaced with new LED bulbs on Loughborough Road and there was a 30 mph sign on one of the streetlights but it was not replaced. The road is now lacking a 30mph sign. . Submitted by Advisor: personal
Location: Streetlight on Loughborough Road, NG2 7EH **Contact:**

Enquiry No.: 6144498 **Logged by:** External to Confirm **on:** 06/11/2019 08:15 **Officer:** personal
Service: Carriageway/Footway **Subject:** Traffic Signal Fault **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-155279602
Desc.: Traffic light fault - Traffic lights not working. . Online report Customer title pers
Location: Northwold Avenue/Loughborough Rd traffic lights not working. Dangerous with children walking to school. **Contact:**

Enquiry No.: 6144236 **Logged by:** External to Confirm **on:** 04/11/2019 13:21 **Officer:** personal
Service: Trees/Verges **Subject:** Overhanging Vegetation/Trees **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-154826189
Desc.: Overhanging trees -
 I wish to report that on the A60 Loughborough Road West Bridgford Nottingham NG2 there is an overgrown tree that is protruding into the bus lane opposite County Hall. The offending tree is in the grounds of Rushworth Court and when buses use their correct lane the strong branches clutter the vehicle.

In the last few months I complained that the same trees were obstructing the pavement and this was resolved by Notts County Council.

. Submitted by Advisor: personal

Location: see email:

Contact:

I wish to report that on the A60 Loughborough Road West Bridgford Nottingham NG2 there is an overgrown tree that is protruding into the bus lane opposite County Hall.
 The offending tree is in the grounds of Rushworth Court and when buses use their correct lane the strong branches clutter the vehicle.

In the last few months I complained that the same trees were obstructing the pavement and this was resolved by Notts County Council.

Enquiry No.: 6143868 **Logged by:** External to Confirm **on:** 31/10/2019 11:00 **Officer:** personal
Service: Carriageway/Footway **Subject:** Request new line marking/studs **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-153960396
Desc.: New road marking - Customer calling to report that the road markings on the A60 loughborough road just near to the Nottingham Knight Pub. are really faint and require remarking if possible. Please could this be looked into. . Submitted by Advisor: personal
Location: A60 Loughborough Road **Contact:**

Enquiry No.: 6143850 **Logged by:** External to Confirm **on:** 31/10/2019 09:39 **Officer:** personal
Service: Carriageway/Footway **Subject:** Line Marking/Stud Renewal **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-153934414
Desc.: Road marking renewal - The white lines and arrows on the road are so faded that vehicles are constantly in the wrong lane and therefore swapping lanes on the roundabout making the road even more dangerous. . Online report Customer title is per
Location: Outside Nottingham Knight Pub - facing Ruddington **Contact:**

Enquiry No.: 6143814 **Logged by:** External to Confirm **on:** 30/10/2019 16:12 **Officer:** personal
Service: Lighting **Subject:** Street Light Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-153801780
Desc.: Other requests - Lamp post obscures residents drive, finds it difficult to park as has disabled children. Would like the post moving so that easier access can be gained to his property. . Submitted by Advisor: personal - Customer title is
Location: Lamp Post #65 **Contact:**

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6142350	Logged by: External to Confirm	on: 16/10/2019 08:48	Officer: personal
Service: Carriageway/Footway	Subject: Spillage/Debris on Carriageway	Classification: Report or Observation	Enquiry Ref: FS-CASE-150672057
Desc.: Spillage/debris in road - Petrol / Diesel spill, half a meter wide, from ruddington towards bunny . Submitted by Advisor: personal			
Location: a60 Ruddington to bunny (maybe even past)	Contact:		
Enquiry No.: 6141395	Logged by: External to Confirm	on: 07/10/2019 15:30	Officer: personal
Service: Carriageway/Footway	Subject: Line Marking/Stud Renewal	Classification: Report or Observation	Enquiry Ref: FS-CASE-148710849
Desc.: Road marking renewal - Sorry as above . Online report Customer person.			
Location: Junction with Loughborough road and Wilford lane traffic lights. I am fairly sure Loughborough road is NOT a dual carriageway yet vehicles approach this junction two across. Causing confusion for those ahead where a vehicle will charge in front to fill a gap. For vehicles coming from Trent bridge there is a much narrower road with vehicles spread two across a single track road. This really ought to be clearly marked where the twin lane for the junction starts and ends. Dose the Highway Code not say keep to the left unless over taking. Please advise accordingly.			
Enquiry No.: 6140664	Logged by: External to Confirm	on: 01/10/2019 09:18	Officer: Risk & Insurance
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS147236851
Desc.: Insurance claim - related to Confirm defect reference: 6140663 Date/Time: 17/07/2019 20:00:00 Direction of travel: North-bound Account of what happened: The customer was riding a bike on 17/07/2019 and hit a raised manhole cover at this location which resulted in two punctured tyres and broke two of their ribs after falling off the bike, to the right-hand side, impacting the road surface.			
The customer would like to claim damages for the bike tyres in particular as they were completely destroyed, splitting with the impact. The helmet the customer was wearing was also destroyed by the impact and they would like to claim for this also.			
Location: On Loughborough Road, just outside the turn-off towards the West Bridgford School, Contact: West Bridgford			
Enquiry No.: 6140663	Logged by: External to Confirm	on: 01/10/2019 09:17	Officer: personal
Service: Carriageway/Footway	Subject: Manholes/Gullies	Classification: Report or Observation	Enquiry Ref: FS-CASE-147236851
Desc.: Insurance claim form requested - Missing and damaged manhole/drain covers - The customer was riding a bike on 17/07/2019 and hit a raised manhole cover at this location which resulted in two punctured tyres and the breakage of two of their ribs after falling off the bike, to the right-hand side impacting the road surface.			
The issue has been reported and repaired as a result of this, but the customer would now like to claim damages.. Submitted by Advisor: personal			
Location: On Loughborough Road, just outside the turn-off towards the West Bridgford School, Contact: West Bridgford			
Enquiry No.: 6138741	Logged by: External to Confirm	on: 11/09/2019 22:18	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-143145123
Desc.: Road Damage - Large open crack in the tarmac surface in the middle of this busy junction. Uneven when passed over by drivers turning left into ASDA and right turners out of ASDA. Potholes have appeared along the fissure line. . Online report Customer title p pe			
Location: Loughborough Road/ASDA junction, West Bridgford (the damage and crack centres around the middle of the carriageway, around the junction turning spaces. Contact:			
Enquiry No.: 6137714	Logged by: External to Confirm	on: 30/08/2019 13:00	Officer: Winter Maintenance South
Service: Winter Maintenance	Subject: Gritting Request	Classification: Service Request	Enquiry Ref: FS-CASE-140528611
Desc.: Road gritting request - Cross Boundary Agreement 2019/2020 from Leicestershire County Council. Wanting the attached to be passed to the Winter Maintenance Department. . Submitted by Advisor: personal pers			
Location: No location, this is not a new gritting request. Contact:			

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6136390	Logged by: External to Confirm	on: 14/08/2019 13:04	Officer: personal
Service: Carriageway/Footway	Subject: Carriageway Obstruction	Classification: Report or Observation	Enquiry Ref: FS-CASE-137369025
Desc.: Road obstructions - Outside the shop there is currently a water leak coming the water mains outside the property. A gentleman is currently on site from Watersafe who work with Severn Trent Water who has located the leak but will not go further down into the mains until he is allowed to close this service road to complete the works. Can someone contact persona back to advise or to speak to the gentleman from Watersafe. . Submitted by Advisor: personal			
Location: Outside The Salon per Loughborough Road in West Bridgford.		Contact:	
Enquiry No.: 6135530	Logged by: External to Confirm	on: 05/08/2019 16:54	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Blocked Drain	Classification: Report or Observation	Enquiry Ref: FS-CASE-135524417
Desc.: Blocked drains - The caller is wanting to report that the gullies on Loughborough Road are blocked and water is flowing down the road at a high rate. The caller is aware that it was an exceptional downpour but he would like the drains to be cleared as this would stop any further running water.. Submitted by Advisor: personal			
Location: Outside the caller's property but also near the fire station on Loughborough Road.		Contact:	
Enquiry No.: 6135469	Logged by: External to Confirm	on: 05/08/2019 13:42	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Blocked Drain	Classification: Report or Observation	Enquiry Ref: FS-CASE-135467056
Desc.: Blocked drains - drain is blocked. Rainwater is going over drain and down road. It is the drains on the side of the road next to West Bridgford School.. Online reportCustomer title is pe			
Location: drain in road opposite persrs Loughborough road west Bridgford is blocked. Rainwater is going over drain and down road. It is the drains on the side of the road next to West Bridgford School.		Contact:	
Enquiry No.: 6135451	Logged by: External to Confirm	on: 05/08/2019 12:49	Officer: p
Service: Carriageway/Footway	Subject: Stray Animal	Classification: Report or Observation	Enquiry Ref: FS-CASE-135452666
Desc.: Live/dead animal in road - Police have called advising there is a dead badger in the middle of the carriageway at the above location.			
Police incident 314 05/08/2019 . Submitted by Advisor: personal			
Location: Loughborough Road, about 60-70 yards after the oub heading away from Ruddington		Contact:	
Enquiry No.: 6135446	Logged by: External to Confirm	on: 05/08/2019 12:14	Officer: personal
Service: Carriageway/Footway	Subject: Manholes/Gullies	Classification: Report or Observation	Enquiry Ref: FS-CASE-135442065
Desc.: Missing and damaged manhole/drain covers - Customer has advised there is a missing manhole cover on the road outside the above address. Lots of cyclists use this road and he feels this could be extremely dangerous. . Submitted by Advisor: personal			
Location: Outside of Funky Pots, Loughborough Road, West Bridgford, Notts		Contact:	
Enquiry No.: 6135442	Logged by: External to Confirm	on: 05/08/2019 11:48	Officer: personal
Service: Other	Subject: Other Enquiry (Highways)	Classification: Report or Observation	Enquiry Ref: FS-CASE-135432732
Desc.: Road work issue - 1. (Loughborough Road) Dead badger on footpath alongside Loughborough Road.			
2. (Landmere Lane) Plastic boxes dumped at side of road (A52 - wooded side). . Online report Customer title is pe			
Location: 1. Loughborough Road, West Bridgford - south of traffic light junction with Europa Way, southbound - Wilford Hill side.		Contact:	
2. Landmere Lane, West Bridgford - near to junction with A52/Nottingham Knight PH raer car park entrance.			
NB Not Road Work issues - I know.			

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6135408	Logged by: External to Confirm	on: 05/08/2019 10:36	Officer: personal
Service: Carriageway/Footway	Subject: Manholes/Gullies	Classification: Report or Observation	Enquiry Ref: FS-CASE-135417593
Desc.: Missing and damaged manhole/drain covers - Customer has called from the pharmacy to make us aware that half of the manhole cover that is in the road has fell into the road, it is still attached, but customer is concerned that the rest of the manhole cover could collapse. . Submitted by Advisor: personal			
Location: Outside the Manor Pharmacy on Loughborough Road	Contact:		
Enquiry No.: 6135266	Logged by: External to Confirm	on: 02/08/2019 14:18	Officer: personal
Service: Trees/Verges	Subject: Grass Cutting	Classification: Report or Observation	Enquiry Ref: FS-CASE-134936000
Desc.: Overgrown grass and verges - The caller received an email from personal say that the grass verges that he had reported (6132493) would be cut imminently. This has not happened, if possible he would like Laura to contact him about this. Also he would like to report that the grass verges on loughborough Road heading toward the fire station have also been missed. . Submitted by Advisor: personal			
Location: The grass verge on Loughborough Road, West Bridford opposite Boundary Road.	Contact:		
Enquiry No.: 6135242	Logged by: External to Confirm	on: 02/08/2019 11:42	Officer: personal
Service: Trees/Verges	Subject: Overhanging Vegetation/Trees	Classification: Report or Observation	Enquiry Ref: FS-CASE-134893067
Desc.: Overgrown hedges and vegetation - Trees, bushes, hedges and vegetation are covering more than half of the path along this busy stretch of road. The path way is covered in debris and needs clearing as well as the vegetation chopping back*****UPDATE - LETTER 1 SENT TO NUMBERS personal AS IT WAS UNCLEAR WHAT HOUSE NUMBERS HAVE OVERGROWN VEG SO WROTE TO ALL.....CSC PLEASE READ THE FOLLOWING TO ENABLE YOU TO ANSWER ANY QUERIES: THE HEDGES DO BELONG TO THE PROPERTIES (SEE LAND REGISTRY PLAN) AND ARE THE PROPERTY OWNERS RESPONSIBILITY TO MAINTAIN. IF THEY DO NOT HAVE A HEDGE OR TREE THAT IS OVERGROWN OVER THE FOOTWAY THEN APOLOGISE FOR THEM RECIVING A LETTER AND MAKE A NOTE OF THE NAME, PHONE NUMBER AND HOUSE NUMBER. THANKS YOU, person			
Location: Btwn Stanhome Dr and Europa Way, north side, opposite the cemetery	Contact:		
Enquiry No.: 6133561	Logged by: External to Confirm	on: 16/07/2019 12:30	Officer: personal
Service: Road Works	Subject: Road Works Report	Classification: Report or Observation	Enquiry Ref: FS-CASE-131279781
Desc.: Road work issue - Customer has advised there has been road works directly outside her property from 11pm til 3am, with pneumatic drills being used keeping her family awake. She has had no information given that this will be taking place. Her family have lost lots of sleep and she would like to complain regarding this. . Submitted by Advisor: personal			
Location: Road Works on Loughborough road and Pavilion Road West Bridgford.	Contact:		
Enquiry No.: 6133442	Logged by: External to Confirm	on: 15/07/2019 12:33	Officer: personal
Service: Traffic Management	Subject: Pedestrian Crossing Request	Classification: Service Request	Enquiry Ref: FS-CASE-131040366
Desc.: Pedestrian crossing - Please could a pedestrian crossing be installed in this area? Loughborough road can be very busy and it can be dangerous to cross especially near the bus stop. It can take a very long time before the road is clear and safe to cross. A pedestrian crossing would be very helpful for those trying to reach the nurseries on either side of Loughborough Road safely with small children, and for local residents. . Online report - personal			
Location: Loughborough Road, West Bridgford - between Elm Tree Avenue and Chestnut Grove	Contact:		
Enquiry No.: 6132602	Logged by: External to Confirm	on: 05/07/2019 12:24	Officer: personal
Service: Other	Subject: Other Request (Highways)	Classification: Service Request	Enquiry Ref: FS-CASE-129016856
Desc.: Other requests - Gentlemen is calling from fire service in regards to an incident at the above location there reference - Incident number was pers They attended the scene and had noticed that after a couple of days this part of the road was resurfaced. Customer is wanting to speak to someone who dealt with this diesel spillage incident as he wants to discuss the policies and procedures for this and whether the fire service could of done anything differently for this incident. Customer would like to be contacted back about this. . Submitted by Advisor: personal - Customer title pers.			
Location: A52 Westbridgford, Landmere Lane Near Wheatcroft Island	Contact:		

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6132548 **Logged by:** External to Confirm **on:** 04/07/2019 23:12 **Officer:** personal
Service: Cycling & Covid-19 temp **Subject:** New cycling facilities **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-128903522
Desc.: New cycle facility - Hi,

My name is personal I'm interested in opening the conversation about providing your bike routes with public bike repair stations so patrons can repair their bike for free and on the go. If this interests you, please don't hesitate to respond.

Best,

personal

. Online report - Customer title pers

Location: Nottinghamshire

Contact:

Enquiry No.: 6131256 **Logged by:** External to Confirm **on:** 20/06/2019 19:51 **Officer:** personal
Service: Carriageway/Footway **Subject:** Footway Obstruction **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-125903018
Desc.: Pavement obstructions - Hello, I reported this a few months ago but nothing seems to have happened. The hedge and verge is hampering safe passage on this path and would be unsafe for a wheelchair user or someone with a pushchair. . Online report Customer person
Location: Foot path on the corner of Old Road and Loughborough Road. **Contact:**

Enquiry No.: 6130914 **Logged by:** External to Confirm **on:** 18/06/2019 12:03 **Officer:** personal
Service: Carriageway/Footway **Subject:** Footway Obstruction **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-125316269
Desc.: Pavement obstructions - Hello, I have a complaint to make about a sign that has been attached to the pedestrian crossing at the Asda junction on Loughborough Road, West Bridgford. Please see photo attached. It is highly inappropriate for a public pathway. . Submitted by Advisor: personal
Location: Asda Junction on Loughborough Road. West Bridgford. **Contact:**

Enquiry No.: 6130722 **Logged by:** External to Confirm **on:** 17/06/2019 10:47 **Officer:** personal
Service: Carriageway/Footway **Subject:** Manholes/Gullies **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-125108808
Desc.: Missing and damaged manhole/drain covers - There is a manhole cover in this location which is no longer attached to the surface via screws or another fastening mechanism. This has caused the cover to become detached and while employees of the Trent Bridge Inn have put the cover back, it does not appear that it would hold a significant weight and could cause a person to fall ~2m into the sewer.

There is also a significant cricket match coming up on Thursday which will lead to increased foot traffic and a high risk of someone falling in if it's not secured. Submitted by Advisor: perso

personal

Location: Outside Trent Bridge Inn on the left-hand side when starting out from the front of the property, towards the cricket ground ticket booths. Right aside to the building on the pavement area. **Contact:**

Enquiry No.: 6130261 **Logged by:** External to Confirm **on:** 12/06/2019 17:03 **Officer:** personal
Service: Trees/Verges **Subject:** Overhanging Vegetation/Trees **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-124312779
Desc.: Overhanging trees - The trees are overgrown and overhanging the pavement making it near impossible to stay on the pavement. Need to duck to get through. . Submitted by Advisor: personal
Location: On the A60 in the garden of Rushworth court. **Contact:**

Enquiry No.: 6129276 **Logged by:** External to Confirm **on:** 04/06/2019 15:36 **Officer:** personal
Service: Other **Subject:** Other Enquiry (Highways) **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-122704913
Desc.: Other enquiry - Could you advise me on the Nottinghamshire County Council's policy regarding parking on grass verges please. . Submitted by Advisor: personal
Location: Nottinghamshire **Contact:**

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6128155	Logged by: External to Confirm	on: 20/05/2019 12:03	Officer: personal
Service: Other	Subject: Other Request (Highways)	Classification: Service Request	Enquiry Ref: FS-CASE-119811142
Desc.: Other requests - Customer is a location scout and are doing adverts for cricket days. And would like to know on international cricket days which of the roads on the highways are closed to public road users. This is because they would like to make it safe for there filmers and would like to know information on highways on these days. Customer needs to know this information relatively quickly personal . Happy to receive this in writing by email as soon as possible. . Submitted by Advisor: personal - Customer personal			
Location: Trent Bridge Cricket Ground, Radcliffe Road		Contact:	
Enquiry No.: 6127418	Logged by: External to Confirm	on: 10/05/2019 14:06	Officer: Dropped Kerb Requests
Service: Carriageway/Footway	Subject: Dropped Kerb (Vehicle) Request	Classification: Service Request	Enquiry Ref: FS-CASE-118198454
Desc.: Dropped kerb - Cars & other vehicles - REMOVE 1.0m HIGH FRONT WALL AND DROP KERB TO ALLOW OFF STREET PARKING . Online report - Quote NOT required 10 whole kerb(s) and 0 tapered kerb(s) to be dropped Position of kerb - TO THE LEFTHAND SIDE OF STREET LIGHT FACING PROPERTY Streetlight - Yes Customer title is pe			
Location:		Contact:	
Enquiry No.: 6126840	Logged by: External to Confirm	on: 02/05/2019 14:09	Officer: Dropped Kerb Requests
Service: Carriageway/Footway	Subject: Dropped Kerb (Vehicle) Request	Classification: Service Request	Enquiry Ref: FS-CASE-116870644
Desc.: Dropped kerb - Cars & other vehicles - Extension to current dropped kerb. . Submitted by Advisor: personal - Quote NOT required 4 whole kerb(s) and 1 tapered kerb(s) to be dropped Position of kerb - To the right hand side of the current dropped kerb, if you are looking on at the property. Streetlight - personal			
Location: Outside pe Loughborough Road, West Bridgford, to the right of the existing kerb (looking on at the house).		Contact:	
Enquiry No.: 6126664	Logged by: External to Confirm	on: 30/04/2019 14:06	Officer: personal
Service: Carriageway/Footway	Subject: St Furn/Non Illum Sign Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-116437629
Desc.: Street furniture request - personal is calling as she is having trouble with cars turning onto Pavilion Road while she is crossing the street due to the cars not being able to see pedestrians crossing around the corner. This has caused personal and her dog to be almost hit multiple times. personal was wondering if something could be put in place to prevent this. For example mirrors to shows if anyone is crossing on the road as you turn the corner or a sign to advise drivers that pedestrians may be crossing. Can someone please look into this for per			
Location: On the junction of Loughborough Road and Pavilion Road in West Bridgford.		Contact:	
Enquiry No.: 6126241	Logged by: External to Confirm	on: 25/04/2019 14:21	Officer: Dropped Kerb Requests
Service: Carriageway/Footway	Subject: Dropped Kerb (Vehicle) Request	Classification: Service Request	Enquiry Ref: FS-CASE-115644955
Desc.: Dropped kerb - Cars & other vehicles - Customer would like a quote for a dropped kerb . Submitted by Advisor: personal - Quote required 5 whole kerb(s) and 1 tapered kerb(s) to be dropped Position of kerb - Directly outside of number 40 Streetlight - No Customer title pers			
Location: Outside number p Loughborough road		Contact:	
Enquiry No.: 6126240	Logged by: External to Confirm	on: 25/04/2019 14:15	Officer: personal
Service: Carriageway/Footway	Subject: St Furn/Non Illum Sign Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-115643514
Desc.: Street furniture request - The customer owns the above property and there is a directional sign outside and this has been hit so many times that it is absolutely battered. It is now pitching at a 30 degree angle and needs re-positioning as well. As well as being hit by lorries buses the sign also restricts access to his drive so he is wondering, when replaced could this be moved by about 3 ft towards number pe . Submitted by Advisor: personal			
Location: Outside p Loughborough Road West bridgford		Contact:	
Enquiry No.: 6126147	Logged by: External to Confirm	on: 24/04/2019 14:51	Officer: personal
Service: Carriageway/Footway	Subject: St Furn/Non Illum Sign Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-115443763
Desc.: Traffic sign damage - The no entry sign is so faded no one can see it and traffic is coming in the wrong end of the one way slip road causing problems with traffic going the correct way. . Online report Customer title is per .			
Location: The end of the slip road to the shops on Loughborough Road opposite The Wolds pub.		Contact: 'No Entry'/sign	

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6125610	Logged by: External to Confirm	on: 15/04/2019 10:51	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-114033618
Desc.: Road Pothole - Pothole identified by person during tour of Lutterell Ward . Submitted by Advisor: person .			
Location: Centre of the carriageway on Loughborough Road - between the VW dealer and junction with Chaworth Road (around house no per			
West Bridgford			
Enquiry No.: 6125460	Logged by: External to Confirm	on: 12/04/2019 10:21	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-113710387
Desc.: Road Pothole - Reported via FixMyStreet; Pothole and subsidence on LHS of carriage travelling way towards the island . Submitted by Advisor: person			
Location: A60 Loughborough Road, Ruddington near Europa Way heading towards the island Contact:			
Enquiry No.: 6125443	Logged by: External to Confirm	on: 12/04/2019 08:51	Officer: p
Service: Trees/Verges	Subject: Grass Cutting	Classification: Report or Observation	Enquiry Ref: FS-CASE-113690182
Desc.: Overgrown grass and verges - The grass verge needs cutting - other verges in the area have been trimmed but it seems the grass verges in the area haven't been cut, not been along since last September. He also mentioned that the grass when cut never seems to get taken away and requests that it be done. he would like it cutting down so it is nice and tidy . Submitted by Advisor: pers			
Location: Loughborough Road, WEST BRIDGFORD, West Bridgford, NG2 7JE Contact:			
Enquiry No.: 6123129	Logged by: External to Confirm	on: 18/03/2019 20:36	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-109980510
Desc.: Road Damage - Badly damaged road surface and pot holes . Online report Customer person .			
Location: Corner of Wilford Lane and A60 Contact:			
Enquiry No.: 6122972	Logged by: External to Confirm	on: 17/03/2019 18:03	Officer: Dropped Kerb Requests
Service: Carriageway/Footway	Subject: Dropped Kerb (Vehicle) Request	Classification: Service Request	Enquiry Ref: FS-CASE-109798851
Desc.: Dropped kerb - Cars & other vehicles - Drop kerb request . Online report - Quote required 5 whole kerb(s) and 2 tapered kerb(s) to be dropped Position of kerb - Outside pe Streetlight - No Customer title is per			
Location: In front of home. Contact:			
Enquiry No.: 6121123	Logged by: External to Confirm	on: 26/02/2019 16:06	Officer: person (SL Rush-Brox S)
Service: Carriageway/Footway	Subject: St Furn/Non Illum Sign Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-107218149
Desc.: Street furniture damage - Just past the fire station near customers address there has been some works carried out. The customer has informed that the 30 mph permanent sign has now been turned to face the houses and they have forgot to turn it back and they have tried but are unable to. The vehicles can no longer see this sign could this be turned and corrected please. . Submitted by Advisor: pe person			
Location: Loughborough Road, WEST BRIDGFORD, Nottinghamshire, NG2 7EH Contact:			
Enquiry No.: 6120537	Logged by: External to Confirm	on: 19/02/2019 16:00	Officer: person
Service: Trees/Verges	Subject: Tree Enquiry	Classification: Report or Observation	Enquiry Ref: FS-CASE-106363287
Desc.: Other enquiry - Customer would like to know what happens to the wood from the trees that are felled by the council. If this wood is tipped then the caller would like to request that it is given away to residents as a scheme to heat houses or to make it available for residents to purchase. . Submitted by Advisor: person			
Location: Not location related, all county Contact:			

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6120513 **Logged by:** External to Confirm **on:** 19/02/2019 13:36 **Officer:** Coordination South
Service: Road Works **Subject:** Road Works Report **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-106331821
Desc.: Road work issue - Customer has called regarding workmen in the area that block the pavement near the above junction forcing people to walk in the busy main road. Customer has a pushchair with his child and does not feel anyone should be put at risk by being forced to walk in the main road, just because the workmen are parking fully on the pavement rather than half on half off. .
Submitted by Advisor: **personal** .
Location: Loughborough Road, just down from Boundary Road **Contact:**

Enquiry No.: 6119947 **Logged by:** External to Confirm **on:** 13/02/2019 15:57 **Officer:** **personal**
Service: Other **Subject:** Other Request (Highways) **Classification:** Service Request **Enquiry Ref:** FS-CASE-105695056
Desc.: Other requests - We have had a request from the president of the National Federation for the Blind of the UK regarding the use of 'shared space' policy (e.g. pedestrians sharing streets with motorists and cyclists) on Nottinghamshire streets. - will email the full letter over and quote the FS number in email. . Submitted by Advisor: **personal** - Customer title is
Location: n/a **Contact:**

Enquiry No.: 6119946 **Logged by:** External to Confirm **on:** 13/02/2019 15:54 **Officer:** Coordination South
Service: Road Works **Subject:** Road Works Report **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-105694161
Desc.: Road work issue - There have been works on Loughborough Road through the last 2 nights and they have been keeping the caller's daughter awake as her property backs on to Loughborough Road. This has been going on for 2 nights now and she has been unable to sleep, she may have to move in with her mother (the caller) until the works finish.
Can the customer be called today if possible as the daughter is becoming frustrated with the noise. . Submitted by Advisor: **personal** .
Location: Loughborough Road/Lancelyn Gardens **Contact:**

Enquiry No.: 6119513 **Logged by:** External to Confirm **on:** 10/02/2019 10:36 **Officer:** **person**
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-105270881
Desc.: Road Pothole - Deep pothole . Online report Customer **person**
Location: Outside **D** Loughborough Road (Skin clinic) **Contact:**

Plot Number: 2,001.00 **Feature Id - Location:** Bridgford Road To Asda **Feature Type:** Street Section
Job Number: 2704498 **Defect Number:** 3600938

Enquiry No.: 6118431 **Logged by:** External to Confirm **on:** 29/01/2019 13:36 **Officer:** **personal**
Service: Carriageway/Footway **Subject:** Dropped Kerb (Vehicle) Request **Classification:** Service Request **Enquiry Ref:** FS-CASE-104003791
Desc.: Dropped kerb - Cars & other vehicles - Lower the curb at the front of the property so cars can be parked on the front of the property . Online report - Quote NOT required 5 whole kerb(s) and 2 tapered kerb(s) to be dropped Position of kerb - At the front of the property Streetlight - No Customer title **pers**
Location: **D** Loughborough Road, West Bridgford, Nottingham, NG2 7JX **Contact:**

Enquiry No.: 6118356 **Logged by:** External to Confirm **on:** 28/01/2019 16:55 **Officer:** **personal**
Service: Carriageway/Footway **Subject:** Traffic Signal Fault **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-103906721
Desc.: Traffic light fault - The traffic lights on this junction are completely non-functional not displaying any lights at all making it very dangerous. . Submitted by Advisor: **personal** Customer title is **pc**.
Location: At the junction of Loughborough Road. Chaworth Road and Northwold Avenue, West Bridgford **Contact:**

Enquiry No.: 6117877 **Logged by:** External to Confirm **on:** 23/01/2019 19:06 **Officer:** **personal**
Service: Carriageway/Footway **Subject:** Footway Obstruction **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-103446918
Desc.: Pavement obstructions - Overgrown verge and hedge has reduced the size of the original footpath. Tight for two people to walk it alongside, and a bit unnerving as on such a busy stretch of road. . Online report Customer title **pers**
Location: Short section of path on the RHS of Loughborough Road going towards Nottm just after Old Road. **Contact:**

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6117657	Logged by: External to Confirm	on: 21/01/2019 16:30	Officer: [REDACTED] (SL Rush-Brox S)
Service: Carriageway/Footway	Subject: St Furn/Non Illum Sign Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-103189127
Desc.: Traffic sign damage - National Water Sports Sign twisted and Colwick Races sign needs attention also. Been like it for 12 months. Surely someone has spotted it in this period. . Online report Customer title is			
Location: In centre refuge A60 between County Hall and TBI	Contact:		
Enquiry No.: 6117648	Logged by: External to Confirm	on: 21/01/2019 16:06	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-103185674
Desc.: Road Pothole - Road sunk in around gully. Breaking up around frame. . Online report Customer title is			
Location: Loughborough Rd before bus shelter	Contact:		
Enquiry No.: 6117646	Logged by: External to Confirm	on: 21/01/2019 16:03	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-103184405
Desc.: Road Pothole - Pot hole in channel. Also sign up against railings been left since you surfaced Loughborough Rd. Can you collect? . Online report Customer title is			
Location: Loughborough Rd right next to gully. Take a cyclist over quite easily.	Contact:		
Plot Number: 2,001.00	Feature Id - Location: Bridgford Road To Asda	Feature Type: Street Section	
Job Number: 2702620	Defect Number: 3599099		
Enquiry No.: 6117447	Logged by: External to Confirm	on: 18/01/2019 16:21	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-102981116
Desc.: Road Pothole - Deep pothole . Online report Customer title is [REDACTED]			
Location: At the lights on the A60 at junction with B679 in the right hand lane.	Contact:		
Plot Number: 2,001.00	Feature Id - Location: Bridgford Road To Asda	Feature Type: Street Section	
Job Number: 2702445	Defect Number: 3598924		
Enquiry No.: 6116810	Logged by: External to Confirm	on: 11/01/2019 14:48	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Footway Request	Classification: Service Request	Enquiry Ref: FS-CASE-102237837
Desc.: New pavement request - Customer is wanting to request something to be done with the pavements here as they are very narrow. Customer has said that there is only a small island to cross the road and this is very dangerous also so she would like to request a better crossing. She was very alarmed when she was stood in the centre point when cars were driving so fast either side with her in the middle with no where to go hoping cars would not crash or knock her over. A better crossing here would be suitable as it is a very busy road with cars driving very fast. Customer has also seen elderly people with frame stood waiting here to cross the road. Also there should be better speed signs here that people will take note of. Could something be done in this area to make it safer for pedestrians. Please correspond with the customer about this as she has reported this before at least 2 months ago online with no response at all. . Submitted by Advisor: [REDACTED]			
Location: Loughborough Road Near to the junction with Stanhome Drive	Contact:		
Enquiry No.: 6116795	Logged by: External to Confirm	on: 11/01/2019 13:36	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Line Marking/Stud Renewal	Classification: Report or Observation	Enquiry Ref: FS-CASE-102225201
Desc.: Road marking renewal - There is a yellow lined do not block box marked out on the road in front of the station on Loughborough Road. This has become degraded and should be done again to make it visible. Can somebody get in touch to let us know when this can be done please. I am the estates office for Notts Fire & Rescue based at Arnold HQ . Online report Customer title is [REDACTED]			
Location: On the main A60 in front of the fire station fire appliance exit route	Contact:		
Enquiry No.: 6116085	Logged by: External to Confirm	on: 04/01/2019 16:19	Officer: [REDACTED]
Service: Carriageway/Footway	Subject: Traffic Signal Fault	Classification: Report or Observation	Enquiry Ref: FS-CASE-101437195
Desc.: Traffic light fault - The conical button under traffic light k3 which crosses from the centre of the road to melton road has an intermittent fault. This has caused the caller's wife to have difficulties crossing. . Submitted by Advisor: [REDACTED]			
Location: Loughborough road, west bridgford, nction with melton road	Contact:		

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6116084	Logged by: External to Confirm	on: 04/01/2019 16:15	Officer: personal
Service: Carriageway/Footway	Subject: Traffic Signal Fault	Classification: Report or Observation	Enquiry Ref: FS-CASE-101436244
Desc.: Traffic light fault - Wife is visually impaired and a guide dog user. Relies on the conical button to know when to cross. The conical is not working on post number personal			
Location: On Loughborough road, west bridgeford, near the entrance to asda on the asda side of the orad Contact:			
Enquiry No.: 6115907	Logged by: External to Confirm	on: 03/01/2019 10:33	Officer: personal (LEFT Viaem)
Service: Trees/Verges	Subject: Overhanging Vegetation/Trees	Classification: Report or Observation	Enquiry Ref: FS-CASE-101228123
Desc.: Overhanging trees - there are 5 trees that are extremely large and the customer feels they need felling or pruning back. . Submitted by Advisor: personal			
Location: Edmonton Court NG2 7EQ Contact:			
Enquiry No.: 6114233	Logged by: External to Confirm	on: 10/12/2018 15:30	Officer: personal
Service: Traffic Management	Subject: Parking General	Classification: Report or Observation	Enquiry Ref: FS-CASE-99191017
Desc.: Parking issues - Parked cars reducing the two lane road down to a single lane road . Email received from customer Hi, I don't know which department this needs to be sent to, so please can you forward on. Everyday I drive to work from West Bridgford to Ruddington. My route is along Loughborough road, and across the Nottingham Knight roundabout. There is always congestion just before the roundabout- this is made worse by the parked cars on the side of the road. These cars mean that the traffic has to be single lane, when it should be double lane. I feel that such a busy road warrants double yellow lines. All of the residences seem to have off road parking so I think this seems reasonable. . Submitted by Advisor: personal is			
Location: A60 Loughborough Road heading towards Ruddington from West Bridgford towards Nottingham Knight Roundabout Contact:			
Enquiry No.: 6113739	Logged by: External to Confirm	on: 04/12/2018 16:36	Officer: Dropped Kerb Requests
Service: Carriageway/Footway	Subject: Dropped Kerb (Vehicle) Request	Classification: Service Request	Enquiry Ref: FS-CASE-98439060
Desc.: Dropped kerb - Cars & other vehicles - Currently outside the property the only access is the back that leads onto Victoria road apart from a gate at the front that is not used. person calling to request a drop kerb be placed outside the front extending a drop kerb in place for next door. This will allow them to open up the front of the house as an access as it was originally used. . Submitted by Advisor: personal - Quote NOT required 3 whole kerb(s) and 1 tapered kerb(s) to be dropped Position of kerb - On Loughborough Road facing the front of the property. Streetlight - No Customer title pers			
Location: Outside de Loughborough Road in West Bridgford. Contact:			
Enquiry No.: 6112390	Logged by: External to Confirm	on: 19/11/2018 14:33	Officer: personal
Service: Carriageway/Footway	Subject: Footway Obstruction	Classification: Report or Observation	Enquiry Ref: FS-CASE-96326831
Desc.: Pavement obstructions - Double Mattress obstructing road/ pavement. Has been moved off te road to the pavement. . Submitted by Advisor: personal			
Location: Outside council house on Loughborough road Contact:			
Enquiry No.: 6112306	Logged by: External to Confirm	on: 18/11/2018 10:27	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Footway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-96171446
Desc.: Pavement Damage - Hole in manhole cover. . Online report Customer title pers			
Location: p Loughborough West Bridgford, outside nursery Contact:			
Enquiry No.: 6112291	Logged by: External to Confirm	on: 17/11/2018 15:42	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-96108677
Desc.: Road Pothole - pothole repaired but receding again. this is in front of the bus shelter . Online report Customer title is per			
Location: opposite County Hall Contact:			

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6111544

Logged by: External to Confirm

on: 09/11/2018 10:12

Officer: personal (LEFT Viaem)

Service: Trees/Verges

Subject: Overhanging Vegetation/Trees

Classification: Report or Observation

Enquiry Ref: FS-CASE-95010309

Desc.: Overhanging trees - Email from customer:

Good morning

The property at [p] Loughborough Road, West Bridgford, has two large evergreen trees growing in the front garden, these trees have been allowed to grow over the pavement area resulting in all pedestrians having to walk near to the edge of the pavement, bringing them in close proximity to the flowing traffic, in addition to this, pedestrians walking in opposite direction cannot pass at this place without either stepping into the road, or having the low branches scratching one's face or endanger one's sight. It would be appreciated if the relevant council department could look at this issue as a matter of priority.

Thank you

Regards

personal

Submitted by Advisor: personal personal

Location: Outside [p] Loughborough Road in West Bridgford.

Contact:

Enquiry No.: 6111088

Logged by: External to Confirm

on: 05/11/2018 14:09

Officer: personal

Service: Traffic Management

Subject: Traffic Issues

Classification: Report or Observation

Enquiry Ref: FS-CASE-94447864

Desc.: Traffic issues - Email from customer

I am writing as a pedestrian concerning Loughborough Road at the top of the road from Boundary Lane and past the Crematorium. The pavements on both sides of the road are VERY narrow. There are bus stops along the road on both sides. Many of the people who use the buses on this route are elderly and disabled. Navigating these pavements to get to the bus stops or crematorium have become a dangerous endeavour.

I myself am partially sighted. The older people tend to have walking aids. The speed of the cars and the width of the pavements together make walking and standing at the bus stops frightening and dangerous. Apart from the speed limit signs, that many cars fail to adhere to, there are no other speed control measures. Unless you are disabled it is hard to experience the feeling of reduced accessibility.

I hope you will give this matter your attention. This importance of this becomes even more pressing in the Winter with snow and ice and ungritted pavements. . Submitted by Advisor: pe

Location: Loughborough Road, West Bridgford from its junction of Boundary Road past the Crematorium.

Contact:

Enquiry No.: 6110320

Logged by: External to Confirm

on: 26/10/2018 13:48

Officer: personal

Service: Traffic Management

Subject: Parking General

Classification: Report or Observation

Enquiry Ref: FS-CASE-93299187

Desc.: Parking issues - On Loughborough Road, West Bridgford and a car transporter was parked at 8.30am unloading in the middle of peak traffic going into town. There is a no loading and unloading between the hours of 7.30 and 9.30. Double yellow lines. They have this done before.

personal

Location: Loughborough road, west bridgford outside the VW dealership called Vertu

Contact:

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6110194 **Logged by:** External to Confirm **on:** 25/10/2018 12:18 **Officer:** personal
Service: Carriageway/Footway **Subject:** Spillage/Debris on Carriageway **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-93150252
Desc.: Spillage/debris in road - There is now an Excess of gravel / tarmac chippings that have appeared on the Toucan crossing refuge: probably as a result of the recent-re-surfacing (messy / thoughtless workmen?). This loose gravel / fine chippings is now a slip / fall hazard to all users.

Can someone take a look . Submitted by Advisor: Shane Sims Customer title per .

Location: A60 on junction of Millicent Road**Contact:**

Enquiry No.: 6106695 **Logged by:** External to Confirm **on:** 19/09/2018 12:03 **Officer:** South Highways Management
Service: Carriageway/Footway **Subject:** Carriageway Obstruction **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-88745032
Desc.: Road obstructions - A tree and a lamppost are down and blocking the road. . Online report Customer title is
Location: On Loughborough Road, West Bridgford between the fire station and the West Bridgford School **Contact:**

Enquiry No.: 6105684 **Logged by:** External to Confirm **on:** 06/09/2018 11:45 **Officer:** personal
Service: Road Works **Subject:** Utility Works **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-87249095
Desc.: Other enquiry - Hi,
A customer enquiry has been completed using the online contact us form.
Please see the details below:
Date: 05/09/2018
Reference number: FS-Case-87112149

personal

What district do you live in?: Rushcliffe
Your address:

Full Address

pe Loughborough Road, WEST BRIDGFORD, West Bridgford, NG2 7JH

Your message : I was directed to this complaints procedure personal of your Performance and Reputation Team. He was very helpful when I was uncertain as to who would be the best people to contact.

Here is the issue I am hoping that you can help with.

BT OpenReach plan to install two large cabinets immediately in front of my property, where there was previously only a small GPO box. Here are the reasons I object to the change:

1/ The cabinets proposed will stretch all along my front wall, although there is an alternative site less than 8 metres away at which one or both cabinets could be sited.

2/ The cabinets will be much larger and taller than the existing GPO box and will restrict my vision of oncoming traffic. Cars now park fully on the pavement outside my house and that of my neighbours. As a result, the only way to see oncoming vehicles whilst pulling out onto the road is via the remaining line of sight between the parked cars and the existing GPO box. The change in size of the proposed cabinets will make pulling out onto the busy Loughborough Rd a more hazardous operation for both myself and my neighbour than it is at present.

3/ I was planning to make a small increase to the size of the entrance to my forecourt. The increased size of the cabinets will now m . Submitted by Advisor: personal

Location: Outside no. p**Contact:**

pe Loughborough Road, WEST BRIDGFORD, West Bridgford, NG2 7JH

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6104965 **Logged by:** External to Confirm **on:** 28/08/2018 10:33 **Officer:** personal
Service: Road Works **Subject:** Information Request **Classification:** Service Request **Enquiry Ref:** FS-CASE-86151296
Desc.: Roadworks and Events - information request - Customer runs a mobile coffee shop and he would like someone to contact him to see where the best place to have this mobile coffee shop along the route. Customer can travel anywhere in Nottinghamshire with it . Submitted by Advisor: personal
Location: Anywhere along the Tour of Britain route within Nottinghamshire **Contact:**

Enquiry No.: 6104129 **Logged by:** External to Confirm **on:** 16/08/2018 09:36 **Officer:** personal (LEFT Viaem)
Service: Trees/Verges **Subject:** Overhanging Vegetation/Trees **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-85004513
Desc.: Overgrown hedges and vegetation - The hedges are very overgrown, have to walk onto the road. Pushchairs and wheelchairs would have to go onto the edge of the road to get by. Normal pedestrians have to do the same and it is a very dangerous road. If have any children with her, she has to have them walk behind her which is also very dangerous . Submitted by Advisor: personal
Location: Opposite Wilford Hill Crematorium, between the entrance and junction of person Drive **Contact:**

Enquiry No.: 6103999 **Logged by:** External to Confirm **on:** 15/08/2018 10:24 **Officer:** Transport Facilities
Service: Carriageway/Footway **Subject:** Bus Shelter/Stop Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-84890205
Desc.: Bus Stop Electronic Display damage - RU0071 no real time information working . Submitted by personal is
Location: On Loughborough Road just outside the exit for asda heading towards the city **Contact:**

Enquiry No.: 6101406 **Logged by:** External to Confirm **on:** 16/07/2018 15:27 **Officer:** personal (LEFT Viaem)
Service: Trees/Verges **Subject:** Overhanging Vegetation/Trees **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-81736893
Desc.: Overgrown hedges and vegetation - A few years ago the council delivered letters to residents with responsibility for trimming the hedges in front of their houses at the location described above to remind them of their responsibilities. This lead to some improvement in the situation.
Now it is impossible for a pedestrian to walk this pavement without brushing against vegetation or, especially in the rush hour when cars approach the K/N roundabout two-abreast, to have to take evasive action to avoid wing mirrors.
Could I suggest that it is time to remind residents of their responsibilities.
Thank you
. Online report Customer title is pe.
Location: East side of Loughborough Road from Nottingham Knight PH to traffic lights with Europa Way **Contact:**

Enquiry No.: 6100858 **Logged by:** External to Confirm **on:** 09/07/2018 16:36 **Officer:** person
Service: Road Works **Subject:** Road Works Report **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-81056260
Desc.: Road work issue - I have lived here three months and outside my window (Loughborough Road) there is a sign easel, not being used and on the footpath. On the Point between Loughborough Rd. and Melton Mowbray Road is a diversion sign, of no use whatever.
On the pavement outside Flat pe is another sign, face down.
Please advise your action. Many thanks. . Submitted by Advisor: personal
Location: Flat pe 1Century Court, Wilford Lane, WEST BRIDGFORD, West Bridgford, per **Contact:**

Plot Number: 2,001.00
Job Number: 2687698

Feature Id - Location: Bridgford Road To Asda
Defect Number: 3584476

Feature Type: Street Section

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6100441	Logged by: External to Confirm	on: 04/07/2018 14:44	Officer: personal
Service: Carriageway/Footway	Subject: Dropped Kerb (Ped) Request	Classification: Service Request	Enquiry Ref: FS-CASE-80568459
Desc.: Dropped kerb - Pedestrian - 1) within the hedge forming the boundary of "West Bank" onto Loughborough Road, create a gap of approx 1m width to create access from West Bank onto the Loughborough Road pavement.			
2) install a wooden gate in the gap leading to Loughborough Road pavement, but within the West Bank plot (opening inwards into West Bank)			
3) if necessary, create a step down from the gate opening onto the pavement level, but within the West Bank plot . Online report - Customer title per .			
Location: within the frontage of "West Bank" onto Loughborough Road (NG11 6LU) Contact:			
. Although the address is Loughborough Road, there is no direct pedestrian access from the property onto the pavement.			
Enquiry No.: 6100346	Logged by: External to Confirm	on: 03/07/2018 14:18	Officer: personal
Service: Road Works	Subject: Road Works Report	Classification: Report or Observation	Enquiry Ref: FS-CASE-80444255
Desc.: Road work issue - Unusual sticker on BT cabinet...needs investigation. I am the Operations manager for Openreach in this area and have not been approached about this. Is this a sticker put on by the council, if so we need to discuss our 24/7 access to this cabinet. We are treating the sticker as a hoax or maybe some complaint raised that has not reached me yet but we will continue to go in this cabinet. I am checking with you if this is your sticker and we can then discuss the issue. . Online report Customer title pers			
Location: BT Green cabinet per outside p Loughborough rd West Bridgford Contact:			
Enquiry No.: 6098167	Logged by: External to Confirm	on: 11/06/2018 15:30	Officer: South Highways Management
Service: Trees/Verges	Subject: Grass Cutting	Classification: Report or Observation	Enquiry Ref: FS-CASE-78446307
Desc.: Overgrown grass and verges - Customer is the grounds supervisor for the cemetery and has requested that the grass verge that runs long Loughborough Road be cut back, this runs as you turn left out of the cemetery, towards Nottingham Knight island, and it is on your left hand side, running along the cemetery railings. . Submitted by Advisor: personal			
Location: Loughborough Road Contact:			
Enquiry No.: 6098155	Logged by: External to Confirm	on: 11/06/2018 14:57	Officer: Dropped Kerb Requests
Service: Carriageway/Footway	Subject: Dropped Kerb (Vehicle) Request	Classification: Service Request	Enquiry Ref: FS-CASE-78437845
Desc.: Dropped kerb - Cars & other vehicles - Our property has a pedestrian entrance at the from, we would like to create a driveway and have vehicular access to Loughborough Road . Online report - Quote required 5 kerb(s) to be dropped Position of kerb - Facing the property the dropped kerb is required to the right handside Customer title is pe			
Location: pe Loughborough Road Contact:			
Enquiry No.: 6097594	Logged by: External to Confirm	on: 06/06/2018 11:27	Officer: p (LEFT Viaem)
Service: Trees/Verges	Subject: Overhanging Vegetation/Trees	Classification: Report or Observation	Enquiry Ref: FS-CASE-77860266
Desc.: Hedges obstructing footpath on Loughborough Road making it difficult for pedestrians.			
Location: The left side footpath on Loughborough Road from Landmere Lane to Nottingham Knight (Left side as you go towards Nottingham Knight) Contact:			
Enquiry No.: 6096911	Logged by: External to Confirm	on: 31/05/2018 13:03	Officer: personal
Service: Trees/Verges	Subject: Grass Cutting	Classification: Report or Observation	Enquiry Ref: FS-CASE-77156889
Desc.: Overgrown grass and verges - Customer has advised that the grass verges here have no been maintained in along while- the grads is currently at Hip height and needs tending to. . Submitted by Advisor: personal			
Location: On Loughborough road- across from Boundry Road Park- West bridgeford. Contact:			
Enquiry No.: 6096258	Logged by: External to Confirm	on: 25/05/2018 10:36	Officer: personal
Service: Traffic Management	Subject: Parking General	Classification: Report or Observation	Enquiry Ref: FS-CASE-76609685
Desc.: Parking of car transporters on this road is dangerous. Can the rush hour loading restriction be made 24hrs to force them to unload within their site ?			
Location: A60 Loughborough Road, West bridgeford, outside the Voltswagon garage on the road. Contact:			

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6095446

Logged by: External to Confirm

on: 17/05/2018 13:48

Officer: personal

Service: Trees/Verges

Subject: Tree Enquiry

Classification: Report or Observation

Enquiry Ref: FS-CASE-75896767

Desc.: Other tree issues - Hi there

Would someone be able to assist me in answering the following comment on Twitter regarding trees/hedges cutting:

personal

Hi thanks for the reply to my tweet, earlier today, having read the link you sent regarding trees/ hedges, and neighbours trees hedges, - what if there council trees on council land? Can we still chop them our selfs,- cos they block any sunlight we would get early evening, obviously as I've said there not a danger to the highway or roads, and I'm sure you have enough 'important ' trees hedges verges to do without bothering about 4 trees that block sunlight out someone's garden.

This was the previous response he refers to back in August 2017:

Nottinghamshire County Council @NottsCC

Hi per NCC would only act if the tree had become a danger to road users or pedestrians. If it is a neighbour's tree growing over into your property you have the right to remove overgrowing branches yourself, but only back to the common boundary personal

Thanks,

per

personal

Location: General Query

Contact:

Enquiry No.: 6095436

Logged by: External to Confirm

on: 17/05/2018 13:09

Officer: personal

Service: Traffic Management

Subject: Parking General

Classification: Report or Observation

Enquiry Ref: FS-CASE-75888835

Desc.: Parking issues - This same car keeps parking over drive way of the customers home

the driver of the car is a 6th form pupil of West Bridgford School

there is ample room for the driver to park on opp side of the road but keeps repeatedly parking on the pathway and over my drive.

Please can you come out and inspect and try and give both the customer and driver a solution

Customer has spoken kindly to the driver but she keeps parking in same place.
the car in question is personal

Times 08.30 - 3.30 . Submitted by Advisor personal

Location: A60 Loughborough road in West Bridgford just before school entrance outside pe Contact:

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6094194	Logged by: External to Confirm	on: 04/05/2018 15:42	Officer: personal
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-74748328
Desc.: Road Pothole - Customer says that there is a very large pothole at said location, roughly 4 foot round (circumfrance) and at least 4 inches deep. It us dangerous for drivers, and especially for cyclists and needs attending to asap. . Submitted by Advisor: personal			
Location: Loughborough road, 10 years near a bollard before the turning onto the Wilford Cemetary		Contact:	
Enquiry No.: 6094192	Logged by: External to Confirm	on: 04/05/2018 15:32	Officer: personal
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-74747616
Desc.: Road Pothole - Customer says that there is a large and deep (at least a few inches deep). There is a manhole cover nearby that has been repaired, and the road has dropped significantly and getting worse and worse and sinking . Submitted by Advisor: personal			
Location: A60 loughhborough road, outside 'woodlands' house and going towards the Nottingham Knight roundabout		Contact:	
Enquiry No.: 6093542	Logged by: External to Confirm	on: 30/04/2018 12:27	Officer: personal
Service: Carriageway/Footway	Subject: Footway Obstruction	Classification: Report or Observation	Enquiry Ref: FS-CASE-74228049
Desc.: Pavement obstructions - There is a large flat bed transit van which parks at this location on the pavement, causing an obstruction for drivers trying to look out onto this busy road to join the A60 safely. The vehicle is parked in a way that almost completely blocks the vision for drivers exiting Carlyle Road to turn right towards Nottingham. The vehicle is there more often than not but there is no specific times for when it is definitely there. The person who owns the vehicle has a driveway which he is obviously not using. If any further details are required please contact per on personal . Submitted by personal			
Location: On Loughborough Road, between Chantry Road and Carlyle Road.		Contact:	
Enquiry No.: 6092053	Logged by: External to Confirm	on: 16/04/2018 17:54	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Footway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-73055500
Desc.: Pavement Damage - The pavement along this stretch is looking increasingly grim, mainly from the stones that have been thrown up from the poor state of the roads. However, there's also what I would consider to be quite a build up of other materials (soils, leaves and assorted detritus) that has built up along this stretch for a quite some time now. It could really do with a load of the materials being taken away. So, though not technically a pavement disrepair, it's becoming increasingly difficult to walk on some parts of the pavement along whis stretch. Plus it looks crap and isn't a great site for those coming along this stretch. . Online report Customer person			
Location: Pavement on Loughborough Road from the junction of Melton road/Wilford Lane up to County Hall		Contact:	
Enquiry No.: 6089432	Logged by: External to Confirm	on: 04/04/2018 00:00	Officer: personal
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-71952306
Desc.: Road Pothole - There are several deep ones which are very inconvenient and given the fact that hundreds of cars travel along the same path makes the pothole worse day by day. . Online report			
Location: The junction before turning right into Boundary Road has several deep potholes in which are in that certain area.		Contact:	
Enquiry No.: 6088098	Logged by: External to Confirm	on: 26/03/2018 10:30	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-71251066
Desc.: Road Pothole - 2 potholes, both within 2 metres apart . Online report			
Location: cemetery side of the road, near bus stop		Contact:	
Enquiry No.: 6087847	Logged by: External to Confirm	on: 23/03/2018 11:42	Officer: personal
Service: Trees/Verges	Subject: Root Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-71102863
Desc.: Root damage - The eastern boundary of my property abuts the grass verge alongside the A60 Loughborough Road. On the grass verge, outside my boundary line, there are trees and shrubs that have grown to the extent that they may cause an obstruction to high sided vehicles on the A60, the roots are disturbing the footings of my fence posts, and there is a danger of falling branches at a place where cars park to deliver and collect the pupils of nearby schools . Submitted by Advisor: personal			
Location: A60 - where p Swithland Drive backs onto the A60.		Contact:	

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6087390	Logged by: External to Confirm	on: 20/03/2018 16:00	personal
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-70835078
Desc.: Road Pothole - Series of ridges/holes in carriageway by the kerb . Online report			
Location: Between lamp post and telephone box on nottingham bound side of the carriageway Contact:			
Enquiry No.: 6086819	Logged by: External to Confirm	on: 17/03/2018 13:18	personal
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-70586125
Desc.: Road Damage - Many potholes and poor road condition . Online report			
Location: Loughborough Road full stretch both ways between County Hall and Wilford Lane Contact:			
Enquiry No.: 6086523	Logged by: External to Confirm	on: 15/03/2018 20:51	personal (Rushcliffe)
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-70462630
Desc.: Road Pothole - Multiple potholes . Online report			
Location: The bus lane outside the old ford car garage on the A60. There are multiple potholes along this stretch of road Contact:			
Enquiry No.: 6086522	Logged by: External to Confirm	on: 15/03/2018 20:24	Officer: personal
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-70461143
Desc.: Road Damage - Road has collapsed near manhole cover. . Online report			
Location: Road has collapsed near manhole cover Contact:			
Enquiry No.: 6086280	Logged by: External to Confirm	on: 15/03/2018 08:57	Officer: personal (Rushcliffe)
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-70369680
Desc.: Road Pothole - pot holes . Online report			
Location: a number of potholes along this stretch of road on the outbound side Contact:			
Enquiry No.: 6085923	Logged by: External to Confirm	on: 13/03/2018 16:54	Officer: personal
Service: Traffic Management	Subject: Traffic Calming	Classification: Report or Observation	Enquiry Ref: FS-CASE-70233318
Desc.: Traffic calming requests - the traffic is travelling at night extremely fast on Loughborough Road and concerns about safety and also the noise is really loud causing sleepless nights. Would like something in place to control this please. . Submitted by Advisor: personal - - -			
Location: the road outside Loughborough Road Contact:			
Enquiry No.: 6085921	Logged by: External to Confirm	on: 13/03/2018 16:51	Officer: personal
Service: Carriageway/Footway	Subject: Manholes/Gullies	Classification: Report or Observation	Enquiry Ref: FS-CASE-70232816
Desc.: Blocked gullies - blocked gulley and when heavy rains the cars splash water onto the property. Submitted by Advisor: personal			
Location: outside Loughborough Road Contact:			
Enquiry No.: 6085920	Logged by: External to Confirm	on: 13/03/2018 16:48	Officer: personal
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS70231953
Desc.: Insurance claim - related to Confirm defect reference: 6081504 Date/Time: 13/03/2018 16:00:00 Direction of travel: On Melton road towards London Road Account of what happened: Hit pothole outside and Melton road approx 2/3 inches deep and 73 cm wide x 85cm long passengers side of car damaged			
Location: On left hand lane heading towards town near kerb Contact:			
Enquiry No.: 6085277	Logged by: External to Confirm	on: 11/03/2018 17:00	Officer: South Highways Management
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-70017485
Desc.: Road Damage - Lots on both sides of the road along the stretch of road parallel with /County Hall and it's car park . Online report			
Location: On the main road outside County Hall Contact:			

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6085075	Logged by: External to Confirm	on: 09/03/2018 10:36	Officer: personal
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-69901269
Desc.: Road Pothole - big pot hole . Online report			
Location: just past the traffic lights	Contact:		
Enquiry No.: 6084983	Logged by: External to Confirm	on: 08/03/2018 16:42	Officer: personal
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-69856593
Desc.: Road Damage - There is a stretch of road that is severely damaged and causes my car to jump around as driving over it . Online report			
Location: the A60 outside the Point buildings	Contact:		
Enquiry No.: 6084787	Logged by: External to Confirm	on: 07/03/2018 16:15	Officer: personal
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-69743606
Desc.: Road Damage - There's not much road left in this location to try and dodge around the substrate - the damage is big enough to bathe a baby hippo in! I find it hard to believe that no further action will taken presuming we're talking about the areas of destruction - the road surfacing is currently akin to bombed runway in a far flung impoverished country! . Online report			
Location: Outside The Point, north bound on the A60 in lane two just past the pedestrian crossing!	Contact:		
Enquiry No.: 6084685	Logged by: External to Confirm	on: 07/03/2018 10:12	Officer: personal (HW Inspector)
Service: Other	Subject: Other Request (Highways)	Classification: Service Request	Enquiry Ref: FS-CASE-69679673
Desc.: Other requests - Customer has called as they have received an email from you quoting FS69588118, they require their reference so that they can forward it onto the claims department. . Submitted by Advisor: personal			
Location: Location is not relevant.	Contact:		
Enquiry No.: 6084398	Logged by: External to Confirm	on: 05/03/2018 17:15	Officer: personal
Service: Carriageway/Footway	Subject: St Furn/Non Illum Sign Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-69527080
Desc.: Street furniture damage - Email from customer at CSC			
Hi,			
We had someone report some road furniture damage			
On Cambridge Court, Loughborough Rd, West Bridgford, Nottingham NG2 7NN			
That's all the information we were given unfortunately			
Could you send someone out to look at it?			
. Submitted by Advisor: personal			
Location: Cambridge Court, Loughborough Road, West Bridgford, NG2 7NN	Contact:		
Enquiry No.: 6083697	Logged by: External to Confirm	on: 28/02/2018 14:10	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-69134756
Desc.: Road Pothole - Huge series of potholes in the wheel tracks ie difficult to avoid hitting them without exiting the lane or mounting central reservation . . Online report			
Location: Loughborough Rd, heading North, Lane 2, approx opposite Cambridge Ct, Google Maps Grid ref 52.933198,-1.136703.	Contact:		
Enquiry No.: 6082927	Logged by: External to Confirm	on: 22/02/2018 12:24	Officer: personal
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-68689197
Desc.: Road Pothole - personal is reporting a pothole on Loughborough Rd, near the junction with Landmere Lane. . Submitted by Advisor: personal			
Location: Near the junction of Loughborough Rd and Landmere Lane	Contact:		

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6082926 **Logged by:** External to Confirm **on:** 22/02/2018 12:24 **Officer:** personal
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-68689485
Desc.: Road Pothole - personal has reported several potholes in and around West Bridgford, the only information given is:
Victoria Road - at junction with Loughborough Road . Submitted by Advisor: personal
Location: Victoria Road - at junction with Loughborough Road **Contact:**

Enquiry No.: 6082921 **Logged by:** External to Confirm **on:** 22/02/2018 12:18 **Officer:** personal
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-68688052
Desc.: Road Pothole - personal is reporting a pothole on Loughborough Rd, directly outside of the VW Dealership . Submitted by Advisor: personal
Location: Outside of VW Dealership on Loughborough Road **Contact:**

Enquiry No.: 6082918 **Logged by:** External to Confirm **on:** 22/02/2018 12:12 **Officer:** personal
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-68686864
Desc.: Road Pothole - personal is reporting two potholes, one outside of number p and the other outside p p Loughborough Rd. . Submitted by Advisor: personal
Location: Outside of p and p Loughborough Rd **Contact:**

Enquiry No.: 6082917 **Logged by:** External to Confirm **on:** 22/02/2018 12:06 **Officer:** personal
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-68686520
Desc.: Road Pothole - personal is reporting a pothole outside of number personal Rd . Submitted by Advisor: personal
Location: Outside of p Loughborough Rd **Contact:**

Enquiry No.: 6082914 **Logged by:** External to Confirm **on:** 22/02/2018 12:03 **Officer:** personal
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-68684407
Desc.: Road Pothole - personal is reporting a pothole on Loughborough Rd, outside of number p . Submitted by Advisor: personal
Location: Outside of p Loughborough Rd **Contact:**

Enquiry No.: 6082001 **Logged by:** External to Confirm **on:** 16/02/2018 11:51 **Officer:** personal
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-68232802
Desc.: Road Damage - Stretch of road between Wilford Lane and County Hall in very poor condition. Potholes and general poor condition of this stretch of road. . Online report
Location: Between Wilford Lane and County Hall **Contact:**

Enquiry No.: 6081898 **Logged by:** External to Confirm **on:** 15/02/2018 19:09 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-68187691
Desc.: Road Damage - Serious road damage that could potentially cause serious damage to road vehicles. Needs addressing urgently . Online report
Location: A60 inbound near to junction of Wilford Lane. **Contact:**

Enquiry No.: 6081833 **Logged by:** External to Confirm **on:** 15/02/2018 15:24 **Officer:** personal
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-68169647
Desc.: Road Pothole - Multiple potholes. Impossible to avoid without swerving into left hand lane. . Online report
Location: Loughborough Rd, West Bridgford. Near Welbeck Rd. Approx. 52°55'58.5" N 1°08'12.5" W **Contact:**

Enquiry No.: 6081514 **Logged by:** External to Confirm **on:** 14/02/2018 09:09 **Officer:** person
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-68023550
Desc.: Road Pothole - Pothole has become significantly worse, dangerous to two wheeled vehicles. suggest an emergency repair . Online report
Location: Loughborough Road near to its junction with Sandringham Avenue **Contact:**

Plot Number: 2,001.00

Feature Id - Location: Bridgford Road To Asda

Feature Type: Street Section

Job Number: 2670941

Defect Number: 3567985

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6081504	Logged by: External to Confirm	on: 13/02/2018 21:09	Officer: personal
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-68007568
Desc.: Road Pothole - Very deep pothole a four long. Damaged my alloy wheel on it this evening . Online report			
Location: On left hand lane heading towards town near kerb		Contact:	
Enquiry No.: 6081377	Logged by: External to Confirm	on: 13/02/2018 10:39	Officer: personal
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS67941882
Desc.: Insurance claim - related to Confirm defect reference: 6081376 Date/Time: 13/02/2018 09:30:00 Direction of travel: From Loughborough Road towards Trent Bridge barrier Account of what happened: Customer was travelling along the road - he had right of way - the barrier has sharp bolts on it which has caused the near side tyres to be cut.			
Location: From Loughborough Road towards Trent Bridge		Contact:	
Enquiry No.: 6081376	Logged by: External to Confirm	on: 13/02/2018 10:37	Officer: personal
Service: Bridges/Structures	Subject: Bridges/Structures Damage	Classification: Report or Observation	Enquiry Ref: FS-CASE-67941882
Desc.: Insurance claim form requested - Bridges/structure damage - There are 2 sharp bolts on the barrier at Trent Bridge by the kerbside - these have cut through the tyres on the nearside. . Submitted by Advisor: personal			
Location: From Loughborough Road towards Trent Bridge		Contact:	
Enquiry No.: 6081342	Logged by: External to Confirm	on: 13/02/2018 08:33	Officer: person
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-67926621
Desc.: Road Pothole - Lots of very deep potholes either side of Loughborough Road from Wilford Lane/Loughborough Road/Melton Road junction up to traffic lights outside of Council House (heading towards Trent Bridge) . Online report			
Location: Lots of very deep and long potholes either side of Loughborough Road from Wilford Lane/Loughborough Road/Melton Road junction up to traffic lights outside of Council House (heading towards Trent Bridge)		Contact:	
Plot Number: 2,001.00	Feature Id - Location: Bridgford Road To Asda	Feature Type: Street Section	
Job Number: 2670723	Defect Number: 3567767		
Enquiry No.: 6080745	Logged by: External to Confirm	on: 08/02/2018 10:54	Officer: personal
Service: Other	Subject: Other Enquiry (Highways)	Classification: Report or Observation	Enquiry Ref: FS-CASE-67616297
Desc.: Other enquiry - Dear Sirs I have updated my Garmin Sat Nav this week but it appears you have not informed them that the 30mph speed limits have been extended on these two roads into the 40mph area. So the Sat Nav is misleading. Can you please give Garmin an update, they say they get their information from the Local Authority. Many thanks personal . Submitted by Advisor: personal - - -			
Location: 30mph Speed limit road signs on A60 Loughborough Rd & A606 Melton Rd		Contact:	
Enquiry No.: 6080646	Logged by: External to Confirm	on: 07/02/2018 15:15	Officer: personal
Service: Carriageway/Footway	Subject: Traffic Signal Fault	Classification: Report or Observation	Enquiry Ref: FS-CASE-67559545
Desc.: Traffic light fault - The traffic lights heading towards Nottingham are stuck on Green causing potential problems with traffic at this busy junction. Rang through by the police. The incident number for this is 470 of 07/02/2018 . Submitted by Advisor: personal			
Location: At the junction of Loughborough Road and Wilford Lane on the A60		Contact:	
Enquiry No.: 6079572	Logged by: External to Confirm	on: 31/01/2018 16:27	Officer: personal
Service: Other	Subject: Other Enquiry (Highways)	Classification: Report or Observation	Enquiry Ref: FS-CASE-67037721
Desc.: Other enquiry - **This is a generic question and is not for a specific location**			
Customer would like to know what the laws are on blocking someones drive, either totally or partially. Her reason for wanting to know this is because she is in the process of getting a dropped kerb installed and there is a problem on her road with neighbours and visitors parking over peoples driveways. . Submitted by Advisor: personal - - -			
Location: See map coordinates and description details		Contact:	

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 6079002 **Logged by:** External to Confirm **on:** 29/01/2018 15:45 **Officer:** personal
Service: Carriageway/Footway **Subject:** Dropped Kerb (Vehicle) Request **Classification:** Service Request **Enquiry Ref:** FS-CASE-66855141
Desc.: Other enquiry - Customer is calling from the company Merlin Utilities, they are often getting request from NCC residents who are wanting the company to do their dropped kerbs. When this happens the company has to send a copy of their insurance and accreditation for working on the highways to you, and this is something they have to keep doing.

They were wondering if they can be on an approved trader list for you instead of having to go through lots of paper work each time. She has informed she can send the new insurance policy every year and when the accreditation is renew send you confirmation for that.

Can you please confirm if this is something you can do, thank you. . Submitted by Advisor: personal - -

Location: See map coordinates and description details **Contact:**

Enquiry No.: 6078906 **Logged by:** External to Confirm **on:** 29/01/2018 11:42 **Officer:** personal
Service: Carriageway/Footway **Subject:** Blocked Drain **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-66818436
Desc.: Blocked drains - Reported by Twitter user personal
personal drains in bus lane opposite County Hall blocked. (By the bus stops) not sure people waiting for the bus wish to get drenched from the large puddles.. Online report
Location: Bus lane opposite County Hall. **Contact:**

Enquiry No.: 6078620 **Logged by:** External to Confirm **on:** 26/01/2018 15:21 **Officer:** personal
Service: Carriageway/Footway **Subject:** Footway Obstruction **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-66722160
Desc.: Pavement obstructions - Customer has called regarding an electronic flashing sign, advertising road works taking place between the 11th and 14th of January. Customer believes this has been left behind by mistake. . Submitted by Advisor: personal
Location: Junction of Loughborough road and Boundary Road. **Contact:**

Enquiry No.: 6077009 **Logged by:** External to Confirm **on:** 18/01/2018 11:17 **Officer:** personal
Service: Other **Subject:** Other Enquiry (Highways) **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-66102877
Desc.: Other enquiry - TEST ENQUIRY - THIS SUBMISSION CAN BE DELETED FROM HAMS - THANK YOU, personal . Online report - - -
Location: See map coordinates and description details **Contact:**

Enquiry No.: 6076157 **Logged by:** External to Confirm **on:** 12/01/2018 12:54 **Officer:** personal
Service: Carriageway/Footway **Subject:** Manholes/Gullies **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-65667246
Desc.: Missing manhole/drain covers - **Email Enquiry**

Good morning. The attached is a picture of a broken manhole cover on Loughborough Road near the lights at Wilford Lane (outside new retirement flats). I thought you would know who to contact to get it fixed. Cheers . Submitted by Advisor: personal

Location: See map coordinates and description details **Contact:**

Enquiry No.: 6075116 **Logged by:** External to Confirm **on:** 05/01/2018 10:24 **Officer:** South Highways Management
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-65098960
Desc.: Road Damage - Road surface from Wilford Lane to County Hall (perhaps a little further) is in very poor state with many potholes and general deterioration . Online report
Location: See map coordinates and description details **Contact:**

Enquiry No.: 3207706 **Logged by:** person **on:** 13/03/2019 11:08 **Officer:** personal
Service: Carriageway/Footway **Subject:** Manholes/Gullies **Classification:** Report or Observation
Desc.: Gully fully silted .
Location: Directly opposite L / C 68 adjacent with house number pe **Contact:**

Plot Number: 2,001.00

Feature Id - Location: Bridgford Road To Asda

Feature Type: Street Section

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 96697 Logged by: **personal** on: 25/03/2021 16:50 Officer: **personal**
 Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation
 Desc.: Road has cracked and damage next to ironwork
 Location: Junction Welbeck Road Contact:

Plot Number: 2,001.00 Feature Id - Location: Bridgford Road To Asda Feature Type: Street Section
 Job Number: 2771842 Defect Number: 3668032

Enquiry No.: 96689 Logged by: **personal** on: 25/03/2021 15:41 Officer: **personal**
 Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation
 Desc.: **personal**
 Date: 23/03/2021 21:14 (GMT+00:00)
personal
personal k>
 Subject: RE: FW: West Bridgford Roads

Dear **pers**

Thank you for your reply.

I have now noticed a number of potholes and road damage on Melton Road and Musters Road have been circled with yellow paint which no doubt indicates temporary repairs are due.

However there is no yellow paint around the section of road damage outside the block of flats I reside in at **personal**. I note you say the resurfacing work on Loughborough Road is scheduled for August. However this section is surely not going to be left in this state for over another 4 months ? The depth of damage is certainly more than 4cm's so a temporary repair is required now.

Can you please confirm this will happen

Location: Photo in Links - Outside Barons Court and "West One Letting Agent". Opposite the junction with Balmoral Avenue (carriageway side that heads out of Nottingham) Contact:

Enquiry No.: 96537 Logged by: **personal** on: 23/03/2021 09:32 Officer: **personal**
 Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation
 Desc.: "The section of Melton Road at Loughborough Road / Wilford Lane junction has taken priority, as we are planning to include it in with the proposed works on Loughborough Road opposite County Hall in the coming financial year (2021/2022)."

Presumably you have some sort of order already in place for works to be carried out in April so where are these on your priority list ? Although the section near the bus stop near **p** Melton Road was patched up last month it has already started crumbling away again. As for the section at **p** Loughborough Road directly outside the block of flats I reside in no temporary repairs have taken place. As you can see from the latest attached photo it is in an atrocious condition. Also as previously stated every time a heavy lorry drives over this damaged section my property physically vibrates. A temporary repair is urgently required regardless of when the proper resurfacing work is due to take place. When I have walked across the road a bit further down so much tarmac has crumbled away that there are cables actually visible.

Regarding Musters Road and Millicent Road when you say "features on our candidate list" does that relate to a list for financial year 2021/2022 or a later year ? I don't know if you recall but I have been in contact with you previously particularly regarding Musters Road which I have the misfortune of driving over every day. At one point I submitted several photos showing the plethora of collapsing utility trenches. As I said in my original email considering the sheer volume of traffic that uses it every day with 2 major medical practices it's no wonder how rapidly it is deteriorating. Another road I didn't mention was Gordon Road from the junction of Burleigh Road right into the centre of West Bridgford. Are there any plans for this section next financial year or is it also just on the candidate list for a future year ?

Location: Various - West Bridgford Contact:

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 96508 Logged by: personal on: 22/03/2021 14:47 Officer: pers Poole-Richardson
 Service: Trees/Verges Subject: Grass Cutting Classification: Report or Observation
 Desc.: Customer unhappy with condition of verge and wants it cut.
 Location: O/S No p Contact:

Enquiry No.: 96507 Logged by: personal on: 22/03/2021 14:19 Officer: pers Poole-Richardson
 Service: Traffic Management Subject: Speed Limits/Issues Classification: Report or Observation
 Desc.: Customer is concerned about speeding traffic
 Location: No p Contact:

Enquiry No.: 96465 Logged by: personal on: 22/03/2021 09:07 Officer: personal
 Service: Traffic Management Subject: Parking General Classification: Report or Observation
 Desc.: From: personal
 Sent: Wednesday, March 17, 2021 9:57:18 AM
 To: personal
 Subject: car parking

Hello.

I am a resident of Compton Acres and I am concerned about the persistent car parking on Loughborough rd outside the houses on the site of the old filling station.

This road is used by a large amount of traffic including buses and lorries it is a very busy road ,these vehicles are either parked on the road and on the pavement which makes it awkward for disabled and mums with pushchairs etc, these residences have ample parking at the rear provided for them when built so there is no need for this indiscriminate parking .

Sooner or later there is going to be a accident and action should be taken before this happens.

Perhaps yellow lines could be applied here to prevent this.

personal

View, Loughborough Road

Contact:

Enquiry No.: 96385 Logged by: personal on: 17/03/2021 15:39 Officer: personal
 Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation
 Desc.: Cllr queries when this will be resurfaced.
 Location: From County Hall to Wilford Lane junction Contact:

Enquiry No.: 95814 Logged personal on: 01/03/2021 14:34 Officer: personal
 Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation
 Desc.: Pothole at the edge of the road
 Location: At the entrance to Cambridge Court Contact:

Plot Number: 2,001.00 Feature Id - Location: Bridgford Road To Asda Feature Type: Street Section

Enquiry No.: 95812 Logged personal on: 01/03/2021 14:32 Officer: personal
 Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation
 Desc.: A number of potholes
 Location: O/S Aries Motors Contact:

Plot Number: 2,001.00 Feature Id - Location: Bridgford Road To Asda Feature Type: Street Section
Job Number: 2767848 Defect Number: 3664044

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 94920 Logged by: personal on: 04/02/2021 12:15 Officer: personal
 Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation
 Desc.: Large pothole
 Location: Junction Wilford Lane, by "The Point" Building Contact:

Plot Number: 2,001.00 Feature Id - Location: Bridgford Road To Asda Feature Type: Street Section
 Job Number: 2764360 Defect Number: 3660560

Enquiry No.: 94699 Logged by: personal on: 29/01/2021 10:49 Officer: personal
 Service: Other Subject: Other Enquiry (Highways) Classification: Report or Observation
 Desc.: From: personal
 Sent: 29 January 2021 10:11
 To: personal
 Subject: BT pole on Loughborough Road

Hi Laura

Further to our discussion yesterday, I attach photos. The pole is a visual irritation from the garden of 5 Swithland Drive. There was nothing there prior to the installation of the pole on Loughborough Road.

Kind Regards

personal

Contact:

Enquiry No.: 94249 Logged by: personal on: 19/01/2021 08:38 Officer: personal
 Service: Highway Searches Subject: CON29 Classification: Report or Observation
 Desc.: con enquiry with bacs 18.1.2021
 Location: 5 Rushworth Court Loughborough Road, West Bridgford Nottingham NG2 7LH Contact:

Enquiry No.: 94195 Logged by: personal on: 18/01/2021 11:30 Officer: personal
 Service: Carriageway/Footway Subject: Footway Obstruction Classification: Report or Observation
 Desc.: Dear pers

Just to up date you, top soil as been laid on much of the subject verge.
 However would it be possible for LA contractors to push back the edges of the verge that are spreading over the footpath.

Regards

personal

Location: Outside the Cemetery Contact:

Enquiry No.: 93713 Logged by: personal on: 29/12/2020 09:03 Officer: personal
 Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation
 Desc.: surface damage
 Location: from the junction of Melton Rd/Loughborough rd/ Wilford lane to County Hall-
 obviously not the County hall side of the road. Contact:

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 92005

Logged by: personal

on: 29/10/2020 15:20

Officer: personal

Service: Highway Searches

Subject: CON29

Classification: Report or Observation

Desc.: con enquiry with bacs 29.10.2020

Location: D Loughborough Road, West Bridgford Nottingham NG2 7JJ

Contact:

Enquiry No.: 91168

Logged by: personal

on: 02/10/2020 13:38

Officer: personal

Service: Carriageway/Footway

Subject: Carriageway Damage

Classification: Report or Observation

Desc.: From: personal

Sent: 23 September 2020 17:29

To: personal

Subject: RE: From personal (Case Ref: RE0550)

Good Evening

Thank you for your response. However this is completely unacceptable. This means the users of this road have to wait at least 6 months for the surface to be replaced, most of that through the winter months.

I think now is the time to involve the local media and see whether it can be resolved quicker.

I will also getting legal advice to see if the council is failing in its duty of care to provide a safe roadway

Can you please find out why Cadent are not resurfacing this area as they caused the issue in the first place?

Regards

personal

Location: Junction Wilford Lane

Contact:

Effective: 01/01/2018 to 22/04/2021
Display Action Officer: Yes

Feature No.: 2001.00 to 2001.00
Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 90684 Logged by: personal on: 16/09/2020 09:40 Officer: personal
Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation
Desc.: Dear pers

Further to your email below, my constituent, personal has got back to me and confirms that Cadent now seem to have solved the drainage issue and resurfaced a small area of the carriageway.

However, he has said that the rest of the lane is still in a very broken up state and so I am writing to ask if the lane is due to be completely resurfaced in the near future

Thank you and I look forward to hearing from you in due course.

Best wishes

per

Member of Parliament for Rushcliffe
personal

personal

Location: Junction Wilford Lane Contact:

Enquiry No.: 90480 Logged by: personal on: 08/09/2020 16:12 Officer: personal
Service: Trees/Verges Subject: Overhanging Vegetation/Trees Classification: Report or Observation
Desc.: Hi pers

Could you look into this please and respond please.

Thanks per

From: personal
Sent: 07 September 2020 16:00
To: personal
Subject: Pavement along A60 Rempstone

Hi pers

The parish council has reported the condition of the overgrown pavement along the A60 between Rempstone and the county boundary near Hoton on a couple of occasions over the last couple of months. I know Highways will have been extremely busy with the Covid situation but nothing has been done about this. This section links up the public rights of way and is regularly used by walkers. It has become so bad that walkers are forced to walk on the main A60 carriageway which is extremely dangerous.

Would you mind following up with NCC to see if anything can be done about this please?

Thanks,
person

personal

Location: Overgrown pavement along the A60 between Rempstone and the county boundary near pers Contact:

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 90219

Logged by: personal

on: 27/08/2020 14:26

personal

Service: Carriageway/Footway

Subject: Blocked Drain

Classification: Report or Observation

Desc.: ST Classification: OFFICIAL PERSONAL

pers

Many thanks for your teams attendance here yesterday. I have met personal this morning to discuss further STW issues. If you would still please diary the gully clearances for the Northbound part of Loughborough Road, after the road works have finished, that would be great.

The Southbound gullies look spotless and the rainfall this morning, as heavy as it was, has not caused any further incident. I will continue to monitor the SWS with six monthly planned cleansing, and include Victoria Road also. I would recommend that the gullies in Victoria Road are also cleaned out when you can please.

Kind regards,

personal

Contact:

Enquiry No.: 89882

Logged by: personal

on: 17/08/2020 10:47

Officer: p

Service: Carriageway/Footway

Subject: Manholes/Gullies

Classification: Report or Observation

Desc.: From: personal

Sent: Friday, August 14, 2020 2:54:12 PM

To: personal

Subject: Loose Drain cover - Loughborough Road

Dear Councillo personal,

There is a loose drain cover located on the inbound A60 lane close to the entrance to Wilford and Southern Cemetery. Every time a wheel of a vehicle is driven over it the cover clatters and this as been happening for at least two months. Even worse at night when large delivery lorries are heading towards Asda every one of the six wheels hits the cover and subsequent noise wakes people up. It must be very disturbing for the NHS workers who reside on this stretch of the Loughborough Road.

I and at least one other neighbour as reported this problem and to say we are being given the run around would be an understatement.

I first contacted the Borough Council who referred me to County Hall. Then County Hall stated it was not their responsibility but that of Utilities namely Seven Trent. Seven Trent employees have visited the subject site and have stated that the cover is for a drain and not a sewer and is therefore a County Council responsibility.

If you wish to view the site of the problem and of course listen to the noise made when vehicle drive over the drain cover. I would certainly agree to meet with you.

In the meantime can you chase up the appropriate department and get them to deal with this frustrating problem.

Thanking You

personal

Location: Inbound A60 lane close to the entrance to Wilford and Southern Cemetery

Contact:

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 89137 Logged by: personal on: 17/07/2020 16:31 Officer: personal

Service: Other Subject: Other Enquiry (Highways) Classification: Report or Observation

Desc.: From: personal
[Redacted]

Dear per

I am writing again on behalf of my constituent, personal, and following your email below of 3rd March in relation to at the junction of Wilford Lane and Loughborough Road.

I would appreciate it if you would provide an update in relation to the work that was due to be carried out by Cadent. personal has also asked during the lockdown why the work was not carried out as it would have been an opportune time to do so, in his view.

Thank you and I look forward to hearing from you in due course.

Best wishes

per

[Redacted signature block]

Contact:

Enquiry No.: 88851 Logged by: personal on: 08/07/2020 11:21 Officer: personal

Service: Trees/Verges Subject: Overhanging Vegetation/Trees Classification: Report or Observation

Desc.: Do you know who would be responsible for the path known as 'Old Road' between Loughborough Road and the A52 that runs up the side of the cemetery? The path on the A52 side is overgrown.

Kind regards

per
son

Contact:

Enquiry No.: 88156 Logged by: personal on: 10/06/2020 12:16 Officer: Vehicle Access Licences

Service: Carriageway/Footway Subject: Dropped Kerb (Vehicle) Request Classification: Service Request

Desc.: Contractor app

Location: personal

Contact:

Enquiry No.: 87750 Logged by: personal on: 18/05/2020 13:52 Officer: personal

Service: Trees/Verges Subject: Grass Cutting Classification: Report or Observation

Desc.: See Links for customer's Tweets

Location: Verges from the Cemetery Northbound

Contact:

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 87732

Logged by: [redacted]

on: 18/05/2020 10:33

Officer: [redacted]

Service: Traffic Management

Subject: Speed Limits/Issues

Classification: Report or Observation

Desc.: per per

My address is [redacted] Loughborough Road, West Bridgford, Nottingham NG2 7JT.

I would like to ask you about something, if I may. I live on a very busy road and the speed limit is 30 however a lot of cars travel much faster and I have sent an email to Notts County Council (based on advice from the Highways Department) to ask how I can campaign to get a speed camera installed. I haven't heard anything from them apart from the automatic reply I had on 3 March (see attached) and wondered if this is something that you can look into?

Many years ago, I [redacted] to bring this matter to his attention and as a result a flashing speed message was installed further down the road, this has helped a little but a lot of cars still travel too fast and I am extremely concerned that there will be fatality one day.

I realise you'll be extremely busy at the moment but any assistance with this would be gratefully received.

With best wishes

[redacted]
per
son

Contact:

Enquiry No.: 87704

Logged by: [redacted]

on: 14/05/2020 14:56

Officer: [redacted] r

Service: Other

Subject: Other Enquiry (Highways)

Classification: Report or Observation

Desc.: [redacted]

Subject: Care workers Banners - Rushcliffe

Just to confirm that Rushcliffe has been done this morning (see attached photo's). If you have any concerns at all regarding the installation please do not hesitate to let me know.

Others areas to follow on completion.

Kind Regards

[redacted]
pers

Location: O/S County Hall

Contact:

Enquiry No.: 86914

Logged by: [redacted]

on: 19/03/2020 10:58

Officer: [redacted]

Service: Carriageway/Footway

Subject: Carriageway Damage

Classification: Report or Observation

Desc.: See attached

Location: Junction of Wilford Lane and A60 Loughborough Road

Contact:

Enquiry No.: 86644

Logged by: [redacted]

on: 09/03/2020 11:24

Officer: [redacted]

Service: Highway Searches

Subject: Adoption Extents

Classification: Report or Observation

Desc.: extent plan

Location: [redacted] Loughborough Road, West Bridgford, Nottingham NG2 7JS

Contact:

Enquiry No.: 86467

Logged by: [redacted]

on: 03/03/2020 11:32

Officer: [redacted]

Service: Carriageway/Footway

Subject: Flooding

Classification: Report or Observation

Desc.: See attached letter and photos regarding ponding at the bus stop and concerns re: pollution from the buses

Location: O/S No [redacted] and the bus stop

Contact:

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 85646 Logged by: personal on: 04/02/2020 12:36 Officer: personal
 Service: Highway Searches Subject: Adoption Extents Classification: Report or Observation
 Desc.: extent plan
 Location: West Bridgford Fire Station, Loughborough Road Contact:

Enquiry No.: 84876 Logged by: personal on: 08/01/2020 16:06 personal
 Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation
 Desc.: Councillor reports that this defect was repaired previously but has deteriorated. He says his car goes down it with a bump.
 Location: Heading towards the Nottingham Knight Island, near to the bus stop at Landmere Lane Contact:

Enquiry No.: 83835 Logged by: personal on: 14/11/2019 12:03 Officer: personal
 Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation
 Desc.: Several deep potholes at the kerb edge where cyclists cycle
 Location: From No 1 to the junction with Melton Road, especially outside Cambridge Court Contact:

Plot Number: 2,001.00 Feature Id - Location: Bridgford Road To Asda Feature Type: Street Section
 Job Number: 2728469 Defect Number: 3624745

Enquiry No.: 83815 Logged by: personal on: 14/11/2019 09:40 personal
 Service: Other Subject: Other Request (Highways) Classification: Service Request
 Desc.: PJ

Please see attached which is self-explanatory.

Secondly are you able to have a look at HAMS for me and tell me who owns/has responsibility for the small green area at the front of County Hall opposite the north-bound exit to Trent Bridge. I have spoken to a company that wants to sponsor and maintain the plot in question.

Kind Regards

perso

Location: County Hall land

Contact:

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 82448

Logged by: personal

on: 12/09/2019 15:22

Officer: personal r

Service: Other

Subject: Other Request (Highways)

Classification: Service Request

Desc.: Good Afternoon pers

Thank you for your response and subsequent action in regards to the speeding on Loughborough Road, however, for some reason you have ignored my main reason for contacting the Council - cyclist riding on the pavement. I have already been knocked over (luckily saw his intention so was able to avoid serious contact thus only received bruising) but I and my wife who walk from Northwold Avenue to the Point and return Monday to Friday are constantly having to avoid cyclist who use the pavement as a cycle track and therefore their sole right in addition at the junction of Loughborough Road and Wilford Lane, cyclist speed onto the pavement to avoid the traffic lights, paying no regard to the fact that there is a blind bend on the pavement. As we are now rapidly approaching dark nights and inclement weather I am in fear of being seriously injured by one of these thoughtless riders.

My question therefore is: Where am I, my wife and other pedestrians supposed to walk in safety? I expect your response to be 'carry a torch' but this will do nothing to deter these people. Perhaps we should therefore consider buying cycles ourselves and joining this idiots. I look forward to your response which hopefully will address my concerns.

Regards

personal

This e-mail (including any attachments) is private and confidential and may contain privileged material. If you have received this e-mail in error, please notify the sender and delete (including any attachments) immediately. You must not copy, distribute, disclose or use any of the information in it or any attachments.

Location: Loughborough Road

Contact:

Enquiry No.: 81790

Logged by: personal

on: 12/08/2019 09:21

Officer: personal

Service: Claims

Subject: Highway Insurance Claim

Classification: Report or Observation

Desc.: Incident 17/07/2019: Claimant was correctly proceeding when his bike has hit the metal upstand of the manhole cover causing his tyres to puncture and resulting in the claimant losing control of his bike and falling into the road.(enquiry raised on receipt of claim notification)

Location: opposite No. pe

Contact:

Enquiry No.: 81610

Logged by: personal

on: 02/08/2019 09:12

Officer: p

Service: Carriageway/Footway

Subject: Spillage/Debris on Carriageway

Classification: Report or Observation

Desc.: Lorry has spilt chicken guts and waste on the carriageway

Location: Just passed County Hall Nottingham bound towards Trent Bridge

Contact:

Enquiry No.: 81192

Logged by: personal

on: 12/07/2019 09:01

Officer: personal

Service: Road Works

Subject: Information Request

Classification: Service Request

Desc.: Road Closure info. re. football matches

Location: UNSURE - "W. B'FORD"

Contact:

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 80281	Logged by: personal	on: 31/05/2019 10:27	Officer: personal
Service: Carriageway/Footway	Subject: Traffic Signal Fault	Classification: Report or Observation	
Desc.: Pedestrian stage - crossing at location indicated on attached plan (southbound - ahead movement).			
At about 8.15am today I couldn't help but notice that the timing appears to have been altered to show a green man to pedestrians crossing when northbound vehicular traffic is making the left turn into Radcliffe Rd (when vehicles are making this turn, pedestrians are ordinarily shown a red man - owing to fears over people making an illegal ahead movement). I could understand this if the change is intended to give more green time with the crowds expected for the cricket tournament and there being limited room for standing on the refuge etc. However, the normal green man stage (when traffic exiting Radcliffe Rd runs) is now showing a red man - so people are standing for no good reason / the timing for pedestrians hasn't been extended. Perhaps I was just observing a point in time when the stages were in the process of changing, but I thought I'd query things just to be sure you are aware.			
Location: junction with Radcliffe Road	Contact:		
Enquiry No.: 79599	Logged by: personal	on: 29/04/2019 15:16	Officer: personal
Service: Cycling & Covid-19 temp	Subject: New cycling facilities	Classification: Report or Observation	
Desc.: Proposal to remove/redesign advanced cyclist stop line			
Location: Southbound approach to Wilford Ln jcn	Contact:		
Enquiry No.: 79396	Logged by: personal	on: 15/04/2019 14:28	Officer: personal
Service: Trees/Verges	Subject: Overhanging Vegetation/Trees	Classification: Report or Observation	
Desc.: Highways England offering to cut back private vegetation as part of their roundabout upgrade scheme.			
Location: Adjacent A52T Nottm Knight rdbt	Contact:		
Enquiry No.: 79380	Logged by: personal	on: 15/04/2019 09:40	Officer: personal
Service: Trees/Verges	Subject: Grass Cutting	Classification: Report or Observation	
Desc.: Wants West Bridgford West division grass cutting schedule not 11 day West Bridgford whole area schedule			
Location: grass cutting in the Compton Acres area	Contact:		
Enquiry No.: 77862	Logged by: personal	on: 11/02/2019 13:44	Officer: personal
Service: Trees/Verges	Subject: Overhanging Vegetation/Trees	Classification: Report or Observation	
Desc.: Overhanging vegetation - see photos linked			
Location: near A52T Nottm Knight island	Contact:		
Enquiry No.: 76938	Logged by: personal	on: 28/12/2018 09:15	Officer: personal
Service: Carriageway/Footway	Subject: Blocked Drain	Classification: Report or Observation	
Desc.: standing water ("giant puddle")			
Location: near bus stop RU0073 (Chaworth Rd)	Contact:		
Enquiry No.: 76752	Logged by: personal	on: 13/12/2018 10:58	Officer: personal
Service: Highway Searches	Subject: Extents and CON29	Classification: Report or Observation	
Desc.: received £62.34 - 13.12.18			
Location: Asda pe Loughborough Road, West Bridgford	Contact:		
Enquiry No.: 75763	Logged by: personal	on: 31/10/2018 13:35	Officer: personal
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: Following the recent County Hall area resurfacing on one side, is the other side going to be resurfaced too ?			
Location: Near County Hall	Contact:		
Enquiry No.: 74267	Logged by: personal	on: 04/09/2018 16:18	Officer: personal
Service: Trees/Verges	Subject: Grass Cutting	Classification: Report or Observation	
Desc.: haven't been cut yet but he noticed that the other verges had.			
Location: the grass verges from Swithland Drive up Loughborough Road to Wilford Cemetery	Contact:		

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 73460	Logged by: personal	on: 25/07/2018 13:57	Officer: personal
Service: Carriageway/Footway	Subject: Line Marking/Stud Renewal	Classification: Report or Observation	
Desc.: Suggestion of not replacing the red surfacing in bus lanes or cycle lanes as part of maintenance scheme			
Location: Near County Hall	Contact:		
Enquiry No.: 73257	Logged by: personal	on: 18/07/2018 11:59	Officer: personal
Service: Highway Searches	Subject: Adoption Extents	Classification: Report or Observation	
Desc.: payment requested 18/7/2018 - said will pay by BACS - requested remittance for proof of payment made 23.7.18 received 25.7.18			
Location: Siam House, 195	Contact: If you have paid by BA		
Enquiry No.: 72910	Logged by: personal	on: 04/07/2018 15:19	Officer: personal
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: Pothole			
Location: By drain cover outside the entrance to Cambridge Court	Contact:		
Enquiry No.: 72909	Logged by: personal	on: 04/07/2018 15:17	Officer: personal
Service: [REDACTED]	Subject: [REDACTED]	Classification: Report or Observation	
Desc.: Potholes			
Location: O/S West One and Barons Court	Contact:		
Enquiry No.: 72723	Logged by: personal	on: 27/06/2018 11:05	Officer: personal
Service: Highway Searches	Subject: Adoption Extents	Classification: Report or Observation	
Desc.: requested £42.60 - 27.6.18 - paid by card 27.6.18			
Location: DE JRSO Loughborough Road, West Bridgford	Contact:		

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Customer Services

Enquiry No.: 71269

Logged by: personal

on: 27/04/2018 11:19

Officer: personal

Service: Trees/Verges

Subject: Grass Cutting

Classification: Report or Observation

Desc.: From: personal

Sent: 26 April 2018 14:08

To: personal

Subject: FW: CCTS - Activity Roadside Verge in Front of Wilford Hill Cemetery

Hi pers

This was reported to us this morning and I have just been speaking to the manager of the Wilford Hill Cemetery and said I would pass on his contact details to you. He was saying that he always has to cut the grass verge in front of Wilford Hill Cemetery on Loughborough Road even though he doesn't own it- it appears to be adopted highway. The section he is referring to is to the west of the main entrance to the Cemetery where it runs in the direction towards the Nottingham Knight roundabout.

Could you ask someone to get in touch and as he would like to discuss its maintenance .

personal
[Redacted]

perso
[Redacted]

Location: Outside the Cemetery

Contact:

Enquiry No.: 70219

Logged by: personal

on: 20/03/2018 10:03

Officer: personal

Service: Highway Searches

Subject: Adoption Extents

Classification: Report or Observation

Desc.:

Location: junction Bridgford Road

Contact:

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,001.00	Feature Id - Locn.: Bridgford Road To Asda			Feature Type: Street Section		Area: Rushcliffe	
222567	Manholes/Gullies - f/h cover and reinstatement has sunk considerably. defect required. (Enquiry 2600191)	junction of Welbeck Rd	personal	SL- Unactioned	Job Closed	17/05/2011	22/06/2018	Act.
242673	Gully silted / blocked (HW DR Blocked Gully Z3)	Outside house number [Redacted] - near to Balmoral Avenue marked in yellow	person	Category 2	Job Cancelled	07/07/2014	04/08/2014	Est. RUSH/811852

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,001.00	Feature Id - Locn.:	Bridgford Road To Asda	Feature Type:	Street Section	Area:	Rushcliffe	
2601403	Gully blocked with rotten vegetation - T / M - road busy and on a blind bend ! (HW DR Blocked Gully Z3)	On the junction with North Rd	person	Category 2	Job Cancelled	01/12/2014	29/12/2014	Est. RUSH/3700263
2665680	HWIA - Numerous defects require making safe and unable to mark up due to high volume of traffic and job will require early start because of this - please add any extra defects made safe to ticket. (CW Repairs-Bituminous)	From the Junctions of Welbeck Road to Bridgford Road (TBI) either side of Carriageway .	person	Category 2	Job Completed	03/01/2018	10/01/2018	Act. RUS-AS/5600897
2670723	HWIA - Numerous defects require making safe which been unable to mark up due to high volume of traffic & rainfall .Recommend early start as road section gets very busy. (CW Repairs-Bituminous)	From the Junctions of Welbeck Road to Bridgford Road (TBI / Cricket Ground) either side of the Carriageway.	person	Category 2	Job Completed	13/02/2018	20/03/2018	Act. RUS-AS/5600938
2670941	Carriageway defect has now been made safe and ticket in the system for other actionable defects to be made safe by the Assistants . (CW Repairs-Bituminous)	Loughborough Road near to its junction with Sandringham Avenue city inbound.	person	Filled when found (Cat 1)	Job Completed	14/02/2018	14/02/2018	Act. RUS-AS/5600942
2672552	CW overlay - Wide spread Carriageway erosion along this location that will require making safe .The location gets large volume of Traffic so TM sensitive and unable to mark up due to this . (CW Repairs-Bituminous)	From the Junction with Welbeck Road to Balmoral Avenue	person	Category 2	Job Completed	28/02/2018	10/03/2018	Act. RUSH/3703179
2679611	HWIA - Defects require making safe and unable to mark up due to rainfall . (CW Repairs-Bituminous)	Outside the Old Sandcliffe Garage & property called West One L / C 37 (around hydrant cover) City outbound side .	person	Category 2	Job Completed	26/04/2018	01/06/2018	Act. RUS-AS/5601062
2682306	CW infill - Defects are within the centre lining of Carriageway and causing issues for road users and require infilling with HOT BITMAC which are marked up . (CW Repairs-Bituminous)	Starting from L / C 54 (Ryan House Day Nursery) and no further than L / C 51 city in bound side .	person	Category 2	Job Completed	21/05/2018	06/06/2018	Act. RUSH/3703540
2687698	Road Works Report - Priority road sign left by Utility at given location requires removing from grass verge and into stock at Gamston (Enquiry 6100858) (Other)	Near L / C 46 which is just before the left turn into Wilford Lane - city in bound side of the Carriageway .	person	Category 3	Job Completed	16/07/2018	23/07/2018	Act. RUS-AS/5601140

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,001.00	Feature Id - Locn.: Bridgford Road To Asda			Feature Type: Street Section		Area: Rushcliffe	
2690220	HWIA - Small deep defects causing complaints form Bike users which require making safe and unable to mark up due to rainfall & traffic - please add more onto ticket if required . (CW Repairs-Bituminous)	Either side of the Carriageway from the Traffic lights with Wilford Lane to Traffic Lights with Bridgford Road .	person	Category 2	Job Completed	16/08/2018	22/08/2018	Act. RUS-AS/5601185
2690584	Defects have already been made safe by person following phone conversation with ticket only requiring signing off. (CW Repairs-Bituminous)	From Victoria Road junction to the traffic lights adjacent with the junction of Wilford lane.	person	Category 2	Job Completed	22/08/2018	22/08/2018	Act. RUS-AS/5601189
2698556	HWIA - Defects are marked up to be made safe . (CW Repairs-Bituminous)	From leaving Bridgford Road (TBI) & no further than the Traffic Lights (closed Sandiccliffe Garage)	person	Category 2	Job Completed	03/12/2018	05/12/2018	Act. RUS-AS/5601300
2699889	HWIA - Defects on the crossing point require making safe - unable to mark up. (CW Repairs-Bituminous)	At the traffic lights / Tac Tile crossing form County Hall to Bridgford Road .	person	Category 2	Job Completed	17/12/2018	18/12/2018	Act. RUS-AS/5601329
2702445	HWIA - Defect is marked up to be made safe .(Enquiry 6117447) (CW Repairs-Bituminous)	At the Traffic lights on the Junction with right hand turn to Wilford / Clifton adjacent with L / C 39 .	person	Category 2	Job Completed	21/01/2019	24/01/2019	Act. RUS-AS/5601372
2702620	Carriageway defect made safe during inspection. (CW Repairs-Bituminous)	Adjacent with L / C 47 just before the left turning for Wilford Lane .	person	Filled when found (Cat 2)	Job Completed	22/01/2019	22/01/2019	Act.
2703451	HWIA - Unable to mark up defect during inspection . (CW Repairs-Bituminous)	Travelling past Asda city inbound side directly on the stop line for the Traffic lights adjacent with L / C 46 which is to the side of new care home just before the left Wilford Lane turning .	person	Category 2	Job Completed	31/01/2019	05/02/2019	Act. RUS-AS/5601382
2704498	HWIA - Various defects marked up along road section require making safe . (Enquiry 6119513) (CW Repairs-Bituminous)	From Bridgford Rd junction (old sandiccliffe garage) to the Traffic lights with Melton / Loughborough Rd Junction .	person	Category 2	Job Completed	12/02/2019	07/02/2019	Act. RUS-AS/5601401
2704500	HWIA - Various defects marked up along road section require making safe . (Enquiry 6119513) (CW Repairs-Bituminous)	From Bridgford Rd junction (old sandiccliffe garage) to the Traffic lights with Melton / Loughborough Rd Junction.	person	Category 2	Job Completed	12/02/2019	20/03/2019	Act. RUS-AS/5601403
2707255	CW repairs - Wearing course erosion marked up for repairs .Footpath is wide so vehicle can park on it if required . (CW Repairs-Bituminous)	Directly opposite The Wolds pub on the exit for the row of shops	person	Category 2	Job Completed	11/03/2019	18/03/2019	Act. RUSH/3704360

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,001.00	Feature Id - Locn.: Bridford Road To Asda			Feature Type: Street Section		Area: Rushcliffe	
2716700	HWIA - Defects are marked up for repairs . (CW Repairs-Bituminous)	Near L / C 54 & outside house number 73 & the central lining opposite the T junction of South Road (near ASDA)	person	Category 2	Job Completed	14/06/2019	18/06/2019	Act. RUS-AS/5601570
2728469	Carriageway defects require making safe and unable to mark up due to rainfall (Enquiry 83835) (CW Repairs-Bituminous)	From the junction with Millicent road city outbound side L / C 37 (opposite county hall) to the traffic lights with Melton road	person	Category 2	Repair Completed	15/11/2019	05/12/2019	Act.
2729702	pothole cat 1 repaired on site with via fix 500x500 and 200ml depth (CW Repairs-Bituminous)	outside old peoples rest home	person	Filled when found (Cat 1)	Job Completed	28/11/2019	28/11/2019	Act.
2729789	HWIA - Please make safe any wearing erosion & infill around STW utility lid , unable to mark up due to rainfall .This location is TM sensitive and recommend early start if possible . (Enquiry 6148067) (CW Repairs-Bituminous)	On the corner of Wilford road adjacent to building called The Point & around manhole surround situated in the middle of the crossroad .	person	Category 2	Repair Completed	29/11/2019	05/12/2019	Act.
2731871	Carriageway defect has been made safe . (CW Repairs-Bituminous)	Outside number 81	person	Filled when found (Cat 2)	Job Completed	19/12/2019	19/12/2019	Act.
2734686	CW repairs - Section of Carriageway has an old repair with the wearing course eroding off which is now causing the customers house to vibrate when lorries / buses pass over it . Section is near a splitter Island so TM will be required during the works - photo in link . . Online report Customer title is pe (Enquiry 6154642) (CW Repairs-Bituminous)	On the southbound carriageway of the A60 by the gate of house number 161 , directly opposite L / C 68 .	person	Category 2	Job Completed	20/01/2020	03/02/2020	Act. RUSH/3705231
2736435	Defect has been made safe . (CW Repairs-Bituminous)	City out bound side (opposite County Hall) on the lane that takes you to Loughborough Rd directly on the stop line with the main Traffic lights adjacent to property called Welbeck House .	person	Filled when found (Cat 2)	Job Completed	05/02/2020	05/02/2020	Act.

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,001.00	Feature Id - Locn.: Bridford Road To Asda			Feature Type: Street Section		Area: Rushcliffe	
2737010	Carriageway repairs - Road section has been recommended for the resurface program and until this takes place various lengths of wide spread erosion requires overlaying . TM sensitive . (Enquiry 6157969) (CW Repairs-Bituminous)	Opposite County Hall outbound side from L / C 31 (Aries Garage) to L / C 35 - no further than the main Traffic lights .	person	Category 2	Job Completed	11/02/2020	17/02/2020	Act. RUSH/3705295
2739017	HWIA - Short road section of defects are marked up to be made safe . Be advised location gets heavy traffic so recommend early start if possible . (Enquiry 6162693) (CW Repairs-Bituminous)	City out bound side starting from the junction with South Rd to the right turning into ASDA and no further than The Wolds Pub .	person	Category 2	Job Completed	03/03/2020	14/03/2020	Act. RUSH/3705375
2739851	HWIA - Defects require making safe (Enquiry 6163860) (CW Repairs-Bituminous)	Inbetween L / C 50 to L / C 51	person	Category 2	Repair Completed	10/03/2020	16/03/2020	Act.
2740907	Carriageway defect made safe (CW Repairs-Bituminous)	Outside house number 167	person	Filled when found (Cat 2)	Job Completed	23/03/2020	23/03/2020	Act.
2741172	Carriageway defect made safe & recorded - D 60 W 300 L 300 . (Enquiry 6165399) (CW Repairs-Bituminous)	Located on the double yellow lines outside the retirement living complex on Loughborough Road just before the traffic lights for Wilford Lane .	person	Filled when found (Cat 1)	Repair Completed	27/03/2020	27/03/2020	Act.
2741402	Defects made safe . (CW Repairs-Bituminous)	From the junction of Millicent Road to Traffic lights at Melton Road & directly opposite on the the corner outside building called The Point .	person	Filled when found (Cat 2)	Job Completed	03/04/2020	03/04/2020	Act.
2742179	Footpath defect made safe (FW Repairs-Bituminous)	At the entrance for Ryan House Day Nursery	person	Filled when found (Cat 2)	Job Completed	01/05/2020	01/05/2020	Act.
2743076	Defects / erosion causing issue for road users and are marked up to be made safe / infilled . (CW Repairs-Bituminous)	On the T junction for South Road & entrance for Vertu Volkswagen car dealership .	person	Category 2	Job Completed	19/05/2020	21/05/2020	Act. RUSH/3705440
2746790	CW infill - Carriageway has sections of erosion including central which are marked up to be infilled with Hot Bitmac. Road section is TM sensitive with high volume of Traffic . (CW Repairs-Bituminous)	Either side of L / C 52 & adjacent to L / C 59 & L / C 54	person	Category 2	Job Completed	07/07/2020	22/07/2020	Act. RUSH/3705596
2754105	(CW Repairs-Bituminous)	Area out side Aries motor company	person	Filled when found (Cat 2)	Job Completed	09/10/2020	09/10/2020	Act.

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,001.00	Feature Id - Locn.: Bridgford Road To Asda			Feature Type: Street Section		Area: Rushcliffe	
2764360	Carriageway repairs - Defects require making safe - unable to mark up due heavy traffic (Enquiry 94920) (CW Repairs-Bituminous)	Adjacent to "The Point" Building left lane turning off Wilford lane & junction with Welbeck Road around Hydrant lids .	personal	Category 2	Repair Completed	05/02/2021	08/02/2021	Act.
2767125	HWIA - Carriageway defects require making safe - (Enquiry 6198119) (CW Repairs-Bituminous)	On the entrance for Asda around gully & the traffic lights stop line before the left turn into Wilford Lane	personal	Category 2	Repair Completed	24/02/2021	25/02/2021	Act.
2767848	HWIA - Road section is on the resurfacing program and the worst erosion requires making safe - 1. Aries garage with traffic loops protruding & L / C number erosion are around gully surrounds . (Enquiry 95812) (CW Repairs-Bituminous)	O/S Aries Motors - L / C p & just before L / C 41 Cambridge Court	personal	Category 2	Repair Completed	02/03/2021	03/03/2021	Act.
2769429	Defects made safe (CW Repairs-Bituminous)	Outside Ryan House Day Nursery and house numbers p / p	person	Filled when found (Cat 2)	Job Completed	11/03/2021	11/03/2021	Act.
2771842	HWIA - Defect requires making safe (Enquiry 96697) (CW Repairs-Bituminous)	Junction Welbeck Road around Ironwork	personal	Category 2	Repair Completed	26/03/2021	26/03/2021	Act.
2772981	HWIA - Defect around utility defect is marked up to be made safe (CW Repairs-Bituminous)	Adjacent to L / C p just before left turn for Balmoral Avenue if travelling from Wilford Lane junction to County Hall	personal	Category 2	Repair Completed	07/04/2021	08/04/2021	Act. RUS-AS/5601917
2774660	HWIA - Defects causing issue for cyclist's are marked up to be made safe . (Enquiry 620551) (CW Repairs-Bituminous)	Outside house number p adjacent to L / C p	personal	Category 2	Repair Completed	20/04/2021	18/05/2021	Est.

Street Works Inspections

Organisation: BT -MTS - ONSA (0030411)

Works Ref: WBMT5T7K015

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 04/10/2020 14:08:50
Category: Category A		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: personal (NRSWA)		pe	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: os pe on loughborough road, Actual Depth: 0.6
Defect Notes:			Position: Verge
			Site Post Code:

Effective: 01/01/2018 to 22/04/2021

Display Action Officer: Yes

Feature No.: 2001.00 to 2001.00

Street: Loughborough Road (33001159)

Street Works Inspections

Organisation: BT -MTS - Fibre First/Gfast (0030311)

Works Ref: D29901001

Group No: 2	Site No: 1	Street Authority: Nottinghamshire	Inspected: 04/03/2021 13:31:36
Category: Category A		Outcome: Passed	Sampled: No
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: person		Tel:	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: jnc of swithland drive on loughborough road, Actual Depth: 0.35
Defect Notes:			Position: Footway
			Site Post Code:

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 04/03/2021 13:31:17
Category: Permit Conditions		Outcome: Passed	Sampled: No
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: person		Tel:	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: jnc of swithland drive on loughborough road, Actual Depth: 0.35
Defect Notes:			Position: Footway
			Site Post Code:

Organisation: BT: OR DL (0030008)

Works Ref: WAQNPF7H01

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 01/10/2020 16:15:09
Category: Category A		Outcome: Abortive	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: person		Tel:	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: Outside p South Road West Bridgford NG2 7AH (Footpath)
Defect Notes:			Position: Carriageway
			Site Post Code:

Organisation: CADENT GAS LIMITED (formerly National Grid Gas Di... (0010109)

Works Ref: 1001018218

Group No: 2	Site No: 1	Street Authority: Nottinghamshire	Inspected: 23/12/2020 10:10:25
Category: Permit Conditions		Outcome: Non-Compliant (with Conditions)	Sampled: No
Defect Notif. No: 1138		Defect No: 1138	Site Informed: Yes
Officer: person		Tel:	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: pe Loughborough road west bridgford Nottingham, Actual Depth: 0.6
Defect Notes:			Position: Footway
			Site Post Code:

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 23/12/2020 10:08:27
Category: Category A		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: person		Tel:	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: pe Loughborough road west bridgford Nottingham, Actual Depth: 0.6
Defect Notes:			Position: Footway
			Site Post Code:

Effective: 01/01/2018 to 22/04/2021

Display Action Officer: Yes

Feature No.: 2001.00 to 2001.00

Street: Loughborough Road (33001159)

Street Works Inspections

Organisation: Last Mile Gas - S&R Construction Ltd (7311018)

Works Ref: MU1139-2

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 24/12/2020 10:15:27
Category: Category B		Outcome: Failed (Lower Risk/Non Dangerous)	Sampled: Yes
Defect Notif. No: 11301898		Defect No: 11301898	Site Informed: Yes
Officer: personal (NRSWA)		pe [REDACTED]	Sign./Light./Guard. Inadequacy: No
Insp. Notes: verge needs addressing to make good			Site Location: From existing gas governor to the junction of Boundary Road, Actual Depth: 1
Defect Notes: verge needs addressing to make good			Position: Verge
			Site Post Code:

Works Ref: MU1139-7

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 24/12/2020 10:16:07
Category: Category B		Outcome: Abortive	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: personal (NRSWA)		Tel: personal	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: Excavation o/s existing gas governor & 1 x excavation at the junc of Boundary Road in footpath (Footway, Verge)
Defect Notes:			Position: Carriageway
			Site Post Code:

Works Ref: MU1139-LOUGH

Group No: 4	Site No: 1	Street Authority: Nottinghamshire	Inspected: 21/02/2021 10:50:55
Category: Permit Conditions		Outcome: Non-Compliant (with Conditions)	Sampled: No
Defect Notif. No: 1361		Defect No: 1361	Site Informed: Yes
Officer: personal		Tel:	Sign./Light./Guard. Inadequacy: No
Insp. Notes: RC10 This would include instances where required conditions have not been provided/are not necessary or conflict. The works description or location information provided is insufficient. Use this code for missing information issues not covered by the below			Site Location: From existing gas governor to the junction of Boundary Road, Actual Depth: 1
Defect Notes: RC10 This would include instances where required conditions have not been provided/are not necessary or conflict. The works description or location information provided is insufficient. Use this code for missing information issues not covered by the below			Position: Verge
			Site Post Code:

Group No: 3	Site No: 1	Street Authority: Nottinghamshire	Inspected: 21/02/2021 10:47:17
Category: Category A		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: personal		Tel:	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: From existing gas governor to the junction of Boundary Road, Actual Depth: 1
Defect Notes:			Position: Verge
			Site Post Code:

Group No: 2	Site No: 1	Street Authority: Nottinghamshire	Inspected: 16/02/2021 11:04:53
Category: Category A		Outcome: Passed	Sampled: No
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: person		Tel:	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: From existing gas governor to the junction of Boundary Road, Actual Depth: 1
Defect Notes:			Position: Verge
			Site Post Code:

Effective: 01/01/2018 to 22/04/2021

Display Action Officer: Yes

Feature No.: 2001.00 to 2001.00

Street: Loughborough Road (33001159)

Street Works Inspections**Organisation:** Last Mile Gas - S&R Construction Ltd (7311018)**Works Ref:** MU1139-LOUGH

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 16/02/2021 11:04:25
Category: Permit Conditions		Outcome: Passed	Sampled: No
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: person		Tel:	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: From existing gas governor to the junction of Boundary Road, Actual Depth: 1
Defect Notes:			Position: Verge
			Site Post Code:

Organisation: NCC - RUSHCLIFFE (3055008)**Works Ref:** GCAI06062018120304

Group No: 1	Site No: 1	Street Authority: NCC - RUSHCLIFFE	Inspected: 06/06/2018 12:03:04
Category: Category A		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: person		Tel: person	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: Outside house number pe
Defect Notes:			Position: Carriageway
			Site Post Code:

Works Ref: GCAI18092019103207

Group No: 1	Site No: 1	Street Authority: NCC - RUSHCLIFFE	Inspected: 18/09/2019 10:32:07
Category: Category A		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: person		pe	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: Outside the new retirement complex corner of Loughborough Rd / Wilford Lane
Defect Notes:			Position: Carriageway
			Site Post Code:

Organisation: NRSWA - Cadent Gas EM (0010001) (Street Works Admin Team NG Gas)**Works Ref:** 1000941917

Group No: 1	Site No: 1	Street Authority: Nottinghamshire Highway Works	Inspected: 22/05/2020 08:32:20
Category: Category A		Outcome: Passed	Sampled: Yes
Defect Notif. No: pe		Defect No: N/A	Site Informed: Yes
Officer: TS		Tel: person	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: O/S UNIT 6 BRIDGFORD HOUSE, PAVILION ROAD, IN FOOTWAY AND CARRIAGEWAY OF LOUGHBOROUGH ROAD
Defect Notes:			Position: Carriageway
			Site Post Code:

Organisation: NRSWA - Virgin Media - National (7160100)**Works Ref:** /NEMRBU/CX00048183

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 31/01/2020 10:03:02
Category: Category B		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: person		pe	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: pers LOUGHBOROUGH ROAD, WEST BRIDGFORD, NOTTINGHAM NG2 7JJ
Defect Notes:			Position: Footway
			Site Post Code:

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Inspections

Organisation: Severn Trent Water East (9103908)

Works Ref: 1101/000011800994

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 29/01/2020 10:47:44
Category: Category C		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: personal		Tel: personal	Site Location: 312
Insp. Notes:			Position: Footway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Site Post Code:

Works Ref: 1101/000012271810

Group No: 1	Site No: 1	Street Authority: NCC - RUSHCLIFFE	Inspected: 15/04/2020 12:56:36
Category: Category B		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: person		Tel: pe	Site Location: 169
Insp. Notes:			Position: Footway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Site Post Code:

Works Ref: 1101/000060220954

Group No: 5	Site No: 3	Street Authority: NCC - RUSHCLIFFE	Inspected: 09/07/2019 14:44:12
Category: Category C		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: person		Tel: pe	Site Location: JUNCTION OF ETON ROAD & LOUGHBOROUGH ROAD, NG27JR
Insp. Notes:			Position: Carriageway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Site Post Code:

Group No: 4	Site No: 2	Street Authority: Nottinghamshire	Inspected: 09/07/2019 09:00:39
Category: Category C		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: personal	(Rushcliffe)	Tel: personal	Site Location: JUNCTION OF ETON ROAD & LOUGHBOROUGH ROAD, NG27JR
Insp. Notes:			Position: Carriageway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Site Post Code:

Group No: 3	Site No: 1	Street Authority: Nottinghamshire	Inspected: 09/07/2019 09:00:10
Category: Category C		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: personal	(Rushcliffe)	Tel: personal	Site Location: JUNCTION OF ETON ROAD & LOUGHBOROUGH ROAD, NG27JR
Insp. Notes:			Position: Carriageway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Site Post Code:

Works Ref: 1101-000012514990

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 27/08/2020 10:57:16
Category: Category A		Outcome: Abortive	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: personal		Tel:	Site Location: OUTSIDE NUMBER pe (Footway, Verge)
Insp. Notes:			Position: Carriageway
Defect Notes:			Sign./Light./Guard. Inadequacy: No
			Site Post Code:

Effective: 01/01/2018 to 22/04/2021

Display Action Officer: Yes

Feature No.: 2001.00 to 2001.00

Street: Loughborough Road (33001159)

Street Works Inspections

Organisation: Severn Trent Water East (9103908)

Works Ref: 1101-000060365938

Group No: 2	Site No: 1	Street Authority: Nottinghamshire	Inspected: 06/12/2020 12:09:54
Category: Permit Conditions		Outcome: Passed	Sampled: No
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: personal		Tel:	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: CORNER OF FIRE STATION, LOUGHBOROUGH ROAD, NG2 7FA, Actual Depth: 1
Defect Notes:			Position: Footway
			Site Post Code:

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 06/12/2020 10:51:43
Category: Category A		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: personal		Tel:	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: CORNER OF FIRE STATION, LOUGHBOROUGH ROAD, NG2 7FA, Actual Depth: 1
Defect Notes:			Position: Footway
			Site Post Code:

Organisation: WPD 5154 Keyworth (7011554)

Works Ref: 2278573

Group No: 2	Site No: 1	Street Authority: Nottinghamshire	Inspected: 11/03/2021 09:15:05
Category: Permit Conditions		Outcome: Passed	Sampled: No
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: person		Tel:	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: OUTSIDE TESLA UK per, LOUGHBOROUGH ROAD, NOTTINGHAM, Actual Depth: 0.9
Defect Notes:			Position: Footway
			Site Post Code:

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 11/03/2021 09:14:31
Category: Category A		Outcome: Passed	Sampled: Yes
Defect Notif. No: N/A		Defect No: N/A	Site Informed: Yes
Officer: person		Tel:	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: OUTSIDE TESLA UK per, LOUGHBOROUGH ROAD, NOTTINGHAM, Actual Depth: 0.9
Defect Notes:			Position: Footway
			Site Post Code:

Works Ref: 9520075B

Group No: 2	Site No: 1	Street Authority: Nottinghamshire	Inspected: 21/03/2021 10:17:26
Category: Permit Conditions		Outcome: Non-Compliant (with Conditions)	Sampled: No
Defect Notif. No: 1464		Defect No: 1463	Site Informed: Yes
Officer: personal		Tel:	Sign./Light./Guard. Inadequacy: No
Insp. Notes:			Site Location: NEAR JUNCTION (Footway)
Defect Notes:			Position: Carriageway
			Site Post Code:

Effective: 01/01/2018 to 22/04/2021

Display Action Officer: Yes

Feature No.: 2001.00 to 2001.00

Street: Loughborough Road (33001159)

Street Works Inspections

Organisation: WPD 5154 Keyworth (7011554)

Works Ref: 9520075B

Group No: 1	Site No: 1	Street Authority: Nottinghamshire	Inspected: 21/03/2021 10:12:29
Category: Category A		Outcome: Failed (Lower Risk/Non Dangerous)	Sampled: Yes
Defect Notif. No: 1463		Defect No: 1463	Site Informed: No
Officer: personal		Tel:	Sign./Light./Guard. Inadequacy: Yes
Insp. Notes:			Site Location: NEAR JUNCTION (Footway)
Defect Notes:			Position: Carriageway
			Site Post Code:

Street Works Notices

Organisation: BT (0030006)

Works Ref: BC006JHGJN0004001

Notice Type: Cancellation

Work Status: Abandoned Works

Work Type: EToN 4: Minor

Version: 2

Start: 24/07/2020 07:30:00

Issued: 21/07/2020 14:31:46

Est. End: 28/07/2020

Work Desc: Excavate to clear blockage

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Junction Walcote Drive and Greythorn Drive (Footway, Carriageway, Verge)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	24/07/2020 07:30:00			28/07/2020

Works Ref: CT001MW500255319900

Notice Type: Cancellation

Work Status: Abandoned Works

Work Type: EToN 4: Minor

Version: 2

Start: 13/02/2018 00:00:00

Issued: 15/02/2018 13:40:15

Est. End: 15/02/2018

Work Desc: Erect/Renew 1 PCP cabinet and base (600mm x 300mm x 1000mm),Install 2m of 4 poly ducts in Footway,Provide 4 core drill(s) into jointbox or building

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	O/S 92, LOUGHBOROUGH ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	13/02/2018			15/02/2018

Works Ref: KNOVBNATARKWRIGHT-4

Notice Type: Works Stop

Work Status: Works Stopped

Work Type: EToN 4: Minor

Version: 3

Start: 08/05/2019 00:00:00

Issued: 13/05/2019 13:24:05

Est. End: 10/05/2019

Work Desc: Rolling programme to install fibre optic cables in existing underground duct - No excavations

Completion: 10/05/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	From Trent Bridge to Radcliffe Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	10/05/2019			09/05/2019

Works Ref: TI001MW500255319900

Notice Type: Cancellation

Work Status: Abandoned Works

Work Type: EToN 4: Minor

Version: 2

Start: 29/05/2018 00:00:00

Issued: 30/05/2018 15:39:17

Est. End: 31/05/2018

Work Desc: Erect/Renew 1 PCP cabinet and base (600mm x 300mm x 1000mm),Install 2m of 4 poly ducts in Footway,Provide 4 core drill(s) into jointbox or building

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	O/S 92, LOUGHBOROUGH ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	29/05/2018			31/05/2018

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: BT (0030006)

Works Ref: TI001MW500255319901

Version: 3

Work Desc: Erect/Renew 1 PCP cabinet and base (600mm x 300mm x 1000mm),Install 2m of 4 poly ducts in Footway,Provide 4 core drill(s) into jointbox or building

Notice Type: Works Stop

Start: 22/06/2018 00:00:00

Work Status: Works Stopped

Issued: 26/06/2018 13:54:33

Work Type: EToN 4: Minor

Est. End: 26/06/2018

Completion: 26/06/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	O/S pe LOUGHBOROUGH ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	26/06/2018			25/06/2018

Works Ref: TI001MW500256236900

Version: 4

Work Desc: Replace 1 jointbox frame and cover(s) (625mm x 625mm) in Carriageway

Notice Type: Registration of Reinstatement - Full

Start: 01/05/2018 00:00:00

Work Status: Works Stopped

Issued: 10/05/2018 09:09:41

Work Type: EToN 4: Minor

Est. End: 03/05/2018

Completion: 02/05/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OPP ROBINS CROFT, LOUGHBOROUGH ROAD	Carriageway	Up to 1.5 Metres of Cover	1.20	1.20	A Permanent Reinstatement	02/05/2018		02/05/2018	02/05/2018

Works Ref: TI001MW500290207200

Version: 2

Work Desc: Install 14m of 1 way poly duct in Footway,Provide 1 core drill(s) into jointbox or building

Notice Type: Cancellation

Start: 05/12/2019 00:00:00

Work Status: Abandoned Works

Issued: 06/12/2019 09:21:36

Work Type: EToN 4: Minor

Est. End: 09/12/2019

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	O/S NO pe LOUGHBOROUGH ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	05/12/2019			09/12/2019

Works Ref: TI001MW500290207201

Version: 5

Work Desc: Install 14m of 1 way poly duct in Footway,Provide 1 core drill(s) into jointbox or building

Notice Type: Registration of Reinstatement - Full

Start: 01/03/2020 00:00:00

Work Status: Works Stopped

Issued: 18/03/2020 13:34:20

Work Type: EToN 4: Minor

Est. End: 04/03/2020

Completion: 04/03/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	O/S NO pe LOUGHBOROUGH ROAD	Footway	Up to 1.5 Metres of Cover	12.40	0.30	A Permanent Reinstatement	04/03/2020		04/03/2020	04/03/2020

Works Ref: TI001MW500290918100

Version: 3

Work Desc: Replace 1 jointbox frame and cover(s) (2315mm x 737mm) in Footway

Notice Type: Registration of Reinstatement - Full

Start: 16/12/2019 14:20:00

Work Status: Works Stopped

Issued: 19/12/2019 08:57:30

Work Type: EToN 4: Immediate - Urgent

Est. End: 18/12/2019

Completion: 18/12/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OPPOSITE per LOUGHBOROUGH ROAD	Footway	Up to 1.5 Metres of Cover	2.80	1.20	A Permanent Reinstatement	18/12/2019		18/12/2019	18/12/2019

Works Ref: TI001MW500295225600

Version: 3

Work Desc: Locate and excavate 1 blockage in existing duct

Notice Type: Registration of Reinstatement - Full

Start: 16/03/2020 10:20:00

Work Status: Works Stopped

Issued: 24/03/2020 06:08:32

Work Type: EToN 4: Immediate - Urgent

Est. End: 18/03/2020

Completion: 18/03/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	EM0TVG42, OPP per LOUGHBOROUGH ROAD	Footway	Up to 1.5 Metres of Cover	1.80	1.00	A Permanent Reinstatement	18/03/2020		18/03/2020	18/03/2020

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: BT (0030006)

Works Ref: T1002AP500273388600

Version: 4

Work Desc: Replace 1 existing pole 0.5m x 0.5m

Notice Type: Registration of Reinstatement - Full

Start: 25/03/2019 00:00:00

Work Status: Works Stopped

Issued: 27/03/2019 12:28:37

Work Type: EToN 4: Minor

Est. End: 27/03/2019

Completion: 26/03/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	O/S LYNDHURST ON LOUGHBOROUGH LANE, LOUGHBOROUGH ROAD	Verge	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	26/03/2019		26/03/2019	26/03/2019

Works Ref: T1002AP500293819400

Version: 4

Work Desc: Replace 1 existing DAMAGED pole - PIDOC - TLF - 3 Way Lights

Notice Type: Registration of Reinstatement - Full

Start: 24/02/2020 09:59:00

Work Status: Works Stopped

Issued: 25/02/2020 09:00:09

Work Type: EToN 4: Immediate - Emergency

Est. End: 26/02/2020

Completion: 24/02/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	EM0TRG60, OS person LOUGHBOROUGH ROAD	Verge	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	24/02/2020		24/02/2020	26/02/2020

Works Ref: T1003MW500295698603

Version: 4

Work Desc: Locate and excavate 2 blockage in existing duct

Notice Type: Registration of Reinstatement - Full

Start: 27/03/2020 00:00:00

Work Status: Works Stopped

Issued: 14/04/2020 06:34:59

Work Type: EToN 4: Minor

Est. End: 31/03/2020

Completion: 31/03/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FW JNC NORTH RD AND OS NURSING HOME, LOUGHBOROUGH ROAD	Footway	Up to 1.5 Metres of Cover	0.30	0.30	A Permanent Reinstatement	31/03/2020		31/03/2020	30/03/2020

Works Ref: T1003MW500296733102

Version: 8

Work Desc: Locate and excavate 1 blockage in existing duct

Notice Type: Registration of Reinstatement - Full

Start: 21/04/2020 00:00:00

Work Status: Works Stopped

Issued: 07/05/2020 15:53:15

Work Type: EToN 4: Minor

Est. End: 24/04/2020

Completion: 24/04/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN F/W O/S NO pe LOUGHBOROUGH ROAD	Footway	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	24/04/2020		24/04/2020	23/04/2020

Works Ref: T1003MW500296733105

Version: 4

Work Desc: Clear duct blockage

Notice Type: Works Stop

Start: 08/06/2020 00:00:00

Work Status: Works Stopped

Issued: 10/06/2020 15:10:04

Work Type: EToN 4: Minor

Est. End: 10/06/2020

Completion: 10/06/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN F/W O/S NO pe LOUGHBOROUGH ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	10/06/2020		10/06/2020	10/06/2020

Works Ref: T1003MW500296867901

Version: 7

Work Desc: Locate and excavate 1 blockage in existing duct

Notice Type: Registration of Reinstatement - Full

Start: 21/04/2020 00:00:00

Work Status: Works Stopped

Issued: 07/05/2020 12:57:02

Work Type: EToN 4: Minor

Est. End: 24/04/2020

Completion: 24/04/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FW OS per LOUGHBOROUGH ROAD	Footway	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	24/04/2020		24/04/2020	23/04/2020

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** BT (0030006)**Works Ref:** T1003MW500296913101**Version:** 5**Work Desc:** Locate and excavate 1 blockage in existing duct**Notice Type:** Registration of Reinstatement - Full**Start:** 22/04/2020 00:00:00**Work Status:** Works Stopped**Issued:** 07/05/2020 16:04:56**Work Type:** ETon 4: Minor**Est. End:** 24/04/2020**Completion:** 24/04/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FW OS ^{pe} LOUGHBOROUGH ROAD	Footway	Up to 1.5 Metres of Cover	0.30	0.40	A Permanent Reinstatement	24/04/2020		24/04/2020	24/04/2020

Works Ref: T1003MW500296913102**Version:** 5**Work Desc:** Clear duct blockages**Notice Type:** Registration of Reinstatement - Full**Start:** 13/05/2020 00:00:00**Work Status:** Works Stopped**Issued:** 29/05/2020 13:59:32**Work Type:** ETon 4: Minor**Est. End:** 15/05/2020**Completion:** 15/05/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FW OS ^{pe} LOUGHBOROUGH ROAD	Footway	Up to 1.5 Metres of Cover	2.10	0.30	A Permanent Reinstatement	15/05/2020		15/05/2020	15/05/2020

Works Ref: T1003MW500298795901**Version:** 5**Work Desc:** Locate and excavate 1 blockage in existing duct**Notice Type:** Registration of Reinstatement - Full**Start:** 02/06/2020 00:00:00**Work Status:** Works Stopped**Issued:** 17/06/2020 13:23:41**Work Type:** ETon 4: Minor**Est. End:** 04/06/2020**Completion:** 04/06/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FW OS ^{per} LOUGHBOROUGH ROAD	Footway	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	04/06/2020		04/06/2020	04/06/2020

Works Ref: T1003MW500299167800**Version:** 5**Work Desc:** Locate and excavate 1 blockage in existing duct**Notice Type:** Registration of Reinstatement - Full**Start:** 11/06/2020 00:00:00**Work Status:** Works Stopped**Issued:** 26/06/2020 15:08:58**Work Type:** ETon 4: Minor**Est. End:** 15/06/2020**Completion:** 15/06/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FW OS ^{pe} LOUGHBOROUGH ROAD	Footway	Up to 1.5 Metres of Cover	0.40	0.60	A Permanent Reinstatement	15/06/2020		15/06/2020	15/06/2020

Organisation: BT -MTS - ONSA (0030411)**Works Ref:** NLWCHCNW7K001**Version:** 6**Work Desc:** TRENTSIDE 804253 - POLING WORKS - Excavate for new BT Openreach Pole 1x in FW to facilitate overhead spine cabling works.**Notice Type:** Registration of Reinstatement - Full**Start:** 20/11/2020 12:13:00**Work Status:** Works Stopped**Issued:** 25/11/2020 15:54:58**Work Type:** ETon 4: Minor**Est. End:** 24/11/2020**Completion:** 20/11/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	approx 87m ne from the junction of rushworth avenue on loughborough road, Actual Depth: 0.5	Footway	Up to 1.5 Metres of Cover	0.40	0.40	A Permanent Reinstatement	20/11/2020		20/11/2020	24/11/2020

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: BT -MTS - ONSA (0030411)

Works Ref: NLWCHCNW7K002

Version: 5

Work Desc: TRENTSIDE 804253 - POLING WORKS - Excavate for new BT Openreach Pole 1x in FW to facilitate overhead spine cabling works.

Notice Type: Registration of Reinstatement - Full

Start: 30/11/2020 09:45:00

Work Status: Works Stopped

Issued: 09/12/2020 14:01:09

Work Type: EToN 4: Minor

Est. End: 02/12/2020

Completion: 30/11/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	apprx 85m ne from jnc of rushworth avenue on loughborough road, Actual Depth: 1.6	Footway	Over 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	30/11/2020		30/11/2020	02/12/2020

Works Ref: NLWCHCP23S001

Version: 7

Work Desc: TRENTSIDE 805216 - Overlay -PROVISION OF SERVICE - Lay approx 3m of Duct 54/56 in footway to link existing BT Boxes to facilitate spine cabling works.

Notice Type: Registration of Reinstatement - Full

Start: 11/12/2020 09:51:00

Work Status: Works Stopped

Issued: 24/12/2020 14:54:03

Work Type: EToN 4: Minor

Est. End: 15/12/2020

Completion: 15/12/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	approx 96m north east from the junction with rushworth avenue on loughborough road, Actual Depth: 0.5	Footway	Up to 1.5 Metres of Cover	3.20	0.30	A Permanent Reinstatement	15/12/2020		15/12/2020	15/12/2020

Works Ref: WBKN959M001

Version: 5

Work Desc: TRENTSIDE 760673 - POLING WORKS - Excavate for new BT Openreach Pole (s) or to Replace Existing BT Openreach Pole (s) in footway to facilitate overhead spine cabling works.

Notice Type: Registration of Reinstatement - Full

Start: 10/06/2020 00:00:00

Work Status: Works Stopped

Issued: 11/06/2020 09:52:25

Work Type: EToN 4: Minor

Est. End: 10/06/2020

Completion: 10/06/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Opposite of [redacted] on LOUGHBOROUGH ROAD	Verge	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	10/06/2020		10/06/2020	10/06/2020

Works Ref: WBLH9M5V001

Version: 4

Work Desc: TRENTSIDE 767721 - PLANNED MAINTENANCE - Renew / Raise / Lower Frame and Cover on FW

Notice Type: Works Stop

Start: 21/05/2020 00:00:00

Work Status: Works Stopped

Issued: 22/05/2020 15:42:30

Work Type: EToN 4: Minor

Est. End: 22/05/2020

Completion: 22/05/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside of [redacted] LOUGHBOROUGH ROAD on LOUGHBOROUGH ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	22/05/2020			22/05/2020

Works Ref: WBLL131P001

Version: 7

Work Desc: TRENTSIDE 768720 - POLING WORKS - Excavate for new BT Openreach Pole (s) or to Replace Existing BT Openreach Pole (s) in fw to facilitate overhead spine cabling works.

Notice Type: Registration of Reinstatement - Full

Start: 11/06/2020 00:00:00

Work Status: Works Stopped

Issued: 12/06/2020 10:26:52

Work Type: EToN 4: Minor

Est. End: 11/06/2020

Completion: 11/06/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside of [redacted] LOUGHBOROUGH ROAD on LOUGHBOROUGH ROAD	Footway	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	11/06/2020		11/06/2020	11/06/2020

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: BT -MTS - ONSA (0030411)

Works Ref: WBLL196W001

Notice Type: Cancellation

Work Status: Abandoned Works

Work Type: EToN 4: Minor

Version: 5

Start: 11/06/2020 00:00:00

Issued: 12/06/2020 09:19:36

Est. End: 11/06/2020

Work Desc: TRENTSIDE 768726 - POLING WORKS - Excavate for new BT Openreach Pole (s) or to Replace Existing BT Openreach Pole (s) in footway to facilitate overhead spine cabling works.

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	At the junction of VICTORIA ROAD on LOUGHBOROUGH ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	11/06/2020			11/06/2020

Works Ref: WBLL196W004

Notice Type: Registration of Reinstatement - Full

Work Status: Works Stopped

Work Type: EToN 4: Minor

Version: 7

Start: 03/07/2020 00:00:00

Issued: 06/07/2020 14:46:48

Est. End: 03/07/2020

Work Desc: TRENTSIDE 768726 - POLING WORKS - Excavate for new BT Openreach Pole (s) or to Replace Existing BT Openreach Pole (s) in footway to facilitate overhead spine cabling works.

Completion: 03/07/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	junction of VICTORIA ROAD on LOUGHBOROUGH ROAD	Footway	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	03/07/2020		03/07/2020	03/07/2020

Works Ref: WBLL1C7K001

Notice Type: Cancellation

Work Status: Abandoned Works

Work Type: EToN 4: Minor

Version: 3

Start: 12/06/2020 00:00:00

Issued: 15/06/2020 09:03:29

Est. End: 12/06/2020

Work Desc: TRENTSIDE 768727 - POLING WORKS - Excavate for new BT Openreach Pole (s) or to Replace Existing BT Openreach Pole (s) in footway to facilitate overhead spine cabling works.

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Opposite 85 on LOUGHBOROUGH ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	12/06/2020			12/06/2020

Works Ref: WBLL1C7K002

Notice Type: Cancellation

Work Status: Abandoned Works

Work Type: EToN 4: Minor

Version: 3

Start: 19/06/2020 00:00:00

Issued: 22/06/2020 08:53:37

Est. End: 19/06/2020

Work Desc: TRENTSIDE 768727 - POLING WORKS - Excavate for new BT Openreach Pole (s) or to Replace Existing BT Openreach Pole (s) in fw to facilitate overhead spine cabling works.

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside of [redacted] on LOUGHBOROUGH ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	19/06/2020			19/06/2020

Works Ref: WBLL1C7K003

Notice Type: Registration of Reinstatement - Full

Work Status: Works Stopped

Work Type: EToN 4: Standard

Version: 7

Start: 27/07/2020 09:00:00

Issued: 04/08/2020 12:17:08

Est. End: 29/07/2020

Work Desc: TRENTSIDE 768727 - POLING WORKS - Excavate for new BT Openreach Pole (s) or to Replace Existing BT Openreach Pole (s) in FW to facilitate overhead spine cabling works.

Completion: 28/07/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	opp of [redacted] loughborough road on loughborough road, Actual Depth: 1.6	Footway	Over 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	28/07/2020 01:00:00		28/07/2020 01:00:00	29/07/2020

Works Ref: WBLL1D5V001

Notice Type: Registration of Reinstatement - Full

Work Status: Works Stopped

Work Type: EToN 4: Minor

Version: 7

Start: 11/06/2020 00:00:00

Issued: 15/06/2020 11:23:57

Est. End: 11/06/2020

Work Desc: TRENTSIDE 768730 - POLING WORKS - Excavate for new BT Openreach Pole (s) or to Replace Existing BT Openreach Pole (s) in footway to facilitate overhead spine cabling works.

Completion: 11/06/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside 141 on LOUGHBOROUGH ROAD	Footway	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	11/06/2020		11/06/2020	11/06/2020

Effective: 01/01/2018 to 22/04/2021

Display Action Officer: Yes

Feature No.: 2001.00 to 2001.00

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: BT -MTS - ONSA (0030411)

Works Ref: WBL1H2D001

Notice Type: Registration of Reinstatement - Full

Work Status: Works Stopped

Work Type: EToN 4: Minor

Version: 7

Start: 10/06/2020 00:00:00

Issued: 12/06/2020 09:39:02

Est. End: 10/06/2020

Work Desc: TRENTSIDE 768732 - POLING WORKS - Excavate for new BT Openreach Pole (s) or to Replace Existing BT Openreach Pole (s) in verge/footway to facilitate overhead spine cabling works.

Completion: 10/06/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Opposite pe on LOUGHBOROUGH ROAD	Verge	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	10/06/2020		10/06/2020	10/06/2020

Works Ref: WBLW561P001

Notice Type: Registration of Reinstatement - Full

Work Status: Works Stopped

Work Type: EToN 4: Standard

Version: 7

Start: 20/07/2020 09:35:00

Issued: 21/07/2020 07:56:13

Est. End: 22/07/2020

Work Desc: TRENTSIDE 773524 - POLING WORKS - Excavate for new BT Openreach Pole (s) or to Replace Existing BT Openreach Pole (s) in Verge to facilitate overhead spine cabling works.

Completion: 20/07/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	opp of per loughborough road on loughborough road, Actual Depth: 1.6	Verge	Over 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	20/07/2020 01:00:00		20/07/2020 01:00:00	22/07/2020

Works Ref: WBMT5T7K015

Notice Type: Registration of Reinstatement - Full

Work Status: Works Stopped

Work Type: EToN 4: Major

Version: 11

Start: 29/09/2020 16:35:00

Issued: 16/11/2020 14:01:54

Est. End: 02/11/2020

Work Desc: RUDDINGTON V8025 - PON 783588 - BLOCKAGES - Excavate onto BT ducts for the clearance of duct blockages in to facilitate spine cabling works.

Completion: 02/11/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	os pe on loughborough road, Actual Depth: 0.6	Verge	Up to 1.5 Metres of Cover	3.10	1.50	A Permanent Reinstatement	02/11/2020		02/11/2020	12/10/2020
2	os pe on loughborough road, Actual Depth: 0.5	Footway	Up to 1.5 Metres of Cover	0.80	1.20	A Permanent Reinstatement	02/11/2020		02/11/2020	
3	os perss on loughborough road, Actual Depth: 0.5	Footway	Up to 1.5 Metres of Cover	0.90	1.10	A Permanent Reinstatement	02/11/2020		02/11/2020	

Works Ref: WBPJ1R6J001

Notice Type: Registration of Reinstatement - Full

Work Status: Works Stopped

Work Type: EToN 4: Immediate - Urgent

Version: 10

Start: 15/11/2020 08:47:00

Issued: 23/11/2020 12:27:30

Est. End: 16/11/2020

Work Desc: (Trentside) (791528) hazardous site - raise/lower/renew dangerous damaged frame and cover in (Footway) causing hazard to (Pedestrians). Section 81

Completion: 16/11/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	junction of millicent road on loughborough road, Actual Depth: 0.1	Footway	Up to 1.5 Metres of Cover	1.00	1.00	A Permanent Reinstatement	16/11/2020		16/11/2020	16/11/2020

Works Ref: WCCH1T3F001

Notice Type: Cancellation

Work Status: Abandoned Works

Work Type: EToN 4: Minor

Version: 7

Start: 08/09/2020 01:00:00

Issued: 09/09/2020 09:57:38

Est. End: 09/09/2020

Work Desc: TRENTSIDE 793035 - BLOCKAGES - Excavate onto BT ducts for the clearance of duct blockages in to facilitate spine cabling works.

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	From outside of pe to approx 233m NE on LOUGHBOROUGH ROAD (Footway, Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	08/09/2020 01:00:00			09/09/2020

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** BT -MTS - ONSA (0030411)

Works Ref: WCCMFJ7K001 **Version:** 3 **Work Desc:** EDWALTON 794600 - hazardous site - raise/lower/renew dangerous damaged frame and cover in cw causing hazard to Vehicles(cw). Section 81
Notice Type: Registration of Reinstatement - Full **Start:** 19/10/2020 10:30:00
Work Status: Works Stopped **Issued:** 02/11/2020 11:12:46
Work Type: EToN 4: Immediate - Urgent **Est. End:** 21/10/2020 **Completion:** 19/10/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	opp [pe] loughborough road access road on loughborough road, Actual Depth: 0.2	Carriageway	Up to 1.5 Metres of Cover	1.30	1.30	A Permanent Reinstatement	19/10/2020 01:00:00		19/10/2020 01:00:00	21/10/2020

Organisation: BT -MTS - Fibre First/Gfast (0030311)

Works Ref: D29901001 **Version:** 7 **Work Desc:** EDWALTON V8031 - PON D29901, D29902, D29903 - BLOCKAGES – Excavate onto BT ducts for the clearance of duct blockages in FW/ CW/ VERGE to facilitate spine cabling works..
Notice Type: Registration of Reinstatement - Full **Start:** 03/03/2021 16:31:00
Work Status: Works Stopped **Issued:** 19/03/2021 16:16:02
Work Type: EToN 4: Minor **Est. End:** 05/03/2021 **Completion:** 05/03/2021
Footway closure. Alternative route will be provided

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	jnc of swithland drive on loughborough road, Actual Depth: 0.35	Footway	Up to 1.5 Metres of Cover	1.16	0.53	A Permanent Reinstatement	05/03/2021		05/03/2021	05/03/2021

Works Ref: WC2J9G4G001 **Version:** 7 **Work Desc:** EDWALTON V8031 - PON 821887 - POLING WORKS - Excavate for 2 x BT Openreach Pole in verge to facilitate overhead spine cabling works.
Notice Type: Registration of Reinstatement - Full **Start:** 25/01/2021 16:35:00
Work Status: Works Stopped **Issued:** 27/01/2021 04:50:55
Work Type: EToN 4: Minor **Est. End:** 27/01/2021 **Completion:** 26/01/2021

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	opp [pe] on loughborough road, Actual Depth: 1.6	Verge	Over 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	26/01/2021		26/01/2021	27/01/2021
2	opp [pe] on loughborough road, Actual Depth: 1.6	Verge	Over 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	26/01/2021		26/01/2021	

Works Ref: WC2V288L001 **Version:** 10 **Work Desc:** EDWALTON V8020 - PON 827940 - Overlay – Lay approx 44m of Duct 54/56 in footway/verge to link existing BT Boxes to facilitate spine cabling works.
Notice Type: Registration of Reinstatement - Full **Start:** 24/02/2021 13:30:00
Work Status: Works Stopped **Issued:** 12/03/2021 15:28:49
Work Type: EToN 4: Minor **Est. End:** 26/02/2021 **Completion:** 26/02/2021

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	outside of [pe] on loughborough road, Actual Depth: 0.6	Carriageway	Up to 1.5 Metres of Cover	1.00	0.60	A Permanent Reinstatement	26/02/2021		26/02/2021	26/02/2021
2	from outside of [pe] to approx 15m north on loughborough road, Actual Depth: 0.6	Footway	Up to 1.5 Metres of Cover	15.00	0.60	A Permanent Reinstatement	26/02/2021		26/02/2021	
3	from rear of [pe] swithland drive to approx 29m north on loughborough road, Actual Depth: 0.6	Verge	Up to 1.5 Metres of Cover	29.00	0.60	A Permanent Reinstatement	26/02/2021		26/02/2021	

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** BT -Telent - NEMSA (0030210)**Works Ref:** MW00000500296913100**Version:** 3**Work Desc:** Locate and excavate 1 blockage in existing duct**Notice Type:** Cancellation**Start:** 11/08/2020 01:00:00**Work Status:** Abandoned Works**Issued:** 12/08/2020 08:01:00**Work Type:** EToN 4: Minor**Est. End:** 13/08/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FW OS pe LOUGHBOROUGH ROAD (Footway, Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	11/08/2020 01:00:00			13/08/2020

Works Ref: MW00000500300557100**Version:** 5**Work Desc:** Provide 2excavation to expose cable damage**Notice Type:** Registration of Reinstatement - Full**Start:** 31/07/2020 10:05:00**Work Status:** Works Stopped**Issued:** 04/08/2020 16:19:01**Work Type:** EToN 4: Minor**Est. End:** 04/08/2020**Completion:** 04/08/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN SOFT O/S NOS perso AND THEN IN SOFT O/S NOS per LOUGHBOROUGH ROAD, Actual Depth: 0.8	Verge	Up to 1.5 Metres of Cover	1.30	0.50	A Permanent Reinstatement	04/08/2020 01:00:00		04/08/2020 01:00:00	04/08/2020
2	IN SOFT O/S NOS perso AND THEN IN SOFT O/S NOS per LOUGHBOROUGH ROAD, Actual Depth: 0.5	Verge	Up to 1.5 Metres of Cover	0.30	0.20	A Permanent Reinstatement	04/08/2020 01:00:00		04/08/2020 01:00:00	04/08/2020

Works Ref: MW00000500300995700**Version:** 3**Work Desc:** replace 1 x telegraph pole**Notice Type:** Cancellation**Start:** 18/09/2020 09:00:00**Work Status:** Abandoned Works**Issued:** 23/12/2020 12:27:00**Work Type:** EToN 4: Minor**Est. End:** 22/09/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
pe	LOUGHBOROUGH ROAD (Footway, Verge)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	18/09/2020 09:00:00			22/09/2020

Works Ref: MW00000500300995700**Version:** 4**Work Desc:** replace 1 x telegraph pole**Notice Type:** Grant Permit Variation**Start:** 30/11/2020 09:00:00**Work Status:** Proposed Works**Issued:** 25/11/2020 15:09:24**Work Type:** EToN 4: Minor**Est. End:** 30/11/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
pe	LOUGHBOROUGH ROAD (Footway, Verge)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	30/11/2020 09:00:00			30/11/2020

Works Ref: MW00000500302769900**Version:** 4**Work Desc:** Provide 1 new pole**Notice Type:** Cancellation**Start:** 18/11/2020 09:00:00**Work Status:** Abandoned Works**Issued:** 09/12/2020 14:05:04**Work Type:** EToN 4: Minor**Est. End:** 20/11/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
pe	ADJ per ON, LOUGHBOROUGH ROAD (Verge)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	18/11/2020 09:00:00			20/11/2020

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** BT -Telent - NEMSA (0030210)**Works Ref:** MW00000500302769901**Version:** 5**Work Desc:** replace 1 x telegraph pole - PEU is to car in the carpark**Notice Type:** Registration of Reinstatement - Full**Start:** 01/12/2020 12:53:00**Work Status:** Works Stopped**Issued:** 01/12/2020 15:34:01**Work Type:** EToN 4: Minor**Est. End:** 03/12/2020**Completion:** 01/12/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	ADJ per ON, LOUGHBOROUGH ROAD, Actual Depth: 1.6	Verge	Over 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	01/12/2020		01/12/2020	03/12/2020

Works Ref: MW00000500303477500**Version:** 5**Work Desc:** Build 1 concrete chamber 2315mm x 737mm x 1565mm deep in Footway**Notice Type:** Registration of Reinstatement - Full**Start:** 08/12/2020 16:33:00**Work Status:** Works Stopped**Issued:** 15/12/2020 11:52:04**Work Type:** EToN 4: Standard**Est. End:** 11/12/2020**Completion:** 11/12/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	O/S per LOUGHBOROUGH ROAD, Actual Depth: 0.2	Footway	Up to 1.5 Metres of Cover	1.30	0.30	A Permanent Reinstatement	11/12/2020		11/12/2020	11/12/2020

Works Ref: MW00000500304707600**Version:** 7**Work Desc:** Locate and excavate 1 blockage in existing duct**Notice Type:** Registration of Reinstatement - Full**Start:** 10/12/2020 16:54:00**Work Status:** Works Stopped**Issued:** 15/12/2020 08:16:01**Work Type:** EToN 4: Minor**Est. End:** 14/12/2020**Completion:** 14/12/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN SOFT OS CNR OF NO.181E, LOUGHBOROUGH ROAD, Actual Depth: 0.5	Footway	Up to 1.5 Metres of Cover	1.00	1.00	A Permanent Reinstatement	14/12/2020		14/12/2020	14/12/2020

Organisation: BT: Amey - BDUK/SEP/Non NEMSA/Non ONSA (0030128)**Works Ref:** WAPPWU1J**Version:** 14**Work Desc:** POLE REPLACEMENT**Notice Type:** Registration of Reinstatement - Full**Start:** 18/01/2021 11:00:00**Work Status:** Works Stopped**Issued:** 29/01/2021 14:05:57**Work Type:** EToN 4: Minor**Est. End:** 19/01/2021**Completion:** 18/01/2021

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OS 173A, Actual Depth: 1	Footway	Up to 1.5 Metres of Cover	0.40	0.40	A Permanent Reinstatement	18/01/2021		18/01/2021	19/01/2021

Organisation: BT: John Henry Group - Fibre first/ Fibre city's/... (0030333)**Works Ref:** BC006JHGJN0004001**Version:** 5**Work Desc:** Excavate to clear blockage**Notice Type:** Registration of Reinstatement - Full**Start:** 24/07/2020 09:00:00**Work Status:** Works Stopped**Issued:** 27/07/2020 14:45:27**Work Type:** EToN 4: Minor**Est. End:** 28/07/2020**Completion:** 27/07/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Junction Greythorn Drive, Actual Depth: 2	Footway	Over 1.5 Metres of Cover	1.80	0.70	A Permanent Reinstatement	27/07/2020		27/07/2020	28/07/2020

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** BT: John Henry Group - Fibre first/ Fibre city's/... (0030333)**Works Ref:** BC006JHGJN0004004**Version:** 9**Work Desc:** To access chamber in FW for splicing on Loughborough Road**Notice Type:** Works Stop**Start:** 30/07/2020 09:00:00**Work Status:** Works Stopped**Issued:** 31/07/2020 14:35:58**Work Type:** EToN 4: Minor**Est. End:** 31/07/2020**Completion:** 31/07/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Junction of Greythorn Drive (Footway, Carriageway, Verge)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	31/07/2020 14:00:00			30/07/2020

Works Ref: BC006JHGJN0025501**Version:** 8**Work Desc:** Excavate to build boxes and lay duct**Notice Type:** Cancellation**Start:** 26/10/2020 09:00:00**Work Status:** Abandoned Works**Issued:** 27/10/2020 07:58:08**Work Type:** EToN 4: Minor**Est. End:** 28/10/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside woodlands to opposite premier inn (Footway, Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	14/10/2020 09:00:00			28/10/2020

Works Ref: BC006JHGJN0025502**Version:** 3**Work Desc:** Excavate to build boxes and lay duct**Notice Type:** Cancellation**Start:** 28/01/2021 09:00:00**Work Status:** Abandoned Works**Issued:** 29/01/2021 14:46:52**Work Type:** EToN 4: Minor**Est. End:** 01/02/2021**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside woodlands to opposite premier inn (Footway, Verge)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	28/01/2021 09:00:00			01/02/2021

Works Ref: BC006JHGJN0025503**Version:** 5**Work Desc:** Excavate to build boxes and lay duct**Notice Type:** Registration of Reinstatement - Full**Start:** 08/02/2021 10:15:00**Work Status:** Works Stopped**Issued:** 11/02/2021 15:35:35**Work Type:** EToN 4: Minor**Est. End:** 10/02/2021**Completion:** 08/02/2021

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Junction of Oakham road, Actual Depth: 0.3	Footway	Up to 1.5 Metres of Cover	1.00	0.40	A Permanent Reinstatement	08/02/2021		08/02/2021	10/02/2021

Works Ref: BC006JHGJN0260101**Version:** 3**Work Desc:** Excavate verge and footway to lay new track.
Footway closure: Alternative route will be provided**Notice Type:** Cancellation**Start:** 26/03/2021 08:00:00**Work Status:** Abandoned Works**Issued:** 26/03/2021 10:46:31**Work Type:** EToN 4: Minor**Est. End:** 30/03/2021**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	From the junction of Landmerelane to outside 25 (Footway, Verge)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	26/03/2021 08:00:00			30/03/2021

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** BT: John Henry Group - Fibre first/ Fibre city's/... (0030333)**Works Ref:** BC006JHGJN0260201**Version:** 3**Work Desc:** PROVIDE NEW 9M LIGHT POLE IN SOFT SURFACE FOR CARRIER POLE AT WP1.**Notice Type:** Cancellation**Start:** 26/03/2021 09:00:00**Work Status:** Abandoned Works**Issued:** 26/03/2021 10:47:03**Work Type:** EToN 4: Minor**Est. End:** 30/03/2021**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN GRASS NEAR p JNF LOUGHBOROUGH RD / LANDMERE LANE NG11 6LU AT GRID REF: 457579,334963. (Verge)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	26/03/2021 09:00:00			30/03/2021

Organisation: BT: OR DL (0030008)**Works Ref:** ONEA6473360801**Version:** 8**Work Desc:** Lane closure is required in order to a number of manholes in order to carry out cabling works that are required that in the underground network.**Notice Type:** Cancellation**Start:** 18/01/2021 20:00:00**Work Status:** Abandoned Works**Issued:** 12/01/2021 11:00:36**Work Type:** EToN 4: Minor**Est. End:** 19/01/2021**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	o/s Trent Bridge Inn Loughborough Road West Bridgford Nottinghamshire NG2 6AA (Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	18/01/2021 20:00:00			19/01/2021

Works Ref: WAQNPF7H01**Version:** 45**Work Desc:** TM required for safe access to overhead structure.**Notice Type:** Works Stop**Start:** 01/10/2020 09:30:39**Work Status:** Works Stopped**Issued:** 02/10/2020 16:59:57**Work Type:** EToN 4: Minor**Est. End:** 02/10/2020**Completion:** 02/10/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside p South Road West Bridgford NG2 7AH (Footpath)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	02/10/2020 15:30:33			02/10/2020

Works Ref: WAQNPF7H0A**Version:** 8**Work Desc:** ROAD NARROWING REQUIRED FOR ENGINEERS TO SAFELY ACCESS UNDERGROUND STRUCTURE - NIGHT WORKING**Notice Type:** Works Stop**Start:** 06/10/2020 20:00:00**Work Status:** Works Stopped**Issued:** 07/10/2020 08:57:50**Work Type:** EToN 4: Minor**Est. End:** 07/10/2020**Completion:** 07/10/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Opposite Asda Garage, Loughborough Road, Compton Acres, West Bridgford, Nottinghamshire, East Midlands, England, NG2 7HZ, United Kingdom (Footway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	07/10/2020 05:30:57			07/10/2020

Effective: 01/01/2018 to 22/04/2021

Display Action Officer: Yes

Feature No.: 2001.00 to 2001.00

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: BT: OR DL Civils (0030007)

Works Ref: WC1JLM6J

Version: 4

Work Desc: Access is required to repair or replace damaged cable chamber frame and cover to prevent injury to the public.

Notice Type: Registration of Reinstatement - Full

Start: 01/12/2020 08:01:00

Work Status: Works Stopped

Issued: 01/12/2020 12:18:47

Work Type: EToN 4: Immediate - Urgent

Est. End: 03/12/2020

Completion: 01/12/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	pe LOUGHBOROUGH ROAD, NOTTINGHAM, NG2 7FB, (Footway, Verge), Actual Depth: 0.2	Footway	Up to 1.5 Metres of Cover	2.00	1.00 A Permanent Reinstatement	01/12/2020 12:18:18		01/12/2020 12:18:18	03/12/2020

Organisation: CADENT GAS LIMITED (formerly National Grid Gas Di... (0010109)

Works Ref: 1001016483

Version: 1

Work Desc: Registration of Non-Notifiable Works

Notice Type: Registration of Non-Notifiable Works

Start: 24/12/2020 00:00:00

Work Status: Permanent Reinstatement - Bar Holes

Issued: 24/12/2020 10:16:49

Work Type: EToN 4: Minor

Est. End: 24/12/2020

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Barholes between f/p and f/p LOUGHBOROUGH ROAD, Number of Holes: 7	Footway	Up to 1.5 Metres of Cover	0.00	0.00 Bar Hole Registration	24/12/2020		24/12/2020	

Works Ref: 1001018218

Version: 4

Work Desc: Trace, then excavate to repair gas escape and reinstate where possible

Notice Type: Registration of Reinstatement - Full

Start: 18/12/2020 11:43:47

Work Status: Works Stopped

Issued: 22/01/2021 13:36:06

Work Type: EToN 4: Immediate - Emergency

Est. End: 24/12/2020

Completion: 24/12/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	pe Loughborough road west bridford Nottingham, Actual Depth: 0.6	Footway	Up to 1.5 Metres of Cover	1.60	1.20 A Permanent Reinstatement	24/12/2020		24/12/2020	24/12/2020

Organisation: CADENT GAS LIMITED (formerly National Grid Gas Di... (0010702)

Works Ref: 1001026809

Version: 6

Work Desc: LIGHT HEAD ONLY - IN CONJUNCTION WITH 1001010159

Notice Type: Works Stop

Start: 30/01/2021 08:00:00

Work Status: Works Stopped

Issued: 02/02/2021 12:40:39

Work Type: EToN 4: Minor

Est. End: 31/01/2021

Completion: 31/01/2021

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	LIGHT HEAD ONLY - IN CONJUNCTION WITH 1001010159 (Footway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	31/01/2021 16:00:00			31/01/2021

Works Ref: 1001040061

Version: 6

Work Desc: NOTICE FOR LIGHT HEADS ONLY, DIGGING ON ETON ROAD UNDER 4-WAY SIGNALS

Notice Type: Works Stop

Start: 13/03/2021 08:00:00

Work Status: Works Stopped

Issued: 17/03/2021 13:21:31

Work Type: EToN 4: Minor

Est. End: 14/03/2021

Completion: 14/03/2021

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	JUNCTION OF ETON ROAD (Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	14/03/2021 07:25:00			14/03/2021

Effective: 01/01/2018 to 22/04/2021

Display Action Officer: Yes

Feature No.: 2001.00 to 2001.00

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** CityFibre - Hollybox Ltd (7330005)**Works Ref:** S18401-01**Version:** 26**Work Desc:** Complete remedial works on FW2 chamber**Notice Type:** Registration of Reinstatement - Full**Start:** 07/03/2019 00:00:00**Work Status:** Cancelled Phase**Issued:** 13/03/2019 11:43:07**Work Type:** EToN 4: Minor**Est. End:** 11/03/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside The Point FW2	Footway	Up to 1.5 Metres of Cover	1.60	0.90	A Permanent Reinstatement	13/03/2019	21/11/2018	13/03/2019	11/03/2019
2	from FW2 to boundary	Footway	Up to 1.5 Metres of Cover	2.00	0.20	A Permanent Reinstatement	10/12/2018	21/11/2018	10/12/2018	
3	Adjacent to FW2	Footway	Up to 1.5 Metres of Cover	1.00	0.30	A Permanent Reinstatement	10/12/2018	21/11/2018	10/12/2018	
4	Adjacent to trench	Footway	Up to 1.5 Metres of Cover	1.00	0.30	A Permanent Reinstatement	10/12/2018	21/11/2018	10/12/2018	
5	trial hole	Footway	Up to 1.5 Metres of Cover	1.60	1.10	A Permanent Reinstatement	23/01/2019		23/01/2019	
6	trial hole	Footway	Up to 1.5 Metres of Cover	1.30	1.20	A Permanent Reinstatement	23/01/2019		23/01/2019	
7	outside number 6 - trial hole	Footway	Up to 1.5 Metres of Cover	0.50	0.30	A Permanent Reinstatement	28/01/2019		28/01/2019	
8	outside number 6 - trial hole	Footway	Up to 1.5 Metres of Cover	0.30	0.30	A Permanent Reinstatement	28/01/2019		28/01/2019	
9	from outside number 6 to junction of Balmoral Avenue	Footway	Up to 1.5 Metres of Cover	57.70	0.40	A Permanent Reinstatement	28/01/2019		28/01/2019	
10	corner of Balmoral Avenue by kerb	Footway	Up to 1.5 Metres of Cover	0.80	0.50	A Permanent Reinstatement	28/01/2019		28/01/2019	
11	between 100 Loughborough Road by water stop taps	Footway	Up to 1.5 Metres of Cover	0.20	0.20	A Permanent Reinstatement	28/01/2019		28/01/2019	

Organisation: CityFibre - Kelly Communications (7330031)**Works Ref:** CF574/KELLY**Version:** 5**Work Desc:** install footway chamber and lay new duct**Notice Type:** Registration of Reinstatement - Full**Start:** 19/01/2021 09:30:00**Work Status:** Works Stopped**Issued:** 19/01/2021 14:16:28**Work Type:** EToN 4: Minor**Est. End:** 21/01/2021**Completion:** 19/01/2021

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE COUNTY HALL, Actual Depth: 1	Footway	Up to 1.5 Metres of Cover	0.01	0.01	A Permanent Reinstatement	19/01/2021		19/01/2021	19/01/2021

Organisation: Highways England - (Area 7) (0011407)**Works Ref:** 13121255**Version:** 6**Work Desc:** Rebed sunken Manhole cover and frame**Notice Type:** Works Stop**Start:** 05/03/2021 20:00:00**Work Status:** Works Stopped**Issued:** 09/03/2021 11:36:06**Work Type:** EToN 4: Minor**Est. End:** 06/03/2021**Completion:** 06/03/2021

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Loughborough Road (A60 Junction A52 Nottingham Knight Roundabout (Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	06/03/2021 06:00:00			06/03/2021

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** Highways England - (Area 7) (0011407)**Works Ref:** 29811599**Version:** 5**Work Desc:** Rebed sunken Manhole cover and frame**Notice Type:** Cancellation**Start:** 05/03/2021 20:00:00**Work Status:** Abandoned Works**Issued:** 05/02/2021 10:38:02**Work Type:** EToN 4: Minor**Est. End:** 06/03/2021**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Loughborough Road (A60 Junction A52 Nottingham Knight Roundabout (Carriageway))	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	05/03/2021 20:00:00			06/03/2021

Organisation: Last Mile Gas - S&R Construction Ltd (7311018)**Works Ref:** MU1139-2**Version:** 8**Work Desc:** To install approx 250m x 125mm Medium Pressure gas main in verge for new development site**Notice Type:** Registration of Reinstatement - Full**Start:** 01/12/2020 09:28:00**Work Status:** Works Stopped**Issued:** 16/12/2020 15:24:18**Work Type:** EToN 4: Standard**Est. End:** 14/12/2020**Completion:** 14/12/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	From existing gas governor to the junction of Boundary Road, Actual Depth: 1	Verge	Up to 1.5 Metres of Cover	170.00	0.60 A Permanent Reinstatement	14/12/2020		14/12/2020	14/12/2020

Works Ref: MU1139-4**Version:** 3**Work Desc:** For TM purposes only, linked to trial holes permit on Boundary Road**Notice Type:** Cancellation**Start:** 05/12/2020 00:00:00**Work Status:** Abandoned Works**Issued:** 02/12/2020 10:02:07**Work Type:** EToN 4: Minor**Est. End:** 06/12/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	At the junction of Boundary Road (Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	05/12/2020			06/12/2020

Works Ref: MU1139-7**Version:** 10**Work Desc:** To connect 125mm MP gas main at the CSEP connection point o/s existing gas governor in grass verge, to liven up the gas main for new site. POC Also required in the Verge - Location 457994, 335472**Notice Type:** Cancellation**Start:** 03/02/2021 00:00:00**Work Status:** Abandoned Works**Issued:** 03/02/2021 12:03:02**Work Type:** EToN 4: Standard**Est. End:** 16/02/2021**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Excavation o/s existing gas governor & 1 x excavation at the junc of Boundary Road in footpath (Footway, Verge)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	03/02/2021			16/02/2021

Works Ref: MU1139-7-LR**Version:** 2**Work Desc:** To connect 125mm MP gas main at the CSEP connection point o/s existing gas governor in grass verge, to liven up the gas main for new site. POC Also required in the Verge - Location 457994, 335472**Notice Type:** Cancellation**Start:** 15/02/2021 00:00:00**Work Status:** Abandoned Works**Issued:** 03/02/2021 15:13:28**Work Type:** EToN 4: Standard**Est. End:** 26/02/2021**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Excavation o/s existing gas governor & 1 x excavation at the junc of Boundary Road in footpath (Footway, Carriageway, Verge)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	15/02/2021			26/02/2021

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** Last Mile Gas - S&R Construction Ltd (7311018)


Works Ref: MU1139-LOUGH **Version:** 15 **Work Desc:** To install approx 90m x 125mm Medium Pressure gas main in verge for new development site. Coordinates for the connection to the governor - E: 457994, N: 335472
Notice Type: Registration of Reinstatement - Full **Start:** 09/02/2021 08:30:00
Work Status: Works Stopped **Issued:** 04/03/2021 09:34:56
Work Type: EToN 4: Standard **Est. End:** 26/02/2021 **Completion:** 25/02/2021

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	From existing gas governor to the junction of Boundary Road, Actual Depth: 1	Verge	Up to 1.5 Metres of Cover	3.00	3.00	A Permanent Reinstatement	25/02/2021		25/02/2021	19/02/2021
2	Verge from Cemetery Car Park towards Jnct of Boundary Rd, Actual Depth: 1	Verge	Up to 1.5 Metres of Cover	30.00	0.50	A Permanent Reinstatement	25/02/2021		25/02/2021	
3	FW close to Boundary Rd jnct, Actual Depth: 1	Footway	Up to 1.5 Metres of Cover	40.00	0.40	A Permanent Reinstatement	25/02/2021		25/02/2021	

Works Ref: MU1139-LR-TS **Version:** 3 **Work Desc:** SIGNAL HEADS ONLY IN RELATION TO WORKS ON BOUNDARY ROAD
Notice Type: Cancellation **Start:** 08/02/2021 00:00:00
Work Status: Abandoned Works **Issued:** 04/02/2021 16:45:17
Work Type: EToN 4: Minor **Est. End:** 10/02/2021 **Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	AT JNCT OF BOUNDARY (Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	08/02/2021			10/02/2021

Works Ref: MU1139-X **Version:** 4 **Work Desc:** PERMIT FOR SIGNAL HEADS ON LOUGHBOROUGH ROAD
Notice Type: Cancellation **Start:** 15/02/2021 00:00:00
Work Status: Abandoned Works **Issued:** 07/01/2021 13:52:56
Work Type: EToN 4: Standard **Est. End:** 19/02/2021 **Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	O/S  LOUGHBOROUGH ROAD (Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	15/02/2021			19/02/2021

Organisation: NCC - RUSHCLIFFE (3055008)

Works Ref: 30703333 **Version:** 1 **Work Desc:** install new columns (excavate during day, off peak, install at night)
Notice Type: 10 Day Initial Notice **Start:** 13/05/2019 00:00:00
Work Status: Proposed Works **Issued:** 07/05/2019 09:02:01
Work Type: EToN 4: Standard **Est. End:** 21/05/2019 **Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	around Radcliffe Rd junction	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	13/05/2019			21/05/2019

Works Ref: 30703339 **Version:** 1 **Work Desc:** coring works
Notice Type: 3 Day Initial Notice **Start:** 14/05/2019 00:00:00
Work Status: Proposed Works **Issued:** 09/05/2019 09:40:47
Work Type: EToN 4: Minor **Est. End:** 15/05/2019 **Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	between Trentside North and County Hall entrance	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	14/05/2019			15/05/2019

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: NCC - RUSHCLIFFE (3055008)

Works Ref: 30703399

Version: 4

Work Desc: resurface souhbound carriageway following signal works - OVERNIGHT WORKS ONLY

Notice Type: Works Stop

Start: 15/07/2019 00:00:00

Work Status: Works Stopped

Issued: 12/08/2019 15:27:44

Work Type: EToN 4: Major

Est. End: 04/08/2019

Completion: 29/07/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	between Trent Bridge and County Hall entrance - Southbound Only	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	29/07/2019			04/08/2019

Works Ref: 30703482

Version: 1

Work Desc: remove dying tree from central reservation and replace - Off peak work only 9.30 to 15.00

Notice Type: 3 Day Initial Notice

Start: 23/08/2019 00:00:00

Work Status: Proposed Works

Issued: 19/08/2019 08:32:07

Work Type: EToN 4: Minor

Est. End: 23/08/2019

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	northbound inside lane from Radcliffe Rd to Trent Bridge	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	23/08/2019			23/08/2019

Works Ref: 30703661

Version: 1

Work Desc: Urgent Carriageway repairs

Notice Type: 3 Day Initial Notice

Start: 11/01/2020 00:00:00

Work Status: Proposed Works

Issued: 10/01/2020 08:17:36

Work Type: EToN 4: Minor

Est. End: 11/01/2020

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	approx 150m north of Nottingham Knight roundabout	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	11/01/2020			11/01/2020

Works Ref: 3655045

Version: 1

Work Desc: Replace Damaged Post and Bollards

Notice Type: 10 Day Initial Notice

Start: 17/10/2019 00:00:00

Work Status: Proposed Works

Issued: 25/09/2019 15:18:13

Work Type: EToN 4: Standard

Est. End: 17/10/2019

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Opposite No. 336	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	17/10/2019			17/10/2019

Works Ref: 88156

Version: 4

Work Desc: Construct Vehicle Access

Notice Type: Works Stop

Start: 11/06/2020 00:00:00

Work Status: Works Stopped

Issued: 11/06/2020 10:09:14

Work Type: EToN 4: Minor

Est. End: 11/06/2020

Completion: 11/06/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside No. 77	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	11/06/2020			11/06/2020

Works Ref: 973744

Version: 1

Work Desc: REPLACE COLUMN AND TRANSFER SERVICE

Notice Type: 3 Month Initial Notice

Start: 09/05/2018 00:00:00

Work Status: Proposed Works

Issued: 29/06/2018 09:18:12

Work Type: EToN 4: Major

Est. End: 11/06/2018

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside 2-4 The Point Flats	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	09/05/2018			11/06/2018

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** NCC - RUSHCLIFFE (3055008)**Works Ref:** GCAI06062018120304**Version:** 1**Work Desc:** Unidentified Works**Notice Type:** Unattributable Works**Start:** 06/06/2018 00:00:00**Work Status:** In Progress**Issued:** 06/06/2018 12:03:05**Work Type:** Not Applicable**Est. End:** 06/06/2018**Completion:** 06/06/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside house number 211	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	06/06/2018			

Works Ref: GCAI18092019103207**Version:** 1**Work Desc:** Unidentified Works**Notice Type:** Unattributable Works**Start:** 18/09/2019 00:00:00**Work Status:** In Progress**Issued:** 18/09/2019 10:32:09**Work Type:** Not Applicable**Est. End:** 18/09/2019**Completion:** 18/09/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside the new retirement complex corner of Loughborough Rd / Wilford Lane	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	18/09/2019			

Organisation: NCC Transport Services - Trueform (3055150) (Trueform)**Works Ref:** 84432178**Version:** 6**Work Desc:** TRANSFER EXISTING SWA SERVICE INTO NEW RTI POLE AND REMOVE OLD POST & INSTALL REPLACEMENT 10M COLUMN AND TRANSFER SERVICE (OUTSIDE NUMBER 8 LOUGHBOROUGH ROAD)**Notice Type:** Modification Request**Start:** 21/02/2021 08:00:00**Work Status:** Proposed Works**Issued:** 11/02/2021 15:01:01**Work Type:** EToN 4: Minor**Est. End:** 21/02/2021**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	LOUGHBOROUGH ROAD (Footpath)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	21/02/2021 08:00:00			21/02/2021

Works Ref: WAN081**Version:** 2**Work Desc:** Installation of a bus stop pole**Notice Type:** Grant Permit**Start:** 18/02/2021 10:00:00**Work Status:** Proposed Works**Issued:** 28/01/2021 08:03:57**Work Type:** EToN 4: Minor**Est. End:** 18/02/2021**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	West Bridgford Loughborough Road opp County Hall (Footway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	18/02/2021 10:00:00			18/02/2021

Organisation: Nottinghamshire County Council (EON) (3055120)**Works Ref:** S000000000143**Version:** 4**Work Desc:** ERECT NEW 10M LIGHTING COLUMN. TRANSFER SERVICE.**Notice Type:** Actual Start Date**Start:** 29/10/2019 00:00:00**Work Status:** In Progress**Issued:** 29/10/2019 14:43:50**Work Type:** EToN 4: Standard**Est. End:** 04/11/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	per LOUGHBOROUGH ROAD, WEST BRIDGEFORD.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	11/10/2019			01/11/2019

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** Nottinghamshire County Council (EON) (3055120)**Works Ref:** S000000000172**Version:** 3**Work Desc:** INSTALL RTI POLE. TRANSFER SERVICE.**Notice Type:** Works Stop**Start:** 21/11/2019 00:00:00**Work Status:** Works Stopped**Issued:** 22/11/2019 08:01:53**Work Type:** EToN 4: Minor**Est. End:** 25/11/2019**Completion:** 22/11/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	RU0002. LOUGHBOROUGH ROAD, WEST BRIDGEFORD.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	22/11/2019			25/11/2019

Organisation: Nottinghamshire Highway Works (3055042)**Works Ref:** /260411**Version:** 1**Work Desc:** Traffic enforcement Markings**Notice Type:** 10 Day Initial Notice**Start:** 30/04/2018 00:00:00**Work Status:** Proposed Works**Issued:** 26/04/2018 11:47:54**Work Type:** EToN 4: Standard**Est. End:** 04/05/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	From Wilford Lane to Eton rd	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	30/04/2018			04/05/2018

Works Ref: /26049**Version:** 1**Work Desc:** Traffic enforcement Markings**Notice Type:** 10 Day Initial Notice**Start:** 30/04/2018 00:00:00**Work Status:** Proposed Works**Issued:** 26/04/2018 11:34:05**Work Type:** EToN 4: Standard**Est. End:** 04/05/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	From Wilford road to Eton Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	30/04/2018			04/05/2018

Works Ref: /LOUBORORDLINING**Version:** 2**Work Desc:** Refresh worn out road markings on approach to island.**Notice Type:** Works Stop**Start:** 17/05/2020 06:00:00**Work Status:** Works Stopped**Issued:** 27/05/2020 11:47:08**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 17/05/2020**Completion:** 17/05/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	A60 Loughborough Road, West Bridgford.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	17/05/2020			17/05/2020

Works Ref: /LOUGHBOROUGH05032A**Version:** 1**Work Desc:** Lining Works at night**Notice Type:** 10 Day Initial Notice**Start:** 09/03/2020 00:00:00**Work Status:** Proposed Works**Issued:** 05/03/2020 11:47:18**Work Type:** EToN 4: Standard**Est. End:** 14/03/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	One turn right lane may need to be closed on Loughborough Road so lining works can take place on Radcliffe Road at night	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	09/03/2020			14/03/2020

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** /LOUGHBOROUGH051219**Version:** 1**Work Desc:** Coring work at night**Notice Type:** 10 Day Initial Notice**Start:** 16/12/2019 00:00:00**Work Status:** Proposed Works**Issued:** 05/12/2019 14:27:04**Work Type:** EToN 4: Standard**Est. End:** 21/12/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Wilford Lane & Loughborough Road junction	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	16/12/2019			21/12/2019

Works Ref: /LOUGHBOROUGH080519**Version:** 1**Work Desc:** Coring work**Notice Type:** 3 Day Initial Notice**Start:** 14/05/2019 00:00:00**Work Status:** Proposed Works**Issued:** 08/05/2019 14:34:46**Work Type:** EToN 4: Minor**Est. End:** 15/05/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	From Trent Bridge to Rushworth Avenue. Both sides of the road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	14/05/2019			15/05/2019

Works Ref: /LOUGHBOROUGH30**Version:** 1**Work Desc:** Gully Cleansing @ night**Notice Type:** 10 Day Initial Notice**Start:** 06/10/2019 00:00:00**Work Status:** Proposed Works**Issued:** 30/09/2019 09:47:08**Work Type:** EToN 4: Standard**Est. End:** 11/10/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Entire Length	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	06/10/2019			11/10/2019

Works Ref: /LOUGHBOROUGH30**Version:** 2**Work Desc:** Gully Cleansing at Night**Notice Type:** Cancellation**Start:** 08/10/2019 00:00:00**Work Status:** Abandoned Works**Issued:** 30/09/2019 09:07:33**Work Type:** EToN 4: Standard**Est. End:** 12/10/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Entire Length	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	08/10/2019			12/10/2019

Works Ref: /PELOBORORD**Version:** 2**Work Desc:** Parking Enforcement**Notice Type:** Revised Duration Estimate**Start:** 07/05/2018 08:00:00**Work Status:** In Progress**Issued:** 11/05/2018 13:19:25**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 20/05/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Loughborough Road - (Wilford road - radcliffe Road) - West Bridgeford	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	07/05/2018 08:00:00			15/05/2018

Works Ref: 20800844**Version:** 7**Work Desc:** Installation of HMV gate**Notice Type:** Works Stop**Start:** 12/10/2020 00:00:00**Work Status:** Works Stopped**Issued:** 26/10/2020 09:08:10**Work Type:** EToN 4: Major**Est. End:** 06/11/2020**Completion:** 23/10/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	West end of Pavillion Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	23/10/2020			06/11/2020

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: 20801147

Version: 4

Work Desc: Removal of unused CCTV cabinet

Notice Type: Works Stop

Start: 28/08/2020 00:00:00

Work Status: Works Stopped

Issued: 28/08/2020 13:16:59

Work Type: EToN 4: Minor

Est. End: 28/08/2020

Completion: 28/08/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	On island nr Hethbeth bridge	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	28/08/2020			28/08/2020

Works Ref: 20802508

Version: 2

Work Desc: RTC Clear up - IR

Notice Type: Works Stop

Start: 19/11/2020 22:55:20

Work Status: Works Stopped

Issued: 20/11/2020 15:13:42

Work Type: EToN 4: Immediate - Emergency

Est. End: 20/11/2020

Completion: 20/11/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Junction with Wilford lane	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	20/11/2020			20/11/2020

Works Ref: 20803131

Version: 4

Work Desc: RECUT LOOPS IN LANE 1 AND BUS LOOP

Notice Type: Works Stop

Start: 21/01/2021 00:00:00

Work Status: Works Stopped

Issued: 21/01/2021 16:10:09

Work Type: EToN 4: Minor

Est. End: 21/01/2021

Completion: 21/01/2021

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside County hall	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	21/01/2021			21/01/2021

Works Ref: 2691545

Version: 2

Work Desc: carriageway overlay

Notice Type: Cancellation

Start: 13/09/2018 00:00:00

Work Status: Abandoned Works

Issued: 12/10/2018 14:19:01

Work Type: EToN 4: Major

Est. End: 15/09/2018

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	outside 314 opposite boundary rd	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	13/09/2018			15/09/2018

Works Ref: 2746790

Version: 4

Work Desc: CW infill - Carriageway has sections of erosion including central which are marked up to be infilled with Hot Bitmac.

Notice Type: Works Stop

Start: 20/07/2020 00:00:00

Work Status: Works Stopped

Issued: 22/07/2020 07:16:43

Work Type: EToN 4: Minor

Est. End: 22/07/2020

Completion: 22/07/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Either side of L / C p & adjacent to L / C p & L / C 54	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	22/07/2020			22/07/2020

Works Ref: 2759545

Version: 4

Work Desc: Bollard repair

Notice Type: Works Stop

Start: 29/12/2020 00:00:00

Work Status: Works Stopped

Issued: 29/12/2020 13:45:35

Work Type: EToN 4: Minor

Est. End: 30/12/2020

Completion: 29/12/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside per TUDOR HOUSE Loughborough Road cul-de-sac opposite Boundary Road, West Bridgford	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	29/12/2020			30/12/2020

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: 3637401

Version: 4

Work Desc: realign sign

Notice Type: Works Stop

Start: 08/08/2020 06:06:00

Work Status: Works Stopped

Issued: 08/08/2020 11:20:22

Work Type: EToN 4: Minor

Est. End: 08/08/2020

Completion: 08/08/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	loughborough road west bridgford.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	08/08/2020			08/08/2020

Works Ref: 3655287

Version: 3

Work Desc: insatll post

Notice Type: Cancellation

Start: 10/09/2020 00:00:00

Work Status: Abandoned Works

Issued: 02/09/2020 11:13:41

Work Type: EToN 4: Minor

Est. End: 10/09/2020

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	loughborough road west bridgford	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	10/09/2020			10/09/2020

Works Ref: 3655287A

Version: 2

Work Desc: INSTALL 3M BBASE

Notice Type: Grant Permit

Start: 12/12/2020 00:00:00

Work Status: Proposed Works

Issued: 20/11/2020 16:41:24

Work Type: EToN 4: Minor

Est. End: 12/12/2020

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	loughborough road wb	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	12/12/2020			12/12/2020

Works Ref: 3655287B

Version: 3

Work Desc: INSTALL 3M BBASE

Notice Type: Actual Start Date

Start: 29/03/2021 10:20:59

Work Status: In Progress

Issued: 29/03/2021 10:21:02

Work Type: EToN 4: Minor

Est. End: 29/03/2021

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	loughborough road west bridgford.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	29/03/2021 10:20:59			29/03/2021

Works Ref: 3656207

Version: 3

Work Desc: INSTALL NEW 3M BBASE

Notice Type: Cancellation

Start: 20/12/2020 00:00:00

Work Status: Abandoned Works

Issued: 14/12/2020 11:00:10

Work Type: EToN 4: Minor

Est. End: 20/12/2020

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	loughborough road wb	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	20/12/2020			20/12/2020

Works Ref: 3670448

Version: 3

Work Desc: INSTALL 3M X 76MM POST- EXISTING SIGN ON SITE-

Notice Type: Cancellation

Start: 20/01/2021 00:00:00

Work Status: Abandoned Works

Issued: 14/01/2021 08:48:14

Work Type: EToN 4: Minor

Est. End: 20/01/2021

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	loughborough road west bridgford.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	20/01/2021			20/01/2021

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** 3670448A**Version:** 3**Work Desc:** INSTALL 3M X 76MM POST- EXISTING SIGN ON SITE-**Notice Type:** Actual Start Date**Start:** 22/04/2021 10:20:03**Work Status:** In Progress**Issued:** 22/04/2021 14:15:33**Work Type:** EToN 4: Minor**Est. End:** 22/04/2021**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	loughborough road wb	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	22/04/2021 10:20:03			22/04/2021

Works Ref: 3671081**Version:** 3**Work Desc:** REALIGN COLUMN 3' LEAN TO ROAD**Notice Type:** Cancellation**Start:** 22/01/2021 00:00:00**Work Status:** Abandoned Works**Issued:** 14/01/2021 08:52:57**Work Type:** EToN 4: Minor**Est. End:** 22/01/2021**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	loughborough road west bridgford	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	22/01/2021			22/01/2021

Works Ref: 972326**Version:** 1**Work Desc:** Replace signs S10 and S11 and transfer services**Notice Type:** 3 Day Initial Notice**Start:** 09/01/2018 00:00:00**Work Status:** Proposed Works**Issued:** 22/12/2017 10:21:09**Work Type:** EToN 4: Minor**Est. End:** 11/01/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	opposite No. 30	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	09/01/2018			11/01/2018

Works Ref: COREBL12702**Version:** 1**Work Desc:** Core samples**Notice Type:** 3 Day Initial Notice**Start:** 04/03/2018 00:00:00**Work Status:** Proposed Works**Issued:** 27/02/2018 06:59:29**Work Type:** EToN 4: Minor**Est. End:** 04/03/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	A60 Loughborough road - Between boundary road and Europa way	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	04/03/2018			04/03/2018

Works Ref: CORES0806**Version:** 1**Work Desc:** Coring of Carriageway**Notice Type:** Immediate Initial Notice**Start:** 11/06/2018 09:30:00**Work Status:** In Progress**Issued:** 08/06/2018 15:25:00**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 11/06/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	A60 Loughborough road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	11/06/2018 09:30:00			11/06/2018

Works Ref: CORESWC502**Version:** 1**Work Desc:** Coring works under stop and Go**Notice Type:** 3 Day Initial Notice**Start:** 05/02/2018 00:00:00**Work Status:** Proposed Works**Issued:** 31/01/2018 09:49:15**Work Type:** EToN 4: Minor**Est. End:** 06/02/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	A60 Loughborough Road Between Europa way / Boundary road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	05/02/2018			06/02/2018

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** CRICKET2**Version:** 1**Work Desc:** Trial holes**Notice Type:** 3 Day Initial Notice**Start:** 14/07/2018 00:00:00**Work Status:** Proposed Works**Issued:** 13/07/2018 16:18:34**Work Type:** EToN 4: Minor**Est. End:** 17/07/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	just down from Southbank	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	14/07/2018			17/07/2018

Works Ref: EA1800601**Version:** 1**Work Desc:** Replace a damaged traffic signal pole**Notice Type:** 3 Day Initial Notice**Start:** 11/09/2018 00:00:00**Work Status:** Proposed Works**Issued:** 05/09/2018 11:17:21**Work Type:** EToN 4: Minor**Est. End:** 12/09/2018**Completion:**Install Nal socket
Install a nearside equipment due to RTA

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	A60 jct /Rugby Road/Eaton Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	11/09/2018			12/09/2018

Works Ref: F-003930**Version:** 3**Work Desc:** Re-cut damaged loops caused by poor road surface**Notice Type:** Works Stop**Start:** 27/09/2018 00:00:00**Work Status:** Works Stopped**Issued:** 01/10/2018 16:13:41**Work Type:** EToN 4: Minor**Est. End:** 27/09/2018**Completion:** 27/09/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	County Hall Access	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	27/09/2018			27/09/2018

Works Ref: F-004615**Version:** 1**Work Desc:** Loop fault, slot cutting**Notice Type:** 3 Day Initial Notice**Start:** 10/02/2019 00:00:00**Work Status:** Proposed Works**Issued:** 07/02/2019 15:06:44**Work Type:** EToN 4: Minor**Est. End:** 10/02/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	County Hall Access	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	10/02/2019			10/02/2019

Works Ref: GULLIESBL2303**Version:** 1**Work Desc:** Gully Emptying in area**Notice Type:** 3 Day Initial Notice**Start:** 03/04/2018 00:00:00**Work Status:** Proposed Works**Issued:** 23/03/2018 17:52:23**Work Type:** EToN 4: Minor**Est. End:** 05/04/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Loughborough road west Bridgeford	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	03/04/2018			05/04/2018

Works Ref: HW**Version:** 2**Work Desc:** Carriageway Resurfacing works**Notice Type:** Confirmation of Major**Start:** 11/02/2019 00:00:00**Work Status:** Proposed Works**Issued:** 10/01/2019 09:28:49**Work Type:** EToN 4: Major**Est. End:** 18/02/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Between Switchland Drive and Oakham Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	11/02/2019			18/02/2019

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: HW20197LOUGHBOROUGH

Version: 1

Work Desc: Carriageway resurfacing works (Nightworking only)

Notice Type: 3 Month Initial Notice

Start: 15/10/2018 00:00:00

Work Status: Proposed Works

Issued: 26/09/2018 10:32:46

Work Type: EToN 4: Major

Est. End: 21/10/2018

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Between Radcliffe Road and Wilford Lane NORTHBOUND ONLY	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	15/10/2018			21/10/2018

Works Ref: LONDONROAD3

Version: 1

Work Desc: Installation of temporary pedestrian barriers and relining lanes on A60 southbound only
2 x nights 3rd and 5th June 2018
(8pm - 5am)

Notice Type: 3 Day Initial Notice

Start: 03/06/2018 00:00:00

Work Status: Proposed Works

Issued: 29/05/2018 14:40:15

Work Type: EToN 4: Minor

Est. End: 06/06/2018

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Trwent Bridge	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	03/06/2018			06/06/2018

Works Ref: LOUGHBOROUGHHEW

Version: 3

Work Desc: DRIANAGE REPAIR AND PATCHING

Notice Type: Works Stop

Start: 09/03/2020 00:00:00

Work Status: Works Stopped

Issued: 11/03/2020 15:32:56

Work Type: EToN 4: Standard

Est. End: 13/03/2020

Completion: 11/03/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	LOUGHBOROUGH ROAD, WEST BRIDGFORD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	11/03/2020			13/03/2020

Works Ref: LOUGHBOROUGHHRD

Version: 4

Work Desc: Installation of traffic monitoring cabinet

Notice Type: Works Stop

Start: 22/03/2018 00:00:00

Work Status: Works Stopped

Issued: 23/03/2018 09:24:11

Work Type: EToN 4: Minor

Est. End: 22/03/2018

Completion: 22/03/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Between Sandringham Ave and Balmoral Ave southbound right turn (part off)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	22/03/2018			22/03/2018

Works Ref: LOUGHBOROUGHHRDDC

Version: 3

Work Desc: CAcARRIAGEWAY MAINTENANCE

Notice Type: Works Stop

Start: 03/02/2020 00:00:00

Work Status: Works Stopped

Issued: 03/02/2020 16:19:38

Work Type: EToN 4: Minor

Est. End: 05/02/2020

Completion: 03/02/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside [redacted] Loughborough Road, West Bridgford	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	03/02/2020			05/02/2020

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** Nottinghamshire Highway Works (3055042)**Works Ref:** LOUGHRD**Version:** 1**Work Desc:** drainage repairs**Notice Type:** 3 Day Initial Notice**Start:** 26/02/2019 00:00:00**Work Status:** Proposed Works**Issued:** 25/02/2019 16:09:04**Work Type:** EToN 4: Minor**Est. End:** 28/02/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Loughborough Rd, near nursing home	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	26/02/2019			28/02/2019

Works Ref: LOUGHRDRL**Version:** 3**Work Desc:** drainage repair and patch**Notice Type:** Works Stop**Start:** 10/02/2020 00:00:00**Work Status:** Works Stopped**Issued:** 17/02/2020 11:02:18**Work Type:** EToN 4: Standard**Est. End:** 14/02/2020**Completion:** 13/02/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	on loughborough rd	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	13/02/2020			14/02/2020

Works Ref: LOUGH SIGNAL REFURB**Version:** 4**Work Desc:** Traffic signal refurbishment including ducting and street lighting works**Notice Type:** Works Stop**Start:** 24/06/2019 00:00:00**Work Status:** Works Stopped**Issued:** 12/08/2019 15:26:09**Work Type:** EToN 4: Major**Est. End:** 25/08/2019**Completion:** 12/08/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Jct with Radcliffe Road and Bridgford Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	12/08/2019			25/08/2019

Works Ref: TRENT**Version:** 3**Work Desc:** trial holes**Notice Type:** Works Stop**Start:** 20/10/2018 00:00:00**Work Status:** Works Stopped**Issued:** 22/10/2018 10:20:30**Work Type:** EToN 4: Minor**Est. End:** 20/10/2018**Completion:** 20/10/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Loughborough rd inbetween trent bridge and pavilion rd	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	20/10/2018			20/10/2018

Organisation: Nottinghamshire Highway Works (3055043)**Works Ref:** 08832303**Version:** 4**Work Desc:** Coring work at night**Notice Type:** Works Stop**Start:** 07/08/2020 20:00:00**Work Status:** Works Stopped**Issued:** 17/08/2020 08:09:33**Work Type:** EToN 4: Standard**Est. End:** 15/08/2020**Completion:** 15/08/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	between Cemetery entrance & Oakham Road (Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	15/08/2020 05:00:00			15/08/2020

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: Nottinghamshire Highway Works (3055043)

Works Ref: 14852466

Version: 6

Work Desc: Gully Cleansing at night

Notice Type: Grant Permit

Start: 06/12/2020 19:00:00

Work Status: Proposed Works

Issued: 27/11/2020 13:45:11

Work Type: EToN 4: Minor

Est. End: 09/12/2020

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Between South Street & Rugby Road (Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	06/12/2020 19:00:00			09/12/2020

Works Ref: 38630083

Version: 4

Work Desc: Re lining of bus stop markings outside RU0071

Notice Type: Works Stop

Start: 15/12/2020 09:00:00

Work Status: Works Stopped

Issued: 18/12/2020 12:12:18

Work Type: EToN 4: Minor

Est. End: 15/12/2020

Completion: 16/12/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	A60 Loughborough Road near Asda (Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	16/12/2020 15:00:00			15/12/2020

Works Ref: 46756114

Version: 6

Work Desc: Coring Works

Notice Type: Works Stop

Start: 05/08/2020 20:00:00

Work Status: Works Stopped

Issued: 17/08/2020 08:08:50

Work Type: EToN 4: Standard

Est. End: 15/08/2020

Completion: 13/08/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Between County Hall & Wilford Lane traffic lights (Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed	13/08/2020 05:00:00			15/08/2020

Works Ref: 61718332

Version: 6

Work Desc: installing new / refresh bus stop road markings

Notice Type: Works Stop

Start: 26/11/2020 11:00:00

Work Status: Works Stopped

Issued: 27/11/2020 08:36:31

Work Type: EToN 4: Minor

Est. End: 27/11/2020

Completion: 26/11/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	between Balmoral Road & Welbeck Road (Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	26/11/2020 15:30:00			26/11/2020

Works Ref: 81724655

Version: 3

Work Desc: Gully Cleansing at night

Notice Type: Authority Imposed Variation

Start: 06/12/2020 19:00:00

Work Status: Proposed Works

Issued: 25/11/2020 11:11:27

Work Type: EToN 4: Minor

Est. End: 09/12/2020

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Between Wilford Lane & Old Trent Bridge (Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	06/12/2020 19:00:00			09/12/2020

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** Nottinghamshire Highway Works (3055043)**Works Ref:** 83777760**Version:** 4**Work Desc:** Installation of bus stop road markings**Notice Type:** Grant Permit Variation**Start:** 25/11/2020 09:00:00**Work Status:** Proposed Works**Issued:** 27/11/2020 10:45:52**Work Type:** EToN 4: Standard**Est. End:** 02/12/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	various locations (Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	25/11/2020 09:00:00			02/12/2020

Organisation: NRSWA - BT (0030005)**Works Ref:** CA789W000WAQHUU9H03**Version:** 4**Work Desc:** Access required to BT under ground structure for cabling and jointing works no excavation work involved.**Notice Type:** Works Stop**Start:** 05/02/2020 00:00:00**Work Status:** Works Stopped**Issued:** 17/02/2020 09:23:22**Work Type:** EToN 4: Major**Est. End:** 17/02/2020**Completion:** 17/02/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	From Junction with Radcliffe road to Junction with London Road Trent Bridge Road City of Nottingham East Midlands NG2 3B	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	17/02/2020			17/02/2020

Works Ref: CC1W00000WAQPW93X05**Version:** 4**Work Desc:** ROAD NARROWING WITH PEDESTRIAN WALKWAY REQUIRED TO PROVIDE SAFE WORKING ZONE FOR UNDERGROUND CABLING.**Notice Type:** Works Stop**Start:** 05/05/2020 00:00:00**Work Status:** Works Stopped**Issued:** 11/05/2020 08:32:06**Work Type:** EToN 4: Minor**Est. End:** 07/05/2020**Completion:** 07/05/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Loughborough Road junction with Melton Road West Bridgford Nottinghamshire NG2 7JZ	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	07/05/2020			07/05/2020

Works Ref: CN17W021NOVLXP941EM**Version:** 3**Work Desc:** Access required to Underground BT structure to provide service - No structural changes - Highway Surface will be unaffected. Work being carried out on existing BT Plant**Notice Type:** Works Stop**Start:** 21/11/2019 00:00:00**Work Status:** Works Stopped**Issued:** 22/11/2019 08:57:46**Work Type:** EToN 4: Minor**Est. End:** 21/11/2019**Completion:** 21/11/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	os p LOUGHBOROUGH ROAD WEST BRIDGFORD NOTTINGHAMSHIRE NG2 7JZ	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	21/11/2019			21/11/2019

Works Ref: PT001W0000001373726**Version:** 1**Work Desc:** Registration of Non-Notifiable Works**Notice Type:** Registration of Non-Notifiable Works**Start:** 09/10/2018 00:00:00**Work Status:** Permanent Reinstatement - Bar Holes**Issued:** 12/10/2018 08:10:46**Work Type:** EToN 4: Minor**Est. End:** 09/10/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	LOUGHBOROUGH ROAD WEST BRIDGFORD O/S pe	Verge	Up to 1.5 Metres of Cover	0.00	0.00 Pole Test Reinstatement	09/10/2018			09/10/2018

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** NRSWA - BT (0030005)

Works Ref: PT001W0000001393630 **Version:** 1 **Work Desc:** Registration of Non-Notifiable Works
Notice Type: Registration of Non-Notifiable Works **Start:** 13/02/2019 00:00:00
Work Status: Permanent Reinstatement - Bar Holes **Issued:** 15/02/2019 02:02:51
Work Type: EToN 4: Minor **Est. End:** 13/02/2019 **Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	LOUGHBOROUGH RDWILFORD HILL NEAR JUNCTION OF EUROPA WAY	Verge	Up to 1.5 Metres of Cover	0.00	0.00 Pole Test Reinstatement	13/02/2019		13/02/2019	

Works Ref: PT001W0000001415410 **Version:** 1 **Work Desc:** Registration of Non-Notifiable Works
Notice Type: Registration of Non-Notifiable Works **Start:** 23/05/2019 00:00:00
Work Status: Permanent Reinstatement - Bar Holes **Issued:** 25/05/2019 01:05:05
Work Type: EToN 4: Minor **Est. End:** 23/05/2019 **Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	LOUGHBOROUGH RD NOTTINGHAM NEAR ETON RD	Verge	Up to 1.5 Metres of Cover	0.00	0.00 Pole Test Reinstatement	23/05/2019		23/05/2019	

Organisation: NRSWA - Cadent Gas EM (0010001) (Street Works Admin Team NG Gas)

Works Ref: 1000757046 **Version:** 4 **Work Desc:** Trace, then excavate to repair gas escape and reinstate where possible
Notice Type: Registration of Reinstatement - Full **Start:** 14/09/2018 14:56:00
Work Status: Works Stopped **Issued:** 26/09/2018 12:55:20
Work Type: EToN 4: Immediate - Emergency **Est. End:** 26/09/2018 **Completion:** 26/09/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	OPEN LONDON ROAD - CHAKH LE INDIAN RESTAURANT	Footway	Up to 1.5 Metres of Cover	1.00	0.80 A Permanent Reinstatement	23/09/2018		23/09/2018	20/09/2018

Works Ref: 1000762291 **Version:** 1 **Work Desc:** Registration of Non-Notifiable Works
Notice Type: Registration of Non-Notifiable Works **Start:** 10/10/2018 00:00:00
Work Status: Permanent Reinstatement - Bar Holes **Issued:** 10/10/2018 15:25:43
Work Type: EToN 4: Minor **Est. End:** 10/10/2018 **Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Barholes between Kerb and Kerb LOUGHBOROUGH ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Bar Hole Registration	10/10/2018		10/10/2018	

Works Ref: 1000763205 **Version:** 3 **Work Desc:** Trace, then excavate to repair gas escape and reinstate where possible
Notice Type: Registration of Reinstatement - Full **Start:** 03/10/2018 18:48:00
Work Status: Works Stopped **Issued:** 10/10/2018 15:25:50
Work Type: EToN 4: Immediate - Emergency **Est. End:** 09/10/2018 **Completion:** 08/10/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 213	Footway	Up to 1.5 Metres of Cover	1.00	1.00 A Permanent Reinstatement	07/10/2018		07/10/2018	09/10/2018

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** NRSWA - Cadent Gas EM (0010001) (Street Works Admin Team NG Gas)

Works Ref: 1000783311 **Version:** 5 **Work Desc:** ALTER AND RELAY DOMESTIC SERVICE 3M FROM MAIN IN FOOTWAY
Notice Type: Registration of Reinstatement - Full **Start:** 11/01/2019 00:00:00
Work Status: Works Stopped **Issued:** 16/01/2019 15:55:33
Work Type: EToN 4: Standard **Est. End:** 16/01/2019 **Completion:** 16/01/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	pe	Footway	Up to 1.5 Metres of Cover	0.60	0.60	A Permanent Reinstatement	14/01/2019		14/01/2019	16/01/2019
2	pe	Verge	Up to 1.5 Metres of Cover	1.10	0.60	A Permanent Reinstatement	12/01/2019		12/01/2019	

Works Ref: 1000792623 **Version:** 5 **Work Desc:** TO LAY A NEW GAS SERVICE PIPE TO 3 EXISTING PROPERTIES 10M (5M PRIVATE)
Notice Type: Registration of Reinstatement - Full **Start:** 03/02/2019 00:00:00
Work Status: Works Stopped **Issued:** 08/02/2019 09:55:22
Work Type: EToN 4: Minor **Est. End:** 03/02/2019 **Completion:** 04/02/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	flaperson	Carriageway	Over 1.5 Metres of Cover	2.10	1.25	A Permanent Reinstatement	03/02/2019		03/02/2019	03/02/2019
2	flaperson	Footway	Over 1.5 Metres of Cover	1.90	0.50	A Permanent Reinstatement	03/02/2019		03/02/2019	

Works Ref: 1000827756 **Version:** 3 **Work Desc:** EMGA202043. CONNECTION PERMIT ONLY IN CONJUNCTION WITH GASMAINSREPLACEMENT WORKS ON SOUTH ROAD
Notice Type: Revised Duration Estimate **Start:** 11/06/2019 00:00:00
Work Status: Proposed Works **Issued:** 01/07/2019 16:19:18
Work Type: EToN 4: Major **Est. End:** 08/07/2019 **Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	JUNCTION OF SOUTH ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	11/06/2019		08/07/2019	02/07/2019
2	Jcn south road	Carriageway	Up to 1.5 Metres of Cover	2.20	1.00	A Permanent Reinstatement	08/07/2019		08/07/2019	
3	Jcn south road	Footway	Up to 1.5 Metres of Cover	2.70	1.00	A Permanent Reinstatement	08/07/2019		08/07/2019	

Works Ref: 1000849670 **Version:** 1 **Work Desc:** Registration of Non-Notifiable Works
Notice Type: Registration of Non-Notifiable Works **Start:** 28/06/2019 00:00:00
Work Status: Permanent Reinstatement - Bar Holes **Issued:** 30/06/2019 17:04:39
Work Type: EToN 4: Minor **Est. End:** 28/06/2019 **Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Barholes between footpath and footpath/driveway entrance of LOUGHBOROUGH ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Bar Hole Registration	28/06/2019		28/06/2019	

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: NRSWA - Cadent Gas EM (0010001) (Street Works Admin Team NG Gas)

Works Ref: 1000876103

Version: 1

Work Desc: GAS SERVICE DISCONNECTION WITH EXCAVATION UNDER OUR MANDATORY OBLIGATION TO COMPLY WITH GAS SAFETY REGULATIONS 1994 EXCAVATE, DISCONNECT DOMESTIC GAS SUPPLY AND RE-INSTATE.

Notice Type: 3 Day Initial Notice

Start: 06/10/2019 00:00:00

Work Status: Proposed Works

Issued: 01/10/2019 14:43:16

Work Type: EToN 4: Minor

Est. End: 09/10/2019

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE per FOOTWAY	LOUGHBOROUGH ROAD IN	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	06/10/2019			09/10/2019

Works Ref: 1000917656

Version: 3

Work Desc: Trace, then excavate to repair gas escape and reinstate where possible

Notice Type: Registration of Reinstatement - Full

Start: 11/02/2020 10:59:00

Work Status: Works Stopped

Issued: 24/02/2020 15:04:08

Work Type: EToN **p** Immediate - Emergency

Est. End: 17/02/2020

Completion: 15/02/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Verge outside playing fields	Verge	Up to 1.5 Metres of Cover	1.80	1.00 A Permanent Reinstatement		12/02/2020		12/02/2020	17/02/2020

Works Ref: 1000941917

Version: 6

Work Desc: UNDER THE GAS SAFETY REGS 1998 WE HAVE A MANDATORY REQUIREMENT TO UNDERTAKE THE IMMEDIATE ISOLATION OF A HIGH PRIORITY UNUSED LIVE GAS SERVICE INTO THE PROPERTY

Notice Type: Works Stop

Start: 11/05/2020 00:00:00

Work Status: Works Stopped

Issued: 11/05/2020 12:52:05

Work Type: EToN **p** Minor

Est. End: 13/05/2020

Completion: 11/05/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	O/S UNIT p BRIDGFORD HOUSE, PAVILION ROAD, IN FOOTWAY AND CARRIAGEWAY OF LOUGHBOROUGH ROAD	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)		11/05/2020			13/05/2020

Works Ref: 1000942855

Version: 4

Work Desc: OF A HIGH PRIORITY UNUSED LIVE GAS SERVICE INTO THE PROPERTY

Notice Type: Cancellation

Start: 12/05/2020 00:00:00

Work Status: Abandoned Works

Issued: 11/05/2020 13:54:52

Work Type: EToN 4: Minor

Est. End: 14/05/2020

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN FOOTPATH OUTSIDE PROPERTY per BRIDGFORD HOUSE	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned		12/05/2020			14/05/2020

Works Ref: 1000948364

Version: 7

Work Desc: UNDER THE GAS SAFETY REGS 1998 WE HAVE A MANDATORY REQUIREMENT TO UNDERTAKE THE IMMEDIATE ISOLATION OF A HIGH PRIORITY UNUSED LIVE GAS SERVICE INTO THE PROPERTY

Notice Type: Cancellation

Start: 15/06/2020 00:00:00

Work Status: Abandoned Works

Issued: 16/06/2020 15:21:57

Work Type: EToN 4: Standard

Est. End: 19/06/2020

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN CARRIGEWAY O/S CHAKH LE INDIA	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned		15/06/2020			19/06/2020

Effective: 01/01/2018 to 22/04/2021

Display Action Officer: Yes

Feature No.: 2001.00 to 2001.00

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** NRSWA - Cadent Gas EM (0010001) (Street Works Admin Team NG Gas)

Works Ref: 1000955347	Version: 12	Work Desc: UNDER THE GAS SAFETY REGS 1998 WE HAVE A MANDATORY REQUIREMENT TOUNDERTAKE THE IMMEDIATE ISOLATIONOF A HIGH PRIORITY UNUSED LIVE GAS SERVICE INTO THE PROPERTY
Notice Type: Registration of Reinstatement - Full	Start: 28/06/2020 00:00:00	
Work Status: Works Stopped	Issued: 02/07/2020 11:31:34	
Work Type: EToN 4: Minor	Est. End: 01/07/2020	Completion: 01/07/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN F/W O/S CHAKH LE INDIA	Footway	Up to 1.5 Metres of Cover	1.10	1.00	A Permanent Reinstatement	01/07/2020		01/07/2020	30/06/2020
2	IN F/W O/S CHAKH LE INDIA	Footway	Up to 1.5 Metres of Cover	1.00	0.60	A Permanent Reinstatement	01/07/2020		01/07/2020	
3	o/s Unit 6 Bridgford House	Carriageway	Up to 1.5 Metres of Cover	0.90	0.45	A Permanent Reinstatement	01/07/2020		01/07/2020	
4	o/s Unit 6 Bridgford House	Carriageway	Up to 1.5 Metres of Cover	0.90	0.50	A Permanent Reinstatement	01/07/2020		01/07/2020	
5	o/s Unit 4 person House	Carriageway	Up to 1.5 Metres of Cover	1.40	0.65	A Permanent Reinstatement	01/07/2020		01/07/2020	
6	o/s Unit 6 Bridgford House	Carriageway	Up to 1.5 Metres of Cover	1.20	0.80	A Permanent Reinstatement	01/07/2020		01/07/2020	

Works Ref: 1000964539	Version: 4	Work Desc: PERMIT FOR LANE CLOSURE ONLY IN CONJUNCTION WITH INVESTIGATORY WORKS ON WILFORD LANE
Notice Type: Works Stop	Start: 25/07/2020 08:30:00	
Work Status: Works Stopped	Issued: 28/07/2020 07:59:43	
Work Type: EToN 4: Minor	Est. End: 26/07/2020	Completion: 26/07/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	JUNCTION OF WILFORD LANE (Footway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	26/07/2020 16:30:00			26/07/2020

Works Ref: 1000973581	Version: 7	Work Desc: PERMIT FOR LANE CLOSURE ONLY IN CONJUNCTION WITH INVESTIGATORY WORKS ON WILFORD LANE
Notice Type: Works Stop	Start: 21/08/2020 12:00:00	
Work Status: Works Stopped	Issued: 26/08/2020 10:51:13	
Work Type: EToN 4: Minor	Est. End: 25/08/2020	Completion: 24/08/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	JUNCTION OF WILFORD LANE (Footway, Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	25/08/2020 16:29:00			24/08/2020

Organisation: NRSWA - Virgin Media - National (7160100)

Works Ref: /NEMRBU/CX00048183	Version: 4	Work Desc: Construct one tee from the existign track and lay down 2m footway duct into customer premises.
Notice Type: Registration of Reinstatement - Full	Start: 25/10/2019 00:00:00	
Work Status: Works Stopped	Issued: 04/11/2019 11:35:05	
Work Type: EToN 4: Minor	Est. End: 29/10/2019	Completion: 29/10/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	pers LOUGHBOROUGH ROAD, WEST BRIDGFORD, NOTTINGHAM NG2 7JJ	Footway	Up to 1.5 Metres of Cover	1.00	0.30	A Permanent Reinstatement	29/10/2019		29/10/2019	29/10/2019

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** NRSWA - Virgin Media - National (7160100)**Works Ref:** /NEMRF/CX00028472**Version:** 4**Work Desc:** Lay 2m in verge, 2m in footway and 2m in carriageway**Notice Type:** Registration of Reinstatement - Full**Start:** 24/06/2018 00:00:00**Work Status:** Works Stopped**Issued:** 28/06/2018 10:53:01**Work Type:** EToN 4: Minor**Est. End:** 27/06/2018**Completion:** 24/06/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside Leewood	Carriageway	Up to 1.5 Metres of Cover	1.50	0.30	A Permanent Reinstatement	24/06/2018		24/06/2018	27/06/2018
2	Outside Leewood	Footway	Up to 1.5 Metres of Cover	1.10	0.30	A Permanent Reinstatement	24/06/2018		24/06/2018	

Works Ref: /NEMRF/CX00030388**Version:** 4**Work Desc:** Lay 5m in the verge and 2m in footway**Notice Type:** Registration of Reinstatement - Full**Start:** 12/07/2018 00:00:00**Work Status:** Works Stopped**Issued:** 18/07/2018 10:26:36**Work Type:** EToN 4: Minor**Est. End:** 16/07/2018**Completion:** 16/07/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside 160	Footway	Up to 1.5 Metres of Cover	0.60	0.40	A Permanent Reinstatement	16/07/2018		16/07/2018	16/07/2018
2	Outside 160	Verge	Up to 1.5 Metres of Cover	4.00	0.30	A Permanent Reinstatement	16/07/2018		16/07/2018	

Works Ref: /NEMRF/CX00031293A**Version:** 4**Work Desc:** Clear carriageway blockage**Notice Type:** Registration of Reinstatement - Full**Start:** 09/09/2018 00:00:00**Work Status:** Works Stopped**Issued:** 14/09/2018 09:28:31**Work Type:** EToN 4: Minor**Est. End:** 12/09/2018**Completion:** 09/09/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Opposite junction LANDMERE LANE	Carriageway	Up to 1.5 Metres of Cover	0.60	0.60	A Permanent Reinstatement	09/09/2018		09/09/2018	12/09/2018

Works Ref: /NYNLRE/0321513**Version:** 3**Work Desc:** LOCATE TEE**Notice Type:** Works Stop**Start:** 03/08/2018 00:00:00**Work Status:** Works Stopped**Issued:** 06/08/2018 08:36:37**Work Type:** EToN 4: Minor**Est. End:** 07/08/2018**Completion:** 04/08/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE FLAT 3 KENSAL COURT	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	04/08/2018			06/08/2018

Works Ref: /NYNLRE/0323882**Version:** 4**Work Desc:** LOCATE TEE**Notice Type:** Registration of Reinstatement - Full**Start:** 24/10/2018 00:00:00**Work Status:** Works Stopped**Issued:** 25/10/2018 08:48:33**Work Type:** EToN 4: Minor**Est. End:** 26/10/2018**Completion:** 24/10/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE 171	Footway	Up to 1.5 Metres of Cover	0.40	0.40	A Permanent Reinstatement	24/10/2018		24/10/2018	26/10/2018

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: Permits Rushcliffe (3055017) (VIA TBH)

Works Ref: JKS8109073284

Version: 2

Work Desc: Apparatus - Tee/valve/access covers (SMTV)

Notice Type: Defective Apparatus Acceptance

Start: 25/08/2020 08:22:02

Work Status: In Progress

Issued: 26/08/2020 13:06:24

Work Type: Not Applicable

Est. End: 25/08/2020

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	rattling manhole cover in c/way - customer complaint (Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	25/08/2020 08:22:02			25/08/2020

Works Ref: JKS8118789190

Version: 1

Work Desc: Apparatus - Tee/valve/access covers (SMTV)

Notice Type: Defective Apparatus

Start: 16/03/2021 15:48:50

Work Status: In Progress

Issued: 16/03/2021 15:43:27

Work Type: Not Applicable

Est. End: 16/03/2021

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	MH Cover in the vicinity of Whitegates in c/way perishing (Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	16/03/2021 15:48:50			16/03/2021

Works Ref: JKS8130267337

Version: 3

Work Desc: Apparatus - Tee/valve/access covers (SMTV)

Notice Type: Defective Apparatus Acceptance Fixed

Start: 04/02/2021 15:23:29

Work Status: Works Closed (Permanent Reinstatement)

Issued: 05/02/2021 09:36:31

Work Type: Not Applicable

Est. End: 04/02/2021

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	wire coming out of its ducting in a loop - trip hazard (Footway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	04/02/2021 15:23:29			04/02/2021

Works Ref: JKS8143857204

Version: 1

Work Desc: Apparatus - Tee/valve/access covers (SMTV)

Notice Type: Defective Apparatus

Start: 24/02/2021 15:32:02

Work Status: In Progress

Issued: 24/02/2021 14:57:49

Work Type: Not Applicable

Est. End: 24/02/2021

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	single lid c/way MH Cover loose and rattling in frame, surround starting to perish resident complaint, cheers (Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	24/02/2021 15:32:02			24/02/2021

Works Ref: JKS8149311226

Version: 2

Work Desc: Apparatus (IC16)

Notice Type: Defective Apparatus Non-acceptance

Start: 16/11/2020 15:06:32

Work Status: In Progress

Issued: 18/11/2020 11:00:32

Work Type: Not Applicable

Est. End: 16/11/2020

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	outside No p Loughborough Road next to garden wall (Footway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	16/11/2020 15:06:32			16/11/2020

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** Permits Rushcliffe (3055017) (VIA TBH)**Works Ref:** JKS8153102722**Version:** 1**Work Desc:** Apparatus - Tee/valve/access covers (SMTV)**Notice Type:** Defective Apparatus**Start:** 25/02/2021 10:20:23**Work Status:** In Progress**Issued:** 25/02/2021 10:18:12**Work Type:** Not Applicable**Est. End:** 25/02/2021**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	almost dead centre of carriageway, deteriorating frame surround leading to rattling lid. (Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	25/02/2021 10:20:23			25/02/2021

Works Ref: JKS8167352737**Version:** 2**Work Desc:** Apparatus (IC16)**Notice Type:** Defective Apparatus Non-acceptance**Start:** 16/11/2020 15:06:34**Work Status:** In Progress**Issued:** 14/01/2021 16:50:01**Work Type:** Not Applicable**Est. End:** 16/11/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	outside NO ^p Loughborough Road next to garden wall (Footway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	16/11/2020 15:06:34			16/11/2020

Organisation: Severn Trent Integra Utility Services (9103906)**Works Ref:** 0000/00004400569**Version:** 4**Work Desc:** INSTALL NEW MTR AND BBOX DIG IS A METER BY A METER SQUARE WE INTEND TO USE PERMASOIL**Notice Type:** Registration of Reinstatement - Full**Start:** 15/06/2018 00:00:00**Work Status:** Works Stopped**Issued:** 15/06/2018 15:48:32**Work Type:** EToN 4: Minor**Est. End:** 19/06/2018**Completion:** 15/06/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	ON FOOTWAY OUTSIDE NO ^{pe}	Footway	Up to 1.5 Metres of Cover	0.60	0.60	A Permanent Reinstatement	15/06/2018		15/06/2018	19/06/2018

Works Ref: 0000/00004414114**Version:** 4**Work Desc:** INSTALL NEW MTR AND BBOX DIG IS A METER BY A METER SQUARE WE INTEND TO USE PERMASOIL**Notice Type:** Registration of Reinstatement - Full**Start:** 13/09/2018 00:00:00**Work Status:** Works Stopped**Issued:** 14/09/2018 08:50:22**Work Type:** EToN 4: Minor**Est. End:** 17/09/2018**Completion:** 13/09/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	ON FOOTWAY OUTSIDE NO ^{pe}	Footway	Up to 1.5 Metres of Cover	0.70	0.70	A Permanent Reinstatement	13/09/2018		13/09/2018	17/09/2018

Works Ref: 0000/00004442332**Version:** 4**Work Desc:** INSTALL NEW MTR AND BBOX DIG IS A METER BY A METER SQUARE WE INTEND TO USE PERMASOIL**Notice Type:** Registration of Reinstatement - Full**Start:** 28/03/2019 00:00:00**Work Status:** Works Stopped**Issued:** 29/03/2019 08:47:35**Work Type:** EToN 4: Minor**Est. End:** 01/04/2019**Completion:** 28/03/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	ROAD OPENING AND DIG IS TAKING PLACE IN FOOTWAY OUTSIDE NUMBER ^{pe}	Footway	Up to 1.5 Metres of Cover	0.60	0.60	A Permanent Reinstatement	28/03/2019		28/03/2019	01/04/2019

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** Severn Trent Integra Utility Services (9103906)**Works Ref:** 0000/00004518043**Version:** 5**Work Desc:** Install external meter in boundary box at depth of under 1.5 meters by Minimum dig with Permanent Reinstatement**Notice Type:** Registration of Reinstatement - Full**Start:** 11/06/2020 00:00:00**Work Status:** Works Stopped**Issued:** 12/06/2020 08:26:22**Work Type:** EToN 4: Minor**Est. End:** 11/06/2020**Completion:** 11/06/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	ON VERGE OUTSIDE NUMBER pe	Verge	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	11/06/2020		11/06/2020	11/06/2020

Works Ref: 0000/00004519597**Version:** 7**Work Desc:** Install external meter in boundary box at depth of under 1.5 meters by Minimum dig with Permanent Reinstatement Install external meter in boundary box at depth of under 1.5 meters by Minimum dig with Permanent Reinstatement**Notice Type:** Registration of Reinstatement - Full**Start:** 23/06/2020 00:00:00**Work Status:** Works Stopped**Issued:** 24/06/2020 07:57:30**Work Type:** EToN 4: Minor**Est. End:** 23/06/2020**Completion:** 23/06/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	ON FOOTWAY OUTSIDE NUMBER pe	Footway	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	23/06/2020		23/06/2020	23/06/2020

Works Ref: 0000-00004676103**Version:** 5**Work Desc:** Install external meter in boundary box at depth of under 1.5 meters by Minimum dig with Permanent Reinstatement**Notice Type:** Registration of Reinstatement - Full**Start:** 12/03/2021 09:20:00**Work Status:** Works Stopped**Issued:** 12/03/2021 10:33:00**Work Type:** EToN 4: Minor**Est. End:** 12/03/2021**Completion:** 12/03/2021

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	ON FOOTWAY OUTSIDE NUMBER per Actual Depth: 0.6	Footway	Up to 1.5 Metres of Cover	0.60	0.60	A Permanent Reinstatement	12/03/2021		12/03/2021	12/03/2021

Organisation: Severn Trent New Connections East - Water (9103920)**Works Ref:** 5101-000006568347**Version:** 10**Work Desc:** * LIGHTHEAD FOR LB9205101-000006548238 Job in Carriageway**Notice Type:** Works Stop**Start:** 17/10/2020 08:12:20**Work Status:** Works Stopped**Issued:** 19/10/2020 14:22:17**Work Type:** EToN 4: Minor**Est. End:** 18/10/2020**Completion:** 18/10/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OPP 193 (Footway, Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	18/10/2020 19:00:00			18/10/2020

Organisation: Severn Trent Waste (9103902)**Works Ref:** 2103/000011874052A**Version:** 4**Work Desc:** Permit Reinstatement REPLACEMENT OF DEFECTIVE MANHOLE FRAME AND COVER IN CARRIAGEWAY Job in Carriageway**Notice Type:** Cancellation**Start:** 10/03/2019 00:00:00**Work Status:** Abandoned Works**Issued:** 08/03/2019 11:31:27**Work Type:** EToN 4: Minor**Est. End:** 10/03/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	ON THE JUNCTION OF LOUGHBOROUGH ROAD AND NOTTINGHAM KNIGHT ISLAND	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	10/03/2019			10/03/2019

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** Severn Trent Waste (9103902)**Works Ref:** 2103/000012313558**Version:** 5**Work Desc:** MH cover In H'way- PROGRAMMED 02/12 WORKS NEEDED TO REPAIR DAMAGED FRAME AND COVER Job in Carriageway (10mm StoneMastic Asphalt)**Notice Type:** Registration of Reinstatement - Full**Start:** 02/12/2019 00:00:00**Work Status:** Works Stopped**Issued:** 02/12/2019 13:01:21**Work Type:** EToN 4: Minor**Est. End:** 02/12/2019**Completion:** 02/12/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	out side the woodlands	Carriageway	Up to 1.5 Metres of Cover	1.90	1.30	A Permanent Reinstatement	02/12/2019		02/12/2019	02/12/2019

Works Ref: 2103/000012458092**Version:** 5**Work Desc:** Trans Std Sew Rep to 225 EMERG 02/06 Urgent excavation required approx 1mtr deep to repair badly displaced joint within the foul pipeline that is restricting flow Job in Footway (Stone Mastic Asphalt)**Notice Type:** Registration of Reinstatement - Full**Start:** 02/06/2020 15:40:00**Work Status:** Works Stopped**Issued:** 05/06/2020 13:22:00**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 08/06/2020**Completion:** 05/06/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	O/S pe LOUGHBOROUGH ROAD	Carriageway	Up to 1.5 Metres of Cover	2.70	1.20	A Permanent Reinstatement	05/06/2020		05/06/2020	08/06/2020

Works Ref: 2103-000012677970A**Version:** 3**Work Desc:** * URGENT REPLACEMENT OF DEFECTIVE MANHOLE FRAME AND COVER**Notice Type:** Registration of Reinstatement - Full**Start:** 11/01/2021 08:30:00**Work Status:** Works Stopped**Issued:** 05/02/2021 11:41:37**Work Type:** EToN 4: Immediate - Emergency**Est. End:** 11/01/2021**Completion:** 11/01/2021

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	ON JUNCTION TO WELBECK ROAD, Actual Depth: 1.5	Carriageway	Up to 1.5 Metres of Cover	1.30	1.30	A Permanent Reinstatement	11/01/2021		11/01/2021	11/01/2021

Organisation: Severn Trent Water East (9103908)**Works Ref:** 1101/000011800994**Version:** 4**Work Desc:** Boundary box Install 25mm Job in Footway (6mm Bitmac (Tarmac))**Notice Type:** Works Stop**Start:** 05/02/2018 00:00:00**Work Status:** Works Stopped**Issued:** 06/02/2018 14:13:05**Work Type:** EToN 4: Minor**Est. End:** 07/02/2018**Completion:** 06/02/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	312	Footway	Up to 1.5 Metres of Cover	1.00	1.00	A Permanent Reinstatement	06/02/2018		06/02/2018	07/02/2018

Works Ref: 1101/000011850563**Version:** 4**Work Desc:** Short Comm pipe Renew 25mm Job in Footway (6mm Bitmac (Tarmac))**Notice Type:** Registration of Reinstatement - Full**Start:** 04/04/2018 00:00:00**Work Status:** Works Stopped**Issued:** 09/04/2018 09:21:27**Work Type:** EToN 4: Minor**Est. End:** 06/04/2018**Completion:** 05/04/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	per LOUGHBOROUGH ROAD, NG2 7EE	Footway	Up to 1.5 Metres of Cover	2.60	1.50	A Permanent Reinstatement	05/04/2018		05/04/2018	06/04/2018

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** Severn Trent Water East (9103908)**Works Ref:** 1101/000011908374**Version:** 3**Work Desc:** Small Main Cut out Piece through 4" Job in Footway (6mm Bitmac (Tarmac))**Notice Type:** Works Stop**Start:** 05/06/2018 21:31:00**Work Status:** Works Stopped**Issued:** 07/06/2018 14:04:00**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 07/06/2018**Completion:** 07/06/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	211	Footway	Up to 1.5 Metres of Cover	3.00	1.30	A Permanent Reinstatement	07/06/2018		07/06/2018	07/06/2018

Works Ref: 1101/000011914693**Version:** 2**Work Desc:** Long Comm pipe Renew 25mm Job in Carriageway (Hot Rolled Asphalt-30/14)**Notice Type:** Cancellation**Start:** 12/08/2018 00:00:00**Work Status:** Abandoned Works**Issued:** 09/08/2018 06:43:22**Work Type:** EToN 4: Minor**Est. End:** 12/08/2018**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	64	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	12/08/2018			12/08/2018

Works Ref: 1101/000011914693A**Version:** 5**Work Desc:** Long Comm pipe Renew 25mm Job in Carriageway (Hot Rolled Asphalt-30/14)**Notice Type:** Registration of Reinstatement - Full**Start:** 07/10/2018 00:00:00**Work Status:** Works Stopped**Issued:** 10/10/2018 14:25:37**Work Type:** EToN 4: Minor**Est. End:** 07/10/2018**Completion:** 08/10/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	pe LOUGHBOROUGH ROAD, NG2 7JJ	Carriageway	Up to 1.5 Metres of Cover	3.00	0.90	A Permanent Reinstatement	08/10/2018		08/10/2018	07/10/2018
2	pe LOUGHBOROUGH ROAD, NG2 7JJ	Footway	Up to 1.5 Metres of Cover	3.20	0.90	A Permanent Reinstatement	08/10/2018		08/10/2018	
3	pe LOUGHBOROUGH ROAD, NG2 7JJ	Footway	Up to 1.5 Metres of Cover	3.00	0.90	A Permanent Reinstatement	08/10/2018		08/10/2018	

Works Ref: 1101/000011922842**Version:** 4**Work Desc:** Small Main Repair Piece <(><<)>=2m 4" Job in Footway (6mm Bitmac (Tarmac))**Notice Type:** Registration of Reinstatement - Full**Start:** 23/06/2018 15:56:00**Work Status:** Works Stopped**Issued:** 02/07/2018 16:02:40**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 27/06/2018**Completion:** 25/06/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	205	Footway	Up to 1.5 Metres of Cover	2.70	1.20	A Permanent Reinstatement	25/06/2018		25/06/2018	27/06/2018

Works Ref: 1101/000011979323**Version:** 4**Work Desc:** Small Main Repair Collar 4" Job in Verge (Grass)**Notice Type:** Registration of Reinstatement - Full**Start:** 03/09/2018 04:08:00**Work Status:** Works Stopped**Issued:** 11/09/2018 10:42:53**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 07/09/2018**Completion:** 07/09/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	per LOUGHBOROUGH ROAD, NG2 7EG	Footway	Up to 1.5 Metres of Cover	1.40	1.20	A Permanent Reinstatement	07/09/2018		07/09/2018	05/09/2018
2	per LOUGHBOROUGH ROAD, NG2 7EG	Verge	Up to 1.5 Metres of Cover	1.20	1.20	A Permanent Reinstatement	07/09/2018		07/09/2018	

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** Severn Trent Water East (9103908)**Works Ref:** 1101/000011985938**Version:** 4**Work Desc:** Short Comm pipe Renew 25mm Job in Footway (6mm Bitmac (Tarmac))**Notice Type:** Registration of Reinstatement - Full**Start:** 11/10/2018 00:00:00**Work Status:** Works Stopped**Issued:** 16/10/2018 22:07:40**Work Type:** EToN 4: Minor**Est. End:** 15/10/2018**Completion:** 15/10/2018

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	per LOUGHBOROUGH ROAD, NG2 7FB	Footway	Up to 1.5 Metres of Cover	1.25	1.10	A Permanent Reinstatement	15/10/2018		15/10/2018	15/10/2018
2	per LOUGHBOROUGH ROAD, NG2 7FB	Verge	Up to 1.5 Metres of Cover	4.00	0.60	A Permanent Reinstatement	15/10/2018		15/10/2018	

Works Ref: 1101/000012128125**Version:** 6**Work Desc:** Boundary box Install,Clear to Boundary Job in Footway (6mm Bitmac (Tarmac))**Notice Type:** Registration of Reinstatement - Full**Start:** 21/05/2019 00:00:00**Work Status:** Works Stopped**Issued:** 23/05/2019 14:50:22**Work Type:** EToN 4: Minor**Est. End:** 23/05/2019**Completion:** 21/05/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	p	Footway	Up to 1.5 Metres of Cover	0.90	0.90	A Permanent Reinstatement	21/05/2019		21/05/2019	23/05/2019
2	p	Footway	Up to 1.5 Metres of Cover	0.90	0.90	A Permanent Reinstatement	21/05/2019		21/05/2019	

Works Ref: 1101/000012164106**Version:** 4**Work Desc:** Boundary box Install,Clear to Boundary Job in Footway (6mm Bitmac (Tarmac))**Notice Type:** Works Stop**Start:** 21/05/2019 00:00:00**Work Status:** Works Stopped**Issued:** 23/05/2019 08:29:13**Work Type:** EToN 4: Minor**Est. End:** 23/05/2019**Completion:** 22/05/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	91	Footway	Up to 1.5 Metres of Cover	0.80	0.80	A Permanent Reinstatement	21/05/2019		21/05/2019	23/05/2019

Works Ref: 1101/000012243694**Version:** 5**Work Desc:** Boundary box Install 25mm Job in Footway (6mm Bitmac (Tarmac))**Notice Type:** Works Stop**Start:** 27/08/2019 00:00:00**Work Status:** Works Stopped**Issued:** 29/08/2019 15:48:25**Work Type:** EToN 4: Minor**Est. End:** 29/08/2019**Completion:** 29/08/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	87	Footway	Up to 1.5 Metres of Cover	1.00	1.00	A Permanent Reinstatement	27/08/2019		27/08/2019	29/08/2019
2	no89	Footway	Up to 1.5 Metres of Cover	1.00	0.70	A Permanent Reinstatement	29/08/2019		29/08/2019	

Works Ref: 1101/000012271810**Version:** 4**Work Desc:** Boundary box Install 25mm Job in Footway (6mm Bitmac (Tarmac))**Notice Type:** Registration of Reinstatement - Full**Start:** 05/11/2019 00:00:00**Work Status:** Works Stopped**Issued:** 07/11/2019 14:00:29**Work Type:** EToN 4: Minor**Est. End:** 07/11/2019**Completion:** 06/11/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	169	Footway	Up to 1.5 Metres of Cover	1.00	0.80	A Permanent Reinstatement	05/11/2019		05/11/2019	07/11/2019

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** Severn Trent Water East (9103908)**Works Ref:** 1101/000012316183**Version:** 4**Work Desc:** Hydrant Rebuild chamber Job in Carriageway (Hot Rolled Asphalt-30/14)**Notice Type:** Registration of Reinstatement - Full**Start:** 27/01/2020 00:00:00**Work Status:** Works Stopped**Issued:** 31/01/2020 14:29:21**Work Type:** EToN 4: Standard**Est. End:** 30/01/2020**Completion:** 28/01/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	57-59	Carriageway	Up to 1.5 Metres of Cover	2.80	1.30 A Permanent Reinstatement	28/01/2020		28/01/2020	30/01/2020

Works Ref: 1101/000060238676**Version:** 3**Work Desc:** Small Main Repair Collar 6" Job in Carriageway (Hot Rolled Asphalt-30/14)**Notice Type:** Registration of Reinstatement - Full**Start:** 14/02/2018 12:01:00**Work Status:** Works Stopped**Issued:** 23/02/2018 15:55:17**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 16/02/2018**Completion:** 21/02/2018

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	per LOUGHBOROUGH RD, NG2 7JB	Footway	Up to 1.5 Metres of Cover	2.50	0.80 A Permanent Reinstatement	21/02/2018		21/02/2018	16/02/2018
2	per LOUGHBOROUGH RD, NG2 7JB	Carriageway	Up to 1.5 Metres of Cover	2.10	0.80 A Permanent Reinstatement	21/02/2018		21/02/2018	

Works Ref: 1101/000060302719**Version:** 2**Work Desc:** Boundary box Install,Clear to Boundary Job in Footway (6mm Bitmac (Tarmac))**Notice Type:** Cancellation**Start:** 04/10/2019 00:00:00**Work Status:** Abandoned Works**Issued:** 07/10/2019 07:22:45**Work Type:** EToN 4: Minor**Est. End:** 04/10/2019**Completion:**

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	181E	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	04/10/2019			04/10/2019

Works Ref: 1101/000060302719A**Version:** 4**Work Desc:** Boundary box Install 25mm Job in Footway (6mm Bitmac (Tarmac))**Notice Type:** Registration of Reinstatement - Full**Start:** 12/11/2019 00:00:00**Work Status:** Works Stopped**Issued:** 14/11/2019 15:28:10**Work Type:** EToN 4: Minor**Est. End:** 14/11/2019**Completion:** 13/11/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	181E	Footway	Up to 1.5 Metres of Cover	1.10	0.80 A Permanent Reinstatement	13/11/2019		13/11/2019	14/11/2019

Works Ref: 1101/000060303747**Version:** 3**Work Desc:** Short Comm Pipe Repair 25mm Job in Footway (6mm Bitmac (Tarmac))**Notice Type:** Registration of Reinstatement - Full**Start:** 12/09/2019 10:28:00**Work Status:** Works Stopped**Issued:** 17/09/2019 19:06:03**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 16/09/2019**Completion:** 13/09/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	per LOUGHBOROUGH RD, NG2 7EG	Footway	Up to 1.5 Metres of Cover	0.80	0.35 A Permanent Reinstatement	13/09/2019		13/09/2019	16/09/2019

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: Severn Trent Water East (9103908)

Works Ref: 1101/000060335128

Version: 2

Work Desc: Small Meter Renew 100mm Stop visible or significant leakage Job in Footway (6mm Bitmac (Tarmac))

Notice Type: Works Stop

Start: 05/05/2020 09:45:00

Work Status: Works Stopped

Issued: 05/05/2020 11:10:49

Work Type: EToN 4: Immediate - Urgent

Est. End: 07/05/2020

Completion: 05/05/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	APP 40m SOUTHEAST OF #181	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	05/05/2020			07/05/2020

Works Ref: 1101-000012450175A

Version: 10

Work Desc: Long Comm Pipe Cut Off 1" Job in Footway (6mm Bitmac (Tarmac))

Notice Type: Registration of Reinstatement - Full

Start: 09/08/2020 08:04:00

Work Status: Works Stopped

Issued: 12/08/2020 10:23:10

Work Type: EToN 4: Minor

Est. End: 09/08/2020

Completion: 09/08/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	283, Actual Depth: 1	Footway	Up to 1.5 Metres of Cover	2.80	1.00	A Permanent Reinstatement	10/08/2020 21:14:50		10/08/2020 21:14:50	09/08/2020

Works Ref: 1101-000012514990

Version: 9

Work Desc: Boundary box Install, Clear to Boundary Job in Footway (6mm Bitmac (Tarmac))

Notice Type: Cancellation

Start: 25/08/2020 10:00:00

Work Status: Abandoned Works

Issued: 27/08/2020 10:07:17

Work Type: EToN 4: Minor

Est. End: 27/08/2020

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE NUMBER [redacted] (Footway, Verge)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	25/08/2020 10:00:00			27/08/2020

Works Ref: 1101-000012659039

Version: 4

Work Desc: HV Boundary box Install 25mm

Notice Type: Registration of Reinstatement - Full

Start: 18/12/2020 11:12:00

Work Status: Works Stopped

Issued: 23/12/2020 13:57:56

Work Type: EToN 4: Immediate - Urgent

Est. End: 21/12/2020

Completion: 21/12/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	[redacted] LOUGHBOROUGH ROAD, NG2 7EG, Actual Depth: 1	Verge	Up to 1.5 Metres of Cover	1.30	1.00	A Permanent Reinstatement	19/12/2020 08:29:50		19/12/2020 08:29:50	21/12/2020

Works Ref: 1101-000012762167

Version: 4

Work Desc: * Small Main Repair Collar 4" * visible burst on main. Footway closure: Alternative route will be provided

Notice Type: Registration of Reinstatement - Full

Start: 09/04/2021 15:07:00

Work Status: Works Stopped

Issued: 19/04/2021 09:35:40

Work Type: EToN 4: Immediate - Urgent

Est. End: 13/04/2021

Completion: 12/04/2021

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	7-12, ETON PLACE, LOUGHBOROUGH ROAD, [redacted], Actual Depth: 1	Footway	Up to 1.5 Metres of Cover	1.40	1.20	A Permanent Reinstatement	12/04/2021 10:59:50		12/04/2021 10:59:50	13/04/2021

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** Severn Trent Water East (9103908)**Works Ref:** 1101-000060365938**Version:** 4**Work Desc:** Small Main Repair Collar 3"**Notice Type:** Registration of Reinstatement - Full**Start:** 04/12/2020 18:45:00**Work Status:** Works Stopped**Issued:** 10/12/2020 13:02:47**Work Type:** EToN 4: Immediate - Urgent**Est. End:** 08/12/2020**Completion:** 07/12/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	CORNER OF FIRE STATION, LOUGHBOROUGH ROAD, personal , Actual Depth: 1	Footway	Up to 1.5 Metres of Cover	1.70	1.00	A Permanent Reinstatement	07/12/2020 11:25:50		07/12/2020 11:25:50	08/12/2020

Organisation: SEVERN TRENT WATER: Construction Delivery and Com... (9103528)**Works Ref:** A7W-12757005Z**Version:** 3**Work Desc:** 7x Trial hole 1.5x1.5 in footway and carriageway to check ground conditions and locations of underground utilities to confirm technique for possible Serviceability burst mains renewals**Notice Type:** Cancellation**Start:** 13/07/2020 08:00:00**Work Status:** Abandoned Works**Issued:** 24/08/2020 17:04:26**Work Type:** EToN 4: Minor**Est. End:** 15/07/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside pe Opposite pe Outside pe Opposite pe Outside per (Footway, Carriageway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	13/07/2020 08:00:00			15/07/2020

Works Ref: A7W-12757017Z**Version:** 5**Work Desc:** 6x Trial hole 1.5x1.5 in footway and 1x carriageway to check ground conditions and locations of underground utilities to confirm technique for possible Serviceability burst mains renewals**Notice Type:** Cancellation**Start:** 13/07/2020 07:00:00**Work Status:** Abandoned Works**Issued:** 24/08/2020 17:03:53**Work Type:** EToN 4: Minor**Est. End:** 15/07/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside pe Opposite pe Outside pe Opposite pe Outside per Outside 2 (Footway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	13/07/2020 07:00:00			15/07/2020

Works Ref: A7W-12757019Z**Version:** 10**Work Desc:** 1x Trial hole 1.5x1.5 in carriageway and 6x trial hole 1.5x1.5 in footway to check ground conditions and locations of underground utilities to confirm technique for possible Serviceability burst mains renewals**Notice Type:** Registration of Reinstatement - Full**Start:** 27/07/2020 15:00:00**Work Status:** Works Stopped**Issued:** 04/08/2020 14:43:23**Work Type:** EToN 4: Standard**Est. End:** 31/07/2020**Completion:** 31/07/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside pe (Carriageway, Footway), Actual Depth: 1.2	Carriageway	Up to 1.5 Metres of Cover	2.10	0.75	A Permanent Reinstatement	31/07/2020		31/07/2020	31/07/2020
2	Outside per Actual Depth: 1.2	Footway	Up to 1.5 Metres of Cover	2.20	0.90	A Permanent Reinstatement	31/07/2020		31/07/2020	
3	Opp per Actual Depth: 1.2	Footway	Up to 1.5 Metres of Cover	1.75	0.75	A Permanent Reinstatement	31/07/2020		31/07/2020	
4	Outside per Actual Depth: 1.2	Footway	Up to 1.5 Metres of Cover	1.70	0.85	A Permanent Reinstatement	31/07/2020		31/07/2020	
5	Outside per Actual Depth: 1.2	Verge	Up to 1.5 Metres of Cover	1.50	0.80	A Permanent Reinstatement	31/07/2020		31/07/2020	
6	Outside per Actual Depth: 1.2	Footway	Up to 1.5 Metres of Cover	2.00	0.70	A Permanent Reinstatement	31/07/2020		31/07/2020	

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices**Organisation:** Virgin Media - North Midland Construction (7160106)**Works Ref:** EMID166201A**Version:** 5**Work Desc:** Excavate in footway to locate tee - If none found install new tee**Notice Type:** Registration of Reinstatement - Full**Start:** 06/08/2020 10:55:00**Work Status:** Works Stopped**Issued:** 06/08/2020 12:08:41**Work Type:** EToN 4: Minor**Est. End:** 10/08/2020**Completion:** 06/08/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Rear of Kensal Court, Actual Depth: 1	Footway	Up to 1.5 Metres of Cover	1.00	0.50	A Permanent Reinstatement	06/08/2020		06/08/2020	10/08/2020

Works Ref: EMID186267A**Version:** 6**Work Desc:** Excavate in footway / verge to locate tee ? If none found install new tee**Notice Type:** Registration of Reinstatement - Full**Start:** 25/09/2020 12:55:00**Work Status:** Works Stopped**Issued:** 25/09/2020 14:21:31**Work Type:** EToN 4: Minor**Est. End:** 29/09/2020**Completion:** 25/09/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside number pe Actual Depth: 1	Footway	Up to 1.5 Metres of Cover	0.30	0.30	A Permanent Reinstatement	25/09/2020		25/09/2020	29/09/2020

Works Ref: EMID223197A**Version:** 7**Work Desc:** Excavate in footway to locate tee ? If none found install new tee**Notice Type:** Registration of Reinstatement - Full**Start:** 07/12/2020 08:54:00**Work Status:** Works Stopped**Issued:** 07/12/2020 09:44:37**Work Type:** EToN 4: Minor**Est. End:** 09/12/2020**Completion:** 07/12/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside number pe Actual Depth: 1	Footway	Up to 1.5 Metres of Cover	0.50	0.28	A Permanent Reinstatement	07/12/2020		07/12/2020	09/12/2020

Organisation: WPD 5154 Keyworth (7011554)**Works Ref:** 2222199**Version:** 2**Work Desc:** 1 joint hole in tarmac footway for reconnection of supply to streetlight LC139.**Notice Type:** Cancellation**Start:** 24/07/2020 00:00:00**Work Status:** Abandoned Works**Issued:** 20/07/2020 14:46:57**Work Type:** EToN 4: Minor**Est. End:** 26/07/2020**Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Opposite 410 (Footpath)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	24/07/2020			26/07/2020

Works Ref: 2223596**Version:** 12**Work Desc:** 1 joint hole in tarmac footway for streetlamp fault repair on LC139.**Notice Type:** Registration of Reinstatement - Full**Start:** 17/08/2020 10:41:00**Work Status:** Works Stopped**Issued:** 24/08/2020 13:36:20**Work Type:** EToN 4: Minor**Est. End:** 19/08/2020**Completion:** 19/08/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	opposite 410, Actual Depth: 0.3	Verge	Up to 1.5 Metres of Cover	2.00	1.50	A Permanent Reinstatement	19/08/2020		19/08/2020	19/08/2020

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: WPD 5154 Keyworth (7011554)

Works Ref: 2224332C

Notice Type: Cancellation

Work Status: Abandoned Works

Work Type: EToN 4: Minor

Version: 11

Start: 15/08/2020 00:00:00

Issued: 18/08/2020 14:17:16

Est. End: 17/08/2020

Work Desc: Traffic light head only - no excavation, This has to be done in conjunction with DY5542224332A through to DY5542224332C.

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside Numbers person (Footway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	15/08/2020			17/08/2020

Works Ref: 2231226C

Notice Type: Works Stop

Work Status: Works Stopped

Work Type: EToN 4: Minor

Version: 6

Start: 22/08/2020 09:00:00

Issued: 25/08/2020 08:01:01

Est. End: 24/08/2020

Work Desc: Traffic light head only - no excavation to be done in conjunction with DY5542231226A to C Ref SO 170820

Completion: 24/08/2020

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside pe (Footway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	24/08/2020 22:10:00			24/08/2020

Works Ref: 2260593A

Notice Type: Registration of Reinstatement - Full

Work Status: Works Stopped

Work Type: EToN 4: Major

Version: 9

Start: 04/03/2021 13:52:00

Issued: 11/03/2021 11:21:58

Est. End: 05/03/2021

Work Desc: 1 joint hole in tarmac footway for disconnection of supply. In conjunction with DY5542260593BCD

Completion: 05/03/2021

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Opposite Labrador., Actual Depth: 0.6	Verge	Up to 1.5 Metres of Cover	2.00	1.00	A Permanent Reinstatement	05/03/2021		05/03/2021	05/03/2021

Works Ref: 2278573

Notice Type: Registration of Reinstatement - Full

Work Status: Works Stopped

Work Type: EToN 4: Standard

Version: 11

Start: 01/03/2021 06:43:00

Issued: 17/03/2021 10:19:26

Est. End: 12/03/2021

Work Desc: 3 joint holes in tarmac footway for new supply, new substation

Completion: 12/03/2021

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE TESLA UK per LOUGHBOROUGH ROAD, NOTTINGHAM, Actual Depth: 0.9	Footway	Up to 1.5 Metres of Cover	4.50	0.80	A Permanent Reinstatement	12/03/2021		12/03/2021	12/03/2021
2	OUTSIDE TESLA UK pers LOUGHBOROUGH ROAD, NOTTINGHAM, Actual Depth: 0.8	Carriageway	Up to 1.5 Metres of Cover	1.50	1.00	A Permanent Reinstatement	12/03/2021		12/03/2021	
3	OUTSIDE TESLA UK pers LOUGHBOROUGH ROAD, NOTTINGHAM, Actual Depth: 0.9	Footway	Up to 1.5 Metres of Cover	4.50	1.50	A Permanent Reinstatement	12/03/2021		12/03/2021	
4	OUTSIDE TESLA UK per LOUGHBOROUGH ROAD, NOTTINGHAM, Actual Depth: 0.9	Footway	Up to 1.5 Metres of Cover	4.50	1.20	A Permanent Reinstatement	12/03/2021		12/03/2021	
5	OUTSIDE TESLA UK per LOUGHBOROUGH ROAD, NOTTINGHAM, Actual Depth: 0.6	Footway	Up to 1.5 Metres of Cover	8.00	0.50	A Permanent Reinstatement	12/03/2021		12/03/2021	
6	OUTSIDE TESLA UK pers LOUGHBOROUGH ROAD, NOTTINGHAM, Actual Depth: 0.9	Carriageway	Up to 1.5 Metres of Cover	3.50	0.50	A Permanent Reinstatement	12/03/2021		12/03/2021	

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: WPD 5154 Keyworth (7011554)

Works Ref: 2278573

Version: 11

Work Desc: 3 joint holes in tarmac footway for new supply, new substation

Notice Type: Registration of Reinstatement - Full

Start: 01/03/2021 06:43:00

Work Status: Works Stopped

Issued: 17/03/2021 10:19:26

Work Type: EToN 4: Standard

Est. End: 12/03/2021

Completion: 12/03/2021

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
7	OUTSIDE TESLA UKper , LOUGHBOROUGH ROAD, NOTTINGHAM, Actual Depth: 0.8	Carriageway	Up to 1.5 Metres of Cover	5.00	1.00 A Permanent Reinstatement	12/03/2021		12/03/2021	

Works Ref: 9509717

Version: 8

Work Desc: Urgent excavation in highway to locate and repair LV cable fault..
Footway closure: Pedestrian walkway will be provided

Notice Type: Registration of Reinstatement - Full

Start: 22/03/2021 14:10:00

Work Status: Works Stopped

Issued: 30/03/2021 08:25:13

Work Type: EToN 4: Immediate - Urgent

Est. End: 26/03/2021

Completion: 24/03/2021

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside number pe Actual Depth: 0.7	Footway	Up to 1.5 Metres of Cover	7.00	2.10 A Permanent Reinstatement	24/03/2021		24/03/2021	26/03/2021

Works Ref: 9520075B

Version: 3

Work Desc: Urgent excavation in highway to locate and repair LV cable fault.

Notice Type: Works Stop

Start: 17/03/2021 11:00:00

Work Status: Works Stopped

Issued: 22/03/2021 15:09:16

Work Type: EToN 4: Immediate - Urgent

Est. End: 23/03/2021

Completion: 22/03/2021

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	NEAR JUNCTION (Footway)	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	22/03/2021 14:43:00			23/03/2021

Works Ref: 9521141

Version: 4

Work Desc: Urgent excavation in highway to locate and repair street light cable fault.

Notice Type: Registration of Reinstatement - Full

Start: 20/11/2020 00:45:00

Work Status: Works Stopped

Issued: 02/12/2020 11:52:26

Work Type: EToN 4: Immediate - Urgent

Est. End: 25/11/2020

Completion: 22/11/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside number p Actual Depth: 0.3	Footway	Up to 1.5 Metres of Cover	0.80	0.70 A Permanent Reinstatement	21/11/2020		21/11/2020	25/11/2020

Works Ref: M51540494091

Version: 3

Work Desc: Urgent excavation in highway to locate and repair LV cable fault.

Notice Type: Registration of Reinstatement - Full

Start: 08/02/2019 17:00:00

Work Status: Works Stopped

Issued: 21/02/2019 11:17:25

Work Type: EToN 4: Immediate - Urgent

Est. End: 14/02/2019

Completion: 14/02/2019

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	outside pe	Footway	Up to 1.5 Metres of Cover	5.50	1.00 A Permanent Reinstatement	14/02/2019		14/02/2019	14/02/2019

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: WPD 5154 Keyworth (7011554)

Works Ref: M51542075909

Version: 2

Work Desc: 1 joint hole in tarmac footway for reconnection of supply to dead streetlight

Notice Type: Cancellation

Start: 28/09/2018 00:00:00

Work Status: Abandoned Works

Issued: 28/09/2018 11:04:42

Work Type: EToN 4: Standard

Est. End: 04/10/2018

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Adjacent Nottingham Volkswagen	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	28/09/2018			04/10/2018

Works Ref: M51542093856

Version: 5

Work Desc: 2 joint holes in tarmac footway for supply alteration

Notice Type: Registration of Reinstatement - Full

Start: 14/01/2019 00:00:00

Work Status: Works Stopped

Issued: 01/02/2019 11:21:59

Work Type: EToN 4: Standard

Est. End: 18/01/2019

Completion: 18/01/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE THE WOLDS PUB	Footway	Up to 1.5 Metres of Cover	2.00	2.00	A Permanent Reinstatement	18/02/2019		18/02/2019	18/01/2019

Works Ref: M51542122706

Version: 2

Work Desc: 1 joint hole in tarmac footway and 32m trenching in modular footway for new supply

Notice Type: Cancellation

Start: 20/05/2019 00:00:00

Work Status: Abandoned Works

Issued: 21/05/2019 13:52:36

Work Type: EToN 4: Standard

Est. End: 26/05/2019

Completion:

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	SIDE OF COUNTY HALL	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Abandoned	20/05/2019			26/05/2019

Works Ref: M51542129479

Version: 6

Work Desc: 1 joint hole in tarmac footway for new supply to electric vehicle charger

Notice Type: Registration of Reinstatement - Full

Start: 04/07/2019 00:00:00

Work Status: Works Stopped

Issued: 17/07/2019 14:53:48

Work Type: EToN 4: Standard

Est. End: 15/07/2019

Completion: 15/07/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE COUNTY HALL	Footway	Up to 1.5 Metres of Cover	3.20	1.00	A Permanent Reinstatement	15/07/2019		15/07/2019	10/07/2019
2	OUTSIDE COUNTY HALL	Footway	Up to 1.5 Metres of Cover	12.00	0.60	A Permanent Reinstatement	15/07/2019		15/07/2019	

Works Ref: M51542145346

Version: 5

Work Desc: 1 joint hole in tarmac footway for street light cable fault repair.

Notice Type: Registration of Reinstatement - Full

Start: 02/09/2019 00:00:00

Work Status: Works Stopped

Issued: 18/09/2019 12:21:14

Work Type: EToN 4: Standard

Est. End: 06/09/2019

Completion: 06/09/2019

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Outside	Footway	Up to 1.5 Metres of Cover	1.50	0.80	A Permanent Reinstatement	06/09/2019		06/09/2019	06/09/2019
2	Outside	Footway	Up to 1.5 Metres of Cover	2.00	0.40	A Permanent Reinstatement	06/09/2019		06/09/2019	

Effective: 01/01/2018 to 22/04/2021

Feature No.: 2001.00 to 2001.00

Display Action Officer: Yes

Street: Loughborough Road (33001159)

Street Works Notices

Organisation: WPD 5154 Keyworth (7011554)

Works Ref: M51542175540 **Version:** 4 **Work Desc:** 1 joint hole in tarmac footway for reconnection of supply
Notice Type: Registration of Reinstatement - Full **Start:** 09/01/2020 00:00:00
Work Status: Works Stopped **Issued:** 15/01/2020 14:49:49
Work Type: EToN 4: Standard **Est. End:** 16/01/2020 **Completion:** 13/01/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Outside 303	Footway	Up to 1.5 Metres of Cover	1.70	1.20 A Permanent Reinstatement	13/01/2020		13/01/2020	16/01/2020

Works Ref: M51542193128 **Version:** 4 **Work Desc:** 1 joint hole in tarmac footway for disconnection of supply
Notice Type: Registration of Reinstatement - Full **Start:** 10/03/2020 00:00:00
Work Status: Works Stopped **Issued:** 23/03/2020 13:11:35
Work Type: EToN 4: Minor **Est. End:** 12/03/2020 **Completion:** 12/03/2020

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	OUTSIDE pe	Verge	Up to 1.5 Metres of Cover	1.50	1.00 A Permanent Reinstatement	12/03/2020		12/03/2020	12/03/2020