


Photograph B
Taken in the underpass looking north, showing the soil mound that blocks the northern entrance of the underpass. Photograph taken in 2008



Photograph A
Taken in the underpass looking north, showing the northern entrance of the underpass. Photograph taken in 2006

