

Effective: 09/01/2017 to 09/01/2018  
Street: Main Road (26813983)

Display Action Officer: No

Street: Main Road (26813983)

Locality: Averham, Nottinghamshire

Area: Newark

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 1,000.00	<b>Feature Id - Locn.:</b> 3225C - West Of Averham Schools, Averham			<b>Feature Type:</b> Culvert (Spans 1m to 3m)			<b>Area:</b> Newark	
<b>Batch:</b> 105037 - Inspection Batch			<b>Route:</b> 2016 Newark Culverts				<b>Date:</b> 11/07/2017	
No actionable defects found								
<b>Feat No.:</b> 1,000.01	<b>Feature Id - Locn.:</b> 3225C/1/1 - West Of Averham Schools, Averham/1/1			<b>Feature Type:</b> Spans			<b>Area:</b> Newark	
<b>Batch:</b> 105038 - Inspection Batch			<b>Route:</b> 2016 Newark Culverts				<b>Date:</b> 11/07/2017	
No actionable defects found								
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> A617 - Main Road (435M North-East Of Stream Crossing) To Mi			<b>Feature Type:</b> Street Section			<b>Area:</b> Newark	
<b>Batch:</b> 20261752 - Inspection Batch			<b>Route:</b> Newark Area 2 Jan Saf CW				<b>Date:</b> 08/01/2018	
3563216	potholes	08/01/2018	near lc no 96 marked	CW Repairs-Bituminous	Internal		Committed	2666113
3563215	pothole	08/01/2018	opps lc no 69 in center of road marked	CW Repairs-Bituminous	Internal		Committed	2666112
3563217	pothole	08/01/2018	opps lc no 66 next to t lights marked	CW Repairs-Bituminous	Internal		Committed	2666110
3563214	potholes	08/01/2018	opps lc no 62 marked	CW Repairs-Bituminous	Internal		Committed	2666111
<b>Batch:</b> 20258316 - Inspection Batch			<b>Route:</b> Newark Area 2 Dec Saf CW				<b>Date:</b> 07/12/2017	
No actionable defects found								
<b>Batch:</b> 20254187 - Inspection Batch			<b>Route:</b> Newark Area 2 Nov Enh CW/FW				<b>Date:</b> 09/11/2017	
No actionable defects found								
<b>Batch:</b> 20248792 - Inspection Batch			<b>Route:</b> Newark Area 2 Oct Saf CW				<b>Date:</b> 05/10/2017	
No actionable defects found								
<b>Batch:</b> 20246169 - Inspection Batch			<b>Route:</b> Newark Area 2 Sep Saf CW				<b>Date:</b> 18/09/2017	
3555396		18/09/2017	in between lc no 61 and 62 marked	CW Repairs-Bituminous	Internal		Committed	2657912
<b>Batch:</b> 20241681 - Inspection Batch			<b>Route:</b> Newark Area 2 Aug Saf CW				<b>Date:</b> 15/08/2017	
No actionable defects found								
<b>Batch:</b> 20239148 - Inspection Batch			<b>Route:</b> Newark Area 2 Jul Saf CW				<b>Date:</b> 24/07/2017	
No actionable defects found								
<b>Batch:</b> 20233818 - Inspection Batch			<b>Route:</b> Newark Area 2 Jun Saf CW				<b>Date:</b> 13/06/2017	
No actionable defects found								
<b>Batch:</b> 20229122 - Inspection Batch			<b>Route:</b> Newark Area 2 May Saf CW				<b>Date:</b> 09/05/2017	
No actionable defects found								
<b>Batch:</b> 20225951 - Inspection Batch			<b>Route:</b> Newark Area 2 Apr Saf CW				<b>Date:</b> 20/04/2017	
3546867	potholes	20/04/2017	nr lc 61	CW Repairs-Bituminous	Internal		Uncommitt	2648699
<b>Batch:</b> 20219577 - Inspection Batch			<b>Route:</b> Newark Area 2 Mar Saf CW				<b>Date:</b> 03/03/2017	
No actionable defects found								
<b>Batch:</b> 20216003 - Inspection Batch			<b>Route:</b> Newark Area 2 Feb Saf CW				<b>Date:</b> 09/02/2017	
No actionable defects found								
<b>Batch:</b> 20211423 - Inspection Batch			<b>Route:</b> Newark Area 2 Jan Saf CW				<b>Date:</b> 09/01/2017	
No actionable defects found								

Effective: 09/01/2017 to 09/01/2018  
Street: Main Road (26813983)

Display Action Officer: No

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,001.00	<b>Feature Id - Locn.:</b> Lay-By Past Junction With A612 - Averham			<b>Feature Type:</b> Layby - Separated			<b>Area:</b> Newark	
<b>Batch:</b> 20254182 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 2 Nov Enh CW/FW				<b>Date:</b> 09/11/2017
<b>Feat No.:</b> 2,020.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Layby - Integrated			<b>Area:</b> Newark	
<b>Batch:</b> 20261762 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 2 Jan Saf CW				<b>Date:</b> 08/01/2018
<b>Batch:</b> 20255190 - Inspection Batch	No actionable defects found			<b>Route:</b> Newark Area 2 Nov Enh CW/FW				<b>Date:</b> 15/11/2017
<b>Feat No.:</b> 4,053.00	<b>Feature Id - Locn.:</b> 93 - Main Road A 617			<b>Feature Type:</b> Column			<b>Area:</b> Newark	
<b>Batch:</b> 20663014 - Ad Hoc Inspection Batch				<b>Route:</b> Ad Hoc SL Countywide				<b>Date:</b> 05/12/2017
20626660 out.		05/12/2017		SL- (Night Patrol) Column Out	Internal		Committed	3629341
<b>Feat No.:</b> 4,055.00	<b>Feature Id - Locn.:</b> 95 - Main Road A 617			<b>Feature Type:</b> Column			<b>Area:</b> Newark	
<b>Batch:</b> 20663015 - Ad Hoc Inspection Batch				<b>Route:</b> Ad Hoc SL Countywide				<b>Date:</b> 05/12/2017
20626661 out.		05/12/2017		SL- (Night Patrol) Column Out	Internal		Committed	3629342
<b>Feat No.:</b> 4,057.00	<b>Feature Id - Locn.:</b> 97 - Main Road A 617			<b>Feature Type:</b> Column			<b>Area:</b> Newark	
<b>Batch:</b> 20663016 - Ad Hoc Inspection Batch				<b>Route:</b> Ad Hoc SL Countywide				<b>Date:</b> 05/12/2017
20626662 out.		05/12/2017		SL- (Night Patrol) Column Out	Internal		Committed	3629343
<b>Feat No.:</b> 4,059.00	<b>Feature Id - Locn.:</b> 99 - Main Road A 617			<b>Feature Type:</b> Column			<b>Area:</b> Newark	
<b>Batch:</b> 20663017 - Ad Hoc Inspection Batch				<b>Route:</b> Ad Hoc SL Countywide				<b>Date:</b> 05/12/2017
20626663 out.		05/12/2017		SL- (Night Patrol) Column Out	Internal		Committed	3629344
<b>Feat No.:</b> 4,061.00	<b>Feature Id - Locn.:</b> 101 - Main Road A 617			<b>Feature Type:</b> Column			<b>Area:</b> Newark	
<b>Batch:</b> 20663018 - Ad Hoc Inspection Batch				<b>Route:</b> Ad Hoc SL Countywide				<b>Date:</b> 05/12/2017
20626664 out.		05/12/2017		SL- (Night Patrol) Column Out	Internal		Committed	3629345
<b>Feat No.:</b> 4,602.00	<b>Feature Id - Locn.:</b> S12 - nr LC 68			<b>Feature Type:</b> Refuge Beacon			<b>Area:</b> Newark	
<b>Batch:</b> 20642233 - Ad Hoc Inspection Batch				<b>Route:</b> Ad Hoc SL Countywide				<b>Date:</b> 04/04/2017
20617438 out		04/04/2017		SL- (Night Patrol) Sign Out	Internal		Unactioned	
<b>Feat No.:</b> 4,603.00	<b>Feature Id - Locn.:</b> nr LC 66			<b>Feature Type:</b> Refuge Beacon			<b>Area:</b> Newark	
<b>Batch:</b> 20652797 - Inspection Batch	No actionable defects found			<b>Route:</b> Hammer Test				<b>Date:</b> 13/07/2017
<b>Feat No.:</b> 4,606.00	<b>Feature Id - Locn.:</b> S18 - nr LC 60			<b>Feature Type:</b> Refuge Beacon			<b>Area:</b> Newark	
<b>Batch:</b> 20664564 - Ad Hoc Inspection Batch				<b>Route:</b> Ad Hoc SL Countywide				<b>Date:</b> 03/01/2018
20627680 stem out		03/01/2018		SL- (Night Patrol) Sign Out	Internal		Committed	3630474
<b>Batch:</b> 20663030 - Ad Hoc Inspection Batch				<b>Route:</b> Ad Hoc SL Countywide				<b>Date:</b> 05/12/2017
20626675 stem globe out.		05/12/2017		SL- (Night Patrol) Sign Out	Internal		Committed	3629356
<b>Feat No.:</b> 4,805.00	<b>Feature Id - Locn.:</b> B17 nr LC 60			<b>Feature Type:</b> Bollard			<b>Area:</b> Newark	
<b>Batch:</b> 20645227 - Ad Hoc Inspection Batch				<b>Route:</b> Ad Hoc SL Countywide				<b>Date:</b> 03/05/2017
20618443 ASAP OUT & LOOSE ON BASE		03/05/2017		SL- (Night Patrol) Bollard Out	Internal		Committed	3620200

Effective: 09/01/2017 to 09/01/2018  
Street: Main Road (26813983)

Display Action Officer: No

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 8,000.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,002.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 25/08/2017
<b>Feat No.:</b> 8,003.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 25/08/2017
<b>Feat No.:</b> 8,004.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 25/08/2017
<b>Feat No.:</b> 8,005.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 25/08/2017
<b>Feat No.:</b> 8,006.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 25/08/2017
<b>Feat No.:</b> 8,007.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 25/08/2017
<b>Feat No.:</b> 8,009.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,010.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,012.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,014.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,015.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017

Effective: 09/01/2017 to 09/01/2018  
Street: Main Road (26813983)

Display Action Officer: No

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 8,016.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,017.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,018.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,019.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,020.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,021.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,022.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,023.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000269 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/02/2017
<b>Feat No.:</b> 8,028.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,029.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,030.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,031.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017

Effective: 09/01/2017 to 09/01/2018  
Street: Main Road (26813983)

Display Action Officer: No

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 8,032.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,033.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,034.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,035.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,036.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,037.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,038.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,039.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,040.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,041.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,042.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,043.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017

Effective: 09/01/2017 to 09/01/2018  
Street: Main Road (26813983)

Display Action Officer: No

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 8,044.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,045.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,047.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 25/08/2017
<b>Feat No.:</b> 8,048.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Batch:</b> 10000269 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/02/2017
<b>Feat No.:</b> 8,049.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Batch:</b> 10000269 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/02/2017
<b>Feat No.:</b> 8,050.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,051.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,052.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,053.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,055.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,057.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017

Effective: 09/01/2017 to 09/01/2018  
Street: Main Road (26813983)

Display Action Officer: No

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 8,059.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,061.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,063.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,065.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,067.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,069.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,071.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,073.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,075.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,077.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,079.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,081.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017

Effective: 09/01/2017 to 09/01/2018  
Street: Main Road (26813983)

Display Action Officer: No

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 8,083.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,085.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,087.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,089.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,091.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,093.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,096.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,097.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,099.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,101.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,103.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,105.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017



Effective: 09/01/2017 to 09/01/2018  
Street: Main Road (26813983)

Display Action Officer: No

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 8,107.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,109.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,111.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,112.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,113.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,114.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,115.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,116.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,117.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,118.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000338 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,119.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Offlet			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Feat No.:</b> 8,122.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017

Effective: 09/01/2017 to 09/01/2018  
Street: Main Road (26813983)

Display Action Officer: No

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 8,122.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000269 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/02/2017
<b>Feat No.:</b> 8,123.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Batch:</b> 10000269 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/02/2017
<b>Feat No.:</b> 8,124.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Gully			<b>Area:</b> Newark	
<b>Batch:</b> 10000334 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 23/08/2017
<b>Batch:</b> 10000269 - Ad Hoc Inspection	No actionable defects found			<b>Route:</b> Ad Hoc Inspection				<b>Date:</b> 21/02/2017

### Customer Services

**Enquiry No.:** 6059812      **Logged by:** External to Confirm      **on:** 28/07/2017 16:17  
**Service:** Trees/Verges      **Subject:** Grass Cutting      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-56607161  
**Desc.:** Overgrown grass and verges - A617 From Averham to Newark there is a Cycle Path and also used for pedestrians which runs parallel with A617 From Averham Bend for approx 1 mile and again after Kelham bridge for approx 200 mtrs

Grass is taking over the path way and making it very narrow and getting too close to the road.

the hedge way is only a little overgrown but the main problem is the grass!!

. Submitted by Advisor: [REDACTED] TP

**Location:** See map coordinates and description details

**Contact:**

**Enquiry No.:** 6049619      **Logged by:** External to Confirm      **on:** 07/04/2017 16:07  
**Service:** Carriageway/Footway      **Subject:** Carriageway Damage      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-50803531  
**Desc.:** Road Damage - A 617 Road damage causing severe vibration to my house when lorries pass . Online report  
**Location:** See map coordinates and description details

**Contact:**

**Plot Number:** 2,000.00      **Feature Id - Location:** A617 - Main Road ([REDACTED] TP [REDACTED]) To Mi      **Feature Type:** Street Section  
**Job Number:** 2648699      **Defect Number:** 3546867

**Enquiry No.:** 6047718      **Logged by:** External to Confirm      **on:** 22/03/2017 09:28  
**Service:** Carriageway/Footway      **Subject:** St Furn/Non Illum Sign Damage      **Classification:** Report or Observation      **Enquiry Ref:** FS-CASE-50215430  
**Desc.:** Street/road sign damage - The sign is a big square sign that is in two peices. The sign was first damaged in storm Doris, which at first it was just loose but the subsequent weather we've had recently has caused the sign to totally break away from the post it was located on but thankfully it has fallen into a hedge. However the other half of is now loose and could potentially blow into the road. It is just outside the gateway to [REDACTED] TP [REDACTED] Submitted by Advisor: [REDACTED] TP

**Location:** See map coordinates and description details

**Contact:**

**Plot Number:** 3,510.00      **Feature Id - Location:** 50mph Speed Kills Sign      **Feature Type:** Non-Illum Sign - 2 Posts  
**Job Number:** 3618605

Effective: 09/01/2017 to 09/01/2018  
 Street: Main Road (26813983)

Display Action Officer: No

**Customer Services**

Enquiry No.: 6045778      Logged by: External to Confirm      on: 06/03/2017 22:54  
 Service: Carriageway/Footway      Subject: St Furn/Non Illum Sign Damage      Classification: Report or Observation      Enquiry Ref: FS-CASE-13726201  
 Desc.: Street/road sign damage - chevron sign damaged, out of line. . Online report  
 Location: See map coordinates and description details      Contact:

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b> A617 - Main Road	<b>TP</b>	To Mi	<b>Feature Type:</b> Street Section	<b>Area:</b> Newark		
2648699	potholes (CW Repairs-Bituminous)	nr lc 61	Filled when found (Cat 2L)	Job Completed	20/04/2017	20/04/2017	Act.
2657912	CW Repairs-Bituminous	in between lc no 61 and 62 marked	Category 2 (Low)	Job Completed	18/09/2017	19/09/2017	Act. NEW-AS/5503821
2666110	pothole (CW Repairs-Bituminous)	opps lc no 66 next to t lights marked	Category 2 (High)	Job Completed	08/01/2018	09/01/2018	Act. NEW-AS/5504444
2666111	potholes (CW Repairs-Bituminous)	opps lc no 62 marked	Category 2 (Low)	Job Completed	08/01/2018	09/01/2018	Act. NEW-AS/5504445
2666112	pothole (CW Repairs-Bituminous)	opps lc no 69 in center of road marked	Category 2 (Low)	Job Completed	08/01/2018	09/01/2018	Act. NEW-AS/5504446
2666113	potholes (CW Repairs-Bituminous)	near lc no 96 marked	Category 2 (Low)	Job Completed	08/01/2018	09/01/2018	Act. NEW-AS/5504447
<b>Feat No.:</b> 3,510.00	<b>Feature Id - Locn.:</b> 50mph Speed Kills Sign	<b>Feature Type:</b> Non-Illum Sign - 2 Posts			<b>Area:</b> Newark		
3618605	****Repair sign, Sign plate is on site and requires Pop Riviting all the sign rails back in situ. ALSO, the post is in a sleeve and requires some wedges or packing to straighten it back up...no digging required.... ***see pictures. TOWER REQUIRED..... Furn/Non Illum Sign Damage - Street/road sign damage - The sign is a big square sign that is in two peices. The sign was first damaged in storm Doris, which at first it was just loose but the subsequent weather we've had recently has caused the sign to totally break away from the post it was located on but thankfully it has fallen into a hedge. However the other half of is now loose and could potentially blow into the road. It is just outside the gateway to <b>TP</b> <b>TP</b> Submitted by Advisor: <b>TP</b> (Enquiry 6047718)	See map coordinates and description details	SL- 30 Days	Job Completed	22/03/2017	19/04/2017	Act. SLNE/12003599

Effective: 09/01/2017 to 09/01/2018  
Street: Main Road (26813983)

Display Action Officer: No

### Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Feat No.:</b> 4,053.00	<b>Feature Id - Locn.:</b> 93 - Main Road A 617		<b>Feature Type:</b> Column		<b>Area:</b> Newark	
3629341	out. (SL- (Night Patrol) Column Out)		SL - 7 Days	Job Completed	05/12/2017	06/12/2017	Act. SLNE/12005221
	<b>Feat No.:</b> 4,055.00	<b>Feature Id - Locn.:</b> 95 - Main Road A 617		<b>Feature Type:</b> Column		<b>Area:</b> Newark	
3629342	out. (SL- (Night Patrol) Column Out)		SL - 7 Days	Job Completed	05/12/2017	06/12/2017	Act. SLNE/12005222
	<b>Feat No.:</b> 4,057.00	<b>Feature Id - Locn.:</b> 97 - Main Road A 617		<b>Feature Type:</b> Column		<b>Area:</b> Newark	
3629343	out. (SL- (Night Patrol) Column Out)		SL - 7 Days	Job Completed	05/12/2017	06/12/2017	Act. SLNE/12005223
	<b>Feat No.:</b> 4,059.00	<b>Feature Id - Locn.:</b> 99 - Main Road A 617		<b>Feature Type:</b> Column		<b>Area:</b> Newark	
3629344	out. (SL- (Night Patrol) Column Out)		SL - 7 Days	Job Completed	05/12/2017	08/12/2014	Act. SLNE/12005224
	<b>Feat No.:</b> 4,061.00	<b>Feature Id - Locn.:</b> 101 - Main Road A 617		<b>Feature Type:</b> Column		<b>Area:</b> Newark	
3629345	out. (SL- (Night Patrol) Column Out)		SL - 7 Days	Job Completed	05/12/2017	06/12/2017	Act. SLNE/12005225
	<b>Feat No.:</b> 4,600.00	<b>Feature Id - Locn.:</b> S10 - NEAR L/C 85		<b>Feature Type:</b> Lit Sign		<b>Area:</b> Newark	
3610956	OUT (SL- (Night Patrol) Sign Out)		SL - 7 Days	Job Completed	08/11/2016	31/01/2017	Act. SLNE/12002044
	<b>Feat No.:</b> 4,602.00	<b>Feature Id - Locn.:</b> S12 - nr LC 68		<b>Feature Type:</b> Refuge Beacon		<b>Area:</b> Newark	
3612835	STEM / GLOBE OUT + NUMBER (SL- (Night Patrol) Sign Out)		SL - 7 Days	Job Completed	06/12/2016	11/04/2017	Act. SLNE/12002406
	<b>Feat No.:</b> 4,606.00	<b>Feature Id - Locn.:</b> S18 - nr LC 60		<b>Feature Type:</b> Refuge Beacon		<b>Area:</b> Newark	
3629356	stem globe out. (SL- (Night Patrol) Sign Out)		SL - 7 Days	Job Completed	05/12/2017	08/12/2017	Act. SLNE/12005230
3630474	stem out (SL- (Night Patrol) Sign Out)		SL - 7 Days	Job Completed	03/01/2018	09/01/2018	Act. SLNE/12005385
	<b>Feat No.:</b> 4,802.25	<b>Feature Id - Locn.:</b> B30 - nr LC 68		<b>Feature Type:</b> Bollard		<b>Area:</b> Newark	
3622476	**** EA 1700484 ***** Replace existing bollard and base for NON-ILLUMINATED bollard, Black Glasdon Keep Left. - Disconnect and remove supply from feed. - check with Leigh Watson when TM is to be on.		SL- 30 Days	Job Completed	12/07/2017	25/07/2017	Act. SLNE/12004315
	<b>Feat No.:</b> 4,802.50	<b>Feature Id - Locn.:</b> B31 - nr LC 68		<b>Feature Type:</b> Bollard		<b>Area:</b> Newark	
3622477	Replace existing bollard and base for NON-ILLUMINATED bollard, Black Glasdon Keep Left. - Disconnect and remove supply from feed. - check with Leigh Watson when TM is to be on.		SL- 30 Days	Job Completed	12/07/2017	25/07/2017	Act. SLNE/12004316

Effective: 09/01/2017 to 09/01/2018  
Street: Main Road (26813983)

Display Action Officer: No

### Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Feat No.:</b> 4,805.00	<b>Feature Id - Locn.:</b> B17 nr LC 60		<b>Feature Type:</b> Bollard		<b>Area:</b> Newark	
3620200	ASAP OUT & LOOSE ON BASE (SL- (Night Patrol) Bollard Out)		SL - 7 Days	Job Completed	03/05/2017	16/11/2017	Act. SLNE/12003879
3628459	FIT NEW BOLLARD AND BASE COMPLETE		SL- 30 Days	Job Completed	16/11/2017	08/12/2017	Act. SLNE/12005114
	<b>Feat No.:</b> 4,806.00	<b>Feature Id - Locn.:</b> B19 nr LC 60		<b>Feature Type:</b> Bollard		<b>Area:</b> Newark	
3628460	FIT NEW BOLLARD AND BASE COMPLETE		SL- 30 Days	Job Completed	16/11/2017	08/12/2017	Act. SLNE/12005115

### Street Works Notices

Organisation: NCC - NEWARK (3055004)

**Works Ref:** 30603685      **Version:** 4      **Work Desc:** replace damaged signal poles/heads  
**Notice Type:** Works Stop      **Start:** 21/06/2017 00:00:00  
**Work Status:** Works Stopped      **Issued:** 29/06/2017 16:51:19  
**Work Type:** EToN 4: Minor      **Est. End:** 23/06/2017      **Completion:** 23/06/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	At its junctions with Staythorpe Road and Main Road, Hockerton	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed	23/06/2017			23/06/2017

**Works Ref:** EA1700484      **Version:** 2      **Work Desc:** Replacement of Traffic Signal Poles and Bollard  
**Notice Type:** Confirmation of Minor      **Start:** 25/07/2017 00:00:00  
**Work Status:** Proposed Works      **Issued:** 21/07/2017 10:19:52  
**Work Type:** EToN 4: Minor      **Est. End:** 25/07/2017      **Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	Junction Averham Bypass on A617, Main Road	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	25/07/2017			25/07/2017

**Works Ref:** OP1600032      **Version:** 1      **Work Desc:** Replace signal pole  
**Notice Type:** 3 Day Initial Notice      **Start:** 12/01/2017 00:00:00  
**Work Status:** Proposed Works      **Issued:** 13/01/2017 12:05:59  
**Work Type:** EToN 4: Minor      **Est. End:** 12/01/2017      **Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	at its junction with A612	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	12/01/2017			12/01/2017

Organisation: Nottinghamshire Highway Works (3055042)

**Works Ref:** 40807817      **Version:** 1      **Work Desc:** Recutting Damaged Detector Loops  
**Notice Type:** 3 Day Initial Notice      **Start:** 17/10/2017 00:00:00  
**Work Status:** Proposed Works      **Issued:** 13/10/2017 16:00:13  
**Work Type:** EToN 4: Minor      **Est. End:** 17/10/2017      **Completion:**

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	A612 Main Road, A617 Main Road Averham	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	A Site of a Proposed Street Works	17/10/2017			17/10/2017

Effective: 09/01/2017 to 09/01/2018  
 Street: Main Road (26813983)

Display Action Officer: No

### Street Works Notices

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: 40808434

Version: 1

Work Desc: Replace Bollard Bases

Notice Type: 3 Day Initial Notice

Start: 08/12/2017 00:00:00

Work Status: Proposed Works

Issued: 01/12/2017 14:31:37

Work Type: EToN 4: Minor

Est. End: 08/12/2017

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Main Road Averham	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	08/12/2017			08/12/2017