

Effective: 09/01/2017 to 09/01/2018
Street: Main Road (26813978)

Display Action Officer: No

Street: Main Road (26813978)

Locality: Kelham, Nottinghamshire

Area: Newark

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 1,000.00	Feature Id - Locn.: 3224C - Kelham Village Bridge			Feature Type: Culvert (Spans 1m to 3m)			Area: Newark	
Batch: 104827 - Inspection Batch			Route: 2016 Newark Culverts				Date: 30/05/2017	
No actionable defects found								
Feat No.: 1,000.01	Feature Id - Locn.: 3224C/1/1 - Kelham Village Bridge/1/1			Feature Type: Spans			Area: Newark	
Batch: 104828 - Inspection Batch			Route: 2016 Newark Culverts				Date: 30/05/2017	
No actionable defects found								
Feat No.: 2,000.00	Feature Id - Locn.: A617 - From Approx. 415M North East Of Stocks School Entranc			Feature Type: Street Section			Area: Newark	
Batch: 20261751 - Inspection Batch			Route: Newark Area 2 Jan Saf CW				Date: 08/01/2018	
No actionable defects found								
Batch: 20258315 - Inspection Batch			Route: Newark Area 2 Dec Saf CW				Date: 07/12/2017	
3561543	pothole	07/12/2017	at entrance to kelham hall, marked	CW Repairs-Bituminous	Internal		Committed	2664381
Batch: 20254186 - Inspection Batch			Route: Newark Area 2 Nov Enh CW/FW				Date: 09/11/2017	
No actionable defects found								
Batch: 20248793 - Inspection Batch			Route: Newark Area 2 Oct Saf CW				Date: 05/10/2017	
No actionable defects found								
Batch: 20246198 - Inspection Batch			Route: Newark Area 2 Sep Saf CW				Date: 18/09/2017	
3555414	pothole	18/09/2017	junction of ollerton rd on 617 around mh marked	CW Repairs-Bituminous	Internal		Committed	2657929
3555413	potholes	18/09/2017	at junction of blacksmith ln all marked	CW Repairs-Bituminous	Internal		Committed	2657930
Batch: 20241689 - Inspection Batch			Route: Newark Area 2 Aug Saf CW				Date: 15/08/2017	
3553399	potholes	15/08/2017	kelham os ive cottage next to barn marked	CW Repairs-Bituminous	Internal		Committed	2655839
3553398	pothole	15/08/2017	on corner opps broadgate lane next to kerb marked	CW Repairs-Bituminous	Internal		Committed	2655838
3553401	potholes	15/08/2017	at junction of broadgate lane and A617 kelham marked	CW Repairs-Bituminous	Internal		Committed	2655837
3553400	pothole	15/08/2017	opps blacksmith lane kelham on 617marked	CW Repairs-Bituminous	Internal		Committed	2655840
Batch: 20239147 - Inspection Batch			Route: Newark Area 2 Jul Saf CW				Date: 24/07/2017	
No actionable defects found								
Batch: 20233820 - Inspection Batch			Route: Newark Area 2 Jun Saf CW				Date: 13/06/2017	
No actionable defects found								
Batch: 20228781 - Inspection Batch			Route: Newark Area 2 May Saf CW				Date: 08/05/2017	
No actionable defects found								
Batch: 20225943 - Inspection Batch			Route: Newark Area 2 Apr Saf CW				Date: 20/04/2017	
No actionable defects found								
Batch: 20219724 - Inspection Batch			Route: Newark Area 2 Mar Saf CW				Date: 06/03/2017	
No actionable defects found								

Effective: 09/01/2017 to 09/01/2018
Street: Main Road (26813978)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: A617 - From Approx. 415M North East Of Stocks School Entran			Feature Type: Street Section			Area: Newark	
Batch: 20219722 - Inspection Batch				Route: Adhoc Inspection				Date: 06/03/2017
3543854	Carriageway Pothole - pothole next to drain on side of road. Photo in links. (Enquiry	06/03/2017	on the bend, oposite lamp column 22, around ironwork	CW Repairs-Bituminous	Internal		Committed	2645600
Batch: 20218620 - Inspection Batch				Route: Adhoc Inspection				Date: 27/02/2017
3543373	fw pothole	27/02/2017	at entrance to pub carpark, marked on pavement	FW Repairs-Bituminous	Internal		Committed	2645100
Batch: 20216002 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Feb Saf CW				Date: 09/02/2017
Batch: 20211425 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Jan Saf CW				Date: 09/01/2017
Feat No.: 3,501.00	Feature Id - Locn.:			Feature Type: Non-Illum Sign - 1 Post			Area: Newark	
Batch: 20661190 - Inspection Batch	No actionable defects found			Route: Ad Hoc SL Countywide				Date: 08/11/2017
Feat No.: 4,005.00	Feature Id - Locn.: 6 - Main Street A 617			Feature Type: Column			Area: Newark	
Batch: 20636317 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide				Date: 02/02/2017
20614755	OUT	02/02/2017		SL- (Night Patrol) Column Out	Internal		Committed	3616120
Feat No.: 4,013.00	Feature Id - Locn.: 14 - Main Street A 617			Feature Type: Column			Area: Newark	
Batch: 20649989 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide				Date: 15/06/2017
20619737	*****DEAD SERVICE FROM LC7 THROUGH TO LC18 *****Street Light Fault - Light out - There is a light on the bridge and there after the bridge as the immediate right hand turn after the bridge there are several street lights that are completely out. They are the new LED lights and there's only 1 unit working in this area. This was noticed at about 1am. . Submitted by Advisor: [REDACTED] TP (Enquiry 6055565)	15/06/2017		SL- Street Light out	Internal		Committed	3621642
Feat No.: 4,023.00	Feature Id - Locn.: 24 - Main Street A 617			Feature Type: Column			Area: Newark	
Batch: 20648920 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide				Date: 07/06/2017
20619505	OUT	07/06/2017		SL- (Night Patrol) Column Out	Internal		Committed	3621368
Feat No.: 4,600.01	Feature Id - Locn.: S1 - On Lc1			Feature Type: Lit Sign			Area: Newark	
Batch: 20664566 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide				Date: 03/01/2018
20627681	out on LC1	03/01/2018		SL- (Night Patrol) Sign Out	Internal		Committed	3630475
Feat No.: 4,607.01	Feature Id - Locn.: S7 - Nr Lc12			Feature Type: Lit Sign			Area: Newark	
Batch: 20663021 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide				Date: 05/12/2017
20626667	30mph out.	05/12/2017		SL- (Night Patrol) Sign Out	Internal		Committed	3629348

Effective: 09/01/2017 to 09/01/2018
Street: Main Road (26813978)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 4,610.01	Feature Id - Locn.: S9 - NEAR L/C 17			Feature Type: Lit Sign			Area: Newark	
Batch: 20663020 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide				Date: 05/12/2017
20626666	ROAD NARROWS LIGHT OUT AND CLEAN SIGNS out.	05/12/2017		SL- (Night Patrol) Sign Out	Internal		Committed	3629347
Feat No.: 4,613.01	Feature Id - Locn.: S12 - NEXT TO Lc22			Feature Type: Lit Sign			Area: Newark	
Batch: 20654336 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide				Date: 08/08/2017
20621251	OUT. and number if required	08/08/2017		SL- (Night Patrol) Sign Out	Internal		Committed	3623385
Feat No.: 4,614.01	Feature Id - Locn.: S13 - NEAR L/C 20			Feature Type: Lit Sign			Area: Newark	
Batch: 20636314 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide				Date: 02/02/2017
20614752	OUT & NUMBER POST	02/02/2017		SL- (Night Patrol) Sign Out	Internal		Committed	3616117
Feat No.: 4,616.02	Feature Id - Locn.: S15 - NEARLEY OPP L/C 33			Feature Type: Lit Sign			Area: Newark	
Batch: 20657599 - Inspection Batch				Route: Ad Hoc SL Countywide				Date: 22/09/2017
	No actionable defects found							
Feat No.: 4,617.01	Feature Id - Locn.: S16 - NEAR L/C 33			Feature Type: Lit Sign			Area: Newark	
Batch: 20663019 - Ad Hoc Inspection Batch				Route: Ad Hoc SL Countywide				Date: 05/12/2017
20626665	out.	05/12/2017		SL- (Night Patrol) Sign Out	Internal		Committed	3629346
Batch: 20655748 - Inspection Batch				Route: Ad Hoc SL Countywide				Date: 01/09/2017
	No actionable defects found							
Feat No.: 8,000.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection				Route: Ad Hoc Inspection				Date: 24/08/2017
	No actionable defects found							
Feat No.: 8,002.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection				Route: Ad Hoc Inspection				Date: 24/08/2017
	No actionable defects found							
Feat No.: 8,004.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection				Route: Ad Hoc Inspection				Date: 24/08/2017
	No actionable defects found							
Feat No.: 8,006.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection				Route: Ad Hoc Inspection				Date: 24/08/2017
	No actionable defects found							
Feat No.: 8,007.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection				Route: Ad Hoc Inspection				Date: 24/08/2017
	No actionable defects found							
Feat No.: 8,009.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection				Route: Ad Hoc Inspection				Date: 24/08/2017
	No actionable defects found							

Effective: 09/01/2017 to 09/01/2018
Street: Main Road (26813978)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,011.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 23/08/2017
Feat No.: 8,012.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,014.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,016.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,018.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,020.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,022.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,024.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,026.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,028.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,030.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,032.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017

Effective: 09/01/2017 to 09/01/2018
Street: Main Road (26813978)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,034.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,036.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,038.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,040.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,042.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,044.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,046.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,048.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,049.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,050.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 23/08/2017
Feat No.: 8,051.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,053.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017

Effective: 09/01/2017 to 09/01/2018
Street: Main Road (26813978)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,055.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,056.00	Feature Id - Locn.:			Feature Type: Gully (Twin)			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,057.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,058.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,060.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,062.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,064.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,066.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,067.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,069.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,071.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,073.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017

Effective: 09/01/2017 to 09/01/2018
Street: Main Road (26813978)

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 8,075.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,077.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,079.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,081.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,083.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 23/08/2017
Feat No.: 8,084.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 23/08/2017
Feat No.: 8,086.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,087.00	Feature Id - Locn.:			Feature Type: Offlet			Area: Newark	
Batch: 10000338 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,091.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,093.00	Feature Id - Locn.:			Feature Type: Kerb Offlet Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017
Feat No.: 8,094.00	Feature Id - Locn.:			Feature Type: Gully			Area: Newark	
Batch: 10000334 - Ad Hoc Inspection	No actionable defects found			Route: Ad Hoc Inspection				Date: 24/08/2017

Effective: 09/01/2017 to 09/01/2018
Street: Main Road (26813978)

Display Action Officer: No

Customer Services

Enquiry No.: 7000568	Logged by: Andrew Fuller	on: 08/11/2017 10:56
Service: Carriageway/Footway	Subject: St Furn/Non Illum Sign Damage	Classification: Report or Observation
Desc.: sign face off post.		
Location:	Contact:	
Plot Number: 3,501.00	Feature Id - Location:	Feature Type: Non-Illum Sign - 1 Post
Enquiry No.: 6075606	Logged by: External to Confirm	on: 09/01/2018 13:06
Service: Carriageway/Footway	Subject: Manholes/Gullies	Classification: Report or Observation
Desc.: Missing manhole/drain covers - the manhole cover is very loose on the junction A617 opposite Blacksmiths Lane. As well as making a noise when traffic passes over it, it jumps in the air and so far gone back to the same place but could cause an accident.. Submitted by Advisor: TP		
Location: See map coordinates and description details	Contact:	
Enquiry No.: 6058524	Logged by: External to Confirm	on: 17/07/2017 13:32
Service: Carriageway/Footway	Subject: Blocked Drain	Classification: Report or Observation
Desc.: Blocked drains - Blocked drain in front of Fox pub car-park, just before Kelham Bridge, turn off to Blacksmith lane. Quickly accumulates standing water in heavy rain.. Online report		
Location: See map coordinates and description details	Contact:	
Enquiry No.: 6056464	Logged by: External to Confirm	on: 26/06/2017 09:07
Service: Carriageway/Footway	Subject: Footway Damage	Classification: Report or Observation
Desc.: Pavement Damage - Customer is ringing in regard to the uneven surface on the A617 Kirklington Road, is now aware that there is work planned as lots of marking on the surface. However is advising that following a recent service to her car it is in need for work to remedy suspension and tyres, TP Customer advises that she has reported the poor surface over that last year direct online to our highways team. Would like to put in an insurance claim to pay for the work on her car. . Submitted by Advisor: TP		
Location: See map coordinates and description details	Contact:	
Enquiry No.: 6055565	Logged by: External to Confirm	on: 14/06/2017 17:33
Service: Lighting	Subject: Street Light Fault	Classification: Report or Observation
Desc.: Light out - There is a light on the bridge and there after the bridge as the immediate right hand turn after the bridge there are several street lights that are completely out. They are the new LED lights and there's only 1 unit working in this area. This was noticed at about 1am. . Submitted by Advisor: TP		
Location:	Contact:	
Plot Number: 4,013.00	Feature Id - Location: TP Main Street A 617	Feature Type: Column
Job Number: 3621642	Defect Number: 20619737	
Enquiry No.: 6053967	Logged by: External to Confirm	on: 30/05/2017 11:13
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation
Desc.: Insurance claim - related to Confirm defect reference: 6053966 Date/Time: 29/05/2017 18:30:00 Direction of travel: Towards Southwell race course from Newark on Trent just over Kelham Bridge Account of what happened: Hit a large puddle water sprayed over car customer hit on coming vehicle Unable to go to work as has injuries to neck back chest and left hip. Also without a vehicle		
Location: See map coordinates and description details	Contact:	
Enquiry No.: 6053966	Logged by: External to Confirm	on: 30/05/2017 11:12
Service: Carriageway/Footway	Subject: Flooding	Classification: Report or Observation
Desc.: Street flooding - Just over Kelham Bridge on A617 street flooded just going around bend with Broadgate Lane heading toward Southwell Race course pass Kelham Hall Customer hit a large puddle half way across the road water sprayed over car wipes on brakes on but customer unable to see anything and hit on coming traffic both cars write offs. TP		
. Submitted by Advisor: TP		
Location: See map coordinates and description details	Contact:	

Effective: 09/01/2017 to 09/01/2018
Street: Main Road (26813978)

Display Action Officer: No

Customer Services

Enquiry No.: 6051088	Logged by: External to Confirm	on: 26/04/2017 10:51	Enquiry Ref: FS-CASE-51422553
Service: Traffic Management	Subject: Parking General	Classification: Report or Observation	
Desc.: Parking issues - Two white Nottinghamshire county council buses have stop opposite number TP Kelham Road in Newark for approx 30 mins to take a break and change drivers is this going to become the normal as road is very narrow and residents parking permits . Submitted by Advisor: TP			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6050205	Logged by: External to Confirm	on: 18/04/2017 09:51	Enquiry Ref: FS-CASE-51071842
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: Issue with newly laid roads - Large sections of the road surface of the A617 between Kelham Bridge and the entrance to Kelham Hall are breaking up. This has resulted in the wearing course breaking away exposing the base course which is also now eroding. There are large amounts of loose aggregate which is a danger as they fly up from the wheels of vehicles and also make the road surface dangerous due to lack of grip due the loose surface. Further erosiion has also allowed the formation of potholes in these areas to start as the softer basecourse is now fully exposed and recently resulted in the collapse of an inspection chamber in the main highway which required emergency repair. . Online report			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6049336	Logged by: External to Confirm	on: 05/04/2017 12:29	Enquiry Ref: FS-CASE-50706656
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: Road Damage - Mr TP has contacted us today in regards to the current surface conditions on the A617. TP and due to surface water and poor drainage. This is now causing damp in the garage TP			
Now looking on Google Maps, you can that the wall in question is fairly old, but as you look at the top of the wall it looks pretty dry but at the bottom looks pretty damp. . Submitted by Advisor: TP			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6044164	Logged by: External to Confirm	on: 27/02/2017 10:16	Enquiry Ref: FS-CASE-13184490
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: Road Damage - There is a large pothole near the entrance to the Fox and a series of other potholes all along Main Road through the village. Overall the condition of the road as it loops through the village is very poor. . Online report			
Location: See map coordinates and description details		Contact:	
Plot Number: 2,000.00	Feature Id - Location: A617 - From Approx. 415M North East Of Stocks School Entran	Feature Type: Street Section	
Job Number: 2645100	Defect Number: 3543373		
Enquiry No.: 6042029	Logged by: External to Confirm	on: 08/02/2017 14:04	Enquiry Ref: FS-CASE-12706364
Service: Road Works	Subject: Road Works Report	Classification: Report or Observation	
Desc.: Licencing Issue			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6038654	Logged by: External to Confirm	on: 09/01/2017 23:58	Enquiry Ref: FS-CASE-11426565
Service: Carriageway/Footway	Subject: Carriageway Damage	Classification: Report or Observation	
Desc.: Road Damage - Faulty manhole in road? I live directly opposite and every time a car drives over (which is constant) it makes a terr ble noise. It is situated on the left side of the road heading towards Newark. It could be the manhole cover is the issue and not a pothole exactly. The problem has been there for over 2 months now TP so surprised this has not already been sorted? Hope you can help? Wasn't sure who to report this to. I can hear the racket from the other side of the house it's so bad. . Online report			
Location: The pin has been placed near 1 A617, Newark, United Kingdom, NG23 5QP		Contact:	

Effective: 09/01/2017 to 09/01/2018
Street: Main Road (26813978)

Display Action Officer: No

Customer Services

Enquiry No.: 3204286 Logged by: TP on: 02/06/2017 12:04
Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation
Desc.: manhole surround damaged causing noise and vibration
Location: At the junction with Holme farm close on the Southwell bound side Contact:

Plot Number: 2,000.00 Feature Id - Location: A617 - From Approx. 415M North East Of Stocks School Entran Feature Type: Street Section
Job Number: 2654163

Enquiry No.: 3204039 Logged by: TP on: 04/04/2017 11:58
Service: Carriageway/Footway Subject: Carriageway Damage Classification: Report or Observation
Desc.: Councillor Saddington asks that these locations are inspected and repaired if necessary.
Location: Main Road through Kelham, Ollerton Road - especially opposite the entrance to The Fox, A617 from the corner of Ollerton Road towards Averham Contact:

Plot Number: 2,000.00 Feature Id - Location: A617 - From Approx. 415M North East Of Stocks School Entran Feature Type: Street Section
Job Number: 2648914

Enquiry No.: 2505047 Logged by: TP on: 04/10/2017 14:18
Service: Trees/Verges Subject: Overhanging Vegetation/Trees Classification: Report or Observation
Desc.: PVASS is obscured by vegetation
Location: hedge prior to and at the PVASS : inbound from Southwell direction Contact:

Enquiry No.: 2504645 Logged by: TP on: 10/01/2017 16:08
Service: Bridges/Structures Subject: Bridges/Structures Damage Classification: Report or Observation
Desc.: Councillor reports that 7 coping stones have been dislodged where the damage was repaired a few years ago, there is also signs of a lorry scraping the wall
Location: Kelham Bridge Contact:

Enquiry No.: 60001 Logged by: TP on: 17/02/2017 11:43
Service: Carriageway/Footway Subject: Carriageway Pothole Classification: Report or Observation
Desc.: pothole next to drain on side of road. Photo in links.
Location: on the bend, opposite lamp column 22 Contact:

Plot Number: 2,000.00 Feature Id - Location: A617 - From Approx. 415M North East Of Stocks School Entran Feature Type: Street Section
Job Number: 2645600 Defect Number: 3543854

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: A617 - From Approx. 415M North East Of Stocks School Entran		Feature Type: Street Section		Area: Newark	
2645100	fw pothole (FW Repairs-Bituminous)	at entrance to pub carpark, marked on pavement	Category 2 (High)	Job Completed	27/02/2017	09/03/2017	Act. NEW/3604570
2645600	Carriageway Pothole - pothole next to drain on side of road. Photo in links. (Enquiry CW Repairs-Bituminous)	on the bend, opposite lamp column 22, around ironwork	Category 2 (High)	Job Completed	06/03/2017	07/03/2017	Act. NEW-AS/5502561
2648914	Carriageway Damage - Councillor Saddington asks that these locations are inspected and repaired if necessary. (Enquiry 3204039)	Main Road through Kelham, Ollerton Road - especially opposite the entrance to The Fox, A617 from the corner of Ollerton Road towards Averham	Filled when found (Cat 2H)	Job Completed	24/04/2017	10/04/2017	Act.

Effective: 09/01/2017 to 09/01/2018
Street: Main Road (26813978)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.:	2,000.00	Feature Id - Locn.: A617 - From Approx. 415M North East Of Stocks School Entran		Feature Type: Street Section		Area: Newark	
2654163	Carriageway Damage - manhole surround damaged causing noise and vibration (Enquiry 3204286)	At the junction with Holme farm close on the Southwell bound side	Filled when found (Cat 2L)	Job Completed	14/07/2017	28/06/2017	Act.
2655837	potholes (CW Repairs-Bituminous)	at junction of broadgate lane and A617 kelham marked	Category 2 (High)	Job Completed	15/08/2017	16/08/2017	Act. NEW-AS/5503474
2655838	pothole (CW Repairs-Bituminous)	on corner opps broadgate lane next to kerb marked	Category 2 (Low)	Job Completed	15/08/2017	16/08/2017	Act. NEW-AS/5503466
2655839	potholes (CW Repairs-Bituminous)	kelham os ive cottage next to barn marked	Category 2 (High)	Job Completed	15/08/2017	16/08/2017	Act. NEW-AS/5503475
2655840	pothole (CW Repairs-Bituminous)	opps blacksmith lane kelham on 617marked	Category 2 (High)	Job Completed	15/08/2017	16/08/2017	Act. NEW-AS/5503476
2657929	pothole (CW Repairs-Bituminous)	junction of ollerton rd on 617 around mh marked	Category 2 (Low)	Job Completed	18/09/2017	19/09/2017	Act. NEW-AS/5503822
2657930	potholes (CW Repairs-Bituminous)	at junction of blacksmith ln all marked	Category 2 (Low)	Job Completed	18/09/2017	28/09/2017	Act. NEW-AS/5503823
2664381	pothole (CW Repairs-Bituminous)	at entrance to kelham hall, marked	Category 2 (Low)	Job Completed	07/12/2017	18/12/2017	Act. NEW/3606954
Feat No.:	4,005.00	Feature Id - Locn.: 6 - Main Street A 617		Feature Type: Column		Area: Newark	
3616120	OUT (SL- (Night Patrol) Out)	Column	SL - 7 Days	Job Completed	02/02/2017	04/04/2017	Act. SLNE/12003087
Feat No.:	4,007.00	Feature Id - Locn.: 8 - Main Street A 617		Feature Type: Column		Area: Newark	
1247452	OUT (SL- (Night Patrol) Out)	Column	SL - 7 Days	Job Completed	11/08/2015	16/11/2017	Act. SLNE/18609
Feat No.:	4,009.00	Feature Id - Locn.: 10 - Main Street A 617		Feature Type: Column		Area: Newark	
3607006	Street Light Fault - Light out - Light not working . Online report (Enquiry 6025833) (SL- Street Light out)		SL - 7 Days	Job Completed	30/08/2016	24/03/2017	Act. SLNE/12001248
Feat No.:	4,013.00	Feature Id - Locn.: 14 - Main Street A 617		Feature Type: Column		Area: Newark	
3621642	*****DEAD SERVICE FROM LC7 THROUGH TO LC18 *****Street Light Fault - Light out - There is a light on the bridge and there after the bridge as the immediate right hand turn after the bridge there are several street lights that are completely out. They are the new LED lights and there's only 1 unit working in this area. This was noticed at about 1am. . Submitted by Advisor: Sophie Whitley (Enquiry 6055565) (SL- Street Light out)		SL - DNO single 25 W/Days	Job Completed	15/06/2017	10/07/2017	Act. EONNW/3500040

Effective: 09/01/2017 to 09/01/2018
Street: Main Road (26813978)

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 4,015.00	Feature Id - Locn.: 16 - Main Steet A 617			Feature Type: Column		Area: Newark	
1250684	OUT (SL- (Night Patrol) Column Out)		SL - 7 Days	Job Completed	05/01/2016	20/09/2017	Act. SLNE/20272
Feat No.: 4,021.00	Feature Id - Locn.: 22 - Main Street A 617			Feature Type: Column		Area: Newark	
3608863	OUT (SL- (Night Patrol) Column Out)		SL - 7 Days	Job Completed	04/10/2016	04/04/2017	Act. SLNE/12001635
Feat No.: 4,023.00	Feature Id - Locn.: 24 - Main Street A 617			Feature Type: Column		Area: Newark	
3621368	OUT (SL- (Night Patrol) Column Out)		SL - 7 Days	Job Completed	07/06/2017	06/07/2017	Act. SLNE/12004087
Feat No.: 4,600.01	Feature Id - Locn.: S1 - On Lc1			Feature Type: Lit Sign		Area: Newark	
3630475	out on LC1 (SL- (Night Patrol) Sign Out)		SL - 7 Days	Job Completed	03/01/2018	05/01/2018	Act. SLNE/12005386
Feat No.: 4,604.01	Feature Id - Locn.: S4 - Opposite LC 10			Feature Type: Lit Sign		Area: Newark	
1247453	OUT (SL- (Night Patrol) Sign Out)		SL - 7 Days	Job Completed	11/08/2015	06/07/2017	Act. SLNE/18610
Feat No.: 4,607.01	Feature Id - Locn.: S7 - Nr Lc12			Feature Type: Lit Sign		Area: Newark	
3629348	30mph out. (SL- (Night Patrol) Sign Out)		SL - 7 Days	Job Completed	05/12/2017	06/12/2017	Act. SLNE/12005228
Feat No.: 4,610.01	Feature Id - Locn.: S9 - NEAR L/C 17			Feature Type: Lit Sign		Area: Newark	
3629347	ROAD NARROWS LIGHT OUT AND CLEAN SIGNS out. (SL- (Night Patrol) Sign Out)		SL - 7 Days	Job Completed	05/12/2017	06/12/2017	Act. SLNE/12005227
Feat No.: 4,613.01	Feature Id - Locn.: S12 - NEXT TO Lc22			Feature Type: Lit Sign		Area: Newark	
3623385	OUT. and number if required (SL- (Night Patrol) Sign Out)		SL - 7 Days	Job Completed	08/08/2017	15/08/2017	Act. SLNE/12004443
Feat No.: 4,614.01	Feature Id - Locn.: S13 - NEAR L/C 20			Feature Type: Lit Sign		Area: Newark	
3616117	OUT (SL- (Night Patrol) Sign Out)		SL - 7 Days	Job Completed	02/02/2017	20/02/2017	Act. SLNE/12003086
Feat No.: 4,616.01	Feature Id - Locn.: NEARLEY OPP L/C 33			Feature Type: Lit Sign		Area: Newark	
3622843	****EA1700614**** Fit new B/B Post in original position with new 750 signs (30mph & 50mph) mounted at 2.1 joint cables if required, Fit light units. tidy site. number post.		SL- 30 Days	Job Completed	21/07/2017	30/08/2017	Act. SLNE/12004345
Feat No.: 4,617.01	Feature Id - Locn.: S16 - NEAR L/C 33			Feature Type: Lit Sign		Area: Newark	
3629346	out. (SL- (Night Patrol) Sign Out)		SL - 7 Days	Job Completed	05/12/2017	06/12/2017	Act. SLNE/12005226

Effective: 09/01/2017 to 09/01/2018
Street: Main Road (26813978)

Display Action Officer: No

Street Works Notices

Organisation: NCC - NEWARK (3055004)

Works Ref: 30603806

Notice Type: 3 Day Initial Notice

Work Status: Proposed Works

Work Type: EToN 4: Minor

Version: 1

Start: 17/09/2017 00:00:00

Issued: 13/09/2017 11:39:55

Est. End: 17/09/2017

Work Desc: Pipework and drainage investigation

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	On sharp bend	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	17/09/2017			17/09/2017

Works Ref: 3622843

Notice Type: 3 Day Initial Notice

Work Status: Proposed Works

Work Type: EToN 4: Minor

Version: 1

Start: 30/08/2017 00:00:00

Issued: 30/08/2017 11:09:33

Est. End: 30/08/2017

Work Desc: Install lighting column

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Near entrance to Kelham Hall	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	30/08/2017			30/08/2017

Works Ref: OP1600082Y

Notice Type: 3 Day Initial Notice

Work Status: Proposed Works

Work Type: EToN 4: Minor

Version: 1

Start: 17/03/2017 00:00:00

Issued: 16/03/2017 17:25:11

Est. End: 17/03/2017

Work Desc: Urgent sign post replacement

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	Between Averham & Kelham	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	17/03/2017			17/03/2017

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: /GULLYS23/8/1

Notice Type: Cancellation

Work Status: Abandoned Works

Work Type: EToN 4: Minor

Version: 2

Start: 23/08/2017 00:00:00

Issued: 24/08/2017 15:49:50

Est. End: 24/08/2017

Work Desc: Gully cleansing works.

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	A617 Kelham to Newark area.	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	23/08/2017			24/08/2017

Works Ref: /HW10006/02

Notice Type: Works Stop

Work Status: Works Stopped

Work Type: EToN 4: Major

Version: 4

Start: 03/10/2017 00:00:00

Issued: 09/10/2017 09:34:01

Est. End: 08/10/2017

Work Desc: Carriageway resurfacing. Night work 20:00 - 06:00.

Completion: 07/10/2017

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	A617 from A617/A46/A616 roundabout, Newark to Holme Farm Close, Kelham	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	07/10/2017			08/10/2017

Effective: 09/01/2017 to 09/01/2018
Street: Main Road (26813978)

Display Action Officer: No

Street Works Notices

Organisation: Nottinghamshire Highway Works (3055042)

Works Ref: 40807969

Notice Type: 3 Day Initial Notice

Work Status: Proposed Works

Work Type: EToN 4: Minor

Version: 1

Start: 04/11/2017 00:00:00

Issued: 02/11/2017 16:41:50

Est. End: 04/11/2017

Work Desc: Traffic Signals to aid egress from Kelham Hall Fireworks Event

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	At the entrance to Kelham Hall	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 A Site of a Proposed Street Works	04/11/2017			04/11/2017

Organisation: Severn Trent Waste (9103902)

Works Ref: 0000/000011531655

Notice Type: Cancellation

Work Status: Abandoned Works

Work Type: EToN 4: Minor

Version: 2

Start: 01/02/2017 00:00:00

Issued: 02/01/2017 08:27:02

Est. End: 01/02/2017

Work Desc: Rep/reset MH cover In Hwy to 675mmsq

Completion:

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	OPPOSITE 1 MAIN ROAD KELHAM NOTTINGHAMSHIRE	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Abandoned	01/02/2017			01/02/2017

Works Ref: 0000/000011531655A

Notice Type: Registration of Reinstatement - Full

Work Status: Works Stopped

Work Type: EToN 4: Minor

Version: 5

Start: 22/01/2017 00:00:00

Issued: 23/01/2017 09:11:36

Est. End: 22/01/2017

Work Desc: Rep/reset MH cover In Hwy to 675mmsq Rep/reset MH cover In Hwy to 675mmsq

Completion: 22/01/2017

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	OPPOSITE 1 MAIN ROAD KELHAM NOTTINGHAMSHIRE	Carriageway	Up to 1.5 Metres of Cover	1.20	1.20 A Permanent Reinstatement	22/01/2017		22/01/2017	22/01/2017

Works Ref: 0000/000011546841

Notice Type: Registration of Reinstatement - Full

Work Status: Works Stopped

Work Type: EToN 4: Minor

Version: 5

Start: 22/01/2017 00:00:00

Issued: 23/01/2017 09:02:51

Est. End: 22/01/2017

Work Desc: rep/reset mh cover in hwy to 675mmsq rep/reset mh cover in hwy to 675mmsq

Completion: 22/01/2017

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	O/S GROVE COTTAGE MAIN ROAD KELHAM NOTTINGHAMSHIRE	Carriageway	Up to 1.5 Metres of Cover	1.20	1.20 A Permanent Reinstatement	22/01/2017		22/01/2017	22/01/2017

Works Ref: 0000/000011634690

Notice Type: Works Stop

Work Status: Works Stopped

Work Type: EToN 4: Immediate - Emergency

Version: 2

Start: 25/05/2017 11:50:00

Issued: 01/06/2017 11:36:08

Est. End: 26/05/2017

Work Desc: Jetting the sewer to stop pollution

Completion: 26/05/2017

Site No.	Location	Position	Depth	Length	Width Status	Site Date	Interim	Perm.	Prop. End
1	O/S CORNER FARM MAIN ROAD KELHAM NOTTINGHAMSHIRE	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00 Site Closed (No Excavation)	26/05/2017			26/05/2017