

Effective: 25/01/2017 to 25/01/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Longland Lane (26805255)

Street: Longland Lane (26805255)

Locality: Farnsfield, Nottinghamshire

Area: Newark

Condition Survey

Defect No.	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: C68 - Old Rufford Road (A614) Junction To Blidworth Road Junc			Feature Type: Street Section			Area: Newark	
Batch: 20263790 - Inspection Batch				Route: Adhoc Inspection				Date: 22/01/2018
3564808	pothole	22/01/2018	os longland farm, marked with arrow	CW Repairs-Bituminous	Internal		Committed	2667729
Batch: 20262268 - Inspection Batch				Route: Newark Area 2 Jan Saf CW				Date: 10/01/2018
3563614	pothole	10/01/2018	on bends near no footway for 500y sign marked	CW Repairs-Bituminous	Internal		Committed	2666515
3563615	potholes	10/01/2018	near carr banks farm marked	CW Repairs-Bituminous	Internal		Committed	2666516
3563613	pothole	10/01/2018	opps beck lane marked	CW Repairs-Bituminous	Internal		Committed	2666514
3563617	potholes	10/01/2018	opps new farm sheds marked with a arrows	CW Repairs-Bituminous	Internal		Committed	2666518
3563616	pothole	10/01/2018	on stretch of road from 614 to the bend on hill marked with a arrow	CW Repairs-Bituminous	Internal		Committed	2666517
3563619	potholes	10/01/2018	near melrose house marked	CW Repairs-Bituminous	Internal		Committed	2666513
3563618	potholes	10/01/2018	from hill to A614 all marked	CW Repairs-Bituminous	Internal		Committed	2666519
Batch: 20258420 - Inspection Batch				Route: Newark Area 2 Dec Saf CW				Date: 07/12/2017
3561562	potholes	07/12/2017	near 614 junction, marked	CW Repairs-Bituminous	Internal		Committed	2664403
3561561	pothole	07/12/2017	on thr 614 junction, marked	CW Repairs-Bituminous	Internal		Committed	2664404
Batch: 20253516 - Inspection Batch				Route: Newark Area 2 Nov Saf CW				Date: 07/11/2017
3558981	potholes	07/11/2017	on bends as you enter village marked	CW Repairs-Bituminous	Internal		Committed	2661724
Batch: 20251522 - Inspection Batch				Route: Newark Area 2 Oct Enh CW/FW				Date: 24/10/2017
3558065	potholes	24/10/2017	near farnsfeild sign marked	CW Repairs-Bituminous	Internal		Committed	2660744
3558064	potholes	24/10/2017	from 614 to bend all marked	CW Repairs-Bituminous	Internal		Committed	2660745
Batch: 20247928 - Inspection Batch				Route: Newark Area 2 Sep Saf CW				Date: 29/09/2017
3556251	potholes	29/09/2017	full length of road	CW Repairs-Bituminous	Internal		Uncommitt	2658782
Batch: 20241092 - Inspection Batch				Route: Newark Area 2 Aug Saf CW				Date: 09/08/2017
No actionable defects found								
Batch: 20240119 - Inspection Batch				Route: Newark Area 2 Jul Saf CW				Date: 31/07/2017
3552718	cat 2 high repair with highway assistant	31/07/2017	near junction of Beck Lane , filled during inspections	CW Repairs-Bituminous	Internal		Uncommitt	2655049
3552717	cat 2 high repair .	31/07/2017	outside carr banks farm , filled during inspections	CW Repairs-Bituminous	Internal		Uncommitt	2655051
3552716	cat 2 high potholes , repaired with highway assistant .	31/07/2017	opposite the Farnsfield sign just past Beck Lane , filled during inspections.	CW Repairs-Bituminous	Internal		Uncommitt	2655050
Batch: 20234564 - Inspection Batch				Route: Newark Area 2 Jun Saf CW				Date: 19/06/2017
3550593	potholes	19/06/2017	all through this section , also near 30.. mph signs off bad bend coming from farnsfield marked	CW Repairs-Bituminous	Internal		Committed	2652691
3550592	pothole filled	19/06/2017	outside melrose nursery cat 2 high filled during inspections	CW Repairs-Bituminous	Internal		Uncommitt	2652692

Effective: 25/01/2017 to 25/01/2018

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Longland Lane (26805255)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: C68 - Old Rufford Road (A614) Junction To Blidworth Road Junc			Feature Type: Street Section			Area: Newark	
Batch: 20234538 - Inspection Batch				Route: Adhoc Inspection				Date: 19/06/2017
3550573	cat 1 high repair 70 mm deep x 400 mm x 400 mm...photo's are attached	19/06/2017	as mapped half way along this section cat 1 high repair , john english H/insp .	CW Repairs-Bituminous	Internal		Uncommitt	2652672
Batch: 20229454 - Inspection Batch	No actionable defects found			Route: Newark Area 2 May Saf CW				Date: 10/05/2017
Batch: 20227026 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Apr Saf CW				Date: 26/04/2017
Batch: 20219482 - Inspection Batch	No actionable defects found			Route: Newark Area 2 Mar Saf CW				Date: 03/03/2017
Batch: 20217476 - Inspection Batch				Route: Adhoc Inspection				Date: 20/02/2017
3542945	Carriageway Pothole	20/02/2017	200metres from old rufford road junction traveling towards farnsfield, marked	CW Repairs-Bituminous	Internal		Committed	2644671
Batch: 20217474 - Inspection Batch				Route: Adhoc Inspection				Date: 20/02/2017
3542944	Carriageway Potholes	20/02/2017	30m south from Farnsfield	CW Repairs-Bituminous	Internal		Committed	2644670
Batch: 20215570 - Inspection Batch				Route: Newark Area 2 Feb Saf CW				Date: 07/02/2017
3541819	potholes	07/02/2017	just after industrial unit marked	CW Repairs-Bituminous	Internal		Committed	2643534
3541818	potholes	07/02/2017	entrance to carrbanks farm marked	CW Repairs-Bituminous	Internal		Committed	2643535

Customer Services

Enquiry No.: 6078423 **Logged by:** External to Confirm **on:** 25/01/2018 22:24
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-66666122
Desc.: Road Pothole - Pot hole about four inch deep causing major damage to vehicles. . Online report
Location: Longlane Road. Massive pothole burst my tyre and slit my front passenger side wheel. **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** C68 - Old Rufford Road (A614) Junction To Blidworth Road Junc **Feature Type:** Street Section
Job Number: 2668662 **Defect Number:** 3565723

Enquiry No.: 6078405 **Logged by:** External to Confirm **on:** 25/01/2018 19:32
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-66661024
Desc.: Road Damage - Massive damage/pot hole on left hand side...both wide and long hole. Damage to my wheel and popped tyre as a result. . Online report
Location: Half way down longland lane on the left hand side of road as drive in the direction of Farnsfield. **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** C68 - Old Rufford Road (A614) Junction To Blidworth Road Junc **Feature Type:** Street Section
Job Number: 2668661 **Defect Number:** 3565722

Enquiry No.: 6078344 **Logged by:** External to Confirm **on:** 25/01/2018 15:12
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-66641609
Desc.: Road Pothole - A number of earlier repaies to potholes are now failing, so several in a 200-300m stretch. . Online report
Location: Along Longlands Lane at various points from junction with A614 **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** C68 - Old Rufford Road (A614) Junction To Blidworth Road Junc **Feature Type:** Street Section
Job Number: 2668661 **Defect Number:** 3565722

Effective: 25/01/2017 to 25/01/2018

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Longland Lane (26805255)

Customer Services

Enquiry No.: 6078317	Logged by: External to Confirm	on: 25/01/2018 13:24	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-66627376
Desc.: Road Pothole - Pothole of dimensions 2m long x 0.5m wide x 13cm deep . Online report			
Location: On Longland Lane eastbound side approximately 0.4 miles from the intersection of Longland Lane with A614			
Plot Number: 2,000.00	Feature Id - Location: C68 - Old Rufford Road (A614) Junction To Blidworth Road Junc	Feature Type: Street Section	
Job Number: 2668661	Defect Number: 3565722		
Enquiry No.: 6078316	Logged by: External to Confirm	on: 25/01/2018 13:24	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-66625059
Desc.: Road Pothole - 200cm x50cm pothole 5 inches deep in places already caused damage to several vehicles including my vehicle . Online report			
Location: longland lane Farnsfield, when travelling from the A614 it approximately 1/2 a mile along on the nearside			
Plot Number: 2,000.00	Feature Id - Location: C68 - Old Rufford Road (A614) Junction To Blidworth Road Junc	Feature Type: Street Section	
Job Number: 2668661	Defect Number: 3565722		
Enquiry No.: 6075936	Logged by: External to Confirm	on: 11/01/2018 10:42	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS65559807
Desc.: Insurance claim - related to Confirm defect reference: 6075877			
Date/Time: 04/01/2018 17:10:00			
Direction of travel: I was travelling along Longlands Lane Farnsfield in my vehicle E056OND . I had turned from the A614 onto longlands land and had just gone past the four large sheds on the right.			
Account of what happened: A vehicle was travelling towards me in the opposite direction. At this time I struck two large potholes which jarred the vehicle. At this time I stopped and did not see any noticeable damage but it was pitch black and impossible to see. Over the weekend my vehicle developed two slow punctures on both the front and rear nearside wheels. Whilst commuting from work at the University of Nottingham my vehicle suddenly developed a complete flat tyre.			
Location: See map coordinates and description details			
Enquiry No.: 6075877	Logged by: External to Confirm	on: 10/01/2018 17:18	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-65520102
Desc.: Road Pothole - There are several huge pothole on longlands lane, I hit one last wednesday evening and I have now discovered that the alloy wheels are now damaged beyond repair. I believe you may have identified the potholes as after discovereing the damage to my wheels I have returned to the site today and they are circled in yellow paint . Online report			
Location: See map coordinates and description details			
Plot Number: 2,000.00	Feature Id - Location: C68 - Old Rufford Road (A614) Junction To Blidworth Road Junc	Feature Type: Street Section	
Job Number: 2666518	Defect Number: 3563617		
Enquiry No.: 6073500	Logged by: External to Confirm	on: 15/12/2017 10:52	
Service: Winter Maintenance	Subject: Gritting Request	Classification: Service Request	Enquiry Ref: FS-CASE-63960943
Desc.: Road gritting request - Pc Everitt has had a RTC come in where there is a big patch of ice on Longlands Lane near Carr Banks Farm. Vehicles are becoming stuck on here as the ice has just sheeted over and they need some gritting to take place in the area. Collar number 12260, Incident number 24415122017 . Submitted by Advisor: Ryan Farnsworth - - -			
Location: See map coordinates and description details			
Enquiry No.: 6043576	Logged by: External to Confirm	on: 20/02/2017 09:29	
Service: Claims	Subject: Highway Insurance Claim	Classification: Report or Observation	Enquiry Ref: FS13069355
Desc.: Insurance claim - related to Confirm defect reference: 6043575			
Date/Time: 18/02/2017 19:00:00			
Direction of travel: Customer was driving from Farnsfield to the A614 on Longland Lane.			
Account of what happened: Customer his pothole and it caused damage to his tyre and the wheel and the car is currently in the shop to get fixed.			
Location: See map coordinates and description details			

Effective: 25/01/2017 to 25/01/2018

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Longland Lane (26805255)

Customer Services

Enquiry No.: 6043575	Logged by: External to Confirm	on: 20/02/2017 09:29	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-13069355
Desc.: Road Pothole - Customer has called to report a pothole on Longland Lane in Farnsfield that has caused damage to his car. The rough dimensions of this pothole are 4-5 inches deep and roughly 18 inches x 15 inches. The customer urges that if a motorbike were to hit the pothole that it would get someone hurt. . Submitted by Advisor: nathan laverty			
Location: See map coordinates and description details		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C68 - Old Rufford Road (A614) Junction To Blidworth Road Junc	Feature Type: Street Section	
Job Number: 2644671	Defect Number: 3542945		
Enquiry No.: 6043529	Logged by: External to Confirm	on: 20/02/2017 05:18	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-13024386
Desc.: Road Pothole - All of Longland lane needs looking at for all the potholes all the way to Farnsfield some are very deep ITravel down here most days . Online report			
Location: See map coordinates and description details		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C68 - Old Rufford Road (A614) Junction To Blidworth Road Junc	Feature Type: Street Section	
Job Number: 2644671	Defect Number: 3542945		
Enquiry No.: 6043385	Logged by: External to Confirm	on: 18/02/2017 01:16	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-13024386
Desc.: Road Pothole - All of Longland lane needs looking at for all the potholes all the way to Farnsfield some are very deep ITravel down here most days . Online report			
Location: See map coordinates and description details		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C68 - Old Rufford Road (A614) Junction To Blidworth Road Junc	Feature Type: Street Section	
Job Number: 2644671	Defect Number: 3542945		
Enquiry No.: 6043328	Logged by: External to Confirm	on: 17/02/2017 19:29	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-13024386
Desc.: Road Pothole - All of Longland lane needs looking at for all the potholes all the way to Farnsfield some are very deep ITravel down here most days . Online report			
Location: See map coordinates and description details		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C68 - Old Rufford Road (A614) Junction To Blidworth Road Junc	Feature Type: Street Section	
Job Number: 2644671	Defect Number: 3542945		
Enquiry No.: 6043321	Logged by: External to Confirm	on: 17/02/2017 18:58	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-13024386
Desc.: Road Pothole - All of Longland lane needs looking at for all the potholes all the way to Farnsfield some are very deep ITravel down here most days . Online report			
Location: See map coordinates and description details		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C68 - Old Rufford Road (A614) Junction To Blidworth Road Junc	Feature Type: Street Section	
Job Number: 2644671	Defect Number: 3542945		
Enquiry No.: 6043317	Logged by: External to Confirm	on: 17/02/2017 18:30	
Service: Carriageway/Footway	Subject: Carriageway Pothole	Classification: Report or Observation	Enquiry Ref: FS-CASE-13024386
Desc.: Road Pothole - All of Longland lane needs looking at for all the potholes all the way to Farnsfield some are very deep ITravel down here most days . Online report			
Location: See map coordinates and description details		Contact:	
Plot Number: 2,000.00	Feature Id - Location: C68 - Old Rufford Road (A614) Junction To Blidworth Road Junc	Feature Type: Street Section	
Job Number: 2644671	Defect Number: 3542945		

Effective: 25/01/2017 to 25/01/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Longland Lane (26805255)

Customer Services

Enquiry No.: 6043217 **Logged by:** External to Confirm **on:** 17/02/2017 10:16
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-12998204
Desc.: Road Pothole - Southbound side of the road, 12" (30cm) diameter and 2"-4" deep. Disruptive pothole (swerve to miss type size). . Online report
Location: See map coordinates and description details **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** C68 - Old Rufford Road (A614) Junction To Blidworth Road Junc **Feature Type:** Street Section
Job Number: 2644670 **Defect Number:** 3542944

Enquiry No.: 6041729 **Logged by:** External to Confirm **on:** 07/02/2017 10:04
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-12646496
Desc.: Road Pothole - from A614 driving towards Farnsfield . Online report
Location: See map coordinates and description details **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** C68 - Old Rufford Road (A614) Junction To Blidworth Road Junc **Feature Type:** Street Section
Job Number: 2643535 **Defect Number:** 3541818

Enquiry No.: 66991 **Logged by:** Rosie Heald **on:** 26/10/2017 13:07
Service: Highway Searches **Subject:** Searches - Other Enquiries **Classification:** Report or Observation
Desc.: status enquiry 26.10.17
Location: Carr Banks Farm, Longland Lane, Farnsfield **Contact:**

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 2,000.00	Feature Id - Locn.: C68 - Old Rufford Road (A614) Junction To Blidworth Road Junc			Feature Type: Street Section		Area: Newark	
2643534	potholes (CW Repairs-Bituminous)	just after industrial unit marked	Category 2 (High)	Job Completed	07/02/2017	08/02/2017	Act. NEW-AS/5502310
2643535	potholes (CW Repairs-Bituminous)	entrance to carrbanks farm marked	Category 2 (High)	Job Completed	07/02/2017	08/02/2017	Act. NEW-AS/5502311
2644670	Carriageway Potholes (CW Repairs-Bituminous)	30m south from Farnsfield	Category 1	Job Completed	20/02/2017	21/02/2017	Act. NEW-AS/5502456
2644671	Carriageway Pothole (CW Repairs-Bituminous)	200metres from old rufford road junction traveling towards farnsfield, marked	Category 1	Job Completed	20/02/2017	21/02/2017	Act. NEW-AS/5502455
2652672	cat 1 high repair 70 mm deep x 400 mm x 400 mm..photo's are attached (CW Repairs-Bituminous)	as mapped half way along this section cat 1 high repair , john english H/insp .	Filled when found (Cat 1)	Job Completed	19/06/2017	19/06/2017	Act.
2652691	potholes (CW Repairs-Bituminous)	all through this section , also near 30.. mph signs off bad bend coming from farnsfield marked	Category 2 (High)	Job Completed	19/06/2017	29/06/2017	Act. NEW/3605208
2652692	pothole filled (CW Repairs-Bituminous)	outside melrose nursery cat 2 high filled during inspections	Filled when found (Cat 2H)	Job Completed	19/06/2017	19/06/2017	Act.
2655049	cat 2 high repair with highway assistant (CW Repairs-Bituminous)	near junction of Beck Lane , filled during inspections	Filled when found (Cat 2H)	Job Completed	31/07/2017	31/07/2017	Act.
2655050	cat 2 high potholes , repaired with highway assistant . (CW Repairs-Bituminous)	opposite the Farnsfield sign just past Beck Lane , filled during inspections.	Filled when found (Cat 2H)	Job Completed	31/07/2017	31/07/2017	Act.
2655051	cat 2 high repair . (CW Repairs-Bituminous)	outside carr banks farm , filled during inspections	Filled when found (Cat 2H)	Job Completed	31/07/2017	31/07/2017	Act.

Effective: 25/01/2017 to 25/01/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Longland Lane (26805255)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 2,000.00		Feature Id - Locn.: C68 - Old Rufford Road (A614) Junction To Blidworth Road Jun		Feature Type: Street Section		Area: Newark	
2658782	potholes (CW Repairs-Bituminous)	full length of road	Filled when found (Cat 2L)	Job Completed	29/09/2017	29/09/2017	Act.
2660744	potholes (CW Repairs-Bituminous)	near farnsfeild sign marked	Category 2 (Low)	Job Completed	24/10/2017	25/10/2017	Act. NEW-AS/5504029
2660745	potholes (CW Repairs-Bituminous)	from 614 to bend all marked	Category 2 (Low)	Job Completed	24/10/2017	25/10/2017	Act. NEW-AS/5504030
2661724	potholes (CW Repairs-Bituminous)	on bends as you enter village marked	Category 2 (Low)	Job Completed	07/11/2017	08/11/2017	Act. NEW-AS/5504129
2664403	potholes (CW Repairs-Bituminous)	near 614 junction, marked	Category 2 (High)	Job Completed	07/12/2017	18/12/2017	Act. NEW-AS/5504279
2664404	pothole (CW Repairs-Bituminous)	on thr 614 junction, marked	Category 2 (High)	Job Completed	07/12/2017	18/12/2017	Act. NEW-AS/5504278
2666513	potholes (CW Repairs-Bituminous)	near melrose house marked	Category 2 (Low)	Job Completed	10/01/2018	12/01/2018	Act. NEW/3607267
2666514	pothole (CW Repairs-Bituminous)	opps beck lane marked	Category 2 (Low)	Job Completed	10/01/2018	12/01/2018	Act. NEW/3607268
2666515	pothole (CW Repairs-Bituminous)	on bends near no footway for 500y sign marked	Category 2 (Low)	Job Completed	10/01/2018	11/01/2018	Act. NEW/3607269
2666516	potholes (CW Repairs-Bituminous)	near carr banks farm marked	Category 2 (Low)	Job Completed	10/01/2018	12/01/2018	Act. NEW/3607270
2666517	pothole (CW Repairs-Bituminous)	on stretch of road from 614 to the bend on hill marked with a arrow	Category 1	Job Completed	10/01/2018	11/01/2018	Act. NEW-AS/5504515
2666518	potholes (CW Repairs-Bituminous)	opps new farm sheds marked with a arrows	Category 1	Job Completed	10/01/2018	11/01/2018	Act. NEW-AS/5504514
2666519	potholes (CW Repairs-Bituminous)	from hill to A614 all marked	Category 2 (High)	Job Completed	10/01/2018	12/01/2018	Act. NEW/3607258
2667729	pothole (CW Repairs-Bituminous)	os longland farm, marked with arrow	Category 1	Job Completed	22/01/2018	24/01/2018	Act. NEW-AS/5504635

Street Works Notices

Organisation: BT (0030006)

Works Ref: CT001MW500243516000

Version: 4

Work Desc: Build 1 concrete chamber 915mm x 445mm x 965mm deep in Footway,Install 207m of cables in Verge,Install 50m of 1 way poly duct in Carriageway

Notice Type: Registration of Reinstatement - Full

Start: 09/08/2017 00:00:00

Work Status: Works Stopped

Issued: 25/08/2017 10:48:47

Work Type: EToN 4: Minor

Est. End: 11/08/2017

Completion: 11/08/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	O/S ROB SPARES LONGLAND LANE	Verge	Up to 1.5 Metres of Cover	46.00	0.30	A Permanent Reinstatement	11/08/2017		11/08/2017	11/08/2017
2	O/S ROB SPARES LONGLAND LANE	Carriageway	Up to 1.5 Metres of Cover	12.60	0.30	A Permanent Reinstatement	11/08/2017		11/08/2017	
3	O/S ROB SPARES LONGLAND LANE	Verge	Up to 1.5 Metres of Cover	37.70	0.30	A Permanent Reinstatement	11/08/2017		11/08/2017	
4	O/S ROB SPARES LONGLAND LANE	Carriageway	Up to 1.5 Metres of Cover	10.40	0.30	A Permanent Reinstatement	11/08/2017		11/08/2017	

Effective: 25/01/2017 to 25/01/2018

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: Longland Lane (26805255)

Street Works Notices**Organisation:** BT (0030006)**Works Ref:** CT001MW500243516000**Notice Type:** Registration of Reinstatement - Full**Work Status:** Works Stopped**Work Type:** EToN 4: Minor**Version:** 4**Start:** 09/08/2017 00:00:00**Issued:** 25/08/2017 10:48:47**Est. End:** 11/08/2017**Work Desc:** Build 1 concrete chamber 915mm x 445mm x 965mm deep in Footway, Install 207m of cables in Verge, Install 50m of 1 way poly duct in Carriageway**Completion:** 11/08/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
5	O/S ROB SPARES LONGLAND LANE	Verge	Up to 1.5 Metres of Cover	92.70	0.30	A Permanent Reinstatement	11/08/2017		11/08/2017	
6	O/S ROB SPARES LONGLAND LANE	Carriageway	Up to 1.5 Metres of Cover	4.20	0.30	A Permanent Reinstatement	11/08/2017		11/08/2017	

Works Ref: CT003MW500252497800**Notice Type:** Works Stop**Work Status:** Works Stopped**Work Type:** EToN 4: Minor**Version:** 3**Start:** 23/11/2017 00:00:00**Issued:** 27/11/2017 15:33:52**Est. End:** 27/11/2017**Work Desc:** Locate and excavate 1 blockage in existing duct**Completion:** 27/11/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN SOFT BY POLE OUTSIDE HILL TOP HOUSE TO IN CARRIAGEWAY AT JUNCTION TO BLIDWORTH LANE, LONGLAND LANE	Carriageway	Up to 1.5 Metres of Cover	0.00	0.00	Site Closed (No Excavation)	27/11/2017			24/11/2017

Works Ref: CT003MW500252497805**Notice Type:** Registration of Reinstatement - Full**Work Status:** Works Stopped**Work Type:** EToN 4: Minor**Version:** 4**Start:** 05/12/2017 00:00:00**Issued:** 13/12/2017 12:25:22**Est. End:** 07/12/2017**Work Desc:** clear blockages in existing duct.**Completion:** 07/12/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	IN SOFT BY POLE OUTSIDE HILL TOP HOUSE TO IN CARRIAGEWAY AT JUNCTION TO BLIDWORTH LANE, LONGLAND L	Verge	Up to 1.5 Metres of Cover	1.00	0.70	A Permanent Reinstatement	07/12/2017		07/12/2017	06/12/2017
2	IN SOFT BY POLE OUTSIDE HILL TOP HOUSE TO IN CARRIAGEWAY AT JUNCTION TO BLIDWORTH LANE, LONGLAND L	Verge	Up to 1.5 Metres of Cover	1.00	0.70	A Permanent Reinstatement	07/12/2017		07/12/2017	

Organisation: NRSWA - BT (0030005)**Works Ref:** WP00400500246297000**Notice Type:** Registration of Reinstatement - Full**Work Status:** Works Stopped**Work Type:** EToN 4: Minor**Version:** 5**Start:** 14/09/2017 00:00:00**Issued:** 15/09/2017 09:06:16**Est. End:** 18/09/2017**Work Desc:** Provide 5 new pole**Completion:** 14/09/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	FROM JCN OLD RUFFORD ROAD/LONGLAND LANE to APPROX 32 MTRS WEST FROM LONGLAND FARM, on,, LONGLAND LA	Verge	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	14/09/2017		14/09/2017	18/09/2017

Effective: 25/01/2017 to 25/01/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: Longland Lane (26805255)

Street Works Notices**Organisation:** NRSWA - BT (0030005)**Works Ref:** WP00400500246297000**Version:** 5**Work Desc:** Provide 5 new pole**Notice Type:** Registration of Reinstatement - Full**Start:** 14/09/2017 00:00:00**Work Status:** Works Stopped**Issued:** 15/09/2017 09:06:16**Work Type:** EToN 4: Minor**Est. End:** 18/09/2017**Completion:** 14/09/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
2	FROM JCN OLD RUFFORD ROAD/LOGLAND LANE to APPROX 32 MTRS WEST FROM LOGLAND FARM, on,, LOGLAND LA	Verge	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	14/09/2017		14/09/2017	
3	FROM JCN OLD RUFFORD ROAD/LOGLAND LANE to APPROX 32 MTRS WEST FROM LOGLAND FARM, on,, LOGLAND LA	Verge	Up to 1.5 Metres of Cover	0.50	0.50	A Permanent Reinstatement	14/09/2017		14/09/2017	

Organisation: Severn Trent Water East (9103908)**Works Ref:** 1101/000060217532**Version:** 4**Work Desc:** Small Main Repair Collar 3" Job in Carriageway (10mm Bitmac (Tarmac))**Notice Type:** Registration of Reinstatement - Full**Start:** 05/06/2017 00:00:00**Work Status:** Works Stopped**Issued:** 07/06/2017 14:06:52**Work Type:** EToN 4: Minor**Est. End:** 07/06/2017**Completion:** 06/06/2017

Site No.	Location	Position	Depth	Length	Width	Status	Site Date	Interim	Perm.	Prop. End
1	OPP UNIT 1, LOGLAND LANE, NG22 8HB	Carriageway	Up to 1.5 Metres of Cover	0.50	0.30	A Permanent Reinstatement	06/06/2017		06/06/2017	07/06/2017
2	OPP UNIT 1, LOGLAND LANE, NG22 8HB	Verge	Up to 1.5 Metres of Cover	1.00	0.60	A Permanent Reinstatement	06/06/2017		06/06/2017	