

Effective: 01/01/2018 to 27/02/2018  
Street: Bunny Lane (33002419)

Display Action Officer: Yes

Street: Bunny Lane (33002419)

Locality: Keyworth, Nottinghamshire

Area: Rushcliffe

### Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Street Section			<b>Area:</b> Rushcliffe	
<b>Batch:</b> 20268412 - Inspection Batch	No actionable defects found			<b>Route:</b> Rush Area 1 Feb Saf CW		<b>Officer:</b>		<b>Date:</b> 15/02/2018
<b>Batch:</b> 20263109 - Inspection Batch				<b>Route:</b> Rush Area 1 Jan Saf CW		<b>Officer:</b>		<b>Date:</b> 17/01/2018
3564255 Cw overlay.		17/01/2018	Locations are numbers 31 , 35 , 37 and 54. Overlay the carriageway center joint	CW Repairs-Bituminous	Internal		Committed	2667169

### Customer Services

<b>Enquiry No.:</b> 6081509	<b>Logged by:</b> External to Confirm	<b>on:</b> 13/02/2018 21:54	<b>Officer:</b> South Highways Management
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Carriageway Damage	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-68008937
<b>Desc.:</b> Road Damage - Centre of road all breaking up leading to multiple potholes. . Online report			
<b>Location:</b> Central reservation of road along bunny lane entering the village breaking up. Also mud from farm on the left all running onto the road and blocking drains.	<b>Contact:</b>		
<b>Enquiry No.:</b> 6079778	<b>Logged by:</b> External to Confirm	<b>on:</b> 02/02/2018 10:02	<b>Officer:</b>
<b>Service:</b> Trees/Verges	<b>Subject:</b> Grass Cutting	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-67147951
<b>Desc.:</b> Overgrown grass and verges - Mud in road and pavement from Greenhays farm and pavement overgrown with weeds/grass. . Online report			
<b>Location:</b> Bunny lane, between junction of High Court Drive and Greenhays & Hillside Farms.	<b>Contact:</b>		
<b>Enquiry No.:</b> 6077660	<b>Logged by:</b> External to Confirm	<b>on:</b> 22/01/2018 20:56	<b>Officer:</b>
<b>Service:</b> Carriageway/Footway	<b>Subject:</b> Carriageway Damage	<b>Classification:</b> Report or Observation	<b>Enquiry Ref:</b> FS-CASE-66407946
<b>Desc.:</b> Road Damage - The road is covered in mud and detritus leading immediately from the farm on the right hand side when driving towards Bunny from Keyworth , riding conditions are particularly hazardous for me as a cyclist , I feel endangered when using road to commute to and from work . Online report			
<b>Location:</b> See map coordinates and description details	<b>Contact:</b>		
<b>Enquiry No.:</b> 68568	<b>Logged by:</b>	<b>on:</b> 17/01/2018 17:12	<b>Officer:</b>
<b>Service:</b> Lighting	<b>Subject:</b> Street Light Damage	<b>Classification:</b> Report or Observation	
<b>Desc.:</b> the light column is leaning back in a dangerous position.			
<b>Location:</b> Bunny Lane in Keyworth, as you turn into the Health Centre the light column straight in front of you on the left of the entrance to the undercroft	<b>Contact:</b>		
<b>Enquiry No.:</b> 68508	<b>Logged by:</b>	<b>on:</b> 16/01/2018 10:20	<b>Officer:</b>
<b>Service:</b> Lighting	<b>Subject:</b> Street Light Fault	<b>Classification:</b> Report or Observation	
<b>Desc.:</b> I reported yesterday Bunny Lane Car Park column, I have received a phone call from a resident to say that 5 columns are not working on the car park.			
<b>Location:</b> Car Park	<b>Contact:</b>		

### Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
<b>Feat No.:</b> 2,000.00	<b>Feature Id - Locn.:</b>			<b>Feature Type:</b> Street Section			<b>Area:</b> Rushcliffe	
2667169 Cw overlay. (CW Repairs-Bituminous)		Locations are numbers 31 , 35 , 37 and 54. Overlay the carriageway center joint		Category 2 (Low)	Job Completed	17/01/2018	14/02/2018	Act. RUSH/3702987

---

**Effective:** 01/01/2018 to 27/02/2018  
**Street:** Bunny Lane (33002419)

**Display Action Officer:** Yes

---