

Effective: 25/01/2017 to 30/01/2018

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Radcliffe Road (33002264)

Street: Radcliffe Road (33002264)

Locality: Gamston, Nottinghamshire

Area: Rushcliffe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,001.00	Feature Id - Locn.: A52 roundabout to Regatta Way junc			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20265097	- Inspection Batch No actionable defects found			Route: Rush Area 2 Jan Saf CW				Date: 29/01/2018
Batch: 20259359	- Inspection Batch No actionable defects found			Route: Rush Area 2 Dec Saf CW				Date: 15/12/2017
Batch: 20256415	- Inspection Batch No actionable defects found			Route: Rush Area 2 Nov Saf CW				Date: 27/11/2017
Batch: 20250516	- Inspection Batch No actionable defects found			Route: Rush Area 2 Oct Saf CW				Date: 18/10/2017
Batch: 20244363	- Inspection Batch No actionable defects found			Route: Rush Area 2 Sep Enh CW/FW				Date: 05/09/2017
Batch: 20243545	- Inspection Batch No actionable defects found			Route: Rush Area 2 Aug Saf CW				Date: 29/08/2017
Batch: 20238900	- Inspection Batch No actionable defects found			Route: Rush Area 2 Jul Saf CW				Date: 20/07/2017
Batch: 20236208	- Inspection Batch No actionable defects found			Route: Rush Area 2 Jun Saf CW				Date: 30/06/2017
Batch: 20230784	- Inspection Batch			Route: Rush Area 2 May Saf CW				Date: 22/05/2017
3548873	Defect made safe	22/05/2017	Junction of Elms Park	CW Repairs-Bituminous	Internal		Uncommitt	2650831
Batch: 20226268	- Inspection Batch No actionable defects found			Route: Rush Area 2 Apr Saf CW				Date: 24/04/2017
Batch: 20223337	- Inspection Batch No actionable defects found			Route: Rush Area 2 Mar Saf CW				Date: 03/04/2017
Batch: 20218001	- Inspection Batch No actionable defects found			Route: Rush Area 2 Feb Saf CW				Date: 22/02/2017
Batch: 20213726	- Inspection Batch No actionable defects found			Route: Rush Area 2 Jan Saf CW				Date: 25/01/2017

Customer Services

Enquiry No.: 6069660

Logged by: External to Confirm

on: 08/11/2017 13:49

Service: Claims

Subject: Highway Insurance Claim

Classification: Report or Observation

Enquiry Ref: FS61664538

Desc.: Insurance claim - related to Confirm defect reference: 6069659

Date/Time: 06/11/2017 08:45:00

Direction of travel: Travelling back towards Nottingham.

Account of what happened: A chunk of salt fell off the back of our gritter and cracked his windscreen. This was on the A52. Spoke with the driver. Reg of our vehicle YJ61 EKL. Will email pics in separately.

Location: See map coordinates and description details

Contact:

Effective: 25/01/2017 to 30/01/2018

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Radcliffe Road (33002264)

Customer Services

Enquiry No.: 6069659	Logged by: External to Confirm	on: 08/11/2017 13:48	
Service: Other	Subject: Other Request (Highways)	Classification: Service Request	Enquiry Ref: FS-CASE-61664538
Desc.: Insurance claim form requested - Other requests - Next to Gamston Lock pub on the A52. A chunk of salt fell off the back of our gritter and cracked his windscreen. . Submitted by Advisor: Robert Warburton -			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6064743	Logged by: External to Confirm	on: 20/09/2017 15:00	
Service: Other	Subject: Other Enquiry (Highways)	Classification: Report or Observation	Enquiry Ref: FS-CASE-58997879
Desc.: Other enquiry - FAO Jim Freeman			
Further to our telephone conversation today re FS5730084 - reported on 14/08/2017. Karen Allsop was hoping to speak with you directly. Advised as requested that you would contact her. . Submitted by Advisor: Kerry Carby -			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6064087	Logged by: External to Confirm	on: 14/09/2017 08:12	
Service: Carriageway/Footway	Subject: Traffic Signal Fault	Classification: Report or Observation	Enquiry Ref: FS-CASE-58699055
Desc.: Traffic light fault - Customer called to report traffic lights stuck on red in Gamston. He was too sure where he was, but it looks like the main traffic lights on radcliffe road after the A52 roundabout at the junction with Ambleside, or lights very close to here. . Submitted by Advisor: Stephen Towson			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6062824	Logged by: External to Confirm	on: 31/08/2017 10:22	
Service: Carriageway/Footway	Subject: Traffic Signal Fault	Classification: Report or Observation	Enquiry Ref: FS-CASE-58024056
Desc.: Traffic light fault - When turning left on Regatta Way the traffic stops on the main road, it allows traffic to turn into Regatta way however once that traffic has turned in then the main road's traffic resumed leading to the driver not being able to go anywhere. This has happened on multiple occasions. The caller would also like an update on case 6060926. Submitted by Advisor: Jakub Gan			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6062435	Logged by: External to Confirm	on: 25/08/2017 10:34	
Service: Carriageway/Footway	Subject: Blocked Drain	Classification: Report or Observation	Enquiry Ref: FS-CASE-57787442
Desc.: Blocked drains - Outside the entrance to Askham Court is a drain on the road. On Radcliffe Road. This is blocked. Water overflows onto the path. . Submitted by Advisor: Robert Warburton			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6061266	Logged by: External to Confirm	on: 14/08/2017 15:22	
Service: Other	Subject: Other Request (Highways)	Classification: Service Request	Enquiry Ref: FS-CASE-57300824
Desc.: Other requests - Customer has contacted today about a sign for a split cycle and foot path. The customer would like to know whether the sign could be removed or placed somewhere else. as the residents know what type of path it is.			
Address Details			
Personal Data			
. Submitted by Advisor: Liam Newton -			
Location: See map coordinates and description details		Contact:	
Enquiry No.: 6058758	Logged by: External to Confirm	on: 19/07/2017 10:02	
Service: Carriageway/Footway	Subject: Spillage/Debris on Carriageway	Classification: Report or Observation	Enquiry Ref: FS-CASE-56173925
Desc.: Spillage/debris in road - Refuse truck has shed some of its load so there is a lot of rubbish in the street, outside the Gamston Lock . Submitted by Advisor: Shane Sims			
Location: See map coordinates and description details		Contact:	

Effective: 25/01/2017 to 30/01/2018

Display Action Officer: No

Feature No.: 2001.00 to 2001.00

Street: Radcliffe Road (33002264)

Customer Services

Enquiry No.: 6057300 **Logged by:** External to Confirm **on:** 04/07/2017 15:04
Service: Road Works **Subject:** Road Works Report **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-55436442
Desc.: Road work issue - *Received via email*
 To whom this my concern,

I am writing with regards to the current roadworks taking place between Radcliffe on Trent and the Gamston roundabout between 8pm-6am

Personal Data use this road between 2-3am **Personal Data**.

Are you able to give me any clarity as to when and where the roadworks will be taking place? The current diversions are adding an extra 30 minutes on to my journey **Personal Data**

At present it seems that one night/morning the roads are closed, other nights/mornings they're open!

I also believe that there has been absolutely no consideration, empathy or thoughtfulness of the effects that it is having on the residents of Radcliffe on Trent.

At first we were lead to believe that the developments and building works would be in place until the end of May 2017, it is now July and personally I have seen hardly any progress; even during the early morning (when the road has been open) I have only ever seen a maximum of 4 workers working on the site.

Personal Data on Friday (30/6/17) evening and the diversions that were in place took me on a loop around Radcliffe on Trent. I ended up taking a huge diversion (eastbound up to saxondale roundabout, onto the A46, down the A606) and this was extremely inconvenient. Are there any contingencies in place for emergency vehicles etc? It's slightly disconcerting to know that ALL roads into Nottingham and out of Radcliffe are closed unless you make a massive reroute.

Personal Data

Personal Data

Personal Data

. Submitted by Advisor: Candy Cooper

Location: See map coordinates and description details

Contact:

Enquiry No.: 6056167 **Logged by:** External to Confirm **on:** 21/06/2017 13:50
Service: Trees/Verges **Subject:** Overhanging Vegetation/Trees **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-54780917
Desc.: Overgrown hedges and vegetation - Overhanging vegetation on shared foot/cycle way - City bound side of Radcliffe Road . Online report
Location: See map coordinates and description details **Contact:**

Enquiry No.: 6052825 **Logged by:** External to Confirm **on:** 16/05/2017 14:43
Service: Trees/Verges **Subject:** Overhanging Vegetation/Trees **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-52560806
Desc.: Overgrown hedges and vegetation - The stretch of Radcliffe Road, between Ambleside and Davies Road, West Bridgford, including the cycle path on the south side has badly intruding vegetation.
 . Submitted by Advisor: Jakub Gan
Location: Btwn Ambleside & Davies Rd jcns **Contact:**

Enquiry No.: 6042565 **Logged by:** External to Confirm **on:** 13/02/2017 12:16
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-12842627
Desc.: Road Pothole - Email from customer

2 Potholes on slip road off A52, near Ambleside, both quite deep . Submitted by Advisor: Kelly Magill

Location: See map coordinates and description details

Contact:

Effective: 25/01/2017 to 30/01/2018

Feature No.: 2001.00 to 2001.00

Display Action Officer: No

Street: Radcliffe Road (33002264)

Customer Services

Enquiry No.: 6041241	Logged by: External to Confirm	on: 02/02/2017 14:41	
Service: Carriageway/Footway	Subject: Traffic Signal Fault	Classification: Report or Observation	Enquiry Ref: FS-CASE-12462650
Desc.: Traffic light fault - The filter light from Radcliffe Road - turning right onto Ambleside does not seem to be working properly. It normally changes dependent on traffic flow - but seems to be on red for long periods of time. . Submitted by Advisor: kerry carby			
Location: See map coordinates and description details	Contact:		
Enquiry No.: 6040703	Logged by: External to Confirm	on: 30/01/2017 09:21	
Service: Carriageway/Footway	Subject: Spillage/Debris on Carriageway	Classification: Report or Observation	Enquiry Ref: FS-CASE-12305779
Desc.: Spillage/debris in road - Police called to advise of some sort of slippery substance on the road causing a car to loose control. Its just off Gamston round about, heading towards Ratcliffe on trent. . Submitted by Advisor: Anne Lopinto			
Location: See map coordinates and description details	Contact:		
Enquiry No.: 3800131	Logged by: Kelly Douglas	on: 25/01/2017 11:15	
Service: Carriageway/Footway	Subject: Spillage/Debris on Carriageway	Classification: Report or Observation	
Desc.: Spillage of stones on the outer lane of the A52			
Location: Radcliffe Road (a52) near to the gamston depot roundabout opposite the Bridge PH coming out of WB	Contact:		
Enquiry No.: 67814	Logged by: Jim Freeman	on: 05/12/2017 14:15	
Service: Traffic Management	Subject: Traffic Issues	Classification: Report or Observation	
Desc.: safety concerns			
Location: BUS LANE - W.Bound - Gamston Island to Davies Rd	Contact:		
Enquiry No.: 66059	Logged by: Laura Trusler	on: 18/09/2017 10:46	
Service: Trees/Verges	Subject: Overhanging Vegetation/Trees	Classification: Report or Observation	
Desc.: Hedges/trees are overgrown and making it difficult on the cycle track/path			
Location: Junction Ambleside	Contact:		

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 2,001.00	Feature Id - Locn.: A52 roundabout to Regatta Way junc			Feature Type: Street Section		Area: Rushcliffe	
2650831	Defect made safe (CW Repairs-Bituminous)	Junction of Elms Park	Filled when found (Cat 2H)	Job Completed	22/05/2017	22/05/2017	Act.