

Effective: 15/01/2018 to 20/01/2018

Feature No.: 2000.00 to 2001.00

Display Action Officer: No

Street: Gordon Road (33000969)

Street: Gordon Road (33000969)

Locality: West Bridgford, Nottinghamshire

Area: Rushcliffe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: From Tudor Square to no. 50 past Gordon Square		Feature Type: Street Section		Area: Rushcliffe			
Batch: 20263559 - Inspection Batch			Route: Rush Area 2 Jan Enh CW/FW			Date: 19/01/2018		
No actionable defects found								
Feat No.: 2,001.00	Feature Id - Locn.: From Gordon Square to Burleigh Road		Feature Type: Street Section		Area: Rushcliffe			
Batch: 20263356 - Inspection Batch			Route: Rush Area 2 Jan Enh CW/FW			Date: 18/01/2018		
3564428	Defects made safe	18/01/2018	On the T Junction with Ethel Road	CW Repairs-Bituminous	Internal		Uncommitt	2667342

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Feat No.: 2,001.00	Feature Id - Locn.: From Gordon Square to Burleigh Road		Feature Type: Street Section		Area: Rushcliffe		
2667342	Defects made safe (CW Repairs-Bituminous)	On the T Junction with Ethel Road	Filled when found (Cat 2H)	Job Completed	18/01/2018	18/01/2018	Act.