

Effective: 01/11/2014 to 13/03/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: HOSE LANE (33022002)

Street: HOSE LANE (33022002)

Locality: Colston Bassett, Nottinghamshire

Area: Rushcliffe

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: From Harby Lane to Leicestershire boundary			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20267844 - Inspection Batch				Route: Adhoc Inspection				Date: 12/02/2018
3567634	Carriageway Damage - Road Damage - Edges of road breaking up leading to poor road surface. Previous repairs now ineffective. . Online report (Enquiry 6080992)	12/02/2018	300m south of Roses Farm, Hose Lane, Colston Bassett	CW Repairs-Bituminous	Internal		Uncommitt	2670590
Batch: 20267313 - Inspection Batch	No actionable defects found			Route: Review Outcome-TPD				Date: 07/02/2018
Batch: 20266402 - Inspection Batch				Route: Adhoc Inspection				Date: 02/02/2018
3566630	Carriageway Damage. Online report (Enquiry 6079843)	02/02/2018	Potholes reported via Hams. Potholes filled at the location given south of the Farm	CW Repairs-Bituminous	Internal		Uncommitt	2669579
Batch: 20265130 - Inspection Batch				Route: Adhoc Inspection				Date: 29/01/2018
3565792	Carriageway Pothole - Road Pothole - The pothole is deep and usually submerged in water so is not visible. This stretch of road is in very very poor condition and needs replacing urgently . Submitted by Advisor: TPD	29/01/2018	Either side of Roses Farm.	CW Repairs-Bituminous	Internal		Uncommitt	2668732
Batch: 20260686 - Inspection Batch				Route: Rush Area 1 Jan Enh CW/FW				Date: 02/01/2018
3562592	Cw potholes reported via hams	02/01/2018	Location plotted on hams 6074567	CW Repairs-Bituminous	Internal		Uncommitt	2665474
Batch: 20217410 - Inspection Batch				Route: Adhoc Inspection				Date: 20/02/2017
3542892	Carriageway Pothole - Road Pothole - there are several potholes that vary in sizes all across Hose Lane as you turn right onto the lane coming from Colston Basset. Some are extremely deep and they tend to get worse as you get closer to the Leicestershire Boundary. There are some that are by Hose Lodge farm that are particularly bad as well, located on the edges of the road and some all across the road . Submitted by Advisor: TPD	20/02/2017	Various locations marked in yellow from the junction of Harby Lane to the County boundary with Leicester CC. Pothole infill and Overlay, no excavation.	CW Repairs-Bituminous	Internal		Committed	2644616

Effective: 01/11/2014 to 13/03/2018

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: HOSE LANE (33022002)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Feat No.: 2,000.00	Feature Id - Locn.: From Harby Lane to Leicestershire boundary			Feature Type: Street Section			Area: Rushcliffe	
Batch: 20213500 - Inspection Batch				Route: Adhoc Inspection				Date: 23/01/2017
3540922	Carriageway Damage - Road Damage - Customer is reporting that Hose Lane is Carlston Bassett is in terrible condition. The road is littered with potholes and cracks in the road which the customer believes could be dangerous to drive on. Customer would like to know if there will be any road repairs on this road as it is in bad state. . Submitted by TPD	23/01/2017	Various locations, Hams reported.	CW Repairs-Bituminous	Internal		Uncommitt	2642583
Batch: 20211130 - Inspection Batch				Route: Rush Area 1 Jan Enh CW/FW				Date: 05/01/2017
3539906	Cw potholes.	05/01/2017	150m from the entrance to Colstonhill Farm	CW Repairs-Bituminous	Internal		Uncommitt	2641551
Batch: 20193670 - Inspection Batch				Route: Adhoc Inspection				Date: 18/08/2016
3533652	Cw potholes	18/08/2016	Various locations marked in yellow from past the farm entrances to the Leicester boundary.	CW Repairs-Bituminous	Internal		Committed	2634870
Batch: 20160423 - Inspection Batch	No actionable defects found			Route: Rush Area 1 Jan Enh CW/FW				Date: 06/01/2016
Batch: 20107830 - Inspection Batch				Route: Rush Area 1 Jan Enh CW/FW				Date: 05/01/2015
3502336	Edge deterioration and potholes.	05/01/2015	Various locations from Harby Lane to the county boundary, areas marked in yellow.	HW CW Edge Deterioration Z5	Internal		Committed	2602449
Batch: 20101186 - Ad Hoc Inspection Batch				Route: Adhoc Inspection				Date: 13/11/2014
3500375	H W I A - Please repair c/w cracks, pour in Cold Joint Seal, just to seal up cracks for the winter.	13/11/2014	Various areas of Lane, if not sure, TPD	HW CW Pothole Z1	Internal		Committed	2600397

Customer Services

Enquiry No.: 6080992 **Logged by:** External to Confirm **on:** 09/02/2018 22:39
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-67770925
Desc.: Road Damage - Edges of road breaking up leading to poor road surface. Previous repairs now ineffective. . Online report
Location: Hose Lane, Colston Bassett **Contact:**

Plot Number: 2,000.00**Feature Id - Location:** From Harby Lane to Leicestershire boundary**Feature Type:** Street Section**Job Number:** 2670590**Defect Number:** 3567634

Effective: 01/11/2014 to 13/03/2018

Display Action Officer: No

Feature No.: 2000.00 to 2000.00

Street: HOSE LANE (33022002)

Customer Services

Enquiry No.: 6079843 **Logged by:** External to Confirm **on:** 02/02/2018 10:03
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-67109850
Desc.: Road Damage - The single track road has a length (200M) which has not been replaced and is full of potholes and is in very poor condition. I have reported this before and it has been claimed it has be repaired but it has not as I caught another pothole this morning. . Online report
Location: Just on the bends prior to the farm on the right a length of road in in very poor condition and has numerous potholes . **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** From Harby Lane to Leicestershire boundary **Feature Type:** Street Section
Job Number: 2669579 **Defect Number:** 3566630

Enquiry No.: 6078556 **Logged by:** External to Confirm **on:** 26/01/2018 13:00
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-66705092
Desc.: Road Pothole - The pothole is deep and usually submerged in water so is not visible. This stretch of road is in very very poor condition and needs replacing urgently . Submitted by Advisor: **TPD**
Location: Easting/Northing: 471751/330968 (52.871411, -0.935471) **Contact:**
Nearest road to the pin placed on the map (automatically generated by Bing Maps):
Hose Lane, Colston Bassett, LE14 4
Nearest postcode to the pin placed on the map (automatically generated): NG12 3FL
(1036m away)

Plot Number: 2,000.00 **Feature Id - Location:** From Harby Lane to Leicestershire boundary **Feature Type:** Street Section
Job Number: 2668732 **Defect Number:** 3565792

Enquiry No.: 6074567 **Logged by:** External to Confirm **on:** 02/01/2018 09:24
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-64743797
Desc.: Road Pothole - The road surface has disintegrated and for 400 yards adjacent to roses farm and hills farm the road has large holes . Online report
Location: See map coordinates and description details **Contact:**

Enquiry No.: 6043229 **Logged by:** External to Confirm **on:** 17/02/2017 10:52
Service: Carriageway/Footway **Subject:** Carriageway Pothole **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-13000451
Desc.: Road Pothole - there are several potholes that vary in sizes all across Hose Lane as you turn right onto the lane coming from Colston Bassett. Some are extremely deep and they tend to get worse as you get closer to the Leicestershire Boundary. There are some that are by Hose Lodge farm that are particularly bad as well, located on the edges of the road and some all across the road .
Submitted by Advisor: **TPD**
Location: See map coordinates and description details **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** From Harby Lane to Leicestershire boundary **Feature Type:** Street Section
Job Number: 2644616 **Defect Number:** 3542892

Enquiry No.: 6039920 **Logged by:** External to Confirm **on:** 20/01/2017 16:10
Service: Carriageway/Footway **Subject:** Carriageway Damage **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-12042224
Desc.: Road Damage - Customer is reporting that Hose Lane is Carlston Bassett is in terrible condition. The road is littered with potholes and cracks in the road which the customer believes could be dangerous to drive on. Customer would like to know if there will be any road repairs on this road as it is in bad state. . **TPD**
Location: 'See map coordinates and description details' **Contact:**

Plot Number: 2,000.00 **Feature Id - Location:** From Harby Lane to Leicestershire boundary **Feature Type:** Street Section
Job Number: 2642583 **Defect Number:** 3540922

Enquiry No.: 6039919 **Logged by:** External to Confirm **on:** 20/01/2017 16:10
Service: Carriageway/Footway **Subject:** Spillage/Debris on Carriageway **Classification:** Report or Observation **Enquiry Ref:** FS-CASE-12042014
Desc.: Spillage/debris in road - Customer has called to report Slurry and mud about an inch deep is all over Hose Lane in Colston Bassett, along the potholes and cracks that have formed in the road this making it very difficult to drive and is actually quite dangerous to drive on, along with the potholes littering this road. . Submitted by Advisor: **TPD**
Location: 'See map coordinates and description details' **Contact:**

Effective: 01/11/2014 to 13/03/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: HOSE LANE (33022002)

Customer Services

Enquiry No.: 6005274 **Logged by:** External to Confirm **on:** 11/02/2016 09:50
Service: Carriageway/Footway **Subject:** Footway Damage **Classification:** Report or Observation **Enquiry Ref:** 103870767
Desc.: There is a brick culvert that has been hit and needs repair on Hose lane approx 1/4 mile from Hose lodge farm on the left hand side near string dyke (some call it Wash dyke). Mr Parker has pulled it out and its on the side.
 Logged by CSC operator: Cheryl Townsend
Location: Approx 1/4 mile from Hose Lodge Farm on left **Contact:**

Enquiry No.: 6003125 **Logged by:** External to Confirm **on:** 27/01/2016 13:02
Service: Carriageway/Footway **Subject:** Carriageway Obstruction **Classification:** Report or Observation **Enquiry Ref:** 103859806
Desc.: Police had a report in to say that 400/500 yards from stack yard house and roses farm there is a lot of mud on the road causing steering issues for poepl driving and could be dangerous with the rain making it slippy.
 Logged by CSC operator: Ashleigh Taylor
Location: 208 meters from Stackyard House Harby Lane **Contact:**

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: From Harby Lane to Leicestershire boundary		Feature Type: Street Section		Area: Rushcliffe	
2600397	H W I A - Please repair c/w cracks, pour in Cold Joint Seal, just to seal up cracks for the winter. (HW CW Pothole Z1)	Various areas of Lane, if not sure, then give John a call.	Category 2 (High)	Job Completed	13/11/2014	25/11/2014	Act. RUSH/3700093
2602449	Edge deterioration and potholes. (HW CW Edge Deterioration Z5)	Various locations from Harby Lane to the county boundary, areas marked in yellow.	Category 2 (High)	Job Completed	05/01/2015	08/01/2015	Act. RUSH/3700329
2634870	Cw potholes (CW Repairs-Bituminous)	Various locations marked in yellow from past the farm entrances to the Leicester boundary.	Category 2 (High)	Job Completed	18/08/2016	18/11/2016	Act. RUS-AS/5600411
2641551	Cw potholes. (CW Repairs-Bituminous)	150m from the entrance to Colstonhill Farm	Filled when found (Cat 2L)	Job Completed	05/01/2017	05/01/2017	Act.
2642583	Carriageway Damage - Road Damage - Customer is reporting that Hose Lane is Carlston Bassett is in terrible condition. The road is littered with potholes and cracks in the road which the customer believes could be dangerous to drive on. Customer would like to know if there will be any road repairs on this road as it is in bad state. . Submitted by Advisor: nathan laverty (Enquiry 6039920) (CW Repairs-Bituminous)	Various locations, Hams reported.	Filled when found (Cat 2L)	Job Completed	23/01/2017	23/01/2017	Act.
2644616	Carriageway Potholes	Various locations marked in yellow from the junction of Harby Lane to the County boundary with Leicester CC. Pothole infill and Overlay, no excavation.	Category 2 (Low)	Job Completed	20/02/2017	06/07/2017	Act. RUSH/3702178

Effective: 01/11/2014 to 13/03/2018

Feature No.: 2000.00 to 2000.00

Display Action Officer: No

Street: HOSE LANE (33022002)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Feat No.: 2,000.00	Feature Id - Locn.: From Harby Lane to Leicestershire boundary		Feature Type: Street Section		Area: Rushcliffe	
2665474	Cw potholes reported via hams (CW Repairs-Bituminous)	Location plotted on hams 6074567	Filled when found (Cat 1)	Job Completed	02/01/2018	02/01/2018	Act.
2668732	Carriageway Pothole - Road Pothole - The pothole is deep and usually submerged in water so is not visible. This stretch of road is in very very poor condition and needs replacing urgently . Submitted by Advisor: TPD (Enquiry 6078556) (CW Repairs-Bituminous)	Either side of Roses Farm.	Filled when found (Cat 1)	Job Completed	29/01/2018	29/01/2018	Act.
2669579	Carriageway Damage. Online report (Enquiry 6079843) (CW Repairs-Bituminous)	Potholes reported via Hams. Potholes filled at the location given south of the Farm	Filled when found (Cat 2H)	Job Completed	02/02/2018	02/02/2018	Act.
2670590	Carriageway Damage - Road Damage - Edges of road breaking up leading to poor road surface. Previous repairs now ineffective. . Online report (Enquiry 6080992) (CW Repairs-Bituminous)	300m south of Roses Farm, Hose Lane, Colston Bassett	Filled when found (Cat 2H)	Job Completed	12/02/2018	12/02/2018	Act.